

1963 FIAT-ABARTH 1000 GT

110-0380

SERVICE RECORD

1994-2018

- Post Festival 32 notes:
- car runs very well, new Dunlops made a lot of difference in handling. Did not run after Sat morning as there was too much aggressive driving in our group. very disappointing weekend
- need mid view year in right side fender mirror
- prep for Fall finale: 9/27/2014 ~ 10/8
 1. • Switch to direct racing exhaust
 - Timing check total 45° on flywheel at revs - OK
 - Exhaust color perfect light gray.
 - needs mid view outside right mirror check if Talbot available? Ordered - not yet received.
 - Decided not to check valve gap was perfect in April 2014
 - 6 month oil + filter change will Fall Finale oil is clear with only slight color.
 - Should teardown engine and install new rods winter 2014/15
 - replace left engine cover rubber strap w NOS from eBay \$11^{xx}!
 - 10/8/ set tire pressure in garage L 22/24 - reset at track!

BIG KENT BRAINS SHOP
PAST EVENT LOGO

- ~~Yester night 2 Aug 14
Door handles swapped
left to right causing
stem broken in left
Door.~~
- ✓ M4 VLT! ✓ FPVLT!
- Engine runs beautifully, but accucomp may need re pressurizing - must do anyway after oil + filter change.
 - ordered second mid view year for Talbot fender mirrors
 - 11/16 added antifreeze Test good to -20 F



2014 FF

EVENT

10/10/14

DATE

S. Fokk

Sperry Wreck Aug 2014 cont.

Took source of Brake fluid in bottom of master cylinder to bland nut on bottom of fluid reservoir very close look. No significant loss of fluid

Tighten wheel screws!

Check transmission fluid level OK

VSCCA ceremonial day. First practice was wet and very not sticky. 7 ins. over 18/23. In Qualifying session (dry) front tire warm 20.85 rear bumped 4 ins. Lots of rubber stuck to tire. ~~possibly not enough race~~

Check Clutch pedal return spring - replace if needed.

Car ran very well - finally got comfortable on the track. Had nice run with Ed Hyman + his 356

Lewis Rock Historic Festival 32 2014

- 出入 more straightened + restored by automotive restoration in stratified \$25,000 — me rechromed small ^{front} ~~front~~ ^{wheel} shroud panels by radiator.
- Front now front ~~shroud~~ shroud panels by radiator.
- Changed Brake Fluid + bleed brakes - good pedal.
- adjust mirrors
- Set front Dunlop 7 ins + rear (tire) 5" rim
11 rear - pressure 18/23
- Soft rear Bumped to 30 pressure to 24 } Rear to 20/25
front bumped to 27-28 }
- Tech sticker on back of this page

08/25/2013 Lime Rock Restonace - Art Donovan
Driving instead of me. bat was hit left front by a
white Alfa 150 - did not finish

- Lime Rock Fall Trials Oct 11/12 2013.

Car ran very well - clean to 7600 after first few
laps. No prep other than for Boston festival -
10/26/2013. Drain coolant & filled with anti-
freeze 70% - 26 F. Spring 2014 - engine will
need Head re-torque + valve gap check + set timing

04/29/2014 Prep for Spruce Sprint

- Check valve gap

① .020 .010T

② .020 .010

③ .020T .010-

④ .019 .010T-.009

⑤ ⑥ ⑦

Callouts change when gaps are
close enough

- Re-torque cylinder head nuts 37 FT LBS. Loosen all
at once and try. Torq. to spec, nut broke loose nicely
and pulled & torque smoothly.
- Chain tension 3/8" or 10 mm deflection
- Set plug gap to .020" were at about .022 and
antiseize on plug threads
- Torque intake manifold nut to 14 FT LBS
- Only three events since Fall 2012 oil changes/
filter. Change oil before Lime rock historic

- cont: open left rear caliper Bleeder - and fluid flow. Thin wire, pedal comes up a lot, added shunt links - very good pedal. Fill reservoir to "max" line.
- check compensation valve 4 1/2 Turns decrease to ~~0~~ Zero, re-set at 4 1/2 Turns. Check brake Pedal - good.
- Install new fuel cell - Tank repainted, new aeroquip Braided hose and AN fittings.
- Low fuel warning light wiring: Aug 24 2013 original wire to Jaeger gauge fuel level sender: white: when grounded with ignition on, indicate high fuel level on Jaeger gauge
Yellow: when grounded causes low fuel lamp in Jaeger instrument to light up.
Black: is ground to fuel level sender body and fuel tank.
- Pushed all OEM wires inside dash, connected new Brauch and yellow wire to old harness. White wire not used with fuel cell
- wiring Done
- Waiting for AN fittings to connect pump to steel fuel line
- not in right front: Inside of tire rim was very greasy, also inside of rotor where mounted to hub. Brakes were hot at this point.

new gap check

Spring 2013

(E)

(I)

metronome timing no change same
Spring 2011 except #4 EKHHSST -
but not re-adjust valves. Then year
2013 April 4 events new last
adjustment. Re torque head to 57 FT-LBS

1 .020 .010

:

2 .020T .010

3 .020T .010

4 .019 .010

3w up out open exhaust & intake

bulbous top - valve研磨

- drain antifreeze - flush . add distilled water + red line water switch prep for Spring Specs

- Spring, spring - Set tire cold to 18 / 232

- get Pegasus re-certify insurance?

- engine run clean 27500 from no winter break w/ oil filter

Tire 18/23 70Km up front to 40751

- Prep for Historic Festival July 21 2013

✓ FRONT Calipers are either stuck or master cylinder does not return fluid to reservoir - suspect master cylinder ...

8/14/13 Replaced master cylinder - bleed Brakes - no fluid to rear Calipers! Sit in car Pump pedal hard - very low - but hard.

10/7/2012 Prep for winter storage:

- Change oil & filter on top piping evident in filter - will cut apart & examine - drained access sump before refilling engine with fresh oil
Added 2 4oz bottles of 20DP to power cam
- Followed, fill with 15W30 motor oil
Synthetic TOTAL QTY OIL 8 QUARTS - filter
Access sump and engine dump
- Filter was clean after cutting apart metal parts,
appear to be brass^{very fine} - but this may be caused by the
color of dirty (used) engine oil
- Spark plugs were clean, no sign of oil.
- ran engine with starter & plugs out till ~~out~~ oil
pressure needle moves. removed plugs & start. good
oil pressure. ran till access sump showed full pressure
→ shut off.
- fill tire to 35 psi in storage - note right front is
flat spotter!
- remove plugs may well keep cap relate engine
with starter removal plug finger tight 10/7/2012
- Spring 2013 Prep for Spring Spurts
Dismantle top of engine in vane gap check

- Spring Sprints 2012: ran well - Tachometer 8000 RPM over clutch release squeaks needs lube.
- new carburetor front pads broke in easily great pedal feel.
- prep for June rock Histone Festival 2012: anyway
 1. Install solid generator mount made by J. Burch.
 2. Install Brown Top Marelli coil with resistor on repeated bracket. Changed wire end to coil to right angle type
 - 3 started engine ran well 15 second, wire below rebuild! Time for Teardown?
- Traced source of clutch pedal squeak/bouncing to 1. Lack of lube in support bearing - oiled w/ O/HO, also oiled return spring(s) OK
- Swap w/ own racing Hibaut for Rock Festival
- replace cap and shoulder harness. Better wire, say Bar!
- re-torque head (37 FT LBS)
- replace top sheet
- Bleed Brakes
- Just all factory rev limiter set to 7600 - can climb to almost 8000 - rev limit to 7300 as test - D need to 7500 - perfect match to checked point gaps - gap .013 (.012 low)
- Hibaut cold light mag - unusual

Prep for winter storage 2011 - cont.

- Fill tank to 30PSI
- Remove plugs. Spray eyes with degreaser - rotate engine to ~~not~~ oil pressure rises. reinstall plugs - finger tight!

Spring 2012

- replace left rear i-joint with rebuilt spare.
- Change to muffled exhaust for Spring Spurts
- Expansion tank? Leaks...
- Accucomp pressure had dropped over winter to 65PSI - When empty, pressure in accucomp was 8PSI. Filled to 60PSI per Accucomp instruction and boost to 10PSI. Ran engine at this pressure. Changed to 70PSI. System was probably full with no leaks since Fall 2011 - good!
- Remove coolant header tank & check for leaking. Found patches leak at front top of tank, repair!
- Install Carbotech front brake pads HCT9-XD1C - racing lining - the 2 backing plates in inside had to be cleared to spindles - Caliper support
- note: oil from hubs leaked from bearing ^{interior} ~~cartridge~~ hub, storage wiped away springs!
- Turn signal non functional lighter
- TORQUE WHEEL SCREWS!
- Tire wheel pressure within 3LBS of 36PSI from last Fall 2012 ^{4/2012} "no tire deflators!"
- 5/1/2012 Drain antifreeze & coolant water + coolly bottle

2011 Cont:

- Front axle Sway bar - pass
- Clean, repack wheel bearings
- July 2010 prep for Lime Rock Historic races.
Disassembled front suspension. New King pin left front, new A-arm bushings, new upright bushings
• made new springs containing our
- remove clevis & bush radiator and replace
- mag & install new hubs - front passed crack testing
- Aug 2011 reassemble suspension set toe to 1-2 mm camber -
rebuilt calipers, this rotation (replica from Japanese ~~spec~~
especially made and altered to fit (originals rotated,
retired - too thin.)
- Rebuilt master cylinder, all new steel line, to
front brakes, new brake pads (stuck)
- Checked points now! floor! set to .013"
- Reset timing, 15° static - checked on running
- Set tapp to 18/23 at track 9/2/11
- Historic Festival 27 LRP: FRONT BRAKE PADS
overheated due to using street pads after 6 laps,
need racing pads front!
car ran clean to 1800! lots of power...
- got new V-joint slip should replace annually
rebuild worthless need time out
- FIX! PIN HOLE IN EXPANSION TANK
- Drain coolant & refill w/antifreeze max 10/8/2011
GSP70 - 26° (3 Bally Head) page 40

2011 09/1

- Break loose head bolt, & retorque to 37 FT LBS
#3 (in sequence) head bolt was stiff & required total break
bolt to retighten
- reinstall manifold & carb. Torque nuts on manifold
to head studs to 14 FT LBS
- replace Throttle cable - seldom was perfect after
10? years
- Dye test rear stub axles - pass
RIGHT FLEX COUPLING: Crack in outer steel forging.
replaced with NOS rimon 1000/absorb part. left
flex coupling good.
- Torque axle nuts to 101 FT LBS
- Torque U-joint adapter to flex coupling screws to 36 FT LBS
- Torque caliper screws to 26 FT LBS NOTE Smaller washer
used loc-tite on threads
- Hand tighten ujoint to adapter nut
- When removed left & right rear rotors were on opposite
sides - replaced same
- Left U-joint stiff should be replaced, but no play in
Joint now. 5/29/2011 don't retl nuts
- Tightened check valve inline attach to oil line - was
leaking slightly last year
- Right caliper boot ruined (torn) by drilled brake pad
backing plate. ~~Prob~~ probably torn on installation.
Rebuild with front caliper before next time up!
- Left king pin looses - needs rebuild

2011

- Left wheel bearing loose - has slight play in king pin - should be sh. for a while.
- Accuburst showed only 80 psi before start up, should be drained & re-charged properly.
- Check & adjust valves - last time due was 2008 april

VALVE GAP MEASURED:

I 4 3 2 1
 .010T .009T .010 .010⁺
 ⑤

STD = .010"

all except # 3 were
.011 min. 2009

T = TIGHT

E 4 3 2 1
① .019 ② .009T ③ .019 ④ .021+T

STD = .0196"

all were .020 april 2009

All lobes smooth, show no signs of unusual wear.

Reset # 3 intake & H1 exhaust to spec.

1. E4 Shim = .060 NO THINNER - NEED .059" THIS SENT CUT TOO DEEP!

2. E3 Shim = .076" TO .075"

3. E2 Shim = .080" → .079"

4. E1 Shim No change

5. # 3 intake Shim = .071" → .070"

TIGHTEN CAM SOUPHACK NUTS TO 14 FT LBS

RESULTS:

I 4 3 2 1
 .020T .020T .020 .020-021⁺

E 4 3 2 1
 .010T .010T .010-01P .010T

2010 - cont

- Installed acumump July 2010
generator repaired - (field to ground wire was broken)
replaced regulator with original flat as before
- Installed P85 MR while original out for repair and
new seal (was leaking - shaft in pulley end worn
retrofite head.
- July 31 lost and fixed accumulation. pumprunner
noisy
repeat exhaust with open rising exhaust
residual in liner
- August Replaced abarth water pump with same rear, as
used 20 years ago (new one) shaft in pulley end was worn
inside pulley and pulley end bearing. shaft was built
up and resized to fit by Don Breckner. washer between
pump impeller and impeller bearing is .037" yielding about
.015" clearance to pump body. clearance to inlet side is ~~.040"~~
.040" by two original gaskets. assembly leaked
out of weep hole but only minor running. also note
both bearings are on shaft with green loctite. Hoping
seal will hold until we "Bass leak" did not stop
leak after run engine 20 min at 2500 rpm.
- install hill climb 5 speed for Mt. Eguinox
- May 7 in San Jose 2010 - installed 9/37 5 speed
- retires road
- Breaks
adjust clutch set play TURBO READJUST SPRING 2011

1971/0
dimensions & changes with

green coolant. refil w/ANTIFREEZE MIXTURE

2-2 plugs may a deep creep and rotate engine
w/ starter. car will not turn off due to torque
from road magnet

Some details on trap cut.

- Engine locked in left down firmly sealed in hoop • Equal plenum between Hoop and Chassis
hormone 1.8 in $\frac{3}{10}$ in left side.
20% carb from through breather holes in body -
but only at cold rods when engine can
stall. Fuel drops from right carb after shut
down
- Make angle plate? so carbs draw into manifold
fuel lines - will require dropping engine about
1/2" in back - how do? Salvage steel engine
mount?
- Notes from system experts - 7/20
 - replace mudguards wiper blades
 - High speed mix cleared up after first turn out
 - Change problem?
- 2009 5700 ft. 90° N Sierra California - Willows area
Soil feeding front - 2.5'
- Generator will take 100, then on as engine need mixing
cleaning?
- Diesel 4100 kg/m mixed or age 2000 rpm a spec
1.3, 6 steps only H-L only but lower monotony
curve changes to 150 Hz step which is flat not
stepped type.
- PLUGGED SNOWCER only!
Sprayed secondary air displacement 9/19/09

2010

- Rep for spring sprunk
- Change oil + filter - filter was clean except for a few small specs. Our started easily 100 psi cold
ADDED 8 OZ 20PP TO PROTECT LUB & LIFING
initial new brushes on generator still no charge
Polarized Generator NE
- New Battery
- Swapped out regulator for new - polarized generate still NG - Bad generator? yes! no ampera weak output
- Drain antifreeze w/ petcock open. WHEN VIEWED FROM TOP
FLASH Third till bubbles rise w/ distilled water and water meter
- Retighten cylinder head #3 NUT STICKS but
- Tighten intake manifold nuts to 14 FT (B) due to soft studs
- Change brake fluid - old fluid was clean - front rotor should be replaced
- Set pressures (this is at 20/25 cold + just now at a second)
front bumper 2 psi except at cushion bumper 5 psi,
70° Celsius hot pack
- Park cable came out of spring
- Main cooling system 5/8 - front was frayed. Will repair 2 pillows full coolant.
- Generator fan has no controller, remove →

8/5/08

Prep for Mt. Equinox.

Set - First time on Marelli coil w/ resistor - add set slug or .022" - old setting was .025 first 600 (same coil) .020 & .024"

Changed Shift 5 Speed.

9/3/9 Main Carb Drain plug almost completely stripped

- Note on 9/4/11 5 Speed Left Transmission mount was cut down .270" by previous owner. Made up .270" spacers and put in longer stud - This repair problems with throwout action, too deep in mounts and too far left
- Holddown Turning pointer Screw hole on bell housing (9/4/11)
- adder spacer ahead of clutch cable nut to allow adjustment of free pedal properly
- Check Distributor should give 45° at full advance when stock is 207 & 15° appears short a few degrees.
- Set air pressure to 2.0 & 25°F cold
- Dropout pressure to 18/23 hot due to rough road.
- Ram screen to 7800!
- Note on 7/11 2000+ prep. Inner exhaust header bracket went flange - bracket (7mm wide) is new carbon - shows to OK till next event
- Torque head. Change to 9/39 5 Speed.
- New Tires replace #5" Camper w/ 3 1/2" Front Techno Magneisio wheels to 2000. Put new wear lines on front

- Polar Festival 2006 starting 20-25 & 22-28 NWT
Temp ambient 72° water temp 19.5 w/ 768 cap
Seaplane flying well - no banks apparent.
- Prep for Sag Club event VSCCA June 07
 - Torque head - some more than others -
 - Change air cleaner muffed exhaust
 - Change oil + filter mobil 1.5/50
 - Bleed Brakes - ok!
- First race Prokupat 6500+ Fouled plugs + restrictions
Exhaust - too rich? or generator not charging =
low volts?
Second race cleaned up ran well

Prep for Summer Sprint

TORQUE HEAD, Bleed Brakes, checklist - ran well
Breaks occasionally at turns probably due
to restrictive street exhaust

Prep for Fall Fest 2007

- Detorque head - note: NUT #6 Jumps need to loosen a few times
- Dye test rear Stock axles - good!
- Detest water in head next to water outlet leak?
- Lubricate rear w/ synthetic gear oil
- Note tube in muffler will need repair
- Bleed Brakes - good so far!

Fall 2005

- replace Tach & Speedo cable,
clean & calibrate Tach & (Speedo - To actual tire size)
- Drain coolant & refill with Sierra antifreeze
- Note Charge indicator light does not go out
Check if charging - polarity?

5/01/06

5/8/06

- Drain & flush out left rear antifreeze, replace w clean water &
Add 6 red line water meter
- Polarized generator lith cell does not go out. Check on
Tach -

- Bleed Brakes - good pedal. No fluid leaks
- Found right front wheel was rubbing on brake caliper due to
insufficient mount washer thickness. Made thicker washers
in front caliper inboard by about $.030''$ for clearance

Drop in Mt. Equinox - note H.C. 5-Speed screw thread in flywheel
Timing indicator is stripped. will need Helicoil.

- Install 5 Speed H.C. Box
- Retorque head - Broke all nuts loose - retorq to 87 FT LBS
several screws were looser than others. First re-torque after
Fall 2005, Jay Clark 06.
- carbon hub at Jay Clark - hopefully due to 3 LB
Fiat Nutbrain cap. Installed 7 LB cap. for Equinox
- Set cold tire pressure to 18/23 for cold weather & wet
conditions, anticipated at Equinox
- Checked Timing, found it was at about 18° - re-set
to 15° mm sec.

06/2005 after VSCCA 500 Club meet.
Details near docket.

- Found #1 lash cap off valve. had dug hole through retainer + broken. Valve undamaged. Replaced retainer.
- Checked oil pump found much wear from metal that came off retainer. Oil filter full of metal. Changed oil pump to new Fiat unit. Cam bearings showed no sign of scoring - assume main bearings are also OK. Filter appears to have
- Valve gap checked out as follows:
E (1.025") (2 .025") (3 .025") (4 .025")
I (1 .011") (2 .011") (3 .010) (4 .010)

• Change oil + filter use mobil 1 15~50 synthetic
• Retorque head - with moment on nut.

-
- Chassis cracked where inboard rear susp attach. remove engine, trans, + interior for repair.
 - Welded up all cracks + reattached metal to suspension such as area where requires.
 - removed old Hiltam fuel injection hoses from intake manifold + welded up holes.
 - Left front wheel bearing lone- reset - but seems pin appears to be a bit loose to right side OK.
 - Zy gloed rear wheels around bolt holes ok. Blast + repaint.
 - Replaced rubber line from master cyl reservoir to master cylinder with correct, brake fluid resistant hose.
 - New Shoulder + lap belts
 - Re R. paint all splash shields around engine.
Good + go!

fall follow up notes:

Used some water maybe, pint fluid leak
near drain, under passenger compartment.
Tightened all clamps.

70% cocaine 16/23 after practice - reduced to
19/24 hot - max = 20/25 in race on hot
track

11/22/07
winter prep:
• Fill w SAE 50 Sierra antifreeze
Run engine & drain out.
• Remove plugs, spray cylinders w WD40, rotate
engine till 30PSI oil + replace plugs.

• 06/13/08 replace master sump belt.

Check valve gap

(E)	1.021	2 .020	3 .020	4 .020	no change ✓
(I)	1.011	2 .010T	3 .010	4 .009	2+4 changed ✓

RESET TO .010

-.001"

• Chain Tension seems unchanged

• Change oil - lot of metal filings in filter

From 05? a? non magnetic stainless chain
rubbing on case. Why? Chain tension appears
OK? Chain rubs on case below cam cover - tension
OK. No seizure

• Sump cover w/ new gasket

- clean & adjust points. Set to factory specs
- reduced carb. float lift in #4 carb jet
Set float to 8 mm w/ 15mm drop
- 11.5 cylinder exhaust flow was off valve, on top of
Spring retainer - replaced - good, runs well,
- compression test warm 140°

0) 160° 2) 180° 3) 140° 4) 145°

- Retried head 3 times, start and warm up 3 times.
Cold tail pressure 25 R 20 F

Jog Carb Jams 05:

overheated

- Engine overheats upon 5500 - replaced coil and points at time of rocking
Found 100 ohm resistance in condenser - new condenser measure, R=2K
Changed condenser, 2 m. 0.5, bush.
- small metal particles on drain plug.
- Install new NGK R7436-9 plugs clean to 7200 - went back
to old plugs in Friday and overheat disappeared. Conclusion
new plugs have extended tip. - Needed hollow plugs.
Carb note venturi 34 250 air 135 main. Shown by J.P. Mitchell
He felt a richer air cleaner would be better for hot weather.
Recommended just a little more, indicating beginning of pre-
ignition. Changed to 240 air cold weather recommendation
Gas fuel running 100%. w/ 220 air = 130 main

Clech Camshaft journal clearance. Tolerance is .020 mm ~ .062"

intake: Chain end	center	Plywheel end
.038 ~ .051 mm	.051 mm	.051 ~ .058 mm
.051 mm	.051 mm	.051 mm

valve gap w/ old Shim:

E	1	2	3	4
	.014"	.017	.018	.041 mm, .077 -.085" seat height width - width .043 mm = .038"
old shims	.089	.083	.077	.077

new .085" .080" .076" .058

I	1	2	3	4
	.060	.076	.075	.075
	.060	.075	.070	.0678
	.060"	.071"	.070"	.060" Cap

Tighten shaft gear nut (INNER SHAFT) on engine
end w/ 18 FT LBS w/ red LOCTITE

Boring top bolt diameter - used in bore

1 C .0704	.0704-.0704	.0705"
1 B .0704	.0703-.0704	.0705
		.0705

.0707 " .0705 ".0707 new size
main bearing .0002"

measured ends of rod in exhaust side of piston
rod receiver, half ball thickness

1 C	2 C	3 C	4 C
.0712	.0711	.0713 "	.0714
1 R	2 R	3 R	4 R
.0713	.0712	.0715 "	.0713

new clearance measured
.0711"
.0714 - new
dimensions

piston length 2.210 (piston) O.D.: .7085"

piston ring gap

TOP	.014	.013	.015	.013
2	.013	.010	.003	.013
OUT	.010	.013	.014	.010
	1	2	3	4

Plastigauge main 1.002" #2.002" #3.002"
Dynamometer exert in WD40 @ 45 FT LBS

both all .002" with 30 ft lbs

oil pump shaft shaft failure partially due to lack of
Shim between gear bushing block.

read dimensioner -
read shims in place!

E	1	2	3	4
	.089"	.083"	.077"	.077"
I	1	2	3	4
	.0766	.075	.075	.075

read gap east monomer before yesterday 0.4

E	1	2	3	4
	.089"	.089"	.085"	.080"


I	1	2	3	4
	.072"	.071"	.070"	.072"

Measure crank journals:

Rods 1.5743 all within Factor Specs 1.5742 ~ 1.5750

Main 2.1238 outside; 2.122 ~ 2.123

Bearing tang location:



TO 08529

MARLON CRAFT
ATTN: MARLON
83 LITCHFIELD ROAD
NORFOLK, CT 06850
(860) 542-6860

TO 08529

MARLON CRAFT
ATTN: MARLON
83 LITCHFIELD ROAD
NORFOLK, CT 06850
(860) 542-6860



VENOLIA

PISTONS AND RODS

A Product of TOR-CAM Industries, Inc.
2160 CHERRY INDUSTRIAL CIRCLE
LONG BEACH, CA 90805
Phone: (323) 636-9329 • (562) 531-8463
FAX (562) 633-9439

INVOICE NO.	08529
DATE	08/29/95

08529

S [] MARLON CRAFT
D [] ATTEN: MARLON
T [] 83 LITCHFIELD ROAD
O [] NORFOLK, CT 06850
 (860) 542-6860

S [] S-A-H-E
D []
T []
O [] (860) 542-6860

ORDER DATE	CUSTOMER ORDER NO.	JOB NO.	SALESMAN	TERMS				CUSTOMER NO.							
08/29/95	08529			DATE	CREDIT CARD			08529000							
SHIPPED VIA		FREIGHT	SELL	DIS.	NET TOTAL NO.	TOTAL WEIGHT	CTN NO.	P1	R2	R3	R4	R5	R6	R7	
UPS GROUND SERVICE (8529)							WEIGHT	1 LB	1 LB	1 LB	1 LB	1 LB	1 LB	1 LB	
ITEM	QUANTITY ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION											
1	0	0	08910	TEFLON BUTTONS TO 1.000" DIAMETER 2.574											
SUB-TOTAL:															
UPS GROUND SERVICE (8529) LESS DEPOSIT															
XXXX-XXXX-XXXX-0294															
MARLON CRAFT															

OUT OF STATE

THANK-YOU

Please pay from master -- No statement will be sent.

There is no warranty stated or implied due to the unusual stresses placed on racing parts and because we have no control of how they are used.

BALLOONCHARGE:

Buyer agrees to pay a ballooncharge of 2% (24% ANNUAL) on any overdue balance for each 30 day period in which such balance remains overdue and unpaid.

IN THE EVENT OF COLLECTIONS: The customer will pay all costs, including attorney's fees,

for merchandise may be returned without prior consent and is subject to 20% handling and/or restocking charge. All goods must be returned transportation charges prepaid. Claims for damage or shortage must be made within 6 days of invoice date.

Prices subject to change without notice.

PAGE 24

SHIPPING COPY

NAME 750 Fiat 700 C
 YEAR MODEL REBIRTH
 ENGINE

STREET _____
 TOWN & STATE _____
 HOME PHONE _____ BUS PHONE 542-0063

4-6-05

INVOICE NO.

NO.	PARTS	X AMOUNT	NO.	LABOR	X AMOUNT
	RINGS			CLEAN PIST. INSTALL RINGS	
	PISTONS			PRESS PIN JOBS	<u>BUSH. PINS</u> X <u>10.00</u>
	SLEEVES			INSTALL BUSHINGS	
	PISTON RINGS			CHECK RODS	
	PIN BUSHINGS			CLEAN POLISH CRANK	
	CON. RODS			CLEAN GRIND CRANK	
	BLOCK PLUGS			DISEM.	
	CRANK KIT EXCHANGE			DEGREASE TIN	
	ROD BRGS.			DEGREASE BLOCK	<u>5.00</u> X <u>25.00</u>
	MAIN BRGS.			BORE CYL. SIZE	
	CAM BRGS.			HONE CYL.	X <u>60.00</u>
	CAM SHAFT			INSTALL SLEEVES	
	CAM GEAR			INSTALL BLOCK PLUGS	
	CRANK GEAR			R&R VALLEY PLUGS	
	T CHAIN			INSTALL CAM SET	
	TAPPETS			LIN. BORE MAINS	
	EX. VALVES			ASSEM. S. BLOCK	
	INT. VALVES			ASSEM. COMPLETE	
	VALVE GUIDES			SURFACE BLOCK	
	VALVE SEATS			MACHINE GUIDES FOR SEALS	
	VALVE SPRINGS			SURFACE HEAD	<u>OK</u> X <u>60.00</u>
	VALVE SHIMS			INSTALL SEATS	
	VALVE SEALS			INSTALL GUIDES	
	ROCKERS			RECONDITION GUIDES	
	HEAD SET			MAGNAFLUX	
	FULL SET GASKETS			CARBN. VALVE JOB OUT VALVES - SAVIS X <u>110.00</u>	
	OIL PUMP			BALANCE ASSEMBLY	

DRILL FOR DIST. GEAR BUSHING

BL34 ← OK CAM SRK X
SV3 ← OK CAM SRK CLEAR. X
 CLEAN CAM THREADS X 10.00
 (use Plastique)

LABOR	<u>240.00</u>
PARTS	<u>254.40</u>
TAX	<u>14.40</u>

TOTAL PARTS _____

TOTAL 254.40

UNLESS OTHERWISE PROVIDED BY LAW, THE SELLER (ABOVE NAMED) HERBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH SALE OF SAID GOODS.

- Remove & replace rear stabilizer - Dye test ok OK
- remove & replace front hubs. Dye test ok, no cracks OK
- replace brake rotors on front with space original pair
rebuilt all calipers, new seals & new stainless steel pins
on rear calipers.
- remove & place master cylinder assembly, clean, new seals
- replace all flexible brake lines with new -
- Test cooling system to 14 PSI - Found several loose at
Hose connections. Fixed and held pressure for 20 min OK!
- replace brushes in generator - one had broken wire - probably
Caused by low charge w/ - nice wire ground was also broken - requires
new for heat.
- Post full technical note -
- engine breaking up over 6000 - check ignition
- check for brake fluid leak at reservoir master cyl.

6/13 Conclusion post 2quinoy: JP Mitchell says lined hose clamps
do not hold ~~the~~ regular hose well in re-clamping.
we lined clamps only w/ silicone blue racing hose
and cheap clamps elsewhere. 70 DD

- 1. Check all Hose connections.
- 2. Rebuilt Brakes.
- 3. Mag axles.
- 4. Mag (x-ray) wheels - visual test
- 5. Retorque head & adjust valves
- 6. Examine oil for water contamination
- 7. Gen does not charge, check polarization
- 8. Change to regular 5-Speed.
- 9. Tighten oil lines at filter, top in particular

- Compression test showed # 2 low by about 20LBS
air leaks through intake valve at TDC ~~at~~
- applied 60 + PSI TO each cyl at TDC with valves closed
no air bubbles in expansion tank. No bad head gasket?
- check Chain Tension OK
- check valves gap:

1. .012 TIGHT

E₁ .019

2. .012 "

2 .019

3. .011 TIGHT

3 .019

4. .012

4 .020

(I)

(E)

6/17 prep for Mt 2 quinny:

- install Hillclimb 5 speed + report driftgate
- water + red line
- bleed brakes
- note rear calipers drag a little may need rebuided
- repair broken rear muffler bracket to sump.
(fatig shear)

Blew off oil line from pump to filter at filter - non Aerogear fitting - fix! — Report hearings! replace airline!
oil pressure OK after each 90PSI hot. - with low bot at cold
10 or 20 bars (or as 30)

- cooling fan hit radiator - fix!

7/18

Pull sump bottom check bearing, rod bolt torque not recorded at engine assembler site. recall conversation with Dale Hall about PBS rods pulling threads if torqued to PDS threads max 35 FT lbs as recalled! not 45'. Checked #3 rod bearing light polish in stripes along length of bearing no scores - retorque bearing to 35FT lbs

- New Aerogear closer braided oil lines. replaced 3 lines early at filter with genuine Aerogear oil pressure at new 100PSI cold using 15/50 mobilene. at 20 miles steady 30PSI. no leaks. Changed filter no signs of contamination.

6/19

Prep for 3rd run of bleed brakes —

6/17/89

Mt 2 quinny note - Blew off top hose to Expansion tank twice. Engine bogged each time, but ran OK after replacing coolant. Compressor out in garage. 140° water temp.

#1 134, #2 124 #3 B2 HLI 140

06/02


Prep for Fall Festival.
Valve gap:

E 1 • .019 2 .019" 3 • .019 4 .020"

I 1 .012 2 .011 3 .0108 4 .012

original sharts intake is .010 cam makers suggest is .012
Left alone - good chain tension.

- FRONT Right chain case cover silicon trigger, review through Jaeger Fuel tank sender diagram



- Check Brakes -

- Check rear camber under load - 4°!

Spring I.D = ~~4.95~~ 5.95" O.D = 5.130" PAD O.D = 5.350" ~~approx 5.50"~~
 Left side ~~2.5~~ spacer = 1° change
 added $\frac{1}{2}$ spacer right left = ~~-4~~ 4°
 $\frac{3}{8}$ " right = $-4\frac{1}{2}$ "
 HEIGHT FREE 7.35"
 7 turns - 2"
 Sackur coil,

Check tire pressure, recheck camber after adding rear right f" bolt & nut,
 Set rear toe-in to $\frac{1}{16}$ " each side $\frac{1}{8}$ " total, marked line on tire tread with nail
 $+ - \frac{1}{8}$ "
 Set front toe-in to $\frac{1}{16}$ TOTAL max $\frac{3}{16}$ "
 End result: 15 Raps 80(±5) OIL 30 LOKENS y cloudy 75°
 MPH 185

10/4/02 - winterizing flush with 50/50 Sierra antifreeze - drain
 oil filter change 15/50 mobil 1
 Spray cylinders with "Deep Creep" solute engine w seal

8/11

Alignment cont. measured toe by taking measurement from front & rear edge of tire by engaging tape measure in nearest tread groove. Checked also against rim OK both measurements.

- Fall Festivals note: car very much more stable, particularly under hard braking. Plays never fouled and exhaust color is perfect. 25 min / 20 front tires remains good. 4000 -

9/17 Drain coolant except with 50/50 antifreeze & drain after decoking, 10 min.

10/20 Fall Final. Started first, finished third overall all 4 races.

- check royalties counter in road too much.
- Car runs better with street and exhaust than race header.

Wheel problem H's Front 40401 4.5413
Rear

- Drain oil & Change filter. Cut open filter & examine: some minor amt of metallic particles far less than first filter change. Conclusion: normal breakin wear. Ran engine about 3-4 hours this year 2 hrs - Fall finals. 1 hr Fall Fall 45 min - Equinox
- note antifreeze on H 4 spark plug well - probably comes from stud nut or left between 3 & 4 seal up!
- removed all spark plugs & spray with "Deep Creep" silicone grease with plugs out 2 side cylinders, cleaned & sone for mouth

- 6/20
• replace rear shock rods - bleed brakes
• repair left Carb heat Shroud
• Switch to NOK plug

- 6/21 notes, on Mt. Equinox: Car ran very well, except carbs loaded up badly with fuel on first run down using lead 8mm OK. Next run down used 4TH & FIFTH, NOK plug perfect - get second set for second run.
→ R5687-9

- runs regular off 9 gear box very nice to halfway, except for last 2 hair pins. Hit third before first run.

- 6/24 Prepare for matkins glen -

- Torque bolts - all fine
- replace fuel line from fire wall - was chafing on right carb Throttle lever
- Fan belt should be replaced - also check generator mount. Reinforce

- 8/15 • Install new NOK plug - number changed from old R56879 to R7238-9 set gap to .025 - need range was lower + ran OK!
• Check links
• Change fan belt - maple 7312
• Check the front + rear $\frac{1}{8}$ near frame $\frac{1}{16}$ was almost $\frac{1}{8}$ " (use string box method) and weighted car with my weights on dinner table - G Concert Plaza.
rechecked with Bay Square in car centerline - OK
Re-set to $\frac{1}{16}$ " front $\frac{1}{16}$ " rear - OK

02/00 remove disassemble front hub - install spacers
left front may not run due
may originally - case D

08/00 prep for Fall Festival
• Chain Tensioner STICKS

		about 70			
4	E = .023"	- .020"		.050 MM	.0196" Chamfer
3	E = .022" -> .020"		all	I = .013	no spacer shims p. 012
2	E = .023" .020"		TIGHT	I = .012	Torque cam journal cap nuts to 16 FT LBS
1	E = .024" .020"			I = .012	

- reorganize head:
~~front~~ grade
- 4 ~~front~~ dome nut loose + stripped replaced with new stud + nut,
using OEM steel washers and corrugating nuts
replaced hardened washer under stud between 3+4 intake
with own cover washer + steel washer. will surely hold
torque, but not load.
- reset float, right main was dripping fuel from aux -
idle, venturi + pump jet. found right set to 6 mm
left set 707 observed different fuel levels in bowls
reset to 5MM 15 drop - problems gone.
- reset Tolin - was out $\frac{3}{16}$ " set to $\frac{1}{16}$ " Tolin
- Fall Festival 700 pressure, 30 rpm 23 front hot cold ~~2000~~ = 5/20
- Champion Fuel - cleanup of 3 days duration 1:19.4
- 1/17/00 Change oil + filter. First filter change since engine
built. Examination of filter showed fine white metal
particles in element. Conclusion - break in metal from
ring, + cam gear. 15/50 molten 70mm w/ filter
- Fall fort note. get better mesh slugs! - replace rear bushing today
repair & seat bushing on left carb page 16

black paint does not stick to metal - too low
temperature. Steel nuts w/ dome nuts. Nut
between D44 or intake side will not hold.
Type of copper sealing washer is used due to
insufficient thread length. Tagged to 364788

8/99 prep for Fall Festival

- cylinder stub after - OK
- new Danlors
- valve gap After fall fest 98 and approx 99

E	1	2	3	4	
	.024	.023	.022"	.025"	
	+.001	+.002	+.001	4	
1	1	2	3		
	.011"		.011	.013	
		.012			+.002 change
Change	-.001"	very tight			
		NC			

Did not
readjust gap

- Chain loose - result tension. may 10 mm result to 5 mm
fall festival.
- Tire pressure F: 26 R 30 - Jim Duffield suggestion
- Plow fouled at high rpm's. Checked & set point gap - cutting timing
was too tight set at D14
- Fifth wheel - rentals 27/28?
- Front radiator cap. need now + spring to hold + tight
- Brake pedal very firm - makes trax w/ 5% turns increase in
rear circuit. Tendo front pads - front/rear
- Tire pressure - results F: 26 R 30 Thread did not contact track
fully, especially on outside left. Try lower pressure to get
full tread contact.

check camfollower clearance between full lift
and bottom of box: (1000cc cams)

	1	2	3	4
E	.103"	.057"	.063"	.125"
	.103	.138"	.100"	.125"
				after grind for clearance
I	'	2	3	4
	.093"	.061"	.081"	.085
	.091"	.095"	.098"	.105"
				after grind for clearance

2. Combustion chamber (H1) 36°

3. Torque cam gear screws to 70 FT LBS 14mm x 1.0

4. check valve gap with final assembly

	1	2	3	4
I	.012"	.012	.011	.011
	.023	.021	.021	.023
E	1.	2	3	4
	.023	.021	.021	.023

5. Torque distributor drive gear nut to 28 FT LBS
and lock

COMPUTE COMPRESSION RATIO 835cc Bialbero	Date	08/27/9	
ENTER: Cylinder bore mm	mm	65.4	
ENTER: Stroke mm	mm	74	
Cylinder displacement cc	cc	248.59	
ENTER: Head gasket bore dia mm	mm	65.4	
ENTER: Head Gasket thickness mm after break-in	mm	1.14	.045"
Head gasket displacement cc	cc	3.830	
ENTER: Cylinder bore mm	mm	65.4	
ENTER: Piston to deck height in inches	in/mm	0.000	0.00
Cylinder displacement cc	cc	0.000	0.000
ENTER: Combustion chamber cc	cc	36	
ENTER: Piston dome cc	cc	11.52	
Cylinder, combustion chamber, head gasket, deck to piston volume mm	mm	268.42	
Cylinder volume less piston dome cc at bottom dead center	mm	276.90	
Compressed volume cc at top dead center	mm	28.31	
COMPRESSION RATIO		9.78	: 1
ENTER: Gasket height, new, before break-in	mm	1.4	
ENTER: Shortest valve to piston clearance from clay test in inches	in	0.110	
Valve to piston clearance in mm	mm	2.79	
Valve to piston clearance after break-in in inches	in	0.100	
D21(line above) calculates result of change in gasket thickness only			

COMPUTE COMPRESSION RATIO B35cc Blaiberg		Date	08/27/9	
ENTER: Cylinder bore mm	mm	65.4		
ENTER: Stroke mm	mm	74		
Cylinder displacement cc	cc		248.59	
ENTER: Head gasket bore dia mm	mm	65.4		
ENTER: Head Gasket thickness mm after break-in	mm	1	0.39"	
Head gasket displacement cc	cc		3.359	
ENTER: Cylinder bore mm	mm	65.4		
ENTER: Piston to deck height in inches	in/mm	0.000	0.00	
Cylinder displacement cc	cc		0.000	
ENTER: Combustion chamber cc	cc	35		
ENTER: Piston dome cc	cc	11.52		
Cylinder, combustion chamber, head gasket, deck to piston volume mm	mm		287.95	
Cylinder volume less piston dome cc at bottom dead center	mm		276.43	
Compressed volume cc at top dead center	mm		27.84	
COMPRESSION RATIO			9.93 : 1	
ENTER: Gasket height, new, before break-in	mm	1.4		
ENTER: Shortest valve to piston clearance from clay test in inches in	in	0.110		
Valve to piston clearance in mm	mm		2.79	
Valve to piston clearance after break-in in inches.	in		0.094	
D21(line above) calculates result of change in gasket thickness only				

CC-Domey piston : 20Lm set at .12.36" below deck
 add 30cc fluid to fill cylinder under plate

$$12.36 \times 65.4 = 41.52 \text{ cc}$$


$$- 80.$$

$$\text{Dome volume} = \frac{11.52}{}$$

1. Initialled spring height base measurements using afa/absent retainer and .000" spacer on top retainer. No spacer at bottom of bore. measured with dial indicator or depth gauge

Intake	(1) .119	(2) .145	(3) .183	(4) .193	
	1.654"	1.663"	1.649"	1.657"	
	.030	.030	.010	.030	

Effluent	1.625	1.644	1.642	1.646	
	.385	.381	.385	.385	
	.030	.045	.045	.045	



Custom spring seat
Thickness

2. Set valve gap with weak springs

Intake	(1) .010+	(2) .011	(3) .011	(4) .010+	
	.076	.076	.075	.0715	

Fresh cap Thickness

Effluent	.020	.019	.019	.020"	gap
	.085"	.08"	.075"	.08"	Fresh cap Thickness

Turned 55/85/75/95

3. Timing check exhaust open @ 72° close @ 95°
(Early)
Intake open @ 53° close @ 67° monring pin
(late) OIC results in % change.

4. Valve to piston check using dial indicator

(I)	#1	#2	#3	#4
	.044@ 70°	.066"	.085@ 70°	.086" Before cam start
	.105@ 70°-80°	.120@ 70°	.095@ 70°	.100" after

(E)	#1	@ .71°-80°	@ 71°	.125 before
	.105"		.067"	
	107@ 85°	.066	.150@ 85°	.114" af/in @ 85°

1. Distances from base circle to cam follower seated on valve stem
(with out lash cap.)

Ex	1	2	3	4
zero value gap	.157"	.167"	.154"	.161"
	-.020	-.020	-.020	-.020
	.137	.147	.134	.141
zero desired lash cap thickness +.005"	-.075"	-.075"	-.075"	-.075"
	—	—	—	—
	<u>.062"</u>	<u>.072"</u>	<u>.059"</u>	<u>.066"</u>

IN	1	2	3	4
	.107"	.105"	.122"	.110"
	-.010	-.010	-.010	-.010
	.097	.095	.112	.100
	-.075"	-.075"	-.075"	-.075"
	—	—	—	—
	<u>.022"</u>	<u>.020"</u>	<u>.037"</u>	<u>.025"</u>

2. Sink valves into head by amount above
3. Cut new valve faces down to match original values. → (need to remove about .020" - TOP OF STEM SHOULD BE AT SAME INSTALLED HEIGHT AS O.E.M. VALUE.)
4. Machine spring retainers to fit springs supplied
5. Check fit of valve stems in guides - fit clearance if needed.
6. Supply spring seat washers as thin as reliable to fit guides and cam follower base.

1. Bush and float .006 with .005 oversize, working.
2. Chipped cap when it fits. Must weaken - file or square.
3. Piston does needs either clearance or counterweight
Clear Test Dimension:
1.025" 2.010" 3.010" 4.010"
4. Precision evennesses Min. .050"
5. Jason's holes in head about valve head to cylinder deck head deck distance: "Evening value

1	2	3	4	Intake
.033	.037	.022	.031	

1	2	3	4	Exhaust
.107	.097	.111	.105	

~~Cam base circle to~~

Cam follower travel from cam ~~base circle~~ to Top of valve stem with valve on seat (without lash cap) using standard shaft 750 valve.

1	2	3	4	Intake
.107"	.105"	.122"	.110"	

1	2	3	4	Exhaust
.157"	.167"	.154"	.161"	

Alt. vs 1000 CA Engine de Giovanni. 1997

- Followed all scores of 10 hand return from 205. Polaris
- #1 combustion chamber 36 w champion racing oil.
- Valve spring compressed length (car first) .22 cm O
- approximate installed height 37 mm O
- lift 9.2 mm

$$\frac{3.50}{\cancel{2.0}} \\ \cancel{1.5} - \text{travel}$$

$$\frac{9.2}{3.8 \text{ mm. Travel}} \\ \text{lift at full lift}$$

13 kg spring load until 220° = 16.29 mm

$$\begin{array}{r} 13 \text{ kg} \\ \times 9.81 \text{ N/kg} \\ \hline 127.52 \text{ N} \\ \times 10^3 \text{ N/mm} \\ \hline 127.52 \text{ N/mm} \\ \text{approximate installed height} \\ \text{WSTD } 750 \text{ configuration} = 27 \text{ mm} \\ \hline 29 \\ 113 \text{ mm. total} \\ \hline 10.7 \\ \text{lift} \\ \hline 1.5 \text{ mm.} = .059 \text{ in. or } 0.10'' \end{array}$$

7.7 15°

7.7 20°

7.7 25°

PROFILO 062

nuova

IMPIEGO
INTERGO

LIFT
ALZATA

ASP.
SCE.

9.4 (ESIGIBILE)

TAMMI CULISSETTI

COP. SISTEMI

LIFT

ASP.
SCE.

ANGOLI DI LAVORO

SCA.

PERMETT

CON SISTEMI
PUNZETTI:

0.20

0.25

0.30

0.35

0.40

0.45

0.50

322°

312°

304°

302°

CON CALETTI DI 105° (SUPORTO)

INCROCI AL P.M.S./U.D.C.

COP. SISTEMI

PUNZETTI:

0.20

0.25

0.30

0.35

0.40

0.45

0.50

57°

51°

47°

49°

TAMMI CULISSETTI

COP. SISTEMI

LIFT
ALZATA

ASP.
SCE.

ANGOLI DI LAVORO

SCA.

PERMETT

CON SISTEMI
PUNZETTI:

0.20

0.25

0.30

0.35

0.40

0.45

0.50

52°

51°

50°

49°

INCROCI AL P.M.S.

SCA.

PERMETT

INCROCI AL P.M.S.

SCA.

PERMETT

PROFILO 061

nuova

IMPIEGO
INTERGO

LIFT
ALZATA

ASP.
SCE.

ANGOLI DI LAVORO

SCA.

LIFT

ASP.
SCE.

ANGOLI DI LAVORO

SCA.

PERMETT

CON SISTEMI
PUNZETTI:

0.20

0.25

0.30

0.35

0.40

0.45

0.50

58°

57°

56°

55°

54°

53°

52°

51°

50°

49°

48°

47°

46°

45°

44°

INCROCI AL P.M.S.

SCA.

PERMETT

INCROCI AL P.M.S.

SCA.

PERMETT

9 HERMAN DRIV. SIMSBURY, CONN. 06070
(203) 651-3418

MAKE FIAT
YEAR
ENGINE

NAME J. J. NELSON CRAFT
STREET
TOWN & STATE
HOME PHONE BUS. PHONE

5-21-97

INVOICE NO.

NO.	PARTS	QTY AMOUNT	NO.	LABOR	QTY AMOUNT
	RINGS			CLEAN PIST. INSTALL RINGS	
	PISTONS			PRESS PIN JOBS	
	SLEEVES			INSTALL BUSHINGS QJ + HONE	X 20.00 /
	PISTON RINGS			CHECK RODS H.D. R.	X 40.00 /
	PIN BUSHINGS			CLEAN POLISH CRANK	X 25.00 ✓
	CON. RODS			CLEAN GRIND CRANK	
	BLOCK PLUGS			DISEM.	
	CRANK KIT EXCHANGE			DEGREASE TIN	
	ROD BRGS.			DEGREASE BLOCK	X 25.00 /
	MAIN BRGS.			BORE CYL - SIZE $\frac{7}{8}$ IN	X 100.00 /
	CAM BRGS.			HONE CYL	
	CAM SHAFT			INSTALL SLEEVES	
	CAM GEAR			INSTALL BLOCK PLUGS	
	CRANK GEAR			R&R GALLEY PLUGS	
	T. CHAIN			INSTALL CAM SET	
	TAPPETS			LIN BORE MAINS CK	X 25.00 /
	EX. VALVES			ASSEM. S. BLOCK	
	INT. VALVES			ASSEM. COMPLETE	
	VALVE GUIDES			SURFACE BLOCK	X 35.00 /
	VALVE SEATS			MACHINE GUIDES FOR SEALS	
	VALVE SPRINGS			SURFACE HEAD	
	VALVE SHIMS			INSTALL SEATS	
	VALVE SEALS			INSTALL GUIDES	
	ROCKERS			RECONDITION GUIDES	
	HEAD SET			MAGNAFLUX ROPS	X 30.00 /
	FULL SET GASKETS			VALVE JOB	
	OIL PUMP			BALANCE ASSEMBLY	X 175.00 /
				SWIT. PLATE 2023	X 50.00 /
				LIGHTER PLATE	X 15.00 /
1	15mm TAP	0.50		GLASS BREAK ALARM PARTS	X 45.00 /
1	CAM PLUG	1.00		CHAMPION BOLT PARTS 2025	X 25.00 /
				DRILL SHAFT HOLE PLATE	X 10.00 /
				OL. GALLON 1. RADIATOR PLATES	X 60.00 /
				FIT CRANK BEARINGS	X 40.00 /
				TAP BACK SO FIT BOLTS 2040	X 70.00 /
				Part Cams Cam BORG-BILLET	X 60.00 /
				STEEL OIL PLATE (FATIGUE PLATE)	X 10.00 /
				KWIK-OL OL PUMP SPARE PARTS	X 15.00 /
				PLUG CRANK GEAR	X 20.00 /
				DRILL PLATE HOLE	X 10.00 /
				LABOR	1032.00
				PARTS	26.00
				TAX	6.50
				TOTAL	1064.50

TOTAL PARTS 21.00

TOTAL 1064.50

ESTIMATES ARE FOR LABOR ONLY. MATERIAL ADDITIONAL. I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE
ALONG WITH NECESSARY MATERIALS. It is understood that this company assumes no responsibility for loss or damage by theft or
fire to materials placed with them for storage, sale or repair.

CRAFT

2.5, 2.5, 2.5
DATE

- Machine work to convert pushrod block to DOHC -

Block is rare item. When in doubt please call first!

Parts list:

- Bare Fiat-ABARTH block# AB210 1586414
- New 74mm stroke Abarth 1000cc crank
- Flywheel
- Pressure plate assembly
- Fiat rods, new - not matched set.
- 65.4mm forged Piston set with rings & Pins, new (Italian import, custom made.)
- Bearing set: Mains, Rods & Thrustwasher.
- Flywheel end cam bearing and bore plug.
- Oil pump drive shaft bearing.
- Oil pump drive shaft
- Bronze crankshaft pilot bushing.
- Oil line banjo stud.
- Transmission input shaft.

T35

Work required, Block:

- BORE & FIT PISTONS. Note ring gouge in #1 bore near top. Pistons supplied are for 65.4mm bore with .0035" clearance. If bore does not clean up - CALL me.
- DISTRIBUTOR SHAFT HOLE PLUG. Make plug to fit distributor drive shaft hole hole in top of block. Hole is marked 1 on attached drawing.
- OIL GALLERY RESTRICTOR PLUGS. Machine and install aluminum restrictor plugs with .090" passage hole in oil feeds to head. These are shown as 2 and 3 on the attached drawing.
- CHECK DECK FOR STRAIGHT, remove ABSOLUTE minimum required. >>Cut deck only after all plugs are installed. Plugs must be flush with deck.<<
- FIT CRANK to bearings. Clearances: Mains: .0020" - .0025"; Rods: .0018" - .0022"

- 2.2665²
2.2670²
- CHECK HOUSING BORE for straight, align bore if required. Main bearing cap screw torque 45 ft lbs.
 - Note # 1 main bearing is reversed to align with late model crank. Main cap is drilled 5/32" for roll pin to match oil hole in bearing.

18 x 1.5 TAP PRACTICE

- 1 $\frac{1}{2}$ $\frac{1}{2}$ TAP BLOCK TO FIT OIL LINE BANJO STUD. Tap center hole ON SIDE OF

72

$\frac{1}{2}$ Holes BLOCK to main oil gallery to fit stud supplied.

- 1 $\frac{1}{2}$ Holes PLUG CENTER CAM BEARING BORE. Machine and install press fit plug with oil passage hole for center cam journal.

60

- * Flywheel end (Near #3 main cap) cam bearing CAM BEARING . Install cam bearings as plug. No cam will be installed in block. Rotate as required to block oil flow. Install cam bore plug in flywheel end of block.

10

- ✓ → * Enlarge clearance hole in bottom of block for oil pump drive shaft to clear gear.

15

- ✓ OK * Check fit of oil pump drive bush to shaft, clearance: .001-.0025, wear limit .005". If excessive install new bush supplied.

N/C

Work required Crankshaft:

- 71 72 → * Install plugs in crankshaft oil gallery holes.

X 2 R T H A R D C R A N K 80

- ↳ * Drill out pilot hole to a depth of : 1." and fit pilot bush.

S T R E T C H I N G P L O G 180

- ↳ * Fit pilot bush to input shaft supplied.

C A N T T H P

- * Polish crank.

25

Work required Conrods.

- * MAGNAFLUX
- * CHAMFER rod cap bolt hole to clear custom rod bolt.
- * SHOT PEIN to relieve stress.
- * Fit bearings to crank. (See clearances above)
- * Rod bolt torque. See sheet attached to bolt bag
- * Fit pins. Clearance, thumb pressure fit. Factory specs are .00004" - .0005"
- * When balancing rods, use care when removing material so as not to weaken caps, particularly on the ridges.

Other work:

- ↳ * Lighten flywheel

70

- ↳ * Balance assembly


155

- ↳ * End clearance rings per standard machine shop practice for bore size, do not reinstall on pistons.

C H A R G E O N L Y
C I R C U M F

6137
N/C 0.6 mm

QUESTIONS? Call: Mahlon Craft at 860-542-6060, fax 860-542-6029



LIKE THIS?
THEY HOLE?

CHECK FIT OF HEAD GASKET TO BLOCK,
NOTE PROBLEM OF SUPPORT FOR GASKET,
HOLE IN HEAD GASKET WILL BE O-RINGED
TO PREVENT OIL LEAKS - (COMMON PROBLEMS)
DECK SURFACE MUST BE SMOOTH, PLUG SHOULD
FIT WITH NO GAP

1000 Maomile 99 feathered - cont.

male most w/ showed signs of corrosion
in pedal coil. Seals were beginning to go
bad, particularly inner seal.

replaced outer pump seal
replaced outer seal in engine bay
installed cables satisfactorily.