



Payment details

**Ali Castillo****"Mercedes 280C trunk and side
step paint."****- \$1,200**

Social activity



Status

Complete

Payment method

**Visa Debit**

Debit •••• 8960

Transaction details

May 27, 2022, 3:17 PM • **Private**

Paid to

@Ali-Castillo-2

Type of transaction

Payments between friends

Mercedes-Benz Classic

Mercedes-Benz USA LLC

9 Whatney · Irvine, CA 92618-2808

(949) 598-4850

Toll-free: 1-866-MB-CLASSIC (622-5277)

Fax: (949) 598-4860

Email: classicparts@mbusa.com

Web: www.mbusa.com/classic

CLASSIC PARTS SALES

DATE ENTERED 10 MAR 22	YOUR ORDER NO.	DATE SHIPPED 10 MAR 22	INVOICE DATE 10 MAR 22	INVOICE NUMBER 207633
---------------------------	----------------	---------------------------	---------------------------	--------------------------

S
O
L
D

T
O

S
H
I
P

T
O

PAGE 1 OF 1

SHIP VIA TODAY	SLSM. 332	B/L NO. 541273820043	TERMS VIS MASTERCARD	F.O.B. POINT IRVINE, CA
-------------------	--------------	-------------------------	-------------------------	----------------------------

ORD	QUANTITY	B.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	109-973-06-11	COVER	27.50	23.37	23.37
1	1	0	Q-4-76-0037	MASTERKEY	29.50	25.07	25.07
			SHIPPING & HANDLING			10.89	

We are not responsible for errors on parts orders when the part number is furnished to us by the purchaser.

We will not be responsible for any damage to any vehicle caused by parts used on a model they were not specifically intended for, nor is there any warranty on such parts.

All parts shortage and damaged part claims must be made immediately upon receipt of order. All shipments must be signed for upon delivery, unless we are instructed otherwise. We bear no responsibility for a lost shipment released without a proof-of-delivery signature.

Parts returns must have prior authorization and must be accompanied the original sales invoice within 30 days of the original purchase. All returned parts must be their original packaging with our picking label affixed and in saleable condition. No returns on electrical parts if the package has been opened and/or unsealed. No returns on "Special Order" parts. No returns on parts that have been "test" installed, painted, modified, altered or disassembled in any way.

All parts returned are subject to a 20% re-stocking fee. We are not responsible for shipping charges on parts returns. We will pay return freight charges only if we made an error on the parts order.

Core returns must be shipped within 30 days of the exchange part purchase. Cores must be returned in the same package the exchange part was supplied in. The core must be a genuine Mercedes-Benz part in rebuildable and complete condition to satisfy our core deposit refund obligation. The original core deposit invoice must be sent with the return. We will not pay shipping charges on core returns. Failure to return a core will result in forfeiture of the respective core deposit.

PARTS	48.44
SUBLET	
SHIPPING & HANDLING	10.89
SALES TAX	5.12
TOTAL	\$64.45

CUSTOMER'S SIGNATURE
X

SEE REVERSE SIDE FOR IMPORTANT WARRANTY INFORMATION

Mercedes-Benz Classic Center USA

Term ID: 001

Sale - Approved

Date	03/10/22	Time 16:14:28
Method of Payment	Visa	
Entry Method	Manual	
Customer Name		
Account #		
Order ID	207633	
Approval Code	02875B	
Amount	\$64.45	

Customer Copy

WALLY'S AUTO UPHOLSTERY
 2707 GEARY BLVD., SAN FRANCISCO, CA 94118
 (415) 567.7907

A 4303

SOLD TO



3-1-22

CAR LICENSE	CAR MAKE	UNIT PRICE	AMOUNT
8XU V 22P &	1973 280C coupe		
P.O. NUMBER CHOOGS	DESCRIPTION Mercedes		
	Replaced Headlining	\$ 1,500	00
	ARM Rest Repair	\$ 285	00
	PAID		
		Dep	\$ 500 00
Ch. 1023		BALANCE	\$ 1,298.12
		TOTAL	\$ 1,798 12
APPROVED BY			

CC-I INVOICE QUOTE (I) cmbc321 3461

Number: Q121314

Cust: 16430

Name:

Addr:

C/S/Z:

Phone:

Emp: 321

Via:

Invoices:

Zone:

Sale Type: VISAMC

Price Code: 7

Salesperson:

B/L:

PO:

Parts: 25.07

Fees: 0.00

Freight: 0.00

Tax: 0.00

Total: 25.07

Primary	Order	Price	Local	Locate			
PART-NO.	DESC	O.H.	BIN	Q.S.	LIST	SALE	
Q-4-76-0037	MASTERKEY	1	CKEY	1	29.50	25.07	

Ship To
114 073 12 001412
CODE HD 4883

<Expanded> <Page 1 of 1> <1 part>

York's Motorwerke

1531 Second Ave.
 Walnut Creek, CA 94597
 PH: 925-930-7676
 FX: 925-930-7009
 HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# 55545

DATE: 11/05/21 01:04 pm

PAGE: 1

TERMS:

CUSTOMER:	VEHICLE: - MERCEDES BEN 280 COUPE
ADDRESS:	LICENSE: MYRA PR/ FLEET:
CITY:	VIN: 11407312001412 11/72
PHONE 1:	ENGINE: Cyl Disp
PHONE 2:	MILEAGE: 95140 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
JY			INSTALL RADIO INSTALL RADIO		174.25
DN			ANTENNA LOOK FOR A FACTORY ANTENNA REPLACED THE [POWER ANTENNA WITH THE SAME BRAND THAT WAS INSTALLED. REMOVED THE MANUAL SWITCH AND WIRED THE ANTENNA TO GO UP OR DOWN WITH THE RADIO SWITCH		174.25
DN	1.0	URO-014333	POWER ANTENNA	130.91	
DN			OIL LEAKS FOUND THE FUEL PUMP LEAKING ENGINE OIL AND THE POWER STEERING PUMP LEAKING P/S FLUID. REPLACE LEAKING POWER STEERING PUMP AND FUEL PUMP REINSTALL RADIATOR SO THAT IT WILL CLEAR THE FAN SHROUD		609.88
	1.0	PS1	POWER STEERING FLUID	4.25	
	2.0	PC1	PARTS CLEANER	17.00	
	1.0	115 460 09 80	Power Steering Pump	432.06	
DN	1.0	115 090 01 50	Fuel Pump	162.30	
DN			RADIATOR FAN IS HITTING THE RADIATOR SHROUD REMOVED RAIATOR AND REMOUNTED TO CLEAR THE FAN. LABOR WAS PART OF THE OIL LEAK REPAIR		0.00
JY			FUEL SMELL CUSTOMER IS SMELLING GAS IN THE CAR FOUND FUEL LEAKING OUT OF THE FUEL PUMP AND THE CARBURATOR ACCERATOR PUMP REPLACED THE FUEL PUMP AND REMOVED THE CARBURATOR TO REPLACE THE ACCERATOR PUMP DIAPHRAM		209.10
DN	1.0	000 586 76 07	Carburetor Kit	132.63	
			DOME LIGHT		0.00

CUSTOMER REQUEST RETURNED PARTS YES NO

PAYMENTS / SURCHARGE DETAIL

TOTALS

RECOMMENDATIONS

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) 

LABOR:\$	1,469.31
PARTS:\$	1,008.90
SURCHRG:\$	0.00
SUBLET:\$	0.00
SUPPLIES:\$	0.00
DISCOUNT:\$	0.00
TAX:\$	88.28
TOTAL:\$	2566.49
PAID:\$	0.00
DUE:\$	2,566.49

York's Motorwerke

1531 Second Ave.
Walnut Creek, CA 94597
PH: 925-930-7676
FX: 925-930-7009
HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# 55545

DATE: 11/05/21 01:04 pm

PAGE: 2

TERMS:

CUSTOMER:	VEHICLE: - MERCEDES BEN 280 COUPE
ADDRESS:	LICENSE: MYRA PR/ FLEET:
CITY:	VIN: 11407312001412 11/72
PHONE 1:	ENGINE: Cyl Disp
PHONE 2:	MILEAGE: 95140 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
DN	1.0	114 LIGHT	INSTALL DOME LIGHT ORDERED FRONT DOME LAMP	110.00	145.00
DN			SEAT BELT REPAIR THE DRIVERS SIDE SHOLDER HARNESS FOUND GOOD USED PARTS AND REPAIRED THE SEAT BELT		139.40
DN			SPEAKER THE CUSTOMER WOULD LIKE US TO REINSTALL THE SPEAKER COVER REMOVED THE COVER ANMD FOUND THAT THE WOOD HAD BEEN FOAM TAPPED TO THE COVER AND THAT THE COVER WAS MISSING THE CLIPS THAT HOLD THE COVER INTOM THE DASH GLUED THE WOOD TO THE COVER AND REPLACED THE CLIPS		17.43
DN	5.0	LB	TAIL LIGHTS CHECK THE TAIL LIGHT OPERATION REPLACED TAIL LIGHT BULBS light bulb	19.75	0.00
DN			TIRE INFLATION TIRE INFLATION SERVICE CHECK AND INFLATE EACH TIRE TO THE RECOMMENDED TIRE PRESSURE RATING. TIRE INFLATION MEASUREMENTS AFTER COMPLETION OF SERVICE/WORK: FRONT: 32 PSI REAR: 36 PSI.		

CUSTOMER REQUEST RETURNED PARTS YES NO	PAYMENTS / SURCHARGE DETAIL	TOTALS
RECOMMENDATIONS		LABOR:\$ 1,469.31 PARTS:\$ 1,008.90 SURCHRG:\$ 0.00 SUBLET:\$ 0.00 SUPPLIES:\$ 0.00 DISCOUNT:\$ 0.00 TAX:\$ 88.28
	I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. (Signature) _____	TOTAL:\$ 2566.49 PAID:\$ 0.00 DUE:\$ 2,566.49

Date: 8/31/2021 11:03 AM
 Estimate ID: 6745
 Estimate Version: 0
 Preliminary
 Profile ID: AJC Auto Body

AJC Auto Body

250 Napoleon Street - Unit # P AJCAUTOBODYSF.COM, San Francisco, CA 94124
 (415) 821-4745
 Fax: (415) 821-1935
 Email: ajc Autobody@sbcglobal.net

Damage Assessed By: Ali Castillo
 Classification: Drive-In

Type of Loss: Collision
 Deductible: UNKNOWN

Owner:
 Address:
 Telephone:

Mitchell Service: 911000

Description: 73 MERCEDES 280 C COUPE
 OEM/ALT: A

Search Code: B788264

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDS *	REPAIR	REPAIR DENTS	Existing		25.0*
2	900500	BDY *	REPAIR	TOP COLOR 920 DEEP BLUE 2- BODY COLOR 73	Existing		0.0*
3	900500	REF *	REPAIR	COMPLETE PAINT OUTSIDE-TWO TONE .	Existing		50.0*
4	900500	BDY *	REMOVE/INSTALL	REMOVE AND INSTALL MOULDINGS AND BUMPE	Existing		10.0*
5	AUTO		ADD'L COST	Paint/Materials		2,500.00 *	
6	AUTO		ADD'L COST	Hazardous Waste Disposal		5.00 *	

* - Judgment Item

① Undercoating
 ② Paint Doors edges

Remarks

TOP COLOR. 920 DEEP BLUE 2 BODY COLOR 735
 ASTRAL SILVER

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	10.0	110.00	0.00	0.00	1,100.00	Total Replacement Parts Amount	0.00
Bdy-S	25.0	110.00	0.00	0.00	2,750.00		
Refinish	50.0	110.00	0.00	0.00	5,500.00		
Non-Taxable Labor					9,350.00		
Labor Summary	85.0				9,350.00		

ESTIMATE RECALL NUMBER: 08/31/2021 11:01:48 6745

Mitchell Data Version: OEM: JUN_21_V

MAPP:JUN_21_V

Copyright (C) 1994 - 2021 Mitchell International

III. Additional Costs	Amount	IV. Adjustments	Amount
Taxable Costs	2,500.00	Customer Responsibility	0.00
Sales Tax @ 8.500%	212.50		
Non-Taxable Costs	5.00		
Total Additional Costs	2,717.50		

Paint Material Method: Rates
 Init Rate = 50.00 , Init Max Hours = 99.9, Addl Rate = 0.00

*\$500.00 Extra
 To fix front bumper
 Frame bracket.*

I.	Total Labor:	9,350.00
II.	Total Replacement Parts:	0.00
III.	Total Additional Costs:	2,717.50
	Gross Total:	12,067.50
IV.	Total Adjustments:	0.00
	Net Total:	12,067.50


09-01-2021

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

I HEREBY AUTHORIZE AJC AUTO BODY TO COMMENCE REPAIRS ON MY VEHICLE PER THIS ESTIMATE.

SIGNED



DATE

8/31/21

*First Deposit 09-01-2021 \$2,000.00
 Second Deposit 09-09-2021 \$2,000.00
 Third Deposit 09-22-2021 \$2,000.00*

PAID in Full Cash 11-02-2021

VALS AUTO UPHOLSTERY
430 S VAN NESS AVE
SAN FRANCISCO CA 94103
(415)558-8498

Merchant ID: 4836
Term #: 0002

Store #: 3965
Ref #: 0001

Sale

XXXXXXXXXXXX2264

VISA

Entry Method: Chip

Total: \$ 1,948.50

05/28/21

11:53:08

Inv #: 000001

Appr Code: 092788

Transaction ID: 301148679880621

Apprvd: OnLine

Batch#: 000265

CAPITAL ONE VISA

AID: A0000000031010

TSI: F800

IVR: 0080008000

Customer Copy

THANK YOU!



VAL'S AUTO UPHOLSTERY

430 S. VAN NESS AVE. S.F. CA 94103
 (P) 415.558.8498 (F) 415.558.8430
 valsinfo@valsupholstery.com
 www.valsupholstery.com

Invoice

Date	Invoice #
5/27/2021	2389

Bill To

Vehicle	RO Number	VIN Number	Service Rep.	Tag/Vehicle #	PO Number
'73 Mercedes 280C ...					

Description	Quantity	Amount
Recover Front Seats Complete in Leather and Pad as Needed- If Necessary to Replace Original Horse Hair Molded Pads \$1450 for Both Front Seats Will be Added Later- Front Seats Included Bottom Covers, Backrest Covers, Headrests, Rear Seat Panels and Center Armrest Cover- Original Mercedes Blue Leather Parts- Front Seats		1,400.00T
Parts-Headrests, Rear Panels and Armrest		400.00T
Recover Rear Seats with Center Armrest Complete and Pad		1,400.00T
Parts- Bottom and Backrest Cover with Armrest Cover		1,000.00
Labor		
Replace Floor Carpets Complete		
Parts- Original German Multiloop Carpets (Blue)		900.00T
Labor		600.00
Trunk Components are a Vinyl Floor Mat and Possibly Side Panels That We Will Try and Source a Supplier- If Found Labor to Install Will be at No Charge. Deposit of \$4100 is Required to Order Parts. Parts will Take Approx. 4-5 Weeks To Arrive.		

Subtotal	\$5,700.00
Sales Tax (8.5%)	\$348.50
Total	\$6,048.50

Balance Due \$1,948.50

York's I
 1531 Secon
 Walnut Cree
 PH: 925-930-
 FX: 925-930-
 HAZ MAT#77-

YORKS MOTORWERKE
 1531 SECOND AVE
 WALNUT CREEK, CA 94597

02/26/2021

09:49:24

CREDIT CARD
 VISA SALE

REPAIR ORDER# **54612**

DATE: 02/16/21 09:03 am

PAGE: 1

TERMS:

CUSTOMER:
 ADDRESS:
 CITY:
 PHONE 1:
 PHONE 2:

Card #
 Chip Card:
 AID:
 SEQ #:
 Batch #:
 INVOICE
 Approval Code:
 Entry Method:
 Mode:

XXXXXXXXXXXX2264
 CAPITAL ONE VISA
 A0000000031010

1
 1597

07725B
 Chip Read
 Issuer

VEHICLE: - **MERCEDES BEN 280 COUPE**
 LICENSE: MYRA PR/ FLEET:
 VIN: 11407312001412 11/72
 ENGINE: Cyl Disp
 MILEAGE: 95140 COLOR: BLU

IR INSTRUCTIONS/CONCERNS

SALE AMOUNT

\$2816.64

TECH	QTY	PART	SERVICE DESCRIPTION	PARTS	LABOR
AH			PRESSURE HOSES AND THE LOW SIDE LEAKING. END THEM OUT TO BE REBUILT. REPLACE R DRYER, THEN CHARGE A/C SYSTEM.		209.10
AH			(SEE SUBLET FOR COST OF HOSE REBUILD) AC R12 TO R134A UPDATE EVACUATED SYSTEM, REPLACE CHARGE FITTINGS. HOLD SYSTEM UNDER VACUUM FOR TWENTY MINUTES. CHARGED SYSTEM TO CAPACITY OF 2.2 POUNDS. ADDED FLUORESCENT DYE AND AC OIL. CHECK FOR LEAKS. FOUND NO LEAKS. PRESSURE ARE 165 PSI HIGH SIDE AND 32 PSI LOW SIDE. TEMPERATURES ARE 78 DEGREES AMBIENT AND 44 DEGREES INSIDE.		194.95
	2.0	R-134A	R-134 a A/C Refridgere	64.00	
	1.0	TP3090 0601	AC DYE	12.50	
	1.0	AC OIL	A/C OIL	4.25	
	1.0	59977	HIGH SIDE ADAPTER	12.99	
	1.0	59976	LOW SIDE ADAPTER	13.99	
EY DN VY AH			SUN ROOF CUSTOMER REPORTS THE SUN ROOF IS NOT FUNCTIONING PROPERLY. CUSTOMER WOULD LIKE US TO REPLACE THE SUN ROOF SWITCH. WE COULD NOT FIND A NEW SUNROOF SWITCH. THE OLD ONE IS WOKING OKAY AT THIS TIME. REMOVED THE SUNROOF PANEL AND CLEANED AND LUBED THE		174.25
AH			TAIL LIGHTS		34.85

CUSTOMER COPY

CUSTOMER REQUEST RETURNED PARTS YES NO

PAYMENTS / SURCHARGE DETAIL

TOTALS

RECOMMENDATIONS

LABOR:\$ 944.24
 PARTS:\$ 1,123.93
 SURCHRG:\$ 0.00
 SUBLET:\$ 655.75
 SUPPLIES:\$ 0.00
 DISCOUNT:\$ 0.00
 TAX:\$ 92.72
 TOTAL:\$ **2816.64**
 PAID:\$ 0.00
 DUE:\$ **2,816.64**

I hereby authorize the above repair work to be done with the necessary
 material and hereby grant you and/or your employees permission to operate
 the car, truck or vehicle herein described on street, highways or
 elsewhere for the purpose of testing and/or inspection. An express
 mechanics lien is hereby acknowledged on above car, truck or vehicle to
 secure the amount of repairs thereto. You will not be held responsible
 for loss or damage to vehicle or articles left in vehicle in case of
 fire, accident or any other cause beyond your control.

(Signature) _____

York's Motorwerke

1531 Second Ave.
 Walnut Creek, CA 94597
 PH: 925-930-7676
 FX: 925-930-7009
 HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# **54612**

DATE: 02/16/21 09:03 am

PAGE: 2

TERMS:

CUSTOMER:	VEHICLE: - MERCEDES BEN 280 COUPE
ADDRESS:	LICENSE: MYRA PR/ FLEET:
CITY:	VIN: 11407312001412 11/72
PHONE 1:	ENGINE: Cyl Disp
PHONE 2:	MILEAGE: 95140 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
JY			INSTALL TAIL LIGHTS. CUSTOMER SUPPLIED PARTS.		
			HEAD LIGHTS CUSTOMER WOULD LIKE US TO SEE IF WE CAN FIND HEAD LIGHT FRAMES AND MOLDINGS.		17.43
AH	1.0	115 826 01 89	REPLACED THE PASSENGER SIDE WITH A GOOD USED HEADLAGHT DOOR Headlight Door	315.00	
JY			FRONT GRILL TRIM INSTALL MISSING GRILL TRIM. CUSTOMER SUPPLIED PARTS.		17.43
JY			DOME LIGHT PLASTIC IS CRACKING ON INTERIOR DOME LIGHT. CUSTOMER WOULD LIKE US TO SEE IF WE CAN FIND A NEW LIGHT COVER.		0.00
AH	1.0	108 820 03 52	ORDERED PART Dome Light	138.25	
AH			SEAT BELT LIGHT SEAT BELT WARNING LIGHT COVER IS MISSING. SEE IF WE CAN FIND A NEW COVER. REPLACED THE LAMP ASSEMBLY WITH GOOD USED ONE		52.28
AH	1.0	789 USED	SEAT BELT WARN LIGHT	45.45	
AH			SPEAKERS INSTALL FRONT SPEAKERS. SEE IF WE CAN FIND REAR SPEAKERS. CUSTOMER SUPPLIED FRONT SPEAKERS.		174.25
AH			SHIFTER COVER INSTALL SHIFTER COVER. CUSTOMER SUPPLIED PART.		34.85
JY			BUMPER TRIM		34.85

CUSTOMER REQUEST RETURNED PARTS YES NO

PAYMENTS / SURCHARGE DETAIL

TOTALS

RECOMMENDATIONS

LABOR:\$	944.24
PARTS:\$	1,123.93
SURCHRG:\$	0.00
SUBLET:\$	655.75
SUPPLIES:\$	0.00
DISCOUNT:\$	0.00
TAX:\$	92.72
TOTAL:\$	2816.64
PAID:\$	0.00
DUE:\$	2,816.64

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

York's Motorwerke

1531 Second Ave.
 Walnut Creek, CA 94597
 PH: 925-930-7676
 FX: 925-930-7009
 HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# **54612**

DATE: 02/16/21 09:03 am

PAGE: 3

TERMS:

CUSTOMER:	VEHICLE: - MERCEDES BEN 280 COUPE
ADDRESS:	LICENSE: MYRA PR/ FLEET:
CITY:	VIN: 11407312001412 11/72
PHONE 1:	ENGINE: Cyl Disp
PHONE 2:	MILEAGE: 95140 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
JY			BUMPER TRIM IS NOT INSTALLED PROPERLY. REINSTALL THE LEFT REAR BUMPER TRIM		
JY	1.0	PARTS	BODY TRIM PRICE FOR BODY TRIM IS \$485. DO NOT INSTALL BODY TRIM. GIVE TO CUSTOMER TO HAVE BODY SHOP INSTALL AFTER PAINT IS DONE.	485.00	0.00
JY			TRIM		
JY			DOOR SEALS ORDER WINDOW AND DOOR SEALS		0.00
JY			TIRE INFLATION TIRE INFLATION SERVICE CHECK AND INFLATE EACH TIRE TO THE RECOMMENDED TIRE PRESSURE RATING. TIRE INFLATION MEASUREMENTS AFTER COMPLETION OF SERVICE/WORK: FRONT: 32 PSI REAR: 36 PSI.		0.00
JY			REMOVE RADIO REMOVE RADIO AND SEND TO BECKER FOR REPAIR AND TO INSTALL BLUETOOTH AND A AUX JACK		0.00
JY	1.0	110 010 01 72	OIL DIP STICK Dipstick * HOSES * RADIO REPAIR	32.50	0.00
					210.75
					445.00

CUSTOMER REQUEST RETURNED PARTS YES NO	PAYMENTS / SURCHARGE DETAIL	TOTALS
RECOMMENDATIONS		LABOR:\$ 944.24 PARTS:\$ 1,123.93 SURCHRG:\$ 0.00 SUBLET:\$ 655.75 SUPPLIES:\$ 0.00 DISCOUNT:\$ 0.00 TAX:\$ 92.72
	I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. (Signature) _____	TOTAL:\$ 2816.64 PAID:\$ 0.00 DUE:\$ 2,816.64

ROLLING STOCK INC

601 Bayshore Blvd
www.RollingStockSF.com
San Francisco, CA 94124
415-558-9121

Invoice # 1-100982 Dealer ID# Page 1 of 2
Date 02/12/21
In Feb 08, 2021 3:09 PM
Out Feb 12, 2021 1:58 PM

Emp: 1-14 AH / 1-81 RC

*** INVOICE ***

Sold To:

Ship To:

Unit #:
Vehicle: 73 MERCEDES-BENZ 280C BASE L6 2.8
License: SFDWELL
Mileage: In: 95077 Out: 95077
Vin#:
PO#:
BAR ID: ARD00258230
EPA ID: CAL000422944

Salesman	Mechanic	Part #	QTY	Description	Parts	Labor	FET	Total
14	86	1011010	5.00	195/75R14 92S HANKOOK OPTIMO H724 (70K)	89.95	0.00	0.00	449.75
14	86	SRV-DSP01	5.00	DISPOSAL - TIRE - PASS-LT	5.00	0.00	0.00	25.00
14	86	SRV-RF-CAL	5.00	RECYCLE FEE - CALIFORNIA	1.75	0.00	0.00	8.75
14	86	MB-STD	5.00	13-17 MOUNT AND BALANCE 13-17	0.00	25.00	0.00	125.00
14	86	VS413	5.00	1.25 RUBBER VALVE STEM GEN	3.00	0.00	0.00	15.00
14	110	ALIGN-SPECIAL	1.00	ALIGNMENT - SPECIALTY	0.00	129.95	0.00	129.95
14	110	WAR-ALIGN	1.00	WARRANTY ALIGNMENT	0.00	0.00	0.00	0.00

6 MONTH WARRANTY ON MOST ALIGNMENTS—RESTRICTIONS MAY APPLY

If repairs are required in order to align vehicle to spec, repairs must be performed by RSI.

If repairs are performed elsewhere, and re-alignment is required, customer will be responsible for a re-alignment fee based on the alignment procedures needed, and custom car are considered a specialty alignment, RSI does not provide warranty.

14	110	DOT-REG	1.00	DOT TIRE REGISTRATION	0.00	0.00	0.00	0.00
----	-----	---------	------	-----------------------	------	------	------	------

DOT #: T7KAHBH2820
DOT #: T7KAHBH3219
DOT #: T7KAHBH3219
DOT #: T7KAHBH2819
DOT #: T7KAHBH2720

CUSTOMER REQUESTED 5 TIRES TO BE INSTALLED AND THE ALIGNMENT

BLACK OUT

SLIGHT PLAY IN PITMAN ARM AND IDLER ARM
SLIGHT PLAY IN RIGHT FRONT WHEEL BEARING
CAMBER IS MAXED OUT ON LEFT FRONT

ALIGNMENT SET BEST POSSIBLE APPLABEL: VISA CREDIT[AID: A000000031010]TVR: 0080008000[IAD: 06010A03A0A002]TSI:
E800[ARQC: 238A8699246666A0]ARC: 00[CVM: S

Card Type: VISA

CC#: *****2264

Auth. # SALE:04175

Amount: \$792.95

Signature: _____

Buyer agrees to pay total amount above, according to cardholder's agreement with issuer.

ROLLING STOCK INC

601 Bayshore Blvd
www.RollingStockSF.com
San Francisco, CA 94124
415-558-9121

Invoice # 1-100982 Dealer ID# Page 2 of 2
Date 02/12/21
In Feb 08, 2021 3:09 PM
Out Feb 12, 2021 1:58 PM

Emp: 1-14 AH / 1-81 RC

*** INVOICE ***

Sold To:

Ship To:



Unit #:
Vehicle: 73 MERCEDES-BENZ 280C BASE L6 2.8
License: SFDWELL
Mileage: In: 95077 Out: 95077
Vin#:
PO#:
BAR ID: ARD00258230
EPA ID: CAL000422944

Salesman	Mechanic	Part #	QTY	Description	Parts	Labor	FET	Total
----------	----------	--------	-----	-------------	-------	-------	-----	-------

ALL SALES FINAL NO REFUNDS--All labor is non-refundable-All returns or exchanges must be accompanied by original receipt.-25% restocking fee assessed on all items returned to stock-RSI accepts no responsibility for any personal items left inside vehicles at time of service-No returns, exchanges or adjustments on any tire that has been run on flat.-All deposits for lay-away or special orders shall remain in effect for 30 days and are thereafter forfeited and non-refundable.-RSI not responsible for any additional damage to wheels when attempting to repair.-Any items left on premises for longer than 7 days are forfeited and becomes sole property of RSI (includes customer take-offs).-Customers responsibility to re-torque lugs

Cash: 0.00	Check: 0.00	Credit: 792.95	Charge: 0.00	Parts:	498.50
Change: 0.00			Due Date: 02/12/2021	Labor:	254.95
				Subtotal:	753.45
				Sales Tax:	39.50
Signature: _____				Total:	\$792.95

Mercedes-Benz : 114/115 (/8 1967-76) : Power Assisted Steering : Standard Suspension : without Level Control ExpressAlign Total Alignment



2/12/2021

Customer Copy

Mercedes-Benz Classic Center USA

Term ID: 001

Sale - Approved

Date	02/12/21	Time 16:22:08
Method of Payment	Visa	
Entry Method	Manual	
Customer Name		
Account #		
Order ID	194560	
Approval Code	06258B	
Amount	\$99.46	

Customer C

Mercedes-Benz Classic

Mercedes-Benz USA LLC

9 Whatney · Irvine, CA 92618-2808

(949) 598-4850

Toll-free: 1-866-MB-CLASSIC (622-5277)

Fax: (949) 598-4860

Email: classicparts@mbusa.com

Web: www.mbusa.com/classic

CLASSIC PARTS SALES

DATE ENTERED 11 FEB 21	YOUR ORDER NO.	DATE SHIPPED 12 FEB 21	INVOICE DATE 12 FEB 21	INVOICE NUMBER 194560
---------------------------	----------------	---------------------------	---------------------------	--------------------------

S
O
L
D

T
O

S
H
I
P

T
O

PAGE 1 OF 1

SHIP VIA TODAY	SLSM. 315	B/L NO. 9450-9019-8136	TERMS VIS MASTERCARD	F.O.B. POINT IRVINE, CA
-------------------	--------------	---------------------------	-------------------------	----------------------------

QTY	SHIP	B.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
2	2	0	Q-4-76-0038	VALETKEY	29.50	25.07	50.14
1	1	0	116-888-01-85	MLDG	27.50	23.37	23.37
3	3	0	002-988-85-78	CLIP	3.40	2.72	8.16
			SHIPPING & HANDLING		10.00		

Core returns must be shipped within 30 days of the exchange part purchase. Cores must be returned in the same package the exchange part was supplied in. The core must be a genuine Mercedes-Benz part in rebuildable and complete condition to satisfy our core deposit refund obligation. The original core deposit invoice must be sent with the return. We will not pay shipping charges on core returns. Failure to return a core will result in forfeiture of the respective core deposit.

PARTS	81.67
SUBLET	
SHIPPING & HANDLING	10.00
SALES TAX	7.79
TOTAL	\$99.46

We are not responsible for errors on parts orders when the part number is furnished to us by the purchaser.

We will not be responsible for any damage to any vehicle caused by parts used on a model they were not specifically intended for, nor is there any warranty on such parts.

All parts shortage and damaged part claims must be made immediately upon receipt of order. All shipments must be signed for upon delivery, unless we are instructed otherwise. We bear no responsibility for a lost shipment released without a proof-of-delivery signature.

Parts returns must have prior authorization and must be accompanied the original sales invoice within 30 days of the original purchase. All returned parts must be their original packaging with our picking label affixed and in saleable condition. No returns on electrical parts if the package has been opened and/or unsealed. No returns on "Special Order" parts. No returns on parts that have been "test" installed, painted, modified, altered or disassembled in any way.

All parts returned are subject to a 20% re-stocking fee. We are not responsible for shipping charges on parts returns. We will pay return freight charges only if we made an error on the parts order.

CUSTOMER'S SIGNATURE
X

SEE REVERSE SIDE FOR IMPORTANT WARRANTY INFORMATION



From: Manuel Gonzalez restoration@maderaconcepts.com
Subject: Re: '73 Mercedes 280C Coupe (W114)
Date: December 16, 2020 at 12:16 PM
To:

H

So to Fabricate a New Speaker Grille its \$360.00 plus shipping.
We are at your service!

Happy Motoring,

Manuel Gonzalez

805-962-1579

Madera Concepts Inc.

Automotive Wood Restoration Specialists - Since 1982
Exotic Wooden Dashboards and Interior Trim Components
55 - B Depot Rd.
Goleta, CA. 93117

805-962-1579 7am to 3:30pm PT Mon - Thursday and till Noon on Friday

Visit our website: www.maderaconcepts.com

If You Can't Use Us, Please Refer Us To Your Fellow Automotive Enthusiasts, Family and Friends

=====
...Never drive faster than...
your Guardian Angel can fly...
=====

On Dec 15, 2020, at 4:54 PM,

Hello,

Any chance you would be able to custom fabricate a wood dashboard speaker cover to match the existing dash wood trim ([VIN: 114 073 120 014 12](#))? I've attached pics of my car for reference.

Thank you!

Warm regards,

<dash center.jpeg><dash right.jpeg>

York's Motorwerke

1531 Second Ave.
Walnut Creek, CA 94597
PH: 925-930-7676
FX: 925-930-7009
HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# **53900**

DATE: 08/01/20 05:42 pm

PAGE: 1

TERMS:

CUSTOMER:		VEHICLE:	- MERCEDES BEN 280 COUPE
ADDRESS:		LICENSE:	MYRA PR/ FLEET:
CITY:		VIN:	11407312001412 11/72
PHONE 1:		ENGINE:	Cyl Disp
PHONE 2:		MILEAGE:	95001 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
JDY			NEW CUSTOMER / TOW IN		0.00
AH			BATTERY CAR WILL NOT START WITHOUT A JUMPER BOX. RECHARGED BATTERY. FOUND BATTERY 10 YEARS OLD AND WILL NOT HOLD A CHARGE. REPLACE BATTERY.		34.85
AH	1.0	48	MEDIUM BATTERY	145.60	
			CAR CHECK OVER FRONT BRAKES HAVE [NEW] AND REAR BRAKES HAVE [NEW] OF PADDING MATERIAL LEFT. FRONT TIRES HAVE [6 MM] AND REAR TIRES HAVE [4 MM] OF TREAD DEPTH LEFT.		0.00
			COOLANT CHEMICAL TEST: -27° BRAKE FLUID CHEMICAL TEST: 0%		
JY			ROUGH RUNNING CUSTOMER REPORTS THE VEHICLE RUNS ROUGH AND HAS NO POWER. CHECK AND ADVISE. REPLACED SPARK PLUGS RESET DWELL AND TIMING. REMOVED THE TOP OF THE CARBURATOR AND CLEANED OUT ALL JETS AND REPLACE MISSING SECONDARY FLAP ENCENTRIC. RESET FUEL MIXTURE. REPLACE FUEL HOSE AND FUEL FILTER. REPAIR THROTTLE LINKAGE.		522.75
	6.0	7900	SPARK PLUGS WR7DC	29.70	
	1.0	FH	FUEL HOSE	6.23	
	1.0	SO66K	CARBURATOR KIT	81.30	
	1.0	PC1	PARTS CLEANER	8.50	
AH			COOLANT LEAK CUSTOMER REPORTS THERE IS A COOLANT LEAK. CHECK AND ADVISE. FOUND RADIATOR LEAKING, REMOVED RADIATOR FOUND WATER PUMP BEARING BAD.		540.18

CUSTOMER REQUEST RETURNED PARTS YES NO	PAYMENTS / SURCHARGE DETAIL	TOTALS
RECOMMENDATIONS		LABOR:\$ 2,630.47 PARTS:\$ 2,784.66 SURCHRG:\$ 0.00 SUBLET:\$ 984.00 SUPPLIES:\$ 0.00 DISCOUNT:\$ 0.00 TAX:\$ 229.73
	I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.	TOTAL:\$ 6628.86 PAID:\$ 0.00 DUE:\$ 6,628.86
	(Signature) _____	

York's Motorwerke

1531 Second Ave.
Walnut Creek, CA 94597
PH: 925-930-7676
FX: 925-930-7009
HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# **53900**

DATE: 08/01/20 05:42 pm

PAGE: 2

TERMS:

CUSTOMER:

ADDRESS:

CITY:

PHONE 1:

PHONE 2:

VEHICLE: - **MERCEDES BEN 280 COUPE**

LICENSE: MYRA PR/ FLEET:

VIN: 11407312001412 11/72

ENGINE: Cyl Disp

MILEAGE: 95001 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
			REPLACE WORN WATER PUMP AND BELTS. SEND RADIATOR OUT TO BE RECORDED.		
	1.0	110 200 20 20	WATERPUMP	150.23	
	1.0	AF1	COOLANT	15.99	
	1.0	112 018 02 82	HOSE	8.50	
	6.0	9120102039	ALLEN BOLT	19.20	
	6.0	HC	Hose Clamp	10.80	
	1.0	123 470 02 59	FILTER	10.57	
	1.0	PC1	PARTS CLEANER	8.50	
JY			TRANS MODULATOR		174.25
			ENGINE IS SMOKING. FOUND TRANSMISSION MODULATOR DIAPHRAM LEAKING TRANSMISSION FLUID INTO THE VACUUM LINE TO THE ENGINE		
			REPLACE MODULATOR AND ADJUST.		
	1.0	000 270 01 79	Modulator Valve	244.50	
	3.0	ATF	Automatic Transmission	20.55	
	1.0	PC1	PARTS CLEANER	8.50	
AH			SHIFT INDICATOR		174.25
			REPLACE DEFECTIVE SHIFT INDICATOR AND DASH LIGHTING BULBS.		
	1.0	114 270 03 52	Shift Indicator	186.00	
	6.0	LB	light bulb	23.70	
EY			STEERING COUPLER		522.75
			REMOVE POWER STEERING BOX AND REPLACE WORN STEERING COUPLER.		
			REPLACE TIE ROD ASSEMBLES, CENTER DRAG LINK AND STEERING SHOCK.		
			SEND OUT FOR FRONT WHEEL ALIGNMENT.		
	1.0	115 460 05 10	Steering Coupling	93.80	
	1.0	000 463 51 32	Steering Shock	57.79	
	1.0	000 460 00 05	Center Drag Link	70.27	

CUSTOMER REQUEST RETURNED PARTS YES NO

PAYMENTS / SURCHARGE DETAIL

TOTALS

RECOMMENDATIONS

LABOR:\$ 2,630.47
PARTS:\$ 2,784.66
SURCHRG:\$ 0.00
SUBLET:\$ 984.00
SUPPLIES:\$ 0.00
DISCOUNT:\$ 0.00
TAX:\$ 229.73

TOTAL:\$ **6628.86**
PAID:\$ 0.00
DUE:\$ **6,628.86**

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

York's Motorwerke

1531 Second Ave.
Walnut Creek, CA 94597
PH: 925-930-7676
FX: 925-930-7009
HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# **53900**

DATE: 08/01/20 05:42 pm

PAGE: 3

TERMS:

CUSTOMER:

ADDRESS:

CITY:

PHONE 1:

PHONE 2:

VEHICLE: - **MERCEDES BEN 280 COUPE**

LICENSE: MYRA PR/ FLEET:

VIN: 11407312001412 11/72

ENGINE: Cyl Disp

MILEAGE: 95001 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
AH	2.0	107 330 01 03	Tie Rod Assembly	111.14	121.98
	1.0	PS1	POWER STEERING FLUID	4.25	
	1.0	PC1	PARTS CLEANER	8.50	
AH			HEATER VALVE FOUND THE HEATER VALVE LEAKING COOLENT. REMOVE THE HEATER VALVE AND REPLACE THE SEALS		348.50
	2.0	000 835 02 20	SEAL	12.96	
EY	2.0	000 835 48 98	SEAL	10.90	100.00
			BRAKES REPLACE CRACKED BRAKE HOSES AND BLEED BRAKE SYSTEM. WHEN REPLACING THE BRAKE HOSES FOUND THE BRAKE CALIPERS ARE FROZEN. REPLACE FRONT AND REAR BRAKE CALIPERS AND PADS.		
	2.0	116 428 02 35	BRAKE HOSE	45.00	
	2.0	126 428 03 35	Brake Hose	47.00	
	1.0	BF1	Brake Fluid	7.99	
	1.0	PC1	PARTS CLEANER	8.50	
	1.0	141.35012	CALIPER REBUILT	120.61	
	1.0	141.35011	CALIPER REBUILT	120.61	
	1.0	123 420 06 83	Brake Caliper	184.30	
	1.0	123 420 05 83	Brake Caliper	186.10	
	1.0	001 420 06 20	BRAKE PAD SET	42.43	
	1.0	001 420 78 20	Brake Pad Set	37.00	
	2.0	001 989 10 51	ANTI SQUEAL PASTE	4.00	
	AH			SHOCKS REPLACE WORN FRONT AND REAR SHOCKS WITH NEW BILSTEINS. LABOR IS OVERLAPPED WITH STEERING COUPLER JOB.	
2.0		19 118703	REAR SHOCK	220.46	
	2.0	115 320 00 30	Shock Absorber	216.64	
			DOOR CHECK REPLACE BROKEN DRIVERS SIDE DOOR STRAP WITH GOOD USED		

CUSTOMER REQUEST RETURNED PARTS YES NO

PAYMENTS / SURCHARGE DETAIL

TOTALS

RECOMMENDATIONS

LABOR:\$ 2,630.47
PARTS:\$ 2,784.66
SURCHRG:\$ 0.00
SUBLET:\$ 984.00
SUPPLIES:\$ 0.00
DISCOUNT:\$ 0.00
TAX:\$ 229.73

TOTAL:\$ 6628.86
PAID:\$ 0.00
DUE:\$ 6,628.86

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

York's Motorwerke

1531 Second Ave.
Walnut Creek, CA 94597
PH: 925-930-7676
FX: 925-930-7009
HAZ MAT#77-1356 BAR#AF172885

REPAIR ORDER# **53900**

DATE: 08/01/20 05:42 pm

PAGE: 4

TERMS:

CUSTOMER:

ADDRESS:

CITY:

PHONE 1:

PHONE 2:

VEHICLE: - **MERCEDES BEN 280 COUPE**

LICENSE: MYRA PR/ FLEET:

VIN: 11407312001412 11/72

ENGINE: Cyl Disp

MILEAGE: 95001 COLOR: BLU

SERVICE REPAIR INSTRUCTIONS/CONCERNS

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
AH	1.0	108 720 00 16 U	REPLACE BROKEN DRIVERS SIDE DOOR STRAP WITH GOOD USED ONE. NEW ONES ARE NOT AVAILIBLE. REINSTALL UPPER DOOR PANEL AND A PILLER MOLDING.	45.00	
	4.0	002 988 45 78	USED DOOR STRAP Spring Clip	10.00	0.00
AH	1.0	126 410 02 15	DRIVE LINE FLEX DISC FOUND ONE OF THE DRIVE LINE FLEX DISCS IS WORN OUT. REPLACED FLEX DISC. FLEX DISC	118.64	0.00
AH	2.0	40717A	WIPER BLADES REPLACED BOTH WINDSHEILD WIPER BLADES. 17" BOSCH `MICRO EDGE` TIRE INFLATION TIRE INFLATION SERVICE CHECK AND INFLATE EACH TIRE TO THE RECOMMENDED TIRE PRESSURE RATING. TIRE INFLATION MEASUREMENTS AFTER COMPLETION OF SERVICE/WORK: FRONT: 32 PSI REAR: 36 PSI. * RECORE RADIATOR * FRONT WHEEL ALIGNMENT	22.40	837.00 147.00

CUSTOMER REQUEST RETURNED PARTS YES NO

PAYMENTS / SURCHARGE DETAIL

TOTALS

RECOMMENDATIONS

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

LABOR:\$ 2,630.47
PARTS:\$ 2,784.66
SURCHRG:\$ 0.00
SUBLET:\$ 984.00
SUPPLIES:\$ 0.00
DISCOUNT:\$ 0.00
TAX:\$ 229.73

TOTAL:\$ **6628.86**
PAID:\$ 0.00
DUE:\$ **6,628.86**