

Invoice No.
000069348

MORAGA MOTORS

Order Date 02/28/19 09:52 am
Completed: 03/01/19 10:16 am

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair



34 FORD COUPE
656 Mi.
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 02/28/19 09:53am 148.50
PHIL in person.

WINDOW INSPECT/REPAIR- POWER Labor: \$297.00

REMOVE DOOR PANEL AND INSPECT WINDOW

**DRIVER SIDE WINDOW

**TECHNICIAN FOUND WINDOW SWITCH SET SCREW FOR THE HANDLE WAS BACKED OUT. TECHNICIAN REMOVED WINDOW SWITCH AND RESECURED SET SCREW

TIRE PRESSURE CHECK Labor: \$0.00

INFLATE TO FACTORY SPECIFICATIONS

Payments to MORAGA MOTORS Cost Summary

Status: Completed Work Order

Payments:

Labor	297.00
Parts	0.00
Subtotal	297.00
Total	\$297.00
Payments	0.00
Bal Due	297.00

Thank you for choosing MORAGA MOTORS

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Invoice No.
000069428

MORAGA MOTORS

Order Date 03/11/19 09:35 am
Completed: 03/25/19 09:49 am

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair



34 FORD COUPE
678 Mi. Last in 2/28/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 03/11/19 09:41am 297.00
PHIL in person.

INSPECT NOISE

Labor: \$29.70

INSPECT NOISE BEHIND DASH
**CAR HAS THE IGNITION BOX MOUNTED INSIDE CAR.

INSPECT DOOR LATCH

Labor: \$118.80

**INSPECT DRIVERS SIDE DOOR LATCH, DOES NOT CLOSE ALL THE WAY EASILY. AJUST DOOR STRIKER

BATTERY INSPECT

Labor: \$29.70

**LOCATE BATTERY AND FOUND IT ALREADY HAD TENDER. RELOCATE TO THE SIDE OF PASSANGER SEAT

021-0123	BATTERY TENDER-N	1.0 @	41.56 =\$	41.56	41.56
----------	------------------	-------	-----------	-------	-------

IGNITION RELOCATE

Labor: \$668.25

REMOVE MSD IGNITION BOX FROM UNDER DASH AND RELOCATE TO RIGHT INSIDE FRAME. REDUE WIRING TO FRAME RAIL

1	MISC SUPPLIES-N	2.0 @	5.00 =\$	10.00	10.00
---	-----------------	-------	----------	-------	-------

A/C REPAIR

Labor: \$148.50

REPAIR AC LINES-LEAKING AND RUBBING, TIGHTEN LINES AND ADD SUPPORT

TIRE PRESSURE CHECK

Labor: \$0.00

INFLATE TO FACTORY SPECIFICATIONS

Payments to MORAGA MOTORS

Status: Completed Work Order

Payments:

Cost Summary

Labor	994.95
Parts	51.56
Subtotal	1046.51
Tax	4.77
Total	\$1051.28

I hereby authorize the above repair work to be done with the necessary material and heretofore and/or your employee permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

Thank you for choosing MORAGA MOTORS

pd by ce
3-26-19

(Signature) _____

CocoMats.com Packing Slip for Order #415627

236 Zimmer Road
Fort Mill SC 29707
United States

Billing Details

Shipping Details

Order: #415627
Order Date: 27th Mar 2019

Shipping Method: Flat Rate

Shipped Items

Qty	Code/SKU	Product Name	Bin Picking No.
1	002SI	Sisal Floor Mats	N/A
		Choose a Color: #47 Brown Palomino	
		Choose your Custom Mat Set: 2 Piece Custom Set (Driver & Passenger) \$179.95	
		Vehicle Year: 1934	
		Vehicle Make: Ford	
		Vehicle Model (Please Type in Your Model): Cabriolet	
		Vehicle Body Style: Convertible	
		Does your vehicle have Floor Mat Attachments? (Vehicles 1999+) Please visit Mat Attachments page for more info.: No Mat Attachments Required	
		Additional Order Comments: use customer pattern	

Comments

Use the customer patterns I sent in to Chrissy

Invoice No.
000069686

MORAGA MOTORS

Order Date 04/09/19 09:07 am
Completed: 04/15/19 02:43 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair



34 FORD COUPE
717 Mi. Last in 3/11/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 04/09/19 09:25am 0.00
PHIL in person.

BRAKE PEDAL ADJUST INSPECTION Labor: \$0.00

RECOMMEND MOVING SEAT BACK FIRST

SUSPENSION INSPECTION Labor: \$0.00

INSPECT FRONT AND REAR SUSPENSION AND SHOCKS
**NO PROBLEMS FOUND AT THIS TIME
**CUSTOMER REQUEST TO SEE IF SUSPENSION CAN BE MADE INTO A SOFTER RIDE
**ALDAN AMERICAN COIL OVER SUSPENSION
DROP HIGHT 13" RIDE HIGHT 12"

SEAT RELOCATE Labor: \$445.50

**REMOVE SEAT AND DRILL NEW HOLES IN SEAT TRACK TO MOVE SEAT BACK ABOUT 2".
**REMOVE SEAT BELT BRACKETS AND FLIP AROUND TO MOVE BACK SO SEATS BACK

Recommendations:
**FUEL GAUGE INSPECTION
**SUSPENSION SOFTENING

Payments to MORAGA MOTORS Cost Summary

Status: Completed Work Order	Labor	445.50
	Parts	0.00
Payments:	Subtotal	445.50
	Total	\$445.50
	Payments	0.00
	Bal Due	445.50

Thank you for choosing MORAGA MOTORS

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____


Invoice No.
000069939

MORAGA MOTORS

Order Date 05/06/19 07:49 am
Completed: 05/09/19 02:29 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair



34 FORD COUPE
805 Mi.Last in 4/9/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 05/06/19 07:48am 153.19
PHIL in person.

FUEL GAGE INSPECT/READS Labor: \$519.75

**CUSTOMER STATES FUEL GAGE WILL NOT READ FULL. IT READS 3/4 EVEN WHEN FULL OF FUEL
**REMOVE EXHAUST MUFFLERS AND TAIL PIPES AND REAR BUMPER AND LOWER BODY PANEL TO REMOVE FUEL TANK. ADJUST FUEL SENDER TO READ CORRECTLY.

FUEL Labor: \$60.90

ADDED FUEL 13.5 GALLONS

INSPECT/REPAIR FLUID LEAKS Labor: \$148.50

INSPECT FOR FLUID LEAKS.
**FOUND TRANSMISSION PAN GASKET LEAKING- BOLTS WERE LOOSE TIGHTEN AND CLEANED.
**IF LEAK COMES BACK RECOMMEND REPLACING GASKET

M715	BRAKE CLEAN-N	1.0 @	4.29 =\$	4.29	4.29
------	---------------	-------	----------	------	------

FAN SWITCH INSTALLATION Labor: \$267.30

INSTALL THERMOSTAT SWITCH FOR RADIATOR FAN.
**INSTALL THERMOSTAT SWITCH AND WIRE INTO RELAY TO TURN FAN ON AS NEEDED.

30110	THERMOSTAT SWITCH-S	1.0 @	59.95 =\$	59.95	
1	MISC SUPPLIES-N	3.0 @	5.00 =\$	15.00	74.95

BRAKE INSPECTION Labor: \$0.00

INSPECT BRAKES FOR WEAR- HYDRAULIC LEAKS- LINING THICKNESS.
**LIKE NEW
**NOISE
**SEE ATTACHED PAGE FOR MORE INFORMATION

TIRE PRESSURE CHECK Labor: \$0.00

INFLATE TO FACTORY SPECIFICATIONS
FRONT 28 PSI
REAR 28 PSI

DOOR LOCK DRIVERS SIDE INSPECTIO Labor: \$0.00

INSPECT AND FOUND LOCK ACTUATOR NOT WORKING CORRECTLY.
**NEED MORE TIME TO REMOVE DOOR PANEL

Recommendations:

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
000069939

MORAGA MOTORS

Order Date 05/06/19 07:49 am
Completed: 05/09/19 02:29 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair

Recommendations

**DRIVER DOOR LOCK- NEED TO REMOVE PANEL AND INSPECT

Payments to MORAGA MOTORS Cost Summary

Status: Completed Work Order

Payments:

Labor	996.45
Parts	79.24
Subtotal	1075.69
Tax	7.33
Total	\$1083.02
Payments	0.00
Bal Due	1083.02

Thank you for choosing MORAGA MOTORS



I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Invoice No.
000070092

MORAGA MOTORS

Order Date 05/21/19 10:53 am
Completed: 05/30/19 03:14 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair



34 FORD COUPE
853 Mi. Last in 5/6/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 05/21/19 10:57am 148.50
PHIL in person.

DOOR LOCK INSPECT/REPAIR Labor: \$385.00

REMOVE BOTH DOOR PANEL INSPECT AND REPAIR
LOCK WILL NO ENGAGE
REMOVE LOCK AND CLEAN AND ADJUST AND LUBE

TOP INSPECTION Labor: \$0.00

PUT TOP UP

TIRE PRESSURE CHECK Labor: \$0.00

INFLATE TO FACTORY SPECIFICATIONS
**28 PSI

Payments to MORAGA MOTORS Cost Summary

Status: Completed Work Order

Payments:

Labor	385.00
Parts	0.00
Subtotal	385.00
Total	\$385.00
Payments	0.00
Bal Due	385.00

Thank you for choosing MORAGA MOTORS

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

*M. Ned's Auto Supply Concord
1939 Market Street*

Invoice No.
000G70606

MORAGA MOTORS

Order Date 07/18/19 08:46 am
Completed: 08/02/19 01:22 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair

34 FORD COUPE
922 Mi.Last in 5/21/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 07/18/19 09:21am 111.75
PHIL in person.

A/C INSPECTION

Labor: \$148.50

INSPECT SYSTEM FOR LEAK AND INSPECT ELECTRICAL SYSTEM FOR A/C.
SCAN FOR CODES IN SYSTEM
**FOUND THAT THE DRIVERS AND PASSENGER SIDE AIR DUCTS WERE DETACHED FROM THE VENTS,
REATTACHED DUCTING TO VENTS AND SECURED TO BACK SIDE OF THE VINTS.
**FOUND THAT THE LOW SIDE A/C LINE TO COMPRESSOR AT THE FITTING WAS LOOSE ALLOWING THE
SYSTEM TO LEAK FREON, ADJUSTED A/C LINES AND TIGHTENED FITTINGS.
THE COOLING FAN DOES NOT COME ON WHEN THE A/C COMPRESSOR TURNS ON, WILL CAUSE THE A/C
SYSTEM TO OVER PRESSURIZE. WILL NEED TO TIE INTO THE A.C SIGNAL WIRE TO MAKE THE COOLING
FAN COME ON WITH THE COMPRESSOR FOR THE A/C SYSTEM TO WORK PROPERLY.

A/C REPAIR

Labor: \$148.50

ADJUST AC LINES AND TIGHTEN.
ADJUST UNDER DASH VENTS

A/C RECHARGE

Labor: \$118.80

**TEST FREON FOR CONTAMINATION- IDENTIFY.
**EVACUATE SYSTEM.
**VACUUM TEST FOR LEAKS.
**RECHARGE AND ADD DYE.

R134A	FREON-N-N	1.0 @	19.95 =\$	19.95	19.95
-------	-----------	-------	-----------	-------	-------

A/C RADIATOR FAN CONTROLER

Labor: \$445.50

INSTALL SECONDARY RADIATOR FAN CONTROLLER
WIRE IN CONTROLER TO A/C SYSTEM SO THE FAN COMES ON WITH AC

30101	RADI. FAN CONTROL UNIT-N	1.0 @	39.55 =\$	39.55	
1	MISC SUPPLIES-N	2.0 @	5.00 =\$	10.00	49.55

LIGHT INSPECT/REPAIR

Labor: N/C

ADEJUST

TIRE PRESSURE CHECK

Labor: \$0.00

INFLATE TO FACTORY SPECIFICATIONS

Invoice No.
000070606

MORAGA MOTORS

Order Date 07/18/19 08:46 am
Completed: 08/02/19 01:22 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair

Payments to MORAGA MOTORS

Status: Completed Work Order

Payments:

Cost Summary

Labor	861.30
Parts	69.50
Subtotal	930.80
Tax	6.43
Total	\$937.23
Payments	0.00
Bal Due	937.23

Thank you for choosing MORAGA MOTORS



I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Invoice No.
000071055

MORAGA MOTORS

Order Date 09/05/19 09:09 am
Completed: 10/04/19 11:32 am

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair

34 FORD COUPE
1127 Mi.Last in 7/18/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes

1 09/05/19 09:55am 0.00
PHIL in person.

BRAKE INSPECTION

Labor: \$74.25

INSPECT BRAKES FOR NOISE
**REMOVE RIGHT FRONT BRAKE PADS FOR INSPECTION AND FOUND BRAKE PADS HAVE HARD MATERIAL.
AND RECOMMEND REPLACING WITH NEW BRAKE PADS WITH SOFTER MATERIEL

HEAD LIGHT REPAIR

Labor: \$59.40

REMOVE CLASS AND GLUE TO FRAME.

DRIVER SIDE TURN SIGNAL REPAIR

Labor: \$44.55

TIGHTEN DRIVERS SIDE LIGHT

BRAKE JOB FRONT DISC

Labor: \$148.50

REMOVE FRONT DISC ROTORS- CLEAN / LUBE CALIPER SLIDERS- INSTALL NEW DISC PADS- REINSTALL DISC ROTORS.

2417	PARTS CLEANER-N	1.0 @	5.95 =\$	5.95	
WIL-15Q-6824K	BRAKE PADS-S	1.0 @	103.00 =\$	103.00	108.95

BRAKE JOB REAR DISC

Labor: \$148.50

REMOVE REAR DISC ROTORS- CLEAN LUBE CALIPER SLIDERS- INSTALL NEW DISC PADS- REINSTALL DISC ROTORS.

M715	BRAKE CLEAN-N	1.0 @	4.29 =\$	4.29	
WIL-15Q-6824K	BRAKE PADS-S	1.0 @	103.89 =\$	103.89	108.18

HOOD LATCH PASSANGER SIDE

Labor: \$25.00

FOUND BOLTS MISSING. INSTALLED TEMPORARY BOLTS. NEW BOLTS ON ORDER

TIRE PRESSURE CHECK

Labor: \$0.00

INFLATE TO FACTORY SPECIFICATIONS

----->----->----->-----Continued on the next page----->----->----->----->

Invoice No.
000071055

MORAGA MOTORS

Order Date 09/05/19 09:09 am
Completed: 10/04/19 11:32 am

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair

Payments to MORAGA MOTORS

Cost Summary

Status: Completed Work Order

Payments:

Labor	500.20
Parts	217.13
Subtotal	717.33
Tax	20.09
Total	\$737.42
Payments	0.00
Bal Due	737.42

Thank you for choosing MORAGA MOTORS



I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Moal Inc
 937 East 12th Street
 Oakland, CA. 94606
 Phone: 510-834-9066 Fax: 510-272-9288

INVOICE

1425

INVOICE

Printed Date: 01/07/2025 **Work Completed: 03/16/2020**

1934 Ford - Cabriolet -
 Lic # : Odometer In : 0
 VIN # : 18016123

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Ball joint rod end, corrosion resistant, 1/2"-20 right hand thread <i>McMaster Carr</i>	2.00	50.04	100.08	Mechanical Work Performed Rework and straighten bent linkage on convertible top and lubricate pivot points. Remove left hood side for frame rail access. Locate VIN number and sand off paint to expose. Put car on lift and inspect undercarriage and drivetrain. Remove, straighten, and re-install rear suspension trailing links. Disassemble front brakes. Remove front brake rotors and disc sand surface to remove glaze. Clean and sand brake pads. Remove decorative covers from brake calipers to eliminate rattles. Operate seat tracks and seat adjusters back and forth to loosen up, fabricate and install rail with rubber seal behind seat to keep seat belts from getting pinched. Re-route seat belts correctly for proper usage. Remove front suspension sway bar, install new bushings to eliminate rattles. Polish and install 4 new stainless steel teflon lined rod ends on sway bar. Fabricate extension to change angle of right side mirror for better visibility. Test drive vehicle and evaluate changes. Install second set of Wilwood brake pads of different compound to attempt to eliminate brake squeek problem.	32.70	4,414.50
Ball joint rod end, corrosion resistant, 1/2"-20 internal right hand thread <i>McMaster Carr</i>	2.00	50.04	100.08		1.20	162.00
				Mechanical Work Performed Test drive vehicle with new brake pads. Brake squeal still present at slow speed. Remove brake pads and install anti vibration material behind brake pads to try and eliminate noise at suggestion of Wilwood tech dept.		
				Reg Solutions Inspect car and fill out Verification of Vehicle form for DMV		65.00
				McMaster Carr Shipping		11.34

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	4,576.50
Parts:	200.16
Sublet:	76.34
SubTotal:	4,853.00
Tax:	18.51
Total:	4,871.51
Bal Due:	\$4,871.51

[Payments -]

Vehicle Received: 2/17/2020

Customer Number : 165

TERMS - DUE ON RECEIPT

Moal, Inc.

937 East 12th Street
Oakland, CA 94606-3723
(510) 834-0171
(510) 272-9288 Fax



Invoice

DATE	INVOICE #
6/16/2020	548

BILL TO

P.O. NO.	TERMS
Verbal Phil	Due on receipt

DESCRIPTION	QTY	RATE	AMOUNT
1934 Ford Radiator Cap	1	55.00	55.00
Shipping from manufacture to Moal's	1	12.00	12.00
Shipping from Moal's to Moraga	1	14.00	14.00
Thank you for your business.			Total \$81.00

*Phil # 1354
6-23-20*

Moal Inc
 937 East 12th Street
 Oakland, CA. 94606
 Phone: 510-834-9066 Fax: 510-272-9288

INVOICE

1437

INVOICE

Printed Date: 01/07/2025 Work Completed: 06/05/2020

1934 Ford - Cabriolet -
 Lic # : Odometer In : 0

VIN # : 18016123

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Exhaust header gasket set, MRG-5928 <i>Summit</i>	1.00	33.41	33.41	Mechanical Work Performed	8.40	1,134.00
High note horn <i>Moal</i>	1.00	15.08	15.08	Replace single horn with high and low note dual horns and wire as needed. Repair horn button in steering wheel. Set suspension ride setting to soft. Diagnose exhaust leak. Remove right and left exhaust headers and clean mounting surfaces. Order and install new header gaskets (note - installed smaller opening gaskets for correct fit the cylinder head). Fix rattle in left door caused by loose window regulator. Remove steering wheel and clock at correct orientation for turn signal canceling and set steering rack equal turns lock to lock. Test drive and road test car.		
Low note horn <i>Moal</i>	1.00	15.08	15.08			
				Detail Work Performed	12.00	1,620.00
				Clean underside of car. Polish rear end center section and clean chrome suspension components. Polish aluminum wheels. Clean top irons and remove stains from convertible top. Clean off paint. Mask top, running boards, grille, and fender beading. Compound and machine polish exterior painted surfaces. Clean off car and unmask. Hand wax exterior of car. Clean engine and dust from under hood. Clean tires and running boards.		
				Loren Fink A/C		260.00
				Recover, evacuate, and recharge A/C system. Test run and leak test system		
				McM-Carr		11.34
				Shipping Charges		
				Summit		14.29
				Shipping		
				Union 76		33.99
				10 Gallons Super Unleaded Gasoline		

Org. Estimate 2,873.07 Revisions 0.00 Current Estimate 2,873.07

Labor:	2,754.00
Parts:	63.57
Sublet:	319.62
SubTotal:	3,137.19
Tax:	5.88
Total:	3,143.07
Bal Due:	\$3,143.07

[Payments -]

Vehicle Received: 6/2/2020

Customer Number : 165

TERMS - DUE ON RECEIPT

Moal, Inc.

937 East 12th Street
Oakland, CA 94606-3723
(510) 834-0171
(510) 272-9288 Fax



Invoice

DATE	INVOICE #
7/21/2020	553

BILL TO

P.O. NO.	TERMS
Verbal Phil	Due on receipt

DESCRIPTION	QTY	RATE	AMOUNT
1934 Ford Polished S.S. Greyhound Radiator Cap	1	850.00	850.00T
Modify base of cap for better fit	1	75.00	75.00
Shipping	1	20.00	20.00
Sales Tax		9.25%	78.63

Thank you for your business.	Total	\$1,023.63
------------------------------	--------------	------------

*get chg 13 62
7-21-20*

Invoice No.
000084041

MORAGA MOTORS

Order Date 11/13/23 09:52 am
Completed: 11/14/23 01:19 pm

BAR #: AH235392
530 Moraga Road
Moraga, CA 94556
Phone: 925-376-0692

Professional Automotive Service and Repair



34 FORD COUPE
1127 Mi.Last in 9/5/2019
Lic: ? Cyl Eng
Vin: 18016123
Eq: AT

Quotes		
1	11/13/23 10:01am	35.00
PHIL in person.		

TIRE MT & BAL STD Labor: \$347.00

MOUNT & BALANCE TIRE
**SET TIRE PRESSURE TO FACTORY SPEC.
TIRES DO NOT COME WITH ROAD HAZARD WARRANTY

P255/45ZR20 105W NITTO NT 555 G2-S	2.0 @	227.99 = \$	455.98	
P215/40ZR17 87W NITTO NEO GEN-S	2.0 @	145.35 = \$	290.70	746.68

Payments to MORAGA MOTORS

Status: Completed Work Order

Payments:

Cost Summary

Labor	347.00
Parts	746.68
Haz Waste	28.00
Subtotal	1121.68
Tax	72.80
Total	\$1194.48
Payments	0.00
Bal Due	1194.48

Thank you for choosing MORAGA MOTORS

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Date: 12/18/2023 08:11 AM
Estimate ID: 2326
Estimate Version: 4
Supplement: 3 (F F) 12/18/2023 07:09:54 AM
Profile ID: * SPECIALIZED CLAIMS

Specialized Claims Synergy

P.O. BOX 25, PAYSON, AZ 85541
(855) 735-9727
Fax: (855) 572-9812

Email: "All Supplements require pre-authorization from the insurance company."

Damage Assessed By: THOMAS CARVAJAL

Appraised For: HAGERTY INSURANCE AGENCY LLC
(800) 922-4050

Supplemented By: THOMAS CARVAJAL
Classification: None

Condition Code: Good
Date of Loss: 11/14/2023
Deductible: NONE
Claim Number: MK23111551-1

Type of Loss: Collision

Insured:
Owner:
Address:
Telephone:

Description: 34 RED FORD MODEL 40 CONVERTIBLE
VIN: 18016123
OEM/ALT: A
Color: RED

Vehicle Production Date: /34
License: 2B8710 CA
Search Code: B1014542

THE INSURER WARRANTS THAT SUCH PARTS ARE AT
LEAST EQUAL TO THE ORIGINAL EQUIPMENT
MANUFACTURER PARTS IN TERMS OF KIND, QUALITY,
Safety, Fit and Performance.

1. Complete a mechanical check of the engine and all systems prior to starting any repair work or ordering parts. The carrier is not responsible for charges if proper procedures are not followed.
2. Attentional Repair Facility: If you do not agree with the estimate or labor rates, parts, or repair times, please contact our office before you begin repair work to document your concerns.
3. Please be advised that the Insurance Carrier is not responsible for restoration work to this vehicle. If you encounter problem areas during the repair, do not assume it is covered by the loss.
4. Stripping of panels is considered restoration work and is not covered by the Insurance Company. Please be advised that the Insurance Carrier is not responsible for restoration work to this vehicle.

ESTIMATE RECALL NUMBER: 12/11/2023 08:20:31 2326

Mitchell Data Version: OEM: JUL_23_V
MAPP: JUL_23_V

Software Version: 7.1.243

Copyright (C) 1994 - 2023 Mitchell International
All Rights Reserved

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/Part Number	Dollar Amount	Labor Units
				<u>Special/Manual Entry</u>			
S2 1	900500	BDY *	REMOVE/REPLACE	FRONT BUMPER ASSY	** QUAL REPL PART	395.00 *	1.0*
2				SPEEDWAY MOTORS			
S2 3	900500	BDY *	REMOVE/REPLACE	R/L BUMPER OUTER BRKTS(4)	** QUAL REPL PART	312.50 *	2.0*
4				PRE-FIT BRKTS TO VEHICLE			
S2 5	900500	BDY *	REMOVE/REPLACE	R/L INNER BRKTSBUMPER BRKTS	New	300.00 *	2.0*
S3 6	900500	BDY *	ADD'L LABOR OP	RE-CHROME BRKTS(4)	Sublet	700.00 *	0.0*
S3 7	900500	BDY *	ADD'L LABOR OP	BRKT HAZARDOUS WASTE DISPOSAL FEE	Sublet	70.00 *	0.0*
S3 8	900500	BDY *	ADD'L LABOR OP	BRKT SHIPPING CHARGE	Sublet	25.00 *	0.0*
S3 9	900500	BDY *	ADD'L LABOR OP	STRP FRONT CHROME FROM W/SHIELD	(INCS 25% MRKUP)	993.75 *	0.0*
				<u>Grille</u>			
S2 10	100811	BDY	REMOVE/REPLACE	Grille	Qual Recycled Part	4,500.00 *	3.0*
				<u>Special/Manual Entry</u>			
S3 11	900500	BDY *	ADD'L LABOR OP	STRIP AND CHROME USED GRILLE(INCS 25% MRKU	Sublet	2,062.50 *	0.0*
S1 12	900500	BDY *	REMOVE/REPLACE	GRILLE RIVETS	** QUAL REPL PART	20.00 *	0.0*
S3 13	900500	BDY *	REMOVE/REPLACE	SHIPPING	Sublet	25.00 *	0.0*
S1 14	900500	BDY *	REMOVE/INSTALL	GRILLE SURROUND MLDG	Existing		1.0*
				<u>Grille</u>			
S2 15	100812	BDY	REMOVE/REPLACE	Grille Emblem	Remanufactured	52.50 *	0.3*
				<u>Special/Manual Entry</u>			
S1 16	900500	BDY *	REMOVE/INSTALL	GRILLE WELTING ON OLD GRILLE TO NEW GRILLE	Existing		1.0*
S1 17	900500	BDY *	REMOVE/INSTALL	RADIATOR CAP COVER	Existing		0.3*
S3 18	900500	BDY *	ADD'L LABOR OP	RECHROME GRILLE	Sublet	1,500.00 *	0.0*
S2 19	900500	BDY *	REMOVE/REPLACE	V/8 BADGE	New	40.00 *	0.3*
S3 20	900500	BDY *	REMOVE/REPLACE	GRILLE HAZARDOUS WASTE	Sublet	150.00 *	0.0*
S1 21	900500	BDY *	REMOVE/INSTALL	GRILL NOSE ORNAMENT MLDG	Existing		0.5*
S1 22	900500	BDY *	REMOVE/INSTALL	FORD RADIATOR EMBLEM	Existing		0.3*
S1 23	900500	BDY *	REMOVE/INSTALL	LWR GRILLE SHELL FILLER PANEL	Existing		1.0*
S1 24	900500	BDY *	REMOVE/INSTALL	A/C CONDENSOR	Existing		1.0*
S1 25	900500	BDY *	REMOVE/REPLACE	A/C LINE O RINGS 2@15.00	** QUAL REPL PART	30.00 *	0.0*
S1 26	900500	BDY *	ADD'L LABOR OP	DRAIN AND REFILL COOLING SYSTEM	Existing		1.0*
S1 27	900500	BDY *	REMOVE/INSTALL	UPPER/LOWER RSDIATOR HOSES	Existing		0.6*
S1 28	900500	BDY *	REMOVE/INSTALL	RADIATOR	Existing		1.0*
S1 29	900500	BDY *	REMOVE/REPLACE	COOLANT	** QUAL REPL PART	20.00 *	0.0*
S2 30	900500	BDY *	REMOVE/REPLACE	HEADLAMP RINGS 2@55.00	** QUAL REPL PART	110.00 *	0.6*
S1 31	900500	BDY *	REMOVE/INSTALL	R/L HEADLAMP BUCKETS	Existing		1.0*
S1 32	900500	BDY *	REMOVE/INSTALL	R/L HEADLAMP STATIONS	Existing		1.0*
				<u>Hood</u>			
S1 33	100102	BDY	REMOVE/INSTALL	Hood Assy			1.0*
				<u>Special/Manual Entry</u>			
S1 34	900500	BDY *	REMOVE/INSTALL	HOOD BRACES AND LATCHES	Existing		2.0*
				<u>Hood</u>			
35	100263	BDY	REPAIR	Hood Panel	Existing		6.0*
S1 36		REF	REFINISH/REPAIR	Hood Panel	Existing		2.5*
				<u>Special/Manual Entry</u>			
S1 37	900500	BDY *	REPAIR	PREP HOOD EXTERIOR/UNDERSIDE	Existing		4.0*
S1 38	900500	REF *	REFINISH/REPAIR	HOOD UNDERSIDE	Existing		3.0*
S1 39	900500	BDY *	REMOVE/INSTALL	R/L HOOD SIDE PANELS	Existing		1.0*
S1 40	900500	BDY *	REMOVE/INSTALL	L/R HOOD LATCH ASSYS	Existing		1.0*
S1 41	900500	REF *	REFINISH/REPAIR	PREP AND PAINT R/L HOOD SIDE PANELS	Existing		7.0*
S1 42	900500	BDY *	REMOVE/REPLACE	WINDSHIELD	** QUAL REPL PART	450.00 *	3.0*
43				RE-CUT GLASS TO EXISTING FRAME			
				<u>Front Fender</u>			
S2 44	101246	BDY	REMOVE/REPLACE	R Fender Panel	Remanufactured	950.00 *	6.0*
45				Speed Way Motors			

ESTIMATE RECALL NUMBER: 12/11/2023 08:20:31 2326

Mitchell Data Version: OEM: JUL_23_V
 MAPP: JUL_23_V
 Software Version: 7.1.243

Copyright (C) 1994 - 2023 Mitchell International
 All Rights Reserved

Item	REF	REFINISH/REPAIR	R Fender Panel	Special/Manual Entry	Existing	4.0*
S1 46					Existing	4.0*
S1 47	900500	BDY *	REMOVE/INSTALL	R/LRUNNING BOARD	Existing	3.0*
S1 48	900500	BDY *	REMOVE/INSTALL	R/L FENDER FILLER	Existing	3.0*
S1 49	900500	REF *	REFINISH/REPAIR	R/L FENDER FILLER	Existing	1.0*
S1 50	900500	BDY *	REMOVE/INSTALL	R FENDER/HEADLAMP BRACE	Existing	2.0*
S1 51	900500	BDY *	REPAIR	R FENDER/HEADLAMP BRACE	Existing	1.5*
S1 52		REF	REFINISH/REPAIR	R FENDER/HEADLAMP BRACE	Existing	0.5*
S1 53	900500	BDY *	REMOVE/INSTALL	R FENDER/HEADLAMP BRACE REAR	Existing	0.0*
S1 54	900500	REF *	REFINISH/REPAIR	RIGHT FENDER BRACE REAR RED	Existing	1.0*
S1 55	900500	REF *	REFINISH/REPAIR	RIGHT FENDER BRACE REAR BLACK	Existing	1.0*
S1 56	900500	BDY *	REMOVE/INSTALL	RT FENDER WELTING	Existing	4.0*
S1 57	900500	BDY *	REPAIR	RT FENDER MOUNTING/WELD & FIT	Existing	8.0*
S1 58	900500	BDY *	ADD'L LABOR OP	MODIFY RT FENDER BODY TWIST TO MATCH FIT	Sublet	111.87 * 0.0*
S3 59	900500	BDY *	ADD'L LABOR OP	RECHROME FENDER MLDG(INCS 25% MRKUP)	** QUAL REPL PART	1.0*
S1 60	900500	BDY *	ADD'L LABOR OP	RESEAL RT FENDR SIDE MOUNTING	Sublet	100.00 * 0.0*
S1 61	900500	BDY *	REMOVE/INSTALL	STRIP/RECHROME RT FENDER CNTR MLDG	New	950.00 * 6.0*
S2 62	900500	BDY *	REMOVE/REPLACE	LT FENDER(INCS MODIFY TO FIT VEHICLE)	Existing	1.0*
S1 63	900500	BDY *	REMOVE/INSTALL	L HEADLAMP BRACE	Existing	2.0*
S1 64	900500	BDY *	REPAIR	L HEADLAMP BRACE(REAR)	Existing	1.5*
S1 65		REF	REFINISH/REPAIR	L HEADLAMP BRACE(REAR)	Existing	0.5*
S1 66	900500	BDY *	REMOVE/INSTALL	L HEADLAMP BRACE REAR (BLK)	Existing	0.5*
S1 67		REF	REFINISH/REPAIR	L HEADLAMP BRACE REAR (BLK)	Existing	0.0*
S1 68	900500	BDY *	REPAIR	L HEADLAMP BRACE REAR	Existing	1.0*
S1 69	900500	BDY *	REMOVE/INSTALL	LT FENDER WELTING	Existing	8.0*
S1 70	900500	BDY *	REPAIR	LT FENDER MOUNTING/WELD & FIT	Existing	8.0*
S1 71	900500	BDY *	REPAIR	MODIFY RT FENDER BODY TWIST TO MATCH FIT	Existing	4.0*
S1 72	900500	BDY *	REPAIR	LT FENDER MOUNTING/WELD & FIT	Existing	4.0*
S1 73	900500	REF *	REFINISH/REPAIR	LT FENDER OUTER	Existing	2.0*
S1 74	900500	REF *	ADD'L LABOR OP	PREP/SEAL/UNDERCOST FENDER UNDERSIDE	Existing	1.0*
S1 75	900500	BDY *	REMOVE/INSTALL	R/L COWL LAMPS	Existing	1.0*
S1 76	900500	BDY *	REMOVE/INSTALL	COWL VENT ASSY	Existing	1.0*
S1 77	900500	REF *	REFINISH/REPAIR	PREP/PAINT COWL VENT DORR	Existing	1.0*
S1 78	900500	BDY *	REMOVE/INSTALL	WINDSHIELD WIPER ARM AND POST ASSY	Existing	1.0*
S1 79	900500	BDY *	REMOVE/INSTALL	R/L KICK PANELS	Existing	8.0*
S1 80	900500	BDY *	REMOVE/INSTALL	DASH ASSY FOR W/SHIELD FRAME REPAIR	Existing	0.5*
S1 81	900500	BDY *	ADD'L LABOR OP	DROP STEERING COLUMN FOR ACCESS	Existing	1.0*
S1 82	900500	BDY *	REMOVE/INSTALL	R/L WIDSHIELD GARNISH	Existing	0.5*
S1 83	900500	BDY *	REMOVE/INSTALL	INSIDE MIRROR ASSY	Existing	0.0*
S1 84	900500	BDY *	REMOVE/INSTALL	WINDSHIELD HEADER COVER	Existing	2.0*
S1 85	900500	BDY *	REMOVE/INSTALL	WISHIELD FRAME ASSY FOR REPAIR ACCESS	Existing	1.0*
S1 86	900500	BDY *	ADD'L LABOR OP	R/L DOOR POST SEAT AND RETAINER ASSYS	Existing	1.0*
S1 87	900500	BDY *	REMOVE/INSTALL	R/L SIDE COWL WELTING	Existing	2.0*
S1 88	900500	REF *	REFINISH/REPAIR	PREP/PAINT COWL TOP PANEL	Existing	4.0*
S1 89	900500	REF *	REFINISH/REPAIR	PREP/PAINT UPPER WINDSHIELD FRAME	Existing	4.0*
S1 90	900500	REF *	REFINISH/REPAIR	PREP/PAINT R/L COWL SIDES	Existing	0.6*
S1 91	900500	BDY *	REMOVE/INSTALL	RT/ILT DOOR UPPER GARNISH MLDG	Existing	2.0*
S1 92	900500	BDY *	REMOVE/INSTALL	RT/ILT DOOR TRIM PANEL	Existing	2.0*
S1 93	900500	BDY *	REMOVE/INSTALL	RT/ILT DOOR GLASS AND REGULATOR ASSY	Existing	0.5*
S1 94	900500	BDY *	REMOVE/INSTALL	RT DOOR CYL LOCK ASSY	Existing	1.0*
S1 95	900500	BDY *	REMOVE/INSTALL	RT/ILT DOOR MIRROR ASSY	Existing	1.0*
S1 96	900500	BDY *	REMOVE/INSTALL	RT/ILT OUTER DOOR HANDLES	Existing	4.0*
S1 97	900500	BDY *	REMOVE/INSTALL	RT/ILT DOOR SHELL ASSYS	Existing	5.0*
S1 98	900500	REF *	REFINISH/REPAIR	RT/ILT DOOR SHELL ASSY PREP/PAINT	Existing	0.6*
S1 99	900500	BDY *	REMOVE/INSTALL	RT/ILT DOOR SILL MLDG	Existing	4.0*
S1 100	900500	REF *	REFINISH/REPAIR	PREP/PAINT RT/ILT ROCKER PANEL	Existing	4.0*
S1 101	900500	BDY *	ADD'L LABOR OP	TRAVEL TIME TO SACRAMENTO TO OBTAIN PARTS	Sublet	4.0*
102	900500	BDY *	ADD'L LABOR OP	Pull to Square Front Structure	Existing	4.0*
S1 103	900500	BDY *	ADD'L LABOR OP	TINT CUSTOM COLOR(NO FORMULA)	Existing	8.0*

ESTIMATE RECALL NUMBER: 12/11/2023 08:20:31 2326

Mitchell Data Version: OEM: JUL_23_V
 MAPP: JUL_23_V

Software Version: 7.1.243

Copyright (C) 1994 - 2023 Mitchell International
 All Rights Reserved

104				MULTIPLE SPRAYOUT TEST PANELS					
S1 105	900500	BDY *	ADD'L LABOR OP	ALIGN SUSPENSION	Sublet		175.00 *	0.0*	
S3 106	900500	BDY *	REPAIR	STREET CHROME GRILLE	Sublet		1,500.00 *	0.0*	
S3 107	900500	BDY *	REMOVE/REPLACE	STREET CHROME HAZARDOUS WASTE	Sublet		150.00 *	0.0*	
S1 108	900500	BDY *	ADD'L LABOR OP	TOWING CHARGE FROM OWNERS RESIDENCE	Sublet		437.50 *	0.0*	
S3 109	900500	BDY *	REMOVE/REPLACE	SMALL LATCH STREET CHROME	Sublet		65.00 *	0.0*	
				<u>Additional Operations</u>					
				Restore Corrosion Protection			50.00 *	1.0*	
				<u>Special/Manual Entry</u>					
				SMALL LATCH HAZARDOUS WASTE	Sublet		6.50 *	0.0*	
S3 111	900500	BDY *	REMOVE/REPLACE	SHIPPING	Sublet		18.00 *	0.0*	
S3 112	900500	BDY *	ADD'L LABOR OP	COLOR SAND/HAND RUB ALL PAINTED PANELS	Existing			20.0*	
S1 113	900500	BDY *	ADD'L LABOR OP	<u>Additional Operations</u>					
				Mask For Overspray					
				<u>Additional Costs & Materials</u>					
				Paint/Materials			2,496.00 *		
				Hazardous Waste Disposal			10.00 *		
114	933018	REF	ADD'L OPR						
			ADD'L COST						
			ADD'L COST						

* - Judgment Item

Estimate Totals

						II. Part Replacement Summary			Amount
I. Labor Subtotals						Taxable Parts			8,130.00
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Sales Tax	@ 9.000%		731.70
Body	165.6	165.00	50.00	7,693.62	35,067.62				
Refinish	52.5	165.00	25.00	0.00	8,687.50				396.50
Non-Taxable Labor						Non-Taxable Parts			
Labor Summary						218.1			9,258.20
						Total Replacement Parts Amount			
III. Additional Costs						IV. Adjustments			Amount
Taxable Costs						Insurance Deductible			0.00
Sales Tax @ 9.000%						Customer Responsibility			0.00
Non-Taxable Costs									
Total Additional Costs									
Paint Material Method: Rates									
Init Rate = 48.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I. Total Labor:			43,755.12
						II. Total Replacement Parts:			9,258.20
						III. Total Additional Costs:			2,730.64
						Gross Total:			55,743.96