

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____
 Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.
 X _____ Date: _____
 I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 99535

1991 BMW M5

License # 2XGB285

Inv Date: 6/22/2021 @ 9:46am

VIN: BK06159

Odom: 246895

Service Writer: Eric Ingraham

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Color: Alpinweiss 2

Status: Complete

Trans: 5SP MANUAL

Mfg. Date: 04/91

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Rear suspension problems						
Labor Service - Remove & replace rear subframe mounts. NAI			2.50		170.00	425.00
New 33-31-1-128-670	Bushing subframe E32/4			2.00	79.21	158.42
Labor Service - Replace rear suspension toe links. NAI			0.75		170.00	127.50
New 33-32-1-125-665	Link rear trailing arm			2.00	138.38	276.76
Labor Service - Remove & replace rear swaybar links. NAI			1.25		170.00	212.50
New 33-55-1-131-131	Link rear swaybar			2.00	39.48	78.96
4-wheel alignment needed						
Labor Service - 4-wheel alignment. AW			1.00		225.00	225.00
Door open chime comes on going over railroad tracks						
Labor Service - Monitor status via GT1: close/open normal. Recommend replacement of driver's door striker as possible cause. KR			0.30		170.00	51.00
Labor Service - Remove & replace driver's door striker/switch as likely cause of door open warning. KR			0.20		170.00	34.00
New 51-21-8-105-511	Striker w/switch			1.00	47.84	47.84
Check tire pressures. Adjust to recommended pressures.						
Labor Service - Rotate rear wheels left-to-right. NAI			1.00			0.00
Labor Service - Check & adjust tire pressures. Front 33psi Rear 38psi NAI						0.00
Recommended Repairs and Services:						
• Airflow meter suspect NLA						1,210.00
• Slight play in steering gearbox - steering box is worn (adjusted 3/20)						
• 1200 Mile Service @ 247,200						605.71

Invoice Summary
 Parts 561.98
 Labor 1,075.00

X _____
 Customer acknowledges receipt of merchandise and services.

Sub Total 1,636.98
 Sales Tax (DEF) 51.98

Discard old parts

Original Estimate: 1,721.70

Total 1,688.96



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Date:

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X

Date:

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 98399

1991 BMW M5

License # 2XGB285

Inv Date: 3/03/2021 @ 1:03pm

VIN: BK06159

Odom: 246632

Service Writer: Nat Sears

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Color: Alpinweiss 2

Status: Complete

Trans: 5SP MANUAL

Mfg. Date: 04/91

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Replace battery, check alternator. Anti-Lock & Check Engine lights on.						
Labor Service - Remove & replace battery. Check function of charging system: 12v, 0a output, inoperative. Check alternator connections & ground: OK. Recommend replacement of failed alternator. SS			0.75		170.00	127.50
New	61-21-2-353-810	Battery BMW 90ah		1.00	195.00	195.00
Core	61-21-2-353-810	Core Received		1.00	0.00	0.00
New	12 BATTERY PROT	Battery terminal protector		2.00	0.75	1.50
Labor Service - Remove & replace alternator. Replace marginal ring connector. Recheck charging system function: good output, good voltage. CK			1.75		170.00	297.50
New	12-31-1-315-962	Alternator 140a		1.00	849.00	849.00
Core	12-31-1-315-962	Core Received		1.00	0.00	0.00
Sublet	FREIGHT	Shipping & Handling		1.00	140.00	140.00
New		Ring connector 6mm		1.00	2.25	2.25
Labor Service - Download fault codes from DME control unit: 10/oxygen sensor control, mixture too lean, 2x No diagnostic communication w/ABS control unit. Clear codes, test drive & recheck: no warning lights, no codes. Suspect low voltage the cause. Monitor! CK			1.00		60.00	60.00
Check tire pressures. Adjust to recommended pressures.						
Labor Service - Check & adjust tire pressures. Front 38psi Rear 41psi SS						0.00
Recommended Repairs and Services:						
• Airflow meter suspect NLA						1,210.00
• Slight play in steering gearbox - steering box is worn (adjusted 3/20)						
• 1200 Mile Service @ 247,200						605.71
• Rear suspension problems						1,273.68
• 4-wheel alignment needed						225.00
Add On Charges Breakdown						
Haz. Materials						1.00



218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000

TEAM@BAYPROS.COM • WWW.BAYPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Date:

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X

Date:

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 98399

1991 BMW M5

License # 2XGB285

Inv Date: 3/03/2021 @ 1:03pm

Continued from previous page

<p>X</p> <p>Customer acknowledges receipt of merchandise and services.</p>	<p>PAID VISA</p> <p>3/5/21</p> <p>Thanks!</p>	Invoice Summary												
		<table><tr><td>Parts</td><td>1,047.75</td></tr><tr><td>Labor</td><td>485.00</td></tr><tr><td>Sublet</td><td>140.00</td></tr><tr><td>Add On Charges</td><td>1.00</td></tr><tr><td colspan="2">Sub Total 1,673.75</td></tr><tr><td colspan="2">Sales Tax (DEF) 96.92</td></tr><tr><td colspan="2">Total 1,770.67</td></tr></table>	Parts	1,047.75	Labor	485.00	Sublet	140.00	Add On Charges	1.00	Sub Total 1,673.75		Sales Tax (DEF) 96.92	
Parts	1,047.75													
Labor	485.00													
Sublet	140.00													
Add On Charges	1.00													
Sub Total 1,673.75														
Sales Tax (DEF) 96.92														
Total 1,770.67														
Page 2 of 2	Discard old parts	Original Estimate:												

(510) 524-6000

BAR #ARD 162304 EPA #CAL 0000 43044

THANK YOU!



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X Date: _____
Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.
X Date: _____
I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 97384

1991 BMW M5

License # 2XGB285

Inv Date: 11/11/2020 @ 8:18am

Odom: 245935

VIN: BK06159

Color: Alpinweiss 2

Service Writer: Eric Ingraham

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Mfg. Date: 04/1991

Status: Complete

Trans: 5SP MANUAL

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Disc.	Ext
Oil level low indicator/message							
Labor Service - Remove & install check control module: no change. Trace wiring, check voltage, ground, resistance: all good. Oil level sensor needs replacement. KR			0.75		170.00		127.50
Labor Service - W/engine oil drained, remove & replace oil level sensor. CK			0.25		170.00		42.50
New	12-61-1-312-343	Sensor oil level		1.00	268.18		268.18
New	12-61-1-277-129	O-ring oil level sensor		1.00	7.38		7.38
Cylinder head gasket needs replacement							
Labor Service - Remove & install cylinder head. Clean gasket surfaces, replace head gasket. Drain, refill & bleed cooling system. Torque cylinder head to specifications. CK			25.00		170.00		4,250.00
Sublet	VALVE JOB	Sublet valve job		1.00	1,500.00		1,500.00
New	11-12-1-316-705	Head gasket S38		1.00	244.99		244.99
New	11-12-9-059-244	Head gasket set S38 B36		1.00	821.98		821.98
New	17-22-2-245-358	O-ring		2.00	1.72		3.44
New	12-11-1-252-257	O-ring M cam caps		2.00	6.70		13.40
New	11-62-1-304-755	Copper nut 6mm		24.00	1.94		46.56
New	11-61-1-312-670	Hose crankcase breather		1.00	34.86		34.86
New	11-41-1-306-082	O-ring 16x2mm		1.00	12.28		12.28
New	64-11-1-368-684	Vacuum line		1.00	15.38		15.38
New	13-41-1-312-707	Hose ICV S38 B36		1.00	77.71		77.71
New	13-41-1-312-666	Hose ICV S38 B36		1.00	21.55		21.55
New	11-53-1-738-054	Hose 4-way		1.00	135.31		135.31
New	13-41-1-705-564	Mount ICV		2.00	9.00		18.00
New	11-15-1-306-958	Hose breather S38 B35		1.00	40.13		40.13
New	64-12-8-363-817	Connector "I" 20mm		1.00	13.89		13.89
New	82-14-1-467-704	Antifreeze BMW, gallons		1.50	24.75		37.13
New	H2O	Distilled water, gallon		1.50	2.00		3.00
Labor Service - Remove and replace engine oil, oil filter, & seal at drain plug. CK			0.25		170.00	-42.50	0.00
New	20W50 VALVOLINE	Oil Valvoline, liters		6.00	6.95		41.70
New	11-42-9-063-138	OX41D oil filter kit M30		1.00	17.47		17.47
Cooling hoses need replacement							
Labor Service - Remove & replace all cooling hoses. Drain, refill & bleed cooling system. CK			4.00		170.00	-680.00	0.00
New	11-53-1-312-241	Hose upper radiator S38 B36		1.00	48.68		48.68
New	11-53-1-312-292	Hose short @ pipe S38 B36		1.00	8.21		8.21
New	11-53-1-312-684	Hose tstat S38 B36		1.00	24.42		24.42
New	11-53-1-312-690	Hose tstat w/pump S38 B36		1.00	29.53		29.53
New	11-53-1-312-735	Hose lower radiator S38 B36		1.00	47.48		47.48
New	11-53-1-312-817	Hose heater outlet S38 B36		1.00	50.08		50.08
New	11-53-1-312-950	Hose bleeder elbow S38 B36		1.00	19.20		19.20
New	11-53-1-312-966	Coolant pipe S38 B36		1.00	8.50		8.50
New	64-21-1-384-712	Hose heater E34		1.00	17.22		17.22
New	64-21-1-384-763	Hose heater pump/valve E32/34		1.00	87.21		87.21
New	64-21-1-391-286	Hose heater E34 M5 inlet		1.00	448.68		448.68
New	64-21-1-391-766	Hose heater NLA		1.00	120.00		120.00
New	17-12-1-712-736	Hose 8mm coolant, meters		0.50	66.20		33.10
New	CRIMP 14.5	Crimp clamp 14.5		1.00	1.44		1.44
New	GLOBAL 8-12	Hoseclamp 8-12		4.00	2.85		11.40
New	NORMA 12-20	Hoseclamp 12-20		2.00	3.73		7.46



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____
Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.
X _____ Date: _____
I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 97384

1991 BMW M5

License # 2XGB285

Inv Date: 11/11/2020 @ 8:18am

New	NORMA 16-25	Hoseclamp 16-25	11.00	3.45	37.95
New	NORMA 20-32	Hoseclamp 20-32	5.00	2.85	14.25
New	NORMA 30-45	Hoseclamp 30-45	3.00	2.40	7.20
New	NORMA 32-50	Hoseclamp 32-50	3.00	2.73	8.19
New	NORMA 40-60	Hoseclamp 40-60	3.00	2.50	7.50
Labor Service - Remove & replace thermostat. CK			1.00	170.00	-170.00
New	11-53-7-835-558	Thermostat S38B36/S62	1.00	115.56	115.56
New	11-53-1-312-635	Seal tstat S38 B36	1.00	1.86	1.86
New	11-53-1-312-287	Seal thermostat	1.00	21.25	21.25

Center tie rod worn

Labor Service - Remove & replace center tie rod. AW			1.25	170.00	212.50
New	32-21-1-138-864	Center tie rod E34	1.00	276.61	276.61

Instrument cluster illumination out for fuel gauge

Labor Service - Remove & install instrument cluster, replace all bulbs for cluster illumination. AW			0.75	170.00	127.50
New	07-11-9-978-372	Bulb 3w 2821	3.00	4.48	13.44

Wiper blades need replacement

Labor Service - Remove & replace wiper blade inserts. AW			0.20	170.00	34.00
New	61-61-8-217-711	Wiper insert 645mm wide	2.00	21.30	42.60

Loaner car

Labor Service - Customer in Bavarian Professionals courtesy loaner car BAVPRO7, and agrees to terms of Loaner Car Agreement as shown on reverse. EI					0.00
---	--	--	--	--	------

Revisions of Original Estimate - Original Estimate of Services and Parts \$8,702.94

Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
1	12/03/2020 5:25AM				EI	1,347.06	10,050.00
Center tie rod, IC illum, wipers							

X

Customer accepts revision to the invoice and agrees to pay revised amount.

Recommended Repairs and Services:

• Airflow meter suspect NLA	1,210.00
• Slight play in steering gearbox - steering box is worn (adjusted 3/20)	
• 1200 Mile Service @ 247,200	605.71
• Rear suspension problems	1,273.68
• 4-wheel alignment needed	225.00

Add On Charges Breakdown

Haz. Materials	7.50
FET	0.30



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Date:

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X

Date:

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 97384

1991 BMW M5

License # 2XGB285

Inv Date: 11/11/2020 @ 8:18am

Continued from previous page

<div>X Customer acknowledges receipt of merchandise and services.</div>		Invoice Summary	
		Parts	3,383.36
		Labor	4,794.00
		Sublet	1,500.00
		Add On Charges	7.80
		Sub Total	9,685.16
		Sales Tax (DEF)	312.96
		Total	9,998.12

Page 3 of 3 Discard old parts Original Estimate: 8,702.94

(510) 524-6000

EAR #ARD 162304 EPA #CAL 0000 43044

THANK YOU!



18 7TH STREET, BERKELEY, CA 94710
(510) 524-6000

TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Date:

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X

Date:

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 97261

1991 BMW M5

License # 2XGB285

Inv Date: 10/29/2020 @ 10:57am

Odom: 245711

VIN: BK06159

Color: Alpinweiss 2

Service Writer: Nino Guerra Gilmour

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Mfg. Date: 04/1991

Status: Complete

Trans: 5SP MANUAL

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price		Ext
------------------	----------------------	--------------------	-----	-----	-------	--	-----

Oil & filter change

Labor Service - Remove and replace engine oil, oil filter, & seal at drain plug. LL			0.25		170.00		42.50
New 20W50 VALVOLINE Oil Valvoline, liters				6.00	6.95		41.70
New 11-42-9-063-138 OX41D oil filter kit M30				1.00	17.47		17.47
Labor Service - Check & adjust tire pressures.							0.00
Front 33psi							
Rear 38psi LL							

Oil drips from engine

Labor Service - Degrease engine compartment, add dye to oil, test drive car and diagnose source/s of oil leakage: oil pan gasket leaking badly. KR			0.75		170.00		127.50
New 81-22-9-407-104 Degreaser engine, gallons				0.25	72.50		18.13
New TP3400 Trace dye				1.00	12.50		12.50
Labor Service - Drain engine oil, remove oil pan. Clean gasket surfaces, replace pan gasket. Replace engine oil & filter. NAI			4.00		170.00		680.00
New 11-13-1-315-154 Gasket oil pan late M30/S38B36				1.00	30.38		30.38
New 12-61-1-277-129 O-ring oil level sensor				1.00	7.38		7.38
New 07-11-9-915-031 Bolt 6x20mm w/washer				1.00	1.95		1.95

Driver's door warning/chime comes on when going over bigger bumps

Labor Service - Unable to recreate warning while driving. Test all doors for play while closed & check for warning while doing so: no issue present as tested. Lubricate driver's door brake & hinge to eliminate squeak. KR			1.00		170.00		170.00
--	--	--	------	--	--------	--	--------

LR halfshaft worn

Labor Service - NAI			0.75		170.00		127.50
New 33-21-1-226-622R Halfshaft E34				1.00	627.71		627.71
Core 33-21-1-226-622R Core Received				1.00	0.00		0.00

Revisions of Original Estimate - Original Estimate of Services and Parts \$1,092.22

Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
1	10/30/2020 11:16AM				NG	884.34	1,976.56
		oil pan gasket					

X

Customer accepts revision to the invoice and agrees to pay revised amount.

Recommended Repairs and Services:

Airflow meter suspect NLA	1,210.00
Slight play in steering gearbox - steering box is worn (adjusted 3/20)	
Seepage from RF corner of headgasket	
Rear suspension problems	1,273.68

Add On Charges Breakdown

Haz. Materials	1.50
FET	0.30



18 7TH STREET, BERKELEY, CA 94710
(510) 524-6000

TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Date:

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X

Date:

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 97261

1991 BMW M5

License # 2XGB285

Inv Date: 10/29/2020 @ 10:57am

Continued from previous page

		Invoice Summary
		Parts 757.22 Labor 1,147.50 Add On Charges 1.80
		Sub Total 1,906.52 Sales Tax (DEF) 70.04
		Total 1,976.56
Customer acknowledges receipt of merchandise and services.		



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____
Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X _____ Date: _____
I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 96214

1991 BMW M5

License # 2XGB285

Inv Date: 7/13/2020 @ 10:13am

VIN: BK06159

Odom: 244471

Service Writer: Marta Horevajova

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Color: Alpinweiss 2

Status: Complete

Trans: 5SP MANUAL

Mfg. Date: 04/1991

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price		Ext
------------------	----------------------	--------------------	-----	-----	-------	--	-----

Replace spark plugs

Labor Service - Remove & replace spark plugs. Note: oil in spark plug wells	KR	1.25		170.00		212.5
New 12-12-9-061-867 Spark plug BMW S38B36			6.00	19.69		118.1

Car is due for smog, replace oxygen sensor as a preventive measure.

Labor Service - Remove & replace oxygen sensor	KR	0.50		170.00		85.0
New 11-78-1-720-537 Oxygen sensor M30/S38B36			1.00	316.08		316.0

VC seals leaking internally

Labor Service - Remove & install valve cover. Remove and replace all valve cover seals. Clean up residue from leakage. Top up engine oil level.	KR	1.50		170.00		255.0
New 11-12-1-312-172 Gasket VC S38			1.00	63.79		63.7
New 11-12-1-312-173 Gasket VC S14/S38 small			3.00	14.44		43.3

Check tire pressures. Adjust to recommended pressures.

Labor Service - Check & adjust tire pressures.						0.0
Front 33psi						
Rear 38psi						

Note next service due and remaining mileage or SI light status: KR

Revisions of Original Estimate - Original Estimate of Services and Parts \$774.06							
Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
1	7/13/2020 12:18PM				MH	372.55	1,146.61
		VC seals					

X

Customer accepts revision to the invoice and agrees to pay revised amount.

Recommended Repairs and Services:

Airflow meter suspect NLA	1,210.0
Slight play in steering gearbox - steering box is worn (adjusted 3/20)	
LR halfshaft worn	755.2
Rear suspension problems	1,273.6



I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____
Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.
X _____ Date: _____
I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 96214

1991 BMW M5

License # 2XGB285

Inv Date: 7/13/2020 @ 10:13am

Continued from previous page

<div>X Customer acknowledges receipt of merchandise and services.</div>		Invoice Summary	
		Parts	541.33
		Labor	552.50
		Sub Total	1,093.83
		Sales Tax (DEF)	52.78
		Total	1,146.61



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X _____ Date: _____

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 95473

1991 BMW M5

VIN: BK06159

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Trans: 5SP MANUAL

License # 2XGB285

Odom: 243775

Color: Alpinweiss 2

Mfg. Date: 04/1991

Unit #

Inv Date: 4/01/2020 @ 9:39am

Service Writer: Nino Guerra Gilmour

Status: Complete

Driver:

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
------------------	----------------------	--------------------	-----	-----	-------	-----

Smoke seen coming from RF area of engine

Labor Service - Remove & replace leaking oil filler cap, degrease top of engine. Check oil level: good.

Assess engine oil leakage: valve cover gasket leaking, possible additional sources - recommend degrease, dye addition, test drive & recheck. KR

New 11-12-1-468-054 Cap oil filler round

1.00

28.60

0.00

Labor Service - Install SO/PPD vent hose. Refill & bleed cooling system. KR

New CRIMP 14.5 Crimp clamp 14.5

0.30

3.00

170.00

1.44

51.00

4.32

Flex disc cracked

Labor Service - Remove & install exhaust system and forward end of driveshaft.

Remove and replace flex disc. Replace cracked muffler hangers. LK

New 26-11-2-226-527

Flex disc M

1.00

199.83

340.00

New 18-30-1-317-898

Nut 10x1.5mm copper locking

4.00

6.95

199.83

New 18-21-1-177-708

Muffler hanger theta reinforced

2.00

8.20

27.80

16.40

Labor Service - W/flex disc replacement, remove & replace leaking seals @ rear of transmission. Check oil level: good. Replace oil-damaged transmission mounts.

Replace worn components in shifter linkage. LK

New 23-12-8-677-736

Seal shifter shaft

1.00

23.85

1.50

170.00

255.00

New 23-12-1-205-342

Seal transmission output 40mm

1.00

23.73

New 23-21-1-490-120

Lock plate

1.00

3.36

New 23-31-1-228-470

Cover detent

1.00

36.58

New 22-31-6-771-221

Mount transmission

2.00

59.94

119.88

New 25-11-7-503-525

Joint shift linkage

1.00

55.64

New 23-41-1-466-134

Pin linkage joint

1.00

1.88

New 25-11-1-220-439

Shim at base of handle

2.00

2.53

New 25-11-7-519-669

Bushing shift tower front E36/46

1.00

15.39

New 25-11-1-220-600

Ball cup shift lever

1.00

17.17

Check tire pressures. Adjust to recommended pressures.

Labor Service - Check & adjust tire pressures.

Front 38psi

Rear 41psi LK

0.00

Pay attention for noise from suspension (rattle from RF)

Labor Service - Check for wear in front & rear suspension:

* front swaybar links are old but no play found

* rear trailing arm links worn out

* rear subframe mounts cracked/collapsed

* rear swaybar link bushings old/cracked

Note: play & noise from LR outer halfshaft CV joint. Test drive for rattle: heard from RF,

suggest starting w/new swaybar links. NS

0.00

Revisions of Original Estimate - Original Estimate of Services and Parts \$640.56

Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
1	4/01/2020 10:31AM				EI	0.00	640.56
	Flex disc						



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAYPROS.COM • WWW.BAYPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Date: _____

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X

Date: _____

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 95473

1991 BMW M5

License # 2XGB285

Inv Date: 4/01/2020 @ 9:39am

2	4/01/2020 12:27PM	NS	590.00	1,230.56
Trans reseal, trans mounts, shift linkage				

X

Customer accepts revision to the invoice and agrees to pay revised amount.

Recommended Repairs and Services:

• Airflow meter suspect NLA	1,210.00
• Oxygen sensor suspect	401.08
• Slight play in steering gearbox - steering box is worn (adjusted 3/20)	
• LR halfshaft worn	755.21
• Rear suspension problems	1,273.68

<p>X</p> <p>Customer acknowledges receipt of merchandise and services.</p>	<p>PAID VISA</p> <p>4/1/20</p> <p>Thanks!</p>	Invoice Summary								
		<table><tr><td>Parts</td><td>579.49</td></tr><tr><td>Labor</td><td>646.00</td></tr><tr><td>Sub Total</td><td>1,225.49</td></tr><tr><td>Sales Tax (DEF)</td><td>53.60</td></tr><tr><td>Total</td><td>1,279.09</td></tr></table>	Parts	579.49	Labor	646.00	Sub Total	1,225.49	Sales Tax (DEF)	53.60
Parts	579.49									
Labor	646.00									
Sub Total	1,225.49									
Sales Tax (DEF)	53.60									
Total	1,279.09									



1218 7TH STREET, BERKELEY, CA 94710
(510) 524-6000
TEAM@BAVPROS.COM • WWW.BAVPROS.COM

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____

Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

X _____ Date: _____

I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 95436

1991 BMW M5

License # 2XGB285

Inv Date: 3/26/2020 @ 10:28am

Odom: 243711

VIN: BK06159

Color: Alpinweiss 2

Service Writer: Marta Horevajova

Engine: L6 3.6L, 3553cc, DOHC, GAS, FI

Mfg. Date: 04/1991

Status: Complete

Trans: 5SP MANUAL

Driver:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
"Check Engine" light is on/off						
Labor Service - Perform Short Test of all control module fault memories #28/Oxygen sensor: open circuit CK			1.00		80.00	80.00
Labor Service - Set up & leak-check intake system: intake boot is torn. KR			1.00		170.00	170.00
Labor Service - Remove & replace airflow meter boot. Clear DME fault code. Monitor adaptation values: not changing. Recommend driving the car and further diagnosis if CEL KR			0.40		170.00	68.00
New	11-61-1-312-062	Boot airflow meter S38B36		1.00	73.57	73.57
Labor Service - Remove & replace broken bleeder pipe with cooling hose temporary (bleeder pipe is not locally available, special ordered). Refill & bleed cooling system. KR			0.30		170.00	51.00
New	51-48-1-915-964	Rivet plastic		1.00	1.00	1.00
New	CRIMP 14.5	Crimp clamp 14.5		1.00	1.44	1.44
New	17-12-1-712-736	Hose 8mm coolant, meters		0.80	66.20	52.96
Labor Service - Parts only: MH						0.00
New	17-11-2-226-302	Pipe coolant E34 M5		1.00	46.21	46.21
Oil Service						
Labor Service - Oil Service. Includes oil change, topping up fluid levels, undercar inspection, and complete check of lighting and safety systems. KR			2.00		170.00	340.00
New	20W50 VALVOLINE	Oil Valvoline, liters		6.00	6.95	41.70
New	11-42-9-063-138	OX41D oil filter kit M30		1.00	17.47	17.47
New	81-22-1-468-879	CHF 7.1 oil, liter		0.20	18.04	3.61
New	63-14-1-376-979	Bulb socket w/pins		1.00	14.02	14.02
New	07-11-9-978-373	Bulb Osram 5w 2825		1.00	6.56	6.56
RR tire needs repair						
Labor Service - Install patch on inner surface of tire, rebalance tire. LL			1.00		40.00	40.00
Belts need replacement						
Labor Service - Remove and replace all drive belts. KR			1.00		170.00	170.00
New	11-23-1-470-034	13x980 belt		1.00	32.76	32.76
New	32-42-1-469-239	10x825 belt		1.00	20.16	20.16
New	11-72-1-312-977	13x968/970 belt		1.00	32.76	32.76
Play in steering						
Labor Service - Adjust steering gearbox to specifications. Adjust play in steering column. Note: slight play in steering gear box - steering box is worn KR			1.00		170.00	170.00
Loaner car						
Labor Service - Customer in Bavarian Professionals courtesy loaner car BAVPRO8, and agrees to terms of Loaner Car Agreement as shown on reverse. MH						0.00

Revisions of Original Estimate - Original Estimate of Services and Parts \$188.94

Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
------	---------------	---------------	--------	-----------	----------	-----------	-------

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X _____ Date: _____
 Terms: CASH unless other arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.
 X _____ Date: _____
 I have read and agree to the Loaner Car Agreement as set forth on the reverse.

Invoice # 95436

1991 BMW M5

License # 2XGB285

Inv Date: 3/26/2020 @ 10:28am

1	3/26/2020 3:15PM	MH	1,122.23	1,311.17
belts, boot, steering box adjustment				

X _____
 Customer accepts revision to the invoice and agrees to pay revised amount.

Recommended Repairs and Services:

• Airflow meter suspect NLA	1,210.00
• Oxygen sensor suspect	401.08
• Slight play in steering gear box - steering box is worn (adjusted 3/20)	
• Bleeder hose special ordered (part paid)	51.00
• Flex disc cracked	539.83

Add On Charges Breakdown

Haz. Materials	1.50
FET	0.30

<p>X _____ Customer acknowledges receipt of merchandise and services.</p>		Invoice Summary Parts 344.22 Labor 1,089.00 Add On Charges 1.80
		Sub Total 1,435.02 Sales Tax (DEF) 31.84
		Total 1,466.86
		Discard old parts Original Estimate: 188.94

DEPENDABLE TIRE & BRAKE

Phone (415) 456-2311
Fax (415) 456-8740

25 Market Street
San Rafael, CA 94901

BAR# AG126629
EPA# CAL 000 012 611

INVOICE PENDING PAYMENT

INVOICE NUMBER 1078205

February 4, 2020 15:14

.000

ADVISOR: JOHANN

91 BMW M5 2XGB285 CA white

P.O. # 42758

ENGINE 3.5L I6

V.I.N. NUMBER WBSHD9319MBK06159

MILEAGE 242,666

PART NO. DESCRIPTION PRICE

1 31-12-1-13 LOWER CONTROL ARM LEF 348.24
1 31-12-1-13 LOWER CONTROL ARM RIG 348.24

CODE LABOR OPERATION PRICE

008 LOWER CONTROL ARM 351.00

REMOVE AND INSTALL BOTH RIGHT AND LEFT LOWER
CONTROL ARM W/NEW BALL JOINTS.

002 4 WHEEL ALIGNMENT 125.00

FRONT AND REAR WHEEL ALIGNMENT

002 SET TIRE PRESSURE N/C

AS PER CALIFORNIA LAW, SET TIRE PRESSURES TO 39
PSI ALL.

LF _____ PSI, RF _____ PSI

LR _____ PSI, RR _____ PSI

Alignment

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I UNDERSTAND THAT THIS REPAIR FACILITY IS NOT AN INSURER OF SAID VEHICLE AND WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. A STORAGE FEE OF \$10.00 PER DAY WILL BE ADDED TO REPAIR BILL IF VEHICLE IS NOT PICKED UP WITHIN THREE (3) WORKING DAYS OF COMPLETION OF WORK.

AUTHORIZED BY 

ORIGINAL ESTIMATE 1235.16

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE

(SIGNATURE OR INITIALS)

RECOMMENDED SERVICES / FUTURE VEHICLE NEEDS

NOTE:

STEERING GEAR HAS SOME PLAY..

REAR CONTROL ARM LINKS WORN OUT.

VISA	0.00	PARTS	696.48
M/C	0.00	SUBLET	0.00
AM. EXP	0.00	LABOR	476.00
DSCVR	0.00	HAZ. WASTE	0.00
OTHER	0.00		
CHECK	0.00		
CASH	0.00	SUB TOTAL	1172.48
WAPA	0.00		
GW/WTY	0.00	TAX	62.68
O. C/C	0.00		
ATM	0.00	TOTAL	1235.16
AM. PD.	0.00		

Read To

NOTIFIED ☐

PROMISED

when ready NO ☐

SAVE PARTS: ☐ DISCARD PARTS: ☐ C = REFUNDABLE CORE DEPOSIT

R = REBUILT U = USED

CODE N =

Tims Treads1435 E. Francisco Blvd.
San Rafael, CA 94901

(415) 454-7810 FAX: (415) 454-9893

Customer Copy

Invoice #27904Estimated
Time DueFriday, January 17, 2020
10:38:24 AM

Ordered on

Friday, January 17, 2020

Workorder # 29437

MAKE & MODEL		FLEET NO.	PHONE	REP	CSH	PO #	TERMS			
1991 BMW M5			492-0382	Tim Falvey	TF		Cash			
CENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE			
2XGB285	242066	WBSHD9319MBK06159		3.5L L6 FI DOHC	5 SPD MANUAL W/OD					
CATALOG	DESCRIPTION			QTY	PARTS	LABOR	DISC	FET	TOTAL	Code
NT	235/45R17 MICHELIN PILOT SPORT 4S			2	202.03				\$404.06	TF
MB	MOUNT & BALANCE			2		12.00			\$24.00	TF
OF	ENVIRONMENT TIRE DISPOSAL FEE			2	4.00				\$8.00	
MPVS	RUBBER VALVE STEM			2	.00				\$0.00	TF

TR Tire Rotation Reminder : Come back in 6 months

Welcome, We appreciate your business.

PAID BY VISA \$472.43	Parts	\$404.06	Taxable	\$404.06
	Labor	\$24.00	Non-Taxable	\$32.00
	Freight	\$0.00	9.00%	\$36.37
	Other	\$8.00		
	FET	\$0.00		
	Supplies	\$0.00		
TOTAL				\$472.43

Parts and Labor warranties 100 % for 90 days or 4000 mile. Whichever comes first, this warranty limited to the work on this form only. Vehicle must be returned to our shop, any Tire Pros, or American Car Care Centers, at customers expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Because of the extent of the teardown and inspection, the vehicle may not perform as well as before.

No refunds on installed Tires and or Wheels, Special Orders or discontinued items. All returns are subject to 15% handling charge. Any deposits are subject to forfeit if cancelled.

Print Name _____ Signature _____ Date _____

Bill Arnold BMW Repair

Invoice 13328

BAR# ARD 156510

68 Woodland Ave Ste D
San Rafael, California. 94901
Phone: 415-459-2697 Fax: 415-457-2697

INVOICE

Print Date : 04/19/2019

1991 BMW - M5

3.6L, In-Line6 (216CI) VIN(3), 5 speed Standard 280, Not Av

Lic # : 2XGB285 - CA

Odometer In :

Unit # :

Odometer Out :

Vin # : WBSHD9319MBK06159

Hat # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
Wheel Bearing-Rear 33 41 1 468 903	2.00	117.50	235.00	Part sale		0.00
Wheel Hub Assembly-Front 31 21 2 226 640	2.00	208.60	417.20			
Axle Nut-Front 31 21 1 128 336	2.00	14.75	29.50			
Axle Nut-Rear 33 41 1 123 428	2.00	12.77	25.54			

[Technicians : Arnold, Bill]

Org. Estimate \$ 0.00 Revisions \$ 770.89 Current Estimate \$ 770.89

Revision# 1, Previous Estimate Amount: 0.00, Additional Cost: 770.89, Revised Estimate: 770.89, Parts: \$707.24 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$63.65 Authorized by - Hall, Robert, Date - 4/19/2019, Time - 5:35 PM, Initiated By - Shop

Labor:	\$0.00
Parts:	\$707.24
Sublet:	\$0.00
<hr/>	
Sub:	\$707.24
Tax:	\$63.65
Total:	\$770.89
Bal Due:	\$0.00

[Payments - Visa - \$770.89]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original of repair.

SIGNATURE..... Date..... Time.....

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purpose of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.



DINAN

2232 Old Middlefield Way
Mountain View, CA 94043

Phone (650) 962-9401 • Fax (650) 962-0133

BAR # AA099955

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Atra Fmcl 5/31

Invoice # 57718

1991 BMW M5

VIN: WBSHD9319MBK06159

Engine: L6 3.6L, 3553cc, Gas, FI

Trans:

License # 2XGB285

ODO In:154442 Out: 154512

Color: White

Mfg. Date:

Unit #

Inv Date: 10/10/2011 @ 1:07pm

Service Writer: Shaun Withereil

Status: Posted

Driver:

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Disc.	Ext
Customer reports: excessive oil consumption. Upper valve cover gasket recently replaced at Sonnen BMW, please see attached history and e-mail. Inspect and advise on needed repairs.							
	Labor Service - Initial inspection/diagnosis WB		2.00		145.00		290.00
	Labor Service - Inspected engine area, found oil leakage from Intermediate head gasket, front timing cover and oil pan. Remove cylinder heads and oil pan, inspect and sublet to machine shop as/if needed. Customer advised that reassembly in the event of declined repairs is estimated at \$4000 and the maximum time for reassembly would be two weeks from the time of initial teardown.		15.00		145.00		2,175.00
	Removed oil pan and cylinder head as requested. Found multiple cracks in the engine block-sublet cylinder head to machine shop for pressure testing/refinishing. Recommend replacement of engine block and related parts. WB						
	New 11 12 1 315 108 Head gskt set			1.00	0.00		0.00
	Sublet CYLINDER HEAD Sublet for initial inspection, pressure testing and resurfacing of cylinder head.			1.00	600.00		600.00
	Labor Service - Removed engine and sublet with replacement engine block/pistons for repair. Replacement block fitted with serviceable parts from existing engine and new parts as needed. Block cracked in several places-not usable as a core. WB		15.00		145.00		2,175.00
	Sublet ENGINE Engine work			1.00	3500.00		3,500.00
	New 11 12 1 315 108 Head gskt set			1.00	530.38	-29.17	501.21
	New 11 11 1 316 702 Remanufactured engine block			1.00	2602.92		2,602.92
	Core 11 11 1 316 702 Core Deposit Charge			1.00	500.00		500.00
	New 11 81 1 139 019 Engine mount			2.00	73.17		146.34
	New 11 14 1 315 433 Rear cover gasket			1.00	2.55		2.55
	New 11 14 2 245 364 Rear crankshaft seal			1.00	37.78		37.78
	New 11 11 1 743 118 14.5mm dowel			2.00	2.55		5.10
	New 11 12 1 726 238 10.5mm dowel			4.00	2.54		10.16
	New 11 14 1 312 619 Gasket-timing cover			1.00	7.23		7.23
	New 11 14 1 312 618 Gasket-timing cover			1.00	7.05		7.05
	New 11 14 1 312 007 Seal ring			1.00	34.24		34.24
	New 11 13 1 315 154 Oil pan gasket			1.00	23.13		23.13
	New 12 61 1 277 129 Oil level sensor seal			1.00	3.24		3.24
	New 11 41 1 317 100 oil pump			1.00	631.97	-159.17	472.80
	New 11 53 1 312 635 Housing seal			1.00	1.77		1.77
	New 11 53 1 312 287 T-stat/water pump seal			1.00	35.01		35.01
	New 11 76 1 308 686 Exhaust flange gasket			2.00	14.50		29.00
	New PENTOSIN Hydraulic fluid 7.1/11s			2.00	25.20		50.40
	New SVCOL Phosphate free coolant			1.00	24.09		24.09
	New 11 14 1 250 032 Rear seal cover			1.00	65.44		65.44
	New 11 62 1 304 755 6mm copper lock nut			36.00	1.65		59.40
	New 11 12 1 312 096 M6x35 stud			6.00	8.96		53.76
	New 11 42 1 312 175 Oil pipe gasket*			1.00	4.72		4.72
	New 11 42 1 312 210 Oil Filter housing gasket			1.00	4.72		4.72
	New 11 11 1 312 645 Oil dipstick tube			1.00	68.87		68.87
	New 13 64 1 730 767 Injector seal kit			1.00	9.04		9.04
	New 13 31 1 469 781 8mm fuel hose			1.00	37.58		37.58
	New 64 21 1 391 286 Coolant hose			1.00	173.11		173.11
	New 11 53 1 312 817 Coolant hose			1.00	38.98		38.98
	New HOSE PINCH CLAMP Hose Pinch Clamp (Ear Clamp)			10.00	2.49		24.90
	New 32 41 1 093 597 Sealing ring*			4.00	2.07		8.28
	New 07 11 9 963 200 Sealing ring*			4.00	0.96		3.84

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purpose of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.



DINAN

2232 Old Middlefield Way
Mountain View, CA 94043

Phone (650) 962-9401 • Fax (650) 962-0133
BAR # AA099955

λ

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # 57718

1991 BMW M5

License # 2XGB285

Inv Date: 10/10/2011 @ 1:07pm

New	07 11 9 900 052	Washer	2.00	0.88		1.76
New	07 12 9 922 436	M10x1 lock nut	1.00	1.35		1.35
New	07 11 9 905 858	Circlip	1.00	2.45		2.45
New	07 11 9 906 328	O-ring	2.00	0.28		0.56
New	07 11 9 912 680	Hex Bolt	14.00	5.56		77.84
New	07 11 9 932 832	E clip	2.00	0.23		0.46
New	07 11 9 963 355	Sealing ring*	3.00	1.20		3.60
New	11 11 1 308 657	Bearing bolt	1.00	57.04		57.04
New	11 12 1 304 174	O-ring	6.00	6.88		41.28
New	11 12 1 307 135	Cylinder head bolt	14.00	7.91		110.74
New	11 21 1 261 033	Guide-bearing shell red	1.00	315.56		315.56
New	11 21 1 261 034	Guide-bearing shell blue	1.00	37.25		37.25
New	11 21 1 261 041	Bearing shell, red	6.00	26.31		157.86
New	11 21 1 261 042	Bearing shell, blue	6.00	26.31		157.86
New	11 23 1 312 980	Bolt	1.00	28.34		28.34
New	11 24 1 307 140	Bolt	12.00	9.96		119.52
New	11 24 1 310 515	Rod bearing half	12.00	28.19		338.28
New	11 31 1 305 070	M cam gear lock tab	2.00	9.81		19.62
New	11 31 1 307 399	Bearing bolt	1.00	27.35		27.35
New	11 31 1 307 408	O ring	1.00	2.46		2.46
New	11 31 1 307 782	Tensioner	1.00	191.85		191.85
New	11 31 1 308 309	Update tensioner diaphragm	1.00	129.41		129.41
New	11 31 1 308 451	Plug	1.00	9.22		9.22
New	11 31 1 308 495	Slide rail	1.00	26.21	-6.82	19.39
New	11 31 1 308 550	Chain guide	1.00	160.60		160.60
New	11 31 1 309 945	Chain tensioner	1.00	324.12	-18.47	305.65
New	11 31 1 317 335	Tensioner	1.00	297.79	-16.97	280.82
New	11 31 1 403 081	Timing chain	1.00	159.32		159.32
New	11 41 1 317 997	Chain	1.00	38.94		38.94
New	11 31 1 706 503	7-bush	1.00	8.82		8.82
New	11 31 1 744 351	Bearing bolt	2.00	9.32		18.64
New	11 41 1 705 055	Tensioner Oil Pump	1.00	12.44		12.44
New	11 51 1 315 563	Water pump	1.00	446.82	-35.68	411.14
New	11 51 1 265 654	Water pump gasket	1.00	4.16		4.16
New	12 61 1 312 343	Oil level sensor	1.00	226.06	-12.45	213.61
New	11 31 1 304 255	Gear	1.00	39.84		39.84
New	11 31 1 304 257	O ring	1.00	6.14		6.14
New	11 31 1 304 258	Bearing	1.00	16.47		16.47
New	12 12 9 061 882	Spark plug x5dc	6.00	17.09		102.54
New	11 31 1 308 450	Hollow plug fitting	1.00	16.29		16.29
New	82 14 1 467 704	Antifreeze	1.00	28.56		28.56
New	11 61 1 312 670	Vent hose	1.00	24.10		24.10
New	18 21 1 105 638	Exhaust hanger	2.00	8.10		16.20
New	07 11 9 919 228	Coolant drain plug	1.00	3.50		3.50
New	17 11 1 468 467	Radiator drain plug	1.00	5.70		5.70
New	11 42 9 063 138	Oil filter insert*	1.00	21.69		21.69
New	C15W40	Engine Oil	6.00	4.20		25.20
Labor Service - Sublet cylinder head for repair/overhaul. Cylinder head repaired with replacement camshaft, valves, valve springs and seals WB				145.00		0.00
Sublet	ENGINE	Cylinder head labor	1.00	750.00		750.00
New	11 34 9 059 072	Valve stem seals	2.00	44.60		89.20
New	11 34 1 315 912	Set valve spring	24.00	28.97		695.28
New	11 34 1 310 528	Exhaust valve 2nd oversiz	12.00	187.62		2,251.44
New	11 34 1 309 343	Intake valve	12.00	77.70		932.40
New	11 31 1 311 907	Camshaft	1.00	637.20		637.20
Labor Service - Update A/C system to R 134 operation, replace receiver/dryer as precaution per customer request WB			4.00	145.00		580.00
New	82 31 9 067 396	R134 retrofit kit	1.00	81.68		81.68
New	64 53 8 390 469	Receiver/dryer	1.00	243.14		243.14
New	R134	Freon- R134	40.00	2.80		112.00

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purpose of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.



DINAN

2232 Old Middlefield Way
Mountain View, CA 94043

Phone (650) 962-9401 • Fax (650) 962-0133

BAR # AA099955

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # 57718

1991 BMW M5

License # 2XGB285

Inv Date: 10/10/2011 @ 1:07pm

Customer reports: intermittent belt type noise. Please check belts during vehicle inspection and report

Labor Service - No belt noise noted after engine reassembly. No repairs performed WB	145.00	0.00
--	--------	------

Customer requests us to: replace the transmission, clutch and associated parts as needed

Labor Service - Replaced transmission, transmission mounts, clutch assembly and clutch slave cylinder, bleed hydraulic system when completed WB	2.00	145.00	290.00
New 23 00 1 221 632 Transmission/manual	1.00	5685.59	-935.59 4,750.00
Core 23 00 1 221 632 Core Received	1.00	0.00	0.00
New 21 21 2 226 428 Clutch kit	1.00	593.32	-20.27 573.05
New 11 22 1 312 491X Flywheel exchange	1.00	80.00	80.00
New 21 52 2 226 484 Slave cylinder	1.00	115.81	115.81
New 83 22 0 309 031 Mtf/lt/2 synthetic oil*	2.00	36.61	73.22
New 07 11 9 919 979 fillister head screw	6.00	0.60	3.60
New 21 51 1 202 659 Clutch lever pivot	1.00	1.70	1.70
New 21 51 1 204 327 Fork lever spring	1.00	2.22	2.22
New 11 21 1 709 681 Clutch pilot bearing	1.00	15.64	15.64
New 11 22 0 616 143 Flywheel bolt-late	8.00	3.87	30.96
New 22 31 1 094 916 Transmission mount	2.00	28.80	57.60
New 25 11 1 434 194 Felt coupler plug	1.00	3.20	3.20

Customer requests us to: perform complimentary vehicle inspection.

Customer requests us to: Check tire pressure

Front: 38 psi Rear: 40 psi

Customer requests us to: sublet for dent/ding repair on right rear door.

Labor Service - Sublet for dent removal as requested WB	145.00	0.00
Sublet DENT REMOVAL Dent Removal	1.00	600.00 600.00

Customer requests us to: provide estimate to refinish wheels and install center caps.

Labor Service - Provided estimate. Sublet to refinish wheels as requested WB	145.00	0.00
Sublet WHEEL REPAIR Send wheels out for repair.	1.00	600.00 600.00

During the vehicle inspection the technician noted: a leaking power steering hose

Labor Service - Replaced leaking hose WB	1.00	145.00	145.00
New 32 41 2 226 277 Power steering hose	1.00	89.08	89.08
New HOSE PINCH CLAMP Hose Pinch Clamp (Ear Clamp)	1.00	2.49	2.49
New 32 41 1 093 598 Sealing ring	2.00	2.03	4.06

During vehicle testing the technician noted: the coolant temperature was high at idle.

Labor Service - Traced to weak fan clutch and replaced. WB	0.50	145.00	72.50
New 11 52 7 831 619 Fan clutch	1.00	284.11	284.11

Customer requests us to: sublet exhaust headers for removal of rust and refinishing

Labor Service - WB	145.00	0.00
Sublet BEAD BLAST Sublet for rust removal by bead blast and refinishing of exhaust headers	1.00	200.00 200.00

Customer requests us to: check battery condition

Labor Service - Checked battery-ok at 870 CCA, 12.46 volts 508	145.00	0.00
--	--------	------

Customer requests us to: apply Dinan badge to decklid.

Labor Service - Applied badge as requested WB	145.00	0.00
---	--------	------

Revisions of Original Estimate - Original Estimate of Services and Parts \$290.00

Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
------	---------------	---------------	--------	-----------	----------	-----------	-------

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purpose of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.



DINAN

2232 Old Middlefield Way
Mountain View, CA 94043

Phone (650) 962-9401 • Fax (650) 962-0133
BAR # AA099955

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # 57718

1991 BMW M5

License # 2XGB285

Inv Date: 10/10/2011 @ 1:07pm

1	10/17/2011 2:23PM		SW	3,710.00	4,000.00
Customer authorized removal of cylinder heads and oil pan for inspection. Customer authorized sublet of cylinder heads for inspection/repair as needed.					
2	1/30/2012 4:45PM		SW	18,000.00	22,000.00
Customer authorized preliminary rebuild estimate					
3	2/23/2012 11:29AM		504	4,100.00	26,100.00
Additional engine parts and \$600 for dent repair					
4	3/13/2012 11:30AM		504	6,000.00	32,100.00
Additional cylinder head work					
5	4/20/2012 11:31AM		504	1,250.00	33,350.00
Exhaust manifold resurface and A/C repairs					
6	5/11/2012 11:32AM		504	250.00	33,600.00
Power steering hose					
7	5/22/2012 11:33AM		504	375.00	33,975.00
Fan clutch					

X

Customer accepts revision to the invoice and agrees to pay revised amount.

Warranty

24 month/unlimited mileage warranty on all parts and labor. Service warranty until next service due. Due to the nature of racing Dinan offers no warranty on its racing parts and labor.

Posted 5/31/12 2:22PM

Check (109)	\$23,811.96
Credit Used	3,500.00
Credit Used	5,685.59

Invoice Summary

Parts	19,348.74
Labor	5,727.50
Labor Discount	-572.75
Sublet	6,250.00
Fluids	98.42
Cores	500.00

Tax Breakdown:

Customer acknowledges receipt of merchandise and services.

Sub Total	31,351.91
Sales Tax (DEF)	1,645.64

4343 STEVENS CREEK
SANTA CLARA, CA 95051
(408) 249-9070
anyauto.com

SPECIAL ORDER NUMBER	DATE ORDERED	DATE CLOSED	CUSTOMER PO NUMBER	DATE PRINTED	# OF LINES
35480	11NOV11		6246	17JAN12	1

PAGE 1

It was necessary for us to SPECIAL order the above item(s) for you.
Parts will be returned to Manufacturer 10 days after final notice.
*** Thank you for giving us the opportunity to serve you ***

CUSTOMER COPY

11/16/2011
10:50:56

PICKING TICKET

NET548
PAGE 1

INVOICE#
112468

CUST#
6014

BILL TO
DINAN ENGINEERING
2232 OLD MIDDLEFIELD WAY
MOUNTAIN VIEW, CA 94043
650-962-9401

SHIP TO

SOLD BY
CHARLIE

CUST PO#
6262

QORD QSHF PART# / DESCRIPTION

BIN JB PF

1

0 23-00-1-221-632 RMFD-FIVE SP 0

SOP

RECEIVED
EC 05 2011

NOV 16 2011