## Woodinville Sports Cars Inc.

**European Auto Service** Jaguar Land Rover BMW Audi Mini M.B. VW

WOODINVILLE SPORTS CARS, INC. 12602 NE 178TH STREET WOODINVILLE, WA 98072

(425)402-7878

09/10/08

WORK ORDER

MAKE: JAGUAR

MILES:

MODEL: XKE

YEAR: 67

LICENSE: 27905

BY: RKA

SHOP LABOR DESCRIPTION	-MECH	AMOUNT	
TAG# 4696			
7-26-08			**************************************
DIO OIL LEAKS, SEE PREVIOUS RO	GCA		*
REPLACE HEATER FAN SWITCH	GCA	133.00	* POLISHING WAXING *
RAISE IDLE TO 900RPM	GCA		* CARPET SHAMPOO
STEERING WHEEL OFF TO LEFT	GCA		*ALL MAKES AND MODE:
SEE RICK ABOUT 2 PARTS THAT WE HAVE IN PARTS DEPARTMENT TO INSTALL	GCA		* CLASSICS MODERN *SUV'S VAN'S TRUCKS ***********
LOF	GCA		
REMOVED EXHAUST MANIFOLDS TO HAVE RECOATED. REFITT MANIFOLD	GCC	580.00	
3,000 MILE SERVICE. INCLUDES:	GCA	142.50	
-DRAIN ENGINE SUMP & REFILL	GCC		
-REPLACE OIL FILTER	GCC		
-CHECK GEARBOX OIL LEVEL & TOP UP IF NECESSARY			
-CHECK REAR AXLE OIL LEVEL & TOP UP IF NECESSARY	GCC		
-LUBRICATE STEERING HOUSING	GCC		
-LUBRICATE STEERING TIE-ROD BALL JOINTS	GCC		
-LUBRICATE WHEEL SWIVELS	GCC		
-TOP UP CARB DAMPNER OIL	GCC		
-LUBRICATE REAR HALF SHAFT U-JOINTS			
-CHECK CLUTCH FREE TRAVEL	GCC		

Any warranties on parts and accessories sold hereby are made by the manufacturer. The above shop disclaims all warranties, including implied warranties of merchantability or fitness for the particular purpose, and does not authorize any person to assume for it any liability. No Warranties for competion or competion type use. No Warranties on used parts or labor to install them. No Warranties on over the counter part sales.

No Returns on over the counter parts sales.

No Warranties on Classic Cars or reproduction parts.

No Warranties on parts or labor for XJ6 S1,S2,S3, or V12 XJS T+M only

[ccccccccccccccccccccccccccccccccccccc

# Woodinville Sports Cars Inc.

European Auto Service Jaguar Land Rover BMW Audi Mini M.B. VW

WOODINVILLE SPORTS CARS, INC. 12602 NE 178TH STREET WOODINVILLE, WA 98072 (425) 402 - 7878

00/10/00

MAKE: JAGUAR MODEL: XKE YEAR: 67

09/10/08 WORK ORD	ER MILES:	0 LICENSE: 27905	BY: RKA
SHOP LABOR DESCRIPTION	-MECHAMO	UNT	
COOLING FAN(S) OPERATION -CHECK TIRES AND TIRE PRESSURE -CHECK BRAKE & CLUTCH FLUID RESERVOIRS	GCC		
-CHECK BATTERY ELECTROLYTE LEVEL AND CONNECTIONS			
-CHECK ALL LIGHTS, WIPERS & HORNS REPORT			
USE ONLY CASTROL 20/50 GTX *****	GCC		
REPLACED HEATER FAN SWITCH	GCC		
CENTERED STEERING WHEEL. FOUND LOOSE PINCH BOLT ON STEERING RACK	GCC		
FOUND LOOSE PINCH BOLTS ON UPPER U-JOINT			
RETIGHTENED THE WHOLE COLOUM. REMOVED STEERING WHEEL AND CHANGED 1 SPLINE.			
WE HAD TO RESET TURN SIGNAL CANCELING SYSTEN TO WORK WITH THE WHEEL CENTERED.			
INSTALED MISSING TAIL PIPE SAFETY BRACKET	GCC		
REGLUED FELT ON ROCK SHIELD	GCC		

Any warranties on parts and accessories sold hereby are made by the manufacturer. The above shop disclaims all warranties, including implied warranties of merchantability or fitness for the particular purpose, and does not authorize any person to assume for it any liability. No Warranties for competion or competion type use. No Warranties on used parts or labor to install them. No Returns on over the counter parts sales. No Warranties on over the counter part sales.

No Warranties on Classic Cars or reproduction parts.

No Warranties on parts or labor for XJ6 S1,S2,S3, or V12 XJS T+M only

## Woodinville Sports Cars Inc.

**European Auto Service** Jaguar Land Rover BMW Audi Mini M.B. VW

WOODINVILLE SPORTS CARS, INC. 12602 NE 178TH STREET WOODINVILLE, WA 98072 (425)402-7878

09/10/08

WORK ORDER

MAKE: JAGUAR

MODEL: XKE

YEAR: 67

MILES:

LICENSE: 27905

BY: RKA

--SHOP LABOR DESCRIPTION-------MECH----AMOUNT--INSTALLED HEATER BOX GASKET ON AIR DUCT.

--OTHER CHARGES DESCRIPTION------CODE----AMOUNT--COAT EXHAUST MANIFOLDS

0 225.00

-----PARTS----QTY PART NUMBER NAME OF PART PRICE 1 C2369 EX MAN STUD TO CAT CONV (4) 4.03 DRAIN PLUG WSHR -87 XJ6+E HAZARDOUS WASTE FEE SHOP SUPPLIES 1 C2296/1 1.15 1 HWF 3.00 1 SS1 2.50 OIL 20/50 HIGH PHOS. OIL FILTER 4.2 XKE PAPER 10 20/50 64.90 1 GFE101 16.32

Any warranties on parts and accessories sold hereby are made by the manufacturer. The above shop disclaims all warranties, including implied warranties of merchantability or fitness for the particular purpose, and does not authorize any person to assume for it any liability. No Warranties for competion or competion type use. No Warranties on used parts or labor to install them. No Returns on over the counter parts sales. No Warranties on over the counter part sales.

No Warranties on Classic Cars or reproduction parts.

No Warranties on parts or labor for XJ6 S1,S2,S3, or V12 XJS T+M only

Thank You for letting us take care of your car! Rick Korn, Owner Ken, Lead diagnostician, Geoff Classic British BMW Bill, Travis AUDI/VW, Tino Detailing Jay Mercedes Benz

LABOR	TOTAL	855.50
OTHER	CHARGES	225.00
PARTS	TOTAL	91.90
SALES	TAX	104.35
PD IN	ADVANCE	.00
TOTAL	DUE	1276.75



1390 West Highway 26 Blackfoot, Idaho 83221

Internet: www.vintagejag.com

Voice: (208) 684-4767 Fax: (208) 684-3386

Email: sales@vintagejag.com

BILL TO	Allisa
NAME:	SHIP TO
ADDRESS:	-
ADDITEGO.	<u>-</u>
PHONE:	·
	FAX OR EMAIL:
CUSTOMER'S ORDER   SALESMAN   TERMS   SHIP	·····
plr. JOHN WALT P.P. VISA UP	S-GRND BLFT. 4DEC 08
1 31960 BLOWER FAN S	WITCH, RECOND, EXCH, 5300
CORE (REFUN	IDABLE - RETURN OLD SWITCH) 600
*	
1	
	Subtotal 5900
Thank you for your business.	Sales tax
	Shipping and Handling Fees 931
	TOTAL 68 31



Store Front

Account

Search

Product List

**Basket Contents** 

Checkout

Invoice

Order #1122

Date: 06/20/2010 15:53:24 EDT

Thank you for your order. Please keep this invoice for your records.

Ship To:

Bill To:

Name:

Email Address:

Phone Number:

Fax Number:

Company:

Address:

Code Product

Konif Koni Shock Absorbers 51/52 E-Type Front (Pair)

Konir Koni Shock Absorbers for S1/S2 E-Type Rear (Pair)

Quantity

Price/Ea.

Total

1

\$350.00 \$350.00

\$350.00

\$700.00

Shipping: UPS Ground:

\$50.67

Sales Tax:

\$0.00

Total: \$1,100.67

"Isn't that better?"



Home

FAQ

What's New

E-Mail

Contact



#### Woodinville Sports Cars, Inc. 12602 N.E. 178th Street Woodinville, WA 98072 (425)402-7878

www.Woodinvillesportscars.com

BMW Audi Mercedes-Benz VW Mini Cooper Jaguar XKE

Work Order	Order ID: 2810 10/1/2010	Service Writer: RK		Page 1
		License: 27905 Make: 1967 Jaguar X VIN: 1E14286 Mileage: In- 0 Out- 14		B
1wsc insp	WSC - Piece of mind inspection.			n/c
	inspected cam covers leaking recommend cool cat fan Also recommend elec ign.			
Tech - GC		1wsc insp Total		\$0.00
Oil Service Clas	Oil Service Classic cars. includes, use customer supplied engine oil		<u> </u>	\$187.50
	check trans and diff fluids greasing all fittings, wheel bearings and wheel splines check brake fluid and top up check carb dampers and top up set tire pressures and inspect tread depth and age check operation of lights			
Parts: 1	6158 OIL FILTER HSG	SEALING RING	\$3.50	
Tech - GC	GFE101 OIL FILTER 4.2	XKE Oil Service Clas Total	\$19.93	\$23.43 \$210.93
Brakes-Flush	Flush brake and clutch system cleaned out the bottom of the bottles.			\$165.00
Parts: 4	LMA502 Castrol GTLMA	Brake Fluid	\$19.00	\$19.00
Tech - GC		Brakes-Flush Total		\$184.00
Coolant change	replace coolant pressure test and check cooling system including fans e report: Replaced coolant Press test - ok Tightened all hose clamps several were seeping under p Topped up coolant Elec fan works, temp comes up 95 at lights, down when	oressure.	35	\$180.00
Parts: 2	af888 Antifreeze		\$43.98	\$43.98
Tech - GC		Coolant change Total		\$223.98
Susp-Shock Front	Replace front shock absorbers set front shocks on #3 — customer supplied shocks			\$165.00

	Order ID: 2810	10/1/2010	Service Writer: RK	Page
Tech - GC			Susp-Shock Front Total	\$165.0
			ousperious rotal	Ψ100.0
	Susp-Shock Rear Report: Replace rear shocks Set at 2 (out of 4).			\$440.0
Tech - GC			Susp-Shock Rear Total	\$440.0
Sparkplug	Sparkplug Replace sparkplugs check report: Replaced spark plugs - had Test drive Temp rises to over 95 at a l	d champions in it	8 8	\$52.5
Dorto	Also recommend elec ign.	, and a large		000.00
Parts: 6 Tech - GC	BP5ES	sparkplug		\$26.88 \$26.8
recn - GC			Sparkplug Total	\$79.3
Misc	Misc when the wheels are off for	service have brian clean a	and seal the spokes	\$0.0
Tech - GC			Misc Total	\$0.0
Elec-Light	lamp repair interior map light inop, plea report:	se fix.		\$77.0
	Dio map light inop switch Map light works with door, ju			
	Found map light wired to wa properly.	asher switch; swapped wil	res, map light and washer now work	
Parts: 7	Found map light wired to wa	asher switch; swapped wing es and some were wrong	amperage	\$15.75   \$15.7
Parts: 7 Tech - GC	Found map light wired to wan properly.  Replaced all fuses - old fuse	asher switch; swapped wil	amperage	\$15.75 \$15.7 \$92.7
	Found map light wired to wan properly.  Replaced all fuses - old fuse	asher switch; swapped wing es and some were wrong	amperage  Elec-Light Total	\$92.7
	Found map light wired to wa properly. Replaced all fuses - old fuse fuse  Engine-Cam Cover reseal cam covers with conreport: Replace cam cover gaskets  Gaskets were siliconed down Check tappet clearance - infound Lots of deep scrapes	es and some were wrong fuse  netic gaskets s with cometic gaskets. wn - it took extra time to restake 3-4, ex 5-6 = ok	Elec-Light Total  Metal  11	\$92.7 \$704.0 300
Tech - GC Engine-Cam	Found map light wired to wa properly. Replaced all fuses - old fuse fuse  Engine-Cam Cover reseal cam covers with conreport: Replace cam cover gaskets  Gaskets were siliconed dow Check tappet clearance - in found Lots of deep scrapes they will seal or they will leal Install missing circlip on tac we had to repair several bothere are a bunch of cracks previously.	es and some were wrong fuse  netic gaskets s with cometic gaskets. wn - it took extra time to rentake 3-4, ex 5-6 = ok on head and cam cover sk, monitor for now. It holes on the back of the son the inside of these car	Elec-Light Total  Mata /  11944	\$92.7 \$704.0 \$700 \$700 ether
Tech - GC Engine-Cam Cover	Found map light wired to wa properly. Replaced all fuses - old fuse fuse  Engine-Cam Cover reseal cam covers with conreport: Replace cam cover gaskets  Gaskets were siliconed dow Check tappet clearance - infound Lots of deep scrapes they will seal or they will lead Install missing circlip on tack we had to repair several both there are a bunch of cracks previously, we polished covers while the	es and some were wrong fuse  metic gaskets s with cometic gaskets. wn - it took extra time to rentake 3-4, ex 5-6 = ok on head and cam cover sk, monitor for now. th drive. It holes on the back of the conthe inside of these cares	Elec-Light Total  April  1 2 9 4 4 6  move old gaskets  sealing surfaces, see what happens, exceptions are the tach drive being covers that have been puttied up or	\$92.7 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0
Tech - GC Engine-Cam	Found map light wired to wa properly. Replaced all fuses - old fuse fuse  Engine-Cam Cover reseal cam covers with conreport: Replace cam cover gaskets  Gaskets were siliconed dow Check tappet clearance - in found Lots of deep scrapes they will seal or they will leal Install missing circlip on tac we had to repair several bothere are a bunch of cracks previously.	es and some were wrong fuse  netic gaskets s with cometic gaskets.  wn - it took extra time to rentake 3-4, ex 5-6 = ok s on head and cam cover sk, monitor for now. It holes on the back of the s on the inside of these car aley were off  V/C gasket, cover sk Valve Cover scan	Elec-Light Total  April  Agrae  move old gaskets  realing surfaces, see what happens, exceptions that have been puttied up or cometic jag pair  Nasher, Copper	\$92.7 \$704.0 \$700 \$700 ether
Tech - GC  Engine-Cam Cover  Parts: 1 24	Found map light wired to wa properly. Replaced all fuses - old fuse fuse  Engine-Cam Cover reseal cam covers with conreport: Replace cam cover gaskets  Gaskets were siliconed dov Check tappet clearance - in found Lots of deep scrapes they will seal or they will leal Install missing circlip on tack we had to repair several both there are a bunch of cracks previously.  we polished covers while the C4545-060 FW104E C19044	es and some were wrong fuse  netic gaskets s with cometic gaskets.  wn - it took extra time to rentake 3-4, ex 5-6 = ok s on head and cam cover sk, monitor for now. It holes on the back of the s on the inside of these car aley were off  V/C gasket, cover sk Valve Cover scan	Elec-Light Total  Maya /  "14 gara  move old gaskets  realing surfaces, see what happens, electric surfaces, see what happens, electric surfaces where the tach drive being covers that have been puttied up or covers that have been puttied up or cometic jag pair  Nasher, Copper 64.2  SEAL 69-74 4.2	\$92.7 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0 \$704.0

Work Order	Order ID: 28	10 10/1/2010	Service Writer: RK	Pa	age 3
			23 (MI)		
pertronix	install electronic ig			\$39	96.00
	Replaced elec ign	and coil			
	report:		7.10		
	Replaced coil		yas		
	Installed elec ign				
	Disassembled/clea				
	Tighten mech adv				
		list very loose - probably wasn't	getting any vac adv		
	Set timing		± 12		
	Re gap spark plug				
		very lean at cruise - recommer	nd new needles that run richer at crui	se	
	Right				
	Cruise 58 HC 1.3%	00-	5% idle		
	Idle 173 HC 5.8%	. CO_	10 10.0		
	Left	. 2	5-2 100		
	Cruise 84 HC29	000	. 7 . 7		
	Idle 290 HC 6.2	% CO —			
	Has UM needles -				
	Slight hunting feelir	ng when light throttle 30-40mph			
	201				
	recommend trying				
Parts:	1 LU166	ELECTRO	ONIC IGNITION UPDATE 22D	\$155.89	
1.0	1 dlb105b	Lucas Ign	ition Coil	\$65.62 \$22	21.51
Tech - GC			pertronix Total	\$61	7.51
THANK	YOU FOR LETTING	G US TAKE CARE OF YO	UR CAR! Job T	Fotals \$2,83	88.66
		Korn - Owner	Supply - E		39.00
Cooff Cl					73.38
Geom - Cla	ssic British Jay - M	ercedes Benz - BMW Joi	1 K Service		3.30

Advisor

William - Audi -VW Steve - Lexus

Partial Payments

Total Due

\$0.00

\$3,151.04





(269) 353-5250 · FAX (269) 375-1026 TOLL FREE 800-253-4080 www.engelimports.com

(269) 353-5273 · FAX (269) 375-1026 TOLL FREE 800-851-9438 www.terrysjag.com

MAILING ADDRESS: 5850 STADIUM DRIVE

SHIPPING ADDRESS: 5775 VENTURE PARK DRIVE KALAMAZOO, MI 49009









NO REFUND AFTER 45 DAYS, INVOICE OR COPY MUST ACCOMPANY ALL RETURNS.
20% RESTOCKING FEE MAY BE CHARGED ON ALL RETURNS.
ELECTRICAL AND SPECIAL ORDER PARTS ARE NOT RETURNABLE.
ALL ACCEPTED RETURNS MUST BE IN ORIGINAL PACKAGING AND IN CLEAN RESALABLE CO

	The state of the s					
DATE ENTERED 02 APR 12	YOUR ORDER NO.	DATE SHIPPED 02 APR 12	INVOICE DATE 02 APR 12	INVOICE NUMBER	1139475	2
S O L D			C			
T 0						

SHIP V UPSP	PD	EMP. 3.5	SLSM. 5	TERMS CREDIT	CARD	F.O.B. PO	INT AMAZOO, M
QTY.	PART NO	).		DESCRIPTION	LIST	NET	AMOUNT
2 1	C23006 C23007		NUT SHIFT KNOB SHIFT	LEVER LEVER	12.00 25.00	10.35 21.56	20.70 21.56
			10	PARTS SUBLE			42.26
			USTOMER'S SIGNATURE	FREIGH SALES	4T	= 1	11.23
		0	OSTOWER S SIGNATURE				

DISCLAIMERS OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

#### CoolCat Express Corp

#### Invoice

124 Mianus River Road Bedford NY 10506 (914) 234-2083 (914) 205-1096F http://www.CoolCatCorp.com

Date	Invoice #
5/22/2013	3678

Bill To	22120	Ship To	
	05/		

Quantity Item Code	5/22/2013 Descriptio		20	
	Descriptio			
1 0 10 10		n	Price Ea	ach Amount
1 Ottalike Fan Thermost 1 UPS UPS Shipping	for Ser 1 E-Type witch Adapter, 16mm		Price Ea	134.95 134.95 39.95 39.95 20.95 20.95 0.00% 0



# Classic Showcase, Inc. SERVICE ESTIMATE / WORK ORDER

Bureau of Auto Repair License #ARD00184160

DATE:

02/07/18

**CUSTOMER NAME:** 

ADDRESS:

DAY TIME TELEPHONE:

**EMAIL ADDRESS:** 

YEAR/ MAKE / MODEL:

VIN:

LICENSE:

ODOMETER READING:

COLOR:

DATE VEHICLE REC'D / REC'D BY:

1967 Jaguar XKE OTS

1E14286

27905 - Washington State

1,958

Opalescent Silver Grey / Black 1/23/18 Brian Boyce / Tom Krefetz

#### Estimate for Work Recommended

Part Description	Parts Price	Labor Hours	Labor Cost (\$135 hr.)
R & R radiator, and header tank		3.00	\$405.00
Header Tank	\$270.00		Included above
Alloy radiator and aux. fan	\$1,250.00		
Optional - paint radiator black (Parts & Labor)		2.00	\$270.00
Radiator cap	\$11.00		
Flush cooling system		1.00	\$135.00
Parts- thermostat, gasket	\$20.00		
Cooling System- anti freeze	\$24.00		
Waste Fee	\$25.00		
Labor to set up, and with tune up		3.00	\$405.00
Parts for tune up (spark plug, rotor, condenser)	\$100.00		
Marchido - Aftermarket, Shew Still and painted (Parts & Labor)	<b>803.000.90</b>		
Service fuel system		10.00	\$1,350.00
Remove gas in tank & inspect. Hot tank and epoxy seal if needed			Included above
Change fuel filter, and service carburetors. Install new carb kits, fuel filter, O-rings, and misc. parts	\$800.00		Included above
Check status of consumable parts and report		TBD	

All labor is billed at \$150/ hour. VIP Rate is \$135/ hour for Jaguar Club Members. Price quoted does not include unknowns. Any unknowns that are discovered, that may affect cost, will be documented and reported to the vehicle owner for approval before proceeding with work. For all warranty work performed, it is the customer's responsibility to transport the vehicle to the Classic Showcase facility at the customer's expense.



# Classic Showcase, Inc. SERVICE ESTIMATE / WORK ORDER

Bureau of Auto Repair License #ARD00184160

Part Description	Parts Price	Labor Hours	Labor Cost (\$135 hr.)
Back rear right tail light housing, remove, disassemble, and rechrome	\$350.00	2.00	\$270.00
New gaskets front and rear tail light assemblies	\$100.00		
Labor to replace the front gaskets, and back left rubber gasket		1.50	\$202.50
Rubber plugs for bottom of the car	\$30.00	0.50	\$67.50
Clusticarpet Hodicidats—	\$150.00		\$500.00
Inspect hydraulic system and report		1.50	\$202.50
Replace battery w/Tar top battery, and install battery tender	\$350.00	1.00	\$135.00
Replace or replate upper top windshield chrome	\$375.00	1.50	\$202.50
Straighten tailpipes and align best possible		1.00	\$135.00
Replace, lubricate, and set up trunk hinge springs (10 per side) stainless steel	\$200.00	1.50	\$202.50
Check shocks and report back		TBD	
Adjust and aim headlights		1.50	\$202.50
Wet Sand and Buff the Car		24.00	\$3,240.00
Estimated Total - Parts & Labor	\$22,055.00	55.00	\$7,925.00
Tires- Pick which brand you like best below	Choice #1	Choice #2	
Dunlop 185/VR15 Black wall - 4 tires quoted	\$1,700.00		(\$425 each)
Vicedestein 185/15 Black wall Arires quoted		\$1,100.00	(\$275 each)
Tubes	\$100.00	\$100.00	\$25 each
Mounting and Balancing	\$100.00	\$100.00	\$25 each
Shipping of Tires	\$60.00	\$60.00	\$15 each
Total for Tires Only	\$1,960.00	\$1,360.00	
Estimated Grand Total (Parts/Labor/Tires)	\$31,940.00	\$31,340.00	

XSAR/Initials Duncop 185 VR 15 SP Sport Aguaget
Blacks Wall

All labor is billed at \$150/ hour. VIP Rate is \$135/ hour for Jaguar Club Members. Price quoted does not include unknowns. Any unknowns that are discovered, that may affect cost, will be documented and reported to the vehicle owner for approval before proceeding with work. For all warranty work performed, it is the customer's responsibility to transport the vehicle to the Classic Showcase facility at the customer's expense.

2/2/19

### **Estimate/Work Order**

Date	Work Order#
7/25/2018	J67-286,2

Bill To		
	WINCOMO COMPANSA AND A STATE OF THE STATE OF	

		Terms	P.O. No.	BAR#	
	:	Due on receipt	J67-286	ARD00184160	
Quantity	Descript	ion	Rate	Total	
3	1967 Jaguar XKE OTS, VIN: 1E1 Customer's car in for service  Services provided and approved y dated 2/7/18 and subsequent emai ~ Jaguar Club Member VIP billidiscount)  Labor: R & R radiator and header Part: Header tank Parts: Alloy radiator and auxiliary Labor: Paint radiator black (parts Part: Radiator cap Parts: Thermostat, gasket Parts: Cooling system anti-freeze Waste disposal, EPA #CAL00028 Labor: Set up, tune up Parts: Parts for tune up6 spark p Labor: Service fuel system: Remo Parts: Change fuel filter and servic ~ Install new carb kits, fuel filter parts.	ia signed Service Estimate Is and phone conversations ing rate on labor (10%  tank  fan included)  9186  hugs, rotor, condenser we gas in tank and inspect. se carburetors. r, o-rings and miscellaneous	135.00 270.00 1,250.00 135.00 11.00 20.00 24.00 25.00 135.00 100.00 135.00	270.00T 1,250.00T 270.00 11.00T 20.00T 24.00T 25.00 405.00 100.00T 1,350.00 800.00T	
Thank you for choosing			Total		

Signature

#### **Estimate/Work Order**

Date	Work Order #	
7/25/2018	J67-286.2	

Bill To		
***************************************		

		Terms	P.O. No.	BAR#
		Due on receipt	J67-286	ARD00184160
Quantity	Description	on	Rate	Total
2	- Tree tree to the tree tree tree tree tree tree tree		400	0.00 800.00
	Parts: New gaskets front and rear ta		100	T00.001
1.5	Labor: Replaced the front gaskets a	and back left rubber ga	sket 135	.00 202,50
0.5	Labor: Install rubber plugs for botto	om of the car	135	.00 67.50
	Parts: Rubber plugs		1	.00 30,00T
1.5	Labor: Inspect hydraulic system and	d report		.00 202.50
1.5	Labor: Replate upper top windshiel	d chrome	135	
1	Part: Upper top windshield chrome		375	
1	Labor: Straighten tailpipes and alig	n best possible	135	
1.5	Labor: Replace, lubricate and set up stainless steel	p trunk hinge springs	135	
01	Parts: Trunk hinge springs		10	.00 100.00T
	~ Shipping on various parts		100	
	Labor: Check shocks and report back	ck (OK, no charge)		.00 0.00
1.5	Labor: Adjust and aim headlights	, ,	135	
4	Parts: Tires - Dunlop 185VR15 SP	Sport Aquajet black v	vall 425	
4	Parts: Tubes		25	T00.00T
4	Labor: Mounting and balancing		25	.00 100.00
4	Shipping of tires		15	T00.00
	Subtotal		19	9,880.00
1	Labor: Installation of new chrome p windshield	piece on top of the	135.	
1	Part: Chrome piece		550.	.00 550,00T
	Parts: Hardware and clips to install			.00 30.00T
2	Labor: Repaint the cast iron section	of the brake booster	135.	1
Thank you for choosing	g Classic Showcase!	***************************************	Total	

Signature

### **Estimate/Work Order**

Date	Work Order #
7/25/2018	J67-286,2

Bill To	 - DANICOONLAND	***************************************

r side of the eng id installed ie and re-install better ition and EBC pads	R gine	77-286  Rate  135.00  350.00  200.00  135.00  600.00  135.00  20.00  135.00  577.50	350.0 200.0 202.5 21.0 202.5 600.0 810.0 40.0 135.0 675.0 577.5	
r side of the eng nd installed ne and re-install better ition	tine	135.00 350.00 200.00 135.00 7.00 135.00 600.00 135.00 20.00 135.00 577.50	0 1,620.0 0 350.0 0 200.0 0 202.5 0 202.5 0 600.0 0 810.0 0 135.0 0 675.0 0 577.5	
r side of the eng nd installed ne and re-install better ition	tine	350.00 200.00 135.00 7.00 135.00 600.00 135.00 135.00 135.00 577.50	350.0 200.0 202.5 21.0 202.5 600.0 810.0 40.0 135.0 675.0 577.5	
r side of the eng nd installed ne and re-install better ition	tine	350.00 200.00 135.00 7.00 135.00 600.00 135.00 135.00 135.00 577.50	350.0 200.0 202.5 21.0 202.5 600.0 810.0 40.0 135.0 675.0 577.5	
nd installed ne and re-install better ition		200.00 135.00 7.00 135.00 600.00 135.00 135.00 135.00 577.50	200.0 202.5 21.0 202.5 21.0 202.5 0 600.0 810.0 40.0 135.0 675.0	
nd installed ne and re-install better ition		200.00 135.00 7.00 135.00 600.00 135.00 135.00 135.00 577.50	200.0 202.5 21.0 202.5 21.0 202.5 0 600.0 810.0 40.0 135.0 675.0	
nd installed ne and re-install better ition		135.00 7.00 135.00 600.00 135.00 135.00 135.00 577.50	202.5 21.0 202.5 0 202.5 0 600.0 810.0 0 435.0 0 675.0 0 577.5	
nd installed ne and re-install better ition		7.00 135.00 600.00 135.00 20.00 135.00 135.00 577.50	21.0 202.5 0 600.0 810.0 0 43.0 0 675.0 0 577.5	
ie and re-install better ition	then	135.00 600.00 135.00 20.00 135.00 135.00 577.50	202.5 600.0 810.0 40.0 135.0 675.0 577.5	
ie and re-install better ition	then	20.00 135.00 135.00 135.00 577.50	600.0 810.0 0 40.0 135.0 675.0 577.5	
better ition	then	20.00 135.00 135.00 577.50	810.0 40.0 135.0 675.0 577.5	
ition	W 100 100 100 100 100 100 100 100 100 10	135.00 135.00 577.50	40.0 135.0 675.0 577.5	
ition	7//1554	135.00 135.00 577.50	135.0 675.0 577.5	
ition		135.00 577.50	135.0 675.0 577.5	
		135.00 577.50	675.0 577.5	
and EBC pads	14	577.50	577.5	
and EBC pads	- 1		- 1 1 1 1	
	1	135.00	742.5	
	1	1,050.00	1,050.0	
		92.94		
hly		135.00	742.5	
s and rotors		135.00	202.5	
		10.00	10.0	
		135.00	270.0	
d case, and		135,00	236,2	
Part: Battery with rubber hard case				
		14.20	14.20	
	To	ıtal		
	et d case, and	d case, and	135.00 d case, and 135.00 320.00	

Signature

#### **Estimate/Work Order**

Date	Work Order#
7/25/2018	J67-286.2

Bill To	11.000	Or Constitution of the Con
1 1-200000000000000000000000000000000000		 

		Terms	P.O. No.	BAR#
		Due on receipt	J67-286	ARD00184160
Quantity	Descriptio	n	Rate	Total
	Shipping & Handling	50,	50.00	
43	Labor: R & R seats, console, bonne	135.0		
4	Labor: Installation of Dynamat		135.0	- 10000101
	Part: Dynamat		135.0	
	Labor: Upgrade to the gear reduction	on starter on the 4 speed	375.0	
1	Part: Gear reduction starter		700.0	0,010
0.5	Labor: Fit Top Boot to car		135.0	
35	Parts: oil, oil filter, lube, transmission	on fluid	73.5	
12	Part: Gasoline, gallons		4.	
	Waste disposal, EPA #CAL000289	186	35.0	
2	Labor: Fabricate a spark plug wire I	narness	135.0	
1	Part: Wire conduit, ignition wires		31.	
1	Part: Wire sleeve		10.3	
6	Parts: 90 Degree Spark plug boot		1.9	
	Labor: Work done on hydraulic syst	em	135.0	- 1
0.5	Labor: Running and operation test of	of the car	135,0	
0.25	Labor: Inspection of what else need	s to be performed	135.0	
	Labor: Installation of driver's side c for labor)	lip-on mirror (no charge	0.0	
	Part: Clip-on mirror		100.0	100.00
	Labor: Drained oil in the engine in chose that goes from the block to the		135.0	
	Part: Oil hose		40.0	0 40.00
	Labor: Welded up clamps where the pipes to repair exhaust leak	mufflers go into the	135.0	135.00
ank you for choosing	Classic Showcase!		Total	
			าบเสา	

Signature

4 3. . . . . . A

#### Estimate/Work Order

Date	Work Order#	The Control of the Co
7/25/2018	J67-286.2	The second secon

Bill To		

		Terms	P.O. No.	BAR#
		Due on receipt	J67-286	ARD00184160
Quantity	Description	on	Rate	Total
2.5	Labor: Adjusted and tightened fran vibration rattle. Part: Vinyl snapped boot cover to sconvertible top Part: Black towels to go in back wi Labor: Tighten bolts, installed copp Parts: Copper washers  Customer deposit paid: 2/12/18, ch Customer deposit paid: 4/24/18, ch Out of State Sale	stow in trunk for the ndow with top is down per sealing washers eck #1395	-20,00 -10,00	
Thank you for choosing	Classic Showcase!		Total	\$92,19

Signature

AMT	PART NO./ DESC.	COST EA	SALE AMT			1					
			-			BF	RITS	POR	T		
			-						7		
			-	]		The state of the s	OF SE				
	tank mtg grommet	3.39	27.12		421				e, WA 98199		
	fuel tank	511.14	511.14					206) 283-357			
1	filler neck hose	23.65	23.65		Payme	ent address 59	50 34th Av	e SW Seattle,	WA 98126-292	4	
1	pick up gasket	3.45	3.45								
1	sender gasket	2.95		Name							
1	sump seal	2.10		Address							
	UPS	60.68		City, State							
2	motor mount	75.99	151.98	Year	1967 Model	E Type	Make	Jaguar	Mileage	2196	N ess
	bracket		-		REP	AIR ORDER -	LABOR IN	STRUCTIONS		0.023.399	Labor Amt
2	battery hold down	7.49	14.98								
	bolt & nut		-		Various repair iten	ns per custor	ner tick lis	t.		1900	
	UPS	17.99	17.99								
2	motor mount	12.99	25.98		Re attached:	23.5 hour	S				\$3,290.00
1	shop supplies &	14.00	14.00							•	
	materials		-								
1	fresh petrol (clean)	30.00	30.00		2.1						
1	GFE101 filter	10.60	10.60	Remarks:						1	
3	Qts. 85w90 oil	12.50	37.50		Oil pressure gaug	e reads low a	nd is slow	responsive.		Labor	\$3,290.00
1	brake master	46.99	46.99								
	vacuum valve		-							Parts	\$1,019.06
	UPS	7.95	7.95					Name of the second	haz waste		
1	petrol	30.00	30.00						disposal	Misc.	\$8.50
			-								
			-							Sublet	
			-							Repairs	
			_								
			_	I hereby authorize	the above work to be dor	e along with neces	ssary materials	. You and your er	nployees may	Sub Total	\$4,317.56
			-		hicle for purpose of testing			. An express med	hanic's lien is	Sales Tax	\$436.07
		Parts		acknowledged on above vehicle to secure the amount of repairs thereto.							
		Total	\$ 1.019.06	SIGNED: X						Less down	
			.,,.	OIGHED. A							
				NOT RESPONSIBLE F	OR LOSS OR DAMAGE TO					Total Due	\$4,753.63
				OR ARTICLES LEFT IN	CARS IN CASE OF FIRE, E BEYOND OUR CONTROL	Terms: Str	ictly cash u	nless arrangen	ent made	70.07.000	Ţ 1,7 GG.GG

			WEEKLY WORK ORDER						
		***************************************	WEERLT WORK ORDER						
Name:			Date:						
Car:	Jaguar E Ty	/pe							
Note:	22222								
Date	Time	Hours	LABOR PERFORMED						
25-Jun	1400-1500	1	Provide access to inspect fuel system in boot. Interior of tank						
			surface rusted and it appears liner had been installed. Drain off						
			fuel from tank & dispose.						
	1530-1900	3.5	Disassemble tank and remove front mounting bracket. Remove						
			boot lid latch for clearance, unbolt and remove old tank. Fit new						
22			tank and assemble.						
26-Jun	1145-1500	3.25	Collect fresh fuel and add to tank. Pressure up system and						
			inspect for leaks. Reassemble boot compartment. Inspect choke						
			operation and replace knob retaining screw. Run engine from cold.						
			Note "popping" as described by customer. Rattle on RH side due						
			to collapsed motor mount brackets and mounts causing front						
			carb float bowl to strike frame rail. Battery retainers missing.						
			Check charging system for erratic operation of gauge.						
			Remove/test/refit alternator. Swap 4TR regulator for checks.						
	Total Hours	7.75							

			WEEKLY WORK ORDER
Name:			Date:
Car:	Jaguar E Ty	/ре	
Note:			
Date	Time	Hours	LABOR PERFORMED
26-Jun	1700-1900	2	Remove center console to access rear of gauge cluster. Jumper
			amp gauge to eliminate faulty gauge causing erratic readings.
			Remove/test/refit battery. Check all grounds. Refit console.
28-Jun	1330-1500	1.5	R & R motor mounts and brackets.
	1515-1745	2.5	Drain engine oil and R & R filter. Drain gearbox oil. Add fresh oil
			to engine and gearbox. Inspect air cleaner filter element.
1-Jul	1430-1445	0.25	Drain rear axle oil.
	1600-1800	2	Add oil to rear axle. Run up engine oil pressure and top up oil.
			Check engine/exhaust for "popping" sound. Fabricate battery
			hold down bracket and tie down with "J" hooks. Remove brake
			master vacuum unit and inspect (cracks).
2-Jul	1430-1700	2.5	Install new brake master vacuum unit and plumb in. Run engine
			for vacuum leak checks. Remove air plenum assy and adjust
			carb air/fuel mixtures.
3-Jul	1800-1830	0.5	Road test and add fresh fuel to check sender reading.
	Total Hours	11.25	

			WEEKLY WORK ORDER
Name:			Date:
Car:	Jaguar E Ty	уре	
Note:			
Date	Time	Hours	LABOR PERFORMED
5-Jul	1130-1400	2.5	Check over and test complete charging system for erratic amp
	14		gauge fluctuation. Nothing amiss found.
8-Jul	1300-1500	2	Continue charging system checks for erratic amp gauge readings.
			Fit known good alternatorsame issues noted.
			Jumper field terminals to bypass chassis wiringsame issues.
	=	V	
	Total Hours	4.5	

AMT	PART NO./ DESC.	COST EA	SALE AMT			
-	CoolCat fan kit	154.95	154.95	BRITSPORT		
	UPS	17.86	17.86	The state of the s		
1	Bell stainless	653.46	653.46	OF SEATTLE		
	exhaust system		-	4214 - 24th Ave W. (lower level) Seattle, WA 98199		
2	front pipe flange	12.70	25.40	Mark Jones (206) 283-3578		
1	exhaust fitting kit	33.70	33.70	Payment address 5950 34th Ave SW Seattle, WA 98126-2924		
	UPS	55.05	55.05			
8	downpipe brass nut		15.92	Name		
1	shop supplies &	24.50	24.50	Address		
	materials			City, State		
14	Qts. Coolant	2.20	30.80	Year 1967 Model E Type Make Jaguar Mileage	2196	
1	elec sundries	12.00	12.00	REPAIR ORDER - LABOR INSTRUCTIONS		Labor Amt
1	oil pressure	89.99	89.99			
	sending unit		<u> </u>	Various repair items per customer tick list.		
	UPS	11.65	11.65			
			-	Re attached: 22.25 hours		\$2,781.25
			-			
11000			-		1500 BUSSIAN PROPERTY	
			_			
			-	Remarks:		
			-		.abor	\$2,781.25
$\vdash$			-	pressure test radiator inc. enviro fees.		
$\vdash$			-		Parts	\$1,125.28
$\vdash$				haz waste		
			-	disposal M	flisc.	\$6.50
			-			
			-		Sublet	
				R	Repairs	\$156.95
$\vdash$			_	Characte above vehicle for nurness of testing increation or delivery at my risk. An express mechanists lies is	ub Total	\$4,069.98
$\vdash$				acknowledged on above vehicle to secure the amount of repairs thereto.	ales Tax	\$411.07
$\vdash$		Parts	A 405.00	SIGNED: X		La participa de la constitución de
		Total	\$ 1,125.28	Le Le	ess down	
$\vdash$				NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS		
				OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY CAUSE BEYOND OUR CONTROL  Terms: Strictly cash unless arrangement made	otal Due	\$4,481.05
				Torms. Ourody Cash unless arrangement made		

	WEEKLY WORK ORDER							
Name:			Date:					
Car:	Jaguar E T	уре						
Note:	: I							
Date	Time	Hours	LABOR PERFORMED					
25-Jul	1215-1500	2.75	Remove old exhaust system and mountings. Remove adhesive					
			stickers from new system and begin fitment.					
	1545-1900	3.25	Complete the fitting of new exhaust system, trimming pipe ends					
			where nec'y. Adjust geometry and clamp down.					
26-Jul	1230-1430	2	Detach and remove radiator for flow/pressure test. Remove elec					
			fan complete from radiator.					
29-Jul	1030-1115	0.75	Del'vr radiator to Greenwood for cleaning/testing.					
	1530-1730	2	Unpack boot compartment. Remove and test fuel sending reading					
			against gauge. Full float arm shows just past 3/4 on gauge.					
			Refit sender and reassemble boot compartment. Test heater fan					
			blower motorOK on both speeds. Test wiper systemOK.					
30-Jul	1030-1115	0.75	Retrieve tested radiator from Greenwood.					
	1630-1900	2.5	Fit CoolCat fan kit, radiator and cooling hoses.					
31-Jul	1215-1300	0.75	Fit and adjust fan shroud and fill cooling system					
	1615-1930	3.25	Wire in CoolCat. Remove road wheels & tires and begin cleaning.					
V2	Total Hours	18						

			WEEKLY WORK ORDER					
Name:			Date:					
Car:	Jaguar E T	уре						
Note:								
Date	Time	Hours	LABOR PERFORMED					
1-Aug	1215-1500	2.75	Complete cleaning/degreasing wheels & tires. Refit wheels and					
			top up fluids.					
	1530-1600	0.5	Road test for heat cycle thru new exhaust system.					
5-Aug	1530-1630	1	Change out oil pressure sending unit with known good used unit.					
		- 4	Observed normal reading. Fit OE style replacement unit and test.					
			OK with normal pressure reading.					
			8					
100 Miles		10						
88	Total Hours	4.25						

AMT	PART NO./ DESC.	COST EA	SALE AMT					
	brake light switch	12.95	12.95		BRITSP	ORT		
1	DOT4 fluid	12.30	12.30			Name of the last o		
			-		OF SEATT			
_1	shop supplies &	28.50	28.50	42	14 - 24th Ave W. (lower level			
	materials		-		Mark Jones (206)			
			-	Paym	nent address 5950 34th Ave SW	Seattle, WA 98126-2924		
			-	Name				- 2
			-	Address				24/200000000000000000000000000000000000
				City, State				
				Year Model	Make	Mileage	2261	
			-	REI	PAIR ORDER - LABOR INSTRU	CTIONS		Labor Amt
			-	Test and diagnose brake ligh	t failure. Replace both brittle k	orake lines in and out o	f brake	
			-	lamp switch union. R & R bra	ke light switch. Flush and blee	ed braking system.		
325.00			-	Lubricate chassis points and	check leaks. Tighten exhaust	manifold flange nuts.		
			-				***************************************	
			-			4.5 hours		\$562.5
			-	Remarks:				
							Labor	\$562.5
			-					
-			-				Parts	\$53.7
		1992	-					
			-				Misc.	
			-					
			-				Sublet	
			-				Repairs	
			-					
			-	I hereby authorize the above work to be do	one along with necessary materials. You a	nd your employees may	Sub Total	\$616.2
			-		ng, inspection or delivery at my risk. An ex	and the second s	Sales Tax	\$62.24
		Parts		acknowledged on above vehicle to secure	the amount of repairs thereto.			•
		Total	\$ 53.75	SIGNED: X			Less down	
$\neg$								
				NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS			Total Due	\$678.49
_				OR ARTICLES LEFT IN CARS IN CASE OF FIRE,	Terms: Strictly cash unless a		. Juli Duc	φ070.43

TMA	PART NO./ DESC.	COSTEA	SALE AMT	D :10						
1	brake master cyl	249.95	249.9	BritSport						
1	brake servo	399.95		of Seattle						
				4214 - 24th Ave W. (lower level)	Seattle, WA 98	3199				
	DOT4 fluid	12.3	12.	Mark Jones (206) 283-3578						
2	hose clamp	2.75	5.	Payment address 5950 34th Ave SV	V Seattle, WA 981	26-2924				
1	oil pressure gauge	209.95	209.9	5						
	"Air Core" upgrade		(	0 Name			Date	6/1	2/20	
	w/sending unit			0 Address	-	To Anna Anna Anna Anna Anna Anna Anna Ann	Phone	70750		
1	volt meter	129.95	129.9	REPAIR ORDER - LOUIN ING INC					01/07005	
77615				year 1967 Model	E Type	Iviake	Jaguar	ivilleage	Z539	)
1	electrical sundries	26.5	26.	5						Labor A
			(							
				Various repair ite	ms per custome	r tick list.				
			(	0					Welling Astronomy	
			(	Re attached:	23.25 hou	ırs				\$3,02
			(	0						
			(	ol						
			(							
			(	Remarks:						
				0					Labor	\$3,02
			* · · · · · · · · · · · · · · · · · · ·	0					Labor	ψ0,02
				0						64.00
				0					Parts	\$1,09
				I hereby authorize the above work to be done	along with necessary r	naterials. You and	your employees	may operate		
-				above vehicle for purpose of testing, inspectio above vehicle to secure the amount of repairs	n or delivery at my risk				Misc.	
				above vehicle to secure the amount of repairs	thereto.					
				SIGNED: X	GNED:				Sublet	
1	shop supplies &	12.5	12.	NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS					Repairs	
	materials		K	OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY CAUSE BEYOND OUR CONTROL	Terms: Strictly cas	sh unless arran	gement made			
1	shipping charges	48.25	48.2	5					Sub Total	\$4,11
			0						Sales Tax	\$41
		Parts		1					Galos Tax	-
7		Total	1,094.85	3					1	
		.otui	1,004.00	-					Less down	
				-						
_				_					Total Due	\$4,53

-			
6.	hoo	et	1
.7	8 I G-	3,443,6	- 8
_		-	

Sheet2

Sheet3

# BritSport of Seattle

WEEKI	Y WORK	ORDER

Name: Date:

Jaguar E Type Car:

Note:

Date	Time	Hours	LABOR PERFORMED
3-Jun	1300-1500	2	Digest customer tick list. Road test for driveability issues.
			Place car on lift and inspect underchassis for leaks & defects.
	1545-1900	3.25	Inspect braking system to ascertain potential causes of sticking
			pedal. Remove master cylinder and disassemble/clean parts.
			Clean out debris & sediment. Lightly hone cylinder & reassemble
			Refit brake master.
4-Jun	1200-1400	2	Flush and bleed braking system. Remove vacuum valve from
			master and replace with known good unit. Test system and note
			linkage/diaphragm knocking inside servo causing pedal hang.
			Fit missing fastener on bonnet air plenum.
	1700-1900	2	Evacuate fluid from brake master, disconnect and remove same
			Disconnect brake servo & remove battery for access.
5-Jun	1130-1500	3.5	Remove front framework undershield to access servo & remove
			Clean and refit mounting studs on pedal housing for master mtg
			Clean brake fluid from adjacent area and begin master/servo re
	Total Hours	12.75	

# BritSport of Seattle

WEEKLY V	NORK	ORE	)ER
----------	------	-----	-----

Name: Date:

Car: Jaguar E Type

Note:

Date	Time	Hours	LABOR PERFORMED
5-Jun	1545-1900	3.25	Complete installation of new brake master and servo assy's.
			Flush and bleed braking system Refit undershields. Start engine
			for vacuum and test braking systemOK.
8-Jun	1130-1230	1	Run engine to temp and check over braking system. Adjust
			carb idles to customer specs.
12-Jun	1200-1500	3	Replace oil pressure gauge and sending unit. Repair wire ends
			at connectors and fit new amp gauge & test. Road test.
			Remove ignition switch.
	1545-1900	3.25	Disassemble & repair ignition switch. Replace corroded Lucar
			connectors at ignition switch and refit switch. Replace corroded
			Lucar connectors at 4TR voltage regulator. Reassemble center
			dash and test charging system and for proper gauge readingsC
			Note: checked for normal operation of Cool Cat fan circuit. OK.
			Fan starts at 75C and shuts down around 65C. Normal specs.
	Total Hours	10.5	

AMT	PART NO./ DESC.	COSTEA	SALE AMT		
	interior mirror	69.99	69.99	BRITSPORT	
	UPS	16.99	16.99		
			-	OF SEATTLE	
				4214 - 24th Ave W. (lower level) Seattle, WA 98199	
			-	Mark Jones (206) 283-3578	
			-	Payment address 5950 34th Ave SW Seattle, WA 98126-2924	
			-		
			-	Name	
			-	Address	
			-	City, State	
			-	Year Model E Type Make Jaguar Mileage	
				REPAIR ORDER - LABOR INSTRUCTIONS	Labor Amt
			-		
			-	Modify clamp nut and replace interior mirror.	
			-		
			-	Tighten front shock mounting bolts.	\$60.00
			-		
			-		
			-		
			-	Remarks:	
			_	Labor	\$60.00
			-		
			-	Parts	\$86.98
			-		
			-	Misc.	
			-		
			-	Sublet	
			-	Repairs	
			**	I hereby authorize the above work to be done along with necessary materials. You and your employees may	\$146.98
			14	operate above vehicle for purpose of testing, inspection or delivery at my risk. An express mechanic's lien is	
		Parts		acknowledged on above vehicle to secure the amount of repairs thereto.	
		Total	\$ 86.98	SIGNED: X	
$\neg$					
$\top$				NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS TOTAL DUE	\$161.82
-				OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY CAUSE BEYOND OUR CONTROL THEFT OR ANY CAUSE BEYOND OUR CONTROL	7.002