

DOUBLE 02 SALVAGE, INC.

A CALIFORNIA CORPORATION

2034 American Avenue

HAYWARD, CALIFORNIA 94545

(510) 782-2002 FAX (510) 782-2667

CUSTOMER'S ORDER NO.

PHONE

DATE

8-7-97

NAME

ADDRESS

SOLD BY

CASH

C.O.D.

CHARGE

ON ACCT.

MDSE. RET'D.

PAID OUT

QTY.

DESCRIPTION

PRICE

AMOUNT

1

FT OVER RIDER PNL

>

250

✓

1

REAL OVER RIDER PNL

>

1

MISC + REFLECTORS

10

✓

CORE

UPS

SUB

260.00

NO REFUNDS ON PARTS OR DEPOSITS

TAX

21.45

RECEIVED BY

TOTAL

281.45

51128

All claims and returned goods MUST be accompanied by this bill.

THANK YOU

DOUBLE 02 SALVAGE, INC.

A CALIFORNIA CORPORATION

2034 American Avenue

HAYWARD, CALIFORNIA 94545

(510) 782-2002 FAX (510) 782-2667

CUSTOMER'S ORDER NO. _____ PHONE _____ DATE 8 | 8 | 97

NAME _____

ADDRESS _____

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RET'D.	PAID OUT
---------	------	--------	--------	----------	--------------	----------

QTY.	DESCRIPTION	PRICE	AMOUNT
------	-------------	-------	--------

★ 1	FR. - GLASS 2002		205.70 ✓
-----	------------------	--	----------

★ 1	PRZ - GLASS 2002 (HARD)		202.50 170.85 ✓
-----	----------------------------	--	-------------------------------

1	DEFROST SWITCH		10 ✓
---	----------------	--	------

CORE

UPS

SUB 386.05

NO REFUNDS ON PARTS OR DEPOSITS TAX 31.85

RECEIVED BY _____ TOTAL 417.90

51156

All claims and returned goods MUST be accompanied by this bill.

THANK YOU

DOUBLE O2 SALVAGE, INC.

A CALIFORNIA CORPORATION

2034 American Avenue

HAYWARD, CALIFORNIA 94545

(510) 782-2002 FAX (510) 782-2667

CUSTOMER'S ORDER NO. [REDACTED] PHONE [REDACTED] DATE 3-2-97

NAME [REDACTED]

ADDRESS [REDACTED] 1131

SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MOSE. RET'D.	PAID OUT
			<u>VUA</u>			

QTY.	DESCRIPTION	PRICE	AMOUNT
<u>1</u>	<u>MOLDING (CITRONG)</u> <u>51 71 1 919 818</u>		<u>25 50</u> ✓
<u>1</u>	<u>LENS</u>		<u>13 -</u>
<u>1</u>	<u>PURBON MOLDING</u> <u>51 36 7 441 110</u>		<u>17 -</u> ✓
<u>1</u>	<u>PASS FT. TURN SIG.</u>		<u>52</u>
<u>1</u>	<u>SPECIAL ORDL</u>		
<u>1</u>	<u>FT. WINDSHIELD MOLDING</u>		<u>56 -</u>
<u>1</u>	<u>ROAR " "</u>		<u>49 -</u>
<u>1</u>	<u>TRUNK SEAL</u>		<u>38 -</u>
<u>1</u>	<u>LT DOOR SEAL</u>	<u>90</u>	<u>90 -</u> ✓
<u>1</u>	<u>RT " "</u>		<u>90 -</u>
<u>1</u>	<u>LT QUARTER MOLDING</u>	<u>35</u>	<u>35 -</u> ✓
<u>1</u>	<u>RT " "</u>	<u>35</u>	<u>35 -</u> ✓
<u>2</u>	<u>OUTER FELT (TOP OF DOOR)</u>	<u>9 CORE</u>	<u>18</u> <u>APU</u>
<u>2</u>	<u>INNER FELT " "</u>	<u>11 LBS</u>	<u>22 -</u> ✓
		SUB	<u>520 50</u>
	NO REFUNDS ON PARTS OR DEPOSITS	TAX	<u>42 94</u>
RECEIVED BY		TOTAL	<u>563 44</u>

51044

All claims and returned goods MUST be accompanied by this bill.

THANK YOU

DOUBLE O2 SALVAGE, INC.

A CALIFORNIA CORPORATION

2034 American Avenue

HAYWARD, CALIFORNIA 94545

(510) 782-2002 FAX (510) 782-2667

CL

DATE

6/13/97

NA

AD

ANSA EXHAUST SYSTEM 2002 T11 '73

SOLD BY CASH C.O.D. CHARGE ON ACCT. MDSE. RET'D PAID OUT

X

QTY. DESCRIPTION PRICE AMOUNT

QTY.	DESCRIPTION	PRICE	AMOUNT
1	D. PIPE	}	254.04
1	C. RESONATOR		
1	RR. MUFF		
1	GASICET SET		
	w/NUTS/BOLTS		
1	CHROME TIP		

CORE

UPS

SUB

254.04

TAX

20.96

NO REFUNDS ON PARTS OR DEPOSITS

RECEIVED BY

TOTAL

275 -

49900

All claims and returned goods MUST be accompanied by this bill.

THANK YOU

INVOICE NO.
0258

SHIPPED TO

CUSTOM METAL POLISHERS
920 WASHINGTON ST.
SAN CARLOS, CA 94070
(415) 508-9118

BOB

STREET & NO.

CITY

STATE

ZIP

F.O.B.

DATE

9 Aluminum Pieces to be polished
* BMW 2002 TU Engine parts

320.⁰⁰

To be completed 7/21/97

Pick-up on 7/23
PAID \$320.⁰⁰

INVOICE

REDIFORM

7L 706

PARTS HEAVEN
FORMERLY PORSHEAVEN

PARTS HEAVEN, INC.

23694 BERNHARDT STREET
HAYWARD, CA 94545

(510) 782-0354
(FAX) (510) 782-0358
(800) 767-7250

SOLD TO

ACCT NO. RRL5961 No. 51289

TERMS	CASH	CHARGE	C.O.D.	R.O.A.	CREDIT	PHONE NUMBER	ORDER BY	DEPARTMENT	P.O. NUMBER	DATE ORDERED
Card						415-593-5961				05/28/97
WORK ORDER NO.	MAIL COPY	DISMANTLER	READY	CORE EXCHANGE	R/O NUMBER	TRUCK LINE	SALES PERSON	SHIPPING DATE		
63682							AL	05/28/97		

ITEM / DESCRIPTION	STOCK NO.	LOC.	AMOUNT
TAN LEATHER ELECTRIC SEATS PORSCHE 928 89 1-PAIR LEFT AND RIGHT (Extra Sale) #0001	RECARO BRAND #		1500.00 T

Doc # :96619

DISCLAIMER
ALL SALES SUBJECT TO FOLLOWING TERMS
NO CASH REFUNDS
NO GUARANTEE ON LABOR
NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL	1500.00
SALES TAX	123.75
SHIPPING CHARGES	0.00
TOTAL	1,623.75

ALL CLAIMS & RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 1,623.75
Amount due: 0.00



MOTORSPORT-1

465 Convention Way-Suite 5
Redwood City, CA 94063
Phone (415) 367-6666
Fax (415) 367-1403
www.msl.com

NO REFUNDS ON SPECIAL ORDER PARTS.
STORE CREDIT ISSUED ON ALL RETURNS.

BUSINESS HOURS MONDAY-FRIDAY 9-5
SATURDAYS BY APPOINTMENT ONLY

PAGE 1 OF 1

CASH CUSTOMER

INVOICE # 9931
DATE 4/14/97
TIME 3:29PM
WRITTEN BY 1

QTY	CODE	PART NUMBER	PART DESCRIPTION	LIST PRICE	SALE PRICE	EXT PRICE
1.00	N	MOM0155	BMW HUB	54.00	54.00	54.00

+ Purchase @ High Performance House

- 1 Steering wheel Momo Wood (Astron Prestige)
- 1 Momo Gear Shift knob Wood

\$ 329.95

69.95

399.90

Tax 32.99

total \$432.89

58.46

\$491.35

METHOD OF PAYMENT

C. CARDS	58.46	PARTS	54.00	SUB TL	54.00
		LABOR	0.00	TAX	4.46
		MISC.	0.00	TOTAL	158.46
		SUPPLY	0.00		

ORIGINAL



ESTIMATE / INVOICE # 2310

O&R Auto Upholstery
408 La Paloma Rd., El Sobrante, CA 94803
510-758-1358
orauto@yahoo.com

DATE: 03/30/21

NAME	
ADDRESS	
PHONE	

PURCHASE ORDER/CLAIM #	MAKE	MODEL	LIC PLATE #

MATERIAL/PARTS	DESCRIPTION OF WORK	LINE TOTAL
PC407 Sand Beige carpet.	Complete Interior	
Dash and top door Mahogany		
Headliner		
swm 406 Headliner		
Leather for seat match front.		
Material/Parts TOTAL:		

PAYMENT NOTES: <input type="checkbox"/> CHECK # _____ \$ <u>3,500 Deposit</u> <input type="checkbox"/> CASH \$ _____ <input type="checkbox"/> CR \$ _____	LABOR MATERIAL SALES TAX TOTAL	\$ <u>11,000.00</u>
--	--	---------------------

I authorize the above repairs, including sublet work, along with necessary materials. An express mechanic's lien to O&R Auto Upholstery is hereby acknowledged on the above mentioned vehicle to secure the amount of repairs thereto. O&R is not responsible for damage caused by theft, fire or acts of nature. I authorize O&R to operate my vehicle for the purposes of the work to be done, inspection, delivery and/or storage at my own risk. Deposit is non-refundable once the material has been purchased and/or work has started. Customer will be called upon completion of work. A storage fee of \$50 per day will apply to all vehicles left over three (3) days after completion.

Customer signature: Gabriel Dasben Date: 03/30/21

Thank you for your business!

Date: 10/ 5/2019 10:00 AM
 Estimate ID: 6777
 Estimate Version: 0
 Preliminary
 Profile ID: HERTZ

101 AUTO BODY

5327 JACUZZI STREET, STE 3A, RICHMOND, CA 94804
 (510) 524-4857
 Fax: (510) 524-9713

Damage Assessed By : HENRY SENG
 Classification: None

Deductible:

Insured:
 Telephone:

Mitchell Service: 911144

Description: 1973 BMW 2002
 Body Style: 2D Sed
 License: KDH617 AK
 Mileage: 114,925
 OEM/ALT: A

Drive Train:

Search Code: B893460

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Special/Manual Entry</u>							
1	900500	BDY *	REPAIR	COMPLETE PAINT JOB: BODY WORK AND REFINI	Sublet	15,000.00 *	0.0*
2				INCLUDING DOOR JAMS & TRUNK			
3	900500	BDY *	REMOVE/REPLACE	PAINT MATERIAL	Sublet	INC*	0.0*
4	900500	BDY *	REMOVE/REPLACE	OWNER IS TO PROVIDE PARTS AND PAY FOR ANY New		0.00 *	0.0*
5				ADDITIONAL SUBLETING OF CHOMATING PARTS			

* - Judgment Item

Remarks

WARRANTY: DUE TO THE CONDITION (RUST) AND AGE OF THE VEHICLE, 101 AUTO BODY WARRANTS LABOR FOR 36 MONTHS.

1973 BMW 2002tii

- **BMW rubber conditioner – 1 tube (please use to clean ALL rubber seals before install)**
- Front windshield and new rubber seal
- Rear glass and new rubber seal
- Rear side window rubber seals (left + right)
- Rear side window vertical rubber seals (left + right)
- Vent window rubber seals (left + right)
- Door rubber seals (left + right)
- Trunk upper rubber seal
- Rear bumper 12" rubber gaskets – they fit behind rear bumper (left + right)
- Rear bumper rubber molding + clips
- Rubber beading for bumperettes – 4 pcs; need to cut to length - *black*
- Firewall rubber drainage tubes – 3 pcs (they fit on upper rear of engine bay)
- Rubber beading – grey 6 pcs (left + right); part#(51 72 6 440 147)+(51 72 6 440 148) **Please call BMW parts to inquire about where this beading is installed.**

- Roof railing chrome trim (left + right)
- Vertical glass chrome trim (left + right); fits between door glass and rear glass
- Horizontal rear glass chrome trim (left + right)
- Upper door glass felt molding 2 pcs inner & 2 pcs outer (left + right)
- New Door handles + gaskets & keys (left + right)
- New Mirrors (left + right); **please drill holes to install right mirror**
- Front Hood BMW emblem
- Rear panel "2002tii" emblem; **Please drill new holes to install emblem and cover old holes**
- Wheel BMW emblem – 1 pc; **need to order 3 more**
- Mid door trim molding - 3 pcs per side (right + left)
- Lower side trim moldings (left + right); they fit below the doors
- Rear chrome bumperettes – 2 pcs (left + right)
- Rear bumperette rubber moldings (left + right)
- Front hood latch handle & cable replacement; fits under dashboard inside car driver side

- **Various metal + plastics clips for trim and molding installation**

Henry Ford

Chroming required: **please fit & install pieces first and then send out for chroming**

- Luggage rack for rear trunk *\$ 925.00*
 - Front bumper bar
 - Rear bumper bar
 - Door latches – 2 pcs (left + right)
 - Trunk latch – 1 pc
- "bmw2002faq.com" → bumper bar pics*
- High lustre Metal Finishing
510 410 8216 / 510 785 0196
Rich Jr.*

Parts to Oder:

- Upper door latch spacers (left + right)
- Rear inner trunk rubber grommets (left + right); there's one on the car as an example *Under-trunk lid!*
- BMW Wheel emblems – provided 1 pc but need 2 or 3 more; **please paint wheel inserts red to match body**

ALLEN'S AUTO BODY

371 Quarry Road
 BELMONT, CA 94002
 (415) 592-8232
 Fax: (415) 637-1679

Repair Order #3445 by ALLEN CAGLE on 07-24-97

Style : 2DR/4SP Insurer : NO CLAIM FILED
 Lic. Plate: TIITAN Adjuster :
 Paint Code: TAN Appraiser:
 Prod. Date: Claimant :
 Profile : CUSTOM Insured :
 Deductible: 0.00 Policy # :
 Claim # :

73 BMW 2002 TII
 VIN: 2762965
 Mileage: 13617
 Options:

#	Labor Op	Description	Est Price	Price	Est Labor	Labor	Est Paint	Paint	L/G	P/G	Change
1	R & I	HOOD,HOOD BRKTS,NUTS,BOLTS & CLIPS	0.00	0.00	1.5*	1.5*	0.0	0.0	BODY*	EXIS*	
2	REPLACE	CUSTOMER SUPPLIED BATTERY TRAY	0.00	0.00	2.5*	2.5*	0.0	0.0	BODY*		
3	REPAIR	3 AIR CONDITION LINE HOLES	0.00	0.00	3.0*	3.0*	0.0	0.0	BODY*	EXIS*	
4	REF/REP	PREP FOR RUST REPAIR	0.00	0.00	0.0	0.0	7.0*	7.0*	REFI*		
5	REF/REP	PRIME,SAND & PREP FOR PAINT	0.00	0.00	0.0	0.0	8.0*	8.0*	REFI*		
6	REF/REP	PAINT ENGINE COMPARTMENT & UNDER HOOD	0.00	0.00	0.0	0.0	6.0*	6.0*	REFI*		

* Judgement Item

Summary	Estimated	Actual	Estimated	Actual	Estimated	Actual
BODY	7.00 56.00 392.00T	7.00 56.00 392.00T	PAINT MATERIALS	168.13T	168.13T	
REFINISH	21.00 56.00 1176.00T	21.00 56.00 1176.00T				
Taxed Labor	1568.00	1568.00	Taxed Costs	168.13	168.13	
			Tx 8.250 8.250%	13.87	13.87	
			Labor (28.0 units)	1568.00		(28.0 units) 1568.00
			Add'l Costs/Materials	168.13		168.13
			Tax	13.87		13.87
Customer Responsibility	0.00					
Grand Total			1750.00		1750.00	

for Light -17.00
1733.00

Invoice

Larry's Tire Express

Larry's Tire Express

Business Number: (510) 888-1111

31 Pitt Way
El Sobrante
94803
510-222-1914

DATE: Jan 29, 2020
TERMS: Due On Receipt

DESCRIPTION	RATE	QTY	AMOUNT
1956015 Cooper Evolution	\$78.30	4	\$313.20
Balancing, Installation, New Tire Valve	\$20.00	4	* \$80.00
State of Ca New Tire Fee	\$1.75	4	* \$7.00
Tire Disposal Fee	\$6.00	4	* \$24.00
* Indicates non-taxable line item			SUBTOTAL \$424.20
1956015 Cooper Evolution, Road Hazard, Free Tire Rotation, Free Balancing, Free Patches			TAX (8.25%) \$25.84
			TOTAL \$450.04
			BALANCE DUE \$450.04

**Berkeley Motor Works**

736 San Pablo Ave.
 Albany Ca 94706
 BAR # ARD21986
 EPA # CAL000249938
 (510) 528-1214
 Servicedesk@berkeleymotor.com

Invoice #33718

Page 1 of 3
 11-30-21
 Gabriel Dadoun
 1973 BMW 2002 TII

1973 BMW 2002 TII
 2762965
 Engine:
 Plate: KDH617 AK
 Odometer In: 14996
 Odometer Out: 14996

Advisor: Mike
 Technician: Ilja Nemeč

GRAND TOTAL: \$2,315.37**✓ PAID****SERVICES****1 Fix List Items****SUBTOTAL: \$0.00**

- Replace wiper inserts
- Wiper switch is loose - maybe missing chrome nut to secure. Look in trunk for owner supplied parts.
- Left license plate light is loose - tighten or supply needed hardware.
- Adjust idle
- Attempt to free up as best as possible the heater levers
- Repair as needed the shifter mechanism is very loose
- Make sure all lights are working

Labor: \$0.00
 Parts: \$0.00
 Fees: \$0.00
 Sublet: \$0.00

2 Install new heater valve**SUBTOTAL: \$972.15**

Repair heater box

Labor: \$350.00
 Parts: \$622.15
 Fees: \$0.00
 Sublet: \$0.00

LABOR

Remove and install heater valve

PARTS	PART #	QTY	EACH	TOTAL
Heater Control Valve	64 11 1 358 752	1.0	\$550.00	\$550.00
Würth Epoxy	EPOXY	1.0	\$16.50	\$16.50
German Blue Coolant	COOLANT	1.0	\$33.63	\$33.63
OEM HEATER HOSE	64 11 1 353 353	1.0	\$22.02	\$22.02

3 Shift lever Repair.**SUBTOTAL: \$467.39**

replace missing bushings. replace worn out shift rod.

Labor: \$393.75
 Parts: \$73.64
 Fees: \$0.00
 Sublet: \$0.00

LABOR

Shifter

PARTS	PART #	QTY	EACH	TOTAL
Shifter Slide Bushing	23 41 1 466 120	2.0	\$11.82	\$23.64
OEM used shift rod	used shift rod	1.0	\$50.00	\$50.00





Berkeley Motor Works

736 San Pablo Ave.
Albany Ca 94706
BAR # ARD21986
EPA # CAL000249938
(510) 528-1214
Servicedesk@berkeleymotor.com

Invoice #33718

Page 3 of 3
11-30-21
Gabriel Dadoun
1973 BMW 2002 TII

related to recalls or otherwise."

WARRANTY

All new replacement parts and labor have a limited time warranty for 24 months or 24,000 miles. No warranty applicable on used parts. Warranty valid only if vehicle is returned at customers expense to our service department for adjustment. Warranty will be voided by overheating; lack of lubrication, or off road use for non-off road vehicles. This warranty extends only to the person to whom the services were provided and not an subsequent purchaser. Warranty does not apply to friction surfaces, routine maintenance service, or tires. A buyer of this product in California has the right to have the vehicle serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the vehicle has been out of buyers hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer; or if the warranty repairs did not remedy the defect and the buyer notifies the manufacture or seller of the failure of the repairs within 60 days after they were completed. If after reasonable number attempts the defect has not been fixed, the buyer may return the vehicle for replacement of part or refund, subject in either case, to deduction for reasonable charge for usage. This time extension does not affect the protection or remedy the buyer has under other laws. Buyer shall not be entitled to recover from the seller any consequential damages, damages to property, damage to loss of usage loss of time, loss from profit or income or any other incidental damages.

Authorization:

1:41pm 11/17/21





Berkeley Motor Works

736 San Pablo Ave.
Albany Ca 94706
BAR # ARD21986
EPA # CAL000249938
(510) 528-1214
Servicedesk@berkeleymotor.com

Invoice #33438

Page 1 of 2
09-08-21
Gabriel Dadoun
1973 BMW 2002 TII

1973 BMW 2002 TII

Advisor: Scott Babcock

GRAND TOTAL: \$1,287.17

Engine:
Plate: KDH617 AK
Odometer In: 999999
Odometer Out:

Technician: Ilja Nemeč

✓ PAID

SERVICES

Reseal differential

SUBTOTAL: \$1,264.15

Remove differential and reseal. Add fresh gear lube afterward.

Labor: \$1,050.00
Parts: \$214.15
Fees: \$0.00
Sublet: \$0.00

LABOR

Differential Reseal

PARTS	PART #	QTY	EACH	TOTAL
90w Gear Oil	SWEPCO 201	1.0	\$33.72	\$33.72
Parts Cleaner	PARTS CLEANER	1.0	\$10.00	\$10.00
O.E. Sealant	1207B	1.0	\$29.81	\$29.81
Output Shaft Seal	33 12 1 205 302	2.0	\$39.73	\$79.46
Rear Cover Gasket	33 11 3 604 117	1.0	\$19.97	\$19.97
Lock Plate	23 21 1 490 120	1.0	\$11.25	\$11.25
Pinion Seal	33 12 7 621 206	1.0	\$29.94	\$29.94

Terms of Service:

GRAND TOTAL: \$1,287.17

1. "YES, DO THIS WORK"

I hereby authorize the corresponding service to be done along with the necessary materials.

Total Labor: \$1,050.00
Total Parts: \$214.15
Total Fees: \$0.00
Total Sublets: \$0.00
Sales Tax: \$23.02

2. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"

Berkeley Motor Works staff may operate my vehicle for the purpose of testing, inspection, and delivery.

✓ PAID

3. "NO PAYMENT, NO KEYS"

An express lien is acknowledged on my vehicle to secure the amount of services thereto.

09-08-2021 3:39 PM
Paid by Credit Card via Terminal: \$1,287.17

4. "ONLINE COMMUNICATION OK"

I welcome email from Berkeley Motor Works as a means of receiving copies of my estimate, work order, and invoice.

5. "HERE'S MY SIGNATURE"

I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these five terms.

IMPORTANT AIRBAG NOTE: Due to many manufacturer airbag recalls your vehicle may require service or replacement of airbag(s) and/or their associated parts and/or software. Berkeley Motor Works cannot perform these repairs or advise on your vehicle's potential need for them. Your vehicle manufacturer is solely responsible for these repairs and the liability therewith. Berkeley Motor Works cannot and does not take any responsibility for damage to property or persons including injury or even death due to airbag systems.





Berkeley Motor Works

736 San Pablo Ave.
Albany Ca 94706
BAR # ARD21986
EPA # CAL000249938
(510) 528-1214
Servicedesk@berkeleymotor.com

Invoice #33438

Page 2 of 2

09-08-21

Gabriel Dadoun

1973 BMW 2002 TII

Berkeley Motor Works strongly advises you consult with your vehicle's authorized dealership to determine the safety of your airbag system and if it is in need of repairs related to recalls or otherwise."

WARRANTY

All new replacement parts and labor have a limited time warranty for 24 months or 24,000 miles. No warranty applicable on used parts. Warranty valid only if vehicle is returned at customers expense to our service department for adjustment. Warranty will be voided by overheating; lack of lubrication, or off road use for non-off road vehicles. This warranty extends only to the person to whom the services were provided and not an subsequent purchaser. Warranty does not apply to friction surfaces, routine maintenance service, or tires. A buyer of this product in California has the right to have the vehicle serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the vehicle has been out of buyers hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer; or if the warranty repairs did not remedy the defect and the buyer notifies the manufacture or seller of the failure of the repairs within 60 days after they were completed. If after reasonable number attempts the defect has not been fixed, the buyer may return the vehicle for replacement of part or refund, subject in either case, to deduction for reasonable charge for usage. This time extension does not affect the protection or remedy the buyer has under other laws. Buyer shall not be entitled to recover from the seller any consequential damages, damages to property, damage to loss of usage loss of time, loss from profit or income or any other incidental damages.

Authorization:

12:09pm 09/08/21



Berkeley Motor Works

736 San Pablo Ave.
Albany Ca 94706
BAR # ARD21986
EPA # CAL000249938
(510) 528-1214
Servicedesk@berkeleymotor.com

Invoice #32782

Page 1 of 2
03-30-21
Gabriel Dadoun
1973 BMW 2002 TII

1973 BMW 2002 TII

Engine:
Plate: KDH617 AK
Odometer In: 14934
Odometer Out: 14934

Advisor:

Technician: Ilja Nemeč

GRAND TOTAL: \$711.40

✓ PAID

SERVICES

1	Clutch pedal went to the floor	SUBTOTAL: \$477.17
	replace slave cylinder	Labor: \$262.50
	LABOR	Parts: \$214.67
		Fees: \$0.00
		Sublet: \$0.00
	PARTS	
		QTY EACH TOTAL
	Clutch Slave Cylinder	1.0 \$184.82 \$184.82
	Brake Fluid Flush Kit	1.0 \$29.85 \$29.85

2	check operation of cold start system	SUBTOTAL: \$209.90
	replace air intake boot.	Labor: \$175.00
	adjust idle speed.	Parts: \$34.90
	LABOR	Fees: \$0.00
		Sublet: \$0.00
	PARTS	
		QTY EACH TOTAL
	TII SUCTION BOOT	1.0 \$34.90 \$34.90

Terms of Service:

1. "YES, DO THIS WORK"
I hereby authorize the corresponding service to be done along with the necessary materials.
2. "YOU MAY DRIVE MY CAR ON PUBLIC ROADS"
Berkeley Motor Works staff may operate my vehicle for the purpose of testing, inspection, and delivery.
3. "NO PAYMENT, NO KEYS"
An express lien is acknowledged on my vehicle to secure the amount of services thereto.
4. "ONLINE COMMUNICATION OK"
I welcome email from Berkeley Motor Works as a means of receiving copies of my estimate, work order, and invoice.
5. "HERE'S MY SIGNATURE"
I endorse the attached digital image of my signature as equivalent to my written signature and as proof of my agreement to these five terms.

IMPORTANT AIRBAG NOTE: Due to many manufacturer airbag recalls your vehicle may require service or replacement of airbag(s) and/or their associated parts and/or software.

GRAND TOTAL: \$711.40

Total Labor: \$437.50
Total Parts: \$249.57
Total Fees: \$0.00
Total Sublets: \$0.00
Sales Tax: \$24.33

✓ PAID

03-30-2021 10:05 AM
Paid by Credit Card via Remote Pay: \$711.40

Gabriel Dadoun: xxxxxxxxxxxxxxxx
Transaction ID: 761313257377





Berkeley Motor Works

736 San Pablo Ave.
Albany Ca 94706
BAR # ARD21986
EPA # CAL000249938
(510) 528-1214
Servicedesk@berkeleymotor.com

Invoice #32782

Page 2 of 2
03-30-21
Gabriel Dadoun
1973 BMW 2002 TII

Berkeley Motor Works cannot perform these repairs or advise on your vehicle's potential need for them. Your vehicle manufacturer is solely responsible for these repairs and the liability therewith. Berkeley Motor Works cannot and does not take any responsibility for damage to property or persons including injury or even death due to airbag systems. Berkeley Motor Works strongly advises you consult with your vehicle's authorized dealership to determine the safety of your airbag system and if it is in need of repairs related to recalls or otherwise."

WARRANTY

All new replacement parts and labor have a limited time warranty for 24 months or 24,000 miles. No warranty applicable on used parts. Warranty valid only if vehicle is returned at customers expense to our service department for adjustment. Warranty will be voided by overheating; lack of lubrication, or off road use for non-off road vehicles. This warranty extends only to the person to whom the services were provided and not an subsequent purchaser. Warranty does not apply to friction surfaces, routine maintenance service, or tires. A buyer of this product in California has the right to have the vehicle serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the vehicle has been out of buyers hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by circumstances beyond the control of the buyer; or if the warranty repairs did not remedy the defect and the buyer notifies the manufacture or seller of the failure of the repairs within 60 days after they were completed. If after reasonable number attempts the defect has not been fixed, the buyer may return the vehicle for replacement of part or refund, subject in either case, to deduction for reasonable charge for usage. This time extension does not affect the protection or remedy the buyer has under other laws. Buyer shall not be entitled to recover from the seller any consequential damages, damages to property, damage to loss of usage loss of time, loss from profit or income or any other incidental damages.

Authorization:

11:14am 03/29/21

BERKELEY MOTOR WORKS, Inc.

Service Invoice 29741

Name Address Home Work Fax	Company Address 2 Promised VIN # 2762965 Radio Code	Created Time 09/28/18 Invoiced Advisor 10/16/18 Division ScottB PO# BM Checked By Page# 1 of 2	Year 1973 Make BMW Model 2002 TII Lic # KDH617 AK Pro date Color Beige Miles In 14,877 Miles Out 14,877
--	---	---	--

Job Description

Fuel injection pump on engine found to have broken drive belt. Replace drive belt and time injection pump to proper specifications. Test drive thoroughly to make sure brakes are functioning well. Check for engine thermostat operating properly on test drive.

Line Total	963.06
Labor	870.00
Parts	93.06
Sublets	0.00

Part Number	Description	QTY	Each	Total
18498	Injection Pump Belt	1	93.06	93.06

Replace warped water pump pulley with good used unit.

Line Total	420.43
Labor	290.00
Parts	130.43
Sublets	0.00

Part Number	Description	QTY	Each	Total
5712	Coolant Blue	1	29.63	29.63
18523	Used Water Pump Pulley	1	100.80	100.80

Replace fuel filter

Line Total	95.71
Labor	72.50
Parts	23.21
Sublets	0.00

Part Number	Description	QTY	Each	Total
3795	FUEL FILTER	1	23.21	23.21

Install electronic ignition conversion

Line Total	485.00
Labor	290.00
Parts	195.00
Sublets	0.00

Part Number	Description	QTY	Each	Total
15530	Electronic Ignition Kit	1	195.00	195.00

*** SERVICE WARRANTY - LIMITED WARRANTY***

All new replacement parts and labor have a limited time warranty for **24 months or 24,000 miles**. No warranty applicable on used parts. Warranty valid only if vehicle is returned at customer's expense to our service department for adjustment. Warranty will be voided by overheating; lack of lubrication, or off road use for non-off road vehicles. This warranty extends only to the person to whom the services were provided and not an subsequent purchaser. Warranty does not apply to friction surfaces, routine maintenance service, or tires. A buyer of this product in California has the right to have the vehicle serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the vehicle has been out of buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by

Thanks for patronizing
a Green Business!

PAID



736 San Pablo Ave | Albany, CA 94706 | BAR#ARD212986
510-528-1214 | FAX 510-528-8373 | EPA ID#CAL000249938 We appreciate your business and want to thank you for allowing us to handle all your service needs. I hereby acknowledge and approve any oral/electronic increase over the original price for service/repairs.

X _____ Date _____

Invoice Total	
Labor	\$1,522.50
Parts	\$441.70
Sublets	\$0.00
Subtotal	\$1,964.20
Tax	\$43.07
Total	\$2,007.27

BERKELEY MOTOR WORKS, Inc.

Service Invoice 29741

Name Address	Company Address 2	Created Time	09/28/18 9:02 AM	Year Make	1973 BMW
Home Work Fax	Promised V.I.N. # Radio Code	Invoiced Advisor Division PO# Checked By Page#	10/16/18 ScottB BM 2 of 2	Model Lic.# Pro date Color Miles In Miles Out	2002 TII KDH617 AK Beige 14,877 14,877

Job Description

circumstances beyond the control of the buyer; or if the warranty repairs did not remedy the defect and the buyer notifies the manufacture or seller of the failure of the repairs within 60 days after they were completed. If after reasonable number attempts the defect has not been fixed, the buyer may return the vehicle for replacement of part or refund, subject in either case, to deduction for reasonable charge for usage. This time extension does not affect the protection or remedy the buyer has under other laws. Buyer shall not be entitled to recover from the seller any consequential damages, damages to property, damage to loss of usage loss of time, loss from profit or income or any other incidental damages.

Recommended Work

All tires needed 195/60/14

736 San Pablo Ave | Albany, CA 94706 | BAR#ARD212986
 510-528-1214 | FAX 510-528-8373 | EPA ID#CAL000249938 We appreciate your business and want to thank you for allowing us to handle all your service needs. I hereby acknowledge and approve any oral/electronic increase over the original price for service/repairs.

X _____ Date _____

Invoice Total	
Labor	\$1,522.50
Parts	\$441.70
Sublets	\$0.00
Subtotal	\$1,964.20
Tax	\$43.07
Total	\$2,007.27

BERKELEY MOTOR WORKS, Inc.

Service Invoice 29699

Name Address	Company Address 2	Created Time	09/17/18 12:20 PM	Year Make	1973 BMW
Home Work Fax	Promised V.I.N. # Radio Code	Invoiced Advisor Division PO# Checked By Page#	09/21/2018 ScottB BM 1 of 1	Model Lic # Pro date Color Miles In Miles Out	2002 TII KDH617 AK Beige 114,875 114,875
	2762965				

Job Description

Car towed into shop with customer. Car has sat since 2001. Car started with fresh gas but died and would not restart. New battery in car. Get car road worthy. Check cooling system. Check brakes. Car has higher compression pistons in engine. Report: Fuel tank has rust laying in the bottom. 12V Power back to fuel pump but pump not operating. Fuel pump replacement needed and remove rust from tank. Original fuel pump is no longer available - NLA.

Replace fuei pump with modified Mercedes pump with needed parts.

Line Total	1048.66
Labor	696.00
Parts	352.66
Sublets	0.00

Part Number	Description	QTY	Each	Total
14074	Fuel Pump	1	325.00	325.00
18483	Banjo Fitting	1	7.20	7.20
18130	Copper Seals	2	0.88	1.76
17527	Hose Clamp	2	3.47	6.94
9845	Hose Clamp	4	2.94	11.75

Thanks for patronizing
a Green Business!

PAID



736 San Pablo Ave | Albany, CA 94706 | BAR#ARD212986
510-528-1214 | FAX 510-528-8373 | EPA ID#CAL000249938 We appreciate your business and want to thank you for allowing us to handle all your service needs. I hereby acknowledge and approve any oral/electronic increase over the original price for service/repairs.

Date 09/21/2018

Invoice Total	
Labor	\$696.00
Parts	\$352.66
Sublets	\$0.00
Subtotal	\$1,048.66
Tax	\$34.38
Total	\$1,083.04

X

BERKELEY MOTOR WORKS, Inc.

Service Invoice 29741

			2762965		09/28/18 9:02 AM 10/16/2018 ScottB BM		1973 BMW 2002 TII KDH617 AK Beige 14,877 14,877
					1 of 2		

Fuel injection pump on engine found to have broken drive belt. Replace drive belt and time injection pump to proper specifications. Test drive thoroughly to make sure brakes are functioning well. Check for engine thermostat operating properly on test drive.

18498	Injection Pump Belt	1	93.06	93.06		Line Total	963.06
-------	---------------------	---	-------	-------	--	-------------------	---------------

Replace warped water pump pulley with good used unit.

5712	Coolant Blue	1	29.63	29.63		Line Total	420.43
18523	Used Water Pump Pulley	1	100.80	100.80		Labor	290.00
						Parts	130.43
						Sublets	0.00

Replace fuel filter

3795	FUEL FILTER	1	23.21	23.21		Line Total	95.71
						Labor	72.50
						Parts	23.21
						Sublets	0.00

Install electronic ignition conversion

15530	Electronic Ignition Kit	1	195.00	195.00		Line Total	485.00
						Labor	290.00
						Parts	195.00
						Sublets	0.00

***** SERVICE WARRANTY - LIMITED WARRANTY*****

All new replacement parts and labor have a limited time warranty for **24 months or 24,000 miles**. No warranty applicable on used parts. Warranty valid only if vehicle is returned at customer's expense to our service department for adjustment. Warranty will be voided by overheating; lack of lubrication, or off road use for non-off road vehicles. This warranty extends only to the person to whom the services were provided and not an subsequent purchaser. Warranty does not apply to friction surfaces, routine maintenance service, or tires. A buyer of this product in California has the right to have the vehicle serviced or repaired during the warranty period. The warranty period will be extended for the number of whole days that the vehicle has been out of buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been fixed. The warranty period will also be extended if the warranty repairs have not been performed due to delays caused by

736 San Pablo Ave | Albany, CA 94706 | BAR#ARD212986
 510-528-1214 | FAX 510-528-8373 | EPA ID#CAL000249938 We appreciate your business and want to thank you for allowing us to handle all your service needs. I hereby acknowledge and approve any oral/electronic increase over the original price for service/repairs.

X _____ Date _____

	\$1,522.50
	\$441.70
	\$0.00
	\$1,964.20
	\$43.07
	\$2,007.27

BERKELEY MOTOR WORKS, Inc.

Service Invoice 29741

			2762965	09/28/18 9:02 AM	1973 BMW 2002 TII KDH617 AK
				ScottB BM	Beige 14,877 14,877
				2 of 2	

circumstances beyond the control of the buyer; or if the warranty repairs did not remedy the defect and the buyer notifies the manufacture or seller of the failure of the repairs within 60 days after they were completed. If after reasonable number attempts the defect has not been fixed, the buyer may return the vehicle for replacement of part or refund, subject in either case, to deduction for reasonable charge for usage. This time extension does not affect the protection or remedy the buyer has under other laws. Buyer shall not be entitled to recover from the seller any consequential damages, damages to property, damage to loss of usage loss of time, loss from profit or income or any other incidental damages.

All tires needed 195/60/14

736 San Pablo Ave | Albany, CA 94706 | BAR#ARD212986
 510-528-1214 | FAX 510-528-8373 | EPA ID#CAL000249938 We appreciate your business and want to thank you for allowing us to handle all your service needs. I hereby acknowledge and approve any oral/electronic increase over the original price for service/repairs.

X _____ Date _____

	\$1,522.50
	\$441.70
	\$0.00
	\$1,964.20
	\$43.07
	\$2,007.27

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 650-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 1554
 PAGE # :
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 03/05/01

===== CUSTOMER DATA =====+===== CAR DATA =====

| BMW Tii *Mitii*
 | LICENSE PLATE : TIITAN /CA YEAR: 1973
 | ENGINE SIZE/TYPE : 2.0 "R"
 | VIN NUMBER : 2762965
 | MILEAGE : 1 PROD.DATE:

DATE IN : 03/05/01 TIME IN : 11:51 DATE DUE : 03/05/01 TIME DUE : 18:00
 CUST.NO.: 3046 DEPOSIT : 0.00 CORE DEP.: 0.00 SUBLT.EST.: 0.00

LABOR ESTIMATE : 0.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 0.00

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
61 21 9 057 719	BATTERY	1	107.00	84.00	84.00
PARTS TOTAL =====>					84.00

GAS, OIL, GREASE ==>	0.00	SUB-TOTAL =====>	84.00
CORE CHARGES =====>	0.00	SALES TAX =====>	6.72
MISC. CHARGES =====>	0.00	LESS DEPOSITS =====>	0.00
===== TOTAL DUE =====>			90.72

*** REPAIR ORDER INVOICE ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 650-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 12378
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 05/21/98

===== CUSTOMER DATA =====+===== CAR DATA =====

: BMW 2002 Tii
 : LICENSE PLATE : MITII /CA YEAR: 1973
 : ENGINE SIZE/TYPE : 2.0 "L"
 : VIN NUMBER : 2762965
 : MILEAGE : 13610 PROD.DATE:

DATE IN : 06/19/97 TIME IN : 07:45 DATE DUE : 05/21/98 TIME DUE : 18:00
 CUST.NO. : 3046 DEPOSIT : 4000.00 CORE DEP. : 0.00 SBLT.EST. : 0.00

LABOR ESTIMATE : 187.50 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 187.50

TECH(S) : SERVICE DESCRIPTION

```

: CUSTOMER NOTES UNUSUAL KNOCKING UNDER HOOD.
: INSPECT AND REPORT.                                0.5      37.50
: FOUND: ALTERNATOR MOUNT BRACKET DETACHED AND BOLTS
:         SNAPPED OFF IN BLOCK
: REMOVE ENGINE, REMOVE BROKEN BOLTS FROM BLOCK
: PARTIALLY DISASSEMBLE ENGINE. CUSTOMER TO HAVE
: VARIOUS ENGINE PARTS POLISHED OR PLATED.
: CUSTOMER TO HAVE ENGINE COMPARTMENT PAINTED.
: DISASSEMBLE/REASSEMBLE ENGINE COMPARTMENT.
: REINSTALL ENGINE AND TUNE.                          40.0     3000.00
: REPLACE CUSTOMERS DEFECTIVE WATER PUMP AND ALTER-
: NATOR A SECOND TIME.                                3.0      225.00
: REMOVE OVER TIGHT LUGS                              0.5      37.50
: REPLACE REAR BRAKE SHOES, DRUMS, WHEEL CYLINDERS,
: BLEED SYSTEM.                                       3.0      225.00
: FIT NEW EMERGENCY CABLES AND ADJUST                 1.5      112.50
: FIT FRONT BRAKE PADS                                0.6       45.00
: REPLACE TURN SIGNAL SWITCH.                         0.5       37.50
:
: L A B O R   C H A R G E S  =====>                3720.00
    
```

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 963 888	HARDWARE	1	50.00	50.00	50.00
07 12 9 964 672	E BRAKE NUT	1	1.22	1.22	1.22
11 12 1 468 053	OIL CAP GASKET KIT	1	8.27	8.27	8.27
11 61 1 257 034	INTAKE GASKET	2	6.54	6.54	13.08
12 31 1 469 232	BELT ACT.	1	11.90	11.90	11.90

CONTINUED TO NEXT PAGE

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 650-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 12378
 PAGE # : 2
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 05/21/98

===== CUSTOMER DATA =====+===== CAR DATA =====
 : BMW 2002 Tii
 =====!=====

REPAIR ORDER PAGE # 2

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
31 11 1 137 888	E BRAKE BOLT	1	2.41	2.41	2.41
34 41 1 104 265	WASHER E BRAKE	1	2.88	2.88	2.88
34 41 1 116 434	SPRING E BRAKE	1	4.02	4.02	4.02
34 41 1 116 436	BUTTON E BRAKE	1	2.70	2.70	2.70
34 41 1 118 529	E BRAKE BUSHING	1	3.82	3.82	3.82
34 41 1 152 892	ROD E BRAKE	1	3.64	3.64	3.64
51 13 1 808 112	WASHER E BRAKE	1	1.32	1.32	1.32
61 66 1 000 001	BRAIDED WASHER LINE WINDSHIELD	4	3.20	3.20	12.80
07 12 9 952 109	HOSE CLAMP > COOLING	6	1.55	1.55	9.30
07 12 9 952 117	HOSE CLAMP	6	1.23	1.23	7.38
11 12 1 734 276	VALVE COVER GASKET 4 CYL.	1	14.10	14.10	14.10
11 14 1 727 986	TIMING COVER GASKET SET	1	22.51	22.51	22.51
11 42 1 278 059	OIL FILTER 4CYL.	1	8.95	5.80	5.80
11 53 1 257 371	WATER PUMP HOSE	1	18.15	18.15	18.15
11 53 1 260 720	THERMOSTAT 4CYL. 75 DEGREE.	1	27.08	21.00	21.00
11 53 1 266 469	TOP THERM HOSE	1	17.34	17.34	17.34
11 53 1 266 471	MIDDLE THERM HOSE WITH A/C	1	4.52	4.52	4.52
11 53 1 266 477	UPPER HOSE	1	16.50	16.50	16.50
11 61 1 256 604	GASKET	4	1.57	1.57	6.28
11 62 1 259 559	FLANGE NUTS (2) 10 MM	3	1.65	1.65	4.95
11 62 1 711 954	COPPER EX NUT	8	1.02	1.02	8.16
11 72 1 261 404	BUSHING	4	3.48	3.48	13.92
11 73 1 259 995	VACUUM HOSE - RED	1	3.06	3.06	3.06
12 11 1 267 393	IGNITION POINTS	1	5.78	5.78	5.78
12 11 1 356 920	CONDENSER	1	11.07	11.07	11.07
12 11 1 360 305	ROTOR	1	11.28	11.28	11.28
12 11 1 363 423	DISTRIBUTOR CAP	1	13.88	13.88	13.88
12 12 1 269 333	SPARK PLUG	4	5.03	5.03	20.12
12 13 1 359 637	IGNITION COIL	1	77.10	77.10	77.10
13 31 1 272 731	FUEL HOSE	1	10.55	10.55	10.55
13 31 1 272 750	FUEL HOSE - 6 MM	1	4.95	4.95	4.95
13 32 1 256 492	FUEL FILTER	1	18.28	18.28	18.28

CONTINUED TO NEXT PAGE

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 650-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 12378
 PAGE # : 3
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 05/21/98

===== CUSTOMER DATA =====+===== CAR DATA =====

: BMW 2002 Tii

REPAIR ORDER PAGE # 3

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
13 72 1 254 660	AIR FILTER	2	16.75	16.75	33.50
17 11 1 115 755	RADIATOR	1	345.00	270.00	270.00
17 11 1 468 060	RADIATOR CAP	1	13.23	13.23	13.23
17 11 9 963 001	ANTIFREEZE	1	8.00	8.00	8.00
20/50 GTX	ENGINE OIL	5	2.25	2.25	11.25
34 11 1 159 257	BRAKE PADS	1	66.00	66.00	66.00
34 21 1 101 741	REAR DRUM	2	108.00	108.00	216.00
34 21 1 159 584	REAR BRAKE SHOES W/O LEVER	1	62.68	62.68	62.68
34 21 3 460 120	WHEEL CYLINDER	2	81.90	81.90	163.80
34 32 1 113 184	BRAKE HOSE	1	15.92	15.92	15.92
34 41 1 116 435	HANDLE	1	3.75	3.75	3.75
34 41 1 117 325	HAND BRAKE HANDLE	1	26.39	26.39	26.39
34 41 1 151 769	LOCK SEGMENT	1	13.00	13.00	13.00
61 12 1 350 305	BATTERY GROUND STRAP	1	19.07	19.07	19.07
62 11 0 788 115	TEMPERATURE SENDING UNIT	1	18.43	18.43	18.43
64 21 1 353 368	HEATER HOSE	1	24.35	24.35	24.35
64 21 1 354 308	HEATER HOSE	1	19.80	19.80	19.80
81 22 9 407 512	BRAKE FLUID-1 LITER	1	11.65	11.65	11.65
82 14 9 407 408	WASHER FLUID	1	4.11	4.11	4.11
PARTS TOTAL =====>					1464.97

SUBLET SERVICE DESCRIPTION	SUBLET PRIC	
Environmental Charges	3.00	
REBUILD ALTERNATOR	96.00	
TOW	24.00	
SUBLET TOTAL =====>		123.00

PAID

GAS, OIL, GREASE ==>	5.00	SUB-TOTAL =====>	5307.97
CORE CHARGES =====>	0.00	SALES TAX =====>	120.86
MISC. CHARGES =====>	0.00	LESS DEPOSITS =====>	4000.00
===== TOTAL DUE =====>			1433.83

Allen's Auto Body → 592-8252

*** ESTIMATE COPY --- REPAIR ORDER ***

SCHULBA S.M.W. (BELMONT MOTOR WORKS)
415-592-7352
645 HARBOR BLVD.
BELMONT, CA. 94002-

REPAIR ORDER # : 12378
PAGE # : 1
WRITTEN BY : GS
ESTIMATED BY : GS
DATE PRINTED : 06/19/97

CUSTOMER DATA

CAR DATA

BMW Tii
LICENSE PLATE : TIITAN /CA YEAR: 1973
ENGINE SIZE/TYPE : 2.0 "R"
VIN NUMBER : 2762965
MILEAGE : 13610 PROD. DATE:

DATE IN : 06/19/97 TIME IN : 07:45 DATE DUE : 06/19/97 TIME DUE : 18:00
DEPOSIT : 0.00 CORE DEPOSIT : 0.00 SUBLET ESTIMATE : 0.00

LABOR ESTIMATE : 187.50 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 187.50

TECH SERVICE DESCRIPTION HRS. LBR.\$ PARTS \$

CUSTOMER NOTES UNUSUAL KNOCKING SOUND UNDERHOOD
INSPECT AND REPORT
MOUNT CUSTOMER PROVIDED EXHAUST SYSTEM
INSPECT BRAKES AND ADJUST E-BRAKE; REPORT

0.5 37.50
1.0 75.00
1.0 75.00

GS Received 1000.00 9/19/97 Credit Card
GS Received 1500.00 11/25/97 #321

62-16
311

B

M

W

- 1) I hereby authorize the repairs listed above along with the necessary materials, and shop supplies charge of 5% of labor up to \$5.00.
- 2) I hereby authorize sublet work required to expedite repairs.
- 3) I acknowledge your right to a mechanics lien for charges incurred under this repair order and that the vehicle can be held until paid in full plus any legal fees or charges incurred.
- 4) Storage at \$25.00 per day will commence 24 hours after notice of completion of repairs as listed above.
- 5) I UNDERSTAND I HAVE THE RIGHT TO HAVE EMISSION SERVICE AND/OR REPAIRS DONE ELSEWHERE.
- 6) ENVIRONMENTAL CHARGE OF \$3.00 ON OIL/COOLANT CHANGES.

CUSTOMER SIGNATURE : _____

Previous Repair Order : 11100

Shop Phone Number : (415)592-7352

REPAIR ORDER # : 12378

*** ESTIMATE COPY --- REPAIR ORDER ***

CALIFORNIA B.A.R. REGISTERED #A8123112 123112

*** REPAIR ORDER INVOICE ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 11706
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 09/27/96

===== CUSTOMER DATA ===== CAR DATA =====

: DMW P11
 : LICENSE PLATE : TITAN /CA YEAR: 1973
 : ENGINE SIZE/TYPE : 2.0 "K"
 : VIN NUMBER : 2762965
 : MILEAGE : 10682 PROD.DATS:

DATE IN : 09/27/96 TIME IN : 07:09 DATE DUE : 09/27/96 TIME DUE : 18:00
 CUST.NO. : 3046 DEPOSIT : 0.00 CORE DEP. : 0.00 SUBLT.EST. : 0.00
 LABOR ESTIMATE : 68.00 PARTS ESTIMATE : 25.00 ESTIMATE TOTAL : 93.00

TECH(S) : SERVICE DESCRIPTION

OIL & FILTER CHANGE (CUSTOMER REQUESTS ADD SLICK 0.3 20.40
 50 TO OIL CHANGE)
 CUSTOMER REQUESTS CHANGE IGNITION POINTS PER GERRY 0.5 34.00
 LABOR CHARGES =====> 54.40

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 963 355	DRAIN PLUG SEAL	1	0.66	0.66	0.66
11 42 1 278 059	OIL FILTER 4CYL.	1	9.29	7.85	7.85
12 11 1 267 394	IGNITION POINTS	1	7.19	7.19	7.19
20/50 GTX	ENGINE OIL	5	2.25	2.25	11.25
PARTS TOTAL =====>					26.95

SUBLET SERVICE DESCRIPTION SUBLET PRICE

Environmental Charges 3.00
 SUBLET TOTAL =====> 3.00

GAS, OIL, GREASE ==> 0.00
 CORE CHARGES =====> 0.00
 MISC. CHARGES =====> 0.00
 SUB-TOTAL =====> 84.35
 SALES TAX =====> 2.22
 LESS DEPOSITS =====> 0.00
 ===== TOTAL DUE =====> 86.57

*** REPAIR ORDER INVOICE ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 11465
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 06/14/96

===== CUSTOMER DATA ===== CAR DATA =====

: BMW Tii
 : LICENSE PLATE : TITAN /CA YEAR: 1973
 : ENGINE SIZE/TYPE : 2.0 "R"
 : VIN NUMBER : 2762965
 : MILEAGE : 9551 PROD.DATE:

DATE IN : 06/14/96 TIME IN : 08:00 DATE DUE : 06/14/96 TIME DUE : 18:00
 CUST.NO. : 3046 DEPOSIT : 0.00 CORE DEP. : 0.00 SUBLT.EST. : 0.00

LABOR ESTIMATE : 204.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 204.00

TECH(s) : SERVICE DESCRIPTION

: REPLACE DEFECTIVE STARTER AND BATTERY 3.0 68.00
 : (WARRANTY ON STARTER)
 :
 : LABOR CHARGES =====> 68.00

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
12 41 1 355 693	USED STARTER MOTOR (RMFD)	1	145.77	0.00	0.00
61 21 9 057 719	BATTERY	1	107.00	77.00	77.00
PARTS TOTAL =====>					77.00

PAID
 B.C.
 W

GAS, OIL, GREASE ==> 0.00 SUB-TOTAL =====> 145.00
 CORE CHARGES =====> 0.00 SALES TAX =====> 6.35
 MISC. CHARGES =====> 0.00 LESS DEPOSITS =====> 0.00
 ===== TOTAL DUE =====> 151.35

*** REPAIR ORDER INVOICE ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 11433
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 06/04/96

CUSTOMER DATA

CAR DATA

: DMV Tit
 : LICENSE PLATE : TITAN /CA YEAR: 1973
 : ENGINE SIZE/TYPB : 2.0 "R"
 : VIN NUMBER : 2762965
 : MILEAGE : 9438 PROD.DATE:

DATE IN : 06/03/96 TIME IN : 08:40 DATE DUE : 06/04/96 TIME DUE : 18:00
 CUST.NO.: 3046 DEPOSIT : 0.00 CORE DEP.: 0.00 SUBLT.EST.: 0.00

LABOR ESTIMATE : 68.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 68.00

TECH(S) : SERVICE DESCRIPTION

: CAR WONT START SOMETIMES. CUSTOMER HAS TO PUSH
 : START.
 : CHECK STARTING SYSTEM AND REPORT. 0.5 34.00
 : FOUND: BATTERY POSITIVE CABLE FAILED.
 : REPLACE BATTERY POSITIVE CABLE, RETEST STARTING. 0.4 27.20
 : FOUND: SPARK PLUGS FOULD:
 : REPLACE FOULED SPARK PLUGS. 0.4 27.20
 : ADJUST ALTERNATOR BELT. 0.3 20.40
 :
 : LABOR CHARGES =====> 108.80

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
12 12 1 262 360	SPARK PLUG	4	2.63	2.63	10.52
61 12 1 357 247	BATTERY CABLE	1	26.80	26.80	26.80
PARTS TOTAL =====>					37.32

PAID

GAS, OIL, GREASE =====> 0.00
 CORE CHARGES =====> 0.00
 MISC. CHARGES =====> 0.00
 SUB-TOTAL =====> 146.12
 SALES TAX =====> 3.08
 LESS DEPOSITS =====> 0.00

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 11111
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 01/19/96

===== CUSTOMER DATA =====+===== CAR DATA =====

```

: BMW Tii
: LICENSE PLATE : TIITAN /CA YEAR: 1973
: ENGINE SIZE/TYPE : 2.0 "R"
: VIN NUMBER : 2762965
: MILEAGE : 74969  PROD. DATE:
    
```

```

=====+=====
DATE IN : 01/19/96  TIME IN : 09:35  DATE DUE : 01/19/96  TIME DUE : 18:00
CUST.NO.: 3046     DEPOSIT : 0.00   CORE DEP.: 0.00   SUBLT.EST.: 0.00
=====+=====
    
```

```

=====+=====
LABOR ESTIMATE : 88.40  PARTS ESTIMATE : 26.00  ESTIMATE TOTAL : 114.40
=====+=====
    
```

TECH(S) | SERVICE DESCRIPTION

```

=====+=====
: BRAKE FLUID LEAK AT MASTER CYLINDER. APEARS
: TO LEAKING AT TOP.
: INSPECT AND REPAIR OR REPORT PER ESTIMATE 0.5 34.00
: REPLACE MASTER CYLINDER FRONT FEED GROMET AND
: PIPE.
: ENGINE OIL AND FILTER CHANGE 0.3 20.40
:
LABOR CHARGES =====> 54.40
=====+=====
    
```

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 963 355	DRAIN PLUG SEAL	1	0.66	0.66	0.66
11 42 1 278 059	OIL FILTER 4CYL.	1	9.29	6.20	6.20
20/50 GTX	ENGINE OIL	5	2.25	2.25	11.25
PARTS TOTAL =====>					18.11



```

CAS, OIL, GREASE ==> 0.00
CORE CHARGES =====> 0.00
MISC. CHARGES =====> 0.00

SUB-TOTAL =====> 72.51
SALES TAX =====> 1.49
LESS DEPOSITS =====> 0.00
===== TOTAL DUE =====> 74.00
    
```


*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 10102
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 11/18/94

===== CUSTOMER DATA =====+===== CAR DATA =====

: BMW Tii
 : LICENSE PLATE : TIITAN /CA YEAR: 1973
 : ENGINE SIZE/TYPE : 2.0 "R"
 : VIN NUMBER : 2762965
 : MILEAGE : 4528 PROD. DATE:

DATE IN : 11/03/94 TIME IN : 01:41 DATE DUE : 11/18/94 TIME DUE : 18:00
 CUST. NO.: 3046 DEPOSIT : 0.00 CORE DEP.: 0.00 SUBLT. EST.: 0.00

LABOR ESTIMATE : 81.60 PARTS ESTIMATE : 35.00 ESTIMATE TOTAL : 116.60

TECH(S) : SERVICE DESCRIPTION

: RETORQUE CYLINDER HEAD/ADJUST VALVES 2.0
 : CHANGE ENGINE OIL AND FILTER. 0.2
 :
 : LABOR CHARGES =====> 0.00

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 963 130	DRAIN SEAL RING	1	0.66	0.66	0.66
11 12 1 734 276	VALVE COVER GASKET 4 CYL.	1	14.10	11.20	11.20
11 42 1 278 059	OIL FILTER 4CYL.	1	9.29	6.85	6.85
20/50 GTX	ENGINE OIL	5	2.25	2.25	11.25
PARTS TOTAL =====>					29.96

SUBLET SERVICE DESCRIPTION	SUBLET PRICE
Environmental Charges	3.00
SUBLET TOTAL =====>	3.00

PAID

Motor Works

GAS, OIL, GREASE ==>	0.00	SUB-TOTAL =====>	32.96
CORE CHARGES =====>	0.00	SALES TAX =====>	2.47
MISC. CHARGES =====>	0.00	LESS DEPOSITS =====>	0.00
		===== TOTAL DUE =====>	35.43

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W.(BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT,CA.94002-

REPAIR ORDER # : 9790
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 10/14/94

===== CUSTOMER DATA =====+===== CAR DATA =====

```

    | BMW Tii
    | LICENSE PLATE : TIITAN /CA  YEAR: 1973
    | ENGINE SIZE/TYPE : 2.0 "R"
    | VIN NUMBER : 2762965
    | MILEAGE : 3948  PROD.DATE:
  
```

DATE IN : 07/18/94 TIME IN : 15:29 DATE DUE : 10/14/94 TIME DUE : 18:00
 CUST.NO.: 3046 DEPOSIT : 0.00 CORE DEP.: 0.00 SUBLT.EST.: 0.00

LABOR ESTIMATE : 612.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 612.00

TECH(S) | SERVICE DESCRIPTION

```

    | BURNING ANTIFREEZE SMELL NOTED FROM EXHAUST
    | SYSTEM. COMBUSTION CHAMBER TO COOLING SYSTEM
    | LEAK SUSPECTED.
    | REMOVE CYLINDER HEAD AND INSPECT.                8.0      544.00
    | FOUND: HEAD CRACKED.
    | REPLACE CYLINDER HEAD.                            6.0      408.00
    | STARTER MOTOR SOUNDS DEFECTIVE.
    | REPLACE DEFECTIVE STARTER.                        0.5       34.00
    | MAKE ESTIMATE TO REPLACE UNIT.
    | COLD START AND WARM-UP PROBLEM NOTED.
    | TEST COLD START SYSTEM AND WARM-UP REGULATOR.
    |
    | LABOUR CHARGES =====> 986.00
  
```

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 963 130	DRAIN SEAL RING	1	0.66	0.66	0.66
11 12 1 254 044	CYLINDER HEAD	1	1080.00	400.00	400.00
11 12 1 257 296	HEAD GASKET SET	1	87.12	87.12	87.12
11 12 1 263 642	VALVE GUIDE	8	12.23	12.23	97.84
11 33 1 271 833	ROCKER ARM	1	21.80	21.80	21.80
11 42 1 278 059	OIL FILTER 4CYL.	1	9.29	9.29	9.29
11 62 1 259 559	FLANGE NUTS (2) 10 MM	3	1.02	1.02	3.06
11 62 1 711 954	COPPER EX NUT	8	1.02	1.02	8.16
12 41 1 355 693	STARTER MOTOR (RMFD)	1	145.77	128.00	128.00
13 51 1 257 035	LINKAGE TII	1	26.18	26.18	26.18
13 51 1 260 343	CONN ROD	1	16.96	16.96	16.96
18 11 1 728 363	EXHAUST FLANGE GASKET	1	4.02	4.02	4.02

CONTINUED TO NEXT PAGE

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 9790
 PAGE # : 2
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 10/14/94

===== CUSTOMER DATA =====+===== CAR DATA =====
 ! BMW Tii
 !

REPAIR ORDER PAGE # 2

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
20/50 GTX	ENGINE OIL	5	2.25	2.25	11.25
ANTIFREEZE	COOLANT	1	8.00	8.00	8.00
PARTS TOTAL =====>					822.34

SUBLET SERVICE DESCRIPTION	SUBLET PRICE
MACHINE CYLINDER HEAD AND VALVES.	220.00
Environmental Charges	3.00
SUBLET TOTAL =====>	223.00

WARRANTY ON PARTS & LABOR
 GOOD FOR 12 MOS. & UNLIMITED
 MILEAGE. EFFECTIVE 10/14/94

PAID

GAS, OIL, GREASE =====>	0.00	SUB-TOTAL =====>	2031.34
CORE CHARGES =====>	0.00	SALES TAX =====>	67.84
MISC. CHARGES =====>	0.00	LESS DEPOSITS =====>	0.00
		===== TOTAL DUE =====>	2099.18

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

*** REPAIR ORDER INVOICE ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT, CA. 94002-

REPAIR ORDER # : 9747
 PAGE # : 1
 WRITTEN BY : MS
 ESTIMATED BY : MS
 DATE PRINTED : 07/13/94

===== CUSTOMER DATA =====+===== CAR DATA =====

! BMW Tii
 ! LICENSE PLATE : TIITAN /CA YEAR: 1973
 ! ENGINE SIZE/TYPE : 2.0 "R"
 ! VIN NUMBER : 2762965
 ! MILEAGE : 3937 PROD.DATE:

DATE IN : 07/11/94 TIME IN : 07:26 DATE DUE : 07/13/94 TIME DUE : 18:00
 CUST.NO. : 3046 DEPOSIT : 0.00 CORE DEP. : 0.00 SUBLT.EST. : 0.00

LABOR ESTIMATE : 34.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 34.00

TECH(S) | SERVICE DESCRIPTION

| CAR TOWED; RIGHT HALF SHAFT NO LONGER ATTACHED TO
 | DIFFERENTIAL; EVALUATE AND REPORT
 | REPLACE FLANGE BOLTS AT DIFFERENTIAL FLANGES 1.0 68.00
 | CHECK FOR NEEDED SERVICE AND REPORT
 | RECOMMEND 12,5 SERVICE
 | NOTE* COOLANT ODOR NOTICED DURING REPAIR; RECOMMEND
 | CHECK SOURCE OF ODOR

LABOR CHARGES =====> 68.00

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 919 652	BOLT	12	2.18	2.18	26.16
07 12 9 922 716	NUT	12	1.08	1.08	12.96
PARTS TOTAL =====>					39.12

PAID

W

GAS, OIL, GREASE ==>	0.00	SUB-TOTAL =====>	107.12
CORE CHARGES =====>	0.00	SALES TAX =====>	3.23
MISC. CHARGES =====>	0.00	LESS DEPOSITS =====>	0.00
		===== TOTAL DUE =====>	<u>110.35</u>

REPAIR ORDER INVOICE

SCHULBA B.M.W. (BELMONT MOTOR WORKS)
415-592-7352
645 HARBOR BLVD.
BELMONT, CA. 94002-

REPAIR ORDER # : 9503
PAGE # : 1
WRITTEN BY : MS
ESTIMATED BY : MS
DATE PRINTED : 04/08/94

=====
===== CUSTOMER DATA =====+===== CAR DATA =====

! BMW Tii
! LICENSE PLATE : TIITAN /CA YEAR: 1973
! ENGINE SIZE/TYPE : 2.0 "R"
! VIN NUMBER : 2762965
! MILEAGE : 100907 PROD.DATE:

=====
DATE IN : 04/05/94 TIME IN : 06:49 DATE DUE : 04/08/94 TIME DUE : 18:00
CUST.NO. : 3046 DEPOSIT : 0.00 CORE DEP.: 0.00 SUBLT.EST. : 0.00

=====
LABOR ESTIMATE : 170.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 170.00

=====
TECH(s) : SERVICE DESCRIPTION

! CAR TOWED; DIED ON FREEWAY, ELECTRICAL SYSTEM		
! COMPLETELY DEAD, TEST & REPORT		
! FOUND! NO OUTPUT FROM ALTERNATOR.		
! MAIN WIRING PLUG AT ALTERNATOR HAS		
! BURNT CONNECTION.		
! ALTERNATOR GRND WIRE WAS DEFECTIVE.		
! REPLACE ALTERNATOR, VOLTAGE REGULATOR, NEGATIVE	0.3	20.40
! ALT. LEAD AND REPAIR HARNESS END.		
!!		
! DIFFICULT STARTING COLD; TEST & REPORT		
! POOR BATTERY POWER COULD ACCOUNT FOR PROBLEM		
! STARTING. ADDITIONALLY THE STARTER IS DEFECTIVE		
! AND CRANKS SLOWLY.		
! RECOMMEND REPLACE STARTER AND TEST AGAIN.		
! ALSO THE COLD START SYSTEM HAS BEEN MODIFIED TO		
! A MANUAL SYSTEM AND MAY NOT BE GETTING THE JOB		
! DONE.		
!!		
! GRINDING SOUND FROM STATER; TEST & ADVISE		
! FOUND! STARTER MOTOR DEFECTIVE.		
!		
	LABOR CHARGES	122.40

PART NUMBER		DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
12 31 1 353 422	Tii	REMANUFACTURED ALTERNATOR EX	1	148.00	148.00	148.00
12 31 1 353 888	Tii	CORE	1	60.00	60.00	60.00
11 72 1 261 404		BUSHING	2	3.48	3.48	6.96

CONTINUED TO NEXT PAGE

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

REPAIR ORDER INVOICE



SCHULBA B.M.W. (BELMONT MOTOR WORKS)
415-592-7352
645 HARBOR BLVD.
BELMONT, CA. 94002-

REPAIR ORDER # : 9503
PAGE # : 2
WRITTEN BY : MS
ESTIMATED BY : MS
DATE PRINTED : 04/08/94

===== CUSTOMER DATA =====+===== CAR DATA =====
: BMW Tii
=====!

REPAIR ORDER PAGE # 2

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
12 32 1 350 052	EXTERNAL VOLTAGE REGULATOR	1	69.80	69.80	69.80
PARTS TOTAL =====>					284.76



GAS, OIL, GREASE ==> 0.00
CORE CHARGES =====> 0.00
MISC. CHARGES =====> 0.00

SUB-TOTAL =====> 407.16
SALES TAX =====> 23.49
LESS DEPOSITS =====> 0.00
===== TOTAL DUE =====> 430.65

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

*** R E P A I R O R D E R I N V O I C E ***

SCHULBA B.M.W.(BELMONT MOTOR WORKS)
 415-592-7352
 645 HARBOR BLVD.
 BELMONT,CA.94002-

REPAIR ORDER # : 9114
 PAGE # : 1
 WRITTEN BY : GS
 ESTIMATED BY : GS
 DATE PRINTED : 11/06/93

===== CUSTOMER DATA =====+===== CAR DATA =====

PARTS SALE CASH : BMW
 : LICENSE PLATE : xxxxxxxx/xx YEAR:
 : ENGINE SIZE/TYPE : " "
 : VIN NUMBER :
 : MILEAGE : 999999 PROD.DATE:

DATE IN : 11/06/93 TIME IN : 14:01 DATE DUE : 11/06/93 TIME DUE : 18:00
 CUST.NO.: 3062 DEPOSIT : 0.00 CORE DEP.: 0.00 SUBLT.EST.: 0.00

LABOR ESTIMATE : 0.00 PARTS ESTIMATE : 0.00 ESTIMATE TOTAL : 0.00

TECH(S) :SERVICE DESCRIPTION

:PARTS SALE :
 : LABOR CHARGES =====> 0.00

PART NUMBER	DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
07 11 9 978 227	BULB, 5W	2	1.26	1.26	2.52
07 11 9 978 370	LIGHT BULB	1	1.25	1.25	1.25
12 12 1 360 603	SPARK PLUG WIRE SET	1	47.51	29.80	29.80
61 66 1 357 570	W/W PUMP	1	55.00	55.00	55.00
PARTS TOTAL =====>					88.57

PAID

GAS, OIL, GREASE ==>	0.00	SUB-TOTAL =====>	88.57	
CORE CHARGES =====>	0.00	SALES TAX =====>	7.31	
MISC. CHARGES =====>	0.00	LESS DEPOSITS =====>	0.00	
=====			TOTAL DUE =====>	<u>95.88</u>

CALIFORNIA B.A.R. REGISTERED #AB123112 123112

*** R E P A I R O R D E R ***

SCHULBA B.M.W. (BELMONT MOTOR WORKS)

415-592-7352

645 HARBOR BLVD.

BELMONT, CA, 94002-

REPAIR ORDER # : 8958

PAGE # : 1

WRITTEN BY : GS

ESTIMATED BY : GS

DATE PRINTED : 09/20/93

----- CUSTOMER DATA -----

----- CAR DATA -----

BMW Tii

LICENSE PLATE : TIITAN /CA YEAR: 1973

ENGINE SIZE/TYPE : 2.0 "R"

VIN NUMBER : 2762965

MILEAGE : 94612 PROD. DATE:

DATE IN : 09/18/93 TIME IN : 10:09 DATE DUE : 09/20/93 TIME DUE : 18:00
 CUST. NO. : 3046 DEPOSIT : 0.00 CORE DEP. : 0.00 SUBLT. EST. : 0.00

LABOR ESTIMATE : 97.50 PARTS ESTIMATE : 7.00 ESTIMATE TOTAL : 104.50

TECH SERVICE DESCRIPTION

ENGINE NOT PERFORMING WELL CHECK AND REPORT.
 RECOMMEND TUNE ENGINE ADJUST VALVES.
 TUNE ENGINE ADJUST VALVES. 2.0 130.00

REPLACE EXHAUST MANIFOLD GASKETS (SEE GERRY FIRST)
 CALL WITH ESTIMATE.
 FOUND: MANIFOLD NOT LEAKING AT THIS TIME.
 TIGHTEN MANIFOLD BOLTS 0.2 13.00

CHECK BATTERY AND CHARGING SYSTEM. CAR SAT FOR ONE
 YEAR AND THE LIGHTS GROW DIM AND BRIGHT WHEN
 DRIVING.
 FOUND: CHARGING SYSTEM OUTPUT CORRECT. NO DEFECT
 NOTED.
 CERTIFY FOR SMOG (BIENNIAL) 0.5 32.50

LABOR CHARGES =====> 201.50

PART NUMBER	PART DESCRIPTION	QTY.	RETAIL	SELL PR.	TOTAL
11 12 1 734 030	V/C GASKET	1	12.92	12.92	12.92
12 11 1 267 393	IGNITION POINTS	1	5.84	5.84	5.84
12 12 1 262 360	SPARK PLUG	4	3.26	3.26	13.04
PARTS TOTAL =====>					31.80

PAID
B/C

GAS, OIL, GREASE ==>	0.00	SUB-TOTAL =====>	233.30
CORE CHARGES =====>	0.00	SALES TAX =====>	2.62
MISC. CHARGES =====>	7.00	LESS DEPOSITS =====>	0.00
		TOTAL DUE ----->	<u>242.92</u>

CALIFORNIA B.A.R. REGISTERED #AB123112 123112


BAVARIAN AUTOTECH'S

Specializing Exclusively in BMW

551 S. RAYMOND AVE. • FULLERTON, CA 92631
(714) 870-4450 B.A.R. LICENSE #AE-124809

DATE 11/16/90

YEAR	MAKE BMW
MODEL 2002 TL	LICENSE NO. TL/TAN
TIME PROMISED	
A.M. P.M.	
WRITTEN BY MAOZIA	RESIDENCE PHONE
ZIP CODE	BUSINESS PHONE EXT.



SERIAL NUMBER _____ MILEAGE 86502

AUTOTECH'S
 NOV 16 1990
 X 75.00

MECH. NO.	REPAIR ORDER-LABOR INSTRUCTIONS	DATE	TIME
	SET CO TO PASS SMOG	N/C	
	REPLACE BATTERY	11	25

QTS. OIL @ _____
 PTS. GEAR OIL @ _____
 QTS. AUTO TRANS. FLUID @ _____
 ALL PARTS INSTALLED ARE NEW
 UNLESS SPECIFIED OTHERWISE

P.O. NO. _____ SUBLET REPAIRS _____ CUST. INITIAL _____

ORIGINAL ESTIMATE \$	REVISED ESTIMATE \$	2nd REVISED ESTIMATE \$	CONTACTED VIA: <input type="checkbox"/> IN PERSON <input type="checkbox"/> PHONE NO.	DATE
PERSON CONTACTED _____			CONTACTED BY _____	TIME _____ A.M. / P.M.

Six months/6,000 mile guarantee of labor:
 Such guarantee is for six (6) months after performance of the service or until the vehicle has been driven 6,000 miles, whichever comes first. BAVARIAN * AUTOTECH'S is not responsible for damages or malfunctions resulting from (1) accidents, misuse, negligence or alterations by others; (2) use of the vehicle in competitive events; or (3) failure to follow recommended maintenance or other requirements. The above warranty of labor is in lieu of all other express or implied warranties and that the customer agrees that his sole and exclusive remedy for breach of such express warranty regarding labor shall be repair, replacement or, at the option of BAVARIAN * AUTOTECH'S, refund of the purchase price.

NOTE: NO WARRANTY ON SUBLET REPAIRS.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection.

**SUBJECT TO THE CONDITIONS ON THE REVERSE SIDE
 CUSTOMER ACKNOWLEDGES READING SAID CONDITIONS
 AND RECEIVING A COPY OF THIS WORK ORDER.**

X _____ CUSTOMER SIGNATURE	_____ AUTHORIZED CREDIT CARD <input type="checkbox"/> NO CHECKS <input type="checkbox"/>
TERMS: CASH <input type="checkbox"/>	PARTS TO BE RETURNED TO CUSTOMER? <input type="checkbox"/> YES <input type="checkbox"/> NO

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller, BAVARIAN * AUTOTECH'S, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and BAVARIAN * AUTOTECH'S, neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Buyer shall not be entitled to recover from the seller any consequential damages, damages to property, damage for loss of use, loss of time, loss of profit or income, or any other incidental damages.	MECHANICAL LABOR <u>11 25</u> PARTS <u>60.00</u> GAS & OIL _____ SUBLET _____ ACCESSORIES _____ SALES TAX <u>3 75</u> TOTAL AMOUNT <u>75.00</u>
---	--

PARTS INSTALLED ARE NEW UNLESS SPECIFIED OTHERWISE

*CODE N-NEW U-USED R-REBUILT

BAVARIAN RENNSPORT
 5354 Banks Street - Phone (619) 296-0573
 San Diego, California 92110
 BAR No. AK 120710

011151

REPAIR ORDER

QTY.	* PART NO. OR DESCRIPTION	SALE AMOUNT
N	valves (intake-exhaust)	
N	valve stem seals	
N	valve guides	
N	valve springs and retainers	
N	rocker shafts	
N	rocker arms and parts	
N	engine gasket set	
N	camshaft seal	
N	timing chain	
N	tensioner spring	
N	connecting rod bushings	
N	pistons (mahle)	
N	piston rings (revel)	
N	timing chain rails (Ford)	
N	main and rod bearing set	
N	fuel injectors (out)	
N	R+K Fuel Block	
N	Set to euro specs.	
N	Sachs clutch pressure plate disc/throwout bearings	
TOTAL PARTS		
OUTSIDE-SUBLET REPAIRS		
	Block to motor works	
	Balance pressed	
	Balance pist red line	
	Camshaft to schrick	
TOTAL SUBLET REPAIRS		350.00
FOLLOWING REPAIRS RECOMMENDED		

Bill

NAME: [Redacted]

ADDRESS: [Redacted]

CITY: [Redacted]

Phone: [Redacted]

RES. BUS. 566-6013 73 BMW 2002 Tii

VEH. I.D. # 2762965

MILEAGE 81,600 LIC. # TII TAN MOTOR #

TIME REC'D A.M. P.M. TIME PROM. A.M. P.M. GROSS VEH. WT. ORD. WRITTEN BY Skip CUST. ORDER NO.

OPER. NO. **REPAIR ORDER - DESCRIPTION OF WORK**

Complete Rennsport package

PAID CASH 1-1490

LABOR CHARGE PER HR.

MAINTENANCE INSPECTION	<input type="checkbox"/>
LUBRICATION	<input type="checkbox"/>
CHANGE OIL GRADE	<input type="checkbox"/>
CHANGE OIL FILTER CART.	<input type="checkbox"/>
TRANS.	<input type="checkbox"/>
DIFF.	<input type="checkbox"/>
ROTATE TIRES	<input type="checkbox"/>
ALIGN FRONT END	<input type="checkbox"/>
	<input type="checkbox"/>

ORIGINAL ESTIMATE \$	DATE	TIME	BY	TOTAL LABOR	1000
REVISED ESTIMATE \$	DATE	TIME	BY	TOTAL PARTS	1600
REVISED ESTIMATE \$	DATE	TIME	BY	GAS, OIL, GREASE	
I acknowledge notice and oral approval of an increase in the original estimated price.				HAZARDOUS WASTE DISPOSAL	
Tel. _____ Best time to call _____				SUBLET REPAIRS	
Replaced parts requested by customer YES <input type="checkbox"/> NO <input type="checkbox"/>				SMOG CERTIFICATE	
I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read and understand the above and acknowledge receipt of an estimate. "BY LAW, YOU MAY CHOOSE ANOTHER FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS WHICH THE SMOG CHECK TEST INDICATES ARE NECESSARY."				SHOP SUPPLIES	
				TAX	2600
X				PAY THIS AMOUNT	2756.00

TERMS ARE CASH UNLESS OTHER PRIOR ARRANGEMENTS ARE MADE
SEE IMPORTANT INFORMATION ON BACK

CASH CHECK CHARGE CREDIT CARD

INTEREST WILL BE CHARGED AT A RATE OF 1 1/2% PER MONTH ON ACCOUNTS OVER 30 DAYS. THANK YOU



5354 Banks St. • San Diego California 92148 • B.A.D. Reg #AHR1205 • 296-0573
 YEAR 73 NAME _____
 Model Li Address _____
 Mileage 63791299 PHONE _____ BUSINESS 566 603

Chassis # _____
 License # _____
 DATE Oct 588

- Oil & Filter
- Differential
- TRANSMISSION

_____ qts oil @ _____
3 pts gear oil @ 900
 _____ pts hypoid @ _____
2 pts brake fluid @ 500
 Total oil & gas 1400

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle in case of fire, theft, accident or any other cause beyond your control. Some work is sublet at our discretion.

Signature _____ Due Date _____
 Estimate 1100.00 1:30pm New Estimate _____
10-11-88 (W) Called ok _____

QUAN.	PART # Description	
1	bearing set	71 97
4	syncros	170 08
1	gasket set	28 43
1	brake master	97 50
1	m booster hose	18 46
2	Washers	1 10
1	Shaft 13511252035	14 17
1	rod 35111107363	15 42
1	pump to tube hose	14 49
1	tube	25 06
1	heater return hose	5 52
1	heater feed	7 12
	valve	2 23
1	bell crank	
1/2	meter fuel hose	12 50
6	# 13 clamp	5 4
12	hose clamp	14 40
4	anti freeze	3 50
1	Therm. 71°	20 25
1	pump to tube hose	6 57
1	dust coat	1 20
16	lug nuts	40 48
	35111107 363	17 51
TOTAL PARTS		518 17

Description	Labor
R+R trans - overhaul	
Overhaul trans	400 00
install fuel hoses, h2 hoses, clean heater valve	
tubing manifold , R+R radiator	154 10
brake master cyl	} 69 00
purge	

PD MCH 5537531
 (W)
 Oct 12 88

Sublet Labor ... WE RECOMMEND THE FOLLOWING REPAIRS:			Total Labor
C+R radiator	72	50	653 00
			TOTAL Sublet 42 50
			TOTAL PARTS 518 17
			TOTAL GAS
			TOTAL OIL
			Sub Total
			Tax 35 15
			TOTAL DUE 1252 16
TOTAL Sublet			

9416 PARTS

Mike



5354 Banks St. • San Diego, California 92116 • B.A.P. Reg #AH81205 • 206-0573

YEAR 73 NAME [redacted]

Model 2002ti Address _____

MILEAGE 80015 PHONE _____ BUSINESS _____

I hereby authorize the repair work to be done along with necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on vehicle to secure the amount of repairs here to. You will not be held responsible for loss or damage to vehicle in case of fire, theft, accident or any other cause beyond your control. Some work is sublet at our discretion.

SIGNATURE _____ DUE DATE _____

ESTIMATE 17500 NEW ESTIMATE _____

Called ok _____

Chassis # _____

LICENSE # TITAN
DATE 9-20-88

OIL & FILTER

DIFFERENTIAL

TRANSMISSION

___ qts oil @ _____

___ pts gear oil @ _____

___ pts hypoid @ _____

___ pts brake fluid @ _____

Total oil & gas _____

QUAN.	PART #	DESCRIPTION	
1		water pump	5715
1		gasket	71
1		gal antifreeze	700
1		pulley	1000
1		alt belt	536
1		filter	28
1		Hood Emblem	1270
1		10cm	540
			2000
			51
			2141
			20636
			24557
			52787
			218
TOTAL PARTS			8022

DESCRIPTION	LABOR
Replace water pump	
rearrange hoses	
Install starter bracket (part on seat)	
clean fuel screen	
✓drive line - exhaust	
air fuel mixture - suction valves 3 & 4	
Replace crankshaft pulley	
suspension lopsided	
13800	

PDm (# 52787)
②
9218

SUBLET LABOR ...We Recommend the Following Repairs:		TOTAL LABOR	13800
		TOTAL SUBLET	8097
		TOTAL PARTS	8022
		TOTAL GAS	
		TOTAL OIL	22097
		Sub Total	21812
		TAX	539
		TOTAL DUE	22351
Total Sublet			226.36

from Carl
mirror spacer
innir front seat adj.
door seals (both)

9378 PARTS

QUAN.	Part #	Description		
2		lower control arms	60	00
2		strut rod bushings	8	74
4		" " washers	2	50
8		cotter pins	2	40
3		spring pads	8	40
2		Shock tower mts	105	76
1		sway bar	70	00

Bill



5354 Banks St. • San Diego, California 92110 • B.A.R. Reg. #AH81205 • 296-0573

YEAR 73 NAME _____
 Model 2002411 Address _____
 Mileage 79,541 PHONE _____ BUSINESS _____

Chassis # _____

License # _____
 DATE 9-6-88

- OIL & FILTER
- DIFFERENTIAL
- TRANSMISSION

___ qts oil @ _____
 ___ pts gear oil @ _____
 ___ pts hypoid @ _____
 ___ pts brake fluid @ _____

Total oil & gas _____

I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. SOME WORK IS SUBLET AT OUR DISCRETION.

SIGNATURE [Signature] DUE DATE _____

ESTIMATE _____ NEW ESTIMATE 830.00

Called ok (W) 5/17/88

Description	Labor
install install strut rod bushings	22 00
R & R - shocks (in trunk) (strut mts if needed)	88 00
- springs (in trunk)	
R & R - lower control arms	88 00
- outer tie rod end, left side	
- ball joints (in trunk)	
- ✓ brake master cylinder	
- ✓ steering box	
- a alignment	22 00
1 SSES	

paid visa #5837811
 9-9-88

SUBLET LABOR ...WE RECOMMEND THE FOLLOWING REPAIRS:

grease chisel rod !!

TOTAL LABOR	220 00
TOTAL SUBLET	
TOTAL PARTS	257 86
TOTAL GAS	
TOTAL OIL	
Sub Total	477 86
Tax	16 76
TOTAL DUE	494 62

TOTAL PARTS 257 86

TOTAL SUBLET

MIAH, INC.

2659 N.E. DIXIE HWY.
JENSEN BEACH, FLORIDA 33457

INVOICE

INVOICE NUMBER 44288
 INVOICE DATE 08/24/88
 SOLD BY RHO
 PAGE 0

CARD 4226857647983
 EXPIRES 2/89
 AUTH
 YOUR ORDER NO. 202475
 DATE SHIPPED 08/24/88

SHIP VIA UPS

SOLD TO

MC/VISA	CASH	C.O.D.	AMEX	CHECK/M.O.	CHARGE	OTHER	ZONE	LBS.
*****							8	21

QUANTITY	DESCRIPTION	PRICE	AMOUNT
2	P30023 BMW 2002 *4*	83.40	166.80
2	B46803 BMW 2002 *4*	53.40	106.80
0	S020F/R BMW 2002 ALL *3*	184.40	.00
1 of the above Items are on order for you			
Sub-Total.....			273.60
SHIPPING & HANDLING.....			14.16
INSURANCE.....			1.50
TOTAL AMOUNT DUE >>>>>>>>			289.26
<p><i>Suspension Techniques Springs</i> <i>Shocks Springs Bilstein shocks & Struts</i></p>			

MIAH RETURN/EXCHANGE POLICY

No purchase may be returned or exchanged without prior permission. A 20% restocking charge may be made on all returns unless, in the sole opinion of seller, such merchandise is defective. All returns must be returned prepaid and be accompanied by a copy of your invoice, your daytime telephone number and the reason for the return. No returns will be accepted after 45 days from the date of the invoice.

CUSTOMER



**FOREIGN
AUTO
SUPPLY**

11
810 ISLAND STREET
SAN DIEGO, CA 92101
234-7254

13
380 E STREET
CHULA VISTA, CA 92010
420-7200

15
4690 CONVOY STREET
SAN DIEGO, CA 92111
292-5315

17
5476 EL CAJON BLVD.
SAN DIEGO, CA 92115
286-7250

12
1302 BROADWAY
EL CAJON, CA 92020
442-0461

14
1080 GARNET
PACIFIC BEACH, CA 92109
272-6730

16
505 N. BROADWAY
ESCONDIDO, CA 92025
741-1321

TERMS AND CONDITIONS
1. NO RETURN OF ELECTRICAL PARTS
2. NO RETURNS WITHOUT THIS INVOICE
3. NO RETURN OF SPECIAL ORDERS
4. 10% CHARGE ON ALL RETURNS

STORE NO. **#15 KEARNY MESA**

SATURDAY DELIVERIES NOW AVAILABLE!

STORE HOURS: MON-FRI 8:00-5:30, SAT 8:00-4:00, SUN 9:00-4:00

ASK ABOUT OUR PREFERRED CUSTOMER DISCOUNT CARDS TODAY!

CUSTOMER

STEVE
73 2002TII
TUNE UP PARTS

CUSTOMER # 915.000 CASH INVOICE #546668
CUST PO #
RESALE #:
CODES: CSH SD
DATE: 07/09/88

PAGE 1 OF 1 50

QUANTITY	LINE	PART NUMBER	DESCRIPTION	CORE	LIST EA.	YOUR COST	EXTENSION	TAX	
1	BOS 01-011		CONT SET		3.10	2.02	2.02	Y	
4	BOS W7DC		BOSCH PLUG		1.65	1.11	4.44	Y	
1	9B0 *09-012		BOSCH WIRES		36.12	23.48	23.48	Y	
1	9BA *036-0768		V/C GASKET		9.38	6.17	6.17	Y	
1	BOS 03-010		DISTR CAP		8.98	5.84	5.84	Y	
1	BOS 04-033		ROTOR		4.82	3.13	3.13	Y	
1	04 043-0116		FUEL FILTER		20.86	13.71	13.71	Y	
1	08 081-0093		BRAKE SHOES	6.00	19.01	12.49	18.49	Y	
1	08 087-0092		BRAKE PADS		35.46	23.30	23.30	Y	
12				6.00			100.58	6.54	
TOTAL UNITS		FREIGHT	LABOR	MISC.	CORE TOTAL	LIST TOTAL	NON TAXABLE	TAXABLE	TOTAL TAX

*** PAID CASH ***

13:04

RECEIVED BY: X

PAY THIS AMOUNT 107.12

BARON'S
8008 MIRAMAR ROAD STE E SAN DIEGO CA 92126
619 578-2800
FOR THE SERVICING OF BMW & MERCEDES-BENZ

CUSTOMER
ADDRESS
CITY/ST.
ZIP CODE
YR/MODEL/MAKE 1973 2002TII BMW
CHASSIS NO. 2762965

MILEAGE 78472
LICENSE NO. YNKEROZ
WORK PHONE
HOME PHONE
ENGINE NO.

R.O. NO. 1105 OF EST. NO. 146

ORIGINAL B.A.R. # AM099312 DATE 07-07-1988

LABOR COMPLETED


DESCRIPTION	EMP	TOTAL
BMW IGN. SWITCH (REPLACE) 2002	CD	126.00
Includes: remove all parts required to access ign. lock remove break away bolts & replace ign. lock & switch		

MATERIALS ISSUED

QTY	PART NUMBER	DESCRIPTION	EACH	TOTAL
1	BMW32-32-1-109-001	LOCK ASSEMBLY	74.90	74.90
1	BMW13-72-1-255-000	BELLOW	13.63	13.63
2	BMW51-21-1-809-735	DOOR LATCH BUFFER	0.88	1.76

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE.
*COMMENTS: needs check out car for buyer!!

QTY	GAS & OIL	PRICE	TOTAL LABOR	126.00
	GASOLINE	0.00	TOTAL MATERIALS	90.29
0	QTS. OIL @ 1.65	0.00	TOTAL GAS & OIL	0.00
0	TRANS. OIL @ 1.85	0.00	SUBLET LABOR	0.00
0	GEAR FLUID @ 3.70	0.00	OTHER	0.00
	GREASE	0.00	SHOP SUPPLIES	4.33
			SUBTOTAL	220.62
			TAX	6.15
TOTAL GAS & OIL	\$ 0.00		** TOTAL DUE **	\$ 226.77

QTY.	PART NO. AND DESCRIPTION	PRICE
1	Front / lower BALL joint.	18 75
		
TOTAL PARTS		18 75

AUTOBAHN MOTORS
 9555 Black Mountain Rd. Suite D
 SAN DIEGO, CA 92126
 (619) 530-2993
 Bar Reg. #AC-131162

1682

NAME		CUSTOMER'S ORDER NO.	DATE
ADDRESS		PHONE	PROMISED
CITY		ORDER WRITTEN BY	A.M. P.M.
YEAR, MAKE AND MODEL	SERIAL NUMBER	LICENSE NUMBER	TERMS
73 2002 T11		PAKE 202	
	MOTOR NUMBER	ODOMETER	

DESCRIPTION OF WORK	AMOUNT
LUBE <input type="checkbox"/> CHANGE OIL <input type="checkbox"/> FILTER <input type="checkbox"/> TUNE-UP <input type="checkbox"/> TRANSMISSION <input type="checkbox"/> DIFFERENTIAL <input type="checkbox"/>	
R & R Front / Right BALL joint.	\$ 45 -

ESTIMATED COSTS			TOTAL LABOR	45 -
PARTS	LABOR	TOTAL	TOTAL PARTS	18 75
19	45 -		LUBE	
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.			GASOLINE	
			OIL	
			OUTSIDE REPAIRS	63 75
SIGNATURE			TAX	1 20
[Signature] <input type="checkbox"/> RETURN PARTS <input type="checkbox"/> DISCARD PARTS			Thank You	64 95
REVISED ESTIMATE/ADDITIONAL WORK			TOTAL	64 95
PARTS	LABOR	TOTAL		
AUTHORIZED BY				
DATE	TIME	CALLED BY	PHONE NUMBER	

PRODUCT 6844 (REVISED) 1-800-275-4300
 In Order PHONE TOLL FREE 1-800-275-4300