

5% upon receipt/net 15

Please return top portion with payment.

		1	/EHICLE
		1971 Maserat	i Ghibli Coupe
QTY/HRS	DESCRIPTION	COST	AMOUNT
	PARTS		
1	OIL FILTER.	14.50	44.50
13	OIL, VALVOLINE 20W50	4.50	14.50
2	ANTIFREEZE	9.50	58.50
1	FUEL FILTER.	5.90	19.00
2	BRAKE FLUID, CASTROL LMA	17.50	5.90
2	HOSE CLAMPS	0.00	35.00
1	BRAKE CLEAN	3.90	0.00
1	ASST ASSEMBLY SUPPLIES/MATERIALS (74.5hrs@2.50)	186.25	3.90
1	ASSTUPHOLSTERY SUPPLIES/MATERIALS (8 5hrsy5 00)	42.50	186.25
1	BULB, nead lamp	25.10	42.50
1	REPAIR KIT, fuel pipe	18.92	25.10
1	GASKET, exhaust	8.27	18.92
2	SWITCHES, toggle	9.46	8.27
1	RADIATOR CAP	9.12	18.92 9.12
1	STEREO/CD UNIT	348.60	348.60
	BRAKE PAD SET, rear	120.00	120.00
1	BRAKE PAD SET, frt	119.00	119.00
1	AIR FILTER	16.29	The state of the s
	FUEL	24.00	16.29 24.00
1 2	FUEL, more	28.00	28.00
2	FT STEEL ROD	20.19	40.38

TOTAL DUE



5% upon receipt/net 15

Please return top portion with payment.

		V	EHICLE
		1971 Maserat	i Ghibli Coupe
QTY/HRS	DESCRIPTION	COST	AMOUNT
1	SWITCH, battery used	15.00	
1	SWITCH, turn signal	421.25	15.00
1	REGULATOR	57.97	421.25 57.97
	LABOR		
	WORK PERFORMED 9/1/05 TO 9/29/05		
	MECHANICAL/ASSEMBLY		
	Evaluate vehicle/Review customer list Access air filter housing (inner set		
- 18	render). Cridinge engine oil and filter Remove fuel filter close hour Flush		
	brake fluid, Clutch fluid. Replace filel filter Research correct oir filter		
	order and install. Drain radiator, flush refill with fresh coolant. Programs		
	test cooling system, order new cap install Change room and and		
	transmission fluid. Remove brake rotors frt/rear. Disassemble, close		
	inspect and pack wheel bearings. Install new hose at water nume.		
	all beits. Ilistall front and rear rotors caliners brake pade 1 the character		
	dive trail. Nellistali alla torque rear wheels Diagnoss Donoir side turn		
	ramp grounds. Repair Steering column tele lock nut and install. Tighter		
	Steeling wheel till mechanism. Remove tires for balance NOTE		
	spare IIII, lepail. Diagnose rear end leak clean area. Defitb. al-		
	install flew wiper relills. Lest heating system (works which on line)		
	motal license plate. Check gauges and lights (clock intermittent)		
	Fabricate new seat adjuster lever and install. Weld broken seat spring tabs		

TOTAL DUE



5% upon receipt/net 15

Please return top portion with payment.

			VEHICLE		
		1971 Mase	erati Ghibli Coupe		
QTY/HRS	DESCRIPTION	COST	AMOUNT		
74.5	as necessary. Deliver rotor for spacer machine work (hub clearance), install fabricated spacers, install wheels. Road test, note rubbing in front end. Remove center console, radio, install and reassemble. Remove pass seat to adjust handle, adjust. Modify seat tracks, lube reassemble seat. Replace battery switch w/good/used. Remove passenger door window assy, to inspect, window gear transmission cracked, repair/refit. Road test and repair items noted, discuss with customer. Disassemble steering column, fit/modify replacement switch (make 1 good out of 2 replacement not exact). Diagnose and repair fog light. Replace HL bulbs, lens. Adjust brake pedal. Mask dash legend. Replace speakers. Make duplicate keys. Remove radiator, paint, replace. Misc items per list.				
74.0	UPHOLSTERY	70.00	5,215.00		
8.5	Remove seats, disassemble seat bases. Replace webbing. Cut, fit and reshape pads. Disassemble leather from frames, prep for weld. Install 1" foam topping, reassemble. HOURS				
		70.00	595.00		
3.25	COLLECTOR SERVICES Deliver vehicle to DMV for inspection, register, WAIT. HOURS				
		70.00	227.50		

TOTAL DUE



5% upon receipt/net 15

Please return top portion with payment.

		V	/EHICLE
OTI (II II a		1971 Maserat	i Ghibli Coupe
QTY/HRS	DESCRIPTION	COST	AMOUNT
1.75	Clean and delivery prep.	50.00	87.50
4 2 1	SUBLET RESURFACE ROTORS MACHINE ALUM SPACERS, wheels REPAIR/FLUSH/TEST RADIATOR, REPLACE PETCOCK, REPAIR TOP TANK AND BKTS. CT Sales Tax	22.50 110.00 145.00 6.00%	90.00 220.00 145.00 492.98

TOTAL DUE

\$8,709.35

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

pord



DATE 10/20/2005

NVOICE# WS71M-02

5% upon receipt/net 15

Please return top portion with payment.

VEHICLE		
1971 Maserati Ghibli Coupe		
QTY/HRS DESCRIPTION	COST	AMOUNT
PARTS OWNER OPERATOR MANUAL FREIGHT, manual POWER WINDOW DRIVE GEAR, late receipt KEY BLANKS LABOR WORK PERFORMED 9/27/05 TO 10/29/05 MECHANICAL, late time sheets Match, fabricate hoses to replace upper and lower radiator hoses, install and refill coolant. HOURS	93.00 12.50 125.00 22.50	93.00 12.50 125.00 45.00
ASSEMBLY Source key blanks. Make dash legend for customer to have until owners manual arrives. Take keys and have 2 copies of each made. HOURS SUBLET DUPLICATE KEYS, from blanks	70.00	105.00 122.50 24.00

TOTAL DUE



DATE 10/20/2005

NVOICE# WS71M-02

5% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Bill, Most of this relates to work done on previous invoice. Last minute manual, late receipt, late time sheet hence this bill. Apologies, Best, Kent. CT Sales Tax	6.00%	31.62

TOTAL DUE

\$558.62

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

Page 2 17/14/05
AMER

> 547.44 gh 290

AUTOMOTIVE RESTORATIONS, INC. • 1785 Barnum Ave., Stratford, Connecticut 06614 • (203) 377-6745 • Fax (203) 396 0490



12/29/2005

INVOICE# WS71M-03

5% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1 1 1 1 3	PARTS ASST MECHANICAL SUPPLIES (21.5hrs@2.50) LOW OIL PRESSURE SENDER, for warning light OIL PRESSURE SENDER PINION SEAL GASKET, pinion seal GEAR OIL, PENNZOIL 80W90 LABOR WORK PERFORMED 12/1/05 TO 12/29/05 MECHANICAL	53.75 54.30 94.00 50.60 4.00 6.50	53.75 54.30 94.00 50.60 4.00 19.50

TOTAL DUE



12/29/2005

INVOICE#

WS71M-03

5% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
21.5	Access oil pressure switch to hookup mechanical gauge and check hot oil pressure. Pressure OK 80psi+ when hot, parts ordered. Remove clock, send for repair. Check choke operation, poor start, cold. Note frozen choke pistons on rear carb. Disassemble freeup, reassemble. Check operation OK. Check for no fog lights. Trace wiring, note bad relay ground, repair as needed, test OK. Adjust e-brake. Check rear axle leak, order seals needed. Check air horn inop, note compressor stuck, remove, clean, freeup, lube. Install new oil pressure sender and warning light switch, test OK. Reinstall air filter and related parts. Remove, replace pinion seal and diff cover gasket. Refill diff. Start to disassemble turn signal switch to attempt repair, unrepairable. Advise customer. Remove right seat, repair broken seat adjuster, install. Misc items per list. Job Not Complete, Progress Invoice. HOURS CT Sales Tax	70.00 6.00%	1,505.00 106.87

TOTAL DUE

\$1,888.02

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

Page 2

PD 3/8

ofter 290

Television		-	_		THE OWNER OF THE OWNER OF THE OWNER, THE OWN		
QTY.	PART NO. AND DESCRIPTION	. PR	ICE			RESTORATION &	& PERI
	Text Caliber 10:+	125	00	120	00	RPIVI MOTO	R CAR
9	2 Front Broke hose set	45		100		((((00)))) 462 IVIO	
1	reachicke hose	33	00	29		Ph /Fav (80	
1	Front Windshield Seal	400	00	380		NAME	
			00			IAD	
	oil pressure sender	80	60	76		-	
2 (1	E-Brake Pad Set	100	00	95	00		
20ft		1,50	1		00	HO	
7	hose clamps	4.00	lau	28	00	YEAR, MAKE AND MODEL	
	MSD ingition control	200	00	185	00		55
11	MSD Blaster (Gil	65	00	60	00	SEHIAL NUMBER MOTOR	NUMBER
1	MSD tach adapter	57	00	50	00	DESCRIPTION OF	WORK
156				10		LUBE CHANGE OIL OIL FILTER	TUNE-L
15Ft				10		- Pulled wind shidd cleaned	
1	weather proof GM style connect			5	00		Switz
i	By Is I	or		-	00	- Diagnosed electrical prob	de a.
1,	COIL DISCRET	19		20	coc i		() 10
1	intection brub diapherens	18ez		64	00	MSD unit, tested Dist +	Adjus
	Misc hardware					- replaced all Brake bases	.
						- replaced of pressure sen	Var 5
						- replaced all subber full h	CSES
						- Eixel & Ily A/C Switch	
1						- installed Clock	
(MAY BE CON	TINUED ON OTHER SIDE) TOTAL PARTS					LITERS/GALS. OF GAS @	
	ACCESSORIES					LITERS/QTS. OF OIL @	
	- clesded + Adusted saylos	5 hr				kg/LBS. OF GREASE @	المال
	3777						70
						I hereby authorize the above repair work to be done along with the	
						necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure	
	4			-	- 1	the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars	
						in case of fire, theft or any other cause beyond your control. SAVE OLD PARTS? YES NO	
	TOTAL ACCESSORIES					SAVE OLD PARTS? YES NO	
					5	SIGNATURE	



1/31/2006

INVOICE#

WS71M-04

5% upon receipt/net 15

Please return top portion with payment.

VEHICLE

1971 Maserati Ghibli Coupe #AM115492248

QTY/HRS	270027-10 Child Coupe #AMT 15492248		
4,17,1110	DESCRIPTION	COST	AMOUNT
14.5 1 1	PARTS HRS, ASST MECHANICAL SUPPLIES GROUP SWITCH (universal) FUEL	2.50 950.55 40.00	36.25 950.55 40.00
14.5	LABOR WORK PERFORMED 12/29/05 TO 2/2/06 MECHANICAL Install new combo switch (turn signal, head light, wiper). Modify switch and housing as needed to fit (universal update parts supplied). Fabricate brackets necessary and install washer button and interior light switch (new switch missing built in function). Reinstall repaired clock and related parts, test OK.		
	COLLECTOR SERVICES	75.00	1,087.50
1.5	Clean and delivery prep.	50.00	75.00
	SUBLET	50.00	75.00
1 1	REPAIR CLOCK (burnt out movement) FREIGHT, switch CT Sales Tax	385.00 23.49 6.00%	385.00 23.49 155.87

TOTAL DUE



3/30/2006

INVOICE# WS71M-05

2% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
34.5 1 1 1 1	PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS PRIMARY WIRE SET HEADLAMP SWITCH CIRCUIT BREAKER SET WIRES, OEM CODES/COLORS, needed quantity only	3.00 70.42 76.58 18.25 116.15	103.50 70.42 76.58 18.25 116.15
24.5	WORK PERFORMED 3/6/06 TO 3/30/06 MECHANICAL Inspect per customer complaint, discharging. Disassemble dash and wiring, trace source of short circuit and needed repairs. Headlight motor caused short. Disassemble and repair shorted brush. Repair insulation, reference #. Cut apart burned wiring harness trace wires and order replacement wiring as necessary. Remove burned wires and replace with new matching color codes as original. Test system after repairs. Install circuit breaker on feed circuit to protect harness from short circuits. Reassemble dash. Test all circuits, OK. Job Not Complete.		
34.5	HOURS SUBLET	75.00	2,587.50
15	TOW CHARGE, from Westport to Stratford shop LOAD CHARGE CT Sales Tax	3.75 50.00 6.00%	56.25 50.00 184.72

TOTAL DUE

\$3,263.37

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

MD 51, 43308.48 = \$3198.10 36

AUTOMOTIVE RESTORATIONS, INC. • 1785 Barnum Ave., Stratford, Connecticut 06614 • (203) 377-6745 • Fax (203) 386-0486



4/27/2006

INVOICE# WS71M-06

2% upon receipt/net 15

Please return top portion with payment.

DESCRIPTION PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS CIRCUIT BREAKER	COST	AMOUNT .
PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS	COST	AMOUNT .
HRS, ASST ASSY/MECH SUPPLIES/MATERIALS		7 111100111
OIL, CASTROL 20W50	3.00 18.29 4.50	19.50 18.29 9.00
LABOR WORK PERFORMED 3/30/06 TO 4/27/06 MECHANICAL Finish install. Test operation of repairs. Remove dash top (set in place last time). Repaired ammeter (cause of problem). Reinstall related wiring. Reassemble dash and check operation. NOTE clock not working. Perform vehicle leaving function check list. HOURS	75.00	407.50
MECHANICAL, NO CHARGE Check for power, ground OK. Refit clock. Remove clock, return for repair. 1.75 N/C	73.00	487.50
COLLECTOR SERVICES Wash, clean interior and exterior. Polish bright work. Treat interior upholstery. Polish wheels.	50.00	75.00
SUBLET		
MMFR defut MC1.	/ORK PERFORMED 3/30/06 TO 4/27/06 IECHANICAL inish install. Test operation of repairs. Remove dash top (set in place last time). epaired ammeter (cause of problem). Reinstall related wiring. Reassemble ash and check operation. NOTE clock not working. Perform vehicle leaving inction check list. OURS ECHANICAL, NO CHARGE heck for power, ground OK. Refit clock. Remove clock, return for repair. 75 N/C OLLECTOR SERVICES fash, clean interior and exterior. Polish bright work. Treat interior upholstery. Dilsh wheels.	/ORK PERFORMED 3/30/06 TO 4/27/06 IECHANICAL inish install. Test operation of repairs. Remove dash top (set in place last time). epaired ammeter (cause of problem). Reinstall related wiring. Reassemble ash and check operation. NOTE clock not working. Perform vehicle leaving inction check list. OURS 75.00 ECHANICAL, NO CHARGE heck for power, ground OK. Refit clock. Remove clock, return for repair. 75 N/C OLLECTOR SERVICES fash, clean interior and exterior. Polish bright work. Treat interior upholstery. 50.00

TOTAL DUE



4/27/2006

INVOICE# WS71M-06

2% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION		
1	REPAIR AS ORIGINAL, NEW MOVEMENT/AMMETER SHORT CAUSED FAILURE 4/7/06 mileage 51,885 CT Sales Tax	183.50 6.00%	183.50
			47.57

TOTAL DUE

\$840.36

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

AUTOMOTIVE RESTORATIONS, INC. • 1785 Barnum Ave., Stratford, Connecticut 06614 • (203) 377-6745 • Fax (203) 386-0486



5/31/2006

INVOICE# WS71M-07

2% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
7.5 1 10 10 10 10 1 1 2 1 2	PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS FIRE EXTINGUISHER, Emergency kit FLAT FIX LIGHT BULBS LIGHT BULBS LIGHT BULBS EMERG-BELT FUSES, ASST WIPER BLADES FUEL FUEL PUMPS TIRE, GOODYEAR 215/70-15	3.00 22.33 6.99 1.31 2.10 1.66 13.99 9.00 11.64 24.00 299.00 108.68	22.50 22.33 6.99 13.10 21.00 16.60 13.99 9.00 23.28 24.00 598.00 108.68
7.5	LABOR WORK PERFORMED 4/27/06 TO 6/1/06 MECHANICAL Inspect oil pressure gauge. Note oil pressure sender NG, order parts. Check head lights and power window inop. Note blown fuses. Isolate power window circuit from main fuse box with separate inline fuse. Diagnose non start. NOTE left side fuel pump NG, order both. Replace pump and oil pressure sender N/C. Road test, set, check, OK. HOURS	75.00	562.50

TOTAL DUE



5/31/2006

INVOICE# WS71M-07

2% upon receipt/net 15

Please return top portion with payment.

VEHICLE 1971 Maserati Ghibli Coupe #AM115492248 QTY/HRS DESCRIPTION COST **AMOUNT** SUBLET 1 MOUNT AND COMPUTER BALANCE 25.00 25.00 CT Sales Tax 6.00% 86.58

TOTAL DUE

\$1,553.55

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

Page 2

JESSER'S CLASSIC KEYS

26 WEST STREET AKRON OH 44303-2344 PHONE 330-376-8181 FAX 330-384-9129

Date	Invoice #
7/21/2006	2006-1432

Bill To				Ship	То		
				, ,		=	
				L			F
Credit C	Card #	Exp. D	Auth #	Origin	Ad Code	Ship Date	Ship Via
		55	148148	Phone	REO	7/21/2006	US MAIL
RA-4 NOS A	NOS ANGE	Des	cription		Qty	Rate	Amount
RA-4 NOS A RA-3 NOS A	NOS AMC I	GNITION TRUNK				1 15. 1 15.	
SWKF LEF	STEERING 2 CORVAIR LARGE EM 2 MERCEDI	, 2 JAVELII BLEM FOB	N, 4 CHRYS			8 9.9 6 9.9	
SHIPPING	SHIPPING &			RTONS		6.9	95 6.95
Thank you fo	or your bus	siness.			Subtot	al	\$176.25
		Maria de la companya				ax (6.25%)	\$0.94
					Total		\$177.19

ork PART NO AND DESCRIPTION 1 rear Caliper kit #2 front Broke hose set	125 45 e	00	120	000		OR CARS onkton Rd.	2	198	
I rear brake hose	33	F -	29		Dh/Fau (D	02) 877-264			
1 Front Windshield Seal	400		-	000	ti .		CUSTOMER IS CHOSEN NO	DATE	-
1 oil pressure sendor	650		76	-	-		CROSP ARTITIONS	No. of Contract of	
1 E-Brake Pal Set		00	95	7	1		CHEEN WHITEHER	PHOMORE	A.f
20ft 5/16 fuel hose	1.50/	-	30	00	a.				P.M
7 hose clamps	4.00%		-	00	108		ESI	CONSTRA	
1 MSD ingition control	12000		-	-	YEAR MAKE AND MODEL		LICENSE NUMBER	COMMETCH:	
1 MSD Blaster (Bil	1 .		185		1971 Maserati Chibli	SS	TERMS	Contract (III)	
	-	00	60	00				T-11111111111	
1 MSD tach adapter	57	50	50	00	DESCRIPTION OF	0.01501052		AMOL	JNT
15 Et 14 guye wire			10	00		TUNE-UP	TRANS. L. DEF		
15ft wire sheathing		-	10	00	- Pulled wind shidd cleaned	Surfece	of butel	2 hr	
weather proof GM style consec	hor	-	5	æ	- Diagnosed electrical prol	olem . fo	and foully ?		
Coil Bracket	1.0	-	20	ගය	man ignition control bo	c, insta	lled new	18 Hr	4
Insection pump diaphrams	18 cc		64	00	MSD unit, tested Dist +	Adjusted	pts.)		
Misc hardware					- replaced all Brake hose			1,5 h	~
		_			- replaced oil pressure sen	der for	quase	1 hr	1
					- replaced all subber fuel h	oses	3 3	5 45	
					- fixed faulty A/c switch			1.5 W	-
					- installed Clock			.5hr	
MAY DE CONTINUED ON CITER BEE: TOTAL PARTS					LITERS/GALS. OF GAS @		TOTAL LABOR	34,51	-
ACCESSORIES					LITERSAGTS, OF OIL @		TOTAL PARTS	1242	00
- cleaded + Adusted carbs	5 hr				kgABS. OF GREASE B	total		2415	-
						10.	GAS, OL AND SPEASE	~110	-
	-	T					AND GREASE SUBLET REPAIRS		
					bereby authorize the above repair work to be done along with the		EPA: WASTE DISPOSAL		
					hereby authorize the above repair work to be done along with the received produced to the control of the produced produced by an artificial produced by an artificial produced to the control of the con			- 12	
		1			the amount of reports theerto. It is also indenstood that you will not be held responsible for last or demage to cers or entides left in consi- ricate of fine, the't or any other cause beyond your control.		Credit	3000	
	_	+			SAVE CALD PARTIES*		TAX	K	
TOTAL ACCESSORIES							TOTAL	657	
					RANGATURE		THANK YOU		



12/28/2006

INVOICE# WS71M-08

2% upon receipt/net 15

Please return top portion with payment.

VEHICLE 1971 Maserati Ghibli Coupe #AM115492248

QTY/HRS	DESCRIPTION	2007	
33 11 1 1 1 1 1 2	PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS OIL, VALVOLINE 20W50 OIL FILTER. OIL ANALYSIS LAB FEE FUEL VEGLIA SPEEDOMETER CABLE CLUTCH SALVE KIT BRAKE HOSE BRAKE CABLE AXLE STRAPS Parts Subtotal LABOR WORK PERFORMED 11/20/06 TO 12/28/06 MECHANICAL	3.00 4.50 20.62 49.90 26.75 105.00 12.20 26.95 356.76 43.20	99.00 49.50 20.62 49.90 26.75 105.00 12.20 26.95 356.76 86.40 833.08

TOTAL DUE



12/28/2006

INVOICE# WS71M-08

2% upon receipt/net 15

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
29	Repair wiper switch. Disassemble steering wheel to remove combo switch. Reassemble as necessary, secure assy properly. Reassemble switch back into column, test OK. Diagnose fuel and running problem. NOTE; fuel line by pump in trunk pinched. Repair, test OK. Inspect choke operation. Readjust choke cable and carbs. Readjust carb synchronization and mix. Reassemble air filter and housing to carbs. Change oil and filter, send for analysis. Diagnose smoke on road test. NOTE carbs spewing fuel from accelerator pump nozzles. Clean check valves, change float levels, no improvement. Remove check valves, disassemble, make up spacers for valve ball top, per tech support at Pierce Manifold. Reassemble, test, road test OK. Inspect steering wheel position, can't center on splines. Perform vehicle leaving functions check list. Misc item pre test list.		
	COLLECTOR SERVICES	80.00	2,320.0
1	Clean and delivery prep. 12/14/06 mileage 79,385	50.00	50.0
3	MECHANICAL-DIAGNOSIS Vehicle brakes locked up on customer, vehicle returned to shop. Inspect and list findings, nothing found to cause brake lockup. HOURS		
	Labor Subtotal CT Sales Tax	80.00 6.00%	240.0 2,610.0 204.9

TOTAL DUE

\$3,648.06



DATE 1/31/2007
INVOICE# WS71M-09

Please return top portion with payment.

VEHICLE

1971 Maserati Ghibli Coupe #AM115492248

QTY/HRS	DESCRIPTION	COST	AMOUNT
31.25 1 1 1 1	PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS BRAKE FLUID, CASTROL LMA FUEL BRAKE BOOSTER, REBUILT BRAKE MASTER CYL, REBUILT Parts Subtotal	3.00 17.50 41.00 595.00 593.61	93.75 17.50 41.00 595.00 593.61 1,340.86
31.25	UORK PERFORMED 12/28/06 TO 2/1/07 MECHANICAL Remove exhaust system to gain access to brake pipes/e-brake. Install new brake pipe from under transmission back to rear axle. Install new brake hose to rear axle. Repair broken brake "tee". Weld tab to attach to rear axle. Install new e-brake cable, (heat old one to remove nuts/pins from cable). Reinstall e-brake pads correctly (installed upside down). Bleed brake system. Remove clutch slave cylinder, install new cups/seals. Reinstall, bleed clutch. Install new speedo cable. Reinstall exhaust system. Start vehicle, road test. NOTE; brakes still stiff. Remove brake booster/master cylinder assy, send for rebuild. Install new brake booster and master cylinder assemblies. Bleed brake system. Road test, OK. HOURS Labor Subtotal	80.00	2,500.00 2,500.00

TOTAL DUE



1/31/2007

INVOICE# WS71M-09

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1	FREIGHT, return brake cores 1/18/07 mileage 54,756 CT Sales Tax	39.00 6.00%	39.00

TOTAL DUE

\$4,110.19



9/27/2007

INVOICE# WS71M-11

Due on receipt

Please return top portion with payment.

	VEHICLE		-
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
19.25 1 1 1 1 4 2	PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS HEATER VALVE GASKET, heater FAN MOTOR OIL FILTER ORINGS QRTS OIL, CASTROL 20W50 Parts Subtotal LABOR WORK PERFORMED 8/30/07 TO 9/27/07 MECHANICAL Diagnose cause of leaking. NOTE oil filter adapter leaking, replace oring, still weeps a bit. Remove oil filter housing measure, slight distortion. File and fit alt size orings. Speedometer cable OK, head has internal problem. Remove speedometer, send for repair. Left cooling fan NG. Drain oil. Reassemble oil filter mounting with new oring. Refill oil, start, check for leaks, OK. Flush brake fluid. Heater valve leaking, order part. Unable to install fuel cap, noted tank mounts failed causing tank to fall out of grommet. Replace tank mounts with material from stock, tank fits thru grommet, OK. Disassemble interior panels to access, reassemble. Job Not Complete	3.00 72.50 6.43 201.74 22.14 0.89 6.50	57.75 72.50 6.43 201.74 22.14 3.56 13.00 377.12
19.25	HOURS Labor Subtotal	85.00	1,636.25 1,636.25

TOTAL DUE



DATE 9/27/2007
INVOICE# WS71M-11
Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1	SUBLET FREIGHT, send speedometer for repair Sublet Subtotal CT Sales Tax	14.71 6.00%	14.71

TOTAL DUE

\$2,149.76

TERMS: INVOICE IS DUE AND PAYABLE ON RECEIPT FINANCE CHARGE IS 18% PER YEAR (1.5% PER MONTH)

Page 2



DATE 10/31/2007
INVOICE# WS71M-12

Due on receipt

Please return top portion with payment.

PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS HOOD Parts Subtotal LABOR WORK PERFORMED 9/27/07 TO 11/1/07 MECHANICAL Install repaired speedometer (billed previous). Install badge in front area. Road test speedometer, OK. HOURS Labor Subtotal SUBLET CHROME ALUMINUM CLOCK Sublet Subtotal CT Sales Tax		VEHICLE		
PARTS HRS, ASST ASSY/MECH SUPPLIES/MATERIALS HOOD Parts Subtotal LABOR WORK PERFORMED 9/27/07 TO 11/1/07 MECHANICAL Install repaired speedometer (billed previous). Install badge in front area. Road test speedometer, OK. HOURS Labor Subtotal SUBLET CHROME ALUMINUM CLOCK Sublet Subtotal CT Salor Tay		1971 Maserati Ghibli Coupe #AM115492248		
HRS, ASST ASSY/MECH SUPPLIES/MATERIALS HOOD Parts Subtotal LABOR WORK PERFORMED 9/27/07 TO 11/1/07 MECHANICAL Install repaired speedometer (billed previous). Install badge in front area. Road test speedometer, OK. HOURS Labor Subtotal SUBLET CHROME ALUMINUM CLOCK Sublet Subtotal CT Sales Tax	QTY/HRS	DESCRIPTION	COST	AMOUNT
WORK PERFORMED 9/27/07 TO 11/1/07 MECHANICAL Install repaired speedometer (billed previous). Install badge in front area. Road test speedometer, OK. HOURS Labor Subtotal SUBLET CHROME ALUMINUM CLOCK Sublet Subtotal CT Sales Tox	0	HRS, ASST ASSY/MECH SUPPLIES/MATERIALS HOOD	CONTROL	0.0 4,500.0 4,500.0
Labor Subtotal SUBLET CHROME ALUMINUM CLOCK Sublet Subtotal CT Sales Tox		WORK PERFORMED 9/27/07 TO 11/1/07 MECHANICAL Install repaired speedometer (billed previous). Install badge in front area. Road test		
1 CHROME ALUMINUM CLOCK Sublet Subtotal CT Sales Tax	1.25		85.00	106.2 106.2
Sublet Subtotal 290.00 290	1			
		Sublet Subtotal	290.00	290.0 290.0
		CT Sales Tax	6.00%	293.7

TOTAL DUE

\$5,190.03



DATE 12/27/2007
INVOICE# WS71M-13

Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1	SUBLET REPAIR/CALIBRATE VEGLIA MECH SPEEDOMETER LABOR	397.20	397.20
	Still awaiting hood, coming, Italy. CT Sales Tax	6.00%	23.83
	ТОТ	AL DUE	\$421.03



DATE 1/31/2008
INVOICE# WS71M-14


Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1.5	LABOR WORK PERFORMED 12/27/07 TO 1/31/08 BODY Inspect new hood, mock up on vehicle, measure for fit. Hood fit is incorrect. HOURS CT Sales Tax	85.00 6.00%	127.50 7.65

TOTAL DUE

\$135.15



Credit Memo

Date	Credit #
3/27/08	WS71M12CRE

VEHICLE 1971 Maserati Ghibli Coupe #AM115492248

QTY/HRS	DESCRIPTION	COST	AMOUNT
-1	PARTS HOOD CT Sales Tax	4,500.00 6.00%	-4,500.00 -270.00

Balance Credit

\$0.00



DATE 3/27/2008
INVOICE# WS71M-15

Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
50.25 8.75 20	PARTS HRS, ASST BODY SUPPLIES/MATERIALS HRS, ASST PAINT SUPPLIES/MATERIALS HRS, ASST WELD MATERIALS/SUPPLIES Parts Subtotal	10.00 27.00 5.00	502.50 236.25 100.00 838.75
2	LABOR WORK PERFORMED 2/29/08 - 3/27/08 MECHANICAL Repair broken hood hinge, weld, tap. HOURS BODY	85.00	170.00

TOTAL DUE



DATE 3/27/2008

INVOICE# WS71M-15

Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HR\$	DESCRIPTION	COST	AMOUNT
70.25	Restore original hood; Remove many layers of old paint and primer from hood with liquid paint stripper. Cut out rusted areas. Dry strip hood to bare metal. Fabricate templates & fabricate sections from metal stock. Weld in metal, grind welds, cut holes for hood mounts. Fabricate hood mounts, weld, grind welds. Shape hood to fit car properly, install & align hood. Weld splits & holes, grind. Straighten and glaze hood, match to body. Remove wipers & header emblem. Apply spray poly prime to hood & bake. Sand to 180grit for final prime. Mask body prime hood, body, front end for prime. Sand hood, header, cowl & fender top surfaces to prepare for paint. Wet sand hood. Sand fender tops & header with 1200 wet to prepare for polish. Sand fender tops & headers 3 times. Compound and polish entire car. Wash and wax vehicle, touch up nicks & chips as needed. Mask & undercoat underside of hood. Install windshield wipers & header emblem.		
70.25	PAINT	85.00	5,971
8.75	Mask & paint hood, header, cowl, & fender top surfaces with 4 coats color & 3 coats clear. HOURS Labor Subtotal CT Sales Tax	85.00	743. 6,885.
		6.00%	463

TOTAL DUE

\$8,187.18



DATE 4/30/08
INVOICE# WS71M-16
Due on receipt

AMOUNT

Please return top portion with payment.

	1971 Maserati Ghibli Coupe #AM115492248	
QTY/HRS	DESCRIPTION	COST
	PARTS	
48.25	HRS, ASST ASSY/MECH SUPPLIES/MATERIALS	3.00
3.5	HRS, ASST CLEAN/DETAIL MATERIALS	5.00
3.25	HRS, ASST BODY SUPPLIES/MATERIALS	10.00

VEHICLE

48.25 3.5 3.25 2 2 1 8 1 9 1 4	HRS, ASST ASSY/MECH SUPPLIES/MATERIALS HRS, ASST CLEAN/DETAIL MATERIALS HRS, ASST BODY SUPPLIES/MATERIALS OIL FILTERS, ONE SPARE DRAIN PLUG GASKETS FREIGHT, OVER NIGHT SPARK PLUGS, CHAMPION GAL ANTIFREEZE QRTS OIL, VALVOLINE 20W50 FUEL FILTER CARB REBUILD KITS FUEL Parts Subtotal	3.00 5.00 10.00 44.80 3.19 10.00 4.95 17.20 6.40 6.91 63.80 34.00	17.50 32.50 89.60 6.38 10.00 39.60 17.20 57.60 6.91
	LABOR WORK PERFORMED 3/28/08 - 5/1/08 MECHANICAL		

TOTAL DUE



DATE 4/30/08

INVOICE# WS71M-16

Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
43.75	Perform seasonal service. Prep for tour use. Install new fuel filter. Test brake fluid - okay. Inspect, locate & repair wiring under dashboard. Install new spark plugs, road test car, remove spark plugs, inspect for proper combustion color - okay. Check operation of accelerator pumps - okay. Tighten brake booster lines & fittings. Clean brake booster. Drain cooling system, refill, check temperature protection level - okay. Drain oil tank & engine sump, refill oil tank. Order special oil filter required. Remove & disassemble carburetors (4). Soak in cleaner & rinse. Reassemble with new gaskets, metering needles & rebuild parts. Set float level. Install new oil filter. Reinstall carbs, set basic mix, balance, idle. Road test. Note; left cooling fan very noisy failing. Install good/used Lucas fan. Modify to fit, check operation OK. Right side hood latch bolt broken, drill retap, reinstall and adjust. Install new spring in hood safety latch, adjust. Install new heater control valve. Modify new valve and heater cable, only part available. Photo old and new valves. Perform vehicle leaving check list.	85.00	3,718.7
	BODY	00.00	3,7 10.7
3.25	Compound and polish exterior. HOURS	85.00	276.2
3.5	COLLECTOR SERVICES Clean and detail wax vehicle. Delivery prep. Treat leather and seals. Valet. HOURS	60.00	210.0

TOTAL DUE



DATE 4/30/08
INVOICE# WS71M-16
Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
6.5	HOURS, S&H Negotiation and resolution - hood FREIGHT, HOOD CT Sales Tax	60.00 428.40 6.00%	390.00

TOTAL DUE

\$6,076.68



6/26/08

INVOICE# WS71M-17

Due on receipt

Please return top portion with payment.

VEHICLE

1971 Maserati Ghibli Coupe #AM115492248

QTY/HRS	DESCRIPTION	COST	AMOUNT
21.5 38.5 7 1 1 1 1 2	PARTS ASST MECH/ASSY MATERIALS/SUPPLIES, hood hinge HRS, ASST BODY SUPPLIES/MATERIALS HRS, ASST PAINT SUPPLIES/MATERIALS FRONT WINDSHIELD RUBBER GASKET SPEEDOMETER CABLE RADIATOR FAN THERMO SWITCH SEALING WASHER, switch FUEL DURA COOL 12A Parts Subtotal LABOR WORK PERFORMED 5/29 - 6/26/08 MECHANICAL	5.00 10.00 27.00 653.26 120.43 38.56 2.10 42.35 21.95	107.9 385.0 189.0 653.2 120.4 38.9 2.7 42.3 43.9 1,582.7

TOTAL DUE



6/26/08

INVOICE# WS71M-17

Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
21.5	Repair hood hinge. Remove windshield assembly, install new rubber seal & chrome trim to glass & seal. Begin installation of windshield however glass cracked near left pillar mounting point due to previous nick at edge. Disassemble e-brake control cover, adjust cables & rear brake calipers. Test e-brake operation - okay. Check a/c system, not blowing cold. Add duracool freon substitute to a/c system & check for leaks. Check speedometer operation, remove speedometer cable & found seized. Order new speedometer cable. Remove exhaust system to access speedometer output housing & remove pieces of old speedometer cable. Re-install exhaust system & heat shields. Inspect fan relays & flow thru vents. Order new fan relays required. Repair wires to fan relays & install new relays. Road test car following repairs, blower fan operational, speedometer functioning but not steady.		
21.5	BODY	85.00	1,827.
	Remove hood, dry strip original paint remaining, sand, mask & prime. Wash down with metal conditioner cleaner & mask. Apply 2 coats of epoxy primer & bake. Scuff primer & glaze. Apply 4 coats & bake. Block sand to smooth, re-prime. Sand & mask hood for paint, remove wipers & front emblem. Wet sand & polish nose. Install wipers & front emblem.		
38.5	HOURS	85.00	3,272.

TOTAL DUE



6/26/08

INVOICE# WS71M-17

Due on receipt

Please return top portion with payment.

	VEHICLE		
	1971 Maserati Ghibli Coupe #AM115492248		
QTY/HRS	DESCRIPTION	COST	AMOUNT
7	PAINT Prep & paint top surround panel of nose & hood. Prep and paint hood and blend into upper cowl. HOURS Labor Subtotal CT Sales Tax	85.00 6.00%	595.0 5,695.0 434.0

TOTAL DUE

\$7,711.19

Justa quick note & pictures

Nere Are some pictures of what I've done so far, beather seems to be in good shape so I don't see on groblem. The foam in gove from the back of seads where the pleats are, I will reform them ficture # 7.

Seats out of car

Split throads

Bottom cushion belster

Instile cushion cover better back

writing on back side leather

bottom of sent back pleats

pullis, throads out with tweasers

withing throads with razon

Back of seat

(All this driver s. side)

copy of Mand withen notes on tear down of driver seat will be sent with abill at the end of this worth - heather regard color next.

DAUID

PURCHASE ORDER

DAUIT	OPELA	20					
26848 5	PANISH GA	ARDEN DE	2				
CITY, STATE, ZIP							_
BONTT	SPRINCS						
DATE	DATE REQUIRED	TERMS	HOW SHIPPED	REQ. NO. OR DEPT.		FOF	
11-05-08					mas	ART	TI
QUANTITY		DES	CRIPTION		PRICE		UNIT
1							
2	HOURS BI	LLED 9	-4-08 th	rough 11.4.08			
3	•						
4		22 hr	5 @ 37,5	O.	865	00	
5							
6							
7							
8							
9							
10							
11							
12				TOTAL	8010	60	
13				TOTAL	# 065		
14							
15							
16							
17							
18							
19			DAWS	COPELAND			
20			JAU (V	COTOLAIVE			
21			- /	JK/11			
22			~	-19			
	IMPORTANT			- 22-130-12			
INVOICES - PA	RDER NUMBER MUS ACKAGING, ETC.		DUDGUAGIN	BILL OF LADING.	PIES OF YO	UR INV	DICE WITH
PLEASE NOTI	FY US IMMEDIATELY E ORDER BY DATE S	IF YOU ARE UNAB PECIFIED.	BLE FUNCTIASIN	G AGENT			
2. adams 8131			ORIGINAL				

PURCHASE ORDER ADDRESS

26848 Spanish Gardon Dx

CITY, STATE, ZIP

(30n + c Springs FC 34135) HOW SHIPPED 1-04-09 UNIT PRICE DESCRIPTION QUANTITY BILLED FOR 11-4-08-1-4-08 3 Froup 5 4 37hrs @ 37,50 1387 50 5 6 7 8 9 10 11 12 13 TOTAL HRS TO DATE 59 LCS 14 15 16 17 18 19 20 21 22 IMPORTANT COPIES OF YOUR INVOICE WITH PLEASE SEND_ ORIGINAL BILL OF LADING. PURCHASE ORDER NUMBER MUST APPEAR ON ALL INVOICES - PACKAGING, ETC. PURCHASING AGENT PLEASE NOTIFY US IMMEDIATELY IF YOU ARE UNABLE TO COMPLETE ORDER BY DATE SPECIFIED.

adams 8131

ORIGINAL

DATE	9/30/09
INV#	WS71M-19
Due o	on receipt (a/r)

71 Maserati Ghibi

RO # 537

	(**SEC. 10) SHARES		
QTY/HRS	DESCRIPTION	COST	AMOUNT
14.5	LABOR WORK PERFORMED 7/30/09 TO 10/1/09 INSTRUMENTS/CONTROLS Disassemble dash. Remove original radio and install customer supplied Becker radio. Rewire, connect and reassemble dash. Check AC operation. System reading low. Perform AC leak check, nothing obvious noted with condensor or lines/fittings. Top up with Duracool propane based freon replacement. Now blowing cold, but during testing, car ran too hot. Note; cooling service needed if frequent AC use anticipated highway OK, traffic no go. Flush and bleed brakes. Top off motor oil. Install new screws on grill ornament, N/C. Install hardwire battery charger. HOURS		
14.0	UPHOLSTERY	100.00	1,450.00
0.5	Repair lower piping. Re-attach rear bottom of door panel. HOURS	100.00	50.00
2	COLLECTOR SERVICES Perform vehicle leaving functions check out list. Clean and delivery prep. Labor Subtotal	65.00	130.00 1,630.00
14.5	PARTS/SUPPLIES HRS ASST MECH SUPPLIES	5.00	72.50

TOTAL DUE

DATE	9/30/09
INV#	WS71M-19
Due o	n receipt (a/r)

71 Maserati Ghibi RO # 537

QTY/HRS DESCRIPTION	COST	AMOUNT
2 HRS ASST CLEAN SUPPLIES 4 DURACOOL 2 DURACOOL 1 CASTROL GT/LMA BRAKE FLUID 2 QT VALVOLINE VR1 20W-50 RACING OIL 1 FUEL Parts Subtotal CT Sales Tax	5.00 24.95 24.95 14.95 8.69 46.00 6.00%	10.00 99.80 49.90 14.95 17.38 46.00 310.53 113.67

TOTAL DUE \$2,054.20

DATE	9/30/09
INV#	WS71M-18
Due o	n receipt (a/r)

71 Maserati Ghibi

RO # 537

QTY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR		
	WORK PERFORMED 7/30/09 TO 10/1/09		
	GLASS/SEALS		
	Remove windshield assembly. Clean dried sealer from body. Photo rust areas. Prep and apply POR15 rust treatment. Apply new sealer to original weather strip. Install weather strip on new glass. Weld broken chrome on windshield, detail smooth. Install chrome trim in gasket. Windshield not fitting correctly, remove windshield. Regrind WS edge, test, fit and polish until correct. Assemble and install windshield and weather strip. Install mirror. Leak test new windshield OK.		
15.5	HOURS	100.00	1,550.00
	DADTO/CUDDI IFO	100.00	1,000.00
15.5	PARTS/SUPPLIES HRS ASST MECH SUPPLIES	F 00	
1	WINDSCREEN	5.00	77.50
1	WIPER INSERTS	3,351.90 8.77	3,351.90 8.77
	Parts Subtotal	0.77	4,988.17
	CT Sales Tax	6.00%	299.29

TOTAL DUE

\$5,287.46

FNUCKE 18, WINDSITED ONLY



9/30/09

INV#

WS71M-18

Due on receipt (a/r)

Please return top portion with payment.

	71 Maserati Ghibi		
	RO # 537		
QTY/HRS	DESCRIPTION	COST	AMOUNT
14.5	LABOR WORK PERFORMED 7/30/09 TO 10/1/09 INSTRUMENTS/CONTROLS Disassemble dash. Remove original radio and install customer supplied Becker radio. Rewire, connect and reassemble dash. Check AC operation. System reading low. Perform AC leak check, nothing obvious noted with condensor or lines/fittings. Top up with Duracool propane based freon replacement. Now blowing cold, but during testing, car ran too hot. Note; cooling service needed if frequent AC use anticipated highway OK, traffic no go. Flush and bleed brakes. Top off motor oil. Install new screws on grill ornament, N/C. Install hardwire battery charger. HOURS		
14.5	GLASS/SEALS Remove windshield assembly. Clean dried sealer from body. Photo rust areas. Prop.	100.00	1,450.00
15.5	and apply POR15 rust treatment. Apply new sealer to original weather strip. Install weather strip on new glass. Weld broken chrome on windshield, detail smooth. Install chrome trim in gasket. Windshield not fitting correctly, remove windshield. Regrind WS edge, test, fit and polish until correct. Assemble and install windshield and weather strip. Install mirror. Leak test new windshield OK. HOURS UPHOLSTERY	100.00	1,550.00
	Repair lower piping. Re-attach rear bottom of door panel.		

TOTAL DUE



9/30/09

INV#

WS71M-18

Due on receipt (a/r)

Please return top portion with payment.

	71 Maserati Ghibi		
	RO # 537		
QTY/HRS	DESCRIPTION	COST	AMOUNT
0.5	HOURS	100.00	50.00
2	COLLECTOR SERVICES Perform vehicle leaving functions check out list. Clean and delivery prep. Labor Subtotal	65.00	130.00 3,180.00
30 2 1 4 1 2 1 2	PARTS/SUPPLIES HRS ASST MECH SUPPLIES HRS ASST CLEAN SUPPLIES WINDSCREEN DURACOOL WIPER INSERTS DURACOOL CASTROL GT/LMA BRAKE FLUID QT VALVOLINE VR1 20W-50 RACING OIL FUEL Parts Subtotal CT Sales Tax	5.00 5.00 3,351.90 24.95 8.77 24.95 14.95 8.69 46.00 6.00%	150.00 10.00 3,351.90 99.80 8.77 49.90 14.95 17.38 46.00 3,748.70 412.96

TOTAL DUE

\$7,341.66

2/25/10

INV#

WS71M-20

Due on receipt (a/r)

Please return top portion with payment.

	RO # 835		
	No iii ood		
QTY/HRS	DESCRIPTION	COST	AMOUNT
2	LABOR WORK PERFORMED 1/29/10 TO 2/18/10 WIRING/ELECTRIC Diagnose charging system failure. Remove alternator and voltage regulator, send for repair. Reinstall repaired alt/reg. Road test, OK. HOURS	100.00	200.00
	Labor Subtotal	100.00	200.00
2	PARTS/SUPPLIES HRS ASST SUPPLIES Parts Subtotal	5.00	10.00 10.00
1	SUBLET REPLACED FRONT BEARING AND REAR BEARING IN ALTERNATOR Sublet Subtotal	225.00	225.00 225.00
	CT Sales Tax	6.00%	26.10

TOTAL DUE

\$461.10



(203) 377-6745 Fax (203) 386-0486



DATE

1/26/12

INV#

WS71M-21

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
2.5 31.1	LABOR WORK PERFORMED 1/1/2012 TO 1/26/2012 COLLECTOR SERVICES HRS:Transport vehicle from Westport, CT to ARI, Stratford in enclosed trailer. (Load & MILEAGE:Equipment use & fuel	Unload) 65.00 1.25	162.50 38.88
11.7	EVALUATION Initially-Load test battery and check charging system for draw. No draw. Cycle battery o hours. Will not maintain voltage. Battery-NG. Note issue with left headlight-possible motor or transmission binding & causing breaker activate. Further work, diagnosis needed to effect repair. Pressure test cooling system Note radiator leaking, core failing. Corrosion. Road test. Perform general inspection of body, noting extensive corrosion and some tro engine noise. HOURS	to	
	Labor Subtotal	100.00	1,170.00 1,371.38
11.7	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES Parts Subtotal	5.00	58.50 58.50
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	1,429.88 14.30 91.71
Make ch	necks payable to Automotive Restorations, Inc. nec charges are assessed monthly at 1.5%	OTAL DUE	\$1,535.89

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

2/23/12

INV#

WS71M-22

	1971 Maserati Ghibli	11.00		
	RO # 2021			
QTY/HRS	DESCRIPTION		COST	AMOUNT
0.6	LABOR COLLECTOR SERVICES Top off fuel and add fuel stabilizer. Set car in storage. HOURS Labor Subtotal		65.00	39.00
1	PARTS/SUPPLIES FUEL FILL UP STARTRON-FUEL ADDITIVE Parts Subtotal		26.17 6.90	26.17 6.90 33.07
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011		1.00% 6.35%	72.07 0.72 2.96
Make ch	necks payable to Automotive Restorations, Inc.	TOTAL D		\$75.75



(203) 377-6745 Fax (203) 386-0486



DATE

5/31/12

INV#

WS71M-23

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
6.5	LABOR WORK PERFORMED 4/27/2012 TO 5/31/2012 BODY WORK Transfer vehicle to body shop and stage on stand for examination. Grind and feather out bubbling on trunk lid, cracks on b-pillars and base of scoops. Numerous layers of previous paint coatings-Poor foundation to consider another. Re-wo revisit methodology solvent test. Compile and report findings. Transition to temporary warehouse storage. HOURS Labor Subtotal PARTS/SUPPLIES HRS ASST BODY SUPPLIES Parts Subtotal	rk and 85.00	552.5 552.5 65.0 65.0
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	617.5 6.1 39.6
Make ch	necks payable to Automotive Restorations, Inc. to charges are assessed monthly at 1.0%	TAL DUE	\$663.28

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

6/5/12

INV#

Deposit

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Client Deposit: approved estimate, \$69,621.00 6.35% CT SALES TAX - effective 07/01/2011	23,200.0	1.5
Make			
Finan	necks payable to Automotive Restorations, Inc. ce charges are assessed monthly at 1.0%	TOTAL DUE	\$23,200.00

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

6/28/12

INV#

WS71M-24

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
12.7	LABOR WORK PERFORMED 6/1/2012 TO 6/28/2012 DISASSEMBLE Disassemble for metal work and paint: Remove chrome trim. (Not yet complete) HOURS Labor Subtotal	85.00	1,079.50 1,079.50
12.7	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES Parts Subtotal	5.00	63.50
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	
Make cl	necks payable to Automotive Restorations, Inc.	TOTAL DUE	\$1,227.74

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486





DATE

7/26/12

INV#

WS71M-25

	1971 Maserati Ghibli			
	RO # 2021		NEW YORK	
TY/HRS	DESCRIPTION		COST	AMOUNT
	LABOR WORK PERFORMED 6/29/2012 TO 7/26/2012 DISASSEMBLY Disassemble for metal/body/paint work: Remove doors, trunk & hood. Remove insignia/emblems/badges. Remove front and rear windows. Remove door glass and window frames.	all		
25.1	Remove seat and loose carpets. HOURS		85.00	2,133.5
07.0	FINISH REMOVAL Mechanically strip entire exterior of car. Strip finish from interior and edges of do Mask for bodywork. Remove finish from lower fenders, front and rear valance to inspect condition of Remove lead from cracked areas.			
27.8	HOURS COOLING SYSTEM		85.00	2,363.0
3.5	Drain coolant and remove radiator. HOURS		100.00	350.0
62.6	METAL WORK* Weld exposed cracks in steel around windshield frame, rear glass and left & rigil Cut out corroded sections of doors, quarter panels and fenders. Fabricate and fit replacement sections per estimates. Progress invoice, job not complete. HOURS	nt side vents.	100.00	
Make ch	necks payable to Automotive Restorations, Inc.	Invoice Total	100.00	6,260.00
	www.automotiverestorations.com	Payments/Cre	dits	
	www.vintageracingservices.com	BALANCE DU	ı_	



(203) 377-6745 Fax (203) 386-0486





DATE

7/26/12

INV#

WS71M-25

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
0.4	BODY WORK Straighten right rear bumper mount and tail light housing orientation. Heat shrink sections of hood.		
2.4	HOURS	85.00	204.00
2.6	PAINT WORK Match green on car to #M5141A-Ferrari Code 601. Spray out 3 blue met MAZ. Blues 1971 and send to customer. HOURS	s made in 100.00	260.00
2.8	FUEL Remove fuel pumps, fuel tanks, and hard line for metal work/welding access. HOURS Labor Subtotal	100.00	280.0 11,850.5
	PARTS/SUPPLIES		
31.4 62.6 27.8 2.4 2.6	HRS ASST MECH/ASSY SUPPLIES HRS ASST METAL WORK/FAB/WELD SUPPLIES HRS ASST STRIP/UNDERBODY/POWER WASH SUPPLIES HRS ASST BODY SUPPLIES HRS ASST PAINT SUPPLIES SHIP PAINT SAMPLES Parts Subtotal	5.00 10.00 7.50 10.00 35.00 2.29	157.00 626.00 208.50 24.00 91.00 2.29 1,108.79
			12,959.2
Make cl	hecks payable to Automotive Restorations, Inc. nce charges are assessed monthly at 1.5%	Invoice Total	
	www.automotiverestorations.com	Payments/Credits	
	www.vintageracingservices.com	BALANCE DUE	



(203) 377-6745 Fax (203) 386-0486





DATE

7/26/12

INV#

WS71M-25

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	129.59
Vlake ch Finan	necks payable to Automotive Restorations, Inc. ce charges are assessed monthly at 1.5% Www.automotiverestorations.com	Invoice Total Payments/Credits	\$13,920.02 \$-13,920.02
	www.vintageracingservices.com	BALANCE DUE	\$0.00



(203) 377-6745 Fax (203) 386-0486



DATE

8/30/12

INV#

WS71M-26

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	UABOR WORK PERFORMED 7/27/2012 TO 8/30/2012 METAL WORK Complete metal work per estimates and addendum. Included time indicinvoice) but not billed. Does not include floor per 9/13/12 addendum. A Repair and fabricate jack point areas, front and rear. Rebuild right front wing lower section, front of sill. Rebuild lower door sections, left and right. Rebuild lower rear valance inside and out, left and right. Rebuild left side front chassis outrigger. Repair various splits and fatigue cracks. Repair left front sill. Fit left and right moldings and rear molding. Repair front hood, align. Heat hinges as needed. HOURS BODY WORK Mask for epoxy primer. Sand epoxy primer. Weld holes in rear body panel, Apply mold repairs compound to lead repair & patches. Straighten, glaze and sand left & right quarters & doors. Glaze and sand trunk and adjust gaps. Glaze and sand roof and pillars to 180 grits. Align hood. Straighten edges to align with fender edges.	cated to date (7/08/42	
Make ch	necks payable to Automotive Restorations, Inc.	Invoice Total	
	www.automotiverestorations.com	Payments/Credits	
www.vintageracingservices.com		BALANCE DUE	



(203) 377-6745 Fax (203) 386-0486



DATE

8/30/12

INV#

WS71M-26

	1971 Maserati Ghibli			
	RO # 2021			
QTY/HRS	DESCRIPTION		COST	AMOUNT
160.5	Straighten, glaze and sand nose, headlights and hood. Mask for polyester spray fill. Hand block sand entire exterior poly fill application including hinged panels Mask for primer. HOURS	etc.	05.00	
			85.00	13,642.50
	PAINT WORK Spray out MAZ 106G30 Verde Pinto Indi stk#526940. Mail sample to client Solvent wash and epoxy primer left and right doors.	for approval.		
	Epoxy prime body and doors.			
	Prime headlight buckets, fender slats, headlight trim and fuel door. Apply polyester spray filler.			
	Apply (5) coats 285 primer.			
9.1	HOURS		100.00	910.00
	UPHOLSTERY			
0.0	Cover dash for media blast activity.			
0.9	HOURS		100.00	90.00
	WHEELS/TIRES			
1.1	Set car on jack stands. Remove wheels. Send wheels for new tire mounting HOURS	g and balance.	85.00	93.50
	COLLECTOR SERVICES			
	Deliver body parts (doors) to dry strip.			
Make ch	necks payable to Automotive Restorations, Inc.	Investor 3		
rinand	ce charges are assessed monthly at 1.5%	Invoice	otal	
	www.automotiverestorations.com	Payment	s/Credits	
	www.vintageracingservices.com	BALANG	CE DUE	



(203) 377-6745 Fax (203) 386-0486



DATE

8/30/12

INV#

WS71M-26

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
4.5	Deliver body to & from dry strip. HOURS Labor Subtotal	65.00	
5.6 176.6 160.5 8.6 0.9 6 1	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES HRS ASST METAL WORK/FAB/WELD SUPPLIES HRS ASST BODY SUPPLIES HRS ASST PAINT SUPPLIES HRS ASST UPHOLSTERY SUPPLIES GLASURIT 55-1 106A2 - 55 LINE P/QT GLASURIT 923-255G - HS MULTI CLEAR P/GAL POLYESTER REFACE PRIMER PER/0.5 GAL Parts Subtotal	5.00 10.00 10.00 15.00 10.00 239.58 317.78 128.70	1,766.00 1,605.00 129.00 9.00 1,437.48 317.78
2	SUBLET MEDIA BLAST DOORS MEDIA BLAST EXTERIOR BODY Sublet Subtotal	116.00 1,769.00	
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	40,367.86 403.68 2,588.99
Make ch	ecks payable to Automotive Restorations, Inc. be charges are assessed monthly at 1.5%	Invoice Total	\$43,360.53
	www.automotiverestorations.com	Payments/Credits	\$-14,113.04
	www.vintageracingservices.com	BALANCE DUE \$	29,247.49

-1	FINISH RESTORATION ESTIMATE
	DATE: REV 2, 3-8-2012 REV 3, 4-19-12 REV 4, 5-5-12 REV 5. 7-2-12
2	per lines 705-06 REV 8, 9-13-12 per line 723
3	VEHICLE: 1971 Maserati Ghibli Coupe
4	JOB#:2021
5	OWNI
6	ADDR
7	CITY/
8	PHON
10	EMAI
11	
12	NOTE ON LABOR RATES




Automotive Restorations Inc. 100 Lupes Drive Stratford, Connecticut, 06615 203-377-6745 fax 203-386-0486 www.automotiverestorations.com

13 Labor Rate: High skill: Mech Tech/Metalwork/Paint/Fabrication/Upholstery \$100.00/hour
14 Mid Skill: Body & Assembly \$85/hour. Base Skill: Polishing, Gen Prep, Detail \$65/hour

This is an estimate for the work described. It is not to be construed as a firm quote for the price contained herein. The nature of restoration work often requires disassembly beyond visual inspection at which time components can be fully evaluated. Additional work discovered during this process is beyond the scope of this initial estimate. Please note our +/- 20% contingency included to address the nature of our work per our terms and conditions statement above the acceptance signature area of this estimate. Additional time and/or parts and materials may be needed to properly complete the job. Should this occur, we will advise you, request approval, and amend the estimate accordingly. For this reason, the final price of the completed work may differ from the estimate as of this date.

24	Labor P			arts & Sublet	Total
25 Item 26 Control of the control of	Hrs.	Amount	Materials	Oublet	L + P&M + S
27 II. EVALUATION & ROAD TEST L01a/L12					
28 Completed					
43 EVALUATION & ROAD TEST TOTAL	0.00	0.00	0.00	0.00	0.00
44	0.00	0.00	0.00	0.00	0.00
45 IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows:					
GLASS: Remove windshield and backlight compression strips to install a bead					
and lift seal edges off paint surfaces and allow finish penetration under seal					
46 Jareas. Hemove 1/4 glass, door top edge moldings and outer glass assessment					
This is not the state of the st	14.00	1,190	140		1,330
4/ Imirror, emblems and badges	8.00	000			
SEALS: door, trunk, fuel door, headlamp pod, fuel door and book early	0.00	680	80		760
48 Dumpers-stops.	5.00	425	50		
BUMPERS & GRILLS: Front and rear bumper assemblies and front air intake	0.00	423	50		475
49 Igrillwork.	7.00	595	70		
HARDWARE: door handles, jamb strikers & related door hardware, trunk lock	7.00	393	70		665
ou jand laten handles and hardware		_ [
FIXTURES; Head, side, park, license and tails lamps	12.00	1,020	120		0
PANELS; hood, 2.5 - doors, included per line 331 - trunk lid, 1.5 - Fuel doors, 1 -		1,020	120		1,140
oz meadiamp pogs. 6.5			1111111111111		
REPLACE ON REASSEMBLY AS FOLLOWS:	11.50	978	112		1,090
Allotment for seals that cannot be R&R'd without damage		-			0
Allotment for factorers that fall are target to the	2.00	170	500		670
Allotment for fasteners that fail, are tarnished or cannot be R&R'd without damage					
o duniage		-	300		300
Allotment or re-plating of bright work that does not also were the					300
Allotment or re-plating of bright work that does not clean up satisfactorily. We					
think most will be to acceptable levels once polished though it is difficult to be					
at the 100th percentile until underway. A reasonable plating expectation along with time to polish all is included right					
50 DISASSEMBLY TOTAL	12.00	780	120	3,000	3,900
61	71.50	5,837.50	1,492.00	3,000.00	10,329.50
22 V. DRIVETRAIN LO2				_,500,00	10,023.30
4 IV. UNIVERSAINTID		THE RESERVE AND ADDRESS OF THE PERSON NAMED IN			

	Complete diagnosis of engine noise occurring @ 4000 RPM. Timing chain is				<u> </u>	
64	suspect source, adjustment may correct. Adjust and advise.	3.00	200	4.5	1 1	2000
79	ENGINE TOTAL	3.00	300.00	15	0.00	315
80	Tune L02b	5.00	300.00	15.00	0.00	315.00
	Service: Full safety/function check. Drain flush and refill fluids & filters as					
81	necessary. Send labs. (Use up to \$1500 WISELY) Report anything significant.	0.00				
96	TUNE TOTAL	6.00	600	250		850
_	Cooling System L02c	6.00	600.00	250.00	0.00	850.00
	Remove, re-core, refinish and refit radiator to correct corroded leaking cooling					
98	tubes and fins. Drain-flush system, replace coolant	4.00	400	120	950	1 470
113	COOLING SYSTEM TOTAL	4.00	400.00	120.00	950.00	1,470.00
31	Exhaust System L02e		100.00	120.00	330.00	1,470.00
	Note stainless system creates some resonance and added noise in cockpit					
132	especially with windows up.					
147	EXHAUST SYSTEM TOTAL	0.00	-			0
182	TOTAL DRIVETRAIN	0.00	0.00	0.00	0.00	0.00
	VI. CHASSIS & SUSPENSION	13.60	1,360.00	415.00	950.00	2,725.00
	Wheels & Tires L03a					
			-			
	Remove wheels, dismount 4 tires. Medial blast and powder coat 4 wheels to					
30	restore silver finish. Refit tires, high speed precision balance with all weights		_			
200	fitted to the inside. Reinstall	2.00	170	40	1,200	1,410
291	WHEELS & TIRES TOTAL	2.00	170.00	40.00	1,200.00	1,410.00
	IX. WIRING & ELECTRICAL LOG					
293	Checkout lights and battery draw per email attached.			Later and		
300	TOTAL WIRING & ELECTRICAL	1.50	150	200		350
310	TOTAL WINING & ELECTRICAL	1.50	150.00	200.00	0.00	350.00
	X. STRUCTURE & BODY					
	Chassis L07a					
	Chaosid Edita		-			0
	Scrape to remove undercoat in key suspect areas. Initial prod shows this has					
	not started any serious decline yet but some added under seal over proper	1				
	preparation along with some 3M PustEighter inner need over proper		- 1			
313	preparation along with some 3M RustFighter inner panel protectant will do a lot					
313	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338	6.00	390	80		470
313	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth pop-	6.00	390	80		470
313	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mark	6.00	390	80		470
	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original.	6.00	390	80		470
	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original.					470
314	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL	10.00	850	130		980
314 329 330	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b				0.00	9.50.50
314 329 330 331	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance.	10.00 16.00	850 1,240.00	130 210.00	0.00	980 1,450.00
314 329 330 331 332	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer exist door costions.	10.00 16.00	850 1,240.00 850	130 210.00 60	0.00	980 1,450.00 910
314 329 330 331 332	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b	10.00 16.00 10.00 12.00	850 1,240.00 850 1,200	130 210.00 60 120	0.00	980 1,450.00 910 1,320
314 329 330 331 332 333	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds	10.00 16.00	850 1,240.00 850	130 210.00 60	0.00	980 1,450.00 910 1,320
314 329 330 331 332 333	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accept	10.00 16.00 10.00 12.00 4.00	850 1,240.00 850 1,200	130 210.00 60 120	0.00	980 1,450.00 910 1,320
314 329 330 331 332 333	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section.	10.00 16.00 10.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800	130 210.00 60 120	0.00	980 1,450.00 910 1,320 380
314 329 330 331 332 333 334 335	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section.	10.00 16.00 10.00 12.00 4.00 18.00 12.00	850 1,240.00 850 1,200 340 1,800 1,200	130 210.00 60 120 40	0.00	980 1,450.00 910 1,320 380 1,980
314 329 331 332 333 334 335 336	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds	10.00 16.00 10.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800	130 210.00 60 120 40	0.00	980 1,450.00 910 1,320 380
314 329 330 331 332 333 334 335 336	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section.	10.00 16.00 10.00 12.00 4.00 18.00 12.00	850 1,240.00 850 1,200 340 1,800 1,200	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
314 329 330 331 332 333 334 335 336	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
31 32 33 34 35 36 37	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section Remove seats interior kick and guarter panel trims, refit following body.	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
31 32 33 34 35 36 37	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section Remove seats interior kick and quarter panel trims, refit following body restoration. Scrape to remove coatings and mastics. Remove exterior replaces	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
314 329 330 331 332 333 336 337	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section Remove seats interior kick and quarter panel trims, refit following body restoration. Scrape to remove coatings and mastics. Remove exterior rockers as needed to access inner rocker box sections.	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
31 32 33 34 35 36 37	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section Remove seats interior kick and quarter panel trims, refit following body restoration. Scrape to remove coatings and mastics. Remove exterior rockers as needed to access inner rocker box sections. Replace corroded, structural inner rocker panels per photos, adjoining braces/supports (25 bys. ellected to	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
314 329 331 332 335 336 337	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section Remove seats interior kick and quarter panel trims, refit following body restoration. Scrape to remove coatings and mastics. Remove exterior rockers as needed to access inner rocker box sections. Replace corroded, structural inner rocker panels per photos, adjoining braces/supports (25 hrs. allotted to same, not visible at present but some decay likely) and adjoining floor sections.	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320 380
314 329 330 331 332 333 334 335 336 337	preparation along with some 3M RustFighter inner panel protectant will do a lot of good here. Some done to expose damage per lines 334-338 solvent soak and hot water pressure was per above to remove/smooth non-original coatings and sealers. Treat surface rust with conversion coating. Mask and apply textured underbody sealant to appear and function as original. Treat inner body cavities and rocker box sections with 3M Rustfighter CHASSIS TOTAL Body Structure L07b Remove and refit doors for repair, align and clearance Fabricate and install new left lower 4" up outer skin door section Clean and treat interior left door dress welds Fabricate and install new right lower 4" up front and 12" seamed below accent line rear outer door skin section. Fabricate and fit forward to near center lower door frame sections Clean and treat interior right door dress welds Fabricate and fit left rear trunk lid corner skin section Remove seats interior kick and quarter panel trims, refit following body restoration. Scrape to remove coatings and mastics. Remove exterior rockers as needed to access inner rocker box sections.	10.00 16.00 10.00 12.00 4.00 18.00 12.00 4.00	850 1,240.00 850 1,200 340 1,800 1,200 340	130 210.00 60 120 40 180 120 40	0.00	980 1,450.00 910 1,320 380 1,980 1,320



Compound and polish surfaces 3 x. Coarse, medium and fine micro finishing					
materials. Clean residues and hand polish hard to reach areas.	30.00	2,550	300		2,850
403		-			0
104 EXTERIOR PAINT SURFACES TOTAL 105 Interior Paint Surfaces	222.00	18,960.00	4,880.00	600.00	24,440.00
406 Prepare and paint door jamb surface on doors and body shell	14.00	1,190	210		4 400
107 Prepare and paint interior hood panel and gutter surfaces	7.00	595	210 115		1,400 710
408 Prepare and paint interior trunk lid and gutter surfaces	6.00	510	90		600
109 Prepare and paint interior headlamp pod surfaces	3.00	255	55		310
Prepare and paint interior fuel doors and fuel door cavity surfaces.	3.00	255	55		310
Fit all panels, mask interior areas off for exterior topcoat applications in metallic					
111 finish. 122 INTERIOR PAINT SURFACES TOTAL	5.00	425	75		500
423 Underbody L08d	38.00	3,230.00	600.00	0.00	3,830.00
124 See line 313					
140 UNDERBODY TOTAL	0.00	- 0.00	0.00		0
TOTAL SURFACE FINISHES	0.00	0.00	0.00	0.00	0.00
142	260.00	22,190.00	5,480.00	600.00	28,270.00
884 XVI. OTHER COSTS					
598 TOTAL OTHER COSTS	0.00	0.00	0.00	0.00	
					0.00
	0.00	0.00	0.00	0.00	0.00
700 XVII. ADDITIONS	0.00	0.00	0.00	0.00	0.00
	16.00	1,360	680	0.00	
5-4-12: PENDING POST FINISH TESTING: Added time to completely remove/refit glass, door jamb trims and trunk/hood gutter fittings and all hinged body panels as needed for complete strip-refinish replacing seals/fasteners as and where needed on assembly Strip existing finishes to bare metal addition due to quantity of material on vehicle. (3x finishes, heavy film layer). Plastic medial blast to clean surfaces.	16.00	1,360	680	0.00	2,040
5-4-12: PENDING POST FINISH TESTING: Added time to completely remove/refit glass, door jamb trims and trunk/hood gutter fittings and all hinged body panels as needed for complete strip-refinish replacing seals/fasteners as and where needed on assembly Strip existing finishes to bare metal addition due to quantity of material on				0.00	
5-4-12: PENDING POST FINISH TESTING: Added time to completely remove/refit glass, door jamb trims and trunk/hood gutter fittings and all hinged body panels as needed for complete strip-refinish replacing seals/fasteners as and where needed on assembly Strip existing finishes to bare metal addition due to quantity of material on vehicle. (3x finishes, heavy film layer). Plastic medial blast to clean surfaces and prepare jambs and gutters.	16.00	1,360	680	0.00	2,040 970
5-4-12: PENDING POST FINISH TESTING: Added time to completely remove/refit glass, door jamb trims and trunk/hood gutter fittings and all hinged body panels as needed for complete strip-refinish replacing seals/fasteners as and where needed on assembly Strip existing finishes to bare metal addition due to quantity of material on vehicle. (3x finishes, heavy film layer). Plastic medial blast to clean surfaces and prepare jambs and gutters. Remove front and backlight glass completely (seals too hard and will not allow compression strips out without damage). Remove door and 1/4 glass as we not corrosion that should be treated under door and 1/4 can moldings and this will.	16.00	1,360 850	120	0.00	2,040

I

I

_						
708		15.00	1,500	150		1,650
709	Replace poorly patched left and right front fender aft of axle to rocker seam.		-			0
710		16.00	1,600	160		1,760
				P		
711	Replace small left and right outer wheel arch corrosion areas		-			0
712		5.00	500	50		550
	Repair and reinforce cowl/firewall panel cracks on left and right rear engine bay wall.					0
714		6.00	600	60		660
715	Remove fuel tank and lines to facilitate rear lower body panel restoration. Refit	8.50	850	50		000
	Replace exterior rocker panels and related interior brace panels on a sectional					900
716	basis estimate capped basis per figures right 8-14 Add'l to recore radiator	42.00	4,200	550		4,750
/1/	8/20/2012 PENDING With complete strip of car ALL surfaces including factory		-		1,000	1,000
718	original seams etc need straighten and glaze. Magnitude and scope with strip significantly larger. 8/20 PENDING AS WITH ABOVE: Scope of sanding the polyester filler increaed	40.00	3,400	400		3,800
719	with strip	30.00	2,550	300		2,850
720	8/20 PENDING AS WITH ABOVE: Scope of final primer application and sand increased	30.00	2,550	300		
721	8/20 PENDING AS WITH ABOVE: Scope of paint time increased 8/20 PENDING AS WITH ABOVE: Scope of final colorsand, comound and polish	10.00	1,000	350		
722	increased	20.00	1,700	100		1,800
723	Replace corroded (and perviously disguise patched) right floor section.	12.00	1,200	120		1,320
724			-	120		0
775	TOTAL ADDITIONS	202 50	26 580 00	3 030 00	1 000 00	21 510 00

726						
727	Total Labor Hours	850.10				
728 729	Total Labor		76,557.50			
729	Total Parts & Materials			13,657.00		
730	Total Sublet				3,750.00	area poet
731	Amount Subject to Sales Tax					93,965
732	Sales Tax			6.35%		5,967
733	Grand Total					99,931

ACCEPTANCE

I do hereby authorize the preceding repair/restoration work to be done along with all necessary parts and materials. You and your employees may operate the vehicle for purposes of testing, inspection and delivery at my risk. An express mechanics lien is acknowledged on the vehicle to secure or partially secure the amount of repairs thereto. It is understood that I will be held responsible for any cost of collection or legal expense in any way relating to these repairs. I agree to that any controversy or claim rising out of or relating to this agreement, or the breach of this agreement, shall be settled by arbitration in accordance with the rules of the American Arbitrations Association. A judgment of a court having jurisdiction may be entered upon the arbitrator's award. I agree to pay interest on any balances remaining unpaid after 30 days at the standard Automotive Restorations Inc. invoicing rate applicable to the period of time the debt exists. It is also understood that Automotive Restorations Inc. it's officers, agents or employees will not be held responsible for loss or damage to cars or articles left in cars due to fire, theft, or any other cause beyond their control. I will maintain insurance on the vehicle for the period of time it is in the custody of Automotive Restorations Inc. Parts, materials and labor prices are current and subject to change. Occasionally worn or damaged parts/areas are discovered which are not evident on initial inspection. For these reasons the above prices are not guaranteed. The figures provided are an estimate of the time needed invoiced at our labor rate, plus the cost of parts and materials expected to be required. Due to the nature of restoration work all figures given are offered as guidelines only and are subject to a +/- 20% cost range for the specific parts/labor/materials described in this document. We may find work, parts and materials needed that are not described in this document. Should this occur, we will advise of any additional work needed not described herein to seek authorization prior to undertaking repair.

I HAVE READ THE FOREGOING AND AGREE TO THE TERMS STATED THEREIN.

Signature	te
Print name	