

TESTING ENGINEERS, INC 2811 Teagarden Street, San Leandro, California 94577 - (510) 835-3142 Fax (510) 834-3777

WR No: P073				INSPECTION REPORT		
		Perrari 500	ASSESSMENT PROPERTY.	Tage 1011		
Project No: F5T000 Customer: Same		44 Clevela				
Location: NDT LAB	City/State: /	Albany, CA	i D. Di	Part/ Serial No.: NA		
LOCATION. NOT LAB	Item: F	Rear Suspens	ion DeDic	ion Tube Examination: Partial X 100%		
NDE Standard: ASTM	E709	A	ccentance	ce Standard: No Cracks		
Material: Type: C/S	Temp: Ambient			ocedure No.: SPP-MT-211 REV. 3		
	s Final Heat Tre	atment:		Inspection After Inspection N/S		
Type of Work: New 🛛	Repair Maintenance	Insp.		Surface Condition: Grit Blasted		
		Alexander and the second				
Equipment Manufacture			Tecl	chnique:		
Mag. Unit: Model: ARQ-966 S/N No.: 52377 Black Light: Model: ZB-100F S/N No.: J-12744				Fluorescent: Visible: Wet: Dry:		
Black Light: Model: ZB-100F S/N No.: J Consumable Manufacturer: MAGNAFLUX CORP.				: DC: Continuous: Residual:		
Particle Type: 14A Pow		THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME		ad Amperage: 1500		
Medium: Carrier II				l Amperage: 2000		
Medium: Carrier II Batch No.: 11L044 Other NDT Required: Yes: ☐ No: ☒ Type:				Central Conductor Amperage: NA Demagnetized: Yes: ☒ No: ☐		
	от <u>ш</u> пот <u>м</u> турс.		1 Delli	naghetized. 1es. ⋈ No: □		
DESCRIPTION- PC	# or SN #			·		
		Acc.	Rej.	REMARKS		
		22001	riej.	ALDIANG		
Rear Suspension DeDion T	onhe.	1	0	The Committee Table and Early L. C.		
/		1	U	The Suspension Tube was found to be free of any cracks		
				CIACKS		

The results presented in this report relate only to the items(s) tested.

This report can be reproduced only in its entirety unless written permission from TEI is obtained

Samples pertaining to this report will be discarded 30 days from the date of this report unless other wise advised

