PARTSHEAVEN
23694 BERNHARDT STREET
HAYWARD, CA 94545
(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250
www.partsheaven.com

SOLD TO [redacted]

ACCT. NO. [redacted] Invoice No. [redacted]

TERMS	CASH	CHARGE	C.O.D.	R.O.A.	CREDIT	PHONE NUMBER	ORDER BY	DEPARTMENT	P.O. NUMBER	DATE ORDERED
	Card					[redacted]				10/05/09

WORK ORDER NO.	MAIL COPY	DISMANTLER	READY	CORE EXCHANGE	R/O NUMBER	TRUCK LINE	SALES PERSON	SHIPPING DATE
209477							JW	10/05/09

ITEM / DESCRIPTION	STOCK NO.	LOC.	AMOUNT
HEADLIGHT WASHER PUMP 1 PORSCHE 911 (Extra Sale) 82 #0001	#		20.00 T
HEADLIGHT NUT 2 PORSCHE 911 (Extra Sale) 82 #0002	#		1.00 T
Doc # :86962			

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:
NO CASH REFUNDS
NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE, IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A $15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL	21.00
SALES TAX	2.05
SHIPPING CHARGES	0.00
TOTAL	23.05

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 23.05
Amount due: 0.00

HIGH PERFORMANCE HOUSE

Since 1976 Serving Bay Area Porsche Owners

2431 Spring Street
Redwood City, CA 94063-3019
(650) 364-6234
BAR # ARD00062731 • EPA #CAL000030595

Date 9.5.12 — 16106
Time Received — Written By LARRY
A.M. / P.M. — Cust. Order No.
Promised A.M. / P.M. — Phone when ready Yes ☐ No ☐

Name [redacted]
Address
City

Year-Make-Model 82 911 — License No. 1GTK981 — Odometer 106,393 — Parts SAVE ☐ DISCARD ☐
Estimate Amount $ 1000.00 — VIN Number WP0AA0511FC612107

Revised Estimate $ 2000.- — Date 9.6.12 — Time 11:15 — Description ADD PARTS & LABOR — Authorized By FRED — INITIAL LF
Revised Estimate $ 2500 — Date 9.7.12 — Time 2:45 — Description ADD PARTS & LABOR — Authorized By FRED — INITIAL LF

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

*CODE N-NEW U-USED R-REBUILT

	*	PART NO. OR DESCRIPTION			SALE
1	N	FT BRK PAD SET			49 95
1	N	SS BRAKE LINE SET			1FREE
1	N	ENG MD SHOCK			34 95
6	N	SPARK PLUGS	2 95		17 70
1	N	RH CAM LINE			25 95
1	N	HOT AIR HOSE			19 95
2	N	OIL DRAIN GSKT	2 00		4 00
1	N	OIL LINE			119 95
	N	BRK FLUID			10 00
1	N	OIL RETURN TUBE SET			149 95
3	N	SPRAY CLEANER	4 95		14 85

RITE-WAY ELECTRIC

261 6th STREET
SAN FRANCISCO, CA 94103
(415) 882-4444
(800) 732-8863

When you only want the Best.

Invoice Number: 82400

Invoice Date: 10/11/13

ld To: CASH2

Ship To: CASH2

Customer ID	Customer PO	Payment Terms	
CASH2		C.O.D.	
Sales Rep ID	Shipping Method	Ship Date	Due Date
.IR			10/11/13

Quantity	Item	Description	Unit Price	Extension
1	16426	PORSCHE STARTER	189.90	189.90

Paul
VISA

CELEBRATING 70 YEARS OF PERSONAL SERVICE

REBUILDING SPECIALIST SINCE 1939

ALTERNATORS - STARTERS - GENERATORS - DC MOTORS

RECEIVED BY / AUTHORIZATION

Subtotal	189.90
Sales Tax	16.62
Freight	
Total Invoice Amount	$206.52
Payment Received	206.52
TOTAL DUE	0.00

THANK YOU!

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 07/01/2014 @ 08:49

Model Year:	1982	Make:	PORSCHE	Model:	911 SC
License:	1GJK980	State:	CA	VIN:	WP0AA0911CS121075
Engine Size:	3.0 L	Type:	Passenger	Transmission:	Manual
GVWR:	N/A	Test Weight:	3000	Cylinders:	6
Odometer:	107706	Certification:	California	VLT Record #:	15346
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	Change of Ownership

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: PI377496
DMV ID Number: **7341I801P755**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	N/A	Air Injection	N/A	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Ignition Timing: 3 BTDC		
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		$\%CO_2$	$\%O_2$	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1566	14.3	0.4	142	36	26	1.00	0.14	0.08	1148	419	856	PASS
25 mph	1722	14.3	0.3	113	27	28	0.80	0.13	0.13	978	350	845	PASS

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

SMOG QUEEN
160 10TH STREET, SAN FRANCISCO, CA 94103
415-252-0733
Station Number: RC261775

Technician Name/Number: PINI, GONZALO/EO633462
Repair Tech Name/Number:
Software Version/EIS Number: 1301/ES314845

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7/1/14
Date

Technician's Signature

Charles P Rossignol
1480 Howard St.
San Francisco, Ca 94103
415-519-9723
Bar ard - 00259744

388

total 2 bills = 3281.66

[redacted]

2
1987 Porsche 911SC
VIN: WPOAA0911CS121075
LIC: 1GJK980
Mileage: 107728

3-Jul-14

R
INV
8/3

pd ck# 5103 8/3/14

Quantity	Part Number	Description	Cost Each	Cost
1		Hirshman power antenna (used)		$25.00
2	911 631 259 02	Headlight bucket drain	4.20	$8.40
2	911 631 115 02	Headlight gasket	4.68	$9.36
2	TS-G1344R	Pioneer 2-way 51/4 inch speaker		$49.95
2	911 355 013 01	speaker grills	40.00	$80.00
1	MTP-48H6	Interstate battery		$136.90
1	911 355 217 00	speaker plastic housing (used)		$10.00
			Total Parts	$319.61

Hourly Rate
$130.00

1	R&R headlight assemblies, disassemble to repaint rims. Reinstall & adjust Replace seals & drain tubes	$130.00
0.5	Install used power antenna	$65.00
2	Remove original door panels Lube window & door latch mechanisms Install used vinyl panels, speakers & grills	$260.00
0.5	Remove Ungo Box alarm Remove windshield antenna	$65.00
0.5	Reinstall rear jump seats	$65.00
3	Lower chassis 2" rear, adjust front for proper rake	$390.00

Charles P Rossignol
1480 Howard St.
San Francisco, Ca 94103
415-519-9723
Bar ard - 00259744

0.5	R&R stereo head unit to tidy up wiring, and properly anchor head unit. Replace ventilation control illumination bulbs while head unit was out		$65.00
0.5	R&R steering wheel to reattach floppy plastic swich surrounds causing excessive cowl type noise, lube horn brush		$65.00
0	Replace weak battery, clean battery area		$0.00
	Paint headlight rims	Sublet	$120.00
	Four wheel alignment	Sublet	$245.00
		Total Parts	$319.61
		Total Services	$1,470.00
		Sales Tax	$27.97
		Total	~~$2,182.58~~
			1817.58

Charles P Rossignol
1480 Howard St.
San Francisco, Ca 94103
415-519-9723
Bar ard - 00259744

[redacted]

1981 Porsche 911SC
VIN: WPOAA0911CS121075
LIC: 1GJK980
Mileage: 107728

3-Jul-14

Quantity	Part Number	Description	Cost Each	Cost
1	999 703 077 40	Trim plug		
1	928 110 147 05	Mahle fuel filter		$32.70
1	930 107 764 01	Mahle oil filter		$14.84
2	901 423 253 00	Engine throttle bushing (bronze)	$2.38	$4.76
1	PK 03	Valve cover gasket set		$60.66
2	930 101 391 01	Oil sump gasket	$4.28	$8.56
1	03 008	Bosch distributor cap		$33.96
1	930 602 902 00	Bosch ignition rotor		$8.80
2	915 301 139 00	Clutch release seal	$2.40	$4.80
1	10 X 710	Fanbelt		$8.76
21		Assorted amp fuse	$0.25	$5.25
2	40113	Bosch wiper blade	$9.00	$18.00
1		Rear wheel cotter		$0.10
1	911 615 109 01	Multiple relay (black)		$27.34
1		A/C crossover relay		$12.00
			Total Parts	$240.53

Hourly Rate $130.00		
7	Major Service	$910.00
0.75	Replace throttle bushings on engine Lube & adjust linkage for full throttle	$97.50
0.5	Reset clutch cable at pedal, R&R helper spring assembly at gearbox. Clean, lube & adjust	$65.00
0.5	Adjust right front wheel bearing Tighten right rear wheel bearing	$65.00
0.25	Tighten rear shock top mounts	$32.50

Charles P Rossignol
1480 Howard St.
San Francisco, Ca 94103
415-519-9723
Bar ard - 00259744

0.25	Diagnosis of A/C system Replace crossover relay	$32.50
	condensor fan at battery - noisy -disabled fan clutch works, Ventilation fan works	

Total Parts	$240.53
Total Services	$1,202.50
Sales Tax	$21.05
Total	$1,464.08

DENT EXPERT

650 349-3368 OR 650 FIX-DENT

PAINTLESS DENT REMOVAL

see before and after pics: www.dentexpertSAL.com

DATE: 7-2-14 INVOICE# 1141171

CUSTOMER: [redacted] CITY: SF

ADDRESS: PHONE:



TOTAL DUE: 785

Dent Expert mailing address: 326 24TH AVENUE SAN MATEO, CA 94403

Agreement: customer signature below or check or purchase order received by Dent Expert or subcontractors of Dent Expert completes an agreement by both Dent Expert and above customer that the described work above is completed to the satisfaction of the customer(s) which ends any further liability to Dent Expert for the above vehicle(s) or objects.

CUSTOMER: DATE: TECHNICIAN: DATE: 7/2/14

Howard Swig <howardswig@gmail.com>

Receipt from Sal Contreras

1 message

Square <noreply@messaging.squareup.com> Mon, Jul 21, 2014 at 12:40 PM

[redacted]

Things just got easier. Now when you shop at sellers who use Square, your receipts will be delivered automatically. Learn more.

PAID 7/21/14
w/ SFAC Visa

Sal Contreras

Jul. 21, 2014 at 12:39pm

$791.00

1 Item	Receipt #GOV0
Custom Amount	$791.00
Total	$791.00
Visa 5628	

© 2014 Square, Inc. All rights reserved.
1455 Market Street, Suite 600, San Francisco, CA 94103
Square Privacy Policy

Not your receipt?

----->---->---->--Continued on the next page--->---->---->------>

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 11/13/18 04:23 pm
Paid: 11/14/18 05:21 pm
Invoice No. 16086

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627

[redacted]

82 PORSCHE 911 White
109963 Mi.
Lic: ? H6Cyl 3.0 Eng
Vin: WP0AA0911CS121075
Eq:

NEEDS:
-tires (dated 2008)
-carrera chain tensioners
-left cam oil line (dripping oil)
-hood shocks
-hatch strut
-left side washer nozzle (inop)
-door contact switch
-motor mounts
-roll front fenders
-left seat belt

Oil Service, 911s/sc — Labor: $180.00

Change engine oil and filter, set tire pressure, inspect vehicle for safety
Brakes: front= 10mm rear= 9mm
Tires: front= 6/32" rear= 6/32" (Datestamp 2008)

OC54	Oil Filter	1.0 @	12.00 =$	12.00	
GASKET	Copper Gasket	2.0 @	1.00 =$	2.00	
MOTUL 20W50	Engine Oil	10.5 @	11.00 =$	115.50	129.50

Job Subtotal: $309.50

Knock @ Idle, Chk Tensioners — Labor: $0.00

Customer states: audible more when cold, and only @ idle --> seems to be coming from bank 2 (right side of vehicle) timing chain area --> recommend disassemble for diagnosis and also update to Carrera chain tensioners.

Job Subtotal: $0.00

Brake Fluid Flush — Labor: $180.00

Flush the brake hydraulic system on all 4 corners.

706232	Brake Fluid 200	1.0 @	18.00 =$	18.00	18.00

Job Subtotal: $198.00

------->---->---->---Continued on the next page--->---->----->------>

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 11/13/18 04:23 pm
Paid: 11/14/18 05:21 pm
Invoice No. 16086

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627

Payments to Hi Tec Auto

Status: Paid Work Order

Payments: $520.78

1	11/14/18	520.78	Check	5756

Cost Summary

Labor	360.00
Parts	147.50
Tax	13.28
Total	$520.78
Payments	520.78
Bal Due	0.00

Thank you for choosing Hi Tec Auto

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Porsche 911 Inspection

INTERIOR

☑ Horn
☑ Windshield wipers
☐ Windshield washer system L side no spray, headlight washers ings
☑ Interior Light function door switch contact going bad
☑ Exterior light function

FRONT hood shocks

☑ Battery • scan • hold down • cables 542 CCA recharge
☑ Check alternator charging output voltage 14V
☐ Brake fluid scan > 4%

REAR hatch struts

☑ Drive belt condition
☑ Fuel line condition (check "T" hose on 911 Carrera) no engine load
☐ Motor mount condition worn out

UNDERSIDE

☑ Brake hose condition stainless
☑ Brakes: front = 10 rear = 9
- additional observations:

☑ Tires: front = 6 rear = 6
☐ Tire Date Stamp x 4: 2008
- additional observations: front fenders need to be rolled-FL chewed up

☑ Wheel bearing adjustment / freeplay
☐ Engine oil leaks & plumbing evaluation B1 cam oil line, thermostat o-ring?
☐ Transmission leaks square shift plate
☑ Steering system leaks (if applicable)
☑ Axle boot condition
☑ Suspension damper leaks
☑ Suspension control arm/spring plate and bushing condition
☑ Suspension sway bar and bushing condition
☑ Steering rack boot and tie rod condition

TEST DRIVE: Clutch engagement, smoothness of operation and pedal effort, smooth idle, smooth shifting, smoking from vehicle/engine/exhaust, steering wheel on center, vibrations at speed, brake function, over all driving impression: good

WHITMAN'S AUTO BODY, INC.

B.A.R. #AD215745

EPA#CAL000055182 *FINAL BILL*
76 Woodland Ave
San Rafael, Ca 94901-5121

Phone 1:(415)-456-9831
Phone 2:( )- -
Fax :(415)-456-0490

VISIBLE DAMAGE QUOTE

Date: 07/24/19 Page 1 Est 22686 Est Date: 07/24/19

Name [redacted]
Addr
Addr2
City
Phone Bus -
Fax

Car :1982 PORSCHE 911 SC
VIN :
Lic #: Mi: 0
P/Dat: / / Paint:
Color:
Hat #:

#	Type Operation	Description	Units	Amount
1		FULL POLISH AND COMPOUND ENTIRE VEHIC		
2		TOUCH UP WHEN COMPLETED		
3		TOTAL JOB		400.00
4		PAINT MATERIALS		
5		BODY MATERIALS		

Labor Type	Units	Rate	Extension
Body	0.00	120.00	0.00
Structural	0.00	130.00	0.00
Refinish	0.00	120.00	0.00
Glass	0.00	110.00	0.00
Frame	0.00	130.00	0.00
Mechanic	0.00	150.00	0.00

New Parts	0.00
Paint Materials	0.00
Body Materials	0.00
Other	400.00
Tax	0.00
TOTAL	400.00
Grand Total	400.00

Estimator Name:

PAID

7/22/19

ck # 5833

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 09/16/21 02:29 pm
Paid: 09/16/21 02:46 pm
Invoice No. 19962

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627

[redacted]

82 PORSCHE 911 White
109963 Mi.Last in 11/13/2018
Lic: ? H6Cyl 3.0 Eng
Vin: WP0AA0911CS121075
Eq:

Steering Wheel Repair — Labor: $60.00

Install steering wheel bearing spacer sleeve.

92834773902	Steering Wheel Sleeve	1.0 @	18.00 =$	18.00	18.00

Job Subtotal: $78.00

Payments to Hi Tec Auto

Status: Paid Work Order

Payments: $79.67

1	09/16/21	79.67 Visa	1

Cost Summary

Labor	60.00
Parts	18.00
Tax	1.67
Total	$79.67
Payments	79.67
Bal Due	0.00

Thank you for choosing Hi Tec Auto

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Lucas
CLASSIC TIRES

Invoice# 0000012371

Invoice Date: 08/25/2022 17:47:10

Billing Information: **Shipping Information:** **Payment Information:**

[redacted]

Items

Qty	Description	Price Each	Total
2	225/50YR16 PIRELLI CINTURATO™ P7 N4	$335.00	$670.00
2	205/55YR16 PIRELLI CINTURATO™ P7 N4	$299.00	$598.00

Subtotal:	$1,268.00
Tax :	$98.27
Shipping (FedEx Ground®) & Handling:	$72.34
Total:	**$1,438.61**
Balance Due:	**$1,438.61**

If you have any questions concerning this invoice, contact us immediately:
Phone: 800-952-4333
FAX: 562-595-0381
E-mail: lucastiresales@gmail.com
Website: www.lucasclassictires.com

Thank you for your business!
Car Nuts Serving Car Nuts Since 1957 -- 1(800)952-4333

Porsche 911 SC tires

Printed: 9/2/2022 2:38:15 PM
Store: 1

Sales Receipt #86996

9/2/2022
Cashier:
Page 1

Diamond Tire Center of Marin Inc
1133 Francisco Blvd East, Suite K
San Rafael, CA 94901
(415) 459-3808
BAR#ARD00245535 CA ID# 1439587-01

Bill To: [redacted]

YR_____ Make_____ Mdl_____ Lic_____ Mileage_____

Description 1	Attribute	Size	Orig Price	Disc %Type	Qty	Price	Ext Price Tax
Install4TR		InstallTR			1		
Balance		Balance	$20.00		4	$20.00	$80.00
Mount Tire Rack		Mount Tire	$10.00		4	$10.00	$40.00
TR Disposal			$4.00		4	$4.00	$16.00
TPMSTR/Valve Stem		TPMSTR	$5.00		4	$5.00	$20.00
Set Air Pressure on all tires		Set Air	$0.00		1	$0.00	$0.00

	Subtotal:	$156.00
Local Sales Tax	0 % Tax:	+ $0.00
	RECEIPT TOTAL:	**$156.00**

Credit Card: $156.00 Visa

Total Deposit Taken: $0.00
Balance Outstanding: $0.00

From Work Order #118272

All Labor has a 90 day Warranty We offer no mileage Warranty

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 09/03/24 09:07 am
Paid: 09/04/24 02:15 pm
Invoice No. 23796

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627

[redacted]

82 PORSCHE 911 White
109963 Mi.Last in 9/16/2021
Lic: ? H6Cyl 3.0 Eng
Vin: WP0AA0911CS121075
Eq:

NOTES:
-windscreen washer system inop
-battery tests weak but function seems okay
-fuel tank hoses original, but not cracking
-various minor engine oil leaks
-transmission shift seal & selector plate both wet
-shifting is more difficult due to short shifter

Oil Service, 911s/sc — Labor: $249.00

Change engine oil and filter, set tire pressure, inspect vehicle for safety
Brakes: front=8MM rear=8MM
Tires: front=8/32" rear=8/32"

OC54	Oil Filter	1.0 @	20.00 =$	20.00		
GASKET	Aluminum Gasket	2.0 @	1.00 =$	2.00		
MOTUL 20W50	Engine Oil 108081	10.0 @	11.00 =$	110.00	132.00	

Job Subtotal: $381.00

Brake Fluid Flush — Labor: $249.00

Flush the brake hydraulic system on all 4 corners.

706232	Brake Fluid 200	1.0 @	34.00 =$	34.00	34.00

Job Subtotal: $283.00

Odometer Repair — Sublet: $550.00

Sent out gauge for repair, approx 1-2 wks turn-around.

Payments to Hi Tec Auto

Status: Paid Work Order

Payments: $1,259.36
1 09/04/24 1259.36 Visa 2

Cost Summary

Labor	498.00
Parts	166.00
Sublet	550.00
Shipping	30.00
Tax	15.36
Total	$1259.36
Payments	1259.36
Bal Due	0.00

Thank you for choosing Hi Tec Auto

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Porsche 911 Inspection

INTERIOR

- [x] Horn
- [x] Windshield wipers
- [ ] Windshield washer system pump not working
- [x] Interior Light function
- [ ] Exterior light function drivers license plate bulb

FRONT

- [ ] Battery • scan • hold down • cables passed load test
- [x] Check alternator charging output voltage 14.1
- [ ] Brake fluid scan

REAR

- [ ] Drive belt condition cracking
- [ ] Fuel line condition (check "T" hose on 911 Carrera) small not attached
- [x] Motor mount condition

UNDERSIDE

- [x] Brake hose condition
- [x] Brakes: front = 8mm rear = 8mm
  - additional observations:
- [x] Tires: front = ~~27~~ 8 rear = ~~28~~ 8
- [ ] Tire Date Stamp x 4: 2021
  - additional observations:
- [x] Wheel bearing adjustment / freeplay
- [ ] Engine oil leaks & plumbing evaluation thermostat, camtower drips leak
- [ ] Transmission leaks shift shaft seal / bottom plate
- [x] Steering system leaks (if applicable)
- [x] Axle boot condition
- [x] Suspension damper leaks
- [ ] Suspension control arm/spring plate and bushing condition
- [ ] Suspension sway bar and bushing condition
- [x] Steering rack boot and tie rod condition

TEST DRIVE: Clutch engagement, smoothness of operation and pedal effort, smooth idle, smooth shifting, smoking from vehicle/engine/exhaust, steering wheel on center, vibrations at speed, brake function, over all driving impression: shift shifter harsh

Hi-Tec Automotive

Independent Porsche & Audi Service & Sales
We buy, sell & consign cars!

Order Date 12/15/25 10:32 am
Paid: 12/19/25 11:22 am
Invoice No. 25496

BAR #: AM 122034
779 Andersen Drive
San Rafael, CA 94901
Phone: 415-258-9619 FAX: 415-258-1627

[redacted]

82 PORSCHE 911 White
110392 Mi.Last in 9/3/2024
Lic: ? H6Cyl 3.0 Eng
Vin: WP0AA0911CS121075
Eq:

Oil Pressure Sender, 911 78-83 — Labor: $481.25

Replace oil pressure sender on top of engine.

911 606 230 00	Oil Pressure Sender	1.0 @	45.00 =$	45.00	45.00

Job Subtotal: $526.25

Payments to Hi Tec Auto

Status: Paid Work Order

Payments: $546.20
1 12/19/25 546.20 Visa 2

Cost Summary

Labor	481.25
Parts	45.00
Credit Card Fee	15.79
Tax	4.16
Total	$546.20
Payments	546.20
Bal Due	0.00

Thank you for choosing Hi Tec Auto

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____