

7101 Vorden Parkway
South Bend, IN 46628-8422
Phone: (574) 287-2345
800: (800) 428-8355
Customer Service: Ext. 360
Fax: (574) 236-7707

INVOICE


INVOICE NUMBER	INVOICE DATE	PAGE
A358484	8/10/09	1
PURCHASE ORDER NUMBER		
70009926		

3

8/10/09
18:13:10

BILL TO:

SHIP TO:



SHIP METHOD: UPS GROUND

SHIP-TO PHONE:

Plan 60092 Team TIRES Wave 006 Prcl 2282

ORDER DATE	SALES REP. NAME / PHONE EXT.	TERMS	MAKE, MODEL AND YEAR	WHSE	OPER.		
8/10/09	HUNTER (EXT 744)	VISA	308 85	NV	TRP		
PART NUMBER	QUANTITY ORDERED	QUANTITY SHIPPED	DESCRIPTION	UNIT PRICE	EXTENSION	LOC.	
64YR7SPORTPS2 44359	2	2	265/40R17 MI PILOT SP PS2 44359 96Y	259.00	518.00	9-	1
44YR7SPORT2V2 92706	2	2	245/40R17 MI PILOT SP PS2 92706 MO 91Y	228.00	456.00	9-	1
MICH1 WARRANTY	1	1	TIRE WARRANTY PACKET FORM# MDW41156	N/C		9-	1 15
REGCARDR REGISTRATION	1	1	TIRE REGISTRATION CARD -RETAIL RETAIL	N/C		A-	17533
TIRETOTE 00003 S.TIRE TOTE	2	2	SEASONAL TIRE TOTE WITH LOGO 00003 CONTAINS 2 TIRE BAGS CUSTOMER FITMENT: CUSTOMER ASSUMES RESPONSIBILITY FOR USE ON VEHICLE.	19.95	39.90	9-	1 2
			These tires may be eligible for Road Hazard Program coverage until 14 days following invoice date.				
			TOTAL THIS ORDER		1013.90		
			FREIGHT CHG/ALLW		55.67		
			VISA PAYMENT	1069.57-			
			Total Payment		1069.57-		
			You may register your Michelin Tires Online @ http://www.michelinman.com/tire-registration/				
			TOTAL AMOUNT DUE		\$.00	USD	

weight

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.

7101 Vorden Parkway
South Bend, IN 46628-8422
Phone: (574) 287-2345
800: (800) 428-8355
Customer Service: Ext. 360
Fax: (574) 236-7707

INVOICE

INVOICE NUMBER	INVOICE DATE	PAGE
B309234	1/13/10	1
PURCHASE ORDER NUMBER		
77915905		

2

1/13/10
15:13:08

BILL TO:

SHIP TO:

SHIP ME

Plan 77255 Team TIRES Wave 006 Prcl 2735

ORDER DATE	SALES REP. NAME / PHONE EXT.	TERMS	MAKE, MODEL AND YEAR	WHSE	OPER.	
1/13/10	ECOMMERCE ORDERS	AMERICAN EXPRESS	YOU CHOS	NV	TRP	
PART NUMBER	QUANTITY ORDERED	QUANTITY SHIPPED	DESCRIPTION	UNIT PRICE	EXTENSION	LOC.
145WR7PE2XL 55069	2	2	215/45R17~ MI PILOT EXALTO PE2 55069 91W XL	176.00	352.00	9- 1
MICH1 WARRANTY	1	1	TIRE WARRANTY PACKET FORM# MDW41156	N/C		9- 1 12
REGCARDR REGISTRATION	1	1	TIRE REGISTRATION CARD -RETAIL RETAIL	N/C		A- 16968
TIRETOTE 00003 S.TIRE TOTE	4	4	SEASONAL TIRE TOTE WITH LOGO 00003 CONTAINS 2 TIRE BAGS	19.95	79.80	9- 1
			Customer advised that mixing tire types/sizes or new with partially worn tires may cause unpredictable handling, braking or loss of vehicle control. New tires should be installed on the rear axle. CUSTOMER FITMENT: CUSTOMER ASSUMES RESPONSIBILITY FOR USE ON VEHICLE.			
			TOTAL THIS ORDER		431.80	
			FREIGHT CHG/ALLW		35.08	
			AMERICAN EXPRESS PAYMENT	466.88-		
			Total Payment		466.88-	
You may register your Michelin Tires Online @ http://www.michelinman.com/tire-registration/						
			TOTAL AMOUNT DUE		\$.00	USD
			Payable in U.S. Funds			

Weight

52

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.

America's Finest Corvettes

INVOICE

136 10th Street, Suite K
 Ramona, CA 92065
 (760) 789-8423 PH (760) 789-6601 FAX
 afc@corvetteusa.com

Date	Invoice No.
3/26/2010	5966

PAID

Bill To	Ship To
[REDACTED]	[REDACTED]

P.O. #	Year	Ship Date	Via	Terms
	1965	3/30/2010	UPS	Due on Receipt
Qty	Item Code	Description	Price Each	Amount
1	Wheel Set Restoration	Labor to Restore Customers KH Original Wheels	2,538.00	2,538.00
1	Suspension Restoration	Labor to Restore Customers F-40 Original Shocks/Suspension	2,380.00	2,380.00
1	Calipers (Restored)	Restored Set of Calipers	640.00	640.00T
2	Brake Pad (2-Axle, Set)	Brake Pads (2-Axle Set)	13.00	26.00T
	shipping	UPS Tracking #1z53e78e0342960255	149.72	149.72
			8.75%	58.28
			Total	\$5,792.00
<i><u>It's been a pleasure working with you!</u></i>			Balance Due	\$0.00

CORVETTE SPECIALTIES & MD. INC.

QUALITY NEW • USED & REPRO PARTS

1912 Liberty Road, Eldersburg, Maryland 21784
(410) 795-3180 Information - Technical Assistance
(800) 638-6450 Orders only - FAX (410) 795-3247
www.corvettespecialtiesofmd.com

NAME		DATE	
STREET		YEAR	
CITY & STATE		SOLD BY	
CASH	C.O.D.	INT. COLOR	EXT. COLOR
☐ COUPE	☐ AUTO	☐ 3-SPEED	☐ 4-SPEED
☐ CONV.	☐ AIR COND.	ENG. H.P.	YEAR
QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	New H.L. Motors		649 00
	19038102 485 Next Day UPS		96 00
			745 00
PO Pay Pal			
4840 3180			
Thank You		TAX	
		TOTAL	

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL - NO RETURNS AFTER 10 DAYS

RECEIVED BY

SEE REVERSE SIDE FOR WARRANTY INFORMATION

CS MD3/06




Crane's Corvette Supply
4687 Chateau Place • San Diego, CA 92117
Voice: (858) 864-2883 • Fax: (858) 514-8398
Email: corvette4u@aol.com
Website: <http://www.cranescorvette.com/>

<u>SALES ORDER</u>	<u>DATE</u>	<u>PHONE</u>	<u>FAX</u>	<u>CELL</u>	<u>EMAIL</u>
20636	4/9/2010				

BILL TO:

SHIP TO:



PART NUMBER	DESCRIPTION	UNIT PRICE	QTY	AMT
C-2818	CARB 2818 -1964-65 DATED 492 HOLLEY	\$ 875.00	1	\$ 875.00
BASE	BASE GASKET INCLUDED	\$ 0.00	1	\$ 0.00
SUBTOTAL				\$ 875.00
DISCOUNT				\$ 0.00
SALES TAX				\$ 83.13
SHIPPING				\$ 24.00
TOTAL				\$ 982.13

MONTHLY SPECIALS

NEW 1955-62 "POWER STEERING SYSTEM " AVAILABLE
\$1,945 GO TO WEBSITE FOR SAMPLE/INFO.






Crane's Corvette Supply
4687 Chateau Place • San Diego, CA 92117
Voice: (858) 864-2883 • Fax: (858) 514-8398
Email: corvette4u@aol.com
Website: <http://www.cranescorvette.com/>

<u>SALES ORDER</u>	<u>DATE</u>	<u>PHONE</u>	<u>FAX</u>	<u>CELL</u>	<u>EMAIL</u>
20694	4/28/2010				

BILL TO:

SHIP TO:



<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>UNIT PRICE</u>	<u>QTY</u>	<u>AMT</u>
ALT-65	DATED 64J ALTERNATOR REBUILT 37 AMP	\$ 435.00	1	\$ 435.00
TAX	TAX FROM \$775 RADIATOR	\$ 73.62	1	\$ 73.62

SUBTOTAL	\$ 508.62
DISCOUNT	\$ 0.00
SALES TAX	\$ 48.32
SHIPPING	\$ 18.45

TOTAL \$ 575.39

SALE

CRANES CORVETTE SPL
4687 CHATEAU PLACE
SAN DIEGO, CA 921171817
TID: 00000373836

TIME: 01:35 PM DATE: 05/05/10

MERCHANT #: 224216505996
VISA

VS xxxxxxxxxxxx2249 (KEYED)

INVOICE: 0000095003
APPROVAL CODE: 08065B
SEQ: 002
AVS: YY

TOTAL AMOUNT \$575.39

CUSTOMER COPY

MONTHLY SPECIALS

NEW 1955-62 "POWER STEERING SYSTEM " AVAILABLE
\$1,945 GO TO WEBSITE FOR SAMPLE/INFO.

NOTES

45

ECKLER'S®

FAMILY OF AUTOMOTIVE PARTS COMPANY
CHEVROLET * PERFORMANCE PRODUCTS

CUSTOMER SERVICE


1-800-327-4868



Customer No.	Order No.	Print Date/Time	
22412062-000	10771094-00002	5/05/10	8:51:44
Bin No.	Batch No.	Order Date	Page
001	0000970428	5/04/10	1
Sls#	P.O. Number	Order Type	Phone Number
298		INT	
Ship Via		Terms	
FEDX 2ND DAY		AMERICAN EXPRESS	

Sold To:

Ship To:



Location	Part No.	Shpd	UM	Description	B/O	Unit Price	Sale Price	Amount
D/S	A1959B	1	ST	Covers, St Vnyl Black, 1965 (28042-14) USA	0	359.99	359.99	359.99



Cust. #: 22412062-000

Order #: 10771094-00002

INSPECT CONTENTS OF
SHIPMENT FOR DAMAGES AND
SHORTAGES WITHIN 5 DAYS

PICK

PACK

Sale Amount	359.99
Shpg & Hndg	46.98
Sales Tax	37.83
Pkg Protect	1.95
COD Charges	.00
Total	446.75
Prepayment	446.75
Balance Due	.00

Comments:

RTL

ECKLER'S®

5225 South Washington Ave.
Titusville, FL 32780

ATTN: RETURNS DEPT.

ECKLER'S®

FAMILY OF AUTOMOTIVE PARTS COMPANY
CHEVROLET * PERFORMANCE PRODUCTS


CUSTOMER SERVICE
1-800-327-4868



Customer No.	Order No.	Print Date/Time	
22412062-000	10771090-00002	5/10/10	6:59:38
Bin No.	Batch No.	Order Date	Page
001	0000972135	5/04/10	1
Sls#	P.O. Number	Order Type	Phone Number
298		INT	
Ship Via		Terms	
FEDX 2ND DAY		AMERICAN EXPRESS	

Sold To:

Ship To:



Location	Part No.	Shpd	UM	Description	B/O	Unit Price	Sale Price	Amount
D/S	A1986B-65	1	ST	Carpet, Black Conv, 65-66 (28077-14)	USA	0	284.99	284.99
D/S	A8463	1	KT	Insulation Kit, Frt Cpe, 63-67	USA	0	91.99	91.99



Cust. #: 22412062-000
Order #: 10771090-00002

INSPECT CONTENTS OF
SHIPMENT FOR DAMAGES AND
SHORTAGES WITHIN 5 DAYS

PICK

PACK

Sale Amount	376.98
Shpg & Hndg	125.79
Sales Tax	46.69
Pkg Protect	1.95
COD Charges	.00
Total	551.41
Prepayment	551.41
Balance Due	.00

ECKLER'S®

5225 South Washington Ave.
Titusville, FL 32780
ATTN: RETURNS DEPT.

Comments:

RTL



Invoice

Date	Invoice #
5/12/2010	19

Crane's Corvette Supply
4687 Chateau Place - San Diego, CA 92117

David Crane: (858) 864-2883 Corvette4u@aol.com
Ryan Crane: (858) 531-9810 Ryan.Crane@CranesCorvetteSupply.com
Fax: (858) 514-8398
www.CranesCorvetteSupply.com
www.CranesCorvette.com

Bill To	Ship To
[REDACTED]	

P.O. Number	Ship
	5/12/2010

Item Code	Description	Price	Quantity	Total
PULLEY	PULLEY NO PS	45.00	1.00	45.00
SALE CRANES CORVETTE SPLY 4687 CHATEAU PLACE SAN DIEGO, CA 921171817 TID: 00000373836 TIME: 12:01 PM DATE: 05/12/10 MERCHANT #: 224216505996 VISA VS xxxxxxxxxxxx2249 (KEYED) INVOICE: 0000001002 APPROVAL CODE: 06432B SEQ: 002 AVS: NY TOTAL AMOUNT \$49.28 CUSTOMER COPY				
Subtotal				\$45.00
Sales Tax (9.5%)				\$4.28
Total				\$49.28

CHRIS SPRINGER AUTO RESTORATION
25 Ocean View Rd, Los Gatos, CA 95033
408-857-2088

Jan 4, 2011

66 Corvette Hood

Paint & Materials

\$40. Resin, glass, epoxy.
30. Thinner, primer, putty.
115. Paint, catalyst, sandpaper, flattner, tape, reducer.

\$185. Total

Labor

12/24 1.5 P/U hood, unwrap, degrease, check over.

12/30 3.5 Grind out cracks hear hood hinge. Lift substructure & grind for glue to skin. Prep & bond skin to substructure. Glass cracks. Rough grind repairs.

12/31 2.5 Finish grinding glass & putty. Blend out, tape & prep for primer. Prime bottom & areas of skin where skin was bonded to substructure.

01/03 3.0 Sand bottom, tape yellow & paint black section. Touch up yellow on edge.

01/00 2.0 Load & return to Herlinger. Install on car & align.

12.5 Total Labor Hours @ \$76/hr = \$950

\$185. Paint & Materials
\$950. Labor

\$1135. Balance Due

INVOICE

JS Enterprises
780 Virginia Ave.
Campbell Ca. 95008
378-5652

5/12/11

Vin. 194675S102547

Mi 86215

65 Corvette

Parts

Glove box grommets

Glove box bumpers

4 speed indicator

Seat belt emblem

Glove box screws

Cluster screws

Steering column seal

Radio bumper

Radio face kit

Glove box

Cluster rebuild & restoration, Glove box door

NOS consol

Towing from Daves to my shop

NOS horn relay

Visor pivot & mount kit

Channel stops

Wing vent seals left & right

Window channel runs front

Surge tank dated

Upper & lower choke tubes, 3 Pcs.

Vacume hose

Vacume advance tube

Battery tray

Battery hold down

Hold down "J" bolts

Tray bolts, Hood hinges, Hood latches, Seat tracks. Ect

Stock battery cables

Expansion tank straps

Heater box seal kit

Firewall insulation

Under dash deadener

Heater & radio dash bezels

Dash pad retainers

Washer, brake pedal clevis

Front emblem

Fender emblems

Top guide pin bushings

Top latch screws

Top latch LH

Guide pin screws

Top rear striker screws

1.80

3.60

8.00

8.00

5.40

4.50

5.00

1.80

139.00

15.30

1,172.00

1,499.00

122.50

106.01

18.00

13.50

140.00

18.00

187.00

53.40

4.80

16.20

37.80

25.20

7.20

25.00

78.00

9.00

38.00

185.00

43.20

16.20

49.50

1.50

39.00

50.40

4.00

3.00

115.00

2.00

3.60

Mirror mount inside, with screws	42.40
Door glass bumpers 4	9.50
Door striker screws	5.60
Door hinge shims	8.00
Door panel vapor barrier	16.20
Front & rear license plate bezels	28.80
Hood release cable, crossover	8.00
Center arm rest cover leather	28.80
Service window & heater motors	210.00
Shipping charges to this point	231.87
Paint glove box frame & parts	100.00
Headlight switch	32.51
Plating, Hood latches, " lock pins, " hinges, " stand, Rear window runs, Ect.....	75.00
Heater core	85.89
Seats, Recover seats, Rechrome 4 seat hinges, Leather seat covers, Recover arm rest, & shipping	\$1,822.24
Powder coat, 2 splash fillers, Vent flaps, Pedal mount & pedals, Batt hold down, 2 head light supports,	
Shift boot retainer, 4 seat rear anchors, " base plates, 2 seat nut plates, Column support, 2 hood spring	\$150.00
Speaker	\$30.00
Vent flap seals	\$10.00
Consol side panel screws	\$4.00
Oil filter	\$9.78
Power window switch	\$95.00
Hood support bolt kit	\$8.10
Hood hinge shims	\$12.00
Hood release guides (Cable clamps)	\$9.00
Harness straps	\$17.10
Kick panels backings, wind lace	\$31.50
kick panel screws	\$10.80
Clutch pedal rod pivot	\$25.00
Clutch rod boot	\$13.50
Accelerator pedal	\$18.00
Accelerator pedel screws	\$1.20
Accererator pedal spacer	\$5.40
Brake & clutch pedal pads	\$10.80
Temp wire retainers	\$6.00
Clutch pushrod upper	\$22.50
Splash filler seals, Staples	\$12.20
Dash pad grab ring	\$13.50
Hood release cable grommet	\$2.00
Shift boot retainer screws	\$6.40
Power window harness grommets	\$3.60
6 window stops in door	\$12.00
Kick vent grill screws	\$2.40
Heater box	\$650.00
Wiper motor rebuild & restoration	\$185.00
Wiper motor seal	\$3.60
Harness, Under dash, Front lighting, Engine, Tail light, Power window, Ground straps	\$902.00
Power window harness	\$110.00
Horn wire clips	\$4.95
2 body grommets	\$12.60
Radio harness	\$10.80
Ground straps	\$23.40
Sparkplug wires	\$35.10

Shipping to this point	\$245.15
Rebuild 2 original headlight motors	\$158.00
3 well nuts for voltage regulator mounting (expanding rubber inserts)	\$7.37
Voltage regulator solid state type	\$19.71
4 halogen headlights	\$32.73
1 exhaust donut & flange gasket	\$5.90
Dash light bulbs	\$17.00
Carburetor fitting for vacume line to dist.	\$1.65
Vacume advance	\$22.62
Dist cap & rotor	\$40.40
Dist pickup & coil (no points)	\$122.80
sparkplugs	\$15.68
Correct air cleaner stud	\$4.40
Fuel filter	\$37.80
License lamp assembly (pig tail bad)	\$92.00
Turn signal lever	\$16.20
Outter door glass seals	\$19.80
Screws for above	\$1.60
Over flow hose	\$7.00
Hood bumpers	\$3.60
Hood release handle assembly	\$60.00
Lower steering column felt with washer	\$6.30
Clips for above	\$4.00
Zinc plating,seat belt parts column,	\$45.00
Storage compartment board	\$24.00
Bezel for storage board	\$7.00
Ash tray	\$9.60
Headlight motor support grommets	\$7.00
2 vent grills	\$48.80
Oil presure line with fittings	\$6.40
Ignition switch nut	\$13.50
Glove box liner screws	\$10.80
Posi sticker for storage board	\$3.00
Chrome, 2 vent posts, 2 top guides, 2 lock guides	\$551.50
Paint shop, consol, Side panels at consol, 2 side panels behind seats, dash molding, Repair 3 holes	\$325.00
Shipping for above	\$153.64
Jack hold down spring	\$7.20
Jacking instruction decal	\$2.40
Headlight motor switch	\$98.00
Horn button	\$55.80
Horn button liner	\$13.50
Turn signal switch	\$144.00
4 wheel alignment	\$200.00
Trailing arm shims assortment	\$42.23
Alternator belt	\$16.80
1 quart Brad Penn oil	\$5.10
Horn contact	\$19.00
Misc. Materials	\$25.00
Shipping charges to this point	\$55.00

Parts

\$12,290.43

Labor

INVOICE

Scott Jones
780 Virginia Ave.
Campbell Ca. 95008
378-5652

6/6/12



Vin.

Mi87380

65 Corvette

Labor

Pull engine & trans

Tear down engine, Inspect

R&R seat belts, send out for restoration

Disassemble Shifter, Clean, Weld stick send stick for chrome work, Reassemble

Assemble engine, Degree in camshaft, Set & weld oil pick up, Set end play, ect.

Engine Assembly 1,500.00

Blast repaint exhaust mans, Paint & detail engine dress complete, Have alternator repaired,

Engine & trans back in, Adjust shift linkage, Adjust back up light switch, Ass clutch cross shaft,

Install power steering, Have car aligned, Test drive

Get keys made, Air up tires, Install 160 T stat, Adjust up pass door, Test radio speaker OK,

Labor 76.5 hrs. 6,885.00

Parts

Machine shop, Hot tank all parts, Tear down heads replace exhaust seats 8, Replace valve guides 16

Valve job, Cut guides for PC seals, Surface heads, Set up new valve springs, New stainless intake & exhaust valves

Bore & hone block, Install new cam bearings, Bore is now .030 over

Install new rod bolts, Resize rods, Balance complete assembly

Grind crank 10/10

Boil flywheel, Blast, Surface

Rod & main bearings, Rings,

Forged pistons,

Machine Shop Parts & Labor 2,838.94

Cam & lifters 350 hp 327, Comp Cams

199.95

Clutch pressure plate, Disc, Throw out bearing, Centerforce

386.85

Oil pump, Melling

34.95

Oil pump drive, ARP

13.78

Timing chain, Cloyes

74.95

Flywheel & clutch bolts, ARP

21.83

Roller tipped rockers

163.95

By-pass fitting 90 degree with bushing

35.00

Intake bolts

15.20

Air cleaner lid

99.00

Reverse lock out handle

20.80

2 motor mount through bolts & nuts

8.00

Valve cover bolts

6.40

Inspection cover bolts

2.40

Oil filter spin on conversion kit with factory insert with by-pass

48.20

Clutch fork

85.00

Oil filler tube

36.00

Oil filler cap

9.00

Exhaust manifold bolts

16.00

Water pump bolts

5.60

Motor mount bolts to block	8.00
Intake by-pass nipple in manifold	5.60
2 plastic cross shaft bushings	4.50
By-pass hose clamps	4.80
By-pass hose	8.00
Lower clutch rod	12.60
Clutch fork boot	7.20
Intake gaskets	29.00
Valve cover 350hp decals	3.20
Lower dipstick tube	6.30
Clutch fork pivot ball	9.00
Power steering conversion kit	850.00
Clutch anti rattle springs	4.80
4 speed to bellhousing bolts	5.60
Bushings for reverse lock out handle	\$3.60
Harmonic balancer 350hp	\$350.00
Shifter interlock shim	\$10.80
Bellcrank stud lock	\$2.40
Acc. Ground strap bolt	\$0.40
French locks	\$11.20
Starter rebuild, Alternator repair (Bad stater)	\$212.66
Refinish intake manifold & valve covers	\$274.00
Restore seat belts, New webbing, Rechroming, Lables, Exchange buckle bases to correct ones	\$339.95
Rear main seal	\$40.98
Head gaskets	\$39.06
Timing cover gasket set	\$14.63
Oil pan gaskets	\$15.61
Shipping, Parts arriving, Shipping intake & valve covers, Seat belts, Shifter stick out.	\$149.05
Chrome, shifter stick	\$75.00
Misc. Zinc plating hardware, Accerator parts, Clutch cross shaft, Shifter rods, Misc.	\$225.00
Sparkplug wire support Pass side	\$13.50
Bolts, plug wire shields, inspection cover, ect	\$7.20
Cut key blanks	\$4.00
Accelerator return spring bracket	\$8.00
Break in additive	\$5.95
Sparkplug	\$2.25
Heater hose nipples	\$21.35
Valve cover gaskets	\$14.60
Fuel pump	\$72.15
Water pump	\$38.91
4 chevy orange	\$25.41
Side shields for sparkplug wires	\$110.00
Oil pan	\$280.00
Oil pump pick up	\$18.00
Shielding support brackets @ exhaust manifolds	\$26.10
Powder coating, Pulleys, Alt brackets, Fan, Shielding brackets, Vent tube, Hose clamp, P/S brackets,	\$250.00
Shipping charges to this point	\$88.95
Seat belt retractors, Originals	\$55.00
Coolant 2 gallons	\$23.84
Fuel pump "dog house" cover gasket	\$1.92
Dipstick correct chrome & button color	\$27.00
Dipstick tube	\$7.20
Fan clutch	\$128.00

Oil presure line fitting in block	\$1.80
2 motor mounts	\$39.81
Alternator pulley, for power steering moves belt back 1 groove	\$38.00
Key blank GM type	\$14.75
Towing to my shop	\$130.00
Tunnel insulation	\$43.25
Trans mount	\$40.12
Power steering fluid 2	\$12.47
Power steering belt	\$13.86
5 quarts 20/50 Brad Penn oil	\$25.50
Oil filter	\$9.78
Gas super	\$40.00
Align front end, (power steering)	\$129.95

Parts	\$8,613.36
-------	------------

Parts & Labor	\$16,998.36
---------------	-------------

Payments

Ck. 9908	12/23/11	3000.00
Ck. 9054	1/10/12	4000.00
Ck. 10114	2/13/12	4000.00

Total Payments	\$11,000.00
----------------	-------------

Balance Due	\$5,998.36
-------------	------------

INVOICE

Scott Jones
780 Virginia Ave.
Campbell Ca. 95008
378-5652

10/29/12



Vin.

Mi 88376

65 Corvette
Labor
Change oil & filter
Repair hood release
Tighten / Ck intake bolts, Valve cover bolts,
Tighten head pipes
Ck. Hose clamps
Ck. Coolant
Replace outer tail lamps
Replace water pump pulley
Adjust choke

Labor 5 hrs. @ 90.00 450.00

Parts
Oil & filter, Brad Penn 20/50
Pulley, Powder coated
Flasher

53.28
141.00

N/C

Parts 194.28

Parts & Labor 644.28

INVOICE

Scott Jones
780 Virginia Ave.
Campbell Ca. 95008
378-5652

10/26/13


Vin.

Mi 89375

65 Corvette

Labor

Change oil & filter

Bleed brakes

Check lights

Check intake & valve cover bolts

Lower floats, hot start

Retorque rear spring 50lbs

General inspection

Change coolant, Replace drain cock(aluminum failed) coolant cloudy

Resealed T stat housing, Repaint housing, N/C

Labor 5 hrs.

450.00

Parts

Oil & filter 20/50 Brad Penn

53.39

2 coolant

23.40

Drain cock

4.41

Brake fluid

7.50

Parts

88.70

Parts & Labor

538.70

INVOICE

Scott Jones
780 Virginia Ave.
Campbell Ca. 95008
378-5652

3/25/15



Vin.

Mi. 90600

65 Corvette

Labor

Change oil & filter

Snug up head pipes

Torque rear leaf spring bolts 45lbs.

Top off power steering fluid

Check oil around fuel pump, tighten up bolts & screws, clean up oil

General checks, misc.

Drop off at Willy's shop

Labor 4 hrs. @ 95.00

380.00

Parts

Oil filter

7.27

Parts

7.27

Parts & Labor

387.27

INVOICE

Scott Jones
780 Virginia Ave.
Campbell Ca. 95008
378-5652

3/8/16

Vin.

Mi. 91488

65 Corvette

Labor

Check under shielding, Coil blown up, Replace, clean up oil from coil

Change oil & filter

Bleed brakes complete

Retorque rear wheels 75lbs

Check column horn problem, broken retaining pin in upper contact, repair

Horn brush in turn signal worn out, replace as needed, install lighter spring behind brush/contact

Test drive ok

General check over

Replace coolant

Replace water pump & fuel pump, both leaking N/C

N/C

Labor 7hrs.

665.00

Parts

Turn signal switch & upper contact

189.23

Radiator drain cock, failed

4.71

Joe Gibb oil & filter

65.70

Coil Pertronics

38.25

Coolant

24.53

Towing

101.50

Parts

423.92

Parts & Labor

1,088.92

INVOICE



DATE

FEB 7 - 2017

INVOICE NO.


CORVETTE BODY

1547 ALMADEN RD., SAN JOSE 95125 • (408) 297-2262

DESCRIPTION	PARTS	LABOR
REPAIR 05 CORV ROADSTER -		7
FRONT END DAMAGE -		
AS PER ADJ. ESTIMATE		
PMT RECEIVED 3/14 \$21162-		
REPAIR AUTHORIZATION:		
X. J. [Signature]		
PLEASE PAY FROM THIS INVOICE		
[Redacted Box]		LABOR TOTAL
		PARTS TOTAL
		TAX
		TOTAL

PAID IN FULL FRANK PMT (\$23162-)

INVOICE



DATE


MAR 6

INVOICE NO.

15-104

CORVETTE BODY

1547 ALMADEN RD., SAN JOSE 95125 • (408) 297-2262

DESCRIPTION	PARTS	LABOR
REPAIR R & L FENDER TO		
HOOD SURROUND SEAMS		
AS PER T&M SHEET -		
BIO HAS @ 80-		240 -
MAT'S	25 -	
T&M OKED 		
REPAIR AUTHORIZATION: 		
PLEASE PAY FROM THIS INVOICE		
LABOR TOTAL		240 -
PARTS TOTAL		25 -
TAX		2 19
TOTAL		267 19

65 RDSTR

3/4

COVER FENDER - MASK INNER & OUTER
AREAS - OPEN FRACTURED AREA - ROUGH
UP & BOND INNER FENDER & HOOD
SURROUND -

1.0

3/6

SMOOTH OF BONDED AREA - COVER VEHICLE -
RE-MASK L/S FENDER TO SEAM -
APPLY 1/2 SHEEN BLACK - REMOVE MASK -
R/F FENDER SEAM TO MATCH L/SIDE -
REMOVE HOOD STRUT - REMOVE OLD O/S PRIMER -
MASK RT FEND TO SURR SEAM - APPLY
1/2 SHEEN BLACK - UNMASK L/S SEAM -
RE ATTACH HOOD STRUT -

2.0

3.0 HRS @ \$80

240-

MAT'S

25-

TX

2¹⁹

TOTAL

\$ 267¹⁹

INVOICE

Scott Jones
780 Virginia Ave.
Campbell Ca. 95008
378-5652

5/19/18



Vin.

Mi. 92098

65 Corvette

Labor

General check over from bodyshop

Tighten hardware to headlight housing assemblies

Adjust side to side pivot housings

Adjust closed stops

Install pigtail harnesses & bulbs, install adjusters, replace 1 hi beam cracked, test ok

Align headlights

Install headlight doors

Sevice headlight motors dry bushings squealing, replace 1 driven gear bad teeth

Move pass door back & up dragging on striker, adjust striker as well

Reinstall pass park lamp, clock 90 degrees

Install A pillar weather strips

Adjust hood pins & pass hood latch, pass not staying latched,

Small adjustment on clutch

3 test drives (hood latch)

Labor 11hrs.

1,100.00

Parts

Gear, headlight motor

26.00

Headlight beam

12.29

Parts

38.29

Parts & Labor

1,138.29

DIAMOND BACK CLASSICS

Conway, S.C. 29526

www.dbtires.com

1-888-922-1642

Sales Receipt

Date	Sale No.
4/16/2020	76114

Sold To	Ship To

PO#	Payment Method	Rep	AUTO YEAR/MAKE	
	Master Card	TAB	65 CORVETTE	
Qty	Item	Description	Rate	Amount
4	215/70/15/TPTAS...	DB Touring AS Redline Tire	249.00	996.00
		UNIROYAL		
1	FREIGHT	FREIGHT	100.00	100.00
		DOT REGISTRATION FORM ENCLOSED		
			Subtotal	\$1,096.00
			Sales Tax (0.0%)	\$0.00
			Total	\$1,096.00

Invoice: WO# 48939

Custom Alignment

2599 Wyandotte Unit A
Mountain View, CA 94043
Phone:(650) 961-5311, Fax:(650) 961-3938
EPA#: CAL 000178797, BAR#: AK 1911598

Car ID # f34 r34

Started : 5/11/2020 Completed 5/11/2020

Make: Chevrolet Model: Corvette Year: 1965 Color: Yellow License: PDU 832 CA

Odometer: In 93,240 Out Engine: Chassis #: Engine #: Body: Convert. Brakes: Power Trans: Auto AC/PS: Yes/Yes Smog: Brakes (F/R): 900% 900% Battery (A/V):

Customer Comment None

Labor And Parts	Qty	Unit	Parts	Labor	Total
Initial Est: Mount 4 tires 60 series & larger				\$60.00	
MOUNT TIRES ON RIMS AND INSTALL NEW VALVE STEMS IF APPLICABLE.					
VLVSTM/RBR1 Rubber valve stem	4	\$3.00	\$12.00		
Totals for This Initial Est: Labor Item			\$12.00	\$60.00	\$72.00
Initial Est: Balance Four Wheels and Tires				\$48.00	
DUAL PLANE HIGH SPEED BALANCE OF WHEEL AND TIRE ASSEMBLY.					
WW1 WHEEL WEIGHTS	8	\$1.50	\$12.00		
Totals for This Initial Est: Labor Item			\$12.00	\$48.00	\$60.00
Initial Est: Suspension and Alignment Inspection				\$0.00	
COMPLETE INSPECTION OF SUSPENSION AND ALIGNMENT RELATED PARTS AND SYSTEMS.					
No Parts					
Totals for This Initial Est: Labor Item			\$0.00	\$0.00	\$0.00
Initial Est: Time-spent alignment				\$270.00	
Set camber, caster, thrust, & toe angles where applicable					
No Parts					
Totals for This Initial Est: Labor Item			\$0.00	\$270.00	\$270.00

Parts (Taxable):	\$24.00	Hazard Fees:	\$0.00
Parts (Non-Tax):	\$0.00	Info Search:	\$0.00
Labor:	\$378.00	Other:	\$20.00
Sublet:	\$0.00	Other:	\$0.00
		Gas:	\$0.00

Total Parts and Labor:	\$402.00
Additional Fees:	\$20.00
Discounts:	\$0.00
Subtotal:	\$422.00
Sales Tax - Parts(9.%)	\$2.16
Grand Total:	\$424.16

Authorization History

Authorized By:	Date:	Writer:	Contacted:	Amount:
	5/11/2020	Joe Silva	Signature/Initial	\$422.00
Total approved for Revs:				\$0.00
Total approved:				\$422.00

I acknowledge notice and oral approval of an increase in the original estimated price _____.

Amount Paid: \$424.16

Unpaid Balance: \$0.00

Payment Summary

Master Card	0005	\$424.16
Total payment:		\$424.16

No warranty on customer supplied parts or on labor.
SALES TAX NOT INCL. ON ORIGINAL EST.
RELEASED VEHICLE TO CUSTOMER SIGNATURE _____

DATE _____

TIRE PRESSURE SET AT: FRONT 34 psi REAR 34 psi

Refer-A-Friend and receive a \$25 credit Check it out at www.customalignment.com !

Customer

Vehicle ident no.

Repair order no.
R003115Technician
JADate
5/11/20License plate no.
PDU 832

First reg. date

Model
Chevrolet : Corvette : 1963-65Odometer reading: km/miles
93240

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left	-0.8° *	-0.3°	+/-0.5°	-0.3°
		right	-0.5°			-0.3°
		cross	-0.3°	0.0°		0.0°
	Toe	left	7/32in *	1/32in	+/-1/32in	1/16in *
		right	1/32in			1/16in *
		total	1/4in *	1/16in		+/-1/16in
	Geometrical driving axis		0.19°	0.00°	0.01°	
Front axle	Camber	left	0.3°	0.8°	+/-0.5°	-0.4° *
		right	0.5°			-0.4° *
		cross	-0.2°	0.0°		+/-0.5°
	Caster	left	1.7°	1.8°	+/-0.5°	1.8°
		right	2.2°			2.2°
		cross	-0.4°	0.0°		+/-0.5°
	SAI	left	7.5°			8.2°
		right	7.1°			8.0°
		cross	0.4°	0.0°		0.2°
	Track differential angle	left				
		right				
	Toe	left	3/16in *	1/8in	+/-1/32in	1/32in *
		right	1/8in			1/32in *
		total	5/16in *	1/4in		+/-1/16in
	Setback			0.00°		
Max steering lock	left steer	left				
		right				
	right steer	left				
		right				

* This value is not within specification. Tire wear, handling and safety problems may result.