[redacted]

Invoice #: 64541
Tag #: T224
Customer #: 251926
Service Advisor: 1 STEVE ERICKSON

Ferrari and Maserati OF SAN FRANCISCO
454 Du Bois Street
San Rafael, CA 94901
(415) 526-2163
EPA # CAL000260979 -- BAR # ARD 195050

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
RED	99	FERRARI F550 MARANEL	ZFFZR49A9X0115837	ATESH1	13657	13686

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
06JUL99 I	16MAR99		17:00 08AUG08			CASH	08AUG08	05AUG08	08AUG08

OPTIONS: STK:C1305A DLR:6177 ENG:53111 TRN:2316 AXL:ASSY#33005 1)TIRES DOT #'S RF/JMJ388 LF/JMJ388 RR/DLC458

		LIST	NET	TOTAL
A	**OWNER STATES THAT WHEN THE TEMP OUTSIDE IS HOT THE A/C DOES NOT BLOW COLD, CHECK AND ADVISE**			
	S180 A/C RECHARGE			
	49 CP hrs.			400.00
	2 R134A FREON	16.95	16.95	33.90
	LABOR: 400.00 **PARTS:** 33.90 **OTHER:** 0.00 **TOTAL LINE A:**			**$ 433.90**
	TEST DROVE AND VERIFIED COCNERN. CHECKED FREON CHARGE-LOW. RECHARGED SYSTEM WITH 1.67LB. TEST DROVE VEHICLE AGAIN AND VERIFIED A/C IS OPERATING AS DESIGNED. COOLING AT 33 DEG.			
	**********			
B**	**OWNER STATES THE RIGHT SIDE DOOR WILL NOT OPEN FROM THE OUTSIDE, CHECK AND ADVISE**			
	S19 REPAIRED RIGHT FRONT DOOR			
	49 CP hrs.			400.00
	LABOR: 400.00 **PARTS:** 0.00 **OTHER:** 0.00 **TOTAL LINE B:**			**$ 400.00**
	VERIFIED COCNERN. FOUND THAT INSIDE DOOR HANDLE IS COMING INTO CONTACT WITH DOOR PANEL. REMOVED DOOR PANEL AND INSPECTED. DISASSEMBLED DOOR PANEL AND ADJUSTED BRACKET ON INSIDE OF PANEL. REASSEMBLED PANEL AND REINSTALLED ON VEHICLE. VERIFIED PROPER OPERATION OF DOOR LOCK AND HANDLES.			
	**********			

EST: 350.00 05AUG08 08:36 SA: 11

Service Department Hours

Monday - Friday 8:00 AM to 5:00 PM
Saturday - Closed

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty or merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

TERMS: CASH

CUSTOMER SIGNATURE:
X

DESCRIPTION	TOTALS
LABOR AMOUNT	800.00
PARTS AMOUNT	33.90
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	833.90
ADJUSTMENTS	0.00
SALES TAX	2.80
PLEASE PAY THIS AMOUNT	**836.70**

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Customer Copy

Copyright 2000 ADP, Inc. X35/2.370 X35/2.370_1

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 08/17/2009 @ 08:55

Model Year:	1999	Make:	FERRARI	Model:	550
License:	FRREE	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.5 L	Type:	Passenger	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	16063	Certification:	California	VLT Record #:	41839
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: NM597901
DMV ID Number: **3148M883N357**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	MIL/Check Engine Light
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
N/A	Fuel Cap Functional	N/A	Ignition Timing:		
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		$\%CO_2$	$\%O_2$	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1706	15.0	0.0	87	9	1	0.46	0.02	0.00	400	57	10	PASS
25 mph	1857	15.1	0.0	31	9	1	0.43	0.03	0.00	687	50	13	PASS

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

VISTA TEST ONLY CENTER
24-A Woodland Ave., San Rafael, CA 94901
(415) 454-7664
Station Number: TL230903

Technician Name/Number: LALIKIAN, ARMEN/EA133161
Repair Tech Name/Number:
Software Version/EIS Number: 0403/ES316845

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

08/17/09
Date

Technician's Signature

[redacted]

Invoice #: 65786
Tag #: T162
Customer #: 251926
Service Advisor: 1 STEVE ERICKSON

Ferrari and Maserati OF SAN FRANCISCO
454 Du Bois Street
San Rafael, CA 94901
(415) 526-2163
EPA # CAL000260979 -- BAR # ARD 195050

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
RED	99	FERRARI F550 MARANEL	ZFFZR49A9X0115837	ATESH1	15766	15782

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
06JUL99 I	16MAR99		17:00 05JUN09			CASH	15JUN09	02JUN09	15JUN09

OPTIONS: STK:C1305A DLR:6177 ENG:53111 TRN:2316 AXL:ASSY#33005 1)TIRES DOT #'S RF/JMJ388 LF/JMJ388 RR/DLC458

				LIST	NET	TOTAL
A	**PERFORM FERRSRI 48MONTH/45,000 MILE SCHEDULED MAINTENANCE PER FACTORY AND DEALER GUIDELINES (PREVENTATIVE MAINTAINANCE)**					
	48575 PERFORM FERRARI 48 MONTH/45,000 MILE SCHEDULE MAINTENANCE AS PER FACTORY AND DEALER GUIDELLINES(PREVENTATIVE MAINTENANCE)					
	40 CP hrs.					1750.00
		2	206166 OIL FILTER	24.50	24.50	49.00
		12	540 Q-POWER 5W40	14.95	14.95	179.40
		2	10263460 WASHER/COPPER D. 22-28X1.5	0.98	0.98	1.96
		2	502 SWEPCO ADD.	12.95	12.95	25.90
		2	4900 SHELL DONAX UR BRAKE	28.95	28.95	57.90
		8	7590 75W/90 GEAR OIL	8.95	8.95	71.60
		1	4901 DONAX TA ATF	24.95	24.95*	24.95
		1	63897800 FILTER/AIR/COMPLETE	92.00	92.00	92.00
	RECYCLE-O OIL RECYCLE FEE					
	12 CR hrs.					1.75
	RECYCLE-B BRAKE FLUID RECYCLE FEE					
	12 CR hrs.					3.88
	RECYCLE-T TRANSMISSION OIL RECYCLE FEE					
	12 CR hrs.					13.37
	LABOR: 1769.00 **PARTS:** 502.71 **OTHER:** 0.00 **TOTAL LINE A:**					**$ 2271.71**

PERFORMED A 48 MONTH/45,000 MILE SERVICE. SEE ATTACHED CHECK SHEET.
NOTE: DURING INSPECTION NOTED FRONT TIRES WORN TO WEAR INDICATORS,ALARM SIREN BATTERY FAILED, DRIVERS DOOR CHECK STRAP NOISEY. OWNER DECLINED AT THIS TIME.

****

B **OWNER STATES WHEN THE CAR IS WARM AND THE RIGHT SIDE WINDOW IS DOWN THERE IS A FUEL SMELL AT APPROX. 40-50 MPH, CHECK AND ADVISE**
S112 FUEL TANK,REMOVE/REINSTALL

Service Department Hours

Monday - Friday 8:00 AM to 5:00 PM
Saturday - Closed

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty or merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

TERMS: CASH

CUSTOMER SIGNATURE:
X

DESCRIPTION

TOTALS	
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
ADJUSTMENTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Customer Copy

Copyright 2000 ADP, Inc. 9.3512.270 9.3512.270_1

ROBERT GOLDSMITH
KATHRYN B GOLDSMITH
40 BLUE RIDGE RD
KENTFIELD, CA 94904
HOME:415-924-0282 B US:415-362-2100 CELL: 5104096366
EMAIL: RGOLDSMITH@PACBELL.NET | HOME

Invoice #: **65786**
Tag #: **T162**
Customer #: **251926**
Service Advisor: ***1 STEVE ERICKSON***

Ferrari and Maserati OF SAN FRANCISCO
454 Du Bois Street
San Rafael, CA 94901
(415) 526-2163
EPA # CAL000260979 -- BAR # ARD 195050

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN	MILEAGE OUT
RED	99	FERRARI F550 MARANEL	ZFFZR49A9X0115837	ATESH1	15766	15782

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	R.O. OPENED	READY
06JUL99 I	16MAR99		17:00 05JUN09			CASH	15JUN09	02JUN09	15JUN09

OPTIONS: STK:C1305A DLR:6177 ENG:53111 TRN:2316 AXL:ASSY#33005 1)TIRES DOT #'S RF/JMJ388 LF/JMJ388 RR/DLC458

				LIST	NET	TOTAL
40	CP	hrs.				1075.00
3		195049	GUARNIZIONE PER VALVOLA A GALL	9.42	9.42	28.26
1		169937	PIPE	210.78	210.78	210.78
2		169839	PIPE	156.89	156.89	313.78

LABOR: 1075.00 **PARTS:** 552.82 **OTHER:** 0.00 **TOTAL LINE B:** **$ 1627.82**

VERIFIED THAT THERE WAS A FUEL SMELL COMING FROM THE FUEL TANK AREA. REMOVED THE FUEL TANK AND FOUND THAT THE ROLLOVER VALVES WERE NOT SEALING PROPERLY. REPLACED ALL ROLLOVER VALVES AND PRESSURE TESTED THE FUEL TANK, VERIFIED THAT NO MORE LEAKS WERE PRESENT. TEST DROVE THE CAR AND VEFIFIED THAT THE FUEL SMELL WAS NO LONGER PRESENT.

****

EST: 2,615.00 02JUN09 09:06 SA: 11

Service Department Hours

Monday - Friday 8:00 AM to 5:00 PM
Saturday - Closed

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty or merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

TERMS: CASH

CUSTOMER SIGNATURE:
X

DESCRIPTION

TOTALS	
LABOR AMOUNT	2844.00
PARTS AMOUNT	1055.53
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	3899.53
ADJUSTMENTS	0.00
SALES TAX	100.28
PLEASE PAY THIS AMOUNT	**3999.81**

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Customer Copy

Copyright 2000 ADP, Inc. X3812.270 X3812.270_1

Ferrari / Maserati of San Francisco
454 Du Bois Street
San Rafael, Ca 94901
415-526-2163 Phone
415-526-2170 Fax

Ferrari Maintenance Schedule
F575M MY 2002 - 2005
F550 MY 1997 - 2002

Required maintenance and lubrication service - 48 months or 45,000 miles

- ✓ Perform initial test drive
- ✓ Inspect sound system
- ✓ Check seat operation
- ✓ Inspect passenger restraint systems
- ✓ Check window operation
- ✓ Inspect interior, armrests and door pulls
- ✓ Inspect dashboard instruments and lighting
- ✓ Check horn operation
- ✓ Check A/C and climate control system operation
- ✓ Inspect and adjust windshield wiper arm tightness
- ✓ Inspect condition of body
- ✓ Inspect chassis for oil and fluid leaks
- ✓ Diagnosis system: read out fault memory SD3
- ✓ Check exterior light operation, replace failed bulbs*
- ✓ Inspect fuel cap and seal
- ✓ Inspect belt for alternator, A/C compressor, and hydraulic steering control**
- ✓ Renew engine oil and filter**
- ✓ Renew differential oil**
- ✓ Renew gear box oil**
- ✓ Renew hydraulic steering fluid**
- ✓ Inspect coolant level**
- ✓ Install oil additive
- ✓ Inspect air cleaners, replace if needed**
- ✓ Inspect cooling system connections and lines
- ✓ Inspect fuel emission control system: lines connections seals and valves
- ✓ Inspect engine idle speed
- NA Inspect climate control system (replace coolant and filter every 2 years)*
- ✓ Inspect fuel injection system lines and unions
- ✓ Inspect ignition system wiring and connections
- ✓ Inspect air injection system valves lines and unions
- ✓ Renew brake fluid (bleed if necessary)**
- ✓ Inspect brake lines, calipers, and connections
- ✓ Check and adjust parking brake
- ✓ Inspect wear condition of the brakes
  5 mm remaining front. 9 mm remaining rear
- ✗ Inspect front tire tread 2 /32 remaining
- ✓ Inspect rear tire tread 7 /32 remaining
- ✓ Inspect joints for front and rear suspensions, front and rear under-chassis tightening torques
- ✓ Inspect steering system components, knuckle joint boots, steering rack boots, linkage boots, and axle shaft boots
- ✓ Inspect exhaust system for leaks and damage
- ✓ Battery: connections and charge condition 12.6 V
- ✓ Inspect starter motor and generator absorption and charge
- ✓ Replace climate control air inlet filter**
- ✓ Inspect and lubricate hinges, linkages, door locks, and front and rear lids
- ✓ Tighten screws and bolts on the bodywork
- ✓ Inspect chassis and protected area integrity
- ✓ Inspect headlight adjustment
- ✓ Perform final test drive, check tightness of wheel nuts and tire pressure
- ✓ Update service manual

Repair order # 45756 Vin # 115837 Date 6/15/04

Recommendations/Comments: ① Front tires are at the wear bar. ② Alarm siren is dead. ③ LF fog light is broken

Technician 40

For the immediate and long-term benefit of your vehicle, the suggested service/maintenance recommendations at Ferrari/Maserati San Francisco meet and exceed factory maintenance schedules. Service suggestions in this schedule have been determined by the manufacturer's recommendations and our years of automotive experience in normal and under severe driving conditions.

* additional charge to apply ** change more frequently if vehicle is used under heavy-duty or severe conditions

FERRARI OF SAN FRANCISCO
MASERATI OF SAN FRANCISCO

454 Du Bois Street • San Rafael, CA 94901
Service: (415) 526-2163
Parts: (415) 526-2166
Hours: 8am to 5pm Monday through Friday

INVOICE

[redacted]

CUSTOMER NO.	ADVISOR		TAG NO.	INVOICE DATE	INVOICE NO.
602604	ROBERTO	39	843	11/11/10	SFCS51338
[redacted]	LICENSE NO. FRREE	MILEAGE 17,426		COLOR RED/	STOCK NO.
	YEAR / MAKE / MODEL 99/FERRARI/F550 MARANELLO/F550 MARAN			DELIVERY DATE 07/06/99	DELIVERY MILES
	VEHICLE I.D. NO. ZFFZR49A9X0115837			SELLING DEALER NO.	PRODUCTION DATE 03/16/99
	F. T. E. NO.	P.O. NO.		R. O. DATE 10/25/10	
	COMMENTS E# 53111				MO: 17438

[RADIO CODE] TIRES DOT #'S

JOB# 1 CHARGES

LABOR

J# 1 50FEZ24550	24MTH/15000 MILE SRV	TECH(S):38		1850.00
	PERFORM FERRARI 24 MONTH/15,000 MILE SCHEDULED MAINTENANCE			
	PER FACTORY AND DEALER GUIDELINES (PREVENTATIVE MAINTENANCE)			
	PERFORM SERVICE			
	PERFORMED 24 MONTH SERVICE			
	FRONT BRAKE PADS AT 8MM LEFT			
	REAR BRAKE PADS AT 9MM LEFT			
	FRONT AND REAR TIRE TREAD DEPTH AT 6/32NDS			

PARTS

QTY	FP	NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
11		540	5/40 PENN ULTRA	14.95	14.95	164.45
8		1055	1055 75/90 GEAR OIL	9.25	9.25	74.00
2		4900	BRAKE FLUID	28.95	28.95	57.90
1		ATF	SHELL ATF 111	5.95	5.95	5.95
1		502	SWEPCO ADDITIVE	12.95	12.95	12.95
2		206166	OIL FILTER	20.65	20.65	41.30
2		151562	FILTER/AIR	43.58	43.58	87.16
1		63897800	FILTER/AIR/COMPLETE	92.00	92.00	92.00
					TOTAL - PARTS	535.71

MISC

CODE	DESCRIPTION	CONTROL NO	
BRAKE	BRAKE FLUID DISPOSAL FEE		3.88
ENG	ENGINE OIL DISPOSAL FEE		1.75
GEAR	GEAR OIL TAX FEE		13.37
CS	SERVICE COUPON 10%		-185.00
CP	PARTS COUPON 10%		-53.57
		TOTAL - MISC	-219.57

JOB# 1 TOTALS

LABOR	1850.00
PARTS	535.71
MISC	-219.57

JOB# 1 JOURNAL PREFIX SFCS JOB# 1 TOTAL 2166.14

JOB# 2 CHARGES

LABOR

J# 2 50FEZTPC	TIRE PRESSURE CHECK	TECH(S):38	0.00
	TIRE PRESSURE CHECK AND INFLATION SERVICE		
	REGULATORY REQUIREMENT		
	TIRE PRESSURE SERVICE COMPLETED.REFER TO ATTACHED CHECK		
	SHEET		

JOB# 2 TOTALS

JOB# 2 JOURNAL PREFIX SFCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR

J# 3 00FEZ06	MINOR ELECTRICAL	TECH(S):38	0.00
	CHECK OPERATION OF BATTERY MAINTENER		



THANK YOU

The Reynolds and Reynolds Company ERAINTINVE CO0920607.0 (08/09)

FERRARI OF SAN FRANCISCO
MASERATI OF SAN FRANCISCO

454 Du Bois Street • San Rafael, CA 94901
Service: (415) 526-2163
Parts: (415) 526-2166
Hours: 8am to 5pm Monday through Friday

INVOICE

[redacted]

CUSTOMER NO.	ADVISOR		TAG NO.	INVOICE DATE	INVOICE NO.
602604	ROBERTO	39	843	11/11/10	SFCS51338
[redacted]	LICENSE NO. FRREE	MILEAGE 17,426	COLOR RED/		STOCK NO.
	YEAR / MAKE / MODEL 99/FERRARI/F550 MARANELLO/F550 MARAN			DELIVERY DATE 07/06/99	DELIVERY MILES
	VEHICLE I.D. NO. Z F F Z R 4 9 A 9 X 0 1 1 5 8 3 7			SELLING DEALER NO.	PRODUCTION DATE 03/16/99
	F. T. E. NO.	P.O. NO.		R. O. DATE 10/25/10	
	COMMENTS E# 53111				MO: 17438

FOUND MAINTENER NOT TO PROVIDE CHARGE.
NEEDS NEW MAINTENER-OWNER DECLINED.
PARTS $299.95

JOB# 3 TOTALS----------

JOB# 3 JOURNAL PREFIX SFCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES----------

LABOR----------

J# 4+00FEZ03C OIL LEAK TECH(S):38 170.00
CK & ADVISE.INSPECTION REVEALED OIL LEAK FROM VALVE COVER
VENT HOSE
REPLACED RIGHT VALVE COVER VENT HOSE

PARTS	QTY	FP	NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
	1		167936	PIPE	244.95	244.95	244.95
						TOTAL - PARTS	244.95

MISC	CODE	DESCRIPTION	CONTROL NO	
	CS	SERVICE COUPON 10%		-17.00
	CP	PARTS COUPON 10%		-24.50
			TOTAL - MISC	-41.50

JOB# 4 TOTALS----------

LABOR	170.00
PARTS	244.95
MISC	-41.50

JOB# 4 JOURNAL PREFIX SFCS JOB# 4 TOTAL 373.45

JOB# 5 CHARGES----------

LABOR----------

J# 5+00FEZ002 GENERAL REPAIR TECH(S):38 1500.00
CK & ADVISE.INSPECTION REVEALED ENGINE MOUNTS COLLAPSED AND
SAGGING
SAGGING
REPLACED ENGINE MOTOR MOUNTS AS RECOMMEND.

PARTS	QTY	FP	NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
	2		192022	ENGINE MOUNT RUBBER	215.04	215.04	430.08
						TOTAL - PARTS	430.08

MISC	CODE	DESCRIPTION	CONTROL NO	
	CS	SERVICE COUPON 10%		-150.00
	CP	PARTS COUPON 10%		-43.01
			TOTAL - MISC	-193.01

JOB# 5 TOTALS----------

LABOR	1500.00
PARTS	430.08
MISC	-193.01

JOB# 5 JOURNAL PREFIX SFCS JOB# 5 TOTAL 1737.07



THANK YOU

The Reynolds and Reynolds Company ERAINTWE CC690067 Q (05/09)

FERRARI OF SAN FRANCISCO
MASERATI OF SAN FRANCISCO

454 Du Bois Street • San Rafael, CA 94901
Service: (415) 526-2163
Parts: (415) 526-2166
Hours: 8am to 5pm Monday through Friday

INVOICE

[redacted]

CUSTOMER NO.	ADVISOR		TAG NO.	INVOICE DATE	INVOICE NO.
602604	ROBERTO	39	843	11/11/10	SFCS51338
[redacted]	LICENSE NO. FRREE	MILEAGE 17,426		COLOR RED/	STOCK NO.
	YEAR / MAKE / MODEL 99/FERRARI/F550 MARANELLO/F550 MARAN			DELIVERY DATE 07/06/99	DELIVERY MILES
	VEHICLE I.D. NO. ZFFZR49A9X0115837			SELLING DEALER NO.	PRODUCTION DATE 03/16/99
	F. T. E. NO.	P.O. NO.		R. O. DATE 10/25/10	
	COMMENTS E# 53111				MO: 17438

JOB# 6 CHARGES----------

LABOR----------

J# 6+00FEZ003	GENERAL REPAIR	TECH(S):38	170.00

CK & ADVISE.INSPECTION REVEALED THROTTLE CABLE FRAYED/WORN
REPLACED THROTTLE CABLE DUE TO FRAYED/WORN INSTALLATION.

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	
	1	178200	THROTTLE CONTROL CA	185.76	185.76	185.76
					TOTAL - PARTS	185.76

MISC	CODE	DESCRIPTION	CONTROL NO	
	CS	SERVICE COUPON 10%		-17.00
	CP	PARTS COUPON 10%		-18.58
			TOTAL - MISC	-35.58

JOB# 6 TOTALS----------

LABOR	170.00
PARTS	185.76
MISC	-35.58
JOB# 6 JOURNAL PREFIX SFCS JOB# 6 TOTAL	320.18

ESTIMATE----------
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF $2470.00 (+TAX)
APPROVED REVISED ESTIMATE (# 1) OF $4990.00 (+TAX) ON 11/03/10 AT 10:45am
BY ROBERT GOLDSMITH COMMENTS MOTOR MOUNTS,VENT HOSE,THROTTLE CABLE
COMMENTS----------
BUS

TOTALS----------

TOTAL LABOR....	3690.00
TOTAL PARTS....	1396.50
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	19.00
TOTAL MISC DISC	-508.66
TOTAL TAX.....	84.34
TOTAL INVOICE $	**4681.18**

CUSTOMER SIGNATURE _____



THANK YOU

The Reynolds and Reynolds Company ERAINTNVE CO69067.0 (0809)

Ferrari and Maserati of San Francisco
P) 415-526-2163 F) 415-526-2170

Vehicle Inspection Report

DATE: 10/25 REPAIR ORDER # 51338

NAME [redacted] PHONE #

YEAR 99 MAKE/MODEL Maranello VIN ZFFXR48A5X0115837

ODOMETER 17424 TECHNICIAN SERVICE ADVISOR RVD

CHECKED | WILL REQUIRE FUTURE ATTENTION | REQUIRES IMMEDIATE ATTENTION

CHECK

OK	Need		OK	Need	
X		Coolant	X		Brake fluid
X		Window washer fluid	X		Power steering fluid
X		Transmission fluid	X		Clutch fluid
X		Engine Oil			

CHECK SYSTEMS / COMPONENTS

X			Windshield washer spray pattern, wiper operation and wiper blades
X			Check operation of interior lights, exterior head lamps, horn, turn signals, hazard and brake lamps
X			Check Air Conditioner Operation
X			Inspect engine cooling system for visible damage or leaks
X			Radiator, heater, and air conditioning hoses for leaks and/or damage
X			Battery and battery connections
X			Clutch operation (if equipped)
X			Accessory drive belt(s)
X			Visually Inspect brakes / no wheels removed
X			Brake system - inspect lines and hoses for visible leakes and/or damage
X			Inspect shocks/struts and suspension components for leaks and/or damage
X			Steering free-play and steering linkages
X			Check driveshaft, transmission, u-joints and shift linkage. Constant velocity (CV) drive axle boots (if equipped)
X			Exhaust system for damage and loose parts (including mounts)
X			Engine and transmission mounts
X			Check engine, transmission/gear box, differentail for fluid leaks

Comments:

INSPECT TIRES

TREAD DEPTH

	LF	RF	LR	RR
7/32 or more				
4/32 to 6/32	X	X	X	X
3/32 or less				

TIRE WEAR PATTERN or DAMAGE

LF	X		
LR	X		
RF	X		
RR	X		

☐ Alignment Check Needed ☐ Wheel Balance Needed

Tires set to Recommended PSI Front 30 Rear 29

BRAKE INSPECTION

	LF	RF	LR	RR
	X	X	X	X

X Wheel lug torque checked

GOOD

REPAIR SOON

BRAKES NEEDED

NEXT SCHEDULED MAINTENANCE

Date: 10-30-10 Time: 3:58pm

FERRARI OF SAN FRANCISCO
SERVICE FACILITY
454 DU BOIS ST
SAN RAFAEL, CA 94901

Ferrari / Maserati of San Francisco
454 Du Bois Street
San Rafael, Ca 94901
415-526-2163 Phone
415-526-2170 Fax

Ferrari Maintenance Schedule
F575M MY 2002 - 2005
F550 MY 1997 - 2002

Required maintenance and lubrication service - 24 months or 15,000 miles

- X Perform initial test drive
- X Inspect sound system
- X Check seat operation
- X Inspect passenger restraint systems
- X Check window operation
- X Inspect interior, armrests and door pulls
- X Inspect dashboard instruments and lighting
- X Check horn operation
- X Check A/C and climate control system operation
- X Inspect and adjust windshield wiper arm tightness
- X Inspect condition of body
- X Inspect chassis for oil and fluid leaks
- X Diagnosis system: read out fault memory SD3
- X Check exterior light operation, replace failed bulbs*
- X Inspect fuel cap and seal
- X Inspect belt for alternator, A/C compressor, and hydraulic steering control**
- X Renew engine oil and filter**
- X Renew differential oil**
- X Renew gear box oil**
- X Renew hydraulic steering fluid**
- X Inspect coolant level**
- X Install oil additive
- X Inspect air cleaners, replace if needed**
- X Inspect cooling system connections and lines
- X Inspect fuel emission control system: lines connections seals and valves
- X Inspect engine idle speed
- X Inspect climate control system (replace coolant and filter every 2 years)*
- X Inspect fuel injection system lines and unions
- X Inspect ignition system wiring and connections
- X Inspect air injection system valves lines and unions
- X Renew brake fluid (bleed if necessary)**
- X Inspect brake lines, calipers, and connections
- X Check and adjust parking brake
- X Inspect wear condition of the brakes
  8 mm remaining front. 9 mm remaining rear
- X Inspect front tire tread 6 /32 remaining
- X Inspect rear tire tread 6 /32 remaining
- X Inspect joints for front and rear suspensions, front and rear under-chassis tightening torques
- X Inspect steering system components, knuckle joint boots, steering rack boots, linkage boots, and axle shaft boots
- X Inspect exhaust system for leaks and damage
- X Battery: connections and charge condition 12.6V
- X Inspect starter motor and generator absorption and charge
- X Replace climate control air inlet filter**
- X Inspect and lubricate hinges, linkages, door locks, and front and rear lids
- X Tighten screws and bolts on the bodywork
- X Inspect chassis and protected area integrity
- X Inspect headlight adjustment
- X Perform final test drive, check tightness of wheel nuts and tire pressure
- ___ Update service manual

Repair order # 51338 Vin # ZFF2R49A9X0115837 Date 10-30-10

Recommendations/Comments: During Service found LF Tire Installed improperly "corrected" found Left & right Front Strut actuators spiking "Corrected Condition".

Technician T38

For the immediate and long-term benefit of your vehicle, the suggested service/maintenance recommendations at Ferrari/Maserati San Francisco meet and exceed factory maintenance schedules. Service suggestions in this schedule have been determined by the manufacturer's recommendations and our years of automotive experience in normal and under severe driving conditions.

* additional charge to apply ** change more frequently if vehicle is used under heavy-duty or severe conditions

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 07/12/2011 @ 08:13

Model Year:	1999	Make:	FERRARI	Model:	550
License:	FRREE	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.5 L	Type:	Passenger	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	18125	Certification:	California	VLT Record #:	28674
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	Biennial

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: OE501107
DMV ID Number: **3767E2800587**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	MIL/Check Engine Light
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
N/A	Fuel Cap Functional	N/A	Ignition Timing:		
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		$\%CO_2$	$\%O_2$	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1849	15.2	0.0	47	9	1	0.46	0.02	0.00	400	57	6	PASS
25 mph	2063	15.3	0.0	11	7	1	0.43	0.03	0.00	687	50	6	PASS

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

Vista Test Only Center
18 Woodland Ave. Unit A, San Rafael, CA 94901
(415)454-7664
Station Number: TL230903

Technician Name/Number: PAYLOZYAN, SET/EA632088
Repair Tech Name/Number:
Software Version/EIS Number: 0903/ES419268

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7.12.11
Date

Technician's Signature

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
619 Lindaro Street
San Rafael, CA 94901
Phone: 415 259-5553 FAX: 415 259-6380

Work Order No.
211012002

Order Date 10/12/11 02:02 pm
Started: 10/12/11 02:03 pm

THANK YOU FOR YOUR BUSINESS!!

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:18190 out:18195
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Profile:

Quotes
1 10/18/11 09:29am 1451.40
ROBERT in person.

Job01 A/C — Labor: $712.50

R134	FREON-S	3.0 @	11.95 =$	35.85	
USED COIL	A/C COMP CLUTCH/COIL-S	1.0 @	700.00 =$	700.00	735.85

A/C DOES NOT BLOW COLD
INSP SHOWS A/C COMPRESSOR CLUTCH COIL IS SHORTED CAUSING FUSE TO BLOW.

REMOVE COMPRESSOR AND RELACE DEFECTIVE COIL/CLUTCH ASSY WITH USED PARTS.
REINSTALL COMRESSOR. RECHARGE SYSTEM. TEST SYSTEM SHOWS ALL OPERATIONS ARE NORMAL.

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

Payments to San Francisco Motorsports, Inc.

Status: In process Work Order

Payments: $1,510.90
1 10/18/11 1510.90 Visa

Cost Summary

Labor	712.50
Parts	735.85
Non Taxable	0.00
Tax	62.55
Total	$1,510.90
Payments	1,510.90
Bal Due	0.00

Thank you for choosing San Francisco Motorsports, Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
619 Lindaro Street
San Rafael, CA 94901
Phone: 415 259-5553 FAX: 415 259-6380

Invoice No.
230325002

Order Date 03/25/13 11:52 am
Paid: 03/27/13 09:09 am

INQUIRE ABOUT OUR TUNEUP SPECIAL

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:20450 out:20459
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 6/12/2012

Quotes
1 03/25/13 11:55am 1375.00
ROBERT in person.

Job01 TIMING BELTS — Labor: $1,875.00

187744 550	Cam Timing Belt-N	2.0 @	89.50 =$	179.00	
201444 456,550	A/C Belt-N	1.0 @	48.98 =$	48.98	
199834 456GT&M,550	Power Steering Belt-N	1.0 @	53.27 =$	53.27	
156441	Spark Plug Chmpion A59-N	10.0 @	21.80 =$	218.00	
ZAF	Antifreeze Coolant-N	2.0 @	17.49 =$	34.98	
GTLMA	GTLMA Brake Fluid-N	2.0 @	11.95 =$	23.90	
63897800 550,575	Pollen Filter-N	1.0 @	124.95 =$	124.95	
186922	FUEL FILTER-N	2.0 @	37.95 =$	75.90	
64577300	HOOD STRUT 550-N	2.0 @	67.10 =$	134.20	893.18

REPLACE TIMING BELTA DUE TO AGE. CHANGE BRAKE/CLUTCH FLUID, COOLANT. REPLACE ACCY BELTS. REPLACE SPARK PLUGS. REPLACE POLLEN FILTER, REPLACE FUEL FILTERS. CHECK ALL LEVELS AND ADJUSTMENTS.

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

Payments to San Francisco Motorsports, Inc.

Status: Paid Work Order

Payments: $2,844.10
1 03/27/13 2844.10 Visa

Cost Summary

Labor	1,875.00
Parts	893.18
Tax	75.92
Total	$2,844.10
Payments	2,844.10
Bal Due	0.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

Thank you for choosing San Francisco Motorsports, Inc.

(Signature) _____

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
619 Lindaro Street
San Rafael, CA 94901
Phone: 415 259-5553 FAX: 415 259-6380

Invoice No.
230613003

Order Date 06/13/13 02:51 pm
Paid: 06/14/13 08:57 am

INQUIRE ABOUT OUR TUNEUP SPECIAL

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:21740 out:21740
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 4/25/2013

Quotes
1 06/13/13 03:03pm 1142.54
ROBERT in person.

Job01 TIRES — Labor: $125.00

295/35ZR18	REAR TIRE 550 SO-2-N	2.0 @	428.00 =$	856.00	856.00

REPLACE REAR TIRES DUE TO WEAR

Job02 DEPENDABLE TIRE — Sublet: $84.50

MOUNT AND BALANCE REAR TIRES

Recommendations: *Air Conditioning Service*

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

Payments to San Francisco Motorsports, Inc.

Status: Paid Work Order

Payments: $1,142.54
1 06/14/13 1142.54 Visa

Cost Summary

Labor	125.00
Parts	856.00
Sublet	84.50
Tax	77.04
Total	$1,142.54
Payments	1,142.54
Bal Due	0.00

Thank you for choosing San Francisco Motorsports, Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
619 Lindaro Street
San Rafael, CA 94901
Phone: 415 259-5553 FAX: 415 259-6380

Invoice No.
220612001

Order Date 06/12/12 01:58 pm
Paid: 06/19/12 08:48 am

THANK YOU FOR YOUR BUSINESS!!

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:19475 out:19480
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 10/12/2011

Quotes
1 06/19/12 08:48am 779.56
ROBERT in person.

Job01 SERVICE — Labor: $285.00

16X22MM	COPPER SEAL-N	1.0 @	1.50 =$	1.50	
14X18MM	COPPER SEAL-N	1.0 @	1.50 =$	1.50	
206166 456,550,575	Oil Filter 456/550/575-N	2.0 @	26.60 =$	53.20	
15W40 ENGINE OIL	15W40 Swepco Motor Oil-N	12.0 @	8.56 =$	102.72	
DONAXUB	Brake Fluid-N	2.0 @	29.99 =$	59.98	
502	Engine Oil Improver-N	1.0 @	6.50 =$	6.50	225.40

ANNUAL SERVICE. CHANGE ENGINE OIL AND FILTERS, BRAKE AND CLUTCH FLUID.

Job02 DETAIL — Sublet: $250.00

COMPLETE DETAIL

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

Payments to San Francisco Motorsports, Inc.

Status: Paid Work Order

Payments: $779.56
1 06/19/12 779.56 Visa

Cost Summary

Labor	285.00
Parts	225.40
Sublet	250.00
Tax	19.16
Total	$779.56
Payments	779.56
Bal Due	0.00

Thank you for choosing San Francisco Motorsports, Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
619 Lindaro Street
San Rafael, CA 94901
Phone: 415 259-5553 FAX: 415 259-6380

Invoice No.
230425001

Order Date 04/25/13 12:58 pm
Paid: 04/26/13 08:18 am

INQUIRE ABOUT OUR TUNEUP SPECIAL

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:21006 out:21012
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 3/25/2013

Quotes
1 04/25/13 01:08pm 1037.96
ROBERT in person.

Job01 TIRES — Labor: $0.00

255/40/18 SO2	FRONT TIRE 550-N	2.0 @	342.78 =$	685.56	685.56

REPLACE FRONT TIRES.

COMPLETE 4 WHEEL ALIGNMENT

Job02 DEPENDABLE TIRE — Sublet: $290.70

MOUNT AND BALANCE 2 FRONT TIRES.

COMPLETE 4 WHEEL ALIGNMENT

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

Payments to San Francisco Motorsports, Inc.

Status: Paid Work Order

Payments: $1,037.96
1 04/26/13 1037.96 Visa

Cost Summary

Labor	0.00
Parts	685.56
Sublet	290.70
Tax	61.70
Total	$1,037.96
Payments	1,037.96
Bal Due	0.00

Thank you for choosing San Francisco Motorsports, Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

Tims Treads
1435 E. Francisco Blvd.
San Rafael, CA 94901
(415) 454-7810 FAX: (415) 454-9893

Customer Copy

Invoice #9057

[redacted]

Saturday, June 26, 2010
11:56:18 AM
Ordered on
Saturday, June 26, 2010

Workorder # 9879

MAKE & MODEL	FLEET NO.	PHONE	REP	CSH	PO #	TERMS
FERARRI 550		362-2100	Adam Sauve	AS		Cash

LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
FR R EE	16774						

CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	FET	TOTAL	Code
OT	255/40/R18 BRIDGESTONE SO-2	2	302.00				$604.00	AS
MB	MOUNT & BALANCE	2		10.00			$20.00	AS
DF	ENVIRONMENT TIRE DISPOSAL FEE	2	3.50				$7.00	
MPVS	RUBBER VALVE STEM	2	.00				$0.00	AS

Dependable Tire
456-2311
Don or Ron - Adam
4 wheel
25 Market

Welcome, We appreciate your business.

PAID BY
M/C $688.38

Parts	$604.00	Taxable	$604.00
Labor	$20.00	Non-Taxable	$27.00
Freight	$0.00	Local 9.5%	$57.38
Other	$7.00		
FET	$0.00	**TOTAL**	**$688.38**
Supplies	$0.00		

Parts and Labor warranties 100 % for 90 days or 4000 mile.Whichever comes first,this warranty limited to the work on this form only. Vehicle must be returned to our shop, any Tire Pros,or American Car Care Centers, at customers expense, to honor warranty. I herby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechainc's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire,theft, accident or any other cause beyond your control. Because of the extent of the teardown and inspection, the vehicle may not perform as well as before.

No refunds on installed Tires and or Wheels, Special Orders or discontinued items. All returns are subject to 15% handling charge. Any deposits are subject to forfeit if cancelled.

Print Name _____ Signature _____ Date _____

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 07/08/2013 @ 08:43

Model Year:	1999	Make:	FERRARI	Model:	550
License:	FRREE	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.5 L	Type:	Passenger	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	21818	Certification:	California	VLT Record #:	28674
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	Change of Ownership

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: OW993518
DMV ID Number: **3263W289O187**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
N/A	Fuel Cap Functional	N/A	Ignition Timing:		
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		$\%CO_2$	$\%O_2$	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1442	10.4	10.0	82	3	1	0.46	0.03	0.00	40	0		PASS
25 mph	2060	10.5	10.0	81	0	0	0.43	0.03	0.00	68	0	1	PASS

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

Vista Test Only Center
18 Woodland Ave, Unit A, San Rafael, CA 94901
(415)454-7664
Station Number: TL230903

Technician Name/Number: SHARIFI, MOHAMMAD/EO149838
Repair Tech Name/Number:
Software Version/EIS Number: 1301/ES419268

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7/8/13
Date

Technician's Signature

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

INQUIRE ABOUT OUR TUNEUP SPECIAL

Invoice No.
250109001

Order Date 01/09/15 01:25 pm
Paid: 01/14/15 09:42 am

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:24188 out:24188
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 6/13/2013

Quotes
1 01/09/15 01:26pm 750.40
ROBERT in person.

Job01 ANNUAL/575-550-456 — Labor: 4.0 hrs@$165.00/hr=$660.00

206166 456,550,575	Oil Filter 456/550/575-N	1.0 @	26.60 =$	26.60
5W40R	5W40 Pennzoil Ultra Euro-N	12.0 @	12.99 =$	155.88
502	Engine Oil Improver-N	1.0 @	6.50 =$	6.50
503	FUEL IMPROVER-N	1.0 @	8.35 =$	8.35
GTLMA	BRAKE FLUID-N	2.0 @	16.99 =$	33.98
16X22MM	COPPER SEAL-N	1.0 @	1.50 =$	1.50
14X18MM	COPPER SEAL-N	1.0 @	1.50 =$	1.50
ZAF	Antifreeze Coolant-N	2.0 @	17.49 =$	34.98
145030 612	Rad. Tank Cap-N	1.0 @	65.33 =$	65.33

334.62

PERFORM ANNUAL SERVICE. CHANGE ENGINE OIL AND FILTER. CHANGE BRAKE FLUID. CHECK CONDITION OF AIR AND POLLEN FILTERS. CHECK AND ADJUST ALL FLUID LEVELS.

INSPECTION FOUND COOLANT WAS LOW AND WEAK, REPLACED COOLANT AND RADIATOR CAP.

NOTE: POWER STEERING HOSES STARTING TO "WEEP", CHECK ON NEXT VISIT.

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

------->---->---->---Continued on the next page--->---->----->------>

I hereby authorized the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000365423
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.
250109001

Order Date 01/09/15 01:25 pm
Paid: 01/14/15 09:42 am

INQUIRE ABOUT OUR TUNEUP SPECIAL

Payments to San Francisco Motorsports, Inc.		Cost Summary	
Status: Paid Work Order		Labor	660.00
		Parts	334.62
Payments: $1,024.74		Tax	30.12
1 01/14/15 1024.74 Visa	TK	Total	$1024.74
		Payments	1024.74
		Bal Due	0.00

Thank you for choosing San Francisco Motorsports, Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

San Francisco Motorsports, Inc.
BAR #: ARD 263966
EPA #: CAL000402694
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.
260314002

Order Date 03/14/16 09:44 am
Paid: 03/21/16 09:25 am

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:25744 out:25745
Lic: FR R EE/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 7/28/2015

Quotes
1 03/14/16 09:54am 1181.54
ROBERT in person.

Job01 ANNUAL/550-456 — Labor: 3.0 hrs@$165.00/hr=$495.00

206166	FILTER/OIL 456-550-575-N	2.0 @	41.95 =$	83.90	
5W40R	5W40 Pennzoil Ultra Euro-N	12.0 @	12.99 =$	155.88	
502	Engine Oil Improver-N	1.0 @	12.50 =$	12.50	
503	FUEL IMPROVER-N	1.0 @	8.35 =$	8.35	
63897800	FILTER/POLLEN 456-550-57-N	1.0 @	135.95 =$	135.95	
14X18	COPPER SEAL-N	1.0 @	1.50 =$	1.50	
16X22	COPPER SEAL-N	1.0 @	1.25 =$	1.25	
AP RACING	BRAKE/AP 600 FLUID-N	4.0 @	22.45 =$	89.80	489.13

PERFORM ANNUAL SERVICE. CHANGE ENGINE OIL AND FILTER. CHANGE BRAKE FLUID. CHECK CONDITION OF AIR AND POLLEN FILTERS, REPLACED POLLEN FILTER. CHECK AND ADJUST ALL FLUID LEVELS.

Job02 SLOW DOWN LIGHT — Labor: 1.0 hrs@$165.00/hr=$165.00

179278 360	ECU/CATALYTIC TEMP CNT-N	2.0 @	380.99 =$	761.98	
					761.98

INSPECTION SHOWS SLOW DOWN ECU'S ARE 2ND GENERATION. REPLACE BOTH ECU'S WITH LATEST VERSION. LIGHT REMAINS ON AT TIMES. MOTRONICS HAVE NO SLOW DOWN ACTIVATION ERRORS. MULT FUNCTION DISPLAY HAS MULTIPLE ERRORS CAUSING LIGHT TO COME ON. ERRORS WILL NOT CLEAR IN DASH. MULT FUNCTION DISPLAY IF FAULTY.

All labor guaranteed for one year; parts guaranteed for manufacturer's period.
Tire Pressure: LF[32] RF[32] LR [32] RR [32]

Payments to San Francisco Motorsports, Inc.

Status: Paid Work Order

Payments: $2,038.84
1 03/21/16 2038.84 Visa TK

Cost Summary

Labor	660.00
Parts	1251.11
Hazardous Waste	12.00
Tax	115.73
Total	$2038.84
Payments	2038.84
Bal Due	0.00

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

Thank you for choosing San Francisco Motorsports, Inc.

(Signature) _____

AUTOSPORT BY GMP/EXCELSIOR BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 330

Order Date 08/09/17 09:18 am
Paid: 08/16/17 09:23 am

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:26920 out:26921
Lic: FRREE/CA 12Cyl 5.5 Eng
Vin: ZFFZR49A9X0115837
Eq:

Quotes
1 08/11/17 11:27am 1075.00
B. GOLDSMITH by phone 510-409

Job01 ANNUAL/550-456 — Labor: $525.00

PENNZOIL EURO	OIL/ENGINE-5W40-N	12.0 @	12.99 =$	155.88	
502	ENG OIL IMPROVER/SWEPCO-N	1.0 @	12.50 =$	12.50	
503	FUEL IMPROVER/SWEPCO-N	1.0 @	8.35 =$	8.35	
206166	FILTER/OIL 456-550-575-N	2.0 @	27.95 =$	55.90	
16X22	SEAL/COPPER-N	1.0 @	1.25 =$	1.25	
14X18	SEAL/COPPER-N	1.0 @	1.50 =$	1.50	
22X29	SEAL/COPPER-N	2.0 @	1.50 =$	3.00	
GS610	FLUID/BRAKE-N	2.0 @	29.02 =$	58.04	
151562	FILTER/AIR 355-456-550-N	2.0 @	54.15 =$	108.30	404.72

PERFORM ANNUAL SERVICE. CHANGE ENGINE OIL AND FILTER, CHANGE BRAKE FLUID. CHECK AIR AND POLLEN FILTERS. FOUND AIR FILTER DIRTY, REPLACED AIR FILTER.

Job Subtotal: $929.72

Job02 POWER STEERING HOSES/550-575 — Labor: $700.00

801-10	HOSE/PRESSURE-N	4.0 @	8.35 =$	33.40	
801-8	HOSE/PRESSURE-N	6.0 @	4.85 =$	29.10	
7599	FLUID/F1 PENTOSIN-N	2.0 @	32.99 =$	65.98	
16X25	CLAMP/HOSE-N	2.0 @	1.65 =$	3.30	
12X20	CLAMP/HOSE-N	4.0 @	1.35 =$	5.40	137.18

INSPECTION FOUND POWER STEERING HOSES LEAKING, REPLACED POWER STEERING HOSES.

Job Subtotal: $837.18

------->---->---->---Continued on the next page--->---->----->------>

AUTOSPORT BY GMP/EXCELSIOR BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 330

Order Date 08/09/17 09:18 am
Paid: 08/16/17 09:23 am

Job03 DETAIL **Sublet: $250.00**
PERFORMED FULL INSIDE AND OUT DETAIL, INVOICE #643150

Tire Pressure: LF[32] RF[32] LR [32] RR [32]
PARTS USED WILL BE DISCARDED AT THE TIME OF PICK-UP UNLESS OTHERWISE REQUESTED.

WARRANTY: FOR LABOR, WE GUARANTEE OUR WORKMANSHIP FOR 12 MONTHS FROM THE REPAIR ORDER COMPLETION DATE. FOR PARTS, THE WARRANTY FOLLOWS THE SPECIFIC PART MANUFACTURER.

Payments to AUTOSPORT BY GMP/EXCELSIOR BY GMP

Status: Paid Work Order

Payments: $1,883.61
1 08/16/17 1883.61 Visa tk

Cost Summary

Labor	1225.00
Parts	541.90
Sublet	250.00
Discount	183.75
HAZ. WASTE/BRAK E	2.00
HAZ WASTE/OIL	2.40
Tax	46.06
Total	$1883.61
Payments	1883.61
Bal Due	0.00

Thank you for choosing AUTOSPORT BY GMP/EXCELSIOR BY GMP

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant your and/or your employees permission to operate the vehicle for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.
SMOG: I understand I can have emission service and/or adjustment done elsewhere. I hereby waive this right.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

AUTHORIZED BY_____ DATE_____ TIME_____

AUTOSPORT BY GMP/EXCELSIOR BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 451

Order Date 09/27/17 12:47 pm
Paid: 10/24/17 09:39 am

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:27087 out:27088
Lic: FRREE/CA 12Cyl 5.5 Eng
Vin: ZFFZR49A9X0115837
Eq:
Last in 8/9/2017

Quotes
1 10/04/17 01:46pm 2200.00 [redacted]

Job01 A/C INOP

Labor: $1,575.00

201444	BELT-A/C 456-550-360-N	1.0 @	54.99 =$	54.99	
R134	FREON/A-C-N	2.0 @	17.50 =$	35.00	
7653509	OIL-A/C PAG-100-N	1.0 @	16.94 =$	16.94	
64894200	DRYER/A-C-N	1.0 @	115.43 =$	115.43	
MT2105	SEAL KIT/COMPRESSOR-N	1.0 @	15.95 =$	15.95	
MT2228	GASKET KIT/COMPRESSOR-N	1.0 @	22.50 =$	22.50	
31-55317	CONTROL VALVE/COMPRESS-N	1.0 @	26.06 =$	26.06	
5908VAW	BEARING-A/C COMPRESSOR-S	1.0 @	97.53 =$	97.53	384.40

INSPECTION SHOWS A/C COMPRESSOR LEAKS, PRESSURE HOSE FROM COMP TO CONDENSOR LEAKS CAUSING FREON LOSS AND LACK OF COOLING. REMOVE COMPRESSOR AND HOSES. DISASSEMBLE COMPRESSOR, CLEAN AND INSPECT. RESURFACE ALL SEALING AREAS. RESURFACE CLUTCH FACES. REPLACE CONTROL VALVE, FRONT SHAFT SEAL AND O'RING, BODY O'RINGS, HEAD GASKET, AND CLUTCH BEARING. CHECK CONTROL WINDING. REASSEMBLE ALL COMPONENTS, FILL COMP WITH PAG R134 COMPRESSOR OIL. REINSTALL ON ENGINE. REPLACE REC/DRYER WITH NEW O'RINGS. INSTALL NEW COMP/ALT BELT. EVAC AND RECHARGE SYSTEM. ROAD TEST SHOWS SYSTEM OPERATES NORMAL. VENT TEMP IS GOOD AT 40DEG F.

Job Subtotal: $1,959.40

Tire Pressure: LF[32] RF[32] LR [32] RR [32]

PARTS USED WILL BE DISCARDED AT THE TIME OF PICK-UP UNLESS OTHERWISE REQUESTED.

WARRANTY: FOR LABOR, WE GUARANTEE OUR WORKMANSHIP FOR 12 MONTHS FROM THE REPAIR ORDER COMPLETION DATE. FOR PARTS, THE WARRANTY FOLLOWS THE SPECIFIC PART MANUFACTURER.

------->---->---->---Continued on the next page--->---->----->------>

AUTOSPORT BY GMP/EXCELSIOR BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 451

Order Date 09/27/17 12:47 pm
Paid: 10/24/17 09:39 am

Payments to AUTOSPORT BY GMP/EXCELSIOR BY GMP

Status: Paid Work Order

Payments: $1,992.07
1 10/24/17 1992.07 Visa tk

Cost Summary

Labor	1575.00
Parts	384.40
Tax	32.67
Total	$1992.07
Payments	1992.07
Bal Due	0.00

Thank you for choosing AUTOSPORT BY GMP/EXCELSIOR BY GMP

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant your and/or your employees permission to operate the vehicle for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.
SMOG: I understand I can have emission service and/or adjustment done elsewhere. I hereby waive this right.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

AUTHORIZED BY_____ DATE_____ TIME_____

AUTOSPORT BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 1525

Order Date 10/09/18 10:50 am
Paid: 11/16/18 09:32 am

[redacted]

99 Ferrari 550 Maranello RED
Mileage in:27961 out:27961
Lic: FRREE/CA 12Cyl 5.5 Eng
Vin: ZFFZR49A9X0115837
Eq:
Last in 11/3/2017

Job01 TIMING BELT WITH SERVICE/550 — Labor: $4,725.00

PENNZOIL EURO	OIL/ENGINE-5W40-N	12.0 @	12.99 =$	155.88	
PENNZOIL TF	OIL/GEAR 1055-N	7.0 @	18.99 =$	132.93	
206166	FILTER/OIL 456-550-575-N	2.0 @	27.95 =$	55.90	
16X22	SEAL/COPPER-N	1.0 @	1.25 =$	1.25	
14X18	SEAL/COPPER-N	1.0 @	1.50 =$	1.50	
22X29	SEAL/COPPER-N	2.0 @	1.50 =$	3.00	
187744	BELT/TIMING 456-550-575-N	2.0 @	132.99 =$	265.98	
201444	BELT-A/C 456-550-360-N	1.0 @	54.99 =$	54.99	
199834	BELT-P/S 456-550-N	1.0 @	23.96 =$	23.96	
SHELLZONE	COOLANT-N	2.0 @	17.50 =$	35.00	
7599	FLUID/F1 PENTOSIN-N	2.0 @	32.99 =$	65.98	
156441	PLUG/SPARK-CHAMPION-N	12.0 @	23.80 =$	285.60	
186922	FILTER/FUEL-N	2.0 @	64.99 =$	129.98	
GS610	FLUID/BRAKE-N	2.0 @	20.51 =$	41.02	
PT550	BEARING/CAM BELT TENSION-N	2.0 @	171.25 =$	342.50	
SLI48AGM	BATTERY/AGM 458-N	1.0 @	199.99 =$	199.99	
134714	SEAL-N	1.0 @	41.99 =$	41.99	
4824	BLADE/WIPER 360-430-35-N	2.0 @	26.98 =$	53.96	1891.41

PERFORM TIMING BELT SERVICE. CHANGE ENGINE OIL AND FILTER, CHANGE BRAKE FLUID, CHANGE GEAR OIL. CHECK AIR AND POLLEN FILTERS, REPLACED POLLEN FILTER. REPLACED, REPLACED COOLANT, REPLACED GEAR OIL, TIMING BELTS, BELT TENSIONERS,DRIVE BELTS, SPARK PLUGS. REPLACED BATTERY.

Job Subtotal: $6,616.41

Job02 CAM COVER GASKETS-SEALS/550 — Labor: $1,750.00

140787	GASKET/CAM COVER END-N	1.0 @	16.99 =$	16.99	
117275	O-RING-N	7.0 @	7.99 =$	55.93	
324050	GASKET/INTAKE-N	2.0 @	15.99 =$	31.98	
140753	GASKET/CAM COVER-N	2.0 @	67.00 =$	134.00	
114808	O-RING/CAM BOLT-N	4.0 @	12.99 =$	51.96	
163987	SEAL/CAM-N	4.0 @	61.99 =$	247.96	538.82

REMOVE INTAKE MANIFOLD, REMOVE LEFT AND RIGHT CAM COVERS. REMOVE ALL CAMS AND CAM SEAL HOUSINGS. REPLACE SEALS AND O'RINGS. REINSTALL CAMS AND HOUSINGS. REINSTALL CAM COVERS WITH NEW GASKETS. REINSTALL INTAKE MANIFOLD WITH NEW GASKETS. RECONNECT ALL REMOVED COMPONENTS.

------->---->---->---Continued on the next page--->---->----->------>

AUTOSPORT BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 1525

Order Date 10/09/18 10:50 am
Paid: 11/16/18 09:32 am

Job02 CAM COVER GASKETS-SEALS/550

Job Subtotal: $2,288.82

Job03 WATER PUMP

Labor: $262.50

MULTI-WP1	**KIT/WATER PUMP-N**	**1.0 @**	**289.50 =$**	**289.50**	**289.50**

REBUILD WATER PUMP.

Job Subtotal: $552.00

Tire Pressure: LF[32] RF[32] LR [32] RR [32]

PARTS USED WILL BE DISCARDED AT THE TIME OF PICK-UP UNLESS OTHERWISE REQUESTED.

WARRANTY: FOR LABOR, WE GUARANTEE OUR WORKMANSHIP FOR 12 MONTHS FROM THE REPAIR ORDER COMPLETION DATE. FOR PARTS, THE WARRANTY FOLLOWS THE SPECIFIC PART MANUFACTURER.

Payments to AUTOSPORT BY GMP

Status: Paid Work Order

Payments: $9,693.21
1 10/17/18 1900.00 Visa tk
2 11/16/18 7793.21 Visa TK

Cost Summary

Labor	6737.50
Parts	2719.73
Haz Waste	4.80
Tax	231.18
Total	$9693.21
Payments	9693.21
Bal Due	0.00

Thank you for choosing AUTOSPORT BY GMP

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant your and/or your employees permission to operate the vehicle for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.
SMOG: I understand I can have emission service and/or adjustment done elsewhere. I hereby waive this right.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

AUTHORIZED BY_____ DATE_____ TIME_____

AUTOSPORT BY GMP
BAR #: ARD 00284530
EPA CAL000
86 HAMILTON DRIVE
NOVATO, CA 94949
Phone: 415-985-9300 FAX: 415-883-0928

Invoice No. 1692

Order Date 01/31/19 09:56 am
Paid: 02/22/19 09:12 am

[redacted]

99 Ferrari 550 Maranello RED
Mileage in: out:
Lic: FRREE/CA 12Cyl 5.5 Eng
Vin: ZFFZR49A9X0115837
Eq:
Last in 10/9/2018

Job01 ALARM — Labor: $380.00

A23	REMOTE BATTERY-N	1.0 @	3.75 =$	3.75	3.75

WHEN UNLOCKING CAR WITH REMOTE, INTERIOR LIGHTS GO OUT. INSPECTION SHOWS ALARM REMOTE BATTERY IS DEAD.

REPLACE REMOTE FOB BATTERY. REPROGRAM SYSTEM. RETEST SHOWS ALL OPERATIONS ARE NOPRMAL.

Job Subtotal: $383.75

Tire Pressure: LF[32] RF[32] LR [32] RR [32]

PARTS USED WILL BE DISCARDED AT THE TIME OF PICK-UP UNLESS OTHERWISE REQUESTED.

WARRANTY: FOR LABOR, WE GUARANTEE OUR WORKMANSHIP FOR 12 MONTHS FROM THE REPAIR ORDER COMPLETION DATE. FOR PARTS, THE WARRANTY FOLLOWS THE SPECIFIC PART MANUFACTURER.

Payments to AUTOSPORT BY GMP

Status: Paid Work Order

Payments: $384.07
1 02/22/19 384.07 Visa tk

Cost Summary

Labor	380.00
Parts	3.75
Tax	0.32
Total	$384.07
Payments	384.07
Bal Due	0.00

Thank you for choosing AUTOSPORT BY GMP

I hereby authorize the above repair work to be done along with the necessary materials and hereby grant your and/or your employees permission to operate the vehicle for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.
SMOG: I understand I can have emission service and/or adjustment done elsewhere. I hereby waive this right.
NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

AUTHORIZED BY_____ DATE_____ TIME_____

Tims Treads

1435 E. Francisco Blvd.
San Rafael, CA 94901

(415) 454-7810 FAX: (415) 454-9893

Estimated Time Due

Customer Copy

Invoice #28686

[redacted]

Friday, July 31, 2020
11:05:55 AM

Ordered on
Friday, July 31, 2020

Workorder # 30227

MAKE & MODEL	FLEET NO.	PHONE	REP	CSH	PO #	TERMS
FERRARI		362-2100	Tim Falvey	TF		Cash

LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
JMSBOND	29705			3.0L V6 FI DOHC 24V			

CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	FET	TOTAL	Code
OT	255/40R18 BRIDGESTONE SO-4	2	255.85				$511.70	TF
MB	MOUNT & BALANCE	2		12.00			$24.00	TF
DF	ENVIRONMENT TIRE DISPOSAL FEE	2	4.00				$8.00	
MPVS	RUBBER VALVE STEM	2	.00				$0.00	TF

Welcome, We appreciate your business.

PAID BY
VISA $589.75

Parts	$511.70	Taxable	$511.70
Labor	$24.00	Non-Taxable	$32.00
Freight	$0.00	9.00%	$46.05
Other	$8.00		
FET	$0.00	**TOTAL**	**$589.75**
Supplies	$0.00		

Parts and Labor warranties 100 % for 90 days or 4000 mile.Whichever comes first,this warranty limited to the work on this form only. Vehicle must be returned to our shop. any Tire Pros,or American Car Care Centers, at customers expense, to honor warranty. I herby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire,theft, accident or any other cause beyond your control. Because of the extent of the teardown and inspection, the vehicle may not perform as well as before.

No refunds on installed Tires and or Wheels, Special Orders or discontinued items. All returns are subject to 15% handling charge. Any deposits are subject to forfiet if cancelled.

Print Name _____ Signature _____ Date _____

PATRICK OTTIS
1220 TENTH STREET
BERKELEY, CALIFORNIA 94710
ARD NO 120777

INVOICE NO.
369420

SO [redacted]	SHIP TO:
AD	ADDRESS:
CI	CITY, STATE, ZIP

CUSTOMER'S ORDER:	SOLD BY:	TERMS:	F.O.B.	DATE:
550 MARANELLO	11S837	THANK YOU	30812, MI	07 APRIL 2021

QUANTITY		DESCRIPTION	PRICE	AMOUNT
30 MAR.	1	INVESTIGATE NON-OP DRIVER DOOR LOCK. REMOVE LEFT DOOR		
	2	PANEL. REMOVE INNER DOOR RELEASE HANDLE. DISASSEMBLE		
	3	LOCK & RELEASE ROD PIVOTS. CLEAN OLD GREASE FROM ALL		
	4	PARTS. REINSTALL ALL COMPONENTS WITH FRESH GREASE.		
	5	ADJUST LOCK RODS. OPERATION NORMAL. REASSEMBLE.		3.0
31 MAR.	6	LEFT VEHICLE, REMOVE UNDER TRAYS. DRAIN ENGINE OIL		
	7	REMOVE OIL FILTERS. INSP. LEAKING OIL HOSES		2.0
01 APR.	8	DRAIN REPLACE GEAR OIL. SAFETY INSPECT VEHICLE		2.0
05 APR.	9	REMOVE THREE LEAKING OIL HOSES AT DRY SUMP TANK.		
	10	REMOVE END FITTINGS. CLEAN DRY & RESEAL WITH LOCTITE		

PATRICK OTTIS

INVOICE NO.
369421

SOLD T [redacted]	SHIP TO:
ADDRESS:	ADDRESS:
CITY, STATE, ZIP	CITY, STATE, ZIP

CUSTOMER'S ORDER:	SOLD BY:	TERMS:	F.O.B.	DATE:
550 MARANELLO	11S837		30812 MI	07 APRIL 2021

QUANTITY		DESCRIPTION	PRICE	AMOUNT
	1	PLASTIC GASKET SEALANT. REINSTALL LINES		5.0
06 APR.	2	REFILL ENGINE OIL. INSTALL NEW OIL FILTERS. CLEAN, REINSTALL		
	3	UNDERTRAYS. CHECK ADJUST ALL FLUID LEVELS.		
	4	NOTE: REAR TIRES ARE AT WEAR BARS - RECOMMEND REPLACE		
	5	FRONT TIRES GOOD AT 10/32"		
	6	BRAKES GOOD AT 75% REMAINING		
	7	FRONT SUSPENSION BUSHING ARE WORN CAUSING CREAK		
	8	RATTLE NOISE		2.0
	9			
	10	SHOP LABOR 14.0 HRS @ 160		2240

PATRICK OTTS

INVOICE NO.

369422

INVOICE 71721 ©2004 REDIFORM®

SOLD TO: [redacted]	SHIP TO:
ADDRESS:	ADDRESS:
CITY, STATE, ZIP	CITY, STATE, ZIP

CUSTOMER'S ORDER:	SOLD BY	TERMS:	F.O.B.	DATE
550 MARANELLO	115837		30812 MI	07 APRIL 2021

QUANTITY		DESCRIPTION	PRICE	AMOUNT
	1			
	2	10 QTS PENNZOIL PLATINUM ULTRA 5W 40 OIL @ 18.95		189.50
	3	2 OIL FILTERS 206166 @ 46.50		93.-
	4	4.5 LITERS SPIRAX 75W 90 GEAR OIL @ 37.-		166.50
	5	BRAKE FLUID		20.-
	6	PARTS TOTAL 469.- TAX ON PARTS		44.55
	7	91 OCTANE FUEL		53.-
	8	WASH DETAIL CAR. NO CHARGE.		
	9			
	10	JOB TOTAL		2806.55

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 07/03/2017 @ 11:39

Model Year:	1999	Make:	FERRARI	Model:	550
License:	FRREE	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.5 L	Type:	Passenger	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	26886	Certification:	California	VLT Record #:	28674
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: QI182196
DMV ID Number: **3344I884Q857**

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
N/A	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
N/A	Fuel Cap Functional	N/A	Ignition Timing:		
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		$\%CO_2$	$\%O_2$	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1675	15.0	0.0	47	9	0	0.46	0.03	0.00	400	67	0	PASS
25 mph	2004	15.1	0.0	31	6	0	0.43	0.03	0.00	687	62	0	PASS

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

VISTA TEST ONLY CENTER
18 Woodland Ave. Unit A, San Rafael, CA 94901
(415) 454-7664
Station Number: TC230903

Technician Name/Number: LALIKIAN, ARMEN/EO133161
Repair Tech Name/Number:
Software Version/EIS Number: 1301/ES316845

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7/3/17
Date

Technician's Signature

Smog Check Vehicle Inspection Report (VIR)

www.esp-global.com

www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 07/07/2021@13:41:09

Model Year:	1999	Make:	FERRARI	Model:	550
License:	JMSBOND	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.50 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	31,157	Certification:	California	VLT Record #:	28674
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: IL849706

DMV ID Number: 3090L287I147

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing:	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

ASM Emission Test Results

		%CO2	%O2	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1794	15.0	0.0	47	9	3	0.46	0.03	0.00	400	67	2	Pass
25 mph	1960	14.9	0.0	31	6	4	0.43	0.03	0.00	687	62	1	Pass

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

VISTA TEST ONLY CENTER
18 WOODLAND AVE UNIT A SAN RAFAEL, CA 94901
(415) 454-7664
Station Number: TC230903

Technician Name/Number: LALIKIAN, ARMEN/EO133161
Repair Tech Name/Number:
Software Version/EIS Number: 1905 / EP728294

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date 7/7/21

Technician's Signature

Smog Check Vehicle Inspection Report (VIR)

www.esp-global.com

www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 07/11/2023@15:01:08

Model Year:	1999	Make:	FERRARI	Model:	550
License:	JMSBOND	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.50 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	31,987	Certification:	California	VLT Record #:	28674
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: TI886247

DMV ID Number: 3897I288T147

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing:	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

ASM Emission Test Results

		%CO2	%O2	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1738	14.9	0.0	47	9	5	0.46	0.03	0.01	400	67	1	Pass
25 mph	2026	15.0	0.0	31	6	7	0.43	0.03	0.01	687	62	1	Pass

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

VISTA TEST ONLY CENTER
18 WOODLAND AVE UNIT A SAN RAFAEL, CA 94901
(415) 454-7664
Station Number: TC230903

Technician Name/Number: PAYLOZYAN, ANDRANIK/EO642959
Repair Tech Name/Number:
Software Version/EIS Number: 2201 / EP728294

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7/11/23
Date

Technician's Signature

Smog Check Vehicle Inspection Report (VIR)

www.esp-global.com

www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 07/08/2025@09:40:45

Model Year:	1999	Make:	FERRARI	Model:	550
License:	JMSBOND	State:	CA	VIN:	ZFFZR49A9X0115837
Engine Size:	5.50 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	4250	Cylinders:	12
Odometer:	32,676	Certification:	California	VLT Record #:	28674
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: UQ175091

DMV ID Number: 3595Q287U847

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Not applicable	Ignition Timing:	Pass	Other Emission Related Components
Not applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Not applicable	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Bypass	Fuel Evaporative Controls Functional		

ASM Emission Test Results

		%CO2	%O2	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1666	15.3	0.0	47	9	1	0.46	0.03	0.01	400	67	3	Pass
25 mph	2019	15.3	0.0	31	6	2	0.43	0.03	0.01	687	62	3	Pass

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

Smog Check Inspection Station Information

VISTA TEST ONLY CENTER
18 WOODLAND AVE UNIT A SAN RAFAEL, CA 94901
(415) 454-7664
Station Number: TC230903

Technician Name/Number: PAYLOZYAN, ANDRANIK/EO642959
Repair Tech Name/Number:
Software Version/EIS Number: 2402 / EP728294

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

7-8-25
Date

Technician's Signature

BAR #: AF070242 EPA #: AD981416617
Delivered Date: 9/3/2021

ANTHONY'S AUTO CRAFT

103 VERDI ST
SAN RAFAEL, CA 94901
(415) 456-7591, (415) 456-7615 Fax

INVOICE

RO #: 49092; Est #: 7847419
Est: Sean Ballenger

[redacted]

99 Ferrari 550
Color: 322/RED
Type: PC 2 Door Coupe
VIN: ZFFZR49A9X0115837
Prod Date: 0399 Plate: CA JMSBOND
Odometer: 31200
Engine: 5.5L 12 Cyl Gas Injected

CSAA INSURANCE GROUP
Adjustor:
Phone:
Claim #: 1004-29-1132.1
Deductible: 500
Loss Type: Unknown

P = Who Pays? (I = Insurance, C = Customer)

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor	Paint	P
	Parts Existing	Frt Bumper Cover					Refn		490.00	I
		Modified Refinish With Full Clear Coat								I
	Parts Existing	Frt Bumper Assy				Body	Ovrh	560.00		I
	Parts Existing	Frt Bumper Face Bar				Body	Rpr	280.00		I
	Parts Existing	R Front Combination Lamp				Body	R&I	210.00		I
	Parts Existing	L Front Combination Lamp			1	Body	R&I	210.00		I
	Parts Existing	R Fender Outside					Refn		420.00	I
		Modified Refinish With Full Clear Coat A								I
	Parts Existing	R Fender Panel				Body	Rpr	280.00		I
	Parts Existing	R Fender Liner				Body	R&I	84.00		I
1	Parts New	R Fender Nameplate		162.25	2	Body	Repl	28.00		I
	Parts Existing	R Fender Emblem				Body	R&I	70.00		I
	Parts Existing	Wheel				Body	R&I	42.00		I
		Right Front - Repair Access								I
1	Prt/Mat	Paint/Materials		575.00			Addl			I
1	Haz	Hazardous Waste Disposal		3.00			Addl			I
1	Prt/Mat	Flex Additive		7.00			Addl			I
		Clear Coat					Addl		210.00	I
		Tint Color			1		Addl		140.00	I
		Finish Sand And Buff				Detail	Addl	60.00		I
		Additional Two Tone			1		Addl		350.00	I
		Add For Black Out Front Bumper								I
1	Parts AM	Mask For Overspray	** QUAL REPL PART	5.00	2	Paint	Addl		28.00	I
1	Parts AM	Corrosion Protection	** QUAL REPL PART	10.00	2	Body	Addl	14.00		I
	Parts Existing	Pre Scan				Body	Addl	70.00		I
	Parts Existing	Post Scan				Body	Addl	70.00		I
	Parts Existing	Remove Existing Clear Armor			1	Body	Addl	280.00		I
		Remove Clear Armor Front Bumper , Right								I
1	Sublet	Clear Armor		812.50	3	Body	Repl			I
		Front Bumper, Right Fender, Subject to I								I
1	Parts AM	Clean & Re-tape Fender Shield	Aftermarket New	5.00	1	Body	Repl	84.00		I
		Adjustment		10.00						

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor	Paint	P

Parts	189.25
Labor	3,980.00
Additional Costs	588.00
Sublet	812.50
SubTotal	5,569.75
Taxes	70.97
Grand Total	5,640.72

Due from Insurance		Due from Customer	
SubTotal	5,069.75	SubTotal	500.00
Tax	70.97	Tax	0.00
Total	5,140.72	Total	500.00

Total Amount 5,640.72

San Rafael European
BAR #: ARD 00287273
EPA #: CAL000428253
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.
13599

Order Date 01/17/25 11:14 am
Completed: 03/17/25 03:34 pm

I acknowledge notice & oral approval of an increase in the original estimated price.

SIGNATURE

[redacted]

99 Ferrari 550 Maranello RED
Odometer reading in:32422 out:
Lic: JMSBOND/CA 12Cyl 5.5 Eng
Vin: ZZFFZR49A9X0115837
Eq:
Last in 3/14/2016

NEW SHOCK: 21452 - AUTH 2/14
WATER PUMP REBUILD - 22500 AUTH 3/7/25

Quotes
1 01/17/25 02:35pm 8524.74
ROBERT in person.
2 02/07/25 04:29pm13481.22
ROBERT by phone [redacted]
CAM COVERS, CLIMATE CONTROL
3 02/11/25 01:51pm20085.26
ROBERT by phone [redacted]
FRONT SHOCKS
4 02/12/25 04:22pm20873.50
BOB by phone [redacted]
AUX WATER PUMP

Job01 TIMING BELT WITH SERVICE/550 — Labor: $5,000.00

187744	BELT/CAM TIMING 456-550-N	2.0 @	182.33 =$	364.66	
PT550	V12 TENSIONER 456550612-N	2.0 @	176.75 =$	353.50	
201444	BELT-A/C 456-550-360-N	1.0 @	42.15 =$	42.15	
199834	BELT-P/S 456 ALL-550-N	1.0 @	45.96 =$	45.96	
5W40R	SYNTHETIC ENGINE OIL-N	12.0 @	15.32 =$	183.84	
206166	FILTER/OIL 456-550-575-N	2.0 @	124.93 =$	249.86	
115	BG OIL IMPROVER-N	1.0 @	21.40 =$	21.40	
5901	COOLING SYSTEM SERV KIT-N	1.0 @	44.44 =$	44.44	
ZAF	COOLANT/SHELLZONE-N	2.0 @	26.20 =$	52.40	
145030	RADIATOR CAP-N	1.0 @	72.69 =$	72.69	
151562	FILTER/AIR 355-456-550-N	2.0 @	99.32 =$	198.64	
63897800	FILTER/POLLEN 456-550--N	1.0 @	210.70 =$	210.70	
186922	FILTER/FUEL 456-550-N	2.0 @	99.98 =$	199.96	
2913	ETHANOL DEFENSE KIT-N	1.0 @	26.40 =$	26.40	
460.12.16	COPPER WASHER-N	1.0 @	2.35 =$	2.35	
460.20.26	COPPER WASHER 20X26-N	1.0 @	2.75 =$	2.75	
75W90S	SYNTHETIC GEAR OIL-N	8.0 @	31.40 =$	251.20	
DOT4	EURO BRAKEFLUID-N	2.0 @	23.78 =$	47.56	
714	F1 FLUID-N	2.0 @	22.43 =$	44.86	
174954	SPARK PLUG/NGK 612-N	12.0 @	29.00 =$	348.00	
14573987	THROTTLE CABLE CLIP-N	1.0 @	3.00 =$	3.00	2766.32

PERFORMED TIMING BELT REPLACEMENT SERVICE PER CHECK SHEET. CHANGED ENGINE OIL AND FILTER. ADDED BG OIL AND FUEL IMPROVERS. POWER FLUSHED AND REPLACED BRAKE FLUID. CHANGED GEARBOX OIL. REPLACED COOLANT WITH BG CONDITIONING ADDITIVE. REPLACED AIR AND POLLEN FILTERS. REPLACED FUEL FILTERS. REPLACED TIMING BELTS AND TENSIONERS. REPLACED A/C AND POWER STEERING BELTS. DRAINED AND FLUSHED POWER STEERING SYSTEM. CHECKED AND ADJUSTED CAM TIMING. REPLACED RADIATOR CAP. REPLACED SPARK PLUGS. PERFORMED VEHICLE INSPECTION. ADJUSTED PARKING BRAKE. SET CLOCK. CARRIED OUT FINAL QUALITY ASSURANCE ROAD TEST.

------->---->---->---Continued on the next page--->---->----->------>

San Rafael European
BAR #: ARD 00287273
EPA #: CAL000428253
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.
13599

Order Date 01/17/25 11:14 am
Completed: 03/17/25 03:34 pm

Job01 TIMING BELT WITH SERVICE/550

Job Subtotal: $7,766.32

Job02 CAM COVER GSKTS-SEALS 456/550

Labor: $3,420.00

140753	GASKET/CAM COVER-N	2.0 @	67.00 =$	134.00	
163987	SEAL/CAM-N	4.0 @	43.67 =$	174.68	
114808	O-RING/CAM BOLT-N	4.0 @	10.00 =$	40.00	
117275	O-RING/CAM COVER 328-N	7.0 @	16.00 =$	112.00	
140787	GASKET/END CAM COVER-N	1.0 @	16.73 =$	16.73	
324050	GASKET/INTAKE-N	2.0 @	22.99 =$	45.98	
1211	THREE BOND 1/4 TUBE-N	1.0 @	22.90 =$	22.90	
MP-100	SOLVENT-N	1.0 @	15.90 =$	15.90	562.19

INSPECTION REVEALED LEAK FROM DRIVER SIDE REAR OF CAM COVER. REMOVED INDUCTION SYSTEM, INTAKE MANIFOLD, CAM COVERS, AND ALL CAM SHAFTS. CLEANED AND INSPECTED. REPLACED FRONT CAMSHAFT SEALS AND ORINGS, REAR CAMSHAFT SEALS AND ORINGS, AND REPLACED CAM COVER GASKETS. REASSEMBLED TO PROPER CAM TIMING. LABOR REDUCED TO REFLECT OVERLAP WITH TIMING BELT SERVICE.

Job Subtotal: $3,982.19

Job03 RATTLE / FRONT SHOCKS

Labor: $1,710.00

153285	JOINT/BALL-FRONT-N	2.0 @	566.06 =$	1132.12	
949218R	FRONT SHOCK REBUILT-R	1.0 @	950.00 =$	950.00	
173900	UPPER MOUNT-N	1.0 @	1113.19 =$	1113.19	
127991	SLEEVE-N	2.0 @	151.62 =$	303.24	
153286	RUBBER SEAL-N	4.0 @	5.84 =$	23.36	
949218	FRONT SHOCK-N	1.0 @	1468.12 =$	1468.12	4990.03

CLIENT STATES WHEN VEHICLE IS COLD THERE IS A RATTLE FROM THE ENGINE COMPARTMENT. STATES WHEN WARMS UP, GOES AWAY.
INSPECTION FOUND DRIVER FRONT SHOCK CREAKING. ALSO FOUND LEFT UPPER MOUNT HEIM JOINT FAILING AND MAKING NOISE. RECOMMEND REBUILD PAIR OF FRONT SHOCKS AND INSTALL NEW LEFT UPPER SHOCK MOUNT.
REMOVED FRONT WHEELS, UPPER SHOCK ABSORBER NUTS, AND SHOCK ACTUATORS. REMOVED UPPER BALL JOINTS FROM CONTROL ARMS FOR ABSORBER UNIT REMOVAL. SENT OUT FOR REBUILD. WHEN AT REBUIDERS , DISASSEMBLY OF LEFT SHOCK FOUND SHAFT CRACKED AND NOT REPAIRABLE. SOURCED ONE NEW LEFT SHOCK.
REPLACED UPPER AND LOWER SHOCK BUSHINGS. REPLACED UPPER LEFT SHOCK MOUNTING. REPLACED SHOCK BOOTS. INSTALLED RIGHT REBUILT SHOCK AND LEFT NEW SHOCK. REASSEMBLED AND ROAD TESTED TO CONFIRM REPAIR.

Job Subtotal: $6,700.03

Job04 NO CLIMATE CONTROL

Labor: $1,282.50

------->---->---->---Continued on the next page--->---->----->------>

San Rafael European
BAR #: ARD 00287273
EPA #: CAL000428253
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.
13599

Order Date 01/17/25 11:14 am
Completed: 03/17/25 03:34 pm

Job04 NO CLIMATE CONTROL

65460300	AUX WATER PUMP-N	1.0 @	443.94 =$	443.94	443.94

CLIENT STATES NO AIR COMES OUT FOR A/C OR HEATER. DIAGNOSE AND ADVISE.
INSPECTION FOUND BLOWN FUSE TO HVAC SYSTEM. REPLACED. BLEW AGAIN WHEN TESTING. SUSPECT SHORTED WIRE AT BLOWER MOTOR.
REMOVED CENTERCOSOLE PANELS AND RADIO FOR ACCESS. DISCONNECTED CLIMATE CONTROL HARNESSES, HEATER FAN CONTROL, A/C CONTROL. FOUND ISSUE STILL REMAINS. DISCONNECTED HEATER TGK VALVES, NO CHANGE. DETERMINED SHORT AT AUXILLARY WATER PUMP. DISCONNECTED PUMP AND SHORT CIRCUIT ELIMINATED.
REMOVED AND REPLACED AUXILLARY WATER PUMP. REASSEMBLED VEHICLE. INSTALLED NEW FUSE. TESTED AND CONFIRMED PROPER FUNCTION.

Job Subtotal: $1,726.44

Job05 WATER PUMP REBUILD

Labor: $461.12

143742	WATER PUMP BEARING-N	1.0 @	340.70 =$	340.70	
137868	WATER PUMP O-RING-SEAL-N	1.0 @	25.56 =$	25.56	
183759	WATER PUMP SEAL/360-N	1.0 @	65.00 =$	65.00	
141250	O-RING-N	1.0 @	1.99 =$	1.99	433.25

INSPECTION FOUND WATER PUMP LEAKING COOLANT.
REMOVED WATER PUMP ASSEMBLY AND PUMP FROM HOUSING. REPLACED INTERNAL BEARING AND RESEALED UNIT. REASSEMBLED AND REPLACED IN VEHICLE.
LABOR REDUCED TO REFLECT OVERLAP WITH TIMING BELT SERVICE

Job Subtotal: $894.37

Recommendations: ***ADVISED 3/2025***
BRAKES: FRONT 8MM, REAR 7MM
TIRES: FRONT 9/32", REAR 1/32"
PSI: 32/32 TORQUE SPEC: 80 FT/LBS

2 OIL HOSES FROM OIL COOLER TO OIL TANK : OIL LEAK. MONITOR AND HAVE REBUILT AT LATER DATE
FRONT LOWER CONTROL ARM BUSHINGS
REAR TIRES
FRONT HOOD STRUTS
DOOR LAMP INOP

TIRE PRESSURE SET TO: LF[32] RF[32] LR[32] RR[32]

12 MONTH UNLIMITED MILEAGE PARTS AND LABOR WARRANTY ON NEW INSTALLED PARTS;WEARABLE ITEMS CARRY 12-MONTH WORKMANSHIP WARRANTY,USED PARTS SUBJECT TO SUPPLIERS WARRANTY, 12 MONTH WORKMANSHIP WARRANTY. CUSTOMER SUPPLIED PARTS NOT ACCEPTED. VEHICLES LEFT IN SHOP PAST COMPLETION DATE WITHOUT PRIOR ARRANGEMENTS MADE WILL BE SUBJECT TO STORAGE FEES OF $35 PER DAY.

WE GLADLY ACCEPT CASH, CHECK, DEBIT AND ALL MAJOR CREDIT CARDS. ALL

------>---->---->---Continued on the next page--->---->----->------>

San Rafael European
BAR #: ARD 00287273
EPA #: CAL000428253
1421 FRANCISCO BOULEVARD EAST
Suite 2
San Rafael, CA 94901
Phone: 415 259-5488 FAX: 415 259-6380

Invoice No.
13599

Order Date 01/17/25 11:14 am
Completed: 03/17/25 03:34 pm

CREDIT CARD TRANSACTIONS ADD A 2.5% PROCESSING FEE.

Payments to San Rafael European	Cost Summary	
Status: Completed Work Order	Labor	11873.62
	Parts	9195.73
Payments:	Haz Waste	19.60
	2.5CC	526.73
	Tax	850.61
	Total	$22466.29
	Payments	0.00
	Bal Due	22466.29

Thank you for choosing San Rafael European

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

SAN RAFAEL SRE EUROPEAN

1421 Francisco Blvd E San Rafael, CA 94901 415-259-5488 www.sfmotorsports.com service@sfmotorsports.com

3 YEAR TIMING BELT SERVICE FERRARI 550/575/612

- ✓ Renew oil and filters
- ✓ Add BG Fuel Improver
- ✓ Add BG Oil improver
- ✓ Renew Air filters
- ✓ Renew Brake/Clutch fluid (bleed if necessary)
- ✓ Renew timing belts
- ✓ Renew timing belt idler pulleys
- ✓ Check and adjust camshaft position
- ✓ Renew spark plugs
- ✓ Renew ancillary drive belts
- ✓ Check window, sunroof, and/or convertible top operation
- ✓ Inspect dashboard instruments and lighting
- ✓ Check horn operation
- ✓ Check A/C and climate control system operation
- ✓ Inspect condition of body
- ✓ Inspect chassis for oil and fluid leaks
- ✓ Diagnosis system: read out fault memory Leonardo
- ✓ Check exterior light operation, replace failed bulbs
- ✓ Inspect fuel cap and seal
- ✓ Renew fuel filters
- ✓ Install windshield washer solvent/anti-freeze
- ✓ Inspect cooling system connections and lines
- ✓ Inspect water pump – Rebuilt
- ✓ Renew coolant
- ✓ Install BG cooling system conditioner kit
- ✓ Check blow-by system
- ✓ Inspect brake pipes/hoses, calipers, connections
- ✓ Inspect air injection connections and pipe valves
- ✓ Inspect exhaust system for leaks and damage
- ✓ Inspect brake pipes/hoses, calipers, connections
- ✓ Inspect fuel injection connections and lines
- ✓ Check and adjust parking brake
- ✓ Inspect ignition system cables and connections
- ✓ Inspect wear condition of the brakes
- ✓ 8 mm remaining front 7 mm remaining rear
- ✓ Inspect front tire tread 9 /32 remaining
- ✓ Inspect rear tire tread 1 /32 remaining –
- ✓ Set tire pressure Fronts 32 psi Rears 32 psi
- X Check and record clutch value (F1 only) MANUAL
- ✓ Tighten wheel lugnut 80 Ft/Lbs.
- ✓ Inspect joints for front and rear suspensions, front and rear under-chassis tightening torques
- ✓ Inspect steering system, knuckle joint protection, steering rack boots, linkage boots, axle shaft boots
- ✓ Inspect starter motor and generator absorption charge
- ✓ Tighten screws, nuts and bolts (including those on the exhaust system), connections, clips and clamps
- ✓ Inspect headlight adjustment
- ✓ Inspect and lubricate hinges, linkages, door locks, and front and rear lids
- ✓ Check tightening screws and bolts on the bodywork
- ✓ Perform final test drive
- ✓ Set clock
- ___ Update service manual

Recommendations / Comments: _____

_____

Technician Rick

For the immediate and long-term benefit of your vehicle, the suggested service/maintenance recommendations by San Francisco Motorsports meet and exceed factory maintenance schedules. Service suggestions in this schedule have been determined by the manufacturer's recommendations and our years of automotive experience in normal and under severe driving conditions.

NEXT SERVICE DUE March 2026