

CALLER ☐ DONE ☐ IN WORK ☐ C-CODE ☐ U-USED ☐ R-REBUILT ☐ N-NEW ☐ CODE ☐ DISCARD PARTS ☐ SAVE PARTS ☐

I hereby authorize the repair work listed hereon, including related work, to be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

CUSTOMER
SIGNATURE **X**

DATE


TERMS CASH: Unless arrangements made prior to authorization.
Cars left after work is completed may be subject to a storage fee.

THE LAW REQUIRES THAT YOU, THE CUSTOMER, BE INFORMED BEFORE THE SMOG INSPECTION IF THE STATION FOR ANY REASON WOULD NOT REPAIR YOUR VEHICLE SHOULD IT FAIL THE TEST.

X

EUROPEAN PERFORMANCE

32 GALLI DRIVE, SUITE 6 & 7
NOVATO CA 94949
(415)382-8394 (415)382-8395
BAR AC 187779
EPA ID NUMBER: CA0000996348



1979 PORSCHE
LICENSE : ?
VIN
ENGINE F:
ENGINE C:

9113C
MILEAGE: 199738
PD :
DIS :

INVOICE #: 5672

DATE/TIME : 7/06/04 2:34PM

WRITTEN BY :

TYPE : CUSTOMER

10.00	N	ENGINE OIL	ENGINE OIL	2.75	27.50
1.00	N	930 107 164 01	OIL FILTER	8.50	8.50
2.00	N	930 107 040 01	OIL RETURN TUBE KIT	30.39	60.78
1.00	N	901 501 930 22	OIL TANK BRACKET	28.00	28.00
2.00	N	DPS	DRAIN PLUG SEAL	0.90	1.80
1.00	N	901 999 43 00	OIL LINE	17.59	17.59

ESTIMATE OF REPAIRS: Includes all parts, labor, handling, and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

ORIGINAL ESTIMATE \$199.61

X

CUSTOMER SIGNATURE

DATE

I acknowledge notice and oral approval of an increase in the original estimated price. Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales ticket.

MAJOR Every 15K
Last Major Service @ 190,018

0.50	CHANGE OIL AND FILTER,	45.00
	INSPLCT AND REPORT,	
1.80	REPLACE PASSENGER SIDE	162.00
	OIL DRAINBACK	
	TUBES (LEAKING),	
0.30	RENEW BROKEN OIL TANK	27.00
	BRACKET,	

ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 90 DAYS OR 3,000 MILES, (UNLESS OTHERWISE NOTED ON FACE HEREOF) WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED AT CUSTOMER'S EXPENSE TO OUR SERVICE DEPT. FOR ADJUSTMENT. WARRANTY IS VOID IN CASE OF MISUSE/NEGLECT.

NOT TAXED

METHOD OF PAYMENT	PARTS	144.11	
PAYMENT DATE	7/06/04	LABOR	234.00
CHECK	\$199.61	HAZARD	5.00
CHECK #	3439	SUPPLY	5.00
		SUB TOT	188.11
		TAX	10.44
			000000000000000000
		TOTAL	\$398.61

CUSTOMER COPY

(**HAZARDOUS MATERIAL) A hazardous waste disposal charge will be added when items removed from your vehicle or items used in conjunction with the repair of your vehicle must be disposed of in compliance with federal, state and local government waste regulations. These items could include any of the following: Oil, grease, antifreeze, insect cleaning fluids, non-flammable liquids, etc.

"Serving Your Tire Needs Since 1964"

MEL'S TIRE PROS

2154 WASHINGTON AVENUE
SAN LEANDRO, CA 94577
(510) 351-8855

PAGE 1

12/29/2005
CUSTOMER REF No -
SALESMAN - MARK
W/O # -123159

INVOICE # 153597

CUSTOMER CODE

MAKE 1977 PORSCHE

MILEAGE 202195

LICENSE NO. 2VDF154

PHONE

PRODUCT CODE	DESCRIPTION	QTY.	PRICE	AMOUNT
M2056015E	MICH 205/60R15 91H EXALTO A/S	2	98.95	197.90
ZZTMBS	TIRE MOUNT & COMPUTER BALANCE	2	10.00	20.00
DF	DISPOSAL FEE	2	1.25	2.50
CTF	CALIFORNIA TIRE FEE (TAX)	2	1.75	3.50
	REPLACE REARS			



TOTAL PARTS: 197.90
PAID BY M.C./VISA OR DEBIT

TOTAL LABOR: 26.00

SALES TAX 17.32

NO CHARGE FOR TIRE ROTATIONS ON
TIRES PURCHASED FROM MELS TIRE PROS

TOTAL

\$

241.22

I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS.
YOU AND YOUR EMPLOYEES MAY OPERATE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR
DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON VEHICLE TO SECURE
THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE
TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER
CAUSE BEYOND YOUR CONTROL. TAG MUST BE PRESENTED FOR CREDIT OR WARRANTY WORK.


CALLED ☐ DONE ☐ IN WORK ☐ C-CODE ☐ U-USED ☐ R-REBUILT ☐ N-NEW ☐ CODE ☐ DISCARD PARTS ☐ SAVE PARTS ☐

I hereby authorize the repair work listed hereon, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

CUSTOMER SIGNATURE **X** _____ DATE _____
 TERMS CASH: Unless arrangements made prior to authorization.
 Cars left after work is completed may be subject to a storage fee.
 THE LAW REQUIRES THAT YOU, THE CUSTOMER, BE INFORMED BEFORE THE SMOG INSPECTION IF THE STATION FOR ANY REASON WOULD NOT REPAIR YOUR VEHICLE SHOULD IT FAIL THE TEST.
X

EUROPEAN PERFORMANCE

32 GALLI DRIVE, SUITE 6 & 7
 NOVATO CA 94949
 (415)382-8394 (415)382-8395
 BAR AC 187779
 EPA ID NUMBER: CA0000996348



1977 PORSCHE 911
 LICENSE : 2VD7154 MILEAGE: 202512
 VIN : PD :
 ENGINE P: DIS :
 ENGINE C:

INVOICE #: 6216
 DATE/TIME : 4/10/06 10:45AM
 WRITTEN BY :
 TYPE : CUSTOMER

1.00	N	930 107 764 00	OIL FILTER	7.50	7.50
0.00	N	ENGINE OIL	ENGINE OIL	2.93	29.50
2.00	N	DPS	DRAIN PLUG SEAL	0.90	1.80

ESTIMATE OF REPAIRS: includes all parts, labor, handling, and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.
 ORIGINAL ESTIMATE \$106.20

X
 CUSTOMER SIGNATURE _____ DATE _____
 I acknowledge notice and oral approval of an increase in the original estimated price. Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales ticket.

0.60 CHANGE OIL AND FILTER. \$4.00
 INSPECT AND REPORT.
 CHECK FRONT END NOISE.
 NEEDS STEERING RACK.
 FRESH AIR SYSTEM NOT WORKING.

ALL NET REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 90 DAYS OR 3,000 MILES, (UNLESS OTHERWISE NOTED ON FACE HEREOF) WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED AT CUSTOMER'S EXPENSE TO OUR SERVICE DEPT. FOR ADJUSTMENT. WARRANTY IS VOID IN CASE OF MISUSE/NEGLECT.

= NON-TAXED

METHOD OF PAYMENT	J PARTS	39.80
AYMENT DATE / /	J LABOR	54.00
	HAZARD	5.00
	SUPPLY	5.00
	SUB TOT	102.80
	TAX	3.40

TOTAL		\$106.20

("HAZARDOUS MATERIAL") A hazardous waste disposal charge will be added when items removed from your vehicle or items used in conjunction with the repair of your vehicle must be disposed of in compliance with federal, state and local government hazardous waste regulations. These items could include any of the following: Oil, grease, antifreeze, brake, cleaning fluids, non-hazardous items, etc.

PARTSHEAVEN**PARTSHEAVEN**

23694 BERNHARDT STREET

HAYWARD, CA 94545

(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250

www.partsheaven.com

Invoice No. 157913

MEMBER DATE ORDERED

05/30/06

SHIPPING DATE

05/30/06

178529

CORE DUE

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

AIR PUMP

1 PORSCHE 911 (Extra Sale) 77 Int.3673PH SMOG PUMP
FOR 911 75-85 NON-TURBO.-

CORE-DUE

2 AIR PUMP

#0001

125.00 T

#0000

75.00 T

Doc # 18113

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:

NO CASH REFUNDS

NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY REPLACEMENT ONLY GUARANTEE, IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR REMOVAL INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL 200.00

SALES TAX 17.50

SHIPPING CHARGES 0.00

TOTAL 217.50

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.Amount paid: 217.50
Amount due: 0.00

PARTSHEAVEN

PARTSHEAVEN

23694 BERNHARDT STREET

HAYWARD, CA 94545

(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250

www.partsheaven.com

ce No. 158099

DATE ORDERED

07/08/06

WORK ORDER NO. MAIL COPY

DISMANTLER

READY

CORE EXCHANGE

R/O NUMBER

TRUCK LINE

SALES PERSON

SHIPPING DATE

178725

SN

07/08/06

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

KNEE PADS

2 @ \$75.00 each PORSCHE 911 77

#

150.00

#0001

Doc # 2477

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:

NO CASH REFUNDS

NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL

150.00

SALES TAX

13.13

SHIPPING CHARGES

0.00

TOTAL

163.13

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 163.13
Amount due: 0.00

EMISSION CONTROL
WORK ORDER

MARINWOOD SMOG CHECK

100 Marinwood Ave.
SAN RAFAEL, CA 94903
(415) 479-7050
ARD# AH241257
Smog Test Only



Date: 7-17-06
Time Received
A.M.
P.M.
Promised
A.M.
P.M.
Written By

BILLING


☐ CASH

☒ BANK CARD NO.

☐ OIL CO. CARD NO.

☐ CHECK NO.

☐ OTHER



Year - Model PORSCHE SL 911 Odometer 202968
Vin No. 77 License No. 20DF154

Phone when ready
Yes ☐ No ☐
Res.
Bus.
Inspector
Mech.

ALL PARTS ARE NEW UNLESS OTHERWISE DESIGNATED				REPAIR ORDER LABOR INSTRUCTION		INTERNAL
* CODE N-NEW U-USED R-REBUILT				I/M SMOG INSPECTION		60.00
				I/M SMOG CERTIFICATE		8.75
QTY.	*	PART NO. OR DESCRIPTION	PRICE	AMOUNT		
					MT 193 RA	
					F1	
					RCS RGR	
					15.00 910 FWP	
					PLW	
					BEVA 17	
					TAC AIR	
				We are a TEST ONLY facility & can NOT perform any repairs or adjustments to your vehicle if it fails.		
TOTAL PARTS						

THIS IS TO ADVISE YOU THAT SOME EMISSION CONTROL DEVICES MAY STILL BE COVERED UNDER MFG.'S WARRANTY.
BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES ARE NECESSARY.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs hereto. You will hold harmless the shop or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event an attorney is retained to enforce this repair order, the collection of any sums due I agree to pay costs of collection and reasonable attorney fees.

[Signature]

Authorized By _____ CUSTOMER ACKNOWLEDGES RECEIPT OF A COPY HEREOF

DATE _____ TIME _____

ESTIMATE:
INSPECTION FEE 60.00
CERTIFICATE IF ISSUED 8.75
TOTAL ESTIMATE 68.75

RETURN OLD PARTS ☒ ☐

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

X INITIALS _____

ESTIMATED COST
\$ OF ADDITIONAL REPAIR

DATE

TIME

IND.
CONTACTED

PHONE
NO.

TOTAL LABOR 68.25
PARTS
OIL & FLUIDS
SUB-TOTAL
TAX
GAS / GAL
TOTAL AMOUNT 68.25

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 07/17/2006 @ 11:09

Model Year: 1977	Make: PORSCHE	Model: 911 TARGA
License: 2VDF154	State: CA	VIN: 9117210691
Engine Size: 2.7 L	Type: Passenger	Transmission: Manual
GVWR: N/A	Test Weight: 3500	Cylinders: 6
Odometer: 202968	Certification: Federal	VLT Record #: 00006
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: HA386263
DMV ID Number: 9344A564H931

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Pass	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
N/A	Catalytic Converter	Pass	Air Injection	N/A	MIL/Check Engine Light
Pass	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
N/A	Fuel Cap Functional	Pass	Ignition Timing: 15 BTDC		Oxygen Sensor
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	N/A	Liquid Fuel Leaks
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

Test	RPM	%CO ₂		%O ₂		HC (PPM)		CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	
15 mph	1593	14.7	14.4	20.1	17	59	1.45	0.20	0.18	1314	564	831		PASS
25 mph	2535	14.2	14.3	16.8	17	17	1.10	0.17	0.17	1174	469	723		PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

MARINWOOD SMOG CHECK
100 MARINWOOD AVE. SAN RAFAEL 94903
415-479-7050
Station Number: TH241257

Technician Name/Number: GROMOV OLEKSANDR/EA146280
Repair Tech Name/Number:
Software Version/EIS Number: 0403/ES419543

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date

Technician's Signature



GERMAN AUTO REPAIR

CALIFORNIA
ASC
AUTOMOBILE SERVICE CENTERS
PROFESSIONALS -
AUTOMOTIVE SERVICE

Authorized
Service

6508 N. Blackstone Ave. • Fresno, CA 93710 • (559) 438-6508

Customer
Address
City/St.
Zip Code
Home Phone
Work Phone

License No. 2VDF154
Mileage 203332
Yr/Model 1977 911SC
Chassis: 9117210691
Engine:
Color WHITE Prod. Date

R.O. # 22735 of Est. # 3913 Original BAR # AH 148793 Date 08-11-2006

Labor Completed

DESCRIPTION	EMP	TOTAL
VEHICLE TOWED IN FOR NO START	32	135.00
FOUND IGNITION CONTROL UNIT NOT FUNCTIONING.		
REPLACED UNIT WITH AFTERMARKET REPLACEMENT UNIT.		
REPLACE COIL WITH RECOMMENDED COIL.		
INSTALL SMOG PUMP BELT.	32	22.50

Materials Issued

QTY	PART NUMBER	GROUP	EACH	TOTAL
1	901-602-702-00	IGN CNTRL	491.44	491.44
1	00-025	IGN COIL	112.44	112.44
1	10 X 950	V BELT	8.35	8.35

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE *W*

Original Estimate: \$ 90.00

Qty	Fuel & Oil	Price	Payments	TOTAL Labor
	Fuel	0.00	Type <i>VISA</i>	157.50
0	OTS, Oil @ 2.25	0.00	No. <i>518.20</i>	TOTAL Materials 612.23
0	Trans. Oil @ 2.75	0.00	Amount <i>518.20</i>	TOTAL Fuel & Oil 0.00
0	Gear Fluid @ 2.00	0.00	Date <i>8-11-06</i>	TOTAL Sublet Labor 0.00
	Grease	0.00	By <i>W</i>	TOTAL Other 0.00
				Misc. Shop Parts 0.00
				Hazardous Waste 0.00
				SUBTOTAL 769.73
				TAX 48.86
				** TOTAL DUE ** \$ 818.59

SIGNATURE ACKNOWLEDGES RECEIPT OF VEHICLE *W*

EPA ID NUMBER: CAL00183348

READ IMPORTANT INFORMATION ON REVERSE SIDE

PARTSHEAVEN

PARTSHEAVEN

23694 BERNHARDT STREET

HAYWARD, CA 94545

(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250

www.partsheaven.com

SOLD TO

No.

DATE ORDERED

10/30/06

WORK ORDER NO.

MA COPY

DISMANTLES

READY

COKE EXCHANGE

R/O NUMBER

TRUCK LINE

SALES PERSON

SHIPPING DATE

102033

AL

10/30/06

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

RECOVERED HIGHBACK SEAT

1 PORSCHE 911 (Extra Sales) 77

#00002

575.00

500-000-4781

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:
NO CASH REFUNDS
NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE, IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL

575.00

SALES TAX

76.56

SHIPPING CHARGES

0.00

TOTAL

651.56

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 951.56
Amount due: 0.00

PARTSHEAVEN23694 BERNHARDT STREET
HAYWARD, CA 94545(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250
www.partsheaven.com**PARTSHEAVEN**

Invoice No. 170908

NUMBER DATE ORDERED

10/29/07

SHIPPING DATE

10/29/07

WORK ORDER NO.	MAIL COPY	DISMANTLER	READY	CORE EXCHANGE	R/O NUMBER	TRUCK LINE	SALES PERSON
192115							AI

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

ANTENNA

1 PORSCHE 911 (Extra Sale) 76

#0002

#

87.50 T

FLOOR MATS

2 PORSCHE 911 (Extra Sale) 76

#0002

#

135.00 T

TARGA W/RED LOGO

Doc # :33096

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:
NO CASH REFUNDS
NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL 222.50

SALES TAX 19.47

SHIPPING CHARGES 0.00

TOTAL 241.97

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.Amount paid: 241.97
Amount due: 0.00

★ CODE N-NEW U-USED R-REBUILT M-OEM

BRIDGES FOREIGN AUTO

SPECIALIZING IN GERMAN & JAPANESE AUTOS

1475 162nd AVE. (BEHIND THRIFT TOWN)

SAN LEANDRO, CA 94578

(510) 278-6434

BAR # AL 121145

EPA # CAL 000027813

009700

QTY	★	PART NO. OR DESCRIPTION	SALE
1		OIL FILTER	1700
1		FUEL FILTER	4100
6		SPARK PLUGS	3600
1		VALVE COVER KIT	2600
1		AIR FILTER	3400
1		HEATER HOSE	1500
2		VALVE COVER	9000
		NEW 930 COUERS	

Year-Make-Model

77 TAUGA

License No.

2UDF154

Odometer

705482

ESTIMATE AMT.

3500

ADD'L AUTH. AMT.

550

REVISED ESTIMATE

DATE:

TIME: 245

APPROVED BY

IN PERSON

PHONE

I hereby authorize the repair work below to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized by

ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

(SIGNATURE OR INITIALS)

OPER. NO.

REPAIR ORDER LABOR INSTRUCTION

INTERNAL

CHUCK FOR OIL LEAK
REPLACE VALVE COUERS LOWERS
COMPLETE TUN-UP ADJ TIRING
LUBE CLUTCH PEDAL ASSEMBLY
CHUCK ON CLUTCH ASSEMBLY
LUBE PEDAL ASSEMBLY
REPLACE INTERMIN LATER
REPLACE VACUUM HOSE ON DIST. N/C
CHECK OVER VEHICLE N/C

CHECK ON TENSIONER SAUCERS LATER
RECOMMEND NEW HYDRAULIC TENSIONER KIT

Additional Materials from reverse side

TOTAL PARTS

5 28400

QTY.

SALE

GALS. GAS

QTS. OIL

LBS. GREASE

TOTAL GAS OIL GREASE

RECOMMENDED SERVICE:

1. OIL COOLER
2. GEAR AND LEAKING
3. CAR HOUSING
4. GASKET
5. CHAIR TENSIONER

ADDITIONAL COSTS

IN PERSON

PHONE

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.

INIT.

TEARDOWN ESTIMATE - PARTS AND LABOR

ORIGINAL ESTIMATES

PHONE

DATE

TIME

REVISED ESTIMATES

REASON

AUTHORIZED BY

DATE

TIME

Total Labor

Hazardous Waste Disposal

Special Repairs

Parts

Tires

Gas, Oil & Grease

Paint & Body Shop

Sales Tax

TOTAL

64747

2747

64747

2747

64747

2747

64747

BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES ARE NECESSARY. A CUSTOMER WILL BE CHARGED FOR INSPECTION REGARDLESS OF PASS OR FAIL.

SPECIAL REPAIRS

TOTAL SPECIAL REPAIRS

Please read important information on back.

Return Old Parts ☐ Yes ☐ No

INVOICE COPY

ARC-5784

QTY	★	PART NO. OR DESCRIPTION	SALE
-----	---	-------------------------	------

(510) 278-6434

EPA # CAL 000027813

Retrn Old Parts ☐ Yes ☐ No

Date 11/6/01

Time Received

OPERATION

LAB. CHG.

A.M.
P.M.Lubrication

A.M.

Class: 01

	Promised
--	----------

P.M.	Change Oil	☐
	Change Oil	☐

Filter Cart	
Service	

Ar Cleaner	☐
Charger	☐

Change Trans. Oil	☐
-------------------	--------------------------

Adjust Transmission ☐

Hazardous Waste	☐
-----------------	--------------------------

Front
Back ☐

10

Time	
Adult	

Brakes	☐
Exhaust	☐

Control,	Recall Paris	☐
----------	-----------------	--------------------------

Destroy	☐
Parts	

--	--

1

2

2

10

1

SPECIAL REPAIRS

TOTAL SPECIAL REPAIRS

OFFICE COPY

WFO-372

"Serving Your Tire Needs Since 1964"

MEL'S TIRE

2154 WASHINGTON AVENUE
SAN LEANDRO, CA 94577
(510) 351-8855

PAGE 1

2/27/2008
CUSTOMER REF No -
SALESMAN - BRIAN
W/O # -134085

CUSTOMER CODE

INVOICE # 163335

MAKE 1977 PORSCHE MILEAGE 205969 LICENSE NO. 2VDF154 PHONE (510) 632-3699

PRODUCT CODE	DESCRIPTION	QTY.	PRICE	AMOUNT
M2056015E	MICH 205/60R15 91H EXALTO A/S	2	99.95	199.90
	8 AVAIL IN SAN DIMAS 8315-1300			
ZZTMBM	MOUNT & ROAD FORCE BALANCE	2	10.00	20.00
DF	DISPOSAL FEE	2	2.00	4.00
CTF	CALIFORNIA TIRE FEE (TAX)	2	1.75	3.50

TOTAL PARTS: 199.90

TOTAL LABOR: 27.50

PAID BY M.C./VISA OR DEBIT

SALES TAX 17.49

NO CHARGE FOR TIRE ROTATIONS ON
TIRES PURCHASED FROM MELS TIRE

TOTAL

\$

244.89

I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. TAG MUST BE PRESENTED FOR CREDIT OR WARRANTY WORK.

X

PRO SMOG

TEST ONLY CENTER

(510) 614-9888



No 16169

SMOG TEST-ONLY INVOICE

TEST ONLY

B.A.R. #AJ235605 14105 Washington Ave. (Corner of 139th Ave.) • San Leandro, CA 94578

TODAY'S DATE 06/06/08	YEAR 1977	MAKE AURORA	MODEL 311
ODOMETER 107390	LIC. PLATE # 2V8F154	MOTOR #	
WRITTEN BY 1577	CUSTOMER P.O. #	G.V.W.R.	
TEST TYPE: ☐ BIENNIAL ☐ CHANGE OF OWNERSHIP ☐ 2% ☐ HEP ☐ INITIAL			
☒ FED. ☐ CALIF. ☐ O/S		ENGINE	# OF CYLINDERS
TRANSMISSION: ☐ AUTO ☐ STD		TIMING	EM. LIGHT
V.I.N.			

METHOD OF PAYMENT: ☐ CASH ☐ CHECK ☒ CHARGE ☐ DEBIT CARD ☐ CREDIT CARD

ORIGINAL ESTIMATE \$ 75.00

SMOG TEST CHECK OFF						OPR.	DESCRIPTION OF WORK	AMOUNT
P-Pass	M-Modified	F-Defective	D-Disconnected	S-Missing	N-N/A		SMOG TEST	65 00
PCV			C/I				PRETEST ☐ YES ☐ NO	
TAC			AP/P				CERTIFICATE #	25
EVP			OXY				ELECTRONIC TRANSFER FEE (E.T.F.)	75
CAT			WRG				RETEST	
EGR			VAC				GAS CAP	
SPK			OTH					
I understand Pro Smog Test Only Center does not do any repairs or adjustments and cannot diagnose or refer me to any specific shop for repairs. I also understand that I will have to pay the inspection fee whether the vehicle passes or not. The costs of performing required inspection services has been explained to my satisfaction.							VEHICLE WITH FUEL METER IS NOT	
							AVAILABLE (N/A EVAP TEST)	
						TEST RESULTS: ☐ PASS ☐ FAIL ☐ ABORT ☐		

THIS SMOG TEST-ONLY STATION CANNOT PERFORM ANY DIAGNOSTICS, ADJUSTMENTS OR REPAIRS						TOTAL WORK		65 00
I hereby authorize the above smog test to be performed. Smog test fee is due whether above vehicle passes or fails the smog test. You and your employees may operate above vehicle for purposes of testing, inspection and delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of this invoice. You will not be held responsible for loss or damage to vehicle due to fire, theft, accident, dynamometer testing or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read and understand the above and acknowledge receipt of an estimate.						CERTIFICATE		25
X <i>[Signature]</i>						E.T.F.		75
DATE 06/06/08						SUB TOTAL		
REVISED: _____ DATE _____ TIME _____ PHONE • FAX • EMAIL _____ ESTIMATE \$ _____ REASON _____						SALES TAX		
☐ PHONE ☐ EMAIL ☐ IN PERSON ☐ FAX ADDITIONAL COST \$ _____						GRAND TOTAL		75 00
I acknowledge notice and oral approval of an increase in the original estimated price.								

CUSTOMER COPY

(510)614-9888
Station Number: TJ235605

Software Version/EIS Number: 0703/ES315749

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

06/06/08
Date

[Signature]
Technician's Signature

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 06/06/2008 @ 12:04

Model Year: 1977
License: 2VDF154
Engine Size: 2.7 L
GVWR: N/A
Odometer: 207320
Fuel Type: Gasoline

Make: PORSCHE
State: CA
Type: Passenger
Test Weight: 3500
Certification: Federal
Exhaust: Single

Model: 911 TARGA
VIN: 9117210691
Transmission: Manual
Cylinders: 6
VLT Record #: 00006
Inspection Reason: High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: NA985878
DMV ID Number: 9045A766N391

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
N/A	Catalytic Converter	Pass	Air Injection	N/A	MIL/Check Engine Light
Pass	EGR Visual	Pass	Vacuum Lines to Sensors/ Switches	Pass	Carb./Fuel Injection
N/A	EGR Functional			Pass	Other Emission Related Components
N/A	Fuel Cap Functional	Pass	Ignition Timing: 7 BTDC		Oxygen Sensor
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	N/A	Liquid Fuel Leaks
Pass	Spark Controls	N/A	Filipipe Restrictor	Pass	
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

		%CO ₂	%O ₂	HC (PPM)			CO (%)			NO (PPM)			Results
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	1582	13.4	1.8	201	47	45	1.30	0.20	0.27	1314	554	801	PASS
25 mph	2519	12.5	3.2	168	37	16	1.10	0.17	0.15	1174	468	628	PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

Pro Smog
14105 Washington Ave.
(510)614-9888
Station Number: TJ235605

Technician Name/Number: NGUYEN, DANH/EA149542
Repair Tech Name/Number:
Software Version/EIS Number: 0703/ES315749

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

06/06/08
Date

Technician's Signature

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs therefor. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

CUSTOMER
SIGNATURE **X**

DATE

TERMS CASH: Unless arrangements made prior to authorization.
Cars left after work is completed may be subject to a storage fee.

THE LAW REQUIRES THAT YOU, THE CUSTOMER, BE INFORMED BEFORE THE SMOG INSPECTION IF THE STATION FOR ANY REASON WOULD NOT REPAIR YOUR VEHICLE SHOULD IT FAIL THE TEST.

X

EUROPEAN PERFORMANCE

32 GALLI DRIVE, SUITE 6 & 7
NOVATO CA 94949
(415)382-8394 (415)382-8395
BAR AC 187779
EPA ID NUMBER: CA0000996348

1977 PORSCHE 911
LICENSE : 2VDF154 MILEAGE: 208368
VIN : PD :
ENGINE F: DIS :
ENGINE C:

INVOICE #: 6786

DATE/TIME : 9/05/08 12:58PM

WRITTEN BY :

TYPE : CUSTOMER

10.00	N	ENGINE OIL	3.90	39.00
1.00	N	330 167 764 00	14.28	14.28
2.00	N	OIL FILTER	0.90	1.80
2.00	N	DRAIN PLUG SEAL	27.47	54.94
2.00	N	901 355 632 01	28.71	57.42
2.00	N	901 355 631 01	52.58	105.16
1.00	N	911 351 950 01	7.50	15.00
2.00	N	FRONT BRAKE ROSE		
		REAR BRAKE ROSE		
		FRONT BRAKE PADS 911		
		BRAKE FLUID		

ESTIMATE OF REPAIRS: Includes all parts, labor handling, and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

ORIGINAL ESTIMATE \$838.23

X

CUSTOMER SIGNATURE

DATE

I acknowledge notice and oral approval of an increase in the original estimated price. Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales ticket.

CHECK BRAKES-PEDAL GOES
DOWN SOMETIMES WHILE
DRIVING AT HWY SPEED.

RIGHT FRONT
CALIPER-STOCK PUCKS IN
BOTH FRONT CALIPERS HAVE
ROTTATED PADS WORN OUT.

* 3.00 RENEW FRONT AND REAR 300.00
BRAKE HOSES-TEST WARNING
SYSTEM FOR HYD FAILURE-
OK, FLUSH AND BLEED
SYSTEM.

* 2.00 RENEW FRONT BRAKE PADS, 200.00
REMOVE CALIPERS TO
ALIGN PUCKS.

* 0.80 CHANGE OIL AND FILTER, 80.00
INSPECT AND REPORT.

* 1.00 CHECK CLUTCH AND ADJUST
AS NEEDED.

= NON-TAXED

METHOD OF PAYMENT	3 PARTS	235.02
PAYMENT DATE	/ /	3 LABOR 580.00
	HAZARD	5.00
	SUB TOT	820.02
	TAX	18.21

TOTAL		\$838.23

ALL NEW REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 90 DAYS OR 3,000 MILES, (UNLESS OTHERWISE NOTED ON FACE HEREOF) WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED AT CUSTOMER'S EXPENSE TO OUR SERVICE DEPT. FOR ADJUSTMENT. WARRANTY IS VOID IN CASE OF MISUSE/NEGLECT.

CUSTOMER COPY

PARTSHEAVEN23694 BERNHARDT STREET
HAYWARD, CA 94545(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250
www.partsheaven.com**PARTSHEAVEN**

Invoice No. 179083

DATE ORDERED

09/25/08

SHIPPING DATE

09/25/08

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

KNOB

1 PORSCHE 911 (Extra Sale) 77

#0001

#

5.00 T

ROSE

2 PORSCHE 911 (Extra Sale) 77

#0001

#

10.00 T

PIN SWITCH COVER

2 @ \$2.50 each PORSCHE 911 77

#0002

#

5.00 T

PLUG

5 PORSCHE 911 (Extra Sale) 77

#0002

#

1.00 T

SEAT BELT STOP

2 @ \$2.50 each PORSCHE 911 77

#0001

#

5.00 T

Doc # :50102

DISCLAIMERALL SALES SUBJECT TO FOLLOWING TERMS:
NO CASH REFUNDS
NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED, ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL

26.00

SALES TAX

2.28

SHIPPING CHARGES

0.00

TOTAL

28.28

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.

Amount paid:

28.28

Amount due:

0.00

CALLED []
 DONE []
 IN WORK []
 C-CORE []
 U-USED []
 R-REBUILT []
 N-NEW []
 CODE []
 DISCARD PARTS []
 SAVE PARTS []

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

CUSTOMER SIGNATURE **X**

DATE

TERMS CASH: Unless arrangements made prior to authorization. Cars left after work is completed may be subject to a storage fee.

THE LAW REQUIRES THAT YOU, THE CUSTOMER, BE INFORMED BEFORE THE SMOG INSPECTION IF THE STATION FOR ANY REASON WOULD NOT REPAIR YOUR VEHICLE SHOULD IT FAIL THE TEST.

X

EUROPEAN PERFORMANCE

32 GALLI DRIVE, SUITE 6 & 7
 NOVATO CA 94949
 (415)382-8394 (415)382-8395
 BAR AC 187779
 EPA ID NUMBER: CA0000996348

1977 PORSCHE

911

INVOICE #: 6909

LICENSE :2VDF154

MILEAGE: 211779

DATE/TIME : 2/25/89 2:37AM

VIN :

PD :

WRITTEN BY :

ENGINE F:

DIS :

TYPE : CUSTOMER

ENGINE C:

1.00 N	930 107 764 00	OIL FILTER	14.28	14.28
10.00 N		ENGINE OIL	5.75	57.50
2.00 N	DPS	DRAIN PLUG SEAL	0.90	1.80
2.00 N	914 628 433 00	WASHER VALVES	6.12	12.24

ESTIMATE OF REPAIRS: Includes all parts, labor, handling, and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

ORIGINAL ESTIMATE

\$277.47

X

CUSTOMER SIGNATURE

DATE

I acknowledge notice and oral approval of an increase in the original estimated price. Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales ticket.

0.80	CHANGE OIL AND FILTER.	80.00
	INSPECT AND REPORT.	
1.00	CHECK WINDSHIELD	100.00
	WASHERS, RENEW CHECK	
	VALVES, CLEAN AND ADJUST.	
	NEEDS NEW NOZZLES.	

ALL NET REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 90 DAYS OR 3,000 MILES, (UNLESS OTHERWISE NOTED ON FACE HEREOF) WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED AT CUSTOMER'S EXPENSE TO OUR SERVICE DEPT. FOR ADJUSTMENT. WARRANTY IS VOID IN CASE OF MISUSE/NEGLECT.

* = NON-TAXED

METHOD OF PAYMENT	J PARTS	85.83
PAYMENT DATE / /	J LABOR	180.00
	HAZARD	5.00
	SUB TOT	270.83
	TAX	6.65
		00000000000000000000
TOTAL		\$277.47

CUSTOMER COPY

HAZARDOUS MATERIAL: A hazardous waste disposal charge will be added when items removed from your vehicle or items used in conjunction with the repair of your vehicle must be disposed of in compliance with federal, state and local government hazardous waste regulations. These items could include any of the following: Oil, grease, antifreeze, paint, cleaning fluids, non-flammable items, etc.

14450 GRIFFITH STREET
SAN LEANDRO, CA 94577
PH. (510) 583-1015
FAX (510) 583-1051



Jeff's
Mobile Glass Inc
Since 1976

Auto • Residential • Commercial
Serving The Entire East Bay!
www.jeffsmobileglass.com

AUTO • RESIDENTIAL • COMMERCIAL

MAILING ADDRESS
14450 GRIFFITH STREET
SAN LEANDRO, CA 94577

Email: info@jeffsmobileglass.com

INVOICE
IJM-G041-533909

FEDERAL TAX ID NO.
94-3400375

QUOTE MASTER

00000-0000

> > > Invoice < < <

DATE 4/15/200	ACCOUNT NO. 100	PHONE NO. (000)000-0000	WORK ORDER 0	INSTALL BY	DEPT JMG	CLAIM NO./AUTHOR #	INSTALLED BY	SCHED DATE 4/13/2009
YEAR 1977	MAKE PORSH	MODEL 911TRG	BODY STYLE 2DCPE	V.I.N. NO./STOCK NO.	P.O./POLICY NO.	SCHED TIME		
DATE OF LOSS	CAUSE OF LOSS	VEHICLE COLOR	LICENSE NO.	MILEAGE	PHONE NO 1 (510)562-6245	PHONE NO 2 (000)000-0000		

QTY.	PART NO.	DESCRIPTION	CTL	LIST	PRICE	TOTAL
1.00	FW00193GTNY	Windshield PREMIUM PART	65-84	767.10	175.00	175.00
1.00	WCR 193	Weatherstrip (I) LE for a FW001		76.94	76.94	76.94
1.00	LABOR	Labor Hours		150.00	150.00	150.00

MC #
AOP 91977B

PLEASE PAY FROM THIS COPY

SPECIAL INSTRUCTIONS

Thank you for choosing Jeff's Mobile Glass Inc

RELEASE AND AUTHORIZATION TO PAY OTHER THAN INSURED OR CLAIMANT

The glass has been replaced to my complete satisfaction and I authorize the insurance company to pay direct to the above named Company the full amount due me under the terms of my policy and I understand if for any reason my insurance company does not pay this claim I will be responsible for payment of same including any necessary collection or court costs.

Terms: Net 30 days. 1-1/2% per month (38% annual) **FINANCE CHARGE** will be added to accounts not paid 30 days from date of purchase.

SIGNATURE _____ DATE _____
SEE REVERSE OF INVOICE FOR IMPORTANT WARRANTY INFORMATION

SUB TOTAL	\$426.50
SALES TAX	401.94
TOTAL	24.56
	\$426.50



PARTSHEAVEN

23694 BERNHARDT STREET

HAYWARD, CA 94545

(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250

www.partsheaven.com

PARTSHEAVEN

Invoice No. 184562

DATE ORDERED

06/01/09

SHIPPING DATE

06/01/09

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

MIRROR GLASS

1 PORSCHE 911 (Extra Sale) 77

#0001

#

40.00 T

ROSE

2 @ \$21.00 each PORSCHE 911 77

#0002

#

42.00 T

TARGA TOP

4 PORSCHE 911 (Extra Sale) 77

#0001

#

1200.00 T

PRESS DECAL

2 @ \$25.00 each PORSCHE 911 77

#0002

#

50.00 T

Doc # : 60966

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:

NO CASH REFUNDS

NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL

1332.00

SALES TAX

129.87

SHIPPING CHARGES

0.00

TOTAL

1,461.87

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 1,461.87

Amount due: 0.00

Porboys German Automotive

3640 East 9th Street
Oakland, CA 94601
Phone (510) 437-9400 Fax (510) 437-9990

Date 12/22/2009
Invoice # 3685
PO #
Bar # AC247300

Customer Information:

Company
Customer
Address

Vehicle Information:

Vehicle 1977 Porsche 911SC
VIN # 9117210691
License 2VDF154 Tag #
Engine 3.0 Mileage 217407
Trans 0

Vehicle Problem:

perform oil change...est 179.00 customer is aware of current oil leaks

Recommendations:

Parts Detail:

Part Number	Part Description	Qty	Item Price	Hazard	Core	Ext. Price
OC54	OIL FILTER	1	\$18.68	\$0.00	\$0.00	\$18.68
Kendall 20/50	gt1 motor oil	11.5	\$7.99	\$0.18	\$0.00	\$93.95

Labor Detail:

Type ID	Labor Description	Emp ID	Labor Costs
LOF	Perform Oil Service/911	JT	\$67.00

Parts and Labor are warrantied for 3000 miles or 3 months, whichever comes first. This warranty is limited to the work mentioned on this form only and is not transferable. Warranty excludes any and all A/C work. Vehicle must be returned to our workshop, at customers expenses, to honor warranty, warranty is void in case of misuse and/or neglect.

A Storage Fee of \$50.00 a day will be charged on all vehicles left over 48 hours after completion.

The Parts and Accessories sold and installed by this Repair Shop and the Service connected with the installation and adjustments of the Parts and Accessories sold and installed by this Repair Shop, are Guaranteed to be free from defects in material and workmanship under normal service and use until such Parts and Accessories have been driven, used, or operated for a distance of 4000 miles or a period of 90 days, from date of Service, whichever first occurs, unless otherwise stated under the Part or service listed above. Core charges may apply to certian parts. If core is returnable, full payment will be returned to customer within 10 to 14 buisness days. I also hereby acknowlege notice and oral approval of an increase of the original estimate amount.

Parts Total	\$112.64
Labor Total	\$67.00
Sublet	\$0.00
Subtotal	\$179.64
Sales Tax	\$10.78
Sales Tax 2	\$0.00
Work Order Total	\$190.42
Total Payments	\$190.42
Payment Method	Visa
Amount Due	\$0.00

Signature- _____

Page 1 of 1

EMISSION CONTROL WORK ORDER

NORTHGATE SMOG CHECK

930 Del Presidio
SAN RAFAEL, CA 94903
(415) 444-0811
ARD# AC238307



025345

Date 5/28/20
Time Received
A.M. P.M.
Promised
A.M. P.M.
Written By

BILLING	☐ CASH	Name	[Redacted]	Phone when ready	Yes ☐ No ☐
	☒ BANK CARD NO. <u>M/C</u>	Address	[Redacted]	Appt. No.	Res.
	☐ OIL CO. CARD NO.	City	[Redacted]	Zip	Bus.
	☐ CHECK NO.	Year - Model	<u>94 Porsche</u>	Odometer	Inspector
	☐ OTHER	Vin No.		License No.	Mech.

ALL PARTS ARE NEW UNLESS OTHERWISE DESIGNATED				REPAIR ORDER LABOR INSTRUCTION		INTERNAL
* CODE N-NEW U-USED R-REBUILT				I/M SMOG INSPECTION <u>No I/PET</u>		4/20 825
QTY.	PART NO. OR DESCRIPTION	PRICE	AMOUNT	I/M SMOG CERTIFICATE		
				3.0 Cat 0% 0%		
				Cat Air Fgr 0% No Cat		
				No Label (Wrong Label)		
				We are a TEST ONLY facility & can NOT perform any repairs or adjustments to your vehicle if it fails.		
TOTAL PARTS						

THIS IS TO ADVISE YOU THAT SOME EMISSION CONTROL DEVICES MAY STILL BE COVERED UNDER MFG.'S WARRANTY. BY LAW, YOU MAY CHOOSE ANOTHER LICENSED SMOG CHECK FACILITY TO PERFORM ANY NEEDED REPAIRS OR ADJUSTMENTS THAT THE SMOG CHECK TEST INDICATES ARE NECESSARY.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event an attorney is retained to foreclose this lien or to bring suit for collection of any sums due I agree to pay costs of collection and reasonable attorney fees.

Authorized By <u>[Signature]</u>	CUSTOMER ACKNOWLEDGES RECEIPT OF A COPY HEREOF	DATE	TIME
ESTIMATE: INSPECTION FEE <u>4/20</u>	RETURN OLD PARTS ☒ ☐	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.	
CERTIFICATE IF ISSUED <u>825</u>		X INITIALS _____	
TOTAL ESTIMATE <u>4995</u>		ESTIMATED COST \$ OF ADDITIONAL REPAIR	

TOTAL LABOR	<u>4995</u>
PARTS	
OIL & FLUIDS	
SUB-TOTAL	
TAX	
GAS / GAL	
TOTAL AMOUNT	<u>4995</u>

ESTIMATED COST \$ OF ADDITIONAL REPAIR	DATE	TIME	IND. CONTACTED	PHONE NO.
--	------	------	----------------	-----------

ECO 674-4

(1)
ORIGINAL

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 05/28/2010 @ 14:10

Model Year: 1977	Make: PORSCHE	Model: 911 TARGA
License: 2VDF154	State: CA	VIN: 9117210691
Engine Size: 2.7 L	Type: Passenger	Transmission: Manual
GVWR: N/A	Test Weight: 3625	Cylinders: 6
Odometer: 219276	Certification: Federal	VLT Record #: 00598
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: High Emitter Profile

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: NU267615
DMV ID Number: 9752U965N181

Your Smog Check certificate has been electronically transmitted to DMV.
Your certificate is valid for 90 days from date of issuance.
Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	N/A	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	N/A	MIL/Check Engine Light
Pass	EGR Visual	Pass	Vacuum Lines to Sensors/	Pass	Carb./Fuel Injection
N/A	EGR Functional		Switches	Pass	Other Emission Related
N/A	Fuel Cap Functional	Pass	Ignition Timing: TDC		Components
Pass	Fuel Cap Visual	Pass	Wiring to Sensors	N/A	Oxygen Sensor
Pass	Spark Controls	N/A	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
N/A	Fuel Evaporative Controls Functional				

ASM Emission Test Results

Test	RPM	%CO ₂		%O ₂		HC (PPM)		CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	
15 mph	1603	13.3	2.6	198	47	43	1.29	0.20	0.31	1304	554	1170		PASS
25 mph	2479	12.6	3.6	166	37	18	1.09	0.17	0.14	1164	468	742		PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

Northgate Smog Check
930 Del Presidio Blvd.
415 444-0811
Station Number: TC238307

Technician Name/Number: STAFFANOU, MARK/EA305975
Repair Tech Name/Number:
Software Version/EIS Number: 0903/ES519958

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date

Technician's Signature

I hereby authorize the repair work listed hereon, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

CUSTOMER
SIGNATURE **X**

DATE

TERMS CASH: Unless arrangements made prior to authorization.
Cars left after work is completed may be subject to a storage fee.

THE LAW REQUIRES THAT YOU, THE CUSTOMER, BE INFORMED BEFORE THE SMOG INSPECTION IF THE STATION FOR ANY REASON WOULD NOT REPAIR YOUR VEHICLE SHOULD IT FAIL THE TEST.

X

EUROPEAN PERFORMANCE

32 GALLI DRIVE, SUITE 6 & 7
NOVATO CA 94949
(415)382-8394 (415)382-8395
BAR AC 187779
EPA ID NUMBER: CA0000996348

1977 PORSCHE 911
LICENSE : 2VDF154 MILEAGE: 214270
VIN : PD :
ENGINE F: QTS :
ENGINE C:

INVOICE #: 7218
DATE/TIME : 5/23/10 12:35PM
WRITTEN BY :
TYPE : CUSTOMER

1.00	N	130 101 784 00	OIL FILTER	12.55	12.55
1.00	N	911KCG	VALVE COVER ADJ KIT	76.35	16.35
1.00	N	W80C	SPARK PLUG	3.00	18.00
1.00	N	ENGINE OIL	ENGINE OIL	7.75	72.50
1.00	N	6011	GEAR OIL	5.50	38.50
1.00	N	DPS	DRAIN PLUG SEAL	0.90	1.80
1.00	N	103725	V BELT	9.55	9.55
1.00	N	STI 55581	STARTER SOLENOID	30.00	30.00
1.00	N	911 613 303 11	TURN SIGNAL RELAY	56.51	56.51
1.00	N	0 450 905 016	FUEL FILTER	35.22	35.22
1.00	N	430 502 102 001	IGNITION UNIT PERMA	559.53	559.53
1.00	N	901 602 502 00	COIL	153.87	153.87

ESTIMATE OF REPAIRS: includes all parts, labor handling, and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

ORIGINAL ESTIMATE \$1,826.97

X

CUSTOMER SIGNATURE DATE
I acknowledge notice and oral approval of an increase in the original estimated price. Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales ticket.

Notes

Oil Leaks - Right Cam Seal, Left Camline, Frt Seal, S Hose, Oil Line to Thru Damaged Dist worn + clips Lose. Motor Mounts FAN + Pulley Damaged, Battery Fit? Throttle - Bell Crank on top of engine Driver Door Stog, Oil TANK, Engine + TRAN - cleaning, Plug Wire Ends

ALL NET REPLACEMENT PARTS AND LABOR HAVE A LIMITED WARRANTY FOR 90 DAYS OR 3,000 MILES, (UNLESS OTHERWISE NOTED ON FACE HEREOF) WHICHEVER COMES FIRST. WARRANTY VALID ONLY IF VEHICLE IS RETURNED AT CUSTOMER'S EXPENSE TO OUR SERVICE DEPT. FOR ADJUSTMENT. WARRANTY IS VOID IN CASE OF MISUSE/NEGLECT.

Suspension Bushings, Sway Bar Bushings Brake Master Cylinder? Rear Ride Heights

1.00	DIAGNOSIS AND REPAIR TO	100.00
	RUN RENEW IGNITION	
	CONTROL UNIT AND COIL	
	REPAIR GROUND TO PLATE	
	CHECK WIRING	
0.60	INSTALL HOT START KIT	60.00
0.60	CHECK TURN SIGNALS, RENEW RELAY, CLEAN CONNECTIONS	60.00
5.00	15000 MILE SERVICE & TUNE ADJUST VALVES, TUNE ENGINE RENEW FILTERS & FLUIDS, INSPECT & REPORT.	500.00

* NON-TAXED

METHOD OF PAYMENT 7 PARTS 4,009.38
PAYMENT DATE / / 3 LABOR 720.00
HAZARD 8.75
SUB TOT 4,738.13
TAX 90.84
TOTAL \$1,826.97

CUSTOMER COPY

CALLED ☐ DONE ☐ IN WORK ☐ C = CORE ☐ U = USED ☐ R = REBUILT ☐ N = NEW ☐ CODE ☐ DISCARD PARTS ☐ SAVE PARTS ☐

necessary materials, you and your employee may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

EUROPEAN AUTOTECH

31-J BETA COURT
 SAN RAMON CA 945830000
 (925) 820-6460

BAR # RC 116666 EPA# CAL000021453
 FAMILY OWNED AND OPERATED SINCE 84

CUSTOMER SIGNATURE

X

DATE

7-21-10

TERMS CASH: Unless arrangements made prior to authorization.
 Cars left after work is completed may be subject to a storage fee.

CUSTOMER SIGNATURE

X

DATE

Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales invoice.

1977 PORSCHE 911S TARGA
 LICENSE :2VDF154 MILEAGE: 219815
 VIN :9117210691 BODY:
 COLOR CO:WHITE PRO: 10/76
 ENGINE N:3.2

INVOICE #: 28723

DATE/TIME : 7/19/10 2:32PM
 PROMISED BY: 7/21/10 5:00PM
 WRITTEN BY : 9

QTY	COND	PART NUMBER	DESCRIPTION	PRICE	TOTAL
1.00	N	911-355-011-12	BRAKE MASTER CYLINDER	281.45	281.45
2.00	N	DOT-4	BRAKE FLUID	10.00	20.00
1.00	N	EC	BRAKE CLEAN	5.00	5.00
1.00	N	HOSE	BULK MISC. HOSE	10.00	10.00

HRS	EMP	LABOR DESCRIPTION	TOTAL
9		PEDAL IS MUSHY CHECK BRAKE OPERATION AND REPLACE MASTER CYLINDER IF NEEDED.	249.90

BRAKE PEDAL SINKS WHEN YOU HOLD PRESSURE ON IT. THERE ARE NO VISIBLE LEAKS IN THE SYSTEM. THE BRAKE FLUID IS SEVERLY CONTAMINATED. FLUSH SYSTEM AND THEN REPLACE MASTER CYLINDER AND BLEED ENTIRE SYSTEM. RESERVOIR NEEDS TO BE REPLACED. CUSTOMER NEEDS TO BRING CAR BACK FOR REPLACEMENT. PRESSURE SWITCH CONNECTOR IS FRIED AND NEEDS TO BE REPLACED. REPLACED RESERVOIR HOSES.

ESTIMATE OF REPAIRS: Includes all parts, labor, handling and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

ORIGINAL ESTIMATE
 RE 7/21/10 02:32PM WAR 562-6245
 HOSES \$18.92

REVISED ESTIMATE TOTAL \$595.62

X

CUSTOMER SIGNATURE

DATE

I acknowledge notice and oral approval of an increase in the original estimated price.

1 YEAR 12-K MILE WARRANTY WHICHEVER COMES FIRST. GOOD ONLY AT THIS FACILITY. UNLESS OTHERWISE NOTED UNDER LABOR.

METHOD OF PAYMENT
 PAYMENT DATE / /
 PARTS 316.45
 LABOR 249.90
 SUB TOT 566.35
 TAX-DEF 29.27

TOTAL \$595.62

RECOMMENDED SERVICES / FUTURE NEEDS

LEANS: VALVE COVERS, TIMING COVERS, RT INNER CV BOOT
 NEEDS: HYDRAULIC CHAIN TENSIONERS.

CUSTOMER COPY

CALLER ☐ DONE ☐ IN WORK ☐ C = CORE U = USED R = REBUILT N = NEW CODE ☐ DISCARD PARTS ☐ SAVE PARTS ☐

I hereby authorize the repair work listed hereon, including necessary materials. You and your employees may operate of the vehicle, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorney's fees in the event default is made in any payment due. If automobile is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembling) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

sublet work, to be done along with the described vehicle for purposes is acknowledged on said vehicle to

CUSTOMER SIGNATURE

X

DATE

8/16/10

TERMS CASH: Unless arrangements made prior to authorization. Cars left after work is completed may be subject to a storage fee.

CUSTOMER SIGNATURE

X

DATE

Buyer hereby acknowledges receipt of merchandise and services set forth herein and a copy of this sales invoice.

EUROPEAN AUTOTECH

31-J BETA COURT
SAN RAMON CA 945830000
(925) 820-6460

BAR # RC 116666 EPA# CAL000021453
FAMILY OWNED AND OPERATED SINCE 84

1977 PORSCHE 911S TARGA
LICENSE : 2VDF154 MILEAGE: 219960
VIN : 9117210691 BODY:
COLOR CD: WHITE PRO: 10/76
ENGINE N: 3.2

INVOICE #: 28736
DATE/TIME : 7/21/10 2:50PM
PROMISED BY: 8/16/10 5:00PM
WRITTEN BY : 9

QTY	CORE	PART NUMBER	DESCRIPTION	PRICE	TOTAL
1.00	N	911-355-013-13	BRAKE MASTER RESERVOIR	38.50	38.50
2.00	N	113-945-5156	BRAKE PRESSURE SWITCH	39.50	79.00
1.00	N	DC	BRAKE CLEAN	5.00	5.00
1.00	N	RH194101	USED CONNECTOR WITH HARNESS, MASTER CYL. SWIT CH	46.88	46.88
1.00	N	923-332-037-01	CV BOOT KIT W METAL FLANGE	68.31	68.31
1.00	N	DC	PARTS CLEANER	5.60	5.60
6.00	N	985-332-190-00	AXLE BOLT, 45MM LONG, 8 X 1.25 BLACK	3.46	20.76
1.00	N	911-352-950-04	BRAKE PAD SET, 911 PORSCHE OR CARRERA	82.20	82.20
1.00	N	DOT-4	BRAKE FLUID	10.00	10.00

ESTIMATE OF REPAIRS: Includes all parts, labor, handling and diagnosis. If on closer analysis it is found that additional repairs are necessary, you will be contacted for authorization.

ORIGINAL ESTIMATE \$707.22
R# 8/16/10 12:50PM MAR 562-6245 \$254.13
REAR BRAKES

REVISED ESTIMATE TOTAL \$961.35

CUSTOMER SIGNATURE

DATE

I acknowledge notice and oral approval of an increase in the original estimated price.

HRS	EMP	LABOR DESCRIPTION	TOTAL
3		REPLACE BRAKE MASTER CYLINDER RESERVOIR & BOTH SWITCHES ON RESV. FLUSH BRAKE FLUID, REPLACE REAR ELECTRICAL CONNECTOR & REPAIR WIRES ON BRAKE MASTER CYLINDER REAR SWITCH.	249.90
3		RIGHT (PASSANGER) SIDE INNER CV BOOT IS BROKEN IN HALF & SLINGING GREASE. SEVERAL BOLTS ARE ROUNDED OFF. REPLACE BOOT & BOLTS, CLEAN JOINT & REPACK WITH FRESH GREASE.	187.43
3		REAR BRAKE PADS ARE NEARLY METAL TO METAL. REPLACE REAR BRAKE PADS ONLY.	125.95

1 YEAR 12-K MILE WARRANTY WHICHEVER COMES FIRST. GOOD ONLY AT THIS FACILITY. UNLESS OTHERWISE NOTED UNDER LABOR.

METHOD OF PAYMENT
PAYMENT DATE / /

PARTS 356.25
LABOR 563.20
SUB TOT 919.45
TAX-DEF 32.95

TOTAL \$952.40

RECOMMENDED SERVICES / FUTURE NEEDS

FRONT BRAKE LININGS APPROX 50% REMAIN, REAR BRAKE LININGS APPROX 100% REMAIN
CAR LEAKS, ENGINE OIL MAJOR, TIMING CHAIN HOUSING & REAR OF MOTOR

sublet work, to be done along with
purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said
vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or
damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause
beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the
event that default is made in any payment due. If vehicle is returned to customer without repair
service being performed, a diagnostic and handling fee (including reassembly) may be charged.
I have read and understand the above and acknowledge receipt of an estimate.

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is
completed may be subject to a storage fee.

European Autotech

31-J Beta Court

San Ramon, CA 94583

(925) 820-6460

BAR # AC116666, EPA # CAL000021453

EUROPEANAUTOTECH.BIZ

Invoice # 30857

1977 PORSCHE 911S TARGA

VIN: 9117210691

Engine: 3.2

Transmission: MT

License # 2VDF154

ODO In: 220757 Out: 220759

Color: WHITE

Mfg. Date:

Unit # 10/76

Inv Date: 9/13/2011

Service Writer:

Status: Complete

Driver:

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
------------------	----------------------	--------------------	-----	-----	-------	-----

Requests for Service & Vehicle Problems -

Labor Service - Customer says brakes feel spongy, inspect and report, replace rubber
grommet in brake master cylinder and both plastic connectors, bleed brakes front and
rear. No warranty on master cylinder, pedal is firm at this time. Front brake calipers are
sticking. 3

2.00 124.95 249.90

New	DOT-4	Brake fluid	1.00	10.00	10.00
New	000-431-09-50	Brake Reservoir Grommet	2.00	4.20	8.40
New	911-355-323-00	Brake fitting, angled from resv hose to rear master cylinder port	1.00	3.76	3.76
New	911-355-322-00	Brake fitting from resv line to front master cylinder port	1.00	4.30	4.30

Revisions of Original Estimate - Original Estimate of Services and Parts \$124.95

Rev#	Date and Time	Who Contacted	Method	Contact #	Cont. By	Revise By	Total
1	10/03/2011 11:24AM		By Phone		ADMIN	153.01	277.96
2	10/05/2011 10:55AM		In Person		ADMIN	0.58	278.54

X

Customer accepts revision to the invoice and agrees to pay revised amount

Recommended Repairs and Services:

- Recommended Service: Front brake linings aprox 50% remain, rear brake linings aprox 100% remain
- Recommended Service: Car leaks, engine oil major, timing chain housing & rear of motor, front brake calipers sticking

Warranty

1 YEAR OR 12 -K MILE WARRANTY WHICHEVER COMES FIRST. PARTS
AND LABOR GOOD AT THIS REPAIR FACILITY ONLY.

Invoice Summary

Parts 26.46
Labor 249.90

X

Customer acknowledges receipt of merchandise and services.

Sub Total 276.36
Sales Tax (CA) 2.18

PARTSHEAVEN23694 BERNHARDT STREET
HAYWARD, CA 94545(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250
www.partsheaven.com**PARTSHEAVEN**

Invoice No. 210002

DATE ORDERED

11/11/13

WORK ORDER NO.	MAIL COPY	DISMANTLER	READY	CORE EXCHANGE	R/O NUMBER	TRUCK LINE	SALES PERSON	SHIPPING DATE
241294							SN	11/11/13

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

HUB CAPS

2 @ \$47.00 each PORSCHE 911 77

#0002

94.00

Doc # :28279

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:
NO CASH REFUNDS
NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED, ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL

94.00

SALES TAX

8.46

SHIPPING CHARGES

0.00

TOTAL

102.46

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.Amount paid: 102.46
Amount due: 0.00

BOSCH
Service

CAR SERVICE, INC.

BAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389

Invoice No.

000053090

Page 1

Order Date 01/09/14 08:39 am

Completed: 01/09/14 11:28 am

Serving San Leandro Since 1968

77 PORSCHE 911 WHITE

221819 Mi.

Lic: 2VDF154/CA H6Cyl 3.0

Vin: 9117210691 10/76

Eq:

Profile:

Quotes

1 01/09/14 08:45am 62.50

CUSTOMER BROUGHT OIL AND FILTER

911SC OIL SERVICE

Labor: \$62.50

CUSTOMER DECLINED MINOR SERVICE BROUGHT OWN OIL FILTER AND OIL

RECOMMEND REPLACING OIL S HOSE AT NEXT OIL SERVICE (CURRENT HOSE HAS HARDENED SUSCEPTIBLE TO CRACKS/BREAKS)

OIL SEEPAGE NOTICED FROM VALVE COVER GASKETS

RECOMMEND CARRERA CHAIN TENSIONER UPDATE

463 22 27 ALUMINUM WASHER M22X27-N 2.0 @ 1.50 =\$ 3.00 3.00

Tire Pressure: LF[30] RF[30] LR [34] RR [34]

PLEASE CHECK HERE [] FOR OLD/REMOVED PARTS TO BE KEPT FOR INSPECTION OR SELF DISPOSAL

Payments to World Imported Car Service Inc. Cost Summary

Status: Completed Work Order

Payments:

Labor	62.50
Parts	3.00
Subtotal	65.50
Tax	0.28
Total	\$65.78
Payments	0.00
Bal Due	65.78

Thank you for choosing World Imported Car Service Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature)

BOSCH
ServiceBAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389

Invoice No.

000053818

Page 1

Order Date 11/11/14 09:45 am

Completed: 11/13/14 09:09 am

Serving San Leandro Since 1968

77 PORSCHE 911 WHITE

226393 Mi. Last in 1/9/2014

Lic: 2VDF154/CA H6Cyl 3.0

Vin: 9117210691 10/76

Eq:

Profile:

Quotes

1 11/11/14 09:47am 298.33

2 11/11/14 01:17pm 1144.97

MINOR PORSCHE 911

Labor: \$159.60

MINOR TUNE AND SERVICE, SEE SERVICE LITERATURE FOR OPERATIONS PERFORMED. - INCLUDES
REPLACE OIL TANK "S" HOSE - ALSO CHANGE GEAR LUBE (SWEPCO)

20-50	TOTAL 20-50 NON SYN-N	11.5 @	5.20 =\$	59.80	
WWF	WW SOLVENT-N	1.0 @	5.50 =\$	5.50	
CLEANER	SPRAY CLEANER-N	1.0 @	7.00 =\$	7.00	
930 107 764 01	OIL FILTER-N	1.0 @	17.50 =\$	17.50	
911 107 233 00	OIL TANK HOSE-N	1.0 @	39.06 =\$	39.06	
40 713	WIPER BLADE-N	2.0 @	13.30 =\$	26.60	
SWEPCO201	GEAR LUBRICANT(PINT)-N	4.5 @	14.30 =\$	64.35	219.81

FRONT T STAT HOSES

Labor: \$250.00

REPLACE HOSES TO AND FROM FRONT THERMOSTAT -

911 107 730 11	THERMOSTAT HOSE-S	1.0 @	200.81 =\$	200.81	
911 107 743 12	THERMOSTAT HOSE-S	1.0 @	202.00 =\$	202.00	402.81

BRAKE FLUSH

Labor: \$106.40

FLUSH AND BLEED BRAKE HYDRAULICS, INSPECT FOR
FLUID LEAKS AND PERFORMANCE TEST BRAKE SYSTEM

DOT4 PENT 1L	BRAKE FLUID DOT4-N	2.0 @	22.96 =\$	45.92	
901 351 927 10	CAP, BLEEDER-N	1.0 @	3.74 =\$	3.74	49.66

Recommendations: POSSIBLE OIL COOLER OR TOP OF ENGINE RESEAL - VALVE COVERS MAY BE
LEAKING - NEEDS ENGINE CLEAN AND RECHECK FOR LEAKS - OIL PIPE ENGINE MTS AND TRANS MTS
BATTERY GROUP 49
OIL SEEPAGE FROM CYLINDER 1-3 CAM OIL LINE RECHECK NEXT SERVICE

Tire Pressure: 28F 36R

PLEASE CHECK HERE [] FOR OLD/REMOVED PARTS TO BE KEPT FOR INSPECTION OR
SELF DISPOSAL

----->----->----->-----Continued on the next page----->----->----->-----

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your
employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for
the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck
or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to
vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature)

BOSCH
ServiceBAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389

000053818

Order Date 11/11/14 09:45 am

Completed: 11/13/14 09:09 am

*Serving San Leandro Since 1968***Payments to World Imported Car Service Inc. Cost Summary**

Status: Completed Work Order

Payments:

Labor	516.00
Parts	672.28
Haz Waste	4.56
Subtotal	1,192.84
Tax	62.19
Total	\$1,255.03
Payments	0.00
Bal Due	1,255.03

Thank you for choosing World Imported Car Service Inc.



BOSCH
Service

BAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389



000053959

Order Date 01/12/15 09:57 am

Completed: 01/12/15 04:28 pm

Serving San Leandro Since 1968

77 PORSCHE 911 WHITE
227223 Mi. Last in 12/17/2014
Lic: 2VDF154/CA H6Cyl 3.0
Vin: 9117210691 10/76
Eq:
Profile:

Quotes

1 01/12/15 10:00am 911.74

BLOWER FAN FRONT

Labor: \$266.00

REPLACE BLOWER FAN - FAN WAS ORIGINAL (1976) AFTER FAN WAS REPLACED WE FOUND SWITCH ON SLIDE CONTROL NOT SENDING GROUND TO FAN (VARIABLE SPEED CONTROL) NEEDS FURTHER DIAGNOSIS - INSTALL JUMPER WIRE FOR FRONT FAN TO FUNCTION AT 1 SPEED TEMPORARILY UNTIL FURTHER DIAGNOSIS AND REPAIR IN DASH CAN BE DONE.

911 571 320 32 BLOWER MOTOR-N

1.0 @ 243.46 =\$ 243.46 243.46

RECHECK

Labor: N/C

DIAGNOSE AND ADVISE ON CUSTOMER COMPLAINT: - OIL LEAKS - RIGHT VALVE COVER IS LEAKING ONTO OIL COOLER HOSES - SEE PREVIOUS NOTES -

Recommendations: *ENGINE MECHANICAL* POSSIBLE OIL COOLER OR TOP OF ENGINE RESEAL - VALVE COVERS MAY BE LEAKING - NEEDS ENGINE CLEAN AND RECHECK FOR LEAKS - OIL PIPE ENGINE MTS AND TRANS MTS BATTERY GROUP 49
OIL SEEPAGE FROM CYLINDER 1-3 CAM OIL LINE RECHECK NEXT SERVICE

Payments to World Imported Car Service Inc. Cost Summary

Status: Completed Work Order

Payments:

Labor	266.00
Parts	243.46
Subtotal	509.46
Tax	22.52
Total	\$531.98
Payments	0.00
Bal Due	531.98

Thank you for choosing World Imported Car Service Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature)

INVOICE

Print Date : 02/20/2015

1977 Porsche - 911 S

Lic # : 2VDF154


Odometer In : 227518

Unit # :

Vin # :

Hat # :

Ref # :



Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
BUSHING				LAST MAJOR SERVICE WAS DONE AT	
911 424 139 00	1.00	14.04	14.04	219270-NEXT MAJOR AT 234270	
SHIFTER BUSHING				MILES.ELECTRICAL SYSTEM HAS HAD	
914 424 224 00	1.00	16.09	16.09	MANY MODIFICATIONS-ADD ONS.UNDER	
BALL JOINT				DASH WIRING IS A MESS.NOT	
911 341 049 01	2.00	126.60	253.20	RECOMENED.NO BRAKE WARNING	
SHIFT COUPLER BUSHING				SYSTEM-LOW PRESURE OR PARK	
911 424 223 03	2.00	6.06	12.12	BRAKE.LEFT REAR SWAY BAR BRAKET IS	
SWAY BAR BUSHING				WRONG.STEERING RACK HAS BEEN NOISY	
911 343 792 03	4.00	14.86	59.44	FOR 20 YEARS AND HAS TO BE	
BRAKE PAD SET				REPAIRED.BRAKES-HAD NOT BEEN	
911 352 950 04	1.00	56.22	56.22	SERVICED PROPERLY.FRONT BRAKE DISC	
BRAKE FLUID				WORN.ENGINE HAS MANY OIL LEAKS	
BKF	1.00	15.00	15.00	CHECK SHIFTING	287.50
BRAKE CALIPER REPAIR KIT				CHECK TRANS FLUID AND CLUTCH	
911 351 946 00	2.00	21.62	43.24	ADJUSTMENT.RENEW SHIFT	
CALIPER REPAIR KIT				BUSHINGS-CUP,ROD,AND	
911 352 998 00	2.00	24.54	49.08	COUPLER,ADJUST.TRANS IS WORN	
WIPER SWITCH				SHIFTING IS NOTCH, MORE PLAT IN	
911 613 306 02	1.00	164.98	164.98	LINKAGES THAN NORMAL	
BUSHING				FRONT SUSPENSION	460.00
901 423 253 00	2.00	4.10	8.20	INSPECT.RENEW BALL JOINTS,AND SWAY	
MOUNT				BAR BUSHINGS.REMOVE TORSION	
911 110 154 00	1.00	23.48	23.48	BAR-CLEAN AND GREASE. RESET RIDE	
BRAKE PAD SET				HEIGHT.LEFT TORSION BAR SEIZED IN.	
911 351 950 01	1.00	58.60	58.60	REAR SUSPENSION	287.50
OIL LINE				INSTALL LEFT SWAY BAR BUSHING TO FIT	
901 107 347 02	1.00	57.96	57.96	WITH WRONG BRACKET.RESET RIDE	
				HEIGHTS.SET CHASSIS HEIGHTS AND	
				WEIGHTS.SEND OUT FOR 4 WHEEL	
				ALIGNMENT	
				REAR BRAKES	460.00
				REMOVE CALIPERS AND REPAIR,RENEW	
				PADS AND BLEED.REPAIR PARK BRAKE	
				LINKAGES AND ADJUST	
				FRONT BRAKES	402.50
				REMOVE CALIPERS-CLEAN AND INSTALL	
				REPAIR KITS. INSTALL AND BLEED	

European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1305

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 02/20/2015

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 227518

Unit # :

Vin # :

Hat # :

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
				WIPERS	172.50
				HAD JUST HAD REPAIRS.WIRING AT MOTOR ALTERED. SYSTEM DOES NOT GO TO PARK-INTERMITTENT WIPER FUNCTION NOT WORKING.DIAGNOSE AND REPAIR.RENEW SWITCH.CLEAN UP SOME WIRING UNDER DASH.	
				BRAKES	N/C
				BRAKE WARNING SYSTEM NOT WORKING-PRESURE OR PARK BRAKE.HAD BRAKE PADS CHANGED-CALIPERS BAD,PADS HAD BEEN GROUND,DUST SEALS BETWEEN PADS AND SOME MISSING.,PISTONS ROTATED,DISC WORN.	
				CHECK PERFORMANCE	N/C
				THROTTLE LINKAGES BAD- BELL CRANK BUSHINGS-TOP OF ENGINE.BROKEN AIR BOX MOUNT,IGNITION DISTRIBUTOR SEIZED VACUM ADVANCE,CO TO LEAN. REPAIR LIST-ENGINE OIL LEAKS-ENGINE NEEDS RESEAL,LEAKS AT FRONT AND BACK OF ENGINE,CAM SEALS AND HOSES.,OIL RETURN TUBES ETC. CAR HOT START IS POOR,RUNS POORLY AND DIES.AIR FILTER STRAPS.STEERING RACK OR SHAFT. FRONT WHEEL BEARINGS-SERVICE.REAR SWAY BAR-BRACKET AND ALL BUSHINGS. HORN RING-POP FROM STEERING COLUM.ENGINE AND TRANS MOUNTS-ARE ORIGINAL.MAJOR SERVICE,CAP,ROTOR,PLUGS, FILTERS AND FLUIDS.VALVE ADJUST.FUEL INJECTION TESTING.	
				THROTTLE	287.50
				RENEW BELL CRANK BUSHINGS,AND ADJUST.RENEW BROKEN AIR BOX MOUNT-CENTER BACK.	

European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1305

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 02/20/2015

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 227518

Unit # :

Vin # :

Ref # :

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
				CHECK TUNE.	287.50
				REMOVE IGNITION DISTRIBUTOR,CLEAN AND LUBE-FREE UP SIEZED VACUM PLATE.SET TIMING AND MIXTURE.RENEW CAM HOSE WIRH DISTRIBUTOR REMOVED SOME OIL IN AIR BOX-MAY HAVE BEEN OVERFILLED.ENGINE OIL LEAKS-REAR OF ENGINE AND INTER SHAFT COVER IS THE LEAKING DRIVERS DOOR STARP BROKEN IN DOOR.AIR FILTER STRAPS BAD.ELECTRICAL SYSTEM HAS HAD ADD ONS AND REPAIRS,NOT ORIGINAL.AIR CONDIONING SYSTEM HAS BEEN REMOVED.CRUISE CONTROL SYSTEM DISCONNECTED.MAY NEED STEERING SHAFT OR STEERING RACK.FUEL INJECTION-WHEN STARTED HOT RUNS POORLY-POSIBLE FUEL ACCUMULATOR OR IGINITION.POWER MIRRORS NOT WORKING.FRESH AIR FAN HAS WIRING MODIFICATIONS.DASH LIGHTS-SOCKETS	
[Technicians : Please Select, Technician]					

Org. Estimate \$1,605.30 Revisions \$0.00 Current Estimate \$ 1,605.30 Additional Cost Revised Estimate

Labor:	2,645.00
Parts:	831.65
Sublet:	0.00

Sub:	3,476.65
Tax:	74.85
Total:	3,551.50
Bal Due:	\$3,551.50

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

PARTSHEAVEN

PARTSHEAVEN

23694 BERNHARDT STREET

HAYWARD, CA 94545

(510) 782-0354 • (FAX) (510) 782-0358 • (800) 767-7250

www.partsheaven.com

Invoice No. 229088

MEMBER DATE ORDERED

06/22/15

PERSON SHIPPING DATE

06/22/15

252742

JW

ITEM / DESCRIPTION

STOCK NO.

LOC.

AMOUNT

FOG LIGHT

1 PORSCHE 911 (Extra Sale) 80

#0001

150.00 T

Doc # 149856

DISCLAIMER

ALL SALES SUBJECT TO FOLLOWING TERMS:

NO CASH REFUNDS

NO GUARANTEE ON LABOR

NO PARTS EXCHANGED OR RETURNED WITHOUT THIS INVOICE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL NEW PARTS. NO RETURNS ON SPECIAL ORDERS. ALL PARTS COME WITH A 90 DAY, REPLACEMENT ONLY GUARANTEE. IF PROPERLY INSTALLED. ALL EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OF FITNESS FOR USE ARE DISCLAIMED. PARTS HEAVEN INC. WILL NOT BE LIABLE FOR DAMAGES OF ANY LOSS CAUSED BY LABOR, REMOVAL, INSTALLATION, OR ANY CONSEQUENTIAL DAMAGES OR USE OF THIS MERCHANDISE. A \$15.00 SERVICE CHARGE WILL BE ASSESSED ON ALL RETURNED CHECKS.

SUB TOTAL

150.00

SALES TAX

15.00

SHIPPING CHARGES

0.00

TOTAL

165.00

ALL CLAIMS & RETURNED GOODS
MUST BE ACCOMPANIED BY THIS BILL.

Amount paid: 165.00

Amount due: 0.00



WORLD IMPORTED CAR SERVICE, INC.
BAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389



Invoice No.

000054515

Page 1

Order Date 08/11/15 04:09 pm
Completed: 08/12/15 11:53 am

Bill & Bills 568-3782

Serving San Leandro Since 1968

77 PORSCHE 911 WHITE
228839 Mi. Last in 1/12/2015
Lic: 2VDF154/CA H6Cyl 3.0
Vin: 9117210691 10/76
Eq:

BY 1

OIL & FILTER 911 SC

Labor: \$79.80

CHANGE OIL AND FILTER

20-50	TOTAL 20-50 NON SYN-N	10.5 @	5.20 =\$	54.60	
930 107 764 01	OIL FILTER-N	1.0 @	17.50 =\$	17.50	
900 123 011 30	OIL DRAIN PLUG GASKET-N	2.0 @	0.82 =\$	1.64	73.74

INSTALL FOG LIGHT

Labor: \$66.50

INSTALL CUSTOMER SUPPLIED FOG LIGHT (COMPLETE ASSEMBLY) - MAKE WIRING SPLICES AS NEEDED - BODY IS DAMAGED AT FOG LIGHT (BRACKET IS BENT) MOVED STRAIGHT BRACKET ONTO OLD LIGHT SO THAT WHEN BODY WORK IS DONE THIS CAN BE SWITCHED TO MOUNT FLUSH TO STRAIGHT SPOILER -

Recommendations: *ENGINE MECHANICAL* POSSIBLE OIL COOLER OR TOP OF ENGINE RESEAL - VALVE COVERS MAY BE LEAKING - NEEDS ENGINE CLEAN AND RECHECK FOR LEAKS - OIL PIPE ENGINE MTS AND TRANS MTS BATTERY GROUP 49 OIL SEEPAGE FROM CYLINDER 1-3 CAM OIL LINE RECHECK NEXT SERVICE

Tire Pressure: 29F 36R

PLEASE CHECK HERE [] FOR OLD/REMOVED PARTS TO BE KEPT FOR INSPECTION OR SELF DISPOSAL

Payments to World Imported Car Service Inc. Cost Summary

Status: Completed Work Order	Labor	146.30
	Parts	73.74
	Haz Waste	3.63
	Subtotal	223.67
	Tax	7.37
	Total	\$231.04
Payments:	Payments	0.00
	Bal Due	231.04

Thank you for choosing World Imported Car Service Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1602

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 02/10/2016

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 229725

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
PEDAL PAD				CHECK CAR OVER	115.00
914 423 210 00	2.00	8.94	17.88	FRONT END NOISE-LUBE FRONT TORSION BARS.RIGHT REAR TIRE LOW ON AIR-CHECK TIRE PRESURES.RE- NEW PEDAL PADS.ADJUST CLUTCH	

[Technicians : Please Select, Technician]

Org. Estimate	\$134.49	Revisions	\$0.00	Current Estimate	\$ 134.49	Additional Cost	Revised Estimate	Labor:	115.00
								Parts:	17.88
								Sublet:	0.00

								Sub:	132.88
								Tax:	1.61
								Total:	134.49
								Bal Due:	\$134.49

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Written By: <none>

Mels Tires
2154 Washington Ave
San Leandro, CA. 94577
Phone: 510-351-8855

INVOICE

2210

Org. Est. # 002197

INVOICE

Print Date: 02/11/2016

1977 Porsche - 911 S -

Lic #: 2VDF154 - CA

Odometer In : 229772

VIN #: 9117210691

Cust ID : 1572

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Michelin PREMIER A/S Size: 205/60R15 91H M29199	2.00	146.50	293.00	Mount and Balance Tire	30.00
Tire Fee 1	2.00	1.75	3.50	Desposal Fee	5.00

Org. Estimate 360.80 Revisions 0.00 Current Estimate 360.80

Labor:	30.00
Parts:	293.00
Sublet:	5.00
Tire Fees:	3.50
Sub:	331.50
Tax:	29.30
Total:	360.80
Bal Due:	\$0.00

[Payments - MasterCard - \$360.80]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Time _____

Written By: Rodriguez, Ulises - Technicians : Ulises, Ulises UL

INVOICE

Print Date : 03/18/2016

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 230084

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
WIPER CONTACT-HORN 911 613 521 00	1.00	20.42	20.42	FRONT END DAMAGE-HAS BEEN BOTTOMED OUT-DAMAGED FRONT SUPPORT AND FUEL TANK	
CLUTCH CABLE 930 423 401 05	1.00	134.24	134.24	DENT.SUSPENSION HAS BEEN REPAIRED.FUEL INJECTION SYSTEM-COLD	
FUEL ACCUMULATOR 911 110 197 01	1.00	147.42	147.42	START NOT PERFECT- HAS WRONG STARTER MOTOR-NO CONNECTION FOR	
FUEL FILTER 930 110 076 00	1.00	32.20	32.20	COLD START INJECTOR-THERMAL TIME SWITCH AND WARM UP REGULATOR HAS	
S/WHEEL CONTACT 911 347 099 05	1.00	99.01	99.01	BEED ADJUSTED TOO RICH.REAR SUSPENSION WILL NEED SPRING PLATE	
TIE ROD END 000 338 52 10	2.00	33.18	66.36	BUSHINGS.ENGINE OIL LEAKS-REAR PULLEY AREA AND OIL LINE.POWER	
CLUTCH CABLE BUSHING 901 423 343 00	1.00	4.84	4.84	MIRROS NOT WORKING.DRIVERS DOOR STAY BROKEN MOUNT IN DOOR.	
PREMIUN FUEL PF	1.00	20.00	20.00	FRONT END NOISES	747.50
STEERING RACK-USED USR	1.00	600.00	600.00	STEERING AND SUSPENSION.REMOVE RUSTED TORSION BAR RIGHT.REPLACE	
A ARMS-USED ARM911	2.00	170.00	340.00	STEERING RACK ASSEMBLY,A ARMS,STEERING UNIVERSAL,SUBFRAME. SWAP PARTS AS NEEDED.FRONT END WAS BENTS-SEE NOTES	
				HORN	69.00
				RENEW RING AND CONTACT.RENEW DASH LIGHT BULBS IN TACK.	
				CLUTCH	172.50
				RENEW CABLE AND BUSHING AT PEDAL.ADJUST	
				FUEL-HOT START	172.50
				CHECK POOR START HOT-POOR RUNNING.DIAGNOSE AND REPAIR SYSTEM LEAK DOWN.RENEW FUEL FILTER AND FUEL ACCUMULATOR.REPAIR SENSOR PLATE WIRING-FUEL PUMP WAS RUNNING WHEN KEY TURNED ON.COLD START-SEE NOTES	
				ALLIGNMENT	N/C
				4 WHEEL ALLIGNMENT	

European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1623

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 03/18/2016

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 230084

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
---------------------------	-----	------	----------	-------------------	----------

[Technicians : Please Select, Technician]

Org. Estimate	\$2,757.79	Revisions	\$0.00	Current Estimate	\$ 2,757.79	Additional Cost	Revised Estimate
---------------	------------	-----------	--------	------------------	-------------	-----------------	------------------

Labor:	1,161.50
Parts:	1,464.49
Sublet:	0.00

Sub:	2,625.99
Tax:	131.80
Total:	2,757.79
Bal Due:	\$2,757.79

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

INVOICE

Print Date : 11/21/2016

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 231781

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
V BELT				REAR SUSPENSION-SPRING PLATE	
10X950	1.00	10.73	10.73	BUSHING AND SWAY BAR BUSHINGS	
VALVE ADJUST KIT				WORN.IGNITION SYSTEM-OLD STYLE	
PK03	1.00	64.72	64.72	PERMATUNE. DISTRIBUTOR CAP AND	
SPARK PLUG				ROTOR-CHANGE NEXT SERVICE.HAS	
999 170 170 90	6.00	3.40	20.40	WRONG BATTERY-NO HOLD DOWN.HAD	
AIR FILTER				BATTERY SHUT OFF SWITCH-NOT	
911 110 185 02	1.00	32.05	32.05	RECOMENNED-REMOVED RETURN TO	
Oil Filter				ORIGINAL	
930 107 764 01	1.00	15.43	15.43	AFTER SERVICE AND REPAIRS-CHAINS AND	
FUEL FILTER				TENSIONERS WORN- HAD CHAIN	
930 110 076 00	1.00	32.78	32.78	GUARDS-NOT INSTALLED PROPERLY.LEFT	
CHAIN COVER GASKET KIT-CAM				TENSIONER WAS SEIZED.SLIGHT OIL LEAK	
SEAKS,GASKET,PULLEY, INTER				AT SUMP,CASE SEAM.BACK OF ENGINE	
SHAFT				NEEDS OE CRANK PULLEY,COMPLETE	
10 0912 181	1.00	55.00	55.00	REAR ENGINE SUPPORT AND	
TENSIONER REBUILD KIT OE				MOUNTS.COOL- ING FAN AND	
911 105 901 01	2.00	45.89	91.78	PULLEY.POSSIBLE BRAKE MASTER	
MUFFLET GASKET				CYLINDER.HEATER VENT SYSTEM-WAS	
911 111 191 02	1.00	8.10	8.10	MODIFIED FOR AFTERMARKET AIR	
STARTER MOTOR-REMAN				CONDITIONING.ENGINE WAS VERY	
911 604 101 BX	1.00	287.98	287.98	DIRTY-WE CLEANED-BUT CYLINDERS AND	
ENGINE OIL				HEADS ARE DIRTY.SLIGHT OIL LEAK FROM	
EO	12.00	8.95	107.40	BACK OF OIL TANK-NEVER SEE LEAKS IN	
SWEPCO GEAR OIL				THIS AREA.	
GOIL	7.00	12.00	84.00	CLUTCH WORN.ENGINE COOLING FAN	
HAZARDOUS WASTE				DAMAGED,FAN PULLEY DAMAGED-HAD	
HAZ	12.00	0.50	6.00	BEEN LEFT LOSE AT ONE TIME.CRANK	
FAN BELT				PULLEY WAS BENT.LOWER VALVE	
10X710		8.86		COVERS-SOMEONE MACHINED.DRIVERS	
FUEL PUMP				DOOR DAMAGED FROM BAD DOOR STRAP.	
911 608 102 00	1.00	285.92	285.92	CONNECTORS ON HEATER BOX	
RELAY				DAMAGED-AFTERMARKET HEAER	
911 615 108 01	1.00	37.36	37.36	HOSE.OIL INE HAS BEEN BENT.CAR HAS	
NUTS-BOLTS-HARDWARE				HAD IMPACT IN REAR. BRAKE FLUID WAS	
MISCH	1.00	14.00	14.00	SLIGHTLY LOW-NO VISABLE LEAKS-MAY	
				NEED BRAKE MASTER	
				CYLINDER-CUSTOMER MUST CHECK.OIL	

European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1824

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 11/21/2016

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 231781

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
				CAP WAS NOT INSTALLED PROPERLY. 00000000	
				REPAIR TO RUN-TOWED IN	230.00
				DIAGNOSE AND REPAIR TO RUN.RENEW FUEL PUMP AND RELAY.REMOVE SPLICED WIRES AT FUEL PUMP- REPAIR AS NEEDED	
				SERVICE-MAJOR	690.00
				ADJUST VALVES,TUNE ENGINE AS NEEDED.RENEW SPARK PLUGS.RENEW FILTERS AND FLUIDS AS NEEDED.INSPECT AND REPORT.UNABLE TO CHANGE FAN BELT-PULLEY-FAN DAMAGE,NO CLEARANCE IN MOUNT TO PULLEY	
				STARTER	115.00
				WRONG STARTER MOTOR-NO TERMINAL15-STICKS COLD.RENEW STARTER MOTOR	
				HEATERS	11.50
				FANS AND VALVES OK-LOSS OF AIR FLOW IN FRONT OF CAR-SYSTEM STILL WORKS DEFROSTER AND HEATER	
				OIL LEAKS	920.00
				CAM SEALS CHAIN BOXES.RESEAL AS NEEDED.RENEW CRANK SEAL-MODIFY AFTERMARKET AC PULLEY-MAKE SO THAT BELT CAN BE REPLACED.RESEAL INTERMEDIATE SHAFT COVER.CLEAN AND REPORT.	
				CHAIN TENSIONERS	230.00
				ORIGINAL TENSIONERS-REBUILD WITH FACTORY REPAIR KITS.LEFT TENSIONER WAS SEIZED-CHAIN GUARDS NOT INSTALLED PROPERLY-NO CLEARANCE. CHAIN AND SPROKET DAMAGE.RECOMMEND UPDATED TENSIONER-OIL FEED STYLE.	

European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1824

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 11/21/2016

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 231781

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
[Technicians : Please Select, Technician]					

Org. Estimate \$3,453.44 Revisions \$0.00 Current Estimate \$ 3,453.44 Additional Cost Revised Estimate

Labor:	2,196.50
Parts:	1,153.65
Sublet:	0.00

Sub:	3,350.15
Tax:	103.29
Total:	3,453.44
Bal Due:	\$3,453.44

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

BOSCH
ServiceBAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389

55826

Order Date 01/11/17 03:00 pm
Completed: 01/13/17 02:46 pm

Serving San Leandro Since 1968

77 PORSCHE 911 WHITE

232104 Mi. Last in 8/11/2015

Lic: 2VDF154/CA H6Cyl 3.0

Vin: 9117210691 10/76

Eq:

Quotes

1 01/11/17 03:02pm 133.00

in person.

2 01/13/17 02:53pm 369.22

coil

DIAGNOSE AND ADVISE - no start

Labor: \$199.50

CUSTOMER REPORTS: CAR WILL NOT START - FUEL PUMP SEEMS TO BE WORKING - SPARK SEEMS WEAK -
REPLACE IGNITION COIL10 8536 105 COIL, PERMATUNE-N 1.0 @ 154.64 =\$ 154.64 154.64
Job Subtotal: \$354.14Recommendations: *Lube, Oil and Filter* *ENGINE MECHANICAL* POSSIBLE OIL COOLER OR TOP
OF ENGINE RESEAL - VALVE COVERS MAY BE LEAKING - NEEDS ENGINE CLEAN AND RECHECK FOR LEAKS
- OIL PIPE ENGINE MTS AND TRANS MTS BATTERY GROUP 49
OIL SEEPAGE FROM CYLINDER 1-3 CAM OIL LINE RECHECK NEXT SERVICE

Tire Pressure: 30F 36R

PLEASE CHECK HERE [] FOR OLD/REMOVED PARTS TO BE KEPT FOR INSPECTION OR
SELF DISPOSAL

Payments to World Imported Car Service Inc. Cost Summary

Status: Completed Work Order

Payments:

Labor	199.50
Parts	154.64
Subtotal	354.14
Tax	15.08
Total	\$369.22
Payments	0.00
Bal Due	369.22

Thank you for choosing World Imported Car Service Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____



BAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389



January 11, 2017 2:38 pm
Invoice: 55825

Serving San Leandro Since 1968

Sold to:



Part Number	Description	Quan	Unit	Ext Price
S5533B	49 BATTERY	1.0 @	219.00 =\$	219.00N

Payment: Cash

Taxable	219.00
Subtotal	219.00
Tax	21.35
Total	\$240.35
Payment	240.35
Bal Due	0.00



European Performance
32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1865

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 01/30/2017

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 232210

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
RELAY				ENGINE COOLING FAN AND PULLEY	
914 618 303 11	1.00	29.90	29.90	DAMAGED FROM PREVIOUS REPAIRS	
BATTERY CABLE				CHECK NO START	230.00
911 611 899 00	1.00	29.81	29.81	CAR HAS HAD DEAD BATTERY,DIED WHILE	
ALTERNATOR-NEW				DRIVING-TOWED.BATTERY AND COIL	
911 603 120 04	1.00	427.72	427.72	HAVE BEEN CHANGED. CHECK ALL	
				CONNECTIONS-NEG BATTERY CABLE BAD-	
				CONTACT AT BODY HAD BEEN	
				PAINTED.RENEW CABLE AND CLEAN	
				CONTACT.CLEAN AND REPAIR WIRING AT	
				REAR FUSE PANEL.CHECK BATTERY AND	
				CHARGING SYSTEM-OK.	
				DRIVE AND TEST	230.00
				HAS INTERNAL VOLTAGE	
				REGULATOR-ALTERNATOR. DRIVE WITH	
				VOLT METER-WITH HEADLIGHTS,FANS,ETC	
				ON VOLTAGE WOULD RANGE FROM	
				10VTO16V.RENEW ALTERNATOR.CLICKING	
				NOISE IN DASH-RELAY.RENEW RELAY	
				UNDER DASH WIRING IS IN NEED OF	
				WORK.UNKNOWN DAMAGE TO	
				ELECTRICAL COMPONENTS FROM OVER	
				VOLTAGE.HAS OLD STYLE PERMA TUNE.	
				NOTICED WITH FAN ASSEMBLY REMOVED	
				THAT #6 CYLINDER AND OIL COOLER HAVE	
				DEBRIS BUILT UP-NEEDS CLEANING.LEFT	
				REAR AXLE IS WORN-INNER CV PLAY.	

European Performance

32 Galli Dr Suite 4+5
Novato, California. 94949
Phone - 415-382-8394 Fax - 415-382-8395

INVOICE

1865

BAR AC 187779
CAL 0000996348

INVOICE

Print Date : 01/30/2017

1977 Porsche - 911 S

Lic # : 2VDF154

Odometer In : 232210

Unit # :

Vin # :

Hat # :

Cust ID : 291

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
[Technicians : Please Select, Technician]					

Org. Estimate \$991.30 Revisions \$0.00 Current Estimate \$ 991.30 Additional Cost Revised Estimate

Labor:	460.00
Parts:	487.43
Sublet:	0.00

Sub:	947.43
Tax:	43.87
Total:	991.30
Bal Due:	\$991.30

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

European Performance

32 Galli Dr Suite 4+5

Novato, California. 94949

Phone: 415-382-8394 Fax: 415-382-8395

INVOICE**1982**

Org. Est. # 003529

BAR AC 187779

CAL 0000996348

INVOICE

Date: 06/05/2017

1977 Porsche - 911 S -

Lic # :2VDF154 - CA

Odometer In : 233610

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Ex
ENGINE MOUNT 911 375 043 00	2.00	45.82	91.64	ENGINE	600.00
TENSIONER KIT 10 0445 105	1.00	880.00	880.00	RENEW CHAIN TENSIONERS AND UPDATE AS NEEDED.RENEW ENGINE MOUNTS.RENEW CHAIN RAILS-BROKEN,LOCATE BROKEN PARTS.	
TIMING COVER GASKET 930 105 191 03	1.00	7.40	7.40	ENGINE COOLING FAN-HUB DAMAGED .REAR ENGINE SUPPORT HAS BEEN DAMAGED FROM REAR	
TIMING COVER GASKET 930 105 192 04	1.00	7.50	7.50	ACCIDENT.CRANK PULLEY NEEDS REPLACING-SEE OTHER NOTES	
TIMING CHAIN RAIL 911 105 222 06	5.00	10.56	52.80		
TIMING CHAIN RAIL 911 105 222 05	1.00	10.14	10.14		

Org. Estimate 1,861.31 Revisions 0.00 Current Estimate 1,861.31

Labor: 600.00

Parts: 1,049.48

SubTotal: 1,649.48

Tax: 91.83

Total: 1,741.31

Bal Due: \$1,741.31

[Payments -]

Vehicle Received: 6/5/2017

Work Completed Date: 6/5/2017

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

**Bureau of Automotive Repair****State of California Smog Check Referee Center****1-800-622-7733****Invoice Number: 286738****Station: 799189 - COLLEGE OF ALAMEDA****June 08, 2017****Customer:****BAR Rep:****Address:****City:****Case No:****Vehicle Year/Make/Model: 1977 / PORS / 911****License or VIN: 7TVW652****Odometer Reading: 233,687****Service Description****Amount****Payment Type**

Referee Inspection

\$0.00

No Charge

Certificate

\$8.25

Credit Card

Total: \$8.25

Consumer has verified that engine hood was locked down properly on this vehicle.

X _____

I hereby authorize the above work to be done, which may include minor repairs and hereby grant you and / or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on the vehicle to secure the amount of the inspection and / or the smog certificate thereto. I will not hold FCCC or any of its employees or subcontractors responsible for loss or damage to the vehicle or articles left in the vehicle in case of fire, theft, accident or any other cause beyond our control. If action is brought to collect amounts due under this agreement, I agree to pay reasonable attorney's fees. Customer acknowledges receipt hereof.

Work Authorized by:**FINAL**

BOSCH
ServiceBAR # ARD00015082
EPA # CAL000121168
355 E. 14th Street
San Leandro, CA 94577-1845
Phone: 510-568-6800
Fax: 510-568-0389

Invoice No.

58481

Page 1

Order Date 06/25/20 09:53 am

Paid: 06/25/20 11:43 am

Serving San Leandro Since 1968

77 PORSCHE 911 WHITE
235000 Mi. Last in 1/11/2017
Lic: 2VDF154/CA H6Cyl 3.0
Vin: 9117210691 10/76
Eq:

Quotes

1 06/25/20 09:55am 220.76

in person.

O&F PORSCHE 911S/SC 77-83

Labor: \$102.00

CHANGE OIL AND FILTER, CHECK OIL LEVEL HOT AT IDLE - PERFORM STATUTORY TIRE PRESSURE INSPECTION -

930 107 764 01	OIL FILTER-N	1.0 @	17.50 =\$	17.50	
194706	20w50 motor oil-N	10.0 @	7.95 =\$	79.50	
900 123 118 30	DRAIN PLUG WASHER-N	2.0 @	0.82 =\$	1.64	98.64

Job Subtotal: \$200.64

Recommendations: *BRAKES HYDRAULIC* *ENGINE MECHANICAL* FRONT AND REAR PADS 12MM -
SLIGHT INACCURACY IN OIL LEVEL GAUGE - (READS SLIGHTLY HIGH) - VERIFIED FRONT OIL
THERMOSTAT OPENS (OIL CHECKED HOT)

Tire Pressure: 29F 36R

PLEASE CHECK HERE [] FOR OLD/REMOVED PARTS TO BE KEPT FOR INSPECTION OR SELF DISPOSAL

STORAGE WILL BE CHARGED ON CARS LEFT ON PREMISES BEGINNING 2 DAYS AFTER NOTIFICATION OF COMPLETED REPAIRS AT THE RATE OF \$125.00/DAY

Payments to World Imported Car Service Inc. Cost Summary

Status: Paid Work Order

Payments: \$216.26

1 06/25/20 216.26 Visa

Labor	102.00
Parts	98.64
Haz Waste	3.50
CLEANING KIT	2.50
Subtotal	206.64
Tax	9.62
Total	\$216.26
Payments	216.26
Bal Due	0.00

Thank you for choosing World Imported Car Service Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature)

ABP REPAIR INC

BAR #: AH 141375

EPA # CAL 000168351

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

Invoice No.

000022867

Page 1

Order Date 02/08/21 02:43 pm

Paid: 02/08/21 03:17 pm

77 PORSCHE 911 TARGA WHITE
235774 Mi.
Lic: 7TVW652/CA H6Cyl 3.0
Vin: 9117210691 10/76
Eq: FI

Quotes

1 02/08/21 03:17pm 1548.43

in person.

AXLES

Labor: \$338.00

REPLACED BOTH REAR AXLES, AND ONE C.V. JOINT GASKET.

92333203302	AXEL ASSY 911 SC-N	2.0 @	523.79 =\$	1047.58	
92333229700	Gskt. CV Joint 911 '75+-N	1.0 @	13.96 =\$	13.96	1061.54
				Job Subtotal:	\$1,399.54

CHECK CLUTCH ADJUSTMENT

Labor: \$50.70

CHECK CLUTCH ADJUSTMENT.
ADJUSTED CLUTCH.

Job Subtotal: \$50.70

CHECK PARKING BRAKE

Labor: \$0.00

CHECK PARKING BRAKE.
PARKING BRAKE IS ADJUSTED AND HOLDING CORRECTLY.

Job Subtotal: \$0.00

Payments to ABP REPAIR INC**Cost Summary**

Status: Paid Work Order

Payments: \$1,548.43

1 02/08/21 1548.43 MCard

Labor	388.70
Parts	1061.54
Tax	98.19
Total	\$1548.43
Payments	1548.43
Bal Due	0.00

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

MacArthur Smog Check

999 MacArthur Blvd., San Leandro, CA 94577

(510) 383-9999**Certified** BAR# ARD 256716

EPA# CAL 337955



NAME	DATE
[REDACTED]	05-22-71
ADDRESS	PHONE
[REDACTED]	[REDACTED]

YEAR	MAKE	MODEL	LICENSE NO	MILEAGE
77	Porsche	911	7TVW652	236084
VEHICLE I.D NO.				

Engine Size	Timing	Catalyst
CAL / Fed	Pulse Air	Trans R/M
GVLWR	Air Pump	No. of Cyl.

DESCRIPTION OF WORK

SMOG TEST	(Pass, Fail or Abort)	109.75
CERTIFICATE	(Goes to State of CA)	8.25
RETEST		
PRETEST	3L P CA	
EVAP TEST		
GAS CAP	BAR Refill Label	
OIL CHANGE & FILTER		
ENVIRONMENTAL WASTE FEE	N0194831	

REVISED ESTIMATE

DATE: TIME: PHONE:

REASON:

ADDITIONAL COST

I acknowledge notice and oral approval of an increase in the original estimated price

PASS FAIL Sign:

PASS FAIL

118.00

109.75

SUB TOTAL

SALES TAX

GRAND TOTAL

118.00

PLEASE READ AND SIGN FOR SMOG INSPECTION

I hereby authorize the smog inspection to be done and grant you and/or your employees to operate the vehicle herein described for the purpose of testing and/or inspection.

State of California requires your vehicle to be tested on the dynamometer which puts pressure on certain parts of your vehicle. There is a possibility certain problems may occur during the test especially if your vehicle has worn drive systems or parts. We will take all necessary precautions for your vehicle, however, we cannot be responsible for system or part failures during the test.

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

Test Date/Time: 05/22/2021 @ 11:44 AM

Model-Year:	1977	Make:	PORSCHE	Model:	911
License:	7TVW652	State:	California	VIN:	9117210691
Engine Size:	3.00 L	Type:	Passenger	Transmission:	Manual
GVWR:	0	Test Weight:	2063	Cylinders:	6
Odometer:	236084	Certification:	BAR Referee Label 0194831	VLT Record #:	00598
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile (HEP)
BAR Referee Label:	0194831	Engine Make:	PORSC	Engine Year:	1978

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Comprehensive Visual Inspection: PASS

Functional Check: PASS

Emissions Test: PASS

Smog Check Certificate Number: SA871012C

DMV ID Number: 9163A362S881

Your Smog Check certificate will be electronically transmitted to DMV
Please keep this copy for your records

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emission which are not measured during the ASM tests.)

RESULT	ECS	RESULT	ECS	RESULT	ECS
PASS-	PCV	PASS-	Thermostatic Air Cleaner	PASS-	Fuel Evaporative Controls
PASS-	Catalytic Converter	PASS-	Pump Air Injection	PASS-	Fuel Tank Cap Visual
PASS-	Visual EGR	PASS-	Ignition Spark Controls	N/A-	Carburetor
PASS-	Fuel Injection	PASS-	O2 Sensors and Connectors	PASS-	Wiring of Other
PASS-	Vacuum Line Connections	PASS-	Other Emission Related		Sensors or Switches
PASS-	Fuel Cap Functional	N/A-	Functional EGR	PASS-	Ignition Timing: 5 BTDC
N/A-	MIL	N/A-	Fill Pipe Restrictor	PASS-	Liquid Fuel Leaks
N/A-	Fuel Evap Test				

ASM Emission Test Results

Test	RPM	CO2 (%)	O2 (%)	HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	1547	12.65	2.77	255	40	39	1.57	0.17	0.42	1522	520	476	PASS
25 mph	2553	12.11	3.68	223	31	13	1.37	0.15	0.23	1382	452	529	PASS

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

MACARTHUR SMOG CHECK

999 MACARTHUR BLVD.

SAN LEANDRO 94577

510 383 9999

Station Number: TC256716

Technician Name/Number: GOKTURK, AHMET/EO151512

Repair Tech. Name/Number: N/A

Software Version/EIS Number: 1908/WP392368

I certify, under penalty of perjury under the laws of the State of California, that I inspected the vehicle described above, that I performed the inspection in accordance with all bureau requirements, and that the information listed on the vehicle inspection report is true and correct.

Date

Technician's Signature

Certificates are valid for 90 days from date of issuance

ABP REPAIR INC

BAR #: AH 141375

EPA # CAL 000168351

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

Invoice No.

000023760

Page 1

Order Date 11/02/22 01:59 pm

Paid: 11/02/22 02:04 pm

77 PORSCHE 911 TARGA WHITE

235774 Mi. Last in 2/8/2021

Lic: 7TVW652/CA H6Cyl 3.0

Vin: 9117210691 10/76

Eq: FI

Quotes

1 11/02/22 02:03pm 189.00

in person.

STIFF CLUTCH PEDAL

Labor: \$94.50

CLUTCH PEDAL IS STIFF, CHECK AND ADVISE.

INSPECTED CLUTCH PEDAL SPRING, SPRING IS OK. INSPECTED THE HORSE SHOE SPRING, IS GOOD.
INSPECTED CLUTCH CABLE, CLUTCH CABLE IS GOOD. FOUND THAT THE THROW OUT BEARING IS STARTING
TO BIND SOME ON THE GUIDE TUBE. RECOMMEND WAITING UNTIL THE CLUTCH IS WORN TO ADDRESS
PROBLEM.

Job Subtotal: \$94.50

GAS GAUGE

Labor: \$94.50

GAS GAUGE IS READING INACCURATELY, CHECK AND ADVISE.

REMOVED FUEL LEVEL SENDING UNIT, AND TESTED THROW OF GAUGE, GAUGE IS WORKING CORRECTLY.
RECOMMEND REPLACING THE FUEL LEVEL SENDING UNIT.

Job Subtotal: \$94.50

Payments to ABP REPAIR INC**Cost Summary**

Status: Paid Work Order

Labor 189.00

Parts 0.00

Total \$189.00

Payments 189.00

Bal Due 0.00

Payments: \$189.00

1 11/02/22 189.00 MCard

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

[illegible]

14105 Washington Ave., San Leandro, CA 94578

Fax: 510-614-8154



ARD# 270928

Cit

Year-Make-Model

Odometer

Estimate Amount

License No

VIN Number

Revised Estimate

Date _____

Time

Description	Frequency	Severity	Action
1. The patient is unable to walk without assistance.	3 times per week	4 (Severe)	Refer to physical therapist for gait training.
2. The patient experiences dizziness when standing up quickly.	2 times per week	3 (Moderate)	Monitor blood pressure and inform the patient of the risk of falls.
3. The patient has difficulty with balance when walking on uneven surfaces.	4 times per week	4 (Severe)	Refer to physical therapist for balance training.
4. The patient experiences fatigue when walking for more than 10 minutes.	3 times per week	3 (Moderate)	Encourage the patient to take short breaks during walks.
5. The patient has difficulty with stairs.	2 times per week	3 (Moderate)	Refer to physical therapist for stair training.

Authorized

INITIAL

Revised Estimate

Date _____

Time

Description

Authorized

INITIAL

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here, if I choose not to authorize the service recommended.

ORDER NO.

REPAIR ORDER — LABOR INSTRUCTION

LABOR CHG.

TIRE PRESSURE CHECK SERVICE COMPLETE ☐ DECLINED ☐ TIRE PRESSURE:

RECOMMENDED SERVICE:

- | |
|----|
| 1. |
| 2. |
| 3. |
| 4. |

I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By X

TOTAL
LABOR

PARTS

SUBLET
REPAIRS

GAS, OIL
GREASE

SMOG
CERTIFICATEELECTRONIC
TRANSMISSION
ECC

SALES TAX	
-----------	--

ENVIRONMENTAL
SURCHARGETOTAL
AMOUNT

We are not responsible for theft or damage to vehicles left on premises.

WHITE = ORIGINAL YELLOW = CUSTOMER COPY PINK = ESTIMATE COPY



www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 06/16/2023@15:26:32

Model Year:	1977	Make:	PORSCHE	Model:	911
License:	7TVW652	State:	CA	VIN:	9117210691
Engine Size:	3.00 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	3500	Cylinders:	6
Odometer:	237,253	Certification:	Referee	VLT Record #:	598
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile
Referee Label #:	N0194831	Engine Year:	1978	Engine Make:	PORSC

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: IV149712

DMV ID Number: 9808V162I881

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Not applicable	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB05	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Not applicable	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Filipo Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

ASM Emission Test Results

		%CO2	%O2	HC (PPM)			CO (%)			NO (PPM)			
Test	RPM	MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	Results
15 mph	1578	12.9	2.6	201	40	54	1.30	0.17	0.42	1314	520	1089	Pass
25 mph	1781	12.7	3.0	168	31	47	1.10	0.15	0.25	1174	452	1079	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

PRO SMOG

14105 Washington Ave. San Leandro, Ca 94578

510-814-9888

Station Number: TC270928

Technician Name/Number:

NGUYEN, DANH/EO149542

Repair Tech Name/Number:

Software Version/EIS Number:

2201 / EP728108

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date


Technician's Signature

06 - 16 - 23

[Signature]

KS SMOG

16210 Foothill Blvd., San Leandro, CA 94578
510-397-2440 ARD# 292531




YEAR		MAKE		MODEL		PAYMENT: CASH CREDIT CARD DEBIT	
LIC. PLATE		STATE		ODOMETER		DESCRIPTION OF WORK	
VIN#						AMOUNT	
7TVW652		CA		237758		SMOG INSPECTION	
PCV		EGR		ENGINE: 3.6		CERTIFICATE FEE	
CAT		AIS		CA FED		EVAP TEST FEE	
EVAP		TC/SC		FUEL TYPE		RETEST	
SPK		FUEL M.		TIMING 5°			
WRG		VAC		TIRE PRESSURE			
SMOKE		MIL		FL FR			
TAC		OTH		RL RR			

ESTIMATE PASS	ESTIMATE
	FAIL. ABORT. NOT READY
\$ 117.00	\$ 108.75
DISCOUNTED RETEST:	40. + certificate
1 DISCOUNTED RETEST VALID FOR 30 DAYS OF FAILED INSPECTION	
GRAND TOTAL	\$ 117.00

THIS SMOG TEST-ONLY STATION CANNOT PERFORM ANY REPAIRS, DIAGNOSTICS OR ADJUSTMENTS

I hereby authorize the above smog test to be performed and understand that the smog test fee is due whether above vehicle passes, fails, aborts or not ready the smog test. You and your employees may operate above vehicle for purposes of testing, inspection and delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of the service rendered. You will not be held responsible for loss or damage to vehicle due to fire, theft, accident, dynamometer testing or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fee and court costs. I have read and understand the above and acknowledge receipt of estimate

X  DATE 8/28/2025

SMOGOLOGY LLC (REV-2018)



www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)

www.autorepair.ca.gov

Vehicle Information

Test Date/Time: 08/28/2025@12:27:16

Model Year:	1977	Make:	PORSCHE	Model:	911
License:	7TVW652	State:	CA	VIN:	9117210691
Engine Size:	3.00 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	3500	Cylinders:	6
Odometer:	237,758	Certification:	Referee	VLT Record #:	598
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile
Referee Label #:	N0194831	Engine Year:	1978	Engine Make:	PORSCHE

Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: US381742**DMV ID Number: 9587S167U791**

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Not applicable	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB05	Pass	Other Emission Related Components
Not Applicable	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

ASM Emission Test Results

Test	RPM	%CO2		%O2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	
15 mph	1562	13.2	2.1	201	40	44	1.30	0.17	0.46	1314	520	1060			Pass
25 mph	1796	13.0	2.6	168	31	36	1.10	0.15	0.27	1174	452	1080			Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

Smog Check Inspection Station Information

KS SMOG

16210 FOOTHILL BLVD

(510) 397-2440

Station Number: TC292531

Technician Name/Number:

LE MICHAEL/EO634676

Repair Tech Name/Number:

Software Version/EIS Number:

2402: EP831189

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements and that the information listed on this vehicle inspection report is true and accurate.

Date

Technician's Signature

61703

Order Date 09/02/25 11:40 am

Paid: 09/02/25 02:47 pm

BAR #: AD-015082
 CAL 000121168
 355 E 14th Street
 San Leandro, CA 94577
 Phone: 510-568-6800

77 PORSCHE 911 WHITE
 237763 Mi. Last in 6/25/2020
 Lic: 2VDF154/CA H6Cyl 3.0
 Vin: 9117210691 10/76
 Eq:

Quotes

1 09/02/25 11:41am 378.88
 in person.

REPLACE BATTERY

Labor: \$97.50

REPLACE BATTERY

S5533B	49 BATTERY-N	1.0 @	250.00 =\$	250.00	
EYELET, CONNECTO	ELEC EYELET-S	1.0 @	2.00 =\$	2.00	252.00
					Job Subtotal: \$349.50

Recommendations: *BRAKES HYDRAULIC* *Lube, Oil and Filter* *ENGINE MECHANICAL*

Tire Pressure: 29F 36R

PLEASE CHECK HERE [] FOR OLD/REMOVED PARTS TO BE KEPT FOR INSPECTION OR SELF DISPOSAL

STORAGE WILL BE CHARGED ON CARS LEFT ON PREMISES BEGINNING 2 DAYS AFTER NOTIFICATION OF COMPLETED REPAIRS AT THE RATE OF \$125.00/DAY

Payments to World Imported Car Service Inc. Cost Summary

Status: Paid Work Order

Payments: \$378.59
 1 09/02/25 378.59 Visa

Labor	97.50
Parts	252.00
CA BATTERY FEE	2.00
Subtotal	351.50
Tax	27.09
Total	\$378.59
Payments	378.59
Bal Due	0.00

Thank you for choosing World Imported Car Service Inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____