

LASKY COACHWORKS, INC.
License #:BAR#AH174179 Federal ID #:954431407
THE FINEST IN COLLISION REPAIR
2241 FEDERAL AVENUE
LOS ANGELES, CA 90064
(310)479-3223 Fax: (310)473-6608

*Paint
x 26,464.1*

PRELIMINARY ESTIMATE

Written By: Manny Dalyan
Adjuster:

Insured:
Owner:
Address:

Day:

Claim #
Policy #
Deductible:
Date of Loss:
Type of Loss:
Point of Impact:

Inspect LASKY COACHWORKS, INC.
Location: 2241 FEDERAL AVENUE
LOS ANGELES, CA 90064

Business: (310)479-3223

Insurance O.P.A.
Company:

Days to Repair

1978 FERR F 102 BB (512-BB) 2D RED Int:Black

VIN: 25825

Lic: 25825

ID Prod Date:

Odometer:

Condition: Good

Clear Coat Paint

Two Tone Paint

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1#		FRONT BUMPER	1				
2#		O/H Front bumper assy	1			3.5	
3#		add for fog lamps	1			1.3	
4#	Rpr	Front bumper				4.5	2.6
5#		add for clear & two tone	1				1.8
6#	R&I	FRT bumper bottom cover				0.8	
7#		FENDER	1				
8#	R&I	RT Fender Liner					
9#	R&I	LT Fender Liner					
10#	Rpr	LT FRT inner hood/fender section				6.0	3.1
11#		Add for primer	1	15.00	X	0.3	
12#		HEADLAMPS	1				
13#	R&I	RT Headlamp assy attached on hood				0.8	
14#	R&I	LT Headlamp assy attached on hood				0.8	
15#	Refn	RT Headlamp housing cover					1.6
16#		add for clear & two tone	1				1.2
17#	Refn	LT Headlamp housing cover					1.6

PRELIMINARY ESTIMATE

1978 FERR F 102 BB (512-BB) 2D RED Int:Black

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
18#		add for clear & two tone	1				1.2
19#	R&I	RT Signal lamps attached on hood				1.2	
20#	R&I	LT Signal lamps attached on hood				1.2	
21#	R&I	RT Marker lamp attached on hood				0.6	
22#	R&I	LT Marker lamp attached on hood				0.6	
23#		HOOD	1				
24#	Rpr	FRT nose panel section (including headlamp caovers)				9.0	
25#	R&I	Hood assy				5.0	
26#	Refn	Hood					5.0
27#		Add for clear coat	1				2.0
28#		add for two tone	1				2.1
29#	R&I	Insulator				0.6	
30#	R&I	Weatherstrip RT/LT				0.4	
31#	R&I	Emblem				0.3	
32#	R&I	Center Grille				1.3	
33#	R&I	RT Support cylinder				0.3	
34#	R&I	LT Support cylinder				0.3	
35#	R&I	Lock				0.4	
36#	R&I	Catcher				0.4	
37#	R&I	RT hinge				0.3	
38#	R&I	LT hinge				0.3	
39#		WINDSHIELD	1				
40#	R&I	ROPE Front windshield				1.0	
41#	Subl	Seal	1	55.00	X		
42#	R&I	Windshield wiper arm assy				1.2	
43#	Refn	Windshield wiper cover					0.8
44#		add for clear coat	1				0.3
45#		COWL	1				
46#	R&I	Cowl assy				1.3	
47#	R&I	Weatherstrip				0.4	
48#		ELECTRICAL	1				
49#	R&I	FRT Wiring assy				0.6	
50#		DOOR	1				
51#	Rpr	LT Outer door				5.9	
52#	R&I	LT Door				3.0	
53#	Refn	LT Door complete					5.6
54#		add for clear coat	1				1.6
55#		add for two tone	1				1.3
56#	R&I	LT Mirror assy				0.6	
57#	R&I	LT belt molding				0.4	
58#	R&I	LT Weatherstrip				0.6	
59#	R&I	LT Glass assy				1.1	
60#	R&I	LT trim panel				0.8	

PRELIMINARY ESTIMATE

1978 FERR F 102 BB (512-BB) 2D RED Int:Black

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
61#	R&I	LT Handle				0.4	
62#	R&I	LT lock				0.4	
63#	R&I	RT Door				3.0	
64#	Rpr	RT Outer door				5.9	
65#	Refn	RT Door complete					5.6
66#		add for two tone	1				1.3
67#		add for clear coat	1				1.6
68#	R&I	RT belt molding				0.4	
69#	R&I	RT Weatherstrip				0.6	
70#	R&I	RT Glass assy				1.1	
71#	R&I	RT trim panel				0.8	
72#	R&I	RT Handle					
73#	R&I	RT lock				0.4	
74#		ROOF	1				
75#	R&I	RT Drip molding				0.3	
76#	R&I	LT Drip molding				0.3	
77#	Refn	Roof					4.0
78#		add for clear coat	1				1.8
79#		add for two tone	1				1.8
80#	Refn	RT roof rails					1.3
81#		add for clear coat	1				0.7
82#		add for two tone	1				0.5
83#	Refn	LT roof rails					1.3
84#		add for clear coat	1				0.7
85#		add for two tone	1				0.5
86#	R&I	RT inner rail cover				0.4	
87#	R&I	LT inner rail cover				0.4	
88#		QUARTER PANEL	1				
89#	Rpr	RT QTR panel				5.0	
90#	Refn	RT QTR panel					3.5
91#		add for two tone	1				1.0
92#		add for clear coat	1				1.3
93#	Refn	LT QTR panel					3.5
94#		add for clear coat	1				1.3
95#		add for two tone	1				1.0
96#	Rpr	LT QTR panel				5.0	
97#	R&I	RT QTR glass				0.6	
98#	R&I	LT QTR glass				0.6	
99#		PILLARS, ROCKER & FLOOR	1				
100#	R&I	RT Rocker molding				1.6	
101#	Refn	RT Rocker molding					2.9
102#		add for clear coat	1				1.6
103#		add for two tone	1				1.1
104#		RT Rocker molding	1				
105#	R&I	LT Rocker molding				1.6	
106#	Refn	LT Rocker molding					2.9
107#		add for clear coat	1				1.6
108#		add for two tone	1				1.1

PRELIMINARY ESTIMATE

1978 FERR F 102 BB (512-BB) 2D RED Int:Black

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
109#	R&I	RT pillar weatherstrip				0.8	
110#	R&I	LT pillar weatherstrip				0.8	
111#	R&I	RT Door catcher				0.4	
112#	R&I	LT Door catcher				0.4	
113#	R&I	RT Still plate				0.7	
114#	R&I	LT Still plate				0.7	
115#	R&I	RT Wheelhouse assy				0.9	
116#	R&I	LT Wheelhouse assy				0.9	
117#		TRUCK	1				
118#	Rpr	Black scoop				10.0	
119#	Refn	Black scoop cover					5.5
120#		add for flat clear	1				2.3
121#	R&I	Trunk				6.0	
122#	Refn	Trunk					7.0
123#		add for clear coat	1				1.8
124#		add for two tone	1				1.6
125#	R&I	Emblem				0.5	
126#	R&I	"BB-512" Nameplate				0.6	
127#	R&I	Inner trunk vent covers (all 5 sections)				2.6	
128#	R&I	Center red Vent grille				2.0	
129#	Refn	Center red Vent grille					2.5
130#		add for clear & two tone	1				1.8
131#	R&I	RT red vent grille				2.0	
132#	Refn	RT red vent grille					2.5
133#		add for clear & two tone	1				1.8
134#	R&I	LT red vent grille				2.0	
135#	Refn	LT red vent grille					2.5
136#		add for clear & two tone	1				1.8
137#	R&I	RT black vent grille				2.0	
138#	Refn	RT black vent grille					1.9
139#		add for clear & two tone	1				2.0
140#	R&I	LT black vent grille				2.0	
141#	Refn	LT black vent grille					3.0
142#		add for clear & two tone	1				2.0
143#	R&I	RT Black engine carburetor cover				2.0	
144#	Refn	RT Black engine carburetor cover					2.0
145#		add for clear & two tone	1				2.0
146#	R&I	LT Black engine carburetor cover				2.0	
147#	Refn	LT Black engine carburetor cover					2.0
148#		add for clear & two tone	1				2.0
149#	R&I	Fuel door				0.8	
150#	Refn	Fuel door					0.6
151#		add for clear coat	1				0.4

PRELIMINARY ESTIMATE

1978 FERR F 102 BB (512-BB) 2D RED Int:Black

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
152#	R&I	safety latch				0.4	
153#	R&I	RT hinge				0.3	
154#	R&I	LT hinge				0.3	
155#	R&I	RT support cylinder				0.5	
156#	R&I	RT support cylinder				0.5	
157#		REAR LAMPS	1				
158#	R&I	Wiring assy				1.5	
159#	R&I	RT Taillamp assy				1.2	
160#	R&I	LT Taillamp assy				1.2	
161#	R&I	RT Signal lamps assy				0.6	
162#	R&I	RT Signal lamps assy				0.6	
163#	R&I	Back vent grille				1.6	
164#	R&I	Back license plate assy(2 sets)				0.6	
165#		REAR BUMPER	1				
166#		O/H rear bumper	1			5.4	
167#	Rpr	bumper				5.0	3.1
168#		add for clear & two tone	1				2.3
169#		BACK GLASS	1				
170#	R&I	ROPE back glass				0.5	
171#		Undercoating	1	55.00	T	2.0	
172#		Corrosion Protection	1	120.00	T	3.5	
173#		Rust coating	1	65.00	T	2.0	
174#		Color match	1			1.5	
175#		Cover car for overspray	1	35.00	T	0.5	
176#		Cover interior	1	35.00		1.0	
177#		Caulk & seal	1	15.00	T	1.0	
178#		Color sand & buff	1			5.0	
179#		Flex agent additive	2	25.00	T		
180#		Aim headlamp assy	1			2.0	
181#		Hazardous waste disposal	1	5.00	X		
182#		Isolate battery/on BD computer	1			0.5	
183#		ENGINE	1				
184#	R&I	RT AIR FILTER ASSY				0.8	
185#	R&I	LT AIR FILTER ASSY				0.8	
186#	Rpr	STRIP ENGINE COMPARTMENT TO METAL				6.0	
187#		STEAM CLEAN ENGINE	1			4.0	
188#	Refn	PAINT INNER REAR SHELL IN ENGINE COMPARTMENT					6.0
189#	Refn	PAINT RT AIR FILTER ASSY COVER					2.0
190#	Refn	PAINT LT AIR FILTER ASSY COVER					2.0
191#		DETAIL COMPLETE ENGINE	1			8.0	
Subtotals ==>				425.00		184.8	140.1

PRELIMINARY ESTIMATE

1978 FERR F 102 BB (512-BB) 2D RED Int:Black

*This is not an
estimate - this was
the actual cost
for paint*

Parts			35.00
Body Labor	184.8 hrs @ \$ 65.00/hr		12012.00
Paint Labor	140.1 hrs @ \$ 65.00/hr		9106.50
Paint Supplies	140.1 hrs @ \$ 45.00/hr		6304.50
Sublet/Misc.			390.00

SUBTOTAL			\$27848.00
Sales Tax	\$ 6654.50 @ 9.2500%		615.54

GRAND TOTAL			\$28463.54

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO APPEAR ON THIS FORM:

ANY PERSON WHO KNOWINGLY PRESENTS FALSE OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED: MOTOR ABBREVIATIONS/SYMBOLS: D=DISCONTINUED PART A=APPROXIMATE PRICE LABOR TYPES: B=BODY LABOR D=DIAGNOSTIC E=ELECTRICAL F=FRAME G=GLASS M=MECHANICAL P=PAINT LABOR S=STRUCTURAL T=TAXED MISCELLANEOUS X=NON TAXED MISCELLANEOUS PATHWAYS: ADJ=ADJACENT ALGN=ALIGN A/M=AFTERMARKET BLND=BLEND CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION D&R=DISCONNECT AND RECONNECT EST=ESTIMATE EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY INCL=INCLUDED MISC=MISCELLANEOUS NAGS=NATIONAL AUTO GLASS SPECIFICATIONS NON-ADJ=NON ADJACENT O/H=OVERHAUL OP=OPERATION NO=LINE NUMBER QTY=QUANTITY QUAL RECY=QUALITY RECYCLED PART QUAL REPL=QUALITY REPLACEMENT PART COMP REPL PARTS=COMPETITIVE REPLACEMENT PARTS RECOND=RECONDITION REFN=REFINISH REPL=REPLACE R&I=REMOVE AND INSTALL R&R=REMOVE AND REPLACE RPR=REPAIR RT=RIGHT SECT=SECTION SUBL=SUBLET LT=LEFT W/O=WITHOUT W/_=WITH/_ SYMBOLS: #=MANUAL LINE ENTRY *=OTHER [IE..MOTORS DATABASE INFORMATION WAS CHANGED] **=DATABASE LINE WITH AFTERMARKET N=NOTES ATTACHED TO LINE. MQVP=MANUFACTURER'S QUALIFICATION AND VALIDATION PROGRAM. OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT. NWCPP=NATIONWIDE CRASH PARTS PROGRAM.

CCC Pathways - A product of CCC Information Services Inc.

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

78 Ferrari 512 BB RED/BLK

Lic: 4349K/ID 12Cyl 4.9 Eng

Vin: F102BB25525

Eq:

Profile:

Quotes

1 06/19/12 12:28pm 0.00

MICHEAL in person.

1) service

Job01 512 BB 30K SERVICE

Labor: \$0.00

99100110	V/C GASKET KIT-S	1.0 @	140.00 =	\$ 140.00
99100222	GASKET,CAMSEAL KIT-S	1.0 @	160.00 =	\$ 160.00
107833	CAMBELT-S	2.0 @	26.52 =	\$ 53.04
105206	BEARING,TENSIONER-N	2.0 @	133.46 =	\$ 266.92
FPN00191993	FILTER, OIL,288,246,27-N	2.0 @	33.70 =	\$ 67.40
102918	BELT,ALTERNATOR-S	1.0 @	29.95 =	\$ 29.95
105317	A/C BELT-S	1.0 @	44.78 =	\$ 44.78
BP6ES	SPARK PLUG, NGK 7333-N	12.0 @	5.70 =	\$ 68.40
10001453	WATER PUMP REBUILD KIT-S	1.0 @	109.77 =	\$ 109.77
95180050	FILTER, FUEL-N	1.0 @	27.31 =	\$ 27.31
5089189	OIL,GEAR 80-90W VAL-N	9.0 @	7.68 =	\$ 69.12
ZX001	COOLANT,ZEREX-N	2.0 @	14.77 =	\$ 29.54
98HP43	OIL, MOBIL 1 15-50W-N	11.0 @	9.62 =	\$ 105.82
				1172.05

Status: Completed Tech: 02

Job02 PARTS

Labor: \$0.00

92.3276.05	CARB REBUILD KIT-S	4.0 @	44.00 =	\$ 176.00
460.22.29	WASHER,COPPER 22X29-N	2.0 @	1.04 =	\$ 2.08
107867	CLUTCH SLAVE CYLINDER-S	1.0 @	235.00 =	\$ 235.00
95860404K/4	C/V JOINT BOOT KIT-S	1.0 @	104.95 =	\$ 104.95
891.5020.1	MULTI-SOLVENT-N	5.0 @	5.35 =	\$ 26.75
147630	SINGLE EXHAUST GASKET-S	4.0 @	19.58 =	\$ 78.32
147641	EXHAUST GASKET DOUBLE-S	4.0 @	23.00 =	\$ 92.00
154979	EXHAUST GASKET RING-S	4.0 @	19.00 =	\$ 76.00
147697	EXHAUST PIPE GASKET-S	4.0 @	10.00 =	\$ 40.00
146696	EXHAUST PIPE SEAL-S	2.0 @	15.30 =	\$ 30.60
11212120	SQ STEEL TUBE-S	1.0 @	56.70 =	\$ 56.70
7447	SCOTCH BRITE PAD RED-N	1.0 @	2.89 =	\$ 2.89
46993	BRUSH,STEEL1/4"-N	1.0 @	3.56 =	\$ 3.56
76150	RADIATOR HOSE-S	1.0 @	42.89 =	\$ 42.89
24702	HOSE,GAS-S	3.0 @	24.20 =	\$ 72.60
76574	O RING, CARBURETOR-N	12.0 @	0.81 =	\$ 9.72
9262K167	O RING, 7.5X2.5 PACK-N	1.0 @	7.26 =	\$ 7.26

----->----->----->---Continued on the next page--->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job02 PARTS

95300043	DISTRIBUTOR CAP-S	1.0 @	440.00 =\$	440.00
95300313	DIST. ROTOR-S	1.0 @	344.10 =\$	344.10
76125	HOSE, RADIATOR-N	2.0 @	10.26 =\$	20.52
99005.047	BASE GASKET,CARBURETOR-N	12.0 @	1.68 =\$	20.16
41565.009	O-RING, PUMP JET-N	12.0 @	1.25 =\$	15.00
690.8450	BRUSH, STAINLESS-N	1.0 @	3.81 =\$	3.81
713695	SPRAY PAINT,DULL ALU S-N	3.0 @	8.49 =\$	25.47
513812	SPRAY,SEMI BLACK-N	3.0 @	5.80 =\$	17.40
510370	ACETONE-N	2.0 @	26.71 =\$	53.42
SHOP MATERIALS	RAG`S, FENDERLINER. ET-N	1.0 @	10.00 =\$	10.00
3370	BLACK WRINKLE PAINT-N	2.0 @	12.10 =\$	24.20
513812	SPRAY,SEMI BLACK-N	4.0 @	5.80 =\$	23.20
150080	PAINT,SATIN BLACK-N	1.0 @	8.49 =\$	8.49
1211	GASKET,LIQUID BOND-N	1.0 @	25.72 =\$	25.72
WGM-F	WASHER, FLAT, BLK OX-N	5.0 @	0.81 =\$	4.05
NGW-L	NUT, HEX LOCK-N	11.0 @	0.85 =\$	9.35
538.12.02540	CLAMP,25-40-N	6.0 @	2.25 =\$	13.50
76100	HOSE, RETURN 12"-N	1.0 @	9.46 =\$	9.46
538.3850	CLAMP,HOSE #3 M8X14-N	4.0 @	1.45 =\$	5.80
70838	HOSE, COOLANT-N	1.0 @	0.88 =\$	0.88
538.1928	CLAMP,HOSE #10 M19X28-N	2.0 @	1.75 =\$	3.50
BGM-H	BOLT,HEX CAP BLK OX-N	1.0 @	0.85 =\$	0.85
690.8450	BRUSH, STAINLESS-N	1.0 @	3.81 =\$	3.81
538.3244	CLAMP,HOSE #20 M32x44-N	2.0 @	1.89 =\$	3.78
70838	HOSE, COOLANT-N	1.0 @	17.16 =\$	17.16
76088	HOSE, THERMOSTAT-N	3.0 @	18.92 =\$	56.76
103877	BEARING,PILOT-N	1.0 @	30.11 =\$	30.11
3003H14	SHEET, ALUMINUM 3003-N	1.0 @	79.54 =\$	79.54
460.6.10	WASHER,COPPER 6X10-N	3.0 @	0.24 =\$	0.72
AC501-9469	CV JOINT-S	4.0 @	79.95 =\$	319.80
76075	HOSE, COOLANT 3/4"-S	3.0 @	12.20 =\$	36.60
105624	PLUG WIRE SET 1-6-S	1.0 @	385.00 =\$	385.00
105627	PLUG WIRE SET 7-12-S	1.0 @	385.00 =\$	385.00
110908	WIRE,COIL-S	1.0 @	32.20 =\$	32.20
124792	SPARK PLUG EXTINTION-S	4.0 @	12.44 =\$	49.76
52545K57	CLAMP,CV BOOT-S	4.0 @	3.92 =\$	15.68
74403.050	IDLE JET-N	12.0 @	4.87 =\$	58.44
98.0181.00	SET, DRILL .30-2.0MM-N	1.0 @	39.55 =\$	39.55
99005.031	GASKET, BASE DCOE-N	9.0 @	1.64 =\$	14.76
2521A426	7/8" TAP-S	1.0 @	40.87 =\$	40.87
470.16.32	PIN, COTTER-N	4.0 @	0.80 =\$	3.20
460.12.16	WASHER,COPPER 10X14-N	8.0 @	0.28 =\$	2.24
538.3850	CLAMP,HOSE38X50-N	4.0 @	1.80 =\$	7.20
538.1928	CLAMP,HOSE #10 M19X28-N	10.0 @	1.75 =\$	17.50
FC647-12BLK	HOSE,LOW PRESSURE-N	1.0 @	6.80 =\$	6.80
538.1524	CLAMP,#8 M15x24-N	1.0 @	1.59 =\$	1.59

----->----->----->---Continued on the next page--->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job02 PARTS

538.1320	CLAMP,HOSE #3 M8X14-N	5.0 @	1.45 =\$	7.25
NGW-L	NUT, HEX LOCK-N	8.0 @	0.85 =\$	6.80
WGM-W	WASHER,WAVE,BLK OX-N	8.0 @	0.83 =\$	6.64
460.12.18	WASHER,COPPER 12X18-N	2.0 @	0.42 =\$	0.84
65271	WASHER,COPPER 1/2X7/8"-S	1.0 @	4.04 =\$	4.04
116270	1.5 FULE HOSE-S	1.0 @	25.37 =\$	25.37
541.7.11	CLAMP,HOSE MINI-N	10.0 @	2.52 =\$	25.20
GAS2	Gasoline 92 Octane-N	5.0 @	4.90 =\$	24.50
22207	STABILZER, GAS-N	2.0 @	5.00 =\$	10.00
80206	HOSE,VAC 5/32"-N	10.0 @	1.18 =\$	11.80
147687	INTAKE GASKET-S	10.0 @	3.82 =\$	38.20
147688	GASKET CARB-S	2.0 @	22.95 =\$	45.90
460.12.18	WASHER,COPPER 12X18-N	2.0 @	0.42 =\$	0.84
538.2638	CLAMP,HOSE #16 M26X38-N	2.0 @	1.45 =\$	2.90
538.1524	CLAMP,#8 M15x24-N	4.0 @	1.59 =\$	6.36
ACHG0047	BATTERY TENDER, 12V-N	1.0 @	60.74 =\$	60.74
2556	FLUID, BRAKE LMA CASTROL-N	1.0 @	16.11 =\$	16.11
GAS2	Gasoline 92 Octane-N	10.0 @	4.20 =\$	42.00
74403.065	IDLE JET-S	12.0 @	4.87 =\$	58.44
787465	C CLIP, 1/4"-N	1.0 @	0.30 =\$	0.30
9262K634	O-RING, 14X1.5 PKG.-S	1.0 @	6.75 =\$	6.75
463.20.26	WASHER,ALUMINUM 20X26-N	2.0 @	0.60 =\$	1.20
657271	WASHER, COPPER 1/2X7/8"-N	1.0 @	3.44 =\$	3.44
5MXG3	WASHER, SEALING PK-S	1.0 @	11.89 =\$	11.89
10006.408	SHAFT, THROTTLE-S	4.0 @	95.00 =\$	380.00
10016.442	SHAFT, THROTTLE SINGLE-S	4.0 @	65.00 =\$	260.00
34715.014	NUT, THROTTLE SHAFT-S	4.0 @	2.47 =\$	9.88
55520.002	TAB, SHAFT LOCK-S	4.0 @	0.96 =\$	3.84
64570.009	SCREW, THROTTLE PLATE-S	24.0 @	3.35 =\$	80.40
41575.010	BUSHING, SHAFT SEALING-S	10.0 @	2.04 =\$	20.40
52130.010	BUSHING, SHAFT-S	10.0 @	3.56 =\$	35.60
8851A43	REAMER, HSS 8.5MM-S	1.0 @	31.93 =\$	31.93
88755K56	ROD, TOOL STEEL 3`-S	1.0 @	7.51 =\$	7.51
2925A57	BIT, C.S 60 DEG. 7/16"-S	1.0 @	52.12 =\$	52.12
8893A14	BIT, 3/16x2-1.4"-S	1.0 @	35.85 =\$	35.85
8839A14	BIT, TOOL STEEL 3/16"-S	1.0 @	35.85 =\$	35.85
				5115.16

Status: Completed Tech: 02

Job03 4850 SHIPPING

Sublet: \$207.17

JUL-02 PIERCE MANIFOLDS
 JUL-02 T RUTLANDS
 JUL-03 T RUTLANDS
 JUL-12 MCMASTER-CARR
 JUL-16 PIERCE MANIFOLDS
 OCT-05 MCMASTER-CARR
 JUL-17 T RUTLANDS

----->----->----->---Continued on the next page--->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job03 4850 SHIPPING

OCT-03 T RUTLANDS W
OCT-04 MCMASTER CARR
OCT-26 T RUTLANDS W
NOV-09 T RUTLANDS W
NOV-20 PIERCE MANIFOLDS
NOV-30 MCMASTER-CARR
NOV-29 GRAINGER
DEC-20 MCMASTER-CARR
DEC-20 PIERCE MANIFOLDS
DEC-21 PIERCE MANIFOLDS
DEC-26 MCMASTER-CARR

Job04 JUNE 19 - TECH # 31

Labor: N/C

JUNE 19 - RACKED CAR, REMOVED WHEELS, PERFORMED SAFETY INSPECTION

Status: Completed Tech: 31

Job05 JUNE 27 - TECH # 12

Labor: N/C

JUNE 27 - BEGAN INSPECTION PRIOR TO MAJOR SERVICE

Status: Completed Tech: 12

Job06 JUNE 28 - TECH # 12

Labor: \$57.50

JUNE 28 - CONTINUED WITH ENGINE REMOVAL

Status: Completed Tech: 12

Job07 JUNE 29 - TECH # 12

Labor: \$230.00

JUNE 29 - CONTINUED WITH REMOVING MOTOR, REMOVED EXHAUST HEADERS AND HEAT SHIELDS, DRAINED OIL, ORDERED PARTS

Status: Completed Tech: 12

Job08 JULY 2 - TECH # 12

Labor: \$345.00

JULY 2 - REMOVED BOTH AXLE SHAFTS. REMOVED CARBS, DRAINED COOLANT SYSTEM, PULLED MOTOR, BEGAN CLEANING ENGINE BAY, BEGAN MOTOR DISASSEMBLY

Status: Completed Tech: 12

Job09 JULY 2 - TECH # 36

Labor: \$115.00

JULY 2 - ASSISTED FRANCISCO WITH ENGINE REMOVAL

----->----->----->---Continued on the next page--->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job09 JULY 2 - TECH # 36

Status: Completed Tech: 12

Job10 JULY - 4540 METAL SHOP

Labor: \$230.00

JULY 2 - ASSISTED WITH REMOVAL OF ENGINE FROM CAR

JULY 3 - COMPLETED MODIFYING ENGINE STAND, PUT MOTOR ONTO STAND FOR SERVICE

Status: Completed Tech: 11

Job11 JULY 3 - TECH # 12

Labor: \$345.00

JULY 3 - BEGAN DISASSEMBLING CARBS, BEGAN CLEANING PARTS FOR CARBS 1 AND 2, FINISHED CLEANING ENGINE BAY

Status: Completed Tech: 12

Job12 JULY 11 - TECH # 12

Labor: N/C

JULY 11 - BEGAN ASSEMBLING FIRST CARB AND CHECKED FOR CORRECT JETTING--FAILED, INCORRECT IDLE JETS

Status: Completed Tech: 12

Job13 JULY 12 - TECH # 12

Labor: \$115.00

JULY 12 - CONTINUE WITH CARB REBUILD, ORDERED MISSING PIECES, REMOVED VALVE COVERS AND WATER PUMP COVER

Status: Completed Tech: 12

Job14 JULY - TECH # 05

Labor: N/C

JULY 16 - PHOTOGRAPH CARB BEFORE AND AFTER REBUILD

Status: Completed Tech: 05

Job15 JULY 20 - TECH # 12

Labor: \$230.00

JULY 20 - CLEANED BLOCK, BEGAN CHECKING VALVE LASH

Status: Completed Tech: 12

Job16 JULY 25 - TECH # 12

Labor: \$230.00

JULY 25 - FINISHED ADJUSTING AND CHECKING VALVE LASH, BEGAN PULLING CAM AND CLEANING,

----->----->----->---Continued on the next page--->----->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job16 JULY 25 - TECH # 12

CHECKED LEAKDOWN--PASS, REMOVED TIMING BELTS AND TENSIONERS.

Status: Completed Tech: 12

Job17 AUGUST 8 - TECH # 12

Labor: \$345.00

AUGUST 8 - REMOVED EXH CAM ON 7-12 BANK

Status: Completed Tech: 12

Job18 AUGUST 14 - TECH # 12

Labor: \$115.00

AUGUST 14 - ASSISTED WITH PAINTING MOTOR

Status: Completed Tech: 12

Job19 SEPTEMBER 18 - TECH # 12

Labor: \$57.50

SEPTEMBER 18 - BEGAN PAINTING FRAME

Status: Completed Tech: 12

Job20 SEPTEMBER 19 - TECH # 12

Labor: \$287.50

SEPTEMBER 19 - INSTALLED CAMS ON BOTH BANKS, INSTALLED TIMING BELTS, BEGAN TO DEGREE CAMS

Status: Completed Tech: 12

Job21 SEPTEMBER 20 - TECH # 31

Labor: \$57.50

SEPTEMBER 20 - REMOVED WATER PUMP SEALS AND INSTALLED NEW ONES

Status: Completed Tech: 31

Job22 SEPTEMBER 20 - TECH # 12

Labor: \$230.00

SEPTEMBER 12 - DEGREED CAMS ON BOTH BANKS, BEGAN TO REMOVE AND REPLACE WATER PUMP, BEGAN TO CLEAN VALVE COVERS

Status: Completed Tech: 12

Job23 SEPTEMBER 21 - TECH # 12

Labor: \$230.00

SEPTEMBER 21 - CLEANED VALVE COVERS AND PREPPED FOR PAINT, WRINKLE FINISHED RIGHT VALVE COVER, CLEANED ALL GASKET SURFACES AFTER PAINT, COMPLETED REMOVAL AND REPLACEMENT OF WATER PUMP, BEGAN PREP FOR PAINT ON ENGINE BAY

Status: Completed Tech: 12

----->----->----->-----Continued on the next page----->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job24 SEPTEMBER 26 - TECH # 12**Labor: \$345.00**

SEPTEMBER 26 - FINISHED PAINTING FENDER WELLS, WRINKLE FINISHED OIL TANK AND VALVE COVER, BEGAN INSTALLING COOLANT PIPING ON ENGINE, REPAIRED THREADS ON BLOCK, INSTALLED TIMING COVERS

Status: Completed Tech: 12

Job25 SEPTEMBER 28 - TECH # 12**Labor: \$345.00**

SEPTEMBER 28 - INSTALLED SMOG PUMP, ALTERNATOR, A/C COMPRESSOR AND COOLANT HOSES, INSPECTED IGNITION SYSTEM, PLUG WIRES FAILED, PLUG EXTENSIONS--4 FAILED, DISTRIBUTOR BEARINGS ARE SHOT, BEGAN REBUILDING HALF SHAFTS--FAILED, BEARINGS ARE DONE

Status: Completed Tech: 12

Job26 4845 REBUILD**Sublet: \$162.00**

SEP-28 REBUILD ALTERNATOR

Job27 OCTOBER 1 - TECH # 12**Labor: \$517.50**

OCTOBER 1 - CLEANED AND INSPECTED ALL CV JOINTS--FAILED, ORDERED NEW CV JOINTS, DISASSEMBLED DISTRIBUTOR AND BEGAN REBUILD, REMOVE AND REPLACE DISTRIBUTOR BEARING, PAINTED AND ASSEMBLED DISTRIBUTOR, INSTALLED DISTRIBUTOR AND TIMED, CONTINUED REBUILD ON CARBS, CHECKED GEARBOX FILL PLUG, FAILED- COMPLETELY STRIPPED, BEGAN TAKING MEASUREMENTS TO REPAIR PLUG

Status: Completed Tech: 12

Job28 OCTOBER 2 - TECH # 12**Labor: \$230.00**

OCTOBER 2 - RECEIVED CJ JOINTS AND BEGAN ASSEMBLY, 1 OF THE 4 CV JOINTS WAS DEFECTIVE, SENT BACK, INSTALLED HALF SHAFT ON LEFT SIDE, DISASSEMBLED LAST CARB AND BEGAN REBUILD, RESEARCHED BLOCK COVER FOR WIRING HARNESS PER CUSTOMER REQUEST

Status: Completed Tech: 12

Job29 OCTOBER - 4540 METAL SHOP**Labor: \$230.00**

OCTOBER 1 - STARTED MAKING ENGINE BAY HEATSHIELD, MACHINED SMALL SPACERS TO PREVENT HEATSHIELD CRUSHING WHEN BOLTED INTO PLACE.

OCTOBER 3 - MARCO - STARTED MAKING HEAT SHIELD

Status: Completed Tech: 11

Job30 OCTOBER 5- TECH # 12**Labor: \$345.00**

----->----->----->-----Continued on the next page----->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job30 OCTOBER 5- TECH # 12

OCTOBER 5 - FINISHED INSTALLING CV JOINTS, INSTALLED HALF SHAFTS, CONTINUED WORKING ON CARBS, CHANGED FUEL FILTER, INSTALLED NEW FILL PLUG, CLEANED, DRILLED AND TAPED THREADS FOR GENERATOR FILL PLUG

Status: Completed Tech: 12

Job31 OCTOBER - 4530 MACHINE SHOP

Labor: \$172.50

OCTOBER 5 - MODIFY AN OIL DRAIN PLUG AND INTRODUCE THE SOCKET HEXAGONAL IN THE CENTER

OCTOBER 26 - RESURFACE INTAKE MANIFOLDS ON THE SURFACE GRINDER

Status: Completed Tech: 08

Job32 OCTOBER 8 - TECH # 12

Labor: \$230.00

OCTOBER 8 - FINISHED REBUILDING CARBS, INSTALLED ENGINE AND BEGAN CONNECTING COOLANT LINES

Status: Completed Tech: 12

Job33 OCTOBER 9 - TECH # 12

Labor: \$230.00

OCTOBER 9 - CONTINUE CONNECTING ALL LINES AND CONNECTORS, INSTALLED PLUG WIRES AND CLUTCH BELL HOUSING, DRAINED GEAR OIL AND REFILLED

Status: Completed Tech: 12

Job34 OCTOBER 10 - TECH # 12

Labor: \$230.00

OCTOBER 10 - FINISHED IGNITION SYSTEM, FINISHED SMOG SYSTEM, CONTINUED INSTALLING FUEL LINES, BEGAN CLEANING HEAT SHIELDS

Status: Completed Tech: 12

Job35 OCTOBER 11 - TECH # 12

Labor: \$230.00

OCTOBER 11 - CLEANED EXHAUST SYSTEM AND GASKET SURFACES, BEGAN INSTALLING EXHAUST ON RIGHT BANK, FOUND A STRIPPED STUD AND HAD TO REMOVE EXHAUST, CLEANED AND SCUFFED UP HEATSHIELD, INSTALLED HEATSHIELD, FINISHED FUEL SYSTEM

Status: Completed Tech: 12

Job36 OCTOBER 12 - TECH # 12

Labor: \$172.50

OCTOBER 12 - BEGAN INSTALLING EXHAUST SYSTEM ON LEFT BANK, REMOVED MOTOR MOUNT TO ACCESS STRIPPED STUD, BEGAN REPAIRING THREADS

Status: Completed Tech: 12

----->----->----->---Continued on the next page--->----->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job37 OCTOBER 22- TECH # 12**Labor: \$230.00**

OCTOBER 22 - FINISHED REPAIRING EXHAUST AND INSTALLED

Status: Completed Tech: 12

Job38 OCTOBER 23 - TECH # 12**Labor: \$57.50**

OCTOBER 23 - ADDED FLUIDS AND BLED COOLANT

Status: Completed Tech: 12

Job39 OCTOBER 24 - TECH # 12**Labor: \$230.00**

OCTOBER 24 - RAN CAR TO OPERATING TEMP AND CHECKED FOR LEAKS--FOUND FUEL LEAK AND REPAIRED, BEGAN ADJUSTING CARBS - FOUND LEAK AT INTAKE MANIFOLD

Status: Completed Tech: 12

Job40 OCTOBER 25 - TECH # 12**Labor: \$115.00**

OCTOBER 25 - BEGAN PULLING INTAKE MANIFOLDS, DRAINED COOLANT

Status: Completed Tech: 12

Job41 OCTOBER 26 - TECH # 12**Labor: \$115.00**

OCTOBER 26 - REMOVED CARBS AND INTAKES, BEGAN CLEANING GASKET SURFACES, CHECKED MANIFOLDS FOR WARPAGE--FAILED, GAVE TO MACHINIST TO RESURFACE

Status: Completed Tech: 12

Job42 OCTOBER 29 - TECH # 12**Labor: \$230.00**

OCTOBER 29 - FINISHED CLEANING GASKET SURFACES, INSTALLED INTAKE MANIFOLDS, CARBS AND CONNECTED ALL THE LINKAGE, ADDED COOLANT AND PRESSURE TESTED--PASS

Status: Completed Tech: 12

Job43 OCTOBER 30 - TECH # 12**Labor: \$230.00**

OCTOBER 30 - CONTINUED WITH CARB ADJUSTMENT, CONNECTED FUEL SUPPLY, BEGAN CHECKING FLOAT LEVEL

Status: Completed Tech: 12

Job44 OCTOBER 31 - TECH # 12**Labor: \$230.00**

OCTOBER 31 - CAR BACKFIRES AND WILL NOT IDLE CORRECTLY, CONTINUE WITH CARB ADJUSTMENT,

----->----->----->---Continued on the next page--->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job44 OCTOBER 31 - TECH # 12

CHECKED FLOAT LEVELS AND ADJUSTED, CHECKED VAC CHECK VALVE AT
CYLINDER #1--PASS, CHECKED LEAKDOWN--PASS, CHANGED PLUG AND EXT ON CYLINDER #1, CHECKED
TIMING--PASS, CHECKED TIMING ADVANCE--FAILED, GETTING STUCK, REMOVED DISTRIBUTOR

Status: Completed Tech: 12

Job45 NOVEMBER 1 - TECH # 12

Labor: \$287.50

NOVEMBER 1 - DISASSEMBLED DISTRIBUTOR AND INSPECTED, FOUND THAT ONE OF THE COUNTER WEIGHTS
WAS JUST FLOATING, CHECKED ADVANCE CURVE ON MACHINE--FAILED, TIMING RETARDS BELOW 1K RPM

Status: Completed Tech: 12

Job46 NOVEMBER 1 - TECH # 10

Labor: N/C

NOVEMBER 1 - ASSISTED FRANCISCO WITH DIAGNOSING RUNNING ISSUES

Status: Completed Tech: 10

Job47 NOVEMBER 2 - TECH # 12

Labor: \$115.00

NOVEMBER 2 - CHECKED DISTRIBUTOR ON MACHINE--FAILED, DISTRIBUTOR IS RETARDING TIMING,
BEGAN DIAGNOSIS ON DISTRIBUTOR

Status: Completed Tech: 12

Job48 NOVEMBER 8 - TECH # 12

Labor: \$115.00

NOVEMBER 8 - FINISHED ASSEMBLING AND TESTING DISTRIBUTOR, MADE A FLOAT GAUGE AND CHECKED
FLOAT LEVEL

Status: Completed Tech: 12

Job49 NOVEMBER 16 - TECH # 12

Labor: \$115.00

NOVEMBER 16 - INSTALLED REAR BUMPER, INSTALLED AND TIMED DISTRIBUTOR

Status: Completed Tech: 12

Job50 NOVEMBER 19 - TECH # 12

Labor: \$172.50

NOVEMBER 19 - CONTINUED WITH TIMING CARBS

Status: Completed Tech: 12

Job51 NOVEMBER 27 - TECH # 12

Labor: \$57.50

NOVEMBER 27 - INSTALLED NEW IDLE JETS, BEGAN TO CHECK VAC AT INDIVIDUAL INTAKES

----->----->----->---Continued on the next page--->----->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job51 NOVEMBER 27 - TECH # 12

Status: Completed Tech: 12

Job52 NOVEMBER 28 - TECH # 12

Labor: \$172.50

NOVEMBER 28 - CONTINUED WITH DIGANOSING POOR IDLE, CONNECTED IGNITION SCOPE AND CHECKED
IGNITION FIRING--PASS, CHECKED VAC BALANCE--PASS

Status: Completed Tech: 12

Job53 NOVEMBER 30 - TECH # 12

Labor: \$172.50

NOVEMBER 30 - CONTINUED WITH ADJUSTMENT, INSTALLED BIGGER IDLE JETS AND GOT THE IDLE SPEED
TO STABALIZE

Status: Completed Tech: 12

Job54 DECEMBER 3 - TECH # 12

Labor: \$115.00

DECEMBER 3 - CONTINUED WITH DIAGNOSING POOR IDLE, DID A PROPANE ENRICHMENT TEST--FOUND
THAT THROTTLE SHAFT BUSHINGS ARE WORN

Status: Completed Tech: 12

Job55 DECEMBER 10 - TECH # 12

Labor: N/C

DECEMBER 10 - REMOVED CARBS AND HAVE BUSHINGS AND SHAFTS REPLACED

Status: Completed Tech: 12

Job56 DECEMBER 13 - TECH # 12

Labor: \$172.50

DECEMBER 13 - BEGAN CARB DISASSEMBLY, MEASURED SHAFTS AND CHECKED SEALS

Status: Completed Tech: 12

Job57 DECEMBER 13 - TECH # 10

Labor: N/C

DECEMBER 13 - ASSISTED TECH 12 WITH DIASSEMBLY OF CARBS

Status: Completed Tech: 10

Job58 DECEMBER - 4530 MACHINE SHOP

Labor: \$345.00

DECEMBER 24 - MODIFY A FIXTURE ONTO WHICH THE CARBURETORS ARE HELD TO LINE BORE THE
THROTTLE SHAFT HOLES

Status: Completed Tech: 08

----->----->----->-----Continued on the next page-->----->----->----->

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____
Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient. I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

----->----->----->---Continued on the next page--->----->----->----->----->

Fast Cars Ltd

Invoice No.

Page 13

201206036

Order Date 06/19/12 12:24 pm

Completed: 03/27/13 12:42 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Owner or agent _____ Date _____

Payments to Fast Cars Ltd

Cost Summary

Status: Completed Work Order

Payments: \$10,000.00

1 11/27/12 10000.00 AMEX

Labor	9,775.00
Parts	6,287.21
Sublet	369.17
Haz Waste	7.25
Tax	550.13
Total	\$16988.76
Payments	10000.00
Bal Due	6,988.76

Thank you for choosing Fast Cars Ltd

201212042

Order Date 12/28/12 08:14 am

Completed: 03/27/13 12:48 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

78 Ferrari 512 BB RED/BLK

Lic: 4349K/ID 12Cyl 4.9 Eng

Vin: F102BB25525

Eq:

Profile:

Quotes

1 03/27/13 12:49pm 3318.52

MICHEAL in person.

1) INSTALL CARBS

Job01 PARTS

Labor: \$0.00

147636	GASKET, CARB BASE 40MM-N	12.0 @	3.42 =\$	41.04	
460.22.27	WASHER, COPPER 22X27-N	8.0 @	0.67 =\$	5.36	
1F41F52	1/8 DRILL BIT-S	1.0 @	17.91 =\$	17.91	
470.16.32	PIN, COTTER-N	4.0 @	0.80 =\$	3.20	
GAS2	Gasoline 92 Octane-N	5.0 @	4.04 =\$	20.20	
MT-34R	BATTERY, MT34R-N	1.0 @	105.00 =\$	105.00	
74403.075	IDLE JET .075-S	12.0 @	4.75 =\$	57.00	
BGM-H	BOLT, HEX CAP BLK OX-N	6.0 @	0.85 =\$	5.10	
NGW-L	NUT, HEX LOCK-N	6.0 @	0.85 =\$	5.10	
WGM-F	WASHER, FLAT, BLK OX-N	6.0 @	0.81 =\$	4.86	
GAS2	Gasoline 92 Octane-N	10.0 @	3.98 =\$	39.80	
106068	GASKET, CARB-N	12.0 @	13.09 =\$	157.08	461.65

Status: Completed Tech: 02

Job02 4850 SHIPPING

Sublet: \$56.48

DEC-3 T.RUTLANDS
 JAN-14 MCMASTER-CARR
 JAN-16 PIERCE MANIFOLDS

Job03 DECEMBER - 4530 MACHINE SHOP

Labor: \$920.00

DECEMBER 27 - MODIFY THE MANDREL EXTENSIONS FOR THE CARBURETOR LINE BORING

DECEMBER 28 - CAREFULLY MODIFY THE FIRST OF FOUR CARBURETORS AND TEST THE THROTTLE SHAFT
 AND HAVE THE ENGINE TECHNICIAN ASSEMBLE A BUTTERFLY VALVE AND AN END SEAL BEFORE
 CONTINUING WITH THE REMAINING THREE

DECEMBER 31 - COMPLETE THE MODIFICATION OF THE CARBURETOR BASES AND THE OVERSIZED REAMING
 OF THE THROTTLE SHAFT LINE BORES

Status: Completed Tech: 08

Job04 DECEMBER 28 - TECH # 12

Labor: \$115.00

----->----->----->---Continued on the next page--->----->----->----->

201212042

Order Date 12/28/12 08:14 am

Completed: 03/27/13 12:48 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job04 DECEMBER 28 - TECH # 12

DECEMBER 28 = CONTINUED WITH CARB REPAIR, RECEIVED FIRST CARB AND CHECKED OVER

Status: Completed Tech: 12

Job05 JANUARY 2 - TECH # 12

Labor: N/C

JANUARY 2- RECEIVED THE REMAINDER OF THE CARBS AND INSPECTED

Status: Completed Tech: 12

Job06 JANUARY - 4530 MACHINE SHOP

Labor: \$230.00

JANUARY 7 - MODIFY THE PULL ARM HOLES ON THE THROTTLE SHAFT IN THEIR RADIAL POSITIONS TO RECEIVE THE ROLL PIN SECURING DOWELS

JANUARY 9 - MODIFY THE THIRD THROTTLE SHAFT DOWEL HOLE TO POSITION THE RADIAL PULL ARM

JANUARY 10 - MODIFY THE FOURTH THROTTLE SHAFT TO POSITION THE RADIAL PULL ARM

Status: Completed Tech: 08

Job07 JANUARY 7 - TECH # 12

Labor: \$57.50

JANUARY 7 - CONTINUED WITH CARB THROTTLE SHAFT ASSEMBLY

Status: Completed Tech: 12

Job08 JANUARY 8 - TECH # 12

Labor: \$230.00

JANUARY 8 - CONTINUED WORKING ON ASSEMBLING CARBS

Status: Completed Tech: 12

Job09 JANUARY 9 - TECH # 12

Labor: \$115.00

JANUARY 9 - FINISHED CARB ASSEMBLY

Status: Completed Tech: 12

Job10 JANUARY 10 - TECH # 12

Labor: \$287.50

JANUARY 10 - INSTALLED CARBS AND TORQUED DOWN, CONNECTED FUEL LINES AND ADDED 5 GALLONS OF GASOLINE, BALANCED CARBS AND SET FAST IDLE FOR COLD START

Status: Completed Tech: 12

----->----->----->---Continued on the next page--->----->----->----->

201212042

Order Date 12/28/12 08:14 am

Completed: 03/27/13 12:48 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job11 JANUARY 11 - TECH #12

Labor: \$460.00

JANUARY 11 - BEGAN ADJUSTING CARBS. CHECKED FUEL MIXTURE WITH 5 GALLONS AND ANALYZED--MIXTURE IS TOO LEAN, CHANGED IDLE JETS AND RECHECKED FUEL MIXTURE--PASSM REMOVED EXHAUST MUFFLER TO GET ACTUAL READING FROM EACH CARB SET

Status: Completed Tech: 12

Job12 JANUARY 14 - TECH # 12

Labor: \$230.00

JANUARY 14 - TEST DROVE CAR--PASS, INSTALLED EXHAUST MUFFLERS AND AIRBOXES, INSTALLED HEATSHIELD AND DECAL

Status: Completed Tech: 12

Job13 JANUARY 15 - TECH # 12

Labor: \$115.00

JANUARY 15 - INSTALLED AIR FILTER BOX AND BEGAN INSTALLING DECKLID

Status: Completed Tech: 12

Job14 JANUARY 16 - TECH # 12

Labor: N/C

JANUARY 16 - FINISHED INSTALLING DECKLID, TEST DROVE-

Status: Completed Tech: 12

Job15 4815 - DETAILING

Sublet: \$0.00

FEBRUARY 18 - SPRITZ, KLAY WAX, POLISH, CLEAN AND POLISH WHEELS, CLEAN AND DRESS MOTOR, CLEAN INTERIOR, SHAMPOO CARPETS

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

----->----->----->---Continued on the next page--->----->----->----->----->

201212042

Order Date 12/28/12 08:14 am

Completed: 03/27/13 12:48 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient.

I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

Payments to Fast Cars Ltd	Cost Summary	
Status: Completed Work Order	Labor	2,760.00
	Parts	461.65
Payments:	Sublet	56.48
	Tax	40.39
	Total	\$3,318.52
	Payments	0.00
	Bal Due	3,318.52

Thank you for choosing Fast Cars Ltd

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

78 Ferrari 512 BB RED/BLK

Last in 12/28/2012

Lic: 4349K/ID 12Cyl 4.9 Eng

Vin: F102BB25525

Eq:

Profile:

Quotes

1 08/21/13 01:03pm 834.66

MICHEAL in person.

1) recharge ac
 2) detail and prep for pickup
 quoted \$7500
 mats \$500
 tax \$300

Job01 PARTS

Labor: \$0.00

GAS2	Gasoline 92 Octane-N	5.0 @	4.33 =\$	21.65
725268	ING KEY-S	1.0 @	17.98 =\$	17.98
7594940	DOOR KEY-S	1.0 @	17.98 =\$	17.98
891.5020.1	MULTI-SOLVENT-N	4.0 @	6.25 =\$	25.00
119362SG	GASKET SET, 512 BB-S	1.0 @	1300.00 =\$	1300.00
NCBPC-13	CLEANER,PARTS WASH-N	1.0 @	3.23 =\$	3.23
7447	SCOTCH BRITE PAD RED-N	1.0 @	1.68 =\$	1.68
690.8450	BRUSH, STAINLESS-N	1.0 @	3.98 =\$	3.98
H9434	WASHERS, COPPER-S	1.0 @	8.67 =\$	8.67
713695	SPRAY PAINT,DULL ALU S-N	1.0 @	12.25 =\$	12.25
510370	ACETONE-S	1.0 @	13.37 =\$	13.37
SHOP MATERIALS	MISC. SHOP SUPPLIES-N	1.0 @	10.00 =\$	10.00
STD AV7	AIR PUMP CHECK VALVE-S	2.0 @	35.63 =\$	71.26
036.161	DIRKO SILICONE-N	1.0 @	18.00 =\$	18.00
538.3850	CLAMP,HOSE38X50-N	1.0 @	1.81 =\$	1.81
460.22.29	WASHER,COPPER 22X29-N	1.0 @	1.04 =\$	1.04
460.16.22	WASHER,COPPER 6X22-N	2.0 @	0.60 =\$	1.20
465.18.24	WASHER,FIBER 18X24-N	1.0 @	0.39 =\$	0.39
460.12.18	WASHER,COPPER 12X18-N	2.0 @	0.43 =\$	0.86
465.12219	WASHER,FIBER M12X19-N	8.0 @	0.45 =\$	3.60
539.8.12	CLAMP,NORMA 8X12-N	1.0 @	1.72 =\$	1.72
FPN00191993	FILTER, OIL,288,246,27-N	2.0 @	35.00 =\$	70.00
98HP43	OIL, MOBIL 1 15-50W-N	14.0 @	9.62 =\$	134.68
ZX001	COOLANT,ZEREX-N	2.0 @	14.77 =\$	29.54
41530004	FUEL GASKET, 12x22-N	8.0 @	1.45 =\$	11.60
GAS2	Gasoline 92 Octane-N	10.0 @	4.09 =\$	40.90
2556	FLUID, BRAKE LMA CASTR-N	1.0 @	16.11 =\$	16.11
75500.080	ADJUSTABLE LINKAGE-S	2.0 @	22.00 =\$	44.00
NGW-L	NUT, HEX LOCK-N	6.0 @	0.85 =\$	5.10
NGB-F	WASHER,FLAT-N	8.0 @	0.90 =\$	7.20
RI2	FREON-S	2.0 @	55.00 =\$	110.00

----->----->-----Continued on the next page----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job01 PARTS

BGM-H	BOLT, HEX CAP BLK OX-N	4.0 @	0.85 =\$	3.40	
NGB-FW	WASHER, FENDER-N	4.0 @	0.87 =\$	3.48	
FM16	FLOOR MAT SET-S	1.0 @	495.00 =\$	495.00	
GAS2	Gasoline 92 Octane-N	5.0 @	4.04 =\$	20.20	2526.88

Status: Completed Tech: 02

Job02 4820 GENERAL REPAIR

Sublet: \$150.00

JUN-17 EVAC AND RECHARGE A/C SYSTEM, CHECK FOR LEAKS

Job03 4815 - DETAILING

Sublet: \$0.00

JUNE 14 - SPRITZ, CLAY WAX, POLISH WHEELS, CLEAN AND POLISH MOTOR, CLEAN AND DRESS INTERIOR

Job04 JUNE 17 - TECH # 12

Labor: N/C

JUNE 17 - TEST DROVE CAR WITH CUSTOMER AND WENT OVER NEEDED REPAIRS

Status: Completed Tech: 12

Job05 AUGUST 21 - TECH # 12

Labor: \$150.00

AUGUST 21 - BEGAN SERVICE--REMOVED REAR DECKLID AND BUMPER, REMOVED AIRBOXES AND PANELS.

Status: Completed Tech: 12

Job06 AUGUST 26 - TECH # 12

Labor: \$275.00

AUGUST 26 - REMOVED COMPLETE EXHAUST SYSTEM, REMOVED CARBS AND AXLE SHAFTS, DRAINED ALL FLUIDS, REMOVED IGNITION SYSTEM, DISCONNECTED ELECTRICAL, REMOVED CLUTCH BELLHOUSING

Status: Completed Tech: 12

Job07 AUGUST 27 - TECH # 12

Labor: N/C

AUGUST 27 - FINISHED REMOVING MOTOR AND PLACED ON STAND

Status: Completed Tech: 12

Job08 AUGUST 29 - TECH # 44

Labor: \$345.00

AUGUST 29 - REMOVED VALVE COVERS, CAM BELTS AND ALL CAMS, BOTH HEADS ARE STUCK ON, VERY DIFFICULT TIME REMOVING THEM, WAS ABLE TO REMOVE RIGHT SIDE HEAD

Status: Completed Tech: 44

Job09 AUGUST 29 - TECH # 12

Labor: \$115.00

----->----->----->-----Continued on the next page----->----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job09 AUGUST 29 - TECH # 12

AUGUST 29 - ASSISTED TECH 44 WITH ATTEMPTING TO REMOVE STUCK ON CYLINDER HEADS

Status: Completed Tech: 12

Job10 AUGUST 30 - TECH # 12

Labor: N/C

AUGUST 30 - ASSISTED WITH REMOVING LEFT HEAD, HEAD IS STUCK ON

Status: Completed Tech: 12

Job11 AUGUST 30 - TECH # 44

Labor: \$115.00

AUGUST 30 - REMOVED LEFT SIDE HEAD, DIFFICULT REMOVAL AS IT WAS STUCK ON

Status: Completed Tech: 44

Job12 4850 SHIPPING

Sublet: \$121.21

SEP-09 T.RUTLANDS

OCT-16 G.T.CAR PARTS

OCT-21 PIERCE MANIFOLDS

DEC-05 WESTWIND EUROPEAN

Job13 SEPTEMBER 11 - TECH # 12

Labor: N/C

SEPTEMBER 11 - BEGAN CLEANING MOTOR, RECEIVED AND CHECKED PARTS1

Status: Completed Tech: 12

Job14 SEPTEMBER 12 - TECH # 12

Labor: \$200.00

SEPTEMBER 12 - CONTINUED WORKING ON ENGINE BUILD, CLEANED RIGHT BANK DECK SURFACE AND PISTON TOPS ***NOTE*** VISUAL CONCERN ON CYLINDER 7 LINER AND CYLINDER 8 PISTON

Status: Completed Tech: 12

Job15 4820 GENERAL REPAIR

Sublet: \$1,200.00

SEP-12 PROVIDE NEW VALVE GUIDES AND OIL SEALS. INSTALLED GUIDES, VALVE JOB AND RESURFACE HEADS

Job16 SEPTEMBER 17 - TECH # 12

Labor: \$115.00

SEPTEMBER 17 - BEGAN ASSEMBLY

Status: Completed Tech: 12

Job17 SEPTEMBER 20 - TECH # 12

Labor: \$57.50

----->----->----->-----Continued on the next page----->----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job17 SEPTEMBER 20 -TECH # 12

SEPTEMBER 20 - BEGAN FITTING AND MODIFYING GASKETS

Status: Completed Tech: 12

Job18 SEPTEMBER 24 - TECH # 12

Labor: \$200.00

SEPTEMBER 24 - INSTALLED AND TORQUED HEADS, INSTALLED CAMS ON LEFT BANK, BEGAN REPAIRING THREADS FOR BOLT ON BELT TENSIONER

Status: Completed Tech: 12

Job19 SEPTEMBER 25 - TECH # 12

Labor: \$100.00

SEPTEMBER 25 - BEGAN INSTALLING CAM ASSEMBLY

Status: Completed Tech: 12

Job20 SEPTEMBER 26 -TECH # 12

Labor: \$200.00

SEPTEMBER 26 - REPAIRED THREADS ON BLOCK, FINISHED INSTALLING CAMS ON LEFT BANK

Status: Completed Tech: 12

Job21 SEPTEMBER 27 - TECH # 12

Labor: \$200.00

SEPTEMBER 27 - BEGAN CHECKING VALVE LASH AND LEAKDOWN, INSTALLED CAMS AND TIMING BELT ON RIGHT BANK

Status: Completed Tech: 12

Job22 SEPTEMBER 30 - TECH # 12

Labor: \$250.00

SEPTEMBER 30 - FINISHED ADJUSTING VALVE LASH, DEGREED CAMS ON BOTH BANKS, TORQUED EVERYTHING DOWN AND INSTALLED VALVE COVERS, INSTALLED TIMING COVERS AND ALTERNATOR BELT

Status: Completed Tech: 12

Job23 OCTOBER 1 - TECH # 12

Labor: \$200.00

OCTOBER 1 - INSTALLED MOTOR INTO CAR AND BEGAN CONNECTING ALL PARTS

Status: Completed Tech: 12

Job24 OCTOBER 8 - TECH # 12

Labor: \$100.00

OCTOBER 8 - CONTINUE WORKING ON ASSEMBLY OF ENGINE

Status: Completed Tech: 12

----->----->----->---Continued on the next page--->----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job25 OCTOBER 9 - TECH # 12**Labor: \$200.00**

OCTOBER 9 - CONTINUED WITH ENGINE ASSEMBLY, CONNECTED AND TORQUED AXLE SHAFTS, LEFT BANK CARBS, A/C COMPRESSOR, HOSES AND SHIFT LINKAGE

Status: Completed Tech: 12

Job26 OCTOBER 10 - TECH # 12**Labor: \$200.00**

OCTOBER 10 - CONTINUED WITH ASSEMBLY OF ENGINE, INSTALLED AND TORQUED CLUTCH HOUSING, RIGHT BANK CARBS AND COOLANT LINES

Status: Completed Tech: 12

Job27 OCTOBER 11 - TECH # 12**Labor: \$150.00**

OCTOBER 11 - CONTINUED WITH ASSEMBLY OF ENGINE, INSTALLED DISTRIBUTOR AND BEGAN INSTALLING WIRES

Status: Completed Tech: 12

Job28 OCTOBER 15 - TECH # 12**Labor: \$200.00**

OCTOBER 15 - ISNTALLED FUEL LINES, EXHAUST SYSTEM, PANELS, DISTRIBUTOR CAP AND WIRES

Status: Completed Tech: 12

Job29 OCTOBER 16 - TECH # 12**Labor: \$200.00**

OCTOBER 16 - ADDED FLUIDS, BLED COOLING SYSTEM, RAN CAR TO OPERATING TEMPERATURE AND BEGAN ADJUSTING CARBS

Status: Completed Tech: 12

Job30 OCTOBER 18 - TECH # 12**Labor: \$200.00**

OCTOBER 18 - RAN CAR TO OPERATING TEMPERATURE AND CHECKED FOR LEAKS--NO LEAKS, BEGAN ADJUSTING CARBS - ORDERED PROPER ADJUSTABLE LINKAGE FOR THROTTLE

Status: Completed Tech: 12

Job31 OCTOBER 21 - TECH # 12**Labor: N/C**

OCTOBER 21 - INSTALLED NEW LINKAGE

Status: Completed Tech: 12

Job32 OCTOBER 22 - TECH # 12**Labor: N/C**

----->----->----->---Continued on the next page--->----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job32 OCTOBER 22 - TECH # 12

OCTOBER 22 - ADJUSTED FUEL MIXTURE AND FAST IDLE, TEST DROVE CAR--PASS, INSTALLED BUMPER AND REAR DECKLID

Status: Completed Tech: 12

Job33 OCTOBER 23 - TECH # 12

Labor: \$100.00

OCTOBER 23 - ADDED 5 GALLONS OF FUEL TO CAR, INSTALLED AIRBOXES AND CONNECTED, TEST DROVE CAR--PASS, INSTALLED REAR BUMPER

Status: Completed Tech: 12

Job34 4820 GENERAL REPAIR

Sublet: \$150.00

OCT-25 REMOVE FREON, EVAC AND RECHARGE A/C SYSTEM, CHECK FOR LEAKS.

Job35 4820 GENERAL REPAIR

Sublet: \$5.37

OCT-25 GET (2) NEW KEYS CUT

Job36 OCTOBER 25 - TECH # 12

Labor: N/C

OCTOBER 25 - TEST DROVE CAR--PASS

Status: Completed Tech: 12

Job37 OCTOBER 29 - TECH # 12

Labor: N/C

OCTOBER 29 - RAN CAR TO OPERATING TEMPERATURE AND TOPPED OFF FLUIDS, BEGAN TO REMOVE DOOR PANEL

Status: Completed Tech: 12

Job38 NOVEMBER 4 - TECH # 12

Labor: N/C

NOVEMBER 4 - BEGAN REMOVING DOOR PANEL, RESEARCHED SLOW WINDOW REPAIR

Status: Completed Tech: 12

Job39 NOVEMBER 6 - TECH # 12

Labor: \$115.00

NOVEMBER 6 - DRILLED OUT RIVETED PANEL ON PASSENGER DOOR, LUBED AND INSPECTED WINDOW PULLEY, CHECKED WINDOW OPERATION--FAILED, GETS STUCK IN CERTAIN SECTION, REMOVED ASSEMBLY AND DISASSEMBLED MOTOR PULLEY, CLEANED, LUBED AND REASSEMBLED, TESTED--FAILED, STILL GETTING STUCK, DISASSEMBLED AGAIN AND INSPECTED THOROUGHLY--FOUND A DEFECTIVE GEAR--NEEDS REPLACEMENT

Status: Completed Tech: 12

----->----->----->-----Continued on the next page----->----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job40 NOVEMBER 7 - TECH # 12

Labor: N/C

NOVEMBER 7 - BEGAN CLEANING GEARS ON WINDOW MOTOR

Status: Completed Tech: 12

Job41 NOVEMBER 15 - TECH # 12

Labor: \$172.50

NOVEMBER 15 - CLEANED ALL GREASE OFF OF GEAR ASSEMBLY, ADDED A SPECIAL CUTTING PASTE TO ALL THE GEARS AND ASSEMBLED, RAN GEAR ASSEMBLY FOR SEVERAL MINUTES UNTIL CLEARANCING ISSUE WAS RESOLVED, CLEANED AND LUBRICATED ALL PARTS AND ASSEMBLED COMPLETE SYSTEM, INSTALLED, ADJUSTED AND TESTED WINDOW OPERATION---PASS

Status: Completed Tech: 12

Job42 NOVEMBER 20 - TECH # 12

Labor: \$115.00

NOVEMBER 20 - INSTALLED DOOR PANEL ASSEMBLY

Status: Completed Tech: 12

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient. I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

----->----->----->---Continued on the next page--->----->----->----->

201306033

Order Date 06/17/13 12:12 pm

Completed: 01/08/14 02:03 pm

Ref: transfered to a/p no add

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

Payments to Fast Cars Ltd**Cost Summary**

Status: Completed Work Order

Payments:

Labor	4,275.00
Parts	2,526.88
Sublet	1,626.58
Haz Waste	16.25
Tax	227.42
Total	\$8,672.13
Payments	0.00
Bal Due	8,672.13

Thank you for choosing Fast Cars Ltd

201506036

Order Date 06/19/15 02:01 pm

Paid: 07/30/15 02:43 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

78 Ferrari 512 BB RED/BLK
 Last in 6/17/2013
 Lic: 4349K/ID 12Cyl 4.9 Eng
 Vin: F102BB25525
 Eq:

Quotes

1 06/23/15 03:10pm 0.00
 MICHEAL in person.

- 1) QUOTE TO REUPHOLSTER SEATS WITH RED DAYTONA INSERTS
 2) QUOTE TO REPAIR REAR BUMPER

Job01 PARTS

Labor: \$0.00

SHOP MATERIALS	MISC. SHOP SUPPLIES-N	1.0 @	10.00 =\$	10.00	
PH2804-1 FRAM	FILTER, Ferrari 330-30-N	2.0 @	31.89 =\$	63.78	
98HP43	OIL, MOBIL 1 15-50W-N	13.0 @	9.62 =\$	125.06	
893.25.503	HOSE, 5/16 FUEL-N	4.0 @	1.25 =\$	5.00	203.84

Status: Completed Tech: 02

Job02 4810 BODY WORK

Sublet: \$1,177.00

JULY 8 - REMOVE REAR BUMPER , REPAIR BUMPER AND REPAINT. INSTALL

Job03 JULY - TECH # 05

Labor: \$140.00

JULY 9 - PICK UP THE BUMPER FROM THE BODY SHOP IN ORANGE

Status: Completed Tech: 05

Job04 JULY 15 - TECH # 62

Labor: \$312.50

JULY 15 - OIL AND FILTER SERVICE, INSPECT CAR

Status: Completed Tech: 62

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the

----->----->----->---Continued on the next page--->----->----->----->

201506036

Order Date 06/19/15 02:01 pm

Paid: 07/30/15 02:43 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

automobiles nor the long term nature of the work performed by this company. Therefor there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient. I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk. I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

Payments to Fast Cars LtdCost Summary

Status: Paid Work Order

Payments: \$1,858.19

1 07/30/15 1858.19 AMEX

Labor	452.50
Parts	203.84
Sublet	1177.00
Haz Waste	6.50
Tax	18.35
Total	\$1858.19
Payments	1858.19
Bal Due	0.00

Thank you for choosing Fast Cars Ltd

201510028

Order Date 10/21/15 02:09 pm

Completed: 10/30/15 12:18 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

78 Ferrari 512 BB RED/BLK

Last in 6/19/2015

Lic: 4349K/ID 12Cyl 4.9 Eng

Vin: F102BB25525

Eq:

Quotes

1 10/30/15 03:40pm 350.00

MICHEAL in person.

1) FULL DETAIL

Job01 4815 DETAILING**Sublet: \$350.00**

OCT 21 - SPRITZ, CLAY, WAX & POLISH

WHEELS CLEANED & WAXED

MOTOR CLEANED & POLISHED

INTERIOR CLEANED AND SEATS OILED (3 COATS)

INV#988037

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient.

I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of

----->----->----->---Continued on the next page--->----->----->----->

201510028

Order Date 10/21/15 02:09 pm

Completed: 10/30/15 12:18 pm

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

Payments to Fast Cars Ltd

Cost Summary

Status: Completed Work Order

Labor 0.00

Parts 0.00

Payments:

Sublet 350.00

Total \$350.00

Payments 0.00

Bal Due 350.00

Thank you for choosing Fast Cars Ltd

201606052

Order Date 06/20/16 02:13 pm
Completed: 08/17/16 10:55 am

TRANSFERED TO A/P NO ADD

BAR #: AK105357
630 Mary Ann Drive
Redondo Beach, Ca 90278
Phone: 310-937-6700 FAX: 310-376-3392*Replace dash.*

78 Ferrari 512 BB RED/BLK

Quotes

Last in 10/21/2015

Lic: 4349K/ID 12Cyl 4.9 Eng

Vin: F102BB25525

Eq:

1 08/17/16 10:55am 7800.38

MICHEAL in person.

Job01 PARTS

Labor: \$0.00

DASH MATERIAL	UPHOLSTERY-S	1.0 @ 1500.00	= \$ 1500.00
7856K73	SHRINK TUBING 1/8"-N	1.0 @ 0.66	= \$ 0.66
7856K741	SHRINK TUBE 3/16"-N	1.0 @ 1.09	= \$ 1.09
881.9012	TIE, 14.50" BLACK-N	5.0 @ 0.16	= \$ 0.80
773.02.14	WIRE, 14 GA RED-N	6.0 @ 0.35	= \$ 2.10
730.925	FUSE, CERAMIC 25AMP-N	1.0 @ 0.29	= \$ 0.29 1504.94

Status: Completed Tech: 02

Job02 JUNE 21 - TECH # 48

Labor: \$280.00

JUNE 21 - BEGAN REMOVAL OF DASHBOARD

Status: Completed Tech: 48

Job03 JUNE 22 - TECH # 48

Labor: \$280.00

JUNE 22 - FINISH REMOVAL OF DASH AFTER DROPPING DOWN STEERING COLUMN AND REMOVAL OF A-PILLARS AND FILLER PANELS

Status: Completed Tech: 48

Job04 JULY 5 - TECH # 48

Labor: \$140.00

JULY 5 - GO OVER DASHBOARD, INSPECT AND ENSURE QUALITY

Status: Completed Tech: 48

Job05 JULY 8 - TECH # 48

Labor: \$70.00

----->----->----->-----Continued on the next page----->----->----->----->

201606052

Order Date 06/20/16 02:13 pm

Completed: 08/17/16 10:55 am

TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Job05 JULY 8 -TECH # 48

JULY 8 - VACUUM THE DASH STRUCTURE AND STRIP BACK OLD FOAM THAT SEALS THE VENTS

Status: Completed Tech: 48

Job06 4870 UPHOLSTERY

Sublet: \$3,500.00

JULY 7 - RECOVER COMPLETE DASH & KICK PANLES.
INV# 6732

Job07 JULY 12 - TECH # 48

Labor: \$420.00

JULY 12 - REASSEMBLE OIL PRESSURE GAUGE, INSTALL NEW FOAM AND TOP HALF OF DASHBOARD,
INSTALL MAIN DASH BOARD AND ASSEMBLE STEERING COLUMN, NOT SATISFIED WITH FITMENT AND
FINISH IN CAR -- WILL REMOVE TO MAKE ADJUSTMENTS

Status: Completed Tech: 48

Job08 JULY 15 - TECH # 48

Labor: \$630.00

JULY 15 - REASSEMBLE THE REST OF THE DASH, CHECK ALL GAUGES AND CONTROLS FOR PROPER
FUNCTION, MODIFY 16 NUTS TO ALLOW FOR PROPER SECURING OF A-PILLAR PANELS AN DSIDE FILL
PANELS, HORN IS NOT WORKING AND WIPER MOTOR/ARM APPEARS TO BE STRIPPED

Status: Completed Tech: 48

Job09 JULY 27 - TECH # 66

Labor: \$140.00

JULY 27 - CONFIRMED HORN IS INOPERABLE, CHECKED HORN PUMP AND VERIFIED IT IS FUNCTIONAL,
CHECKED HORN SWITCH -- PASS, CONFIRMED HORN RELAY IS OPERATIONAL, FOUND SHORT TO GROUND
FROM FUSE TO RELAY

Status: Completed Tech: 66

Job10 JULY 28 - TECH # 66

Labor: \$420.00

----->----->----->---Continued on the next page--->----->----->----->

201606052

Order Date 06/20/16 02:13 pm

Completed: 08/17/16 10:55 am

TRANSFERED TO A/P NO ADD

BAR #: AK105357
630 Mary Ann Drive
Redondo Beach, Ca 90278
Phone: 310-937-6700 FAX: 310-376-3392

Job10 JULY 28 - TECH # 66

JULY 28 - CHECKED WIRES AT FUSE AND FOUND 5 WIRES, 2 OF THE WIRES GOING TO ONE OF THE CONNECTORS RAN FROM HORN RELAY AND CLOCK CIRCUIT, ISOLATED HORN CIRCUIT AND FOUND SHORT TO BE COMING FROM CLOCK CIRCUIT, TRACED WIRING DIAGRAM AND FOUND TRUNK LIGHT AND CLOCK TO RUN IN SERIES, REMOVED TACHOMETER TO ACCESS CLOCK, ISOLATED ALL CIRCUITS AND FOUND SHORT TO BE FROM FUSE TO CLOCK, REWIRED SYSTEM, REASSEMBLED CAR, CONFIRMED CLOCK, TRUNK LIGHT AND HORN ARE ALL FULLY FUNCTIONAL

Status: Completed Tech: 66

Job11 JULY 29 - TECH # 66

Labor: \$280.00

JULY 29 - TOOK CAR ON TEST DRIVE -- FOUND THAT TURN SIGNALS ARE INOPERABLE, CHECKED FUSE -- PASS, CONFIRMED FLASHER IS FULLY FUNCTIONAL, REMOVE STEERING WHEEL TO ACCESS TURN SIGNAL ASSEMBLY, INSPECTED ALL WIRING -- FOUND LOOSE CONNECTION AT CONNECTOR, RESECURED CONNECTION, REASSEMBLE CAR AND VERFIED TURN SIGNAL SYSTEM IS OPERATING AS PER DESIGN

Status: Completed Tech: 66

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient.

I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree

----->----->----->---Continued on the next page--->----->----->----->

201606052

Order Date 06/20/16 02:13 pm

Completed: 08/17/16 10:55 am

TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

repairs. Therefore I agree that this estimate is an approximation of the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

Payments to Fast Cars Ltd

Cost Summary

Status: Completed Work Order

Payments:

Labor	2660.00
Parts	1504.94
Sublet	3500.00
Tax	135.44
Total	\$7800.38
Payments	0.00
Bal Due	7800.38

Thank you for choosing Fast Cars Ltd

201811030

Order Date 11/14/18 04:21 pm
Closed/Paid: 11/21/18 09:51 am

TRANSFERED TO A/P NO ADD

BAR #: AK105357
630 Mary Ann Drive
Redondo Beach, Ca 90278
Phone: 310-937-6700 FAX: 310-376-3392

5/12

78 Ferrari 512 BB RED/BLK

Quotes

Last in 11/14/2018

1 11/20/18 09:29am 564.00

Lic: 4349K/ID 12Cyl 4.9 Eng

MICHEAL in person.

Vin: F102BB25525

Eq:

- 1) PREP CAR FOR PICKUP
- 2) DETAIL CAR

Job01 4815 DETAILING

Sublet: \$300.00

PERFORM FULL DETAIL OF VEHICLE

Job02 NOVEMBER TECH # 12

Labor: \$217.50

PICKUP CAR FROM STORAGE BUILDING AND CHECK OVER. RUN TO TEMP AND ADD 10 GALLONS OF GAS.
CHECK LIGHTS AND BATTERY CONDITION = PASS

GAS2	Gasoline 92 Octane-N	10.0 @	3.79 =\$	37.90	37.90
------	----------------------	--------	----------	-------	-------

Status: Completed Tech: 12

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient.

I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

----->----->----->---Continued on the next page--->----->----->----->

201811030

Order Date 11/14/18 04:21 pm
Closed/Paid: 11/21/18 09:51 am

TRANSFERED TO A/P NO ADD

BAR #: AK105357
630 Mary Ann Drive
Redondo Beach, Ca 90278
Phone: 310-937-6700 FAX: 310-376-3392

restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

Payments to Fast Cars Ltd

Cost Summary

Status: Closed Work Order

Payments: \$564.00

1 11/21/18 564.00 Visa

Labor	217.50
Parts	37.90
Sublet	300.00
Haz Waste	5.00
Tax	3.60
Total	\$564.00
Payments	564.00
Bal Due	0.00

Thank you for choosing Fast Cars Ltd

202106018

Order Date 06/08/21 03:16 pm

Closed/Paid: 11/02/21 11:47 am

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

78 Ferrari 512 BB RED/BLK
 Last in 6/8/2021
 Lic: 4349K/ID 12Cyl 4.9 Eng
 Vin: F102BB25525
 Eq:

Quotes

1 11/02/21 10:58am 1867.38

MICHEAL in person.

- 1) SERVICE
- 2) CHANGE BATTERY AND ALTERNATOR
- 3) DETAIL AND PREP FOR SALE

Job01 PARTS

Labor: \$0.00

MT-34R	BATTERY, MT34R-N	1.0 @	150.66 =\$	150.66	
PH2804-1 FRAM	FILTER, Ferrari-N	2.0 @	31.89 =\$	63.78	
122377	15-50W OIL-S	14.0 @	12.14 =\$	169.96	384.40

Status: Completed Tech: 02

Job02 OCTOBER 7 - TECH#77

Labor: \$160.00

OCT 7 - INSPECT VEHICLE FOR SALE. BATTERY KEEPS GOING FLAT EVEN WHEN ON TENDER. BATTERY CELLS BAD, RECOMMEND NEW BATTERY. ALTERNATOR IS ALSO NOT CHARGING. DISCUSS WITH MANAGER

Status: Completed Tech: 02

Job03 OCTOBER 8 - TECH#77

Labor: \$480.00

OCT 8 - SERVICE. OIL/FILTER. CHECK TIRE PRESSURES AND ALL FLUIDS
 ALTERNATOR REMOVAL FOR REBUILD

Status: Completed Tech: 02

Job04 4845 REBUILD

Sublet: \$325.00

OCT-11 REBUILD ALTERNATOR

Job05 OCTOBER 11 - TECH#77

Labor: \$480.00

OCT 11 - ALTERNATOR INSTALL. INSTALL NEW BATTERY RUN AND TEST

Status: Completed Tech: 02

Job06 4815 DETAILING

Sublet: \$350.00

DETAIL VEHICLE

I agree to pay reasonable attorney fees if legal action becomes necessary to enforce

----->----->----->-----Continued on the next page----->----->----->----->

202106018

Order Date 06/08/21 03:16 pm

Closed/Paid: 11/02/21 11:47 am

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

collection of debt. All warranties on products sold hereby are those made by the manufacturer. Fast Cars Ltd. hereby expressly disclaims all warranties, either expressed or implied, including implied warranty of merchantability or fitness for any items on this invoice. Should I Choose to use Visa/Master card or American Express for payment of this invoice, it is understood that I will be responsible for any credit card processing fees.

Work accepted by _____ Date _____

Fast Cars, Ltd. offers service & restoration for the most unique, complex & expensive automobiles made. The business philosophy of this company is to offer the highest standard of work available without compromise. The guidelines of the State of California, Consumer Protection Act covering automotive repair were drafted to cover main stream automotive repair & do not take into consideration the unique characteristics of the automobiles nor the long term nature of the work performed by this company. Therefore there are unique stipulations imposed by Fast Cars, Ltd.

As the owner or authorized agent of the above referenced automobile, I authorize the repair or restoration work detailed above, along with the necessary parts & materials. I also request the examination of any system that may appear to be deficient.

I acknowledge the unique hand built nature of my automobile & understand that it is impossible for Fast Cars, Ltd. to estimate the exact cost of repairs. Therefore I agree that this estimate is an approximation of charges & is not a binding absolute ceiling to the final cost of repairs or restoration.

I acknowledge that the extraordinary value of my vehicle dictates that I maintain full liability & comprehensive insurance coverage while my vehicle is in possession of Fast Cars, Ltd. I understand that my insurance is the primary coverage & therefore I will not hold Fast Cars, Ltd. responsible for loss or damage to the vehicle or it's contents, in the case of accident, fire, theft, or any other cause beyond reasonable control. I authorize the employees of Fast Cars, Ltd. to operate my vehicle for the purposes of testing, inspection or delivery at my sole risk.

I acknowledge an expressed mechanics lien on this vehicle to secure payment to Fast Cars, Ltd. in the full amount due for repairs. I agree to pay reasonable attorney's fees if legal action becomes necessary to enforce the collection of debt. I agree to pay any difference between the total cost of repairs & payments made by my insurance company. Billing will be sent out on the completion of, biweekly or monthly basis dependant on the duration & work load. Billing is due & payable on receipt, absolutely no term applies. Interest, calculated at 10% per year will be charged on an unpaid balance. Storage at \$50.00 per day will be charged, beginning the day after notification

I take full responsibility for the operation of my high performance or racing car, acknowledging the dangers of operation therein & the potentially lethal consequences.

Owner or agent _____ Date _____

----->----->----->---Continued on the next page--->----->----->----->

202106018

Order Date 06/08/21 03:16 pm

Closed/Paid: 11/02/21 11:47 am

Ref: TRANSFERED TO A/P NO ADD

BAR #: AK105357

630 Mary Ann Drive

Redondo Beach, Ca 90278

Phone: 310-937-6700 FAX: 310-376-3392

Payments to Fast Cars Ltd	Cost Summary
Status: Closed Work Order	Labor 1120.00
	Parts 384.40
Payments: \$2,217.38	Sublet 675.00
1 11/02/21 2217.38 Visa	Haz Waste 1.46
	Tax 36.52
	Total \$2217.38
	Payments 2217.38
	Bal Due 0.00

Thank you for choosing Fast Cars Ltd