

CUSTOMER #: 504388
UNIT# 211P174



INVOICE

Michael Stead Porsche
2555 North Main Street
Walnut Creek, CA 94597

PAGE 1

(925) 280-4900
Fax: (925) 280-4912
www.steadporsche.com

SERVICE ADVISOR: 379 ERIC SCHAEFER

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
LM5B-33	11	PORSCHE 911 SPEEDSTE	WP0CB2A91BS795566	46356	433/433	SPDSTR	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
15MAR11	DD26JAN11	15MAR2015	WAIT 20SEP11			CASH	20SEP11
R.O. OPENED		READY	OPTIONS: STK:211P174 DLR:146				
13:07 20SEP11		16:56 20SEP11					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PERFORM CAMPAIGN WB25 - RE-CODE INSTRUMENT CLUSTER

CAUSE: workshop campaign

WB25 PERFORM CAMPAIGN WB25 - RE-CODE INSTRUMENT
CLUSTER

770 WP95

(N/C)

FC: WB25 PART#: COUNT:

CLAIM TYPE: r

AUTH CODE:

,,,433 WB25 0.30 Completed WB25 campaign.

B please replace visors as directed (sop's) - see attached work
instructions for WWS submission

CAUSE: 1211

68232010 sun visors removed and reinstalled

770 WP95

(N/C)

FC: 6823 PART#: COUNT:

CLAIM TYPE: 2

AUTH CODE:

,,,433 sop visor 0.30 Replaced both visors.

C please install license plates, including FP-type front plate bracket

88 *DETACH PANEL WORK

786 INEP

(N/C)

1 FPLATE MOUNT

(N/C)

BAR# AK196618 EPA# 000102813

Original Estimate \$

Please read the important information on the reverse side
invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional
warranty repairs discovered and corrected during this
repair visit.

Signature X

I acknowledge notice and oral approval of an increase in
the original estimate price.

Initials X

**MICHAEL
STEAD
PORSCHE**

2555 NORTH MAIN STREET
WALNUT CREEK, CA 94597
(925) 280-4900

BAR# ARD-196618 EPA# CAL000302147

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INS/ADJ.	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00



PORSCHE

Michael Stead Porsche
2555 North Main Street
Walnut Creek, CA 94597

(925) 280-4900
Fax: (925) 280-4912

MICHAEL STEAD PORSCHE WILL ACCEPT PARTS FOR REFUND OR EXCHANGE PROVIDED THE PART IS A NORMALLY STOCKED NON-ELECTRICAL OR CARBURETOR PART PURCHASED WITHIN 5 DAYS AND IS ACCOMPANIED BY THIS INVOICE. ALL PARTS ACCEPTED FOR RETURN MUST MEET THE MANUFACTURER'S CURRENT PACKAGE GUIDELINES AND ARE SUBJECT TO A 20% RESTOCKING CHARGE. SPECIAL ORDERED ITEMS NOT PICKED UP WITHIN 60 DAYS WILL BE RETURNED TO NORMAL STOCK.

SUBJECT TO WARRANTY TERMS AND CONDITIONS LISTED ON REVERSE SIDE.

DATE ENTERED	YOUR ORDER NO.	DATE SHIPPED	INVOICE DATE	INVOICE NUMBER
26 APR 11		26 APR 11	26 APR 11	93752

S
O
L
D

T
O

S
H
I
P

T
O

PAGE 1 OF 1

SHIP VIA			SLSM.	B/L NO.	TERMS	F.O.B. POINT	
			792			WALNUT CREEK CA	
QTY	SHIP	B.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	911-095-932-20-M5B	PAINT TOUC	23.79	23.79	23.79
CHARGE AC# 402 APR 26 2011 MICHAEL STEAD PORSCHE							
					PARTS		23.79
					SUBLET		
					FREIGHT		0.00
					SALES TAX		2.20
					TOTAL		\$25.99
CUSTOMER'S SIGNATURE							
X							

**THANK
YOU
FOR
YOUR
BUSINESS!**



132723

CUSTOMER #: 504388

UNIT# 211P174

PORSCHE

INVOICE

Michael Stead Porsche
2555 North Main Street
Walnut Creek, CA 94597

PAGE 1

(925) 280-4900
Fax: (925) 280-4912
www.steadporsche.com

SERVICE ADVISOR: 806 ENRIQUE ESCANO

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
LM5B-33	11	Porsche 911 SPEEDSTE		WP0CB2A91BS795566		46356	795/796		T412
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
15MAR11	DD26JAN11	15MAR2015	17:00 26APR13				CASH	30APR13	
R.O. OPENED		READY		OPTIONS: STK:211P174 DLR:146					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	PERFORM SERVICE CAMPAIGN WB26	REWORKING CONVERTIBLE TOP (SOP PARTS IN STOCK)					

CAUSE: WC

00 CAMPAIGN WB26

768 WP95

(N/C)

1 997-567-939-01 R-KIT ROOFLINER

(N/C)

2 997-567-943-00 R-KIT ROOFLINER

(N/C)

1 997-567-934-00 F-KIT TENSION CABLE,

(N/C)

1 997-567-936-00 R-KIT BELT STRAP, CO

(N/C)

00 REPAIRING HEADLINER

768 WP95

(N/C)

FC: WB26 PART#: COUNT:

CLAIM TYPE: R

AUTH CODE:

,,, 795 PERFORMED CAMPAIGN WB26 SCOPE 1

B CUSTOMER REQUEST TO INSTALL SUPPLIED FRONT MARKER LIGHT ASSEMBLIES

00 * GENERAL SERVICING

768 CP

0.00

0.00

C** please apply Xpel cleaner/sealant as nec for PPF

CA INSTALL CLEAR PAINT PROTECTION

783 CP

0.00

0.00

,,, 795 CLEANED PAINT PROTECTION FILM AND APPLIED SEALANT.

D** svc indicator on, due for biannual minor maintenance & brake system flush.

WD * OWNER ADVISED & WORK DECLINED AT THIS TIME

768 CP

0.00

0.00

,,, 795 NO WORK PERFORMED

E** WHILE PERFORMING WB26 SERVICE CAMPAIGN FOUND HEADLINER TENSION ROPE BROKEN

Original Estimate

\$

Please read the important information on the reverse side invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.☐ I acknowledge notice and oral approval of additional warranty repairs discovered and corrected during this repair visit.

Signature X

I acknowledge notice and oral approval of an increase in the original estimate price.

Initials X

**MICHAEL
STEAD
PORSCHE**

2555 NORTH MAIN STREET
WALNUT CREEK, CA 94597
(925) 280-4900

BAR# ARD-196618 EPA# CAL000302147

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INS/ADJ.	
SALES TAX	
PLEASE PAY THIS AMOUNT	



132723

CUSTOMER #: 504388

UNIT# 211P174

PORSCHE

INVOICE

Michael Stead Porsche
2555 North Main Street
Walnut Creek, CA 94597

PAGE 2

(925) 280-4900
Fax: (925) 280-4912
www.steadporsche.com

SERVICE ADVISOR: 806 ENRIQUE ESCANO

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
LM5B-33	11	Porsche 911 SPEEDSTE		WP0CB2A91BS795566		46356	795/796		T412
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
15MAR11	DD26JAN11	15MAR2015	17:00 26APR13				CASH	30APR13	
R.O. OPENED		READY		OPTIONS: STK:211P174 DLR:146					

15:31 26MAR13	11:12 30APR13						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

CAUSE: REPAIR HEADLINER

61091910 CONVERTIBLE TOP ROOFLINER REMOVED+REINST

768 WP95

(N/C)

00 REPAIRING HEADLINER

768 WP95

(N/C)

FC: 6109 PART#: COUNT:

CLAIM TYPE: 2

AUTH CODE:

,,, 795 FOUND CONVERTIBLE TOP HEADLINER INTERIOR SIDE STRAP TORN
 ,,,, CAUSING HEADLINER TO BECOME LOOSELY FITTED. R AND R HEADLINER. REPAIRED
 ,,,, TORN TENSION CORD. INSTALLED ALL AND TESTED ALL OKAY AT TIME.

BAR# AK196618 EPA# 000102813

Original Estimate

\$

Please read the important information on the reverse side
invoice!

I acknowledge receipt of this invoice.

☐ I acknowledge the warranty repairs performed.

☐ I acknowledge notice and oral approval of additional
warranty repairs discovered and corrected during this
repair visit.

Signature X _____

I acknowledge notice and oral approval of an increase in
the original estimate price.

Initials X _____

**MICHAEL
STEAD
PORSCHE**

2555 NORTH MAIN STREET
WALNUT CREEK, CA 94597
(925) 280-4900

BAR# ARD-196618 EPA# CAL000302147

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INS/ADJ.	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

Porsche Walnut Creek

Fletcher Jones Porsche Walnut Creek
2555 North Main Street
Walnut Creek, California, 94597, US
Phone: (925) 280-4900

Repair Order #: 203229
Tag #: T836
Advisor: John Kim
Advisor No. #: 740841
Order Open Date: 2023-10-23

Customer Information**Vehicle Information**

2011 PORSCHE 911 SPEEDSTER

VIN #: WP0CB2A91BS795566
Color #: LM5B-33
Mileage In/Out #: 1558/1558

Job # A

Labor Total: \$ 600.00

CLIENT REQUESTS TO HAVE THE XPEL REMOVED

Cause:

Correction(s):

99 MISCELLANEOUS

\$600.00

Tech Number: 740834 Labor Type: CP

Part Number	Part Description	Qty	List
-------------	------------------	-----	------

Parts Total: \$ 0.00

1558 REMOVED XPEL PER REQUEST.

Misc Total: No Charge

Job # A Total

\$ 600.00

Job # B

Labor Total: \$ 0.00

CHECK TIRES PRESSURES, SET TIRE PRESSURES, FRONT ___psi, REAR ___psi

Cause:

Correction(s):

40POZ-TP CHECK TIRES PRESSURES, SET TIRE PRESSURES,
FRONT ___psi, REAR ___psi

\$0.00

Tech Number: 740834 Labor Type: CP

Part Number	Part Description	Qty	List
-------------	------------------	-----	------

Parts Total: \$ 0.00

1558 SET TO SPEC

Misc Total: No Charge

Porsche Walnut Creek

A PORSCHE LONG BEACH COMPANY

Fletcher Jones Porsche Walnut Creek

2555 North Main Street

Walnut Creek, California, 94597, US

Phone: (925) 280-4900

Repair Order #: 203229

Tag #: T836

Advisor: John Kim

Advisor No. #: 740841

Order Open Date: 2023-10-23

Job # B Total**\$ 0.00****RO Comments**

Edward Baker 836

Amount Totals

Total Labor: \$ 600.00

Total Parts: \$ 0.00

Miscellaneous + Discounts: \$ 0.00

Sales Tax: \$ 0.00

Shop Supplies: \$ 0.00

Customer Total:**\$ 600.00****Terms and Acceptance**

Customer acknowledges approval of work described in this Repair Order Summary. Any Warranties on the product sold herein are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Please look for a survey on your service experience. The manufactures survey will be sent to you by email. If you are not sure if your current email address is on file please check with your service advisor.

We're working hard to make customers for life!



Customer acknowledges receipt of copy.