

Linos Mercedes Service

74875 Hovley Lane East
 Palm Desert, CA. 92260
 Phone - 760-773-4707 Fax - 760-776-5084
 We are Your Dealership Alternative

INVOICE

18071

Org. Est. # 037102
 BAR - AD 166439
 EPA ID - CAL00219619

INVOICE

Print Date : 11/11/2014

1970 Mercedes-Benz - 280SEL - 2.8

Lic # : MCM - CA

Odometer In : 71391

Unit # :

Vin # : **111.027-12-003095**

Hat # :

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
OIL FILTER KIT 000 180 00 09	1.00	11.00	11.00	OIL AND FILTER CHANGE engine oil and filter change	0.50	47.50
ENGINE OIL 20W50	8.50	5.00	42.50	inspection of tire pressure and tire wear safety brake inspection check and correct all fluid levels		
BRAKE FLUID BF	1.00	3.00	3.00	CHECK THE RADIATOR LEAK - IS IT WORSE YES!		0.00
THERMOSTAT 116 200 00 15	1.00	61.00	61.00	RADIATOR - remove & replace replace thermostat and radiator cap	4.00	380.00
EXPANSION TANK CAP 123 501 02 15	1.00	31.00	31.00	FAN CLUTCH - Remove & Replace	1.50	142.50
COOLANT Q1030002	2.00	30.00	60.00			
RADIATOR HOSE - Lower 116 501 04 82	1.00	73.50	73.50			
RADIATOR HOSE - Upper 116 501 07 82	1.00	38.50	38.50			
RADIATOR 109 501 03 01	1.00	850.00	850.00			
FAN CLUTCH 000 200 04 22	1.00	476.00	476.00			

[Recommendations]

valve covers wet
 recommend front wheel bearings
 left engine mount has gone flat - recommend doing all 3
 power steering pump leaks and the cover below the power
 steering pump leaks, power steering box leaks and the
 differential pinion shaft seal leaks

Linus Mercedes Service

74875 Hovley Lane East

Palm Desert, CA. 92260

Phone - 760-773-4707 Fax - 760-776-5084

We are Your Dealership Alternative

INVOICE

18071

Org. Est. # 037102

BAR - AD 166439

EPA ID - CAL00219619

INVOICE

Print Date : 11/11/2014

1970 Mercedes-Benz - 280SEL - 2.8

Lic # : MCM - CA

Odometer In : 71391

Unit # :

Vin # : **111.027-12-003095**

Hat # :

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
---------------------------	-----	------	----------	-------------------	-------	----------

Org. Estimate \$ 47.50 Revisions \$ 2,646.32 Current Estimate \$ 2,693.82

Revision # 1, Previous Estimate Amount: 47.50, Additional Cost: 2585.30, Revised Estimate: 2632.80, Parts: \$1910.00 Labor: \$522.50 Sublet: \$0.00 Taxes & Fees: \$152.80
 Authorized by - Meisenbach, , Date - 11/11/2014, Time - 2:42 PM, Initiated By - Customer, Written By - Dukic, Rosemary, Reason - FAN CLUTCH NOT WORKING, Phone
 Number - Home: 760-413-1067
 Revision # 2, Previous Estimate Amount: 2632.80, Additional Cost: 61.02, Revised Estimate: 2693.82, Parts: \$56.50 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$4.52
 Authorized by - Meisenbach, , Date - 11/11/2014, Time - 2:42 PM, Initiated By - Customer, Written By - Dukic, Rosemary, Reason - FAN CLUTCH NOT WORKING, Phone
 Number - Home: 760-413-1067

Labor:	570.00
Parts:	1,646.50
Sublet:	\$0.00
Sub:	2,216.50
Tax:	131.72
Total:	2,348.22
Bal Due:	\$2,348.22

[Payments -]

Mon - Fri 8am to 5pm / Fridays 7am to 3pm

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 12 months or 12000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

QTY	PART AND DESCRIPTION	PRICE
	Rear Caliper kits	50 60
	Front brake Hoses	49 94
	Rear Right Hose	18 73
	Rear Left Hose	16 50
	brake fluid	14 25

EUROPEAN CAR SPECIALISTS

RR SPORTS CARS GARAGE

(760) 773-5098
74-897 42nd Ave.
Palm Desert CA 92260

Mailing Address:
74-866 Velie Way #8
Palm Desert CA 92260

NAME	PHONE RES	DATE
ADD	PHONE BUS	6-20-23
CITY	ORDER WRITTEN BY	A M
YEAR MAKE AND MODEL	LICENSE NUMBER	P M
1971 Merd 280 SE	GEOMETER	
VEH ID NO	71178	

LUBE CHANGE OIL FILTER

Labor
The Mercedes came back in with the brakes not stopping good I found the rear calipers were plugged up with rubber trash I had to rebuild the rear calipers I also installed new front and rear brake hoses Because it looks like the rubber trash came from the brake hoses Then we flush the system Now the brakes work good

The car will need more park shocks and sub frame mounts

TIRE PRESSURE: FRONT	REAR	mounts
ESTIMATE	TOTAL LABOR	950 00
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs there to. It is also understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.	TOTAL PARTS	150 02
SIGNATURE	TOWING	
REVISSED ESTIMATE	OTHER	
DATE	TIME	BY
PHONE NUMBER	HAZARDOUS WASTE HANDLING FEE	12 00
	CALL BY	TAX
		11 63
	TOTAL	1,123 65

Terms of payment are cash, Mastercard or Visa card. Local checks accepted subject to approval before work is started. All labor is guaranteed 4000 miles or 90 days, whichever occurs first. Parts guarantees are generally the same but are the responsibility of the manufacture/supplier and may be subject to limitation. This is a limited guarantee. Positively no Labor Warranty after 4000 miles or 90 days, whichever occurs first. This Warranty valid only at Sports Cars Garage. Any other warranty considerations must be authorized before any work is done.

*CODE N-NEW U-USED R-REBUILT

QTY	*	PART NO. OR DESCRIPTION	SALE
		PPI:	
		DIFF PINION SEAL LEAK/WET	
		VALVECOVER GASKETS	
		CHAIN TENSIONER LEAK	
		LEFT EXHAUST MANIFOLD GASKET LEAK	
		LEFT MOTOR MOUNT LOW	
		WRONG WIPER BLADES	
		WRONG TIRE SIZE	
		WRONG TRANSMISSION COOLER LINES	
		SPARE FLAT	
		CLOCK INOP	
		HEATED LEVERS BROKEN	
		HEATED VALVES FROZEN	
		BODY RUST @ LEFT REAR	
		MAP SENSOR TAMPERED WITH	
		NOTED NEW PARTS &	
		SHOCKS	
		POWER STEERING BOX + COUPLER	
		T-RODS - DRAGLINK AND DAMPER	
		REAR DIFFERENTIAL COMPENSATOR	
		FUEL PUMP AND FILTER AND HOSES	
		SUBFRAME MOUNTS AND SHOCKS	
		BRAKE MASTER CYLINDER	
		REAR CALIPERS + HOSES	
		NEW IDLE AIR VALVE AND COUPLER	

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.

1295 Rollins Road

BURLINGAME, CA 94010-2416

(650) 343-8858 Fax (650) 343-9261

Since 1979

Since 1979

Date 12/10/2024 022500

Time Received	Written By
A.M.	Cust. Order No.
P.M.	Phone when ready
Promised	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

E
Na
Ad
City
Year

10/10 280SE 5.5 85235 W. H1778

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE. SAVE DISCARD

Estimate Amount \$	Engine Size	VIN Number	11102712003095
Revised Estimate \$	Date	Time	Description
Revised Estimate \$	Date	Time	Description

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	CAR TOWED IN - DRAIN TANK - OLD GAS	
	CHECK IGNITION AND FUEL PRESSURE	
	RUNS ROUGH FOUND SPARK PLUG CONNECTORS WIRES PULLED	
	TEMP SENDER DISCONNECTED, COOLANT TEMP SENDER CONNECTOR RIPPED	
	INJECTOR CONNECTORS DISCONNECTED	
	PPI:	
	COMPRESSION 1/180 2/185 3/185 4/175 5/180 6/190 7/185 8/185	

TOTAL PARTS

TIRE PRESSURE CHECK SERVICE COMPLETED
 TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)
 DECLINED Initial REASON:

SUBLET REPAIRS

QTY.	SALE
QTS. OIL	
QTS. OIL	
LBS. GREASE	
TOTAL OIL, GREASE	
TOTAL SUBLET REPAIRS	

WARRANTY ON PARTS & LABOR
 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
 NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).
 WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5. PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS

RECOMMENDED SERVICE:
 1.
 2.
 3.
 I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.
 Authorized By _____

TOTAL LABOR	15000
PARTS	
SUBLET REPAIRS	
OIL & GREASE	
GAS	
SALES TAX	
HAZARDOUS WASTE DISPOSAL FEE	
TOTAL AMOUNT	15000

ORIGINAL