

Invoice

Date	Invoice #
5/19/2017	2251

Bill To
<div>PAYED 06/16/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	11304310-004301	47,761	124G- Arabian Grey	Due On Receipt	6/24/2017
Item	Description	Qty	U/M	Rate	Total
Labor	Removed wheels, drained engine oil and coolant, and removed oil filter housing. Removed spark plugs and wires as well as removed battery. Upon inspection of oil filter housing, an abundance of sludge was present in the filter housing which lead to digging deeper. Performed cylinder leak down test and results were very poor. Determined that the engine needs to be rebuilt. Removed hood. Began engine removal process. Continued with engine compartment disassembly.	7.32		70.00	512.40
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal \$557.40

Payments Applied -\$557.40

Total \$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
6/2/2017	2265

Bill To
<div>PAID 06/16/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	11304310-004301	47,761	124G- Arabian Grey	Due On Receipt	6/24/2017
Item	Description	Qty	U/M	Rate	Total
Labor	Finished removing engine, transmission and subframe.	2.9		70.00	203.00
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal \$248.00

Payments Applied -\$248.00

Total \$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
6/8/2017	2267

Bill To

PAID
08/09/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	11304310-004301	47,761	124G- Arabian Grey	Due On Receipt	6/24/2017

Item	Description	Qty	U/M	Rate	Total
Gasket- 111-268...	Shifter Gasket- 111-268-08-34	1	ea	15.50	15.50
Dust cover- 111...	DustCover- 111-268-09-34	1	ea	68.00	68.00
Bushing- 111-2...	Bushing- 111-267-00-83	2	ea	9.75	19.50
Bushing- 111-2...	Bushing- 111-267-00-86	2	ea	11.50	23.00
Boot- 111-268-...	Boot- 111-268-04-97	1	ea	15.00	15.00
Bushing- 111-9...	Bushing- 111-992-03-10	2	ea	13.00	26.00
Muffler Hanger-...	Muffler Hanger- 107-492-00-82	4	ea	4.40	17.60
Donut- 113-492...	Donut- 113-492-00-82	2	ea	6.00	12.00
Flat Seal- 000-4...	Gasket- 000-477-35-80	1	ea	2.10	2.10
Gasket- 199-077...	Fuel Injection Pump Mounting Gasket- 199-077-02-79	2	ea	1.90	3.80
Buffer- 112-987...	Buffer- 112-987-01-40	1	ea	5.00	5.00
Shield- 113-492...	Shield- 113-492-03-30	1	ea	620.00	620.00
Sway Bar Kit- 1...	Sway Bar Kit- 110-320-00-47	1	ea	230.00	230.00
Flex Disc- 108-...	Flex Disc- 108-410-01-15	1	ea	190.00	190.00
Seal- N 007603-...	Seal- N 007603-030101	1	ea	3.00	3.00
Gasket- 127-203...	Gasket- 127-203-02-80	1	ea	5.50	5.50
Thermostat- 110...	Thermostat- 110-200-05-15	1	ea	54.00	54.00
Fuel Filter- 000-...	Fuel Filter- 000-477-64-15	1	ea	10.00	10.00
Seal- 100-997-0...	Seal- 100-997-00-40	1	ea	1.90	1.90
Boot- 111-268-...	Boot- 111-268-07-97	1	ea	8.00	8.00
Bushing- 198-2...	Bushing- 198-268-01-50	4	ea	7.50	30.00
Bushing- 111-9...	Bushing- 111-992-05-10	2	ea	38.50	77.00
Oil Filter- 000-1...	Oil Filter- 000-180-00-09	1	ea	9.25	9.25
Hose- 108-476-...	Hose- 108-476-02-26	1	ea	22.00	22.00
Hose- 129-997-...	Hose- 129-997-02-82	1	ea	250.00	250.00

Subtotal

Payments Applied

Total

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
6/8/2017	2267

Bill To

PAID
08/09/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	11304310-004301	47,761	124G- Arabian Grey	Due On Receipt	6/24/2017
Item	Description	Qty	U/M	Rate	Total
Hose- 129-070-...	Hose- 129-070-06-32	1	ea	167.00	167.00
Fuel Hose- 113-...	Fuel Hose- 113-476-09-26	1	ea	42.00	42.00
Hose- 108-476-...	Fuel Hose- 108-476-00-26	1	ea	65.00	65.00
Submount Kit- ...	SubMount Kit- 113-586-00-33	1	ea	805.00	805.00
Motor Mount- 1...	Motor Mount- 110-220-02-17	1	ea	258.00	258.00
Mount- 120-223...	Mount- 120-223-04-12	1	ea	100.00	100.00
Labor	Degreased and hot pressure washed subframe and transmission, subframe needs additional degreasing. Stripped engine down to a long block. Crated engine in preparation to be picked up by freight company.	7.01		70.00	490.70
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00
Outside Service	Metric Motors: -Longblock: \$10,260.00 -Cylinder Head Replacement: \$1,320.00 (Cylinder head was badly corroded and demonstrated cracking between #4 and #5 cylinder heads. Replacing the cylinder head was determined to be the better option instead of welding the cracks.) -Round Trip Freight: \$480.00 **PARTIAL PAYMENT MADE 16-16-2017, CHECK # 1535	1		12,060.00	12,060.00

Subtotal \$15,750.85

Payments Applied -\$15,750.85

Total \$0.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
6/16/2017	2279

Bill To
<div>PAID 08/09/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	11304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Labor	Degreased engine compartment components.	5.9		70.00	413.00
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal \$458.00

Payments Applied -\$458.00

Total \$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
6/20/2017	2284

Bill To
<div>PAID 08/09/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Steering Pump- ...	Power Steering Pump- CM092	1	ea	494.82	494.82
Shipping Charges	Shipping Injection Pump to Jerry Fairchild	1		116.20	116.20
Outside Service	Affordable Extreme Coating: -(X1) Cylinder Manifold (Titanium) -Shop Consumables	1		78.91	78.91

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal \$689.93

Payments Applied -\$689.93

Total \$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
6/27/2017	2289

Bill To

PAID
08/09/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Gasket- 127-141...	Manifold Gasket- 121-141-01-79	1	ea	18.93	18.93
O-Ring- 002-99...	O-Ring- 002-997-52-45	1	ea	15.43	15.43
Steering Box- 1...	Power Steering Box- 109-601-001-88	1	ea	746.03	746.03
Alternator 55A- ...	Alternator 55A- AL74X	1	ea	333.00	333.00
Starter- SR 59 X	Starter- SR 59 X	1	ea	475.00	475.00
VoltageRegulat...	Voltage Regulator- 901-603-206-02	1	ea	214.19	214.19

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal	\$1,802.58
Payments Applied	-\$1,802.58
Total	\$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
7/7/2017	2299

Bill To
<div>PAID 08/09/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Outside Service	Performance Radiator: -Clean and repair radiator and oil cooler -Shop supplies -Environmental fee -Recondition oil cooler -Shop Supplies -Environmental fee	1		350.63	350.63

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal	\$350.63
-----------------	----------

Payments Applied	-\$350.63
-------------------------	-----------

Total	\$0.00
--------------	--------

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
7/20/2017	2315

Bill To
<div>PAID 08/09/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Fuel Filter - ED...	Fuel Filter Housing Assembly- ED6022ME4	1	ea	210.00	210.00
Labor	Touched up subframe. Got it onto a cart and began dressing engine in preparation for installation onto subframe. Prepped engine parts for installation. Prepped parts for plating.	17.14		70.00	1,199.80
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal \$1,454.80

Payments Applied -\$1,454.80

Total \$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
7/27/2017	2320

Bill To

PAID
08/09/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Clutch Slave- 00...	Clutch Slave- 000-295-19-07	1	ea	152.00	152.00
Shock Absorber...	Shock Absorber- B 46 539	2	ea	196.00	392.00
Shock Absorber...	Shock Absorber- B 36 539	2	ea	196.00	392.00
Filter- 000-236-...	Filter- 000-236-00-55	1	ea	21.00	21.00
Bracket- 115-15...	Bracket- 115-159-01-40	2	ea	5.75	11.50
Hose- 113-501-...	Hose- 113-501-09-82	1	ea	22.00	22.00
Hose- 1082	Hose- 113-501-10-82	1	ea	45.00	45.00
Hose- 0482	Hose- 113-501-04-82	1	ea	37.00	37.00
Injection Nozzle...	Injection Nozzle- 0-437-004-002	2	ea	222.00	444.00
Hose- 127-203-...	Hose- 127-203-00-82	1	ea	11.50	11.50
Water Pump- 11...	Water Pump- 110-200-20-20	1	ea	122.00	122.00
NGK Spark Plu...	NGK Spark Plug- BP6ES	6	ea	3.63	21.78
Labor	Painted engine oil cooler then installed onto engine. Installed engine onto subframe. Installed injection pump, detailed valve cover, then installed. Installed (X4) injectors, cold start thermostat, and fuel pressure dampener. Finished installing remaining injectors. Installed waterpump, thermostat housing, thermostat and thermostat topper.	5.76		70.00	403.20
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00
Outside Service	Jerry Fairchild Industries: -Disassembled pump and governor. Cleaned and installed all internal parts. Checked governor. Set pump altitude compensator and delivery valves. Replaced all worn parts and seals. Re-calibrated pump and governor. Tested solenoids and assemble.	1		903.29	903.29

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal

\$3,023.27

Payments Applied

-\$3,023.27

Total

\$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/4/2017	2326

Bill To

PAID
08/22/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017

Item	Description	Qty	U/M	Rate	Total
Flat Seal- 000-4...	Gasket- 000-477-35-80	1	ea	2.10	2.10
Repair Kit- 111-...	Steering Arm Repair Kit- 111-460-00-50	1	ea	256.00	256.00
Grommet- 110-9...	Grommet- 110-997-03-81	2	ea	27.50	55.00
Mixture Control...	Oil Seal for 300SL Mixture Control- 3145	1	ea	5.10	5.10
Belt- 006-997-0...	Belt- 006-997-09-92	1	ea	14.50	14.50
Lid Seal- 000-2...	Lid Seal- 000-236-00-80	1	ea	6.25	6.25
Gasket- 000-184...	Seal- 000-184-33-80	1	ea	3.70	3.70
Gasket- 000-184...	Gasket- 000-184-32-80	1	ea	2.20	2.20
Gasket- 000-184...	Seal- 000-184-17-80	1	ea	8.50	8.50
Valve- 181-184...	Valve- 181-184-00-30	2	ea	15.50	31.00
Hose- 109-997-...	Power Steering Hose- 109-997-08-82	1	ea	470.00	470.00
V-Belt- 006-997...	V-Belt 9.5 X 910- 006-997-02-92	1	ea	17.50	17.50
Hose- 128-540-...	Hose- 128-540-00-59	1	ea	105.00	105.00
Bushing- 000-9...	Bushing- 000-988-33-10	2	ea	7.50	15.00
Bearing Kit- 10...	Bearing Kit- 107-330-00-51	2	ea	89.00	178.00
Caliper- 000-42...	Caliper- 000-420-47-83	1	ea	400.00	400.00
Caliper- 000-42...	Caliper- 000-420-46-83	1	ea	400.00	400.00
Caliper- 001-42...	Caliper- 001-421-81-98	1	ea	300.00	300.00
Caliper- 001-42...	Caliper- 001-421-82-98	1	ea	300.00	300.00
Brake Disc- 126...	Brake Disc- 126-423-001-264	2	ea	66.00	132.00
Brake Disc- 115...	Brake Disc- 115-421-111-264	2	ea	98.00	196.00
Brake Booster- ...	Brake Booster- 002-430-68-30	1	ea	869.69	869.69
Flex Hose- 000-...	Flex Hose- 000-428-26-35-MY	1	ea	50.00	50.00
Flex Hose- 000-...	Flex Hose- 000-428-93-35-MY	1	ea	42.00	42.00
Flex Hose- 123-...	Flex Hose- 123-428-05-35-MY	2	ea	45.00	90.00
Reservoir- 001-...	Reservoir- 001-431-42-02	1	ea	113.51	113.51

Subtotal

Payments Applied

Total

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/4/2017	2326

Bill To

PAID
08/22/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017

Item	Description	Qty	U/M	Rate	Total
Hose- 000-295-...	Hose- 000-295-08-35	1	ea	104.00	104.00
Master Cylinder...	Master Cylinder- 002-430-28-01	1	ea	362.00	362.00
Master Cylinder...	Master Cylinder- 000-295-29-06	1	ea	256.00	256.00
Pedal Pad- 107-...	Pedal Pad- 107-291-01-82	2	ea	5.00	10.00
Gas Pedal- 110-...	Gas Pedal- 110-300-00-02	1	ea	422.00	422.00
Grommet- 183-9...	Grommet- 183-997-00-81	1	ea	9.25	9.25
Grommet- 113-9...	Grommet- 113-997-00-81	1	ea	0.90	0.90
Grommet- 113-9...	Grommet- 113-997-01-81	1	ea	8.50	8.50
Radiator Cap- 0...	Radiator Cap- 000-501-00-15	1	ea	70.00	70.00
Pipe- 113-500-0...	Pipe- 113-500-01-72	1	ea	206.00	206.00
Wire Set- 130-1...	Wire Set- 130-150-13-18	1	ea	370.00	370.00
Grommet- 186-9...	Grommet- 186-997-06-81	2	ea	2.40	4.80
Clip- 110-683-0...	Clip- 110-683-00-10	2	ea	37.50	75.00
Clip- 001-988-4...	Clip- 001-998-44-78	4	ea	1.20	4.80
Labor	Began prepped/ sanding of radiator and reservoir tank for paint. Finished sanding and prepping radiator and reservoir tank. Epoxy sealed and painted parts.	3.57		70.00	249.90

Subtotal

Payments Applied

Total

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/4/2017	2326

Bill To

PAID
08/22/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Labor	Began degreasing and detailing engine compartment and miscellaneous components. Continued dressing engine on subframe cart, installed steering box, and connected steering column. Detailed engine compartment components in preparation for engine install. Installed exhaust system and heat shields. Installed engine and subframe onto chassis. Connected driveshaft, clutch slave cylinder, shifter, and installed transmission support brace. Installed injection lines, connected exhaust system to exhaust manifolds, replaced steering idler bushing and seal and installed intake manifold. R&R mixture control then installed onto intake manifold. Plumbed oil, coolant, and fuel system. Installed and plumbed power steering pump and reservoir. Installed new clutch master and slave cylinder. Installed front and rear brake hoses. Installed front and rear dampeners. Began wiring engine and ignition system then installed vacuum hoses and throttle linkages. Installed radiator and hoses.	41.31		70.00	2,891.70
Materials and S...	Materials, supplies and hazardous waste fee.	1		45.00	45.00
Shipping Charges	Shipping gauges to Mo-Ma Manufacturing	1		12.14	12.14
Outside Service	CRC (Chemical Research Corporation) Surface Technologies: - Plated (X276) parts/ pieces.	1		287.50	287.50

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal

Payments Applied

Total

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/4/2017	2326

Bill To
<div>PAID 08/22/2017</div>

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	8/19/2017
Item	Description	Qty	U/M	Rate	Total
Outside Service	Performance Radiator: -Cleaned and repaired Mercedes expansion tank **PARTIAL PAYMENT MADE 07-09-2017, CHECK # 1544	1		43.75	43.75

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal

\$9,496.29

Payments Applied

-\$9,496.29

Total

\$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/10/2017	2332

Bill To

PAID
08/22/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	9/5/2017
Item	Description	Qty	U/M	Rate	Total
Bearing Kit- 11...	Bearing Kit- 111-350-00-68	2	ea	65.00	130.00
Front Pads- 001...	Brake Pad Set- 001-420-77-20	1	ea	46.30	46.30
Brake Pad Set- ...	Brake Pad Set- 001-420-06-20	1	ea	27.00	27.00
Coil (Red)- 00013	Coil (Red)- 00013	1	ea	115.00	115.00
Hose- 111-831-...	Hose- 111-831-00-94	1	ea	32.00	32.00
Oils	Valvoline Race 20-50 Motor Oil	6	ea	11.68	70.08
Labor	Removed front rotors and hubs. Detailed and installed new bearings and seals into front hubs. Installed rotors onto hubs and installed rotors and hubs back onto car. Installed front brake calipers and pads. Finished wiring ignition system, wired alternator, and drained rear differential.	28.55		70.00	1,998.50
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal

\$2,463.88

Payments Applied

-\$2,463.88

Total

\$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/17/2017	2337

Bill To

PAID
08/22/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	9/5/2017
Item	Description	Qty	U/M	Rate	Total
Mounting Brack...	Rear Radio Mounting Bracket- AUTH-003670	1	ea	26.95	26.95
Radio Bracket- ...	Radio Bracket Extension Kit- AUTH-005120	1	ea	19.95	19.95
Washer- 100-54...	Square- 100-542-01-38	1	ea	22.00	22.00
Bracket Kit- 113...	Bracket Kit- 113-887-99-14	1	ea	20.00	20.00
Strap- 000-983-...	Strap- 000-983-14-12-8000	1	ea	7.50	7.50
Hood Stop- 201...	Hood Stop- 201-988-05-11	2	ea	5.00	10.00
Boot- 113-462-...	Boot- 113-462-00-96	1	ea	81.00	81.00
Oil Filter- H 72...	Mann Oil Filter- H 720 X	1	ea	8.00	8.00
Gasket- 110-471...	Fuel Sending Unit- 110-471-01-80	1	ea	4.90	4.90
Sender- 110-542...	Sender- 110-542-12-04-64	1	ea	258.00	258.00
Shim- 100-542-...	Shim- 100-542-00-38	2	ea	18.50	37.00
Switch- 002-545...	Switch- 002-545-29-24	1	ea	610.00	610.00
Alternator- AL ...	Alternator- AL 72 X	1	ea	333.00	333.00
Fuel	Fuel refill	1		49.23	49.23
Oils	Valvoline VR1 20-50W	7	ea	10.83	75.81

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal

Payments Applied

Total

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
8/17/2017	2337

Bill To

PAID
08/22/2017

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00.
Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	124G- Arabian Grey	Due On Receipt	9/5/2017
Item	Description	Qty	U/M	Rate	Total
Labor	Removed rear axle shafts. Cleaned and detailed rear parking brake assemblies. Re-sealed rear axle at wheel bearings. Installed new wheel bearings, rotors, and calipers. Bled brakes. Installed new clutch master cylinder and slave. Bled clutch hydraulics. Got car running and warmed up after initial running, and re-torqued cylinder head while hot. Began dialing in car. Fixed a coolant leak. Adjusted injection pump. Began test driving. Fixed dash lights. Diagnosed fuel gauge. Replaced fuel sender. Fixed windshield wiper linkage. Replaced multi switch. Checked all light functions, fixed dimmer switch, and replaced bulbs in tail light housings. Re-installed hood. Cleaned and reed up hood release cable. Performed valve adjust, oil, and filter change. Replaced fuel hoses and fuel tank. Cleaned and polished a better used steering wheel, then installed onto car.	42.58		70.00	2,980.60
Materials and S...	Materials, supplies and hazardous waste fee.			45.00	45.00
Outside Service	Mo-Ma Manufacturing: - Mercedes temperature gauge repaired	1		357.50	357.50
	CREDIT MEMO 2339 APPLIED				

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal

\$4,946.44

Payments Applied

-\$4,946.44

Total

\$0.00

THANK YOU FOR YOUR BUSINESS!

Invoice

Date	Invoice #
9/25/2017	2372

Bill To

PLEASE NOTE:

Due to the rising costs of conducting our business, effective February 1, 2025, our shop rate will increase to \$185.00. Thank you for your understanding.

Make/Model/Year	Vin. No.	Mileage	Color	Payment Terms	Due Date
MB 250SL 1967	1304310-004301	47,761	24G- Arabian Grey	Due On Receipt	10/10/2017
Item	Description	Qty	U/M	Rate	Total
Donut- 113-492...	Donut- 113-492-00-82	2	ea	0.00	0.00

RW Fabrications LLC

37505 N. 24th St.
Phoenix, Az 85086

480-773-9499

robert@websterwerkstatt.com

Subtotal	\$0.00
Payments Applied	\$0.00
Total	\$0.00

THANK YOU FOR YOUR BUSINESS!