

PIU 4/5
@ 12pm.

CUSTOMER #: 1052976

647046



Mercedes-Benz
of Fairfield

2950 AUTO MALL PARKWAY · FAIRFIELD, CA 94533
(707) 430-0101 · www.mercedesfairfield.com

* INVOICE *

PAGE 1

Service Center Hours:
MONDAY - FRIDAY 7:30 A.M. - 6:00 P.M.
SATURDAY 8:00 A.M. TO 4:00 P.M.

SERVICE ADVISOR: 976 JENNA CASTLEMAN

| COLOR | YEAR | MAKE/MODEL | VIN | LICENSE | MILEAGE IN / OUT | TAG | |
|------------|------------|----------------|-------------------|---------|------------------|---------|-----------|
| | 16 | MERCEDES SL400 | WDDJK6FA1GF038254 | | 19452/19454 | TY483 | |
| DEL. DATE | PROD. DATE | WARR. EXP. | PROMISED | PO NO. | RATE | PAYMENT | INV. DATE |
| 01JAN16 IS | | | 18:00 05APR23 | | | CASH | 05APR23 |
| 01JAN16 DD | | | | | | | |

| R.O. OPENED | READY | OPTIONS: |
|---------------|---------------|----------|
| 08:00 05APR23 | 10:32 05APR23 | |

| LINE | OPCODE | TECH | TYPE | HOURS | LIST | NET | TOTAL |
|------|--------|------|------|-------|------|-----|-------|
|------|--------|------|------|-------|------|-----|-------|

A PERFORM COMPLIMENTARY MULTI-POINT INSPECTION , TIRE PRESSURE CHECK AND ADJUSTMENT AND COMPLIMENTARY CAR WASH
 TPMPWASH PERFORM COMPLIMENTARY MULTI-POINT INSPECTION , TIRE PRESSURE CHECK AND ADJUSTMENT AND COMPLIMENTARY CAR WASH
 1024 IMPI (N/C)
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

PERFORMED MULTI-POINT INSPECTION AS PER INSPECTION CHECKLIST, SEE ATTACHED PRINTOUT FOR INSPECTION RESULTS
 SET TIRE PRESSURES TO: FRONT 36PSI, REAR 42PSI

B Vehicle completed and ready for pick-up on 4/5/2023 and the customer has been notified.

DDATE Vehicle completed and ready for pick-up on xx/xx/xxxx and the customer has been notified.

999 ISP (N/C)
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C Service at 70,000 miles or 7 years - Required
 B008M070000 Service at 70,000 miles or 7 years - Required

| | | | |
|--|------|--------|--------|
| 1024 CM | | 208.00 | 208.00 |
| DWASHERFLUID FILL WASHER FLUID RESERVOIR | | | |
| 1024 CM | | 0.00 | 0.00 |
| 1 000-986-20-00-13 WINDSHIELD WASHER FLUID | | | 6.60 |
| 00001R Replace Engine Oil | | | |
| 1024 CM | | 0.00 | 0.00 |
| 7 000989790219BIFU MB 229.5 SAE 5W-40 BULK | | | 51.52 |
| 7 HAZ OIL DISPOSAL FEE | 0.10 | 0.10 | 0.70 |
| 00003R Replace Engine Oil Filter | | | |
| 1024 CM | | 0.00 | 0.00 |
| 1 276-180-00-09 TS OIL FILTER ELEMENT | | | 30.53 |

PAID

| Mercedes Benz Fairfield | ORIGINAL ESTIMATE: \$ | | | FINAL REVISED ESTIMATE: \$ | | | DESCRIPTION | TOTALS |
|-------------------------|-----------------------|------|---------|----------------------------|-------------------|---------------|------------------------|--------|
| | DATE | TIME | PHONE # | AUTHORIZED | ADDITIONAL AMOUNT | REVISED TOTAL | | |
| | | | | | | | LABOR AMOUNT | |
| | | | | | | | PARTS AMOUNT | |
| | | | | | | | GAS, OIL, LUBE | |
| | | | | | | | SUBLET AMOUNT | |
| | | | | | | | MISC. CHARGES | |
| | | | | | | | TOTAL CHARGES | |
| | | | | | | | LESS ADJUSTMENTS | |
| | | | | | | | SALES TAX | |
| | | | | | | | PLEASE PAY THIS AMOUNT | |

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

CUSTOMER #: 1052976

647046



Mercedes-Benz of Fairfield

INVOICE

2950 AUTO MALL PARKWAY · FAIRFIELD, CA 94533
(707) 430-0101 · www.mercedesfairfield.com

PAGE 2

Service Center Hours:
MONDAY- FRIDAY 7:30 A.M. - 6:00 P.M.
SATURDAY 8:00 A.M. TO 4:00 P.M.

SERVICE ADVISOR: 976 JENNA CASTLEMAN

| | | | | | | | |
|------------|------------|----------------|-------------------|---------|------------------|---------|-----------|
| COLOR | YEAR | MAKE/MODEL | VIN | LICENSE | MILEAGE IN / OUT | TAG | |
| | 16 | MERCEDES SL400 | WDDJK6FA1GF038254 | | 19452/19454 | TY483 | |
| DEL. DATE | PROD. DATE | WARR. EXP. | PROMISED | PO NO. | RATE | PAYMENT | INV. DATE |
| 01JAN16 IS | | | 18:00 05APR23 | | | CASH | 05APR23 |
| 01JAN16 DD | | | | | | | |

| | | |
|---------------|---------------|----------|
| R.O. OPENED | READY | OPTIONS: |
| 08:00 05APR23 | 10:32 05APR23 | |

| LINE | OPCODE | TECH | TYPE | HOURS | LIST | NET | TOTAL |
|--------|---|--------|--------|--------|------|---------------|--------|
| 00004M | Reset Service Indicator | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0029CN | Clean A/C Water Drain | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0079IN | Inspect Tires and Adjust Air Pressures, Including Spare Tire | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0110IN | Inspect Brake Fluid Level | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0123IN | Inspect Window Washer Fluid Level | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0195IN | Inspect Hood Latch and Hinges | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0196IN | Inspect Active Body Control Fluid Level | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0301IN | Inspect Thickness of Brake Pads, Front and Rear | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| 0367IN | Inspect Charging Cable and Vehicle Socket for Mechanical Damage | | | | | | |
| | 1024 | CM | | | | 0.00 | 0.00 |
| PARTS: | 88.65 | LABOR: | 208.00 | OTHER: | 0.70 | TOTAL LINE C: | 297.35 |

COMPLETED 70,000 MILE INTERVAL SERVICE

Oil Quantity 6.9QTS

Inspect seat belts for damage and proper function.

Inspect front and rear brake pad lining and record thickness.

Inspect brake rotor condition front/rear

Inspect engine cooling system

Check all exterior light functions

Check wiper function front/rear

Check head lamp cleaning system

Check for manufacturer service campaigns or recalls.

Adjust tire pressure

| | | | | | | | | |
|-------------------------|-----------------------------|--|--|----------------------------------|--|--|------------------------|--------|
| Mercedes Benz Fairfield | ORIGINAL ESTIMATE: \$ _____ | | | FINAL REVISED ESTIMATE: \$ _____ | | | DESCRIPTION | TOTALS |
| | DATE | | | AUTHORIZED | | | LABOR AMOUNT | |
| | TIME | | | ADDITIONAL AMOUNT | | | PARTS AMOUNT | |
| | PHONE # | | | REVISED TOTAL | | | GAS, OIL, LUBE | |
| | | | | | | | SUBLET AMOUNT | |
| | | | | | | | MISC. CHARGES | |
| | | | | | | | TOTAL CHARGES | |
| | | | | | | | LESS ADJUSTMENTS | |
| | | | | | | | SALES TAX | |
| | | | | | | | PLEASE PAY THIS AMOUNT | |

BAR # ARD00266597
EPA # CAL000366984



NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

CUSTOMER #: 1052976

647046



Mercedes-Benz of Fairfield

INVOICE

2950 AUTO MALL PARKWAY · FAIRFIELD, CA 94533 (707) 430-0101 · www.mercedesfairfield.com

PAGE 3

Service Center Hours: MONDAY- FRIDAY 7:30 A.M. - 6:00 P.M. SATURDAY 8:00 A.M. TO 4:00 P.M.

SERVICE ADVISOR: 976 JENNA CASTLEMAN

| | | | | | | | |
|---------------|---------------|----------------|-------------------|---------|------------------|---------|-----------|
| COLOR | YEAR | MAKE/MODEL | VIN | LICENSE | MILEAGE IN / OUT | TAG | |
| | 16 | MERCEDES SL400 | WDDJK6FA1GF038254 | | 19452/19454 | TY483 | |
| DEL. DATE | PROD. DATE | WARR. EXP. | PROMISED | PO NO. | RATE | PAYMENT | INV. DATE |
| 01JAN16 IS | | | 18:00 05APR23 | | | CASH | 05APR23 |
| 01JAN16 DD | | | | | | | |
| R.O. OPENED | READY | OPTIONS: | | | | | |
| 08:00 05APR23 | 10:32 05APR23 | | | | | | |

| LINE | OPCODE | TECH | TYPE | HOURS | LIST | NET | TOTAL |
|---|--------|------|------|-------|------|-----|-------|
| Inspect and correct coolant, brake fluid and windshield washer fluid levels | | | | | | | |
| Lubricate door hinges and latches | | | | | | | |
| Check battery condition MBUSA Midtronics tester | | | | | | | |
| Inspect engine air filter | | | | | | | |
| Replace Synthetic engine oil and Fleece oil filter | | | | | | | |
| Reset maintenance indicator | | | | | | | |
| See Attached Inspection Sheet for Details. | | | | | | | |

ESTIMATE: 296.65 05APR23 08:00 SA: 976

CONTACT:

SHUTTLE XTIME WEB APPT CREATED
2023-04-03 11:37 :44AM TAKEN
BY C/S: A SERVICE LIGHT IS ON.
MI LEAGE IS APPROXIMATELY
19,500

| Mercedes Benz Fairfield | ORIGINAL ESTIMATE: \$ | | | FINAL REVISED ESTIMATE: \$ | | | DESCRIPTION | TOTALS |
|-------------------------|-----------------------|------|---------|----------------------------|-------------------|---------------|------------------------|--------|
| | DATE | TIME | PHONE # | AUTHORIZED | ADDITIONAL AMOUNT | REVISED TOTAL | | |
| | | | | | | | LABOR AMOUNT | 208.00 |
| | | | | | | | PARTS AMOUNT | 88.65 |
| | | | | | | | GAS, OIL, LUBE | 0.00 |
| | | | | | | | SUBLET AMOUNT | 0.00 |
| | | | | | | | MISC. CHARGES | 0.70 |
| | | | | | | | TOTAL CHARGES | 297.35 |
| | | | | | | | LESS ADJUSTMENTS | 0.00 |
| | | | | | | | SALES TAX | 7.48 |
| | | | | | | | PLEASE PAY THIS AMOUNT | 304.83 |

BAR # ARD00266597
EPA # CAL000366984



NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK



Mercedes Benz Of Fairfield



Automobile Status Report

Prepared For



2016 Mercedes-Benz SL400

Date April 05, 2023

VIN WDDJK6FA1GF038254

Mileage 19452

RO# 647046

Service Advisor

jenna castleman

jennacastleman@mercedesfairfield.com

Mercedes Benz Of Fairfield

2950 Auto Mall Pkwy

Fairfield, CA 94533



Multi-Point Inspection Form

RO# 647046

VIN WDDJK6FA1GF038254

Advisor jenna castleman

Technician Jason Rosas


Created On 4/5/2023

Checked and OK at this time

May Require Future Attention

Requires immediate attention

| Interior / Exterior | |
|-------------------------------------|---|
| <input checked="" type="checkbox"/> | Bulbs and Lights |
| <input checked="" type="checkbox"/> | Windshield Washer / Wiper Operation / Wiper Blades Conditions |
| <input checked="" type="checkbox"/> | Condition of Windshield |
| <input checked="" type="checkbox"/> | Horn Operation |
| <input checked="" type="checkbox"/> | Warning Lights |
| <input checked="" type="checkbox"/> | Air Condition / Heater Operation |
| Under Hood | |
| <input checked="" type="checkbox"/> | Engine Oil (Leaks & Condition) |
| <input checked="" type="checkbox"/> | Engine Coolant (Leaks & Condition) |
| <input checked="" type="checkbox"/> | Power Steering Pump, Lines, Hoses (Leaks & Condition) |
| <input checked="" type="checkbox"/> | Brake Fluid (Condition) |
| <input checked="" type="checkbox"/> | Windshield Washer Fluid (Leaks) |
| <input checked="" type="checkbox"/> | Engine Air Filter |
| <input checked="" type="checkbox"/> | Drive Belt / Belt Tensioner (condition and adjustment) |
| <input checked="" type="checkbox"/> | Engine Mounts (Condition) |
| <input checked="" type="checkbox"/> | Radiator / Heater Hoses |
| Battery Performance | |
| <input checked="" type="checkbox"/> | Battery Condition |
| <input checked="" type="checkbox"/> | Battery Terminals / Cables / Mountings |
| Under Vehicle | |
| <input checked="" type="checkbox"/> | Suspension / Ball Joints / Control Arms / Steering Linkage |
| <input checked="" type="checkbox"/> | Drive Axles / Boots, Drive Shaft, Flex Disc, U-Joints |
| <input checked="" type="checkbox"/> | Shock, Struts / Automatic Leveling System |
| <input checked="" type="checkbox"/> | Exhaust System |
| <input checked="" type="checkbox"/> | Fuel Lines |
| <input checked="" type="checkbox"/> | Brake Lines, Hoses |
| <input checked="" type="checkbox"/> | Transmission / Differential / Transfer Case (Leaks) |
| <input checked="" type="checkbox"/> | Transmission Linkage |

| Tread Depth (measured in millimeters) | |
|--|-----------------------------------|
|  | |
| <input checked="" type="checkbox"/> | Left Front Tire <u>6.5</u> |
| <input checked="" type="checkbox"/> | Right Front Tire <u>6.5</u> |
| <input checked="" type="checkbox"/> | Left Rear Tire <u>Z</u> |
| <input checked="" type="checkbox"/> | Right Rear Tire <u>Z</u> |
| Abnormal Wear Pattern of Tires | |
| <input checked="" type="checkbox"/> | LF |
| <input checked="" type="checkbox"/> | RF |
| <input checked="" type="checkbox"/> | LR |
| <input checked="" type="checkbox"/> | RR |
| Check Brake Linings (measured in millimeters) | |
| <input checked="" type="checkbox"/> | LF <u>5</u> |
| <input checked="" type="checkbox"/> | RF <u>5</u> |
| <input checked="" type="checkbox"/> | LR <u>Z</u> |
| <input checked="" type="checkbox"/> | RR <u>Z</u> |
| Road Test | |
| <input checked="" type="checkbox"/> | Transmission Shift Quality |
| <input checked="" type="checkbox"/> | Abnormal Noises (Squeaks/Rattles) |
| <input checked="" type="checkbox"/> | Vibration |
| Inspection Comments | |
| <input type="checkbox"/> | Comments: |



STAR MOTORS

MERCEDES BENZ SERVICE & REPAIR

986 Adams Street Benicia, CA 94510
Phone: 707 745 5606 Web: starmotorsbenicia.com
E-mail: starmotorsbenicia@outlook.com

Order Date 12/21/23 01:48 pm

Paid: 12/21/23 01:48 pm

16 MercedesBenz S1400

Odometer reading in:21996 out:21996
Lic: 7NZZ966/CA V6Cyl 3.0 Eng
Vin: WDDJK6FA1GF038254 07/15
Eq: AT PS FI TB

Quotes

1 12/21/23 01:49pm 127.90
in person.

Check For Fuel Leak

Labor: 0.8 hrs@\$150.00/hr=\$120.00

Check For Fuel Leak
Replace Clamp At Fuel Hose From Tank

| | | | | | |
|---------------|---------|-------|----------|------|------|
| 114 997 05 90 | CLAMP-N | 2.0 @ | 3.95 =\$ | 7.90 | 7.90 |
|---------------|---------|-------|----------|------|------|

12/21/2023 13:49 American Express****4009 TransID:11588083282 Approval:371296 \$128.56

I agree to pay the above total amount according to the card issuer agreement

Payments to Star Motors

Cost Summary

Status: Paid Work Order

Payments: \$128.56
1 12/21/23 128.56 AMEX

| | |
|----------|----------|
| Labor | 120.00 |
| Parts | 7.90 |
| Subtotal | 127.90 |
| Tax | 0.66 |
| Total | \$128.56 |
| Payments | 128.56 |
| Bal Due | 0.00 |

Thank you for choosing Star Motors

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE

BAR# ARD121200
EPA# 000090068

CREDIT CARDS ACCEPTED
WE RESERVE THE RIGHT TO REFUSE AN PERSONAL CHECKS



ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

By signing below, I hereby authorize the repair work to be done along with the necessary material, and hereby grant your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. If automobile is returned to customer before authorized service is performed, a diagnostic and handling charge will be made. I have read and understand the statements and estimates made on this/these pages (connected with this vehicle). I authorize service to be performed, including sublet work, and acknowledge receipt of this estimate. Customer is hereby notified that the said property is not insured or protected against loss occasioned by theft, fire or vandalism while the property remains with the Repair Garage.

I acknowledge notice and oral approval of an increase in the original estimated price. X

CUSTOMER ACKNOWLEDGMENT

CUST. SIG. X

I ACKNOWLEDGE RECEIPT OF AND AGREE TO THE TERMS AND CONDITIONS OF THIS CONTRACT.

CUSTOMER #: 1052976

662555



Mercedes-Benz of Fairfield

INVOICE

2950 AUTO MALL PARKWAY · FAIRFIELD, CA 94533 (707) 430-0101 · www.mercedesfairfield.com

PAGE 1

Service Center Hours: MONDAY- FRIDAY 7:30 A.M. - 6:00 P.M. SATURDAY 8:00 A.M. TO 4:00 P.M.

SERVICE ADVISOR: 976 JENNA CASTLEMAN

| | | | | | | | |
|------------|------------|----------------|-------------------|---------|------------------|---------|-----------|
| COLOR | YEAR | MAKE/MODEL | VIN | LICENSE | MILEAGE IN / OUT | TAG | |
| | 16 | MERCEDES SL400 | WDDJK6FA1GF038254 | | 23144/23147 | TB604 | |
| DEL. DATE | PROD. DATE | WARR. EXP. | PROMISED | PO NO. | RATE | PAYMENT | INV. DATE |
| 01JAN16 IS | | | 18:00 07MAY24 | | | CASH | 07MAY24 |
| 01JAN16 DD | | | | | | | |

| | | |
|---------------|---------------|----------|
| R.O. OPENED | READY | OPTIONS: |
| 09:01 07MAY24 | 15:49 07MAY24 | |

| LINE | OPCODE | TECH | TYPE | HOURS | LIST | NET | TOTAL |
|---|--------|-----------------------|---|-------|------|--------|--------|
| A Service at 80,000 miles or 8 years - Required | | | | | | | |
| B014M080000 Service at 80,000 miles or 8 years - Required | | | | | | | |
| | 1017 | CM | | | | 441.95 | 441.95 |
| | 1 | B-G-11-5RSC | OIL COND KIT | | | | 30.10 |
| | 1 | 007603-014106 | SEAL RING, VLRUB | | | | 4.34 |
| 00001R | | | Replace Engine Oil | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| | 7 | 000989790219BIFU | MB 229.5 SAE 5W-40 BULK | | | | 51.52 |
| | 7 | HAZ OIL DISPOSAL FEE | | | 0.10 | 0.10 | 0.70 |
| 00003R | | | Replace Engine Oil Filter | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| | 1 | 276-180-00-09 | TS OIL FILTER ELEMENT | | | | 29.50 |
| 00004M | | | Reset Service Indicator | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 00018R | | | Replace Brake Fluid | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| | 2 | 000-989-56-05-09-0109 | BRAKE FLUID | | | | 58.68 |
| 00034R | | | Replace Dust Filter | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| | 1 | 212-830-03-18-90 | DUST FILTER - STARPART | | | | 41.65 |
| 0029CN | | | Clean A/C Water Drain | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 0032IN | | | Inspect Drive Belt(s) | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 0033IN | | | Inspect Propeller Shaft Flex Disc | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 0057IN | | | Inspect Parking Brake Operation | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 0067IN | | | Inspect Steering Gear and Linkage | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 0069IN | | | Inspect Suspension Ball Joints | | | | |
| | 1017 | CM | | | | 0.00 | 0.00 |
| 0079IN | | | Inspect Tires and Adjust Air Pressures, | | | | |

This pricing reflects payments by cash payment options. There is a 3% processing fee on all Credit Cards, which is not greater than our cost of acceptance. There is no processing fee for Non-credit card transactions.

BAR # ARD00266597
EPA # CAL000366984

| ORIGINAL ESTIMATE: \$ | | | FINAL REVISED ESTIMATE: \$ | | | DESCRIPTION | TOTALS |
|---|------|---------|--|-------------------|---------------|------------------------|--------|
| DATE | TIME | PHONE # | AUTHORIZED | ADDITIONAL AMOUNT | REVISED TOTAL | LABOR AMOUNT | |
| | | | | | | PARTS AMOUNT | |
| | | | | | | GAS, OIL, LUBE | |
| | | | | | | SUBLET AMOUNT | |
| | | | | | | MISC. CHARGES | |
| | | | | | | TOTAL CHARGES | |
| | | | | | | LESS ADJUSTMENTS | |
| I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE. | | | I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE. | | | SALES TAX | |
| | | | | | | PLEASE PAY THIS AMOUNT | |

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

CUSTOMER #: 1052976

662555



Mercedes-Benz of Fairfield

INVOICE

2950 AUTO MALL PARKWAY · FAIRFIELD, CA 94533 (707) 430-0101 · www.mercedesfairfield.com

PAGE 3

Service Center Hours: MONDAY- FRIDAY 7:30 A.M. - 6:00 P.M. SATURDAY 8:00 A.M. TO 4:00 P.M.

SERVICE ADVISOR: 976 JENNA CASTLEMAN

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE

Table with columns: R.O. OPENED, READY, OPTIONS, LIST, NET, TOTAL

WASHER ADDITIVE
BRAKE FLUSH PERFORMED
CABIN FILTER REPLACED

B Perform Complimentary Car Wash. A \$19.99 VALUE - No Charge. Passenger cars only Sprinter and Metris vehicles excluded.
WASH Perform Complimentary Car Wash. A \$19.99 VALUE - No Charge. Passenger cars only Sprinter and Metris vehicles excluded.
999 ISP (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C Vehicle completed and ready for pick-up on xx/xx/xxxx and the customer has been notified.
DDATE Vehicle completed and ready for pick-up on xx/xx/xxxx and the customer has been notified.
999 ISP (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

D Perform Complimentary Tire Inspection. Adjust Tire Pressures to manufacturer's specifications as listed on the fuel door (when present). Pressures may vary based on load and temperature.
TP Perform Complimentary Tire Inspection. Adjust Tire Pressures to manufacturer's specifications as listed on the fuel door (when present). Pressures may vary based on load and temperature.
1017 ISP (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00
SET TIRE PRESSURES TO: FRONT 36PSI, REAR 42PSI

E PERFORM MULTI-POINT INSPECTION AND DOCUMENT INSPECTION RESULTS FOR THE CUSTOMER.

Table with columns: ORIGINAL ESTIMATE, FINAL REVISED ESTIMATE, DESCRIPTION, TOTALS. Includes acknowledgment checkboxes and pricing details.

This pricing reflects payments by cash payment options. There is a 3% processing fee on all Credit Cards, which is not greater than our cost of acceptance. There is no processing fee for Non-credit card transactions.

BAR # ARD00266597
EPA # CAL000366984

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

CUSTOMER #: 1052976

662555



Mercedes-Benz of Fairfield

INVOICE

2950 AUTO MALL PARKWAY · FAIRFIELD, CA 94533
(707) 430-0101 · www.mercedesfairfield.com

PAGE 4

Service Center Hours:
MONDAY- FRIDAY 7:30 A.M. - 6:00 P.M.
SATURDAY 8:00 A.M. TO 4:00 P.M.

SERVICE ADVISOR: 976 JENNA CASTLEMAN

| | | | | | | | |
|---------------|------------|----------------|-------------------|----------|------------------|---------|-----------|
| COLOR | YEAR | MAKE/MODEL | VIN | LICENSE | MILEAGE IN / OUT | TAG | |
| | 16 | MERCEDES SL400 | WDDJK6FA1GF038254 | | 23144/23147 | TB604 | |
| DEL. DATE | PROD. DATE | WARR. EXP. | PROMISED | PO NO. | RATE | PAYMENT | INV. DATE |
| 01JAN16 IS | | | 18:00 07MAY24 | | | CASH | 07MAY24 |
| 01JAN16 DD | | | | | | | |
| R.O. OPENED | | READY | | OPTIONS: | | | |
| 09:01 07MAY24 | | 15:49 07MAY24 | | | | | |

| LINE | OPCODE | TECH | TYPE | HOURS | LIST | NET | TOTAL |
|------|--------|------|------|-------|------|-----|-------|
|------|--------|------|------|-------|------|-----|-------|

MPI PERFORM MULTI-POINT INSPECTION AND DOCUMENT
INSPECTION RESULTS FOR THE CUSTOMER.

999 IMPI

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: (N/C)
0.00

ESTIMATE: 684.94 07MAY24 09:01 SA: 976

CONTACT:

*****THE FOLLOWING WORK WAS RECOMMENDED BUT NOT PERFORMED*****

DESCRIPTION: BR20 FRONT BRAKE PADS AT 5MM. ROTORS HAVE EXCESSIVE LIP. REC REP
 REASON DENIED: DEC
 PERSON CONTACTED:
 COMMENTS: None
 RECOMMENDED BY: 976 CASTLEMAN DENIAL ADDED BY: 976 CASTLEMAN
 LINE ASSOCIATED: ESTIMATE: 1193.94

| | | | | | | | | |
|--|---|------|--|------------|-------------------|---------------|------------------------|--------|
| This pricing reflects payments by cash payment options. There is a 3% processing fee on all Credit Cards, which is not greater than our cost of acceptance. There is no processing fee for Non-credit card transactions. | ORIGINAL ESTIMATE: \$ _____ | | FINAL REVISED ESTIMATE: \$ _____ | | | DESCRIPTION | TOTALS | |
| | DATE | TIME | PHONE # | AUTHORIZED | ADDITIONAL AMOUNT | REVISED TOTAL | LABOR AMOUNT | 441.95 |
| | | | | | | | PARTS AMOUNT | 221.54 |
| | | | | | | | GAS, OIL, LUBE | 0.00 |
| | | | | | | | SUBLET AMOUNT | 0.00 |
| | | | | | | | MISC. CHARGES | 0.70 |
| | | | | | | | TOTAL CHARGES | 664.19 |
| | | | | | | | LESS ADJUSTMENTS | 0.00 |
| | I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE. | | I ACKNOWLEDGE RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE. | | | | SALES TAX | 18.61 |
| | BAR # ARD00266597 EPA # CAL000366984 | | | | | | PLEASE PAY THIS AMOUNT | 682.80 |

NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK

Customer Name: _____ Date: 05/07/2024 Advisor: Jenna Castleman
VIN#: WDDJK6FA1GF038254 RO Number/Hat#: 662555 B604
Vehicle Year: 2016 Model: SL400 Mileage: 23144

BRAKE INSPECTION **CHECK TIRES & TREAD DEPTH** **CHECK BATTERY & HORN**

BRAKE PAD AND ROTOR WEAR: EXISTING FRICTION MATERIAL
 Over 50% 20% - 50% Less than 20%



BRAKE PAD: LF LR RF RR

ROTOR WEAR: LF LR RF RR

Emergency Brake Adjustment
 Yes No

4.1mm or greater
LF 2.1mm - 4.0mm
 2mm or less
PSI@: _____ set to: 36 PSI
 4.1mm or greater
LR 2.1mm - 4.0mm
 2mm or less
PSI@: _____ set to: 42 PSI

4.1mm or greater
RF 2.1mm - 4.0mm
 2mm or less
PSI@: _____ set to: 36 PSI
 4.1mm or greater
RR 2.1mm - 4.0mm
 2mm or less
PSI@: _____ set to: 42 PSI

Horn operation

Battery condition

Battery cables and connections

EXTERIOR LIGHTS

Head lights Tail lights Turn signals Brake lights Hazard warning lights Comments: _____

INSTRUMENT CLUSTER CHECKS

Warning Lights Service Reminder FSS Check

CHECK FLUID LEVELS **DRIVETRAIN**

Engine Oil Requires Fluid Leaking No Visible Leaks
 Transmission Oil Requires Fluid Leaking No Visible Leaks
 Brake Fluid Requires Fluid Leaking No Visible Leaks
 Windshield Washer Fluid Requires Fluid Leaking No Visible Leaks
 Coolant Requires Fluid Leaking No Visible Leaks
 Power Steering Fluid Requires Fluid Leaking No Visible Leaks

Transmission Performance
 Poor forward shift pattern
 Banging into gear
 Poor reverse gear response
 Road test performed



CHECK THE FOLLOWING COMPONENTS FOR WEAR, DAMAGE, LEAKS OR PROTECTION

WINDSHIELD, WIPER, WASHER INSPECTION: Reason for yellow or red:
 Condition of wiper blades & washer operation Worn Frt Worn Rear (Replace every 12 months)
 Condition of windshield Front Rear Damage _____

UNDER THE HOOD VISUAL INSPECTION: Reason for yellow or red:
 Condition of engine and mounts Leaking Worn Broken Road Test Performed
 Condition of drive belt (s) Worn Broken
 Condition of steering pump lines, hoses Leaking Worn Broken
 Condition of HVAC temperature and fan speed Leaking Worn Broken
 Condition of radiator, hoses, heater hoses and coolant Leaking Cracked Coolant Protection



UNDER VEHICLE INSPECTION: Reason for yellow or red:
 Condition of suspension ball joints, control arms, steering linkage Leaking Worn Broken
 Condition of drive axle/boots, drive shaft, flex disc and U joints Leaking Worn Broken
 Condition of shocks, struts and automatic leveling systems Leaking Worn Broken
 Condition of exhaust system Leaking Loose Broken
 Condition of fuel lines Leaking Loose Broken

Service Indicator Key:
Red = Immediate action recommended, Yellow = Action strongly recommended within 2000-5000 miles. Speak with Service Advisor and refer to maintenance manual.
Green = No action required, keep with recommended service, see maintenance manual

Recommendations _____

Next Service _____ Miles Technician Eric Cross Appointment scheduled: yes no