

NVOICE #		DATE 08/06/2020	TOTAL DUE \$1,845.36	DUE DATE 08/06/2020	ENCLOSED	
	BILL TO					

MODEL / COLOR

1966 FERRARI 330 GTC

ACTIVITY	QTY	RATE	AMOUNT
Parts ignition coil	1	106.30	106.30T
Parts MSN ignition box	1	314.09	314.09T
Parts Coil wire	2	8.50	17.00T
Parts Oil filter	2	21.36	42.72T
Parts Battery cutoff switch	1	95.00	95.00T
Gasoline & Oil Quarts of engine oil	10	11.50	115.00T
Gasoline & Oil Barrel leaded fuel	1	118.00	118.00T
Labor Replace right ignition box, replace right ignition coil, install battery cutoff switch, replace oil & filter, check charging & electrical systems, check all fluids & tire pressures set to 32psi front & 30psi rear (cold)	5.50	175.00	962.50
Taxable sales (Parts) total = \$808.11		TOTAL	1,770.61
	ΤΑΧ ΤΟΤ	(9.25%)	74.75 1,845.36
		AL ANCE DUE	\$1,845.36

UNITED AUTO COLLISION CENTER

25

gabeuacc@gmail.com 1369 Rollins Road, BURLINGAME, CA 94010 Phone: (650) 548-0954 FAX: (650) 548-0981 Workfile ID: PartsShare:

State EPA:

BAR:

ef7ffbf2 5PT3wV

CAL000309565 AE221661

	Preliminary Estin	nate	iors	
Customer:			Job Nu	mber
	Written By: Gabriel Ar	ias		
Insured:	Policy #:	Claim #:		
Type of Loss: Point of Impact:	Date of Loss:	Days to Re	pair: 0	
Owner:	Inspection Location: UNITED AUTO COLLISION CENTE 1369 Rollins Road BURLINGAME, CA 94010 Repair Facility (650) 548-0954 Business	PA	Company:	
11.5	VEHICLE	\$8	24170	
1967 FERR 330			20 1	
VIN:	Interior Color:	Mileage In:	Vehicle Out:	
License:	Exterior Color:	Mileage Out:		
State:	Production Date:	Condition:	Job #:	

Preliminary Estimate

2

Customer:

1967 FERR 330

Job Number:

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	R&I	FT BUMPER				4.0	2.684
2	#	R&I	RT / LT HEADLAMPS				1.0	
3	#	R&I	GRILLE				1.0	
4	#	R&I	RT & LT SIDE MARKERS				0.8	
5	#	R&I	RT & LT SIDE TRIM				2.0	
6	#	R&I	RT & LT EMBLEMS				0.8	
7	#	R&I	RT & LT ROCKER MOLDINGS				2.0	
8	#	R&I	RT & LT WIPERS AND SPRAY NOZZLES				1.6	
9	#	R&I	RT & LT FENDER LINERS				2.0	
10	#	Rpr	FT NOSE PANEL				4.0	3.0
11	#	Refn	CLEAR COAT					1.0
12	#	Rpr	RT FENDER				1.0	3.0
13	#	Refn	CLEAR COAT					1.2
14	#	Rpr	LT FENDER				1.0	3.0
15	#	Refn	CLEAR COAT					1.0
16	#	R&I	HOOD				3.0	
17	#	Rpr	HOOD				2.0	3.0
18	#	Refn	CLEAR COAT					1.0
19	#	Rpr	ENGINE BAY EDGE				3.0	1.0
20	#	Rpr	WIPER COW AREA PANEL				1.0	1.0
21	#	Rpr	LT DOOR				0.5	3.0
22	#	R&I	LT MIRROR				0.5	
23	#	R&I	LT BELT MOLDING				0.3	
24	#	· R&I	RT REAR WHEEL				0.3	
25	#	Subl	RT REAR WHEEL RE SURFACE		1	200.00 X		
26	#	R&I	LT HANDLE				0.3	
27	#	Subl	Hazardous waste removal		1	5.00 X		
28	#	R&I	LT INNER DOOR PANEL				0.5	
29	#		Color tint / color match		1		0.5	
30	#	A LANGERT	De Nib and Finesse	an acreative	1	OR DISCOUN	3.0	
CURF	TIME"	MEANS THE	LENGTH OF THE THET PE	SUBTOTALS	MARUFACT	205.00	36.1	21.2

CC ONE Setimating - A product of SEC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTO/ CRASH ESTIMATING OUTDE:

TO THE FEDERAL MOTOR VEHICLE SAFETT STANDARDS AND THE VEHICLE MANUFACTURER'S SPECIFICATIONS.

narcheotreau of venomotive Repair, prikeenvironmental Protection Agency, hieltsan hattonat Highway Transportation and Safety Administration, PDR=Pointiess Dent Repair, Vitia Vehicle Toenchostern Number

Preliminary Estimate

Customer:

1967 FERR 330

Job Number:

ESTI	MA	TE	TO	TAI	S
LOIT	1-1/4		10	IA	-0

Category	Basis		Rate	Cost \$
Parts				0.00
Body Labor	36.1 hrs	@	\$ 120.00 /hr	4,332.00
Paint Labor	21.2 hrs	@	\$ 120.00 /hr	2,544.00
Paint Supplies	21.2 hrs	@	\$ 50.00 /hr	1,060.00
Miscellaneous				205.00
Subtotal				8,141.00
Sales Tax	\$ 1,060.00	0	9.5000 %	100.70
Grand Total				8,241.70
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				8,241.70

2.

FOR YOUR PROTECTION CALIFORNIA LAW REQUIRES THE FOLLOWING TO APPEAR ON THIS FORM: ANY PERSON WHO KNOWINGLY PRESENTS FALSE OR FRAUDULENT CLAIM FOR THE PAYMENT OF A LOSS IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN STATE PRISON.

THE FOLLOWING IS A LIST OF ABBREVIATIONS OR SYMBOLS THAT MAY BE USED TO DESCRIBE WORK TO BE DONE OR PARTS TO BE REPAIRED OR REPLACED:

MOTOR ABBREVIATIONS/SYMBOLS: D=DISCONTINUED PART, A=APPROXIMATE PRICE. LABOR TYPES: B=BODY LABOR, D=DIAGNOSTIC, E=ELECTRICAL, F=FRAME, G=GLASS, M=MECHANICAL, P=PAINT LABOR, S=STRUCTURAL, T=TAXED MISCELLANEOUS, X=NON TAXED MISCELLANEOUS. CCC ONE: ADJ=ADJACENT, ALGN=ALIGN, A/M=AFTERMARKET, BLND=BLEND, CAPA=CERTIFIED AUTOMOTIVE PARTS ASSOCIATION, D&R=DISCONNECT AND RECONNECT, EST=ESTIMATE, EXT. PRICE=UNIT PRICE MULTIPLIED BY THE QUANTITY, INCL=INCLUDED, MISC=MISCELLANEOUS, NAGS=NATIONAL AUTO GLASS SPECIFICATIONS, NON-ADJ=NON ADJACENT, O/H=OVERHAUL, OP=OPERATION, NO=LINE NUMBER, QTY=QUANTITY, RECOND=RECONDITION, REFN=REFINISH, REPL=REPLACE, R&I=REMOVE AND INSTALL, R&R=REMOVE AND REPLACE, RPR=REPAIR, RT=RIGHT, SECT=SECTION, SUBL=SUBLET, LT=LEFT, W/O=WITHOUT, W/_=WITH/___ SYMBOLS: #=MANUAL LINE ENTRY, *=OTHER [IE..MOTORS DATABASE INFORMATION WAS CHANGED], **=DATABASE LINE WITH AFTERMARKET, N=NOTES ATTACHED TO LINE. OPT OEM=ORIGINAL EQUIPMENT MANUFACTURER PARTS EITHER OPTIONALLY SOURCED OR OTHERWISE PROVIDED WITH SOME UNIQUE PRICING OR DISCOUNT.

"CURE TIME" MEANS THE LENGTH OF TIME THAT, PER THE ADHESIVE MANUFACTURER, THE WINDSHIELD ADHESIVE NEEDS TO CURE UNTIL THE WINDSHIELD CAN PROPERLY FUNCTION AS A SAFETY DEVICE PURSUANT TO THE FEDERAL MOTOR VEHICLE SAFETY STANDARDS AND THE VEHICLE MANUFACTURER'S SPECIFICATIONS.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.



BILL TO

	DATE			5401 0055
INVOICE #	DATE	TOTAL DUE	DUE DATE	ENCLOSED
15-1508	01/08/2019	\$3,428.70	02/01/2019	

MODEL / COLOR 1966 Ferrari 330GTC

MILEAGE IN 95,280

ACTIVITY	QTY	RATE	AMOUNT
Parts Oil filters	2	28.60	57.20T
Parts Quarts engine oil	11	8.50	93.50T
Parts Alternator pulley	1	345.00	345.00T
Parts Cooling fan relay	1	65.00	65.00T
Parts Can of high temp orange paint	1	21.00	21.00T
Parts Gal. Antifreeze/coolant	1	16.50	16.50T
Parts Gal. Distilled water	3	2.50	7.50T
Sublet Labor Alignment check	1	145.00	145.00
Labor Replace engine oil & filters, remove & clean fuel filter screens, remove radiator to be able to remove the alternator & replace the alternator pulley, discovered that the cooling fans were inop & replaced the relay. wirebrush inside the tail pipes, clean and repaint. High heat orange, check tire pressures (14-18psi). Set to 34psi front & 32psi rear	15	175.00	2,625.00
Taxable sales (Parts) total = \$605.70			3,375.70
Notes:	ΤΑΧ ΤΟΤ	(8.75%)	53.00 3,428.70
 Tire pressures should be monitored weekly set to 34psi Front & 32psi Rear. COLD Right rear shock absorber defective 	_	AL ANCE DUE	\$3,428.70 \$3,428.70
- Carburatore need full reconditioning, the shafts			

- Carburetors need full reconditioning, the shafts have too much play

The Pit Stop Automotive

The Pit Stop Automotive US

(415) 859-5548 pitstop130@gmail.com



	Мо	del / Color	Reg	istration No	Mileage In
	Ferr	ari 330GTC	2	815K	33471
Service	Activity		Quantity	Rate	Amount
Labor \$195	 Final fitting of engine, and transaxle, drive shaft. Tuning, Remove headers and repair warpage. Remove valve covers Re-Torque head, Re-adjust valves, Set ignition timing.Pain 	t and	62.5	195.00	12,187.50
1 0105	install exhaust heat shields and replace engine-oil three tim	es.	29.5	105.00	5 752 50
Labor \$195	• Remove and replace front shocks. Rebuild rear suspension and replace shocks. Bleed the brakes.		29.5	195.00	5,752.50
Labor \$195	• Remove radiator assembly, Remove and replace A/C comp Replace harmonic balancer and evacuate A/C system and r		16	195.00	3,120.00
Sublet Labor	Rebuild and modify alternator		1	663.00	663.00
Sublet Labor	Fabricate fuel pump plate		1	110.00	110.00
Sublet Labor	. Mount and balance tires on newly painted wheels		1	100.00	100.00
Sublet Labor	• Dismount 5 tires with inner tubes		1	70.00	70.00
Sublet Labor	• Sandblast wheels, tape off centers, fill deep pits before pow coating	vder	5	320.00	1,600.00
Sublet Labor	• Detailing		1.	. 250.00	250.00
Sublet Labor	• Wheel alignment		1	216.00	216.00
Sublet Labor	• Trunk carpet and side panel redone		1	810.00	810.00
Gasoline & Oil	Leaded gas for break-in		2	100.00	200.001
Parts	• 30 W break in oil		22	8.50	187.001
Parts	• K&N filter		3	46.00	138.00T
Parts	Vacum reservoir	÷	1	60.00	60.00T
Parts	• Oil/Water temp. sender		1	25.60	25.601
Parts	Clutch hose		1	23.40	23.401
Parts	Clutch slave cylinder		1	40.38	40.381
Parts	Boot/shift linkage		1	94.80	94.807
Shipping	 shipping of boot/shift linkage 		1	8.88	8.88
Parts	• Battery		1	145.19	145.197
	Continue to the next page				

Date	Invoice #
01/27/2015	15-1158

2.

Page 2 of 2

Service	Activity	Quantity	Rate	Amount
Parts	• Nut/Hex	4	8.79	35.16T
arts	• New front & rear shocks NOS	4	610.00	2,440.00T
arts	• Dunlop servo valve	1	141.60	141.60T
hipping	Shipping of Dunlop servo valve	1	6.00	6.00
arts	• V-belt	2	14.28	28.56T
arts	• Oil-filter for break-in oil	4	22.00	88.00T
arts	• Engine Oil	11	8.50	93.50T
arts	Rebuilt A/C Compressor	1	385.00	385.001
arts	Used harmonic balancer	1	500.00	500.001
Parts	• Complete set of rear suspension bushings	1	719.44	719.447
Parts	• Coolant / antifreeze	1.5	16.75	25.137
Parts	• Distilled water	4	2.50	10.007
Parts	A/C Compressor Oil	0.5	14.50	7.251
Parts	• A/C Fluorescent Dye	1	18.00	18.007
Parts	• R12 Freon	3	60.00	180.007
ui to				
	5.			
				Υ.
	£			
	1		-	
t)				
Return in 500 m	niles for:		SubTotal	\$30,479.
Service Valve-adjustr			Tax (9%)	\$502.
Tightening of	suspension and hopefully the last alignment.			
0	· · · · · · · · · · · · · · · · · · ·		Total	\$30,982.

1

- Oil-change in 1500 miles

		Ç Sign in
The Pit Stop AutomotiveInvoiceDue date14-1119Nov 30, 2014	\$16,045.94	
		Print Save PDF
		Send a message Have a question? Add file Send
		December 4, 2014 THURSDAY You viewed this invoice. 12:02 PM Thursday
		Powered by QuickBooks Privacy. Terms of service.
	x	•

13

IN	VIC	ICE#	
111	VU		

2292-13

Customer Inf	ormation			
Name:				1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Address:	1000	1	Initial estimate:	1 9.74
City/St/Zip:			Date:	September 12, 2013
Phone:				
Vehicle Inform	mation			
Model:	1966 FERRARI 330 GTC		316.02	5 018/00
Reg.:	GADIEST CYLINDICH HEAD	Signature:		
Mileage in:	NEATBA VACUE SCHARE		142.00	\$ \$42.60
Color:	SILVER			

PAY THIS AMOUNT:

21,608.80

\$

ITEM	HRS	LABOR		RATE		COST
1	1.1.1	REMOVED ALL COMPONETS IN ENGINE BAY AFTER POWER WASHING		7912-001	\$	792.200
2	1.12	SAND, BONDO AND PRIMER. TWO TOP COATS OF BLACK			\$	- 93-90
3		CLEANED BRAKE LINES, AND OTHER ELECTRICAL WIRES			\$	-
4	26.00	INSTALLED NEW HEATER HOSE, ASSEMBLED HEATER CORES	\$	145.00	\$	3,770.00
5	17.00				\$	
6	47.00	ASSEMBLE ENGINE SHORT BLOCK	\$	195.00	\$	9,165.00
7	1.1.1				\$	7 -
8		REBUILD STEERING BOX & IDLER BOX, REBUILD FRONT SUSPENSION,	7.40		\$	-
9	14.00	PREP FOR INSALATION	\$	195.00	\$	2,730.00
10					\$	
11					\$	-
12					\$	(-)
13	i				\$	141 (H
14					\$	
15					\$	
16					\$	
17					\$	-
18					\$	-
Sub:	87.00	LABOR TOTAL			\$	15,665.00
ltem		SUBLET				COST
1.		S/H OF SEALS 9-12-13			\$	9.06
2		S/H OF SEALS 9-17-13			\$	9.23
3		POWDER COATING OF SPRINGS, CONTROL ARMS, SWAY BAR			5	
4		MISC BRACKETS, STRIP PAINT OF ALUM. INNER FENDERS			\$	475.00
5		R&R BUSHINGS 12 RODS (AT MACHINE SHOP)			\$	298.00
6		2 HEATER CORES			\$	442.00
7		POWER BRAKE BOOSTER REBUILT, INCLUDING SHIPPING			\$	495.00
8	ALC: NOTE:				1.1.1.1.1.1	
9	1.5 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				Charles and	
10	2				1.2521012	
					A CONTRACT OF	
11 Sub:		SUBLET TOTAL				



2292-13

Item	QTY	PARTS		List ea.		Price
1	2	OIL SEAL	\$	3.93	\$	7.86
2	1	OIL SEAL	\$	9.74	\$	9.74
3	1	100X120X13 OIL SEAL	\$	24.51	\$	24.51
4	1	40X56X10 CON. OIL SEAL	\$	11.12	\$	11.12
5	1	19X32X7TC SEAL	\$	3.30	\$	3.30
6	1	INNER FENDER PANEL TRIM-RUBBER	\$	316.00	\$	316.00
7	1	GASKET CYLINDER HEAD	\$	298.20	\$	298.20
8	1	HEATER VALVE COVER	\$	142.00	\$	142.00
9	1	HEATER VALVE DIAPHRAM	\$	52.70	\$	52.70
10	1	COOLANT TAP	\$	97.50	\$	97.50
11	1	HEATER DIAPHRAM	\$	26.21	\$	26.21
12	1	VALVE SPRING SET	\$	1,213.00	\$	1,213.00
13	1	ROLL OF HEATER HOSE	\$	48.30	\$	48.30
14	1	32" BROWN LEATHER COVERED OIL LINE HOSE 21\$/ INCH	\$	672.00	\$	672.00
15	1	44" YELLOW LEATHER COVERED FUEL HOSE 18\$/ INCH	\$	792.00	\$	792.00
16	12	HOSE END FITTINGS	\$	12.75	\$	153.00
17					\$	-
18					\$	-
19					\$	1,170-00
20					\$	-
21					\$	1. N. 1. 1. 1. 1.
22					\$	-
23					\$	
24		pd \$10,000	1	2 11	\$	
25		PU \$10,000	6-1:	2-14	\$	-
26			5		\$	-
27					\$.).
28					\$	-
29					\$	-
30					\$	
31					\$	-
32					\$	-0
33					\$	-
34					\$	
35					\$	
36					\$	
37					\$	
38		SMOP SEALS & 1743			\$	5.25
39					\$	6.13
40		MISC BRADNETS, STREPARTS OF A 201 Second process			\$	<u>-</u>
41		FRAME STREET OF SCHOOL SCHOOL SCHOOL			\$	1945.50
42 43		2 Million Contra			\$	100 00
43					\$	442 62
Sub:		PARTS TOTAL			э \$	3,867.44
						0,001111
			ES TAX	9.00%		

Thank	vou for	vour	continued	patronage

INVOICE#

Customer Information			
Name:		01.00.10	208.02
Address:	Ir	itial estimate:	205.92
City/St/Zip:		Date:	09.09.2010
Phone:			
Vehicle Information		01.00	52.55
Model: 1967 FERRARI 330 GTC		0.50 5	71.50
Reg.: 815K	Signature:		
Mileage in: 91611		18.00 3	224.00
Color: SILVER	ADE		

PAY THIS AMOUNT:

The Pit Stop 130 Industrial Way Brisbane, California 94005 Tel: 415.656.1443 Fax: 415 656 1055

5,044.18

\$

ITEM	HRS	LABOR	RATE	COST
1				\$ -
2		REMOVE WHEELS, RE-PACK GREASE, REPLACE TIE ROD ENDS,		\$ -
3		REPLACE OIL/ FILTER, REPLACE RADIATOR CAPS, GENERAL CHE		\$
4		CK UP. REPACK & ADJUST IDLER ARM ASSEMBLY, ADJUST STEER		\$
5	6.00	ING BOX & REPLACE OIL.	\$ 145.00	\$ 870.00
6		REPLACE HEATER/VENT TUBES, REBUILD BRAKE MASTER CYL.,	1.1.1	\$ \
7		REMOVE GAS TANKS, REPLACE FILLER HOSE, REPLACE VENT	200	\$
8	11.50	HOSES,	\$ 145.00	\$ 1,667.50
9				\$ -
10				\$ -
11				\$
12				\$ -
13			100	\$
14				\$ - 54. M
15			5 5 3	\$ -
16				\$
17			1.00	\$ -
18				\$ -
Sub:	17.50	LABOR TOTAL		\$ 2,537.50

Item	SUBLET	COST
1 2 3	MOUNT & BALANCE 5 TIRES	\$ 125.00
4	4 WHEEL ALLIGNMENT	\$ 225.00
6 7	Λ	
8 9		TRANSPORT STATES
10 11		CONTRACTOR OF STREET
Sub:	SUBLET TOTAL	\$ 350.00

INVOICE#

2120-10

The	e Pit Stop Brisbane, California 94005
130 Industrial Way	Brisbane, California 94005
	Fax: 415 656 1055

ltem	QTY	PARTS		L	ist ea.		Price
1	3	RIGHT HAND TIE ROD ENDS		\$	68.64	\$	205.92
2	3	LEFT HAND TIE ROD ENDS		\$	68.64	\$	205.92
3	1	RADIATOR CAP		\$	43.47	\$	43.47
4	1	EXPANSION TANK CAP		\$	31.68	\$	31.68
5	2	OIL FILTERS		\$	26.40	\$	52.80
6	11	QRTS. ENGINE OIL		\$	6.50	\$	71.50
7	5	MICHELIN INNER TUBES		\$	28.95	\$	144.7
8	14	FT. HEATER/VENT TUBING		\$	16.00	\$	224.00
9	1	BRAKE MASTER CYLINDER UPGRADE		\$	964.00	\$	964.0
10	1	BRAKE FLUID		\$	18.54	\$	18.5
11	1	GEAR OIL		S	11.50	\$	11.50
12		GENTROLE		÷	11.00	\$	-
13						\$	-
14						\$	
15						\$	
16						\$	
17						\$	
18							
19						\$	1.1.1.1.1.1.1.1.1
						\$	47:0
20						\$	/-
21						\$	
22						\$	E.887-8
23						\$	
24						\$	-
25						\$	-
26						\$	-
27						\$	11.22
28						\$	
29	*					\$	
30						\$	
31						\$	
32						\$	
33		and the second				\$	-
34						\$	
35						\$	and the second second
36						\$	
37						\$	-
38						\$	125.0
39						\$	
40		A WHERE ALL CAMPACT					226.0
41						\$	
42						\$	
43						\$ \$ \$ \$	-
44						\$	-
Sub:		PARTS TOTAL				\$	1,974.08
			SALES TAX		9.25%	C	190.0
			SALES TAX	No.	9.29%	\$	182.60

Th	e Pit Stor Brisbane, California	2
130 Industrial Way	Brisbane, California	94005
	Fax: 415 656 1055	

PAY THIS AMOUNT:

IN	IV	οι	C	E#

Customer Information			
Name:			
Address:	Initia	l estimate:	54.00
City/St/Zip:		Date:	03.26.2010
Phone:			
Vehicle Information			
Model: FERRARI 330 GTC		in and in	40.00
Reg.:	Signature:		
Mileage in:			
Color: SILVER			

1,562.83

\$

HOURS			RATE		COST
2.00					COST
	LUBE, OIL & FILTER	\$	145.00	\$	290.00
				\$	
	REPLACE RECEIVER / DRIER, EVACUATE A/C SYSTEM & RECHARGE			\$	-
2.50	FREON	\$	145.00	\$	362.50
				\$	\ -
	UN-LOCK TRUNK, FABRICATE NEW TRUNK RELEASE CABLE &			\$	-
4.00	RE-COAT NEW KEY	\$	145.00	\$	580.00
				\$	-
					-
					-
				\$	2
					-
					-
				\$	-
				\$	-
				\$	2
					-
8.50	LABOR			\$	1,232.50
					0007
	SUBLET				COST
	a				
	SUBLET			\$	
	8.50	8.50 LABOR SUBLET	8.50 LABOR SUBLET	8.50 LABOR SUBLET	\$ \$

INVOICE#

2050-10

The Pit Stop130 Industrial WayBrisbane, California94005Tel: 415.656.1443Fax: 415 656 1055

1.4

amla	and't a	PARTS		List	-	
em Qu				List ea.		rice
	12	OIL		\$ 4.50	\$	54.0
2	2	OIL FILTER		\$ 26.40	\$	52.8
3	1	ACCUM / DRIER		\$ 58.64	\$	58.6
4	2	ADAPTER		\$ 6.46	\$	12.9
5	1	TRUNK RELEASE CABLE	and a survey of the second	\$ 46.00	\$	46.0
6	3	FREON, 3 LBS	Signature:	\$ 26.00	\$	78.0
7					\$	-
8					\$	-
9				and the second	\$	-
10					\$	-
11						-
12				State Street	\$ \$	_
13				Georgen a	\$	
14				RATE	\$	180
				145 60	\$	290
6					\$	
7				1	\$	
8				145.00	\$	362
9						\$
20				1.1.1	\$	١-
1				145.00	\$	
				190.00	\$	1980-
22					\$	-
23				1.00	\$	-
24				6.	\$	
25				1.1.1.1	\$	-
26					\$	
27					\$ \$	1.00
28					\$	-
29					\$	-
30					\$ \$ \$	-
31					\$	-
32					\$	1
33					\$ \$	-
34					\$	-
35				Sector Sector Sector	\$	-
36					\$	
37					\$	-
88					\$	-
9					S	-
10					\$	
11		н н			\$	-
12					\$	-
43				2	* * * * * * *	
14						-
ıb:		PARTS			\$	302.
			SALES TAX	9.25%	e	07
			SALES TAX	9.25%	\$	27.

	MILEAGE	DISCRIPTION	COST	TOTAL
3/19/98	67615	PURCHASED FROM HERITAGE CLASSICS	\$58,438	58438
3/19/98	67677	BEVERLY HILLS FERRARI TO MAKE ROAD SAFE	2312	60750
3/27/98		TOM-FRONT BUMBER, TOOL, BOOKS & MISC	1500	62250
3/27/98		OWNER MANUAL	97	62347
3/27/98		MISC BOOKS-PARTS, SHOP & REPAIR	379	62726
3/29/98		LEO-MISC PARTS USES FRONT LIGHT	400	63126
4/9/98		BRAKE PART, PEDALS, RESERVOIRS & OTHER	335	63461
4/9/98		KNOCK-OFF TOOL KIT	327	63788
4/17/98		TOM-MISC PART & TOOLS	400	64188
4/19/98		NEW CD & SPEAKER	310	64498
4/20/98		PARTS & AIR FILTER	165	64663
4/23/98		BRIAN-START TO REBUILD ENGINE, TRANS, & INERTIOR	5387	70050
5/21/98		BRIAN-CONTINUATION OF REBUILD WORK	13825	83875
5/22/98		COKER TIRE-5 NEW OLD STYLE MICHELIN 205X14 XWX	1097	84972
6/11/98		DELCO BATTERY 27F-7 YEAR	106	85078
6/25/98		BRIAN-REBUILD WORK	21145	106223
7/2/98	68205	BRING HOME AS A NEW CAR!		0
7/21/98	68785	BRIAN-1000 MILE CHECKUP ADJUSTMENTS & INTERIOR REPAIRS	384	106607
8/24/98		BRIAN FOLLOWUP	1821	108428
9/21/98		MCMASTER-CARR AIR DAMPER	139	108567
9/24/98	69500	BRIAN-OIL CHANGE @ 1500 MILES	221	108788
09/31/98		REORIGINALS 2 SET OF WIRE WIPER' BLADES	124	108912
11/21/98		JACK TOOL BAG	150	109062
11/22/98		MISC TOOLS, TOOL ROLL & BOOKS	600	109662
11/22/98		COMPETITION FIRE EXTINGUSER	120	109782
12/3/98		ANSA REAR EXHAUST PIPES	660	110442
12/11/98		STEBRO SS CENTER EXHAUST PATRS	1443	111885
12/13/98		BLACK BARTS NEW BADGES	379	112264
12/14/98		GT PARTS TERMINAL BLOCK - THE LAST PART	46	112310
12/14/98		PARKER HALL-TOOLS AND DECALS	438	112748
12/15/98		TOM-KONI SHOCK, MORE TOOLS & BOOKS	2800	115548
1/4/99		BRIAN-SHOCK, AIR DAMPERS, & EXHAUST SYSTEM FITTING	3682	119230
2/9/99	70470	LUCAS-REDO DIST, TIMING, CARBS, R/WHEEL BEAR, ADJ VALVES/HEAD	3889	123119
2/19/99		CLARK FRONT/REAR ALIGNMENT	125	123244
2/2/99		TRIM CHROME PART	179	123423

The pressen 32/35

(The

1.202

Invoice for Roger Groves Monarch Beach 7 Marbella

76,600 July 2001

330 GTC#

Rebuild 2 distributors

Replace 2 sets 006 and 2 sets 007 Marcelli contacts and 2 new original condensers

Test and Adjust on dist. Machine

Syn - balance - dwell

Install and time

Tune and sync carbs.

Adjust oil pressure @ filter matrix

Parts; shop and on site time:

\$700.00

2.

Thanks,

Jens

ROGER GROVES RHONDA GROVES 7 MARBELLA MONARCH BEACH, CA 92629

PAGE 1 FEPTAPI OF ORANGE COUNTY 1425 West Baker Street

2 FBHBRA 1 GDB522	YEAR 66 FERRA LICENSE NO. TECH. TY OCKED ON LAUL FRON S, REPLA		91 TELEPHONE 714-240-		CUST. PAY LABOR RATE 89.0	Deliver Date		POO BY 43	731 s/A 43
MILEAGE IN MILEAGE OUT 75703 75754 FRONT BRAKES L 99999 OVERH CALIPER 2 FBHBRA 1 GDB522	66 FERRA LICENSE NO. TECH. TY OCKED ON IAUL FRON 2S, REPLA	RI 330 GTC	714-240-			DATE		BY	
75703 FRONT BRAKES L 999999 OVERH CALIPER 2 FBHBRA 1 GDB522	LICENSE NO. TECH. TY LOCKED ON LAUL FRON LS, REPLA	PE HOURS LIST/UNIT		-4410	89.0		N66	43	43
75703 FRONT BRAKES L 99999 OVERH CALIPER 2 FBHBRA 1 GDB522	OCKED ON AUL FRON S, REPLA		NET/UNIT						
FRONT BRAKES L 99999 OVERH CALIPER 2 FBHBRA 1 GDB522	OCKED ON AUL FRON S, REPLA		NET/UNIT	-					
99999 OVERH CALIPER 2 FBHBRA 1 GDB522	OCKED ON AUL FRON S, REPLA		NET/UNIT						
1 SP2511 1 SP2531 2 643858 2 643254 4 643860 2 643854 2 860370 4 70008 1 FBHBRA 2 643258 SC GAS PO#731 CK CLUNCK FROM 99999 REPOS	04 BRAKE KE MTL/P 09 PISTO CP I RH REAR ITION EX	CE PISTONS ALL ST 5.50 S 37.08 ADS 47.38 KIT 63.68 KIT 90.64 ISTON 63.17 ISTON 98.88 N 51.39 ISTON 46.39 3.09 FLUID FLUID 15.43 ST 5.50 NE 63.17 OVER BUMPS HAUST & INSTALL ER BOLTS TIGHEN	1157.00 5.50 37.08 47.38 63.68 90.64 63.17 98.88 51.39 46.39 3.09 15.43 5.50 63.17 35.10 ALL	61.	00 08 38 64 34 76 56 78 18 72 50 34 10				
		GAS,OIL	AMOUNT , LUBE AMOUNT		additi increa ackno receip additi	onal custom ise in the wledge and	er or warr e original approve ele. I also umer ar	anty work estimat all repairs acknow d Warr	approval of a performed and e price. I a s as itemized a vledge receipt anty informat
			CHARGES						orized
		LESS INS	SURANCE		Origina Estimat	l e \$	ti minur Tras na	Revis	
		PLEASE THIS AM	PAY		CUST SIGN/				

ROGER GROVES RHONDA GROVES 7 MARBELLA MONARCH BEACH, CA 92629



REPAIR ORDER WRITTEN	DATE READY	STOCK NO.	VEHICLE	IDENTIFICATION	CUST	NO	TAG NO.	P	.0. NO.	INVO PRIN1		EPA# CAL0002164
		UICONNO.				000000000000	140 100.		.0. 110.	1		
8AUG00	12SEP00		9163		9.	163	1294-14	a series	1246 9109	12SE		731
TIME IN	TIME READY	YEAR	MAKE & MOI	DEL	TELEPHONE	NO.	CUST. LABOR	PAY RATE	DELIV DAT	ERY PF	BY	S/A
		66 FERR	ARI 330 C	STC	714-240	-441	0 89	.00	01JA	N66	43	43
MILEAGE IN	MILEAGE OUT	LICENSE NO					- 1					
75703	75754											
		тесн. 41 С.	TYPE HOURS	LIST/UNIT	NET/UNIT 89.00		89.00	and the second				and the standard
** REP	CE LIPPER		R FRONT E	ATT TOT			89.00					
			R & LOWEF				and and a					
		BOTH SI			A of Determents		THE PROPERTY OF					
		41 C			311.50	3	11.50					
	1 133944	BALL J	JINT		A STREET STREET		and shares					
	LOWE			232.56	232.56		32.56					
) BALL J		150.41	150.41	3	00.82					
			BEARINGS		DOUT		1000					
999		ACE ERON.	T WHEEL E	BEARINGS	BOJH							
	SIDES	41 CI	D		356.00	3	56.00					f = $1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1$
	2 958901		BEARING	52.53	52.53		05.06				17. 11.	
	2 958903			30.78	30.78		61.56					
** REPI			EL BEARIN		242		86. D. O. P.					
999	99 REPLA	ACE LH RI	EAR WHEEL	BEARING	S							
		41 C			311.50		11.50					
	1 101221			64.98	64.98		64.98					
	1 850350			61.88	61.88		61.88					
			GE GASKET		The Mart		191225 R.T. V.					
999	999 REPLA	ACE HEAD	ER FLANGE	GASKETS	222.50	2	22.50					
	4 20268			15.45	15.45		61.80					
	4 20200	EAH/GOK		12.42	15.45		01.00	1.35				
* PRE-1	NVOICE *	**		DESCRI			TALS					and the second
				LABOR A			<u> </u>	ddition	al custon	ner or warr	anty wo	approval of a ork performed and,
				GAS,OIL,	Contraction of the second s	19	60.62 ii	ncrease	in th	e original	estim	ate price. I al
			pul en prove	SUBLET			0 00	eceipt	of veni	cle. I also	o ackno	irs as itemized a owledge receipt
				MISC. CH		10000				sumer an reverse sic		rranty informati
			19-12 C 12-12-14	TOTAL C			43.22					
				LESS INS	and the second second		0 000	riginal			Re	thorized vised
				SALES T	AX	1	51.95	stimate	×	ALC: NO	Est	imate \$
				PLEASE				CUSTOM	ER			
				THIS AM	IOUNT	45	95.17	SIGNATU	RE X_			
		. /										
				an artistatio								

				CE COPY	ΙΟΛΝΙ				
395	200		1ARGE	e l		P	00	16	2 1
003395	By: CS C	TSNN	ARTS LABOR CHARGE	midd	C. C.		150	203	15~
	Written By:	Promised RETAIN PARTS FOR INSPECTION		PA PA	74			IAL	SUB TOTAL SALES TAX HAZARDOUS WASIE DISPOSAL TOTAL
	NO DA			, Re	CLEM		TOTAL	"HE OR	FT SUB TOTAL IN SALES TAX VY HAZARDOUS R WASTE DISPOS AMOUNT
	Deliver YES 🗆	License No. Rusiness License No. Rusiness License No. Rusiness E Rusiness may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on vehicle to secure the amount of repairs thereto.	MADE	Paris Paris	60		Wise you that some amission control devices may still be covered under mig's warranty. By law, you may choose	SPONSIBI SPONSIBI OR LOSS O AMAGE TO	ATTICLES LEFT IN VEHICLES IN CASE OF FIRE THEFT OR ANY THEFT OR ANY THEFT OR ANY CONTROL
	8	Business functions for of delivery at m the amount of	TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE REPAIR ORDER - LABOR INSTRUCTION LC C, Ladiaton Fanis	Ker	HIN IT	-	Å.		a la
14 14	S ado	P Busing along with near along the secure the the secure	S ARRANG 30R INSTI	hend	1 AN		ble	CASH	INTERNAL DBy
Tiamo Motorcars Reversion Service & Restoration 644 Terminal Way • Costa Mesa, Ca 92627 (949) 642-8512 • Fax 642-8514 BAR No. AC 193569		No. K to be done oses of testin	UNLESS ER - LAB	12	The		red under m		
Tiamo Motorcars Prari Service & Restor 4 Terninal Way · Costa Mesa, Ca (949) 642-8512 · Fax 642-85 EAR No. AC 193569		License No.	LY CASH AIR ORD	St. N	44		A (still be cove		
no M Servi mal Wey 642-855 BAR No	S	horize the bel ay operate ve lien is ack	REP	1ch	e de la	-Z			
Tian Herrari 644 Termis (949)	POVE	I hereby aut employees n mechanic's signed X		2 Yo	Alle A		ssion control		
E o	5	141		t I T	1 Star	0	at some emi	ERVICE	
seadt s beidynt britter y britter y britter y	181	420	HK	K K	Ball		dvise you th thork Facility		
Buddense Buddense Constrated Cons	Koc	nodel 7257 916			A to		. This is to a	MENDE	AVE -
	NAME Address CITY	Year-Make-Model Odometer	OPER No.				Smog Cherry This is to ad	RECOMMENDE	USED.
SALE 5 00 5 00			0			Des UL			<u>in 44 in 10</u>
0 272K	A PLAN					200	2		TAM
mult								Or INITIAL	AL I
R-REBUILT		UTSH 25554 2022 2022 2022	121			TOTAL PARTS	2	REPAIRS s and Lab	
CORP. CORP.	851 2 08	207254	SS717 857			TOTAL		TOTAL SPECIAL REPAIRS Amount - for Parts and Lat TIME Direct Phone	ESTIN
TOP CARS	00 16a	101 #	de printe su				5	TOTAL SPECIAL REPAIRS Estimate Amount - for Parts and Labor	
PHOT P	3/22/2000 16:08	Transaction # 1 Card Type: Utsn 4271362072542554 Exp. Date: 0902 Entry: 81281 - 53	h, Code	>	82.4 A A A			Estimate	Amount Addit Auth. Action Acti
C V IV	的前		Res				2220	Add'I Auth	Amount Add'I Auth. Amount NOTICE AN NOTICE AN NOTICE AN NOTICE AN NOTICE AN AN AN AN AN AN AN AN AN AN AN AN AN A

003365		8-24-99	n By: / UCAD	Time Received		.W.	PARTS	PECTION D PARTS	LABOR CHARGE	here here	8				k place	and aich									op ashi	00 621		AL	× 17 25	A STOWN	1642 88
		0 ON	CICILS Written		2-57 Promised	s. You and your isk. An express	Epairs unereru.			all crack	10 200	100 65	P	7.44	Ical COark	C ALCGAN					1/101	n c) N				NOT SPECIAL	PONSIBLE HEPAIKS LOSS OR TOWING	HICLE OR SUB TOTAL	IN VEHICLES IN CASE OF FIRE, SALES TAX THEET OP ANNY	ER CAUSE WASTE DISPOSAL	NTROL. TOTAL
áon 2627		Phone When Deliver Ready YES NO YES	R ALS DIL	Business	N/949 56	I hereby authorize the below/repair/work to be done along with necessary materials. You and your emphases may operate values for purposes of testing, processor of alongery at the processor of the purpose of the processor of the	annu annu annu annu annu annu annu annu	signed X TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE	DR INSTRUCTION	o Tulto	e a	0	en in e	or wel-	Arh CI	crude to		0	11	1 1	V H				de worronty By law you m	the smog check test indicates are necessary.	CASH RES	CHARGE VEN	INTERNAL CAS	OTH	IDE MOI
Tamo Motorcars Fari Service & Restoration Terminal Way - Costa Mesa, Ca 92627	042-0214 * FAX 042-031 BAR No. AC 193569				License No.	w repair work to be done a nicle for purposes of testing,	n Admine in the second in the	Y CASH UNLESS	REPAIR ORDER - LABOR INSTRUCTION			Unces ,	n u	1 Densis	0 + 0	or actit	site Lube		C)		-		etill ha covered under mfr	ustments which the smog				DEPORIDA	OK D By
Tiamo Motorcars Represention Service & Restoration 644 Terminal Way • Costa Mesa, Ca 92627 6440 640 649 • 643 • 644 640 644	EAR No.	10			2306TC.	I hereby authorize the belo employees may operate vel		Signed X TERMS: STRICTI	REP	- antro	1 auccia	F.el	Dreer	50 1 1 0 0 0	der Case	Carlo To	1 aclad a	1 fuel							ssion control devices may	any needed repairs or adj					
and the	un tuose winge ph p et pre ruger oper pp	ver an or	etere year un pe	To the need set tout	Ferenci	0	2	~		when Ct	d twin	the All	and all	uke ri	CNK 7	TimeSert	HK. CLUR	n'n + CeC	5						advise voir that some amis	Check Facility to perform any needed repairs or adjustments which ED SERVICE:					
ander Ander Ander Domony Ander Domony Ander Domony Ander State Ander State And	und self as barran to an ducto a bloc a bub	NAMER 600	ADDRESS CITY	ole guila prist pio buo	Year-Make-Model	50	Vehicle I.D. No. 916		OPER No.	1 Re	And And	2 0	2 2	u l	-	2 2	6 0	7 De							Smon Chack: This is to	RECOMMENDE					OSED ST
SALE SALE	ee S	and and	0	A DUE D'ALIPHE CON			>		0														AMOUNT					N	n	CERIEL ON 4.	WATE NA 2
A-REBUILT		Net	The wargary page	the production of the to																		TOTAL PARTS				EPAIRS	and Labor	ect Phone INITIAL	Direct Phone		ESTIMATE TOTAL
seef 1	hardwar	Ench Stee		LUR MILLING BALO						1		/										TOTAL	SPECIAL REPAIRS			TOTAL SPECIAL REPAIRS	Estimate Amount - for Parts and Labor	TIME Dir		TRAT HO	ESTIM
	This.	B Fil	r yre	bello.	1																		QUAN. *			-	Estimate A	Add'I Auth. DATE Amount	Add'l Auth. Amount	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE F	ORIGINAL ESTIM- ATE AMOUNT.

ΙΝΛΟΙCE CObλ

				VOICE COPY	INI.				
003340	DATE - 30-99 Writien By:	Promised A.M. Promised A.M. Promised A.M. Promised A.M. P.M. P.M. P.M. P.M. P.M. P.M. P.M.	re scal -	05 Captare	٤.		TOTAL 15 00 LABOR 2857 00 PARTS 717 16	REPARS TOWING SUB TOTAL SALES TAX SALES TAX HAZARDOUS WASTE DISPOSAL	OUNT > 7,633.47
	Phone When Deliver Ready YES NO YES NO	Business - 5618 532 - 5618 with necessary materials. You and your before of delivery at my risk. An express the amount of repairs thereto. And the Amount of repairs thereto. NSTRUCTION	Inservede - Replace	UL Parts Res	peset ible space		Ŧ	A Contrologic Control Control Controls of Controls of Controls of Controls of Controls of Control Cont	
Tiamo Motorcars Reprari Service & Restoration 644 Terminal Way • Costa Mesa, Ca 92627 (949) 642-8512 • Far 642-8514 BAR No. AC 193569		License No Conserve and a local and with necessary materials. You and your employees may operate value for purposes of testing, inspection or delivery at my tisk. An express mechanic's lien is actrowedged on vehicle to secure the amount of repairs thereto. Signed Strand Stra	A Leak, 1 Fill Caslant	Le disassenble, d actions clean a Taisrall in care removined , Taisr	Prad test	HSA	Smog Check: This is to advise you that some emission control devices may still be covered under mig's warranty. By law, you may choose another Licensed Smog Check Facility to perform any needed repairs or adjustments which the smog check test indicates are necessary.	CASH	OK D By
Tiam Tiam 644 Termin (949) 6	r Groves	CCANT I hereby author employees may mechanics lie signed	K. Water PUM	more Transau urh-5-th 59 fill gear oil	ube chassis	D. H.	advise you that some emission control de Check Facility to perform any needed re		
SALE SALE	2630 NAME R. 39 C. 5811 ADDRESS	Vear-Make-Model Odometer Vehicle I.D. No.	Let C	2 PT Re		13,16 Buchth Amount	Smog Check: This is to a another Licensed Smog C		5.66.0
U-USED R-REBUILT	Seal adiator					PARTS		arts and Labor Direct Phone INITIAL Direct Phone	ESTIMATE TOTAL
* CODE N-NEW * PART No. 01 Transfayle 5 y chros	Coolant Longe Pur	Hers a superproved the				SPECIAL F		Estimate Amount - for Parts and Labor Addrivuth. DATE Direct Phone Addrivuth. DATE Direct Phone Addrivuth. Direct Phone Addrivuth. Direct Phone Addrivuth. Direct Phone Addrivuth. Direct Phone Addrivuth. Direct Phone Addrivuth. Direct Phone	
Eder		4	12			QUAN		Add Add Add	ATE

					~				· · ·			1010				-									
003319	DATE 9-59 Written By:	Time Received	P.M.		FOR INSPECTION	LABOR CHARGE		cs - Repair t.	Aron &	4	red.	Fillphue	7						► 2075 00	271 46		AL	× 50 37	Posal \$ 00	> 3, 888 64
	Deliver DI YES NO	VH C	55 82 5618 Promised		GEMENTS MADE	TRUCTION	- OIL LEAKS	4 als Distribute	A rilling Realise		des (20 ma) 5 RD	-Reseal, New		and the second se						the smog check test indicates are necessary. SPECIAL			IN VEHICLES IN CASE OF FIRE.	OTHER CAUSE BEYOND OUR WASTE DISPOSAL	CONTROL TOTAL
Tiamo Motorcars Revise & Restoration 644 Terminal Way • Costa Mesa, Ca 92627 (949) 642-8512 • Fax 642-8514 BAR No. AC 193569	Phone When Ready YES 0 NC	H P R L	LICENSE NO. XKH 782 E YY A helinu rensir unit in he done share with	employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lifen is acknowledged on vehicle to secure the amount of repairs thereto.	Signed X Sig	REPAIR ORDER - LABOR INSTRUCTION	· TUNE - CHK	Dump, Tesit	-Jest + Kepos	R CAM (2.10)	uc L L	re od transacle	ve carbs.						and the second	or adjustments which the smog check ter	CASH	CHARGE		· HOITHIR RED	OK D By
Herrari Sei Tiamo Herrari Sei 642 (949) 642-	er Orves	volumentary and pressure of the second secon	CCPANI - Internation the	1300 http: mechanic's lien is	Signed X		of test, cyk	Y:	Rear Hub Car	+ I.H.I. Rti	Hure heads	And	(Timing to						and the second second second	anody clears: include the activity to perform any needed repairs and suit the correlation another Licensed Smoot Flecking to perform any needed repairs or adjustments which ECOMMENDED SERVICE:					
SALE SALE Voo	A NAME R OG C		20 Odometer		Call 00	OPER No.	14000	Cuc	N+U N+U	UII UII	1	CLE	20		-		LIN		Cmon Choole This in to advise	RECOMMENDED S		2	3.	4. PV5 E	5.
	Rear 157	t 69	River D	19:	YOU											1					Labor	Phone INITIAL	Phone	DEBOURT	TOTAL -
* CODE N-NEW U-USED R-REBUILT PART NO. OF DESCRIPTION OLE FILLEN OTS MUTOR OFF	The put on bring 1.7	404	PCH Seal to-	4	sc. Supplier -											TAT INTOT	SPECIAL REPAIRS			TOTAL SPECIAL REPAIRS	Estimate Amount - for Parts and Labor	TIME	Direct Phone	and bala	ESTIMATE TOTAL
**************************************	250	1 VA		1	MISC		24	2									OUAN *	123			Estima	Add'I Auth. DATE Amount	Add'l Auth. Amount	NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE F	ATE AMOUNT.

ROGER GROVES RHONDA GROVES 7 MARBELLA MONARCH BEACH CA 92629

PAGE I

OF BEVERLY HILLS 9372 Wilshire Blvd. Beverly Hills, CA 90212 (310) 275-4400

terrari

SERVICE ADVISOR ALAN WOODARD

REPAIR ORDER	DATE READY	STOCK NO.	VEH	ICLE IDENTIFICATION	1	CUST. NO.	TAG NO.	P.O. NO.	PRINTI	ED	INVOICE NO.
7MAR98	25MAR98	2.	9163		Sector Vis	9163	T WE LEAVE	2010,8304	25MAE	298	8603
TIMEIN	TIME READY	YEAR	MAKE &	MODEL	TELEP	HONE NO.	CUST. F	AY DELIV	ERY PRI	EPARED BY	S/A
15:35	13:40	66 FERR	ART 330	GTC	714-2	40-441		.00 01JA		34	34
MILEAGE IN	MILEAGE OUT	LICENSE NO									
67665	67677	LIGENSEITS		CE CHARGE	1001000	A TRADEMA	anves.				
			TYPE HOURS	LIST/UNIT	NET/UNIT	r	TOTAL	and and sets			
VEH	IRCHASE I I VEHICLI 188 GALS	INSPECTI E PRE-PU 32CPFC S GAS	RCHASE	INSPECTIO	N 288.	00 2	288.00				
		, CHECK C		SION, REPLA	25. CE	42	25.42				
PARK PI ** REPI 299	ACE DRIV	FOR MOTO	TROL SY R AND F	ABLE STEM-REPLA REGULATOR							
	1 FBHCAU	32CPFC BLE WNDW			288.	00	288.00				
	CABLE			13.45	12.	10	12.10				
** FLUS HYL	SH BRAKE	AND CLU HYDRAULI	TCH FLU C SYSTE	MS			"Team				
		32CPFC	A		108.		108.00 20.06				
** DEDI		804 BRAK RBOX FLU		11.14	10.	03	20.00	\wedge			
GBY	C DRAIN	AND REFI	LL GEAF	RBOX FLUID				$\langle \rangle$			
	1 1577	32CPFC AGIP GEA		5 10.30	36.	27	36.00				
** CHE(ING SYST		5 10.50	5.	21	57.00	V			
198	32100 R&	R OR REP	LACE AI	TERNATOR			OTALS				
nel liller boli	10 10 10 10 10 10	CANE:	DEN AR FOL	000000000000000000000000000000000000000	AMOUNT		UTALS	I acknowledge	notice and o	oral approv	al of any addition
eiti boltsir				PARTS	AMOUNT	Del a 100	nsale ban ya	customer or wa	rranty work p	erformed a	and/or increase in t adge and approve
			of and the state	GAS,OIL			1.1.1.1.1.1.1.1	repairs as itemiz	ed and receip	t of vehicle	e. I also acknowled Warranty Informati
			epida tot 1		AMOUNT			contained on the			
				It is the second s	CHARGES			Original		Authorize Revised	d
				LESS IN	SURANCE			Estimate \$		Estimate	\$
				SALES				CUSTOMER		-	
				PLEASE THIS A	MOUNT			SIGNATURE X			
		ative and brits		inter en benefet	1	NIN	:61	e.37	e off be d e off be d e off w electronic		
					EK		6	4.97 ,95.10			
					44	;(D.					
				C	USTOM	ER CO	PY				

BEAEKTA HIFTS					
T-ID-T-IOT	2		0	PAGE 2	
1767191	0			Ferra	ILI
TO THE				BEVERLY I	HILLS
ROGER GROVES RHONDA GROVES				0072 Wilchire	DIVU.
7 MARBELLA MONARCH BEACH CA 92629				Beverly Hills, CA (310) 275-44	100
		IN ON PERLACE	A9	INVOICE PRINTED	INVOICE NO.
SERVICE ADVISOR ALAN WOODARD	VEHICLE IDENTIFICATION	COST. GO.	TAG NO. P.O. N	25MAR98	8603
WRITTEN DATE READY STOCK NO.	163	9163	OUST PAY	DELIVERY PREPARED DATE BY	S/A
17MAR98 25MAR98 9	A MODEL	TELEPHONE NO.	LABOR RATE	1 JAN66 34	34
TIME IN TIME READY YEAR	I 330 GTC 71	4-240-4410	85.00 0	10111100	
15.55					
MILEAGE IN MILEAGE OUT LICENSE NO.	PELANCE CHARGE	ROALATHEMHOR		Manhami ada man pres	
67665 67677	E HOURS LIST/UNIT	NET/UNIT	DTAL		Distances on in Succession
TECH. IT	The management of the		88.00		Constraint of the second
ASSEMBLI 32CPFCA SUBL PO#11604 (ASOM ELECT: DI TERNATOR	RIC, INV#4291) REBU	ILD	-		
SUBL PO#11604 (ASOM HEAD		2 2 2 2	70.00		Dette and its periods
PO#8603		270.00 2			
TIMING, ADJUST	CARBS		396.00		NE TOTAL
SEE NOILS STOR		396.00	States of the second states and		dentes de la constantes de
1 FBHBRAKE MTL/J	PLSTC 4.20	3.78	3.78		e on endite resources
PARTS CLEANER	SPRAY 3.85	3.46	4.46		
1 95180053 CARL		18.92	18.92		Core to the Non of sent
1 95180061 FILI		3.00	36.00		Courter and Supports SA
			the strange of the st		State wanted of Wald
02200 PERFORM LUBE	RICATION DERVICE	0.00	0.00		and stars all and hand the
CYLINDERS	77	nu - toko	30.80		Rectori eluis comprese forte
14 20/50CASTRO	L 2000 2.45	2.20	29.66		periode & converte a action
		C.			
	0,01	DIDTION	TOTALS	o tradició h té	al approval of any additional rformed and/or increase in the
CHECK AND ADJUST THE REPLACE BOTH FUEL FILT	LABOR	AMOUNT	cu	stomer of warranty	acknowledge and approviledge
and line borrest vicentate and solar of	PABTS	AMOUNI	or	pairs as itemized and receipt	acknowledge and approve an of vehicle. I also acknowledge are and Warranty Information
to us not hear purformed due to delega	SUBLE	L, LUBE	re	ontained on the reverse side.	
and been my first and the print of the set	MISC.	CHARGES		Original	Authorized Revised Estimate \$
erit toanis foit save in	TOTA	CHARGES		Estimate \$	
	SALES	STAX	CI	IGNATURE X	
stand with the rest of the second state	PLEA	SE PAY AMOUNT	SI		Number & Resolution
		Count poly to take			
and children's terrotic for it attents more	ed) fallene o ballen film a				
		CUSTOMER	R COPY		

ROGER GROVES RHONDA GROVES 7 MARBELLA MONARCH BEACH CA 92629

I.ID.I.IO.T

BEA

PAGE 3

OF BEVERLY HILLS 9372 Wilshire Blvd. Beverly Hills, CA 90212 (310) 275-4400

errari

SERVICE ADVISOR ALAN WOODARD

THAR UPLAN DATE READY STOCK NO. VEHICLE IDENTIFICA 7MAR98 25MAR98 9163 TIME IN TIME READY YEAR MAKE & MODEL 15:35 13:40 66 FERRARI 330 GTC MILEAGE IN MILEAGE OUT LICENSE NO. USTO 67665 67677 USTO USTO ** REPAIR TURN SIGNAL LEVER REPAIRS PERFORMED AT NO LABOR 32CPFCA 32CPFCA ** REBUILD MECHANICAL FUEL PUMP `SEE NOTES BELOW: 32CPFCA 203. *EBUILD MECHANICAL FUEL PUMP 203. * BEBUILD MECHANICAL FUEL PUMP 203.	TELE 714-2 ZUNIT NETAU CHARGE 0. 180.	.00	A CONTRACTOR OF THE OWNER OF THE	T. PAY R BATE	NO. 2 DELIVERY DATE D1JAN6	PRINTED 5MAR98 PREPARED 5 34	INVOICE NO. 8603 5/A 34
TIME IN TIME READY YEAR MAKE & MODEL 15:35 13:40 66 FERRARI 330 GTC MILEAGE IN MILEAGE OUT LICENSE NO. 67665 67677 ** REPAIR TURN SIGNAL LEVER ~ REPAIRS PERFORMED AT NO LABOR 32CPFCA UST ** REBUILD MECHANICAL FUEL PUMP `SEE NOTES BELOW: 32CPFCA ** REBUILD MECHANICAL FUEL PUMP `SEE NOTES BELOW: 32CPFCA 1 95180130 PUMP KIT 203. EBUILD MECHANICAL FUEL PUMP	714-2 JUNIT NETUR CHARGE 0. 180.	PHONE NO. 240-441 .00 .00 .36 2	10 8! TOTAL 0.00 180.00		DELIVERY DATE	PREPARED BY	S/A
15:35 13:40 66 FERRARI 330 GTC MILEAGE IN MILEAGE OUT LICENSE NO. 67665 67677 ** REPAIR TURN SIGNAL LEVER ~ REPAIRS PERFORMED AT NO LABOR 32CPFCA ** REBUILD MECHANICAL FUEL PUMP ` SEE NOTES BELOW: 32CPFCA 1 95180130 PUMP KIT 203. EBUILD MECHANICAL FUEL PUMP	714-2 JUNIT NETUR CHARGE 0. 180.	240-441 .00 .00 1 .36 2	10 8! TOTAL 0.00 180.00				
MILEAGE IN MILEAGE OUT LICENSE NO. 67665 67677 * REPAIR TURN SIGNAL LEVER ~ REPAIRS PERFORMED AT NO LABOR 32CPFCA * REBUILD MECHANICAL FUEL PUMP ` SEE NOTES BELOW: 32CPFCA 1 95180130 PUMP KIT 203. EBUILD MECHANICAL FUEL PUMP	CHARGE 0. 180.	шт . 00 . 00 1 . 36 2	TOTAL 0.00 180.00	5.00 (34
67665 67677 * REPAIR TURN SIGNAL LEVER ~ REPAIRS PERFORMED AT NO LABOR 32CPFCA * REBUILD MECHANICAL FUEL PUMP ` SEE NOTES BELOW: 32CPFCA 1 95180130 PUMP KIT 203. CBUILD MECHANICAL FUEL PUMP	CHARGE 0. 180.	.00 .00 1 .36 2	0.00				
<pre>* REPAIR TURN SIGNAL LEVER ~ REPAIRS PERFORMED AT NO LABOR 32CPFCA * REBUILD MECHANICAL FUEL PUMP ` SEE NOTES BELOW: 32CPFCA 1 95180130 PUMP KIT 203. BUILD MECHANICAL FUEL PUMP</pre>	CHARGE 0. 180.	.00 .00 1 .36 2	0.00				
 * REPAIR TURN SIGNAL LEVER REPAIRS PERFORMED AT NO LABOR 32CPFCA * REBUILD MECHANICAL FUEL PUMP SEE NOTES BELOW: 32CPFCA 1 95180130 PUMP KIT 203. BUILD MECHANICAL FUEL PUMP 	CHARGE 0. 180.	.00 .00 1 .36 2	0.00				4
PRE-INVOICE ** DE			anita (ti) ma anita (ti) ma anita anita (ti				
PRE-INVOICE AN	ESCRIPTION	тс	OTALS				
IAB	BOR AMOUNT	service services and	584.00	acknow	ledge notice	and oral approva	al of any addition
	RTS AMOUNT		399.68	customer	or warranty	work performed a	nd/or increase in
	S,OIL, LUBE		0.00	repairs as	itemized and	I also acknowled receipt of vehicle	. I also acknowle
	BLET AMOUNT	2	295.42	receipt o		Consumer and V	
MIS	C. CHARGES	11 - 20 - 20	0.00	contained	on the revers	, side.	
	TAL CHARGES	3 27	279.10			Authorized	ł
. LES	S INSURANCE		0.00	Original Estimate	\$	Revised Estimate	\$
the second se	LES TAX	and an and	32.97		Design date	A CONSTRUCTION	
PLE	EASE PAY	23	312.07	CUSTOME	R X		and a starts

			12,	118/-7				
	\bigcirc			\sim	ſċ	5		
	FOREIGN		TECHNICI.	AN INC.	Ir	16	122	(D)
===== CUSTOMER =====			BROADWAY		Enr.d.	*******	•••••••••••••••••••••••••••••••••••••••	
11:16 AM/		MONIC	A CALIF.	90404	= :: = :	==_7	VEHICI	.E =====
HERITAGE CLASSICS			FAX [310] 3		SYMPTOM:			
8980 SANTA MONICA BL.	DAK#A	B1/0744 E	PA#CAL00000000	,	SERVICE:			
WEST HOLLYWOOD CA.90069					YR/MAKE:			OGTC
(310)657-9699- FAX					LICENSE: VIN :		12	
Wk:(FAX)657-9698					MLG :		3	
Date: 11/18/97 Due Date: 11/18/9	97 INVOI (CE NUM	BER: 3035		ХКН382		PA	
							FAU	2: 1
COMMENTS AND DESCRIPTION OF CHARGES	\$	PRICE	PARTS & LUBR	ICANTS USED		QTY.	PRICE	TOTAL
RADIATOR REPAIR			TIE ROD ROD T	IE END			108.90	435.60
REPLACE FAN MOTOR + R.& I. RADIATO	JR		FAN MOTOR			1	165.00	165.00
REPLACE TIE ROD END [FOUR]			SPARK PLUGS			12	4.25	51.00
OIL SERVICE + REPLACE POINTS & PLU			OF OIL FILTER			2	14.50	29.00
TIGHTEN EXHAUST MUFFLER	IGS		HOOD RELESE C			1	16.00	16.00
REPLACE FT. BRAKE PADS			BRA PADS BRAK			1	56.00	56.00
LABOR FOR SERVICES			RADIATOR COOL	ANT		1	10.00	10.00
I LABOR FOR SERVICES			POINTS SET			2	29.00	58.00
		1		O WEIGHT OIL FO		12	2.00	24.00
			BRAKE FLUID			1	6.00	6.00
1								1
								1
								I I
Print -								
		.=================						
	LABOR			ccess: 0.00				.60
		105.00	SHOP SUPPLIES	: 0.00	HAZ. DIS	POSAL	. 3	.00
ļ i								====
	This vehicle will							
	3 days of the dat			1				i i
	not authorize the	recommende	d services.					
CHARGE								1
THANK YOU FOR YOUR BUSINESS					SUB-10TA	.L	1563	.60
					TOTAL		1547	(0)
					TOTAL		1563	.00
				i	BALANCE		1563	.60
				1. J. S. S. J.]
Estimates Record	ACCE	PTANCE	SIGNATUR	E :				- ANDADAS
						=====		
A A A A A A A A A A A A A A A A A A A		PARTS(add		INCREASE CALL	LER PEASO	N FOR	ESTIMATE	INCREASE
HIT IG THE IGA 637-9699 HERITAGE	CLASSIC 1563.60	850.60	710.00		ori	ginal	estimate	1
Lauthorize the should provide the								
authorize the above repairs and nec	essary materials.	Your emp	loyees may oper	ate vehicle for	inspection	, tes	ting, del	ivery at my
Tak. Tou will not be responsible fo	or loss or damage to	o vehicle	or items left i	n it. I agree t	n nav roac	onabl	c stopage	on unhiala
tert more that 40 hours after notific	cation that repairs	are comple	eted. An expr	ess Mechanics Le	in is ackn	owlad	cad on ah	our unhiele
o secure the amount of repairs there	eto. Labor is guarar	nteed for 9	90 days or 4000	miles whichever	occurs fin	rst. /	All other	guarantees
The those made exclusively by the man		anty work	that is based o	n this repair or	der must be	e per	formed at	this shop.
A REMOVED PARIS W	ILL BE DI	SFOSE	DCFUN	LESS 1 I	NITIAL	. н	ERE	

*

THE OWNER WATER A DE LET

-



Invoice submitted to:

ROGER GROVES 7 MARBELLA DANA POINT, CA 92629

March 5, 1999 #2266 In reference to: FERRARI 330

		Hours	Amount	
12/30/98	CLEAN TAIL PIPES AND PAINT TO FINISH.	1.50	75.00	
1/4/99	INSTALL TAIL PIPES, ALL NECESSARY HANGERS FOR EXHAUST SYSTEM.	3.25	162.50	
1/6/99	LOOSEN TAIL PIPES AND POSITION FOR BETTER ALIGNMENT.	1.50	75.00	
1/7/99	INSTALL ALL DASH GAUGES AND WIRE. TEST START CAR, EXHAUST LEAK LEFT HEADER PIPE, REMOVE LEFT EXHAUST SYSTEM FOR RE-SHAPING.	 7.00	350.00	
-	RESOTRE HEADER PIPE FLANGES AND FRONT MUFFLER EXTENSIONS. START TEST FITTING SYSTEM.			
1/8/99	COMPLETE INSTALLATION OF LEFT EXHAUST, INSTALL NOSE BADGE, FENDER BADGES, TRUNK TRIM. MAKE BRACKET TO FIT ALTERNATOR TERMINAL BOARD, INSTALL TERMINAL AND BEGIN WIRING.	4.00	200.00	

ROGER GROVES

March 5, 1999

Page 2

		Hours	Amount
1/11/99	INSTALL VOLTAGE REGULATOR UNDER FENDER AND RE-WIRE. INSTALL REMAINING INTERIOR TRIM PIECES. REMOVE LEFT DISTRIBUTOR CAP AND UPPER FUEL HOSE. TIGHTEN ENDS ON HOSE AND RE-INSTALL.	3.50	175.00
1/12/99	CLEAN AND DETAIL, TEST DRIVE, AND CHECK.	2.50	125.00
	For professional services rendered	23.25	\$1,162.50
	Additional charges		
1/15/99	CLOCK AND TACH REPAIR		402.50
	Total costs		\$402.50
	Total time and expense charges		\$1,565.00
	Previous balance		(\$70.86)
	Balance due		\$1,494.14

FOR YOUR CONVENIENCE WE NOW ACCEPT VISA, MASTER CARD AND DISCOVER CARD



Invoice submitted to:

ROGER GROVES 7 MARBELLA DANA POINT, CA 92629

January 4, 1999 #2230 In reference to: FERRARI 330

		Hours	Amount
11/19/98	DISMANTLE FRONT SUSPENSION ASSEMBLY, REMOVE SHOCK, PRESS SHOCK EYE BUSHINGS AND INSTALL IN NEW SHOCKS.	8.00	400.00
11/20/98	INSTALL SHOCKS, REMOVE REAR SHOCKS, DISMANTLE, REMOVE EYE BUSHINGS AND INSTALL IN NEW SHOCK.	3.00	150.00
11/24/98	DISMANTLE REAR SHOCK, CLEAN SPRING RUBBER SEATS AND PAINT, REMOVE OLD SHOCK BUSHINGS FROM SHOCK TO INSTALL IN NEW SHOCKS.	3.00	150.00
11/25/98	DISMANTLE REAR SHOCKS, CLEAN AND PAINT REAR SPRINGS, SHOCK BOOTS AND SLEEVES.	1.50	75.00
11/27/98			
	INSTALL NEW BUSHING TO REAR SHOCKS AND INSTALL IN CAR.	1.00	50.00
11/30/98	INSTALL REAR SHOCKS, CLEAN AND INSTALL BOLTS, LUBE UPPER CONTROL ARM BUSHINGS.	2.00	100.00

ROGER GROVES

January 4, 1999

		<u>Hours</u>	Amount
11/30/98	CHECK OIL LEAKS FROM ENGINE, REAR END. REMOVE INNER STUB AXLE FLANGE NUTS AND WASHERS, CLEAN OIL FROM FLANGES, REPLACE NEW NUTS AND WAHSERS TO FLANGES. REMOVE TRANSMISSION CASE NUTS, CLEAN AND INSTALL WITH NEW. REMOVE REAR CAM SHAFT CAP NUTS AND SEAL.	3.00	150.00
12/1/98	TIGHTEN ALL OIL PAN BOLTS, INSTALL COPPER WASHER TO TACK DRIVE CABLE, TIGHTEN CAM COVER BOLTS, TIGHTEN FUEL LINE TO CARBS. FILL WITH WATER PRESSURE COOLING SYSTEM, TIGHTEN ALL NECESSARY CLAMPS, TEST DRIVE CAR AND MAKE REPORT.	4.00	200.00
12/2/98	GLUE PADDING BACK OF SEAT, GLUE CARPET AND TUCK UNDER SIDE PANELS. RE-INSTALL REAR CROSS PANEL IN PLACE.	1.00	50.00
12/4/98	RE-STRETCH LEATHER ON DASH BOARD, GLUE LEATHER ON BACK OF DASH AND INSTALL CLIPS TO HOLD LEATHER. REMOVE LEATHER FROM RIGHT POST FRONT PANEL, CUT NEW LEATHER AND INSTALL ON PANEL GLUE LEATHER ON PANEL TRIM TO FINISH. RE-INSTALL DASH BOARD, BOLT DASH IN POSITION. RINSTALL "A" POST PANEL, RE-INSTALL CENTER CONSOL.	3.50	No Charge
	REMOVE DASH BOARD	1.00	No Charge
12/8/98	ADJUST HEATER CONTROL CABLE, START REPAIRING HEAT DUCTS AND FLAPPERS.	4.00	200.00
12/9/98	INSTALL AFTER MARKET AIR FLOW CUT OFF SYSTEM FOR BOTH SIDES OF CABIN.	8.00	400.00
12/10/98	RE-INSTALL FRONT INNER FENDER COVERS, INSPECT FUEL LINES IN TRUNK, INSTALL HOSE CLAMP ON VENT TUBE, RE-PAINT TIRE COVER, RE-GLUE RUBBER SPARE TIRE PAD.	3.00	150.00
12/16/98	REMOVE ENTIRE EXHAUST SYSTEM, BEAD BLAST NEW SYSTEM, PAINT FRONT PIPES AND INSTALL, INSTALL MUFFLER SYSTEM TO FIT.	5.00	250.00
	FIT EXHAUST SYSTEM AND CHECK ALIGNMENT	1.50	75.00

the second

Page 2

ROGER GROVES

January 4, 1999

		Hours	Amount
12/17/98	ASSEMBLE EXHAUST SYSTEM TO CAR, FIR FRONT PIPES, MUFFLERS ETC; MAKE READY FOR PAINT.	5.00	250.00
12/18/98	FIT EXHAUST SYSTEM, REWORK MUFFLERS, PIPES ETC; TO FIT, REMOVE EXHAUST, REWORK PIPES ETC; FIT EXHAUST, REWORK TAIL PIPE BRACKETS, WELD AND FIT.	8.00	400.00
12/21/98	REMOVE EXHAUST SYSTEM, CLEAN MUFFLERS AND PREPARE TO PAINT, WRINKLE FINISH MUFFLER UNITS.	4.00	200.00
	CLEAN TAIL PIPES, WELD, SAND AND PAINT.	0.75	37.50
12/29/98	CLEAN EXHAUST SYSTEM AND WRINKLE FINISH EXHAUST.	1.50	75.00
12/31/98	FIT MUFFLER SYSTEM, TAIL PIPES.	2.00	\100.00
	For professional services rendered	73.75	\$3,462.50
	Additional charges		
12/18/98	SHOCK BUSHINGS		65.00
	SHIPPING		36.03
	EXHAUST PIPES		18.00
12/21/98	PAINT		21.30
	Tabal seabs		<u> </u>
	Total costs		\$140.33
	Sales tax		\$8.08
	Total time and expense charges		\$3,610.91
	Previous balance		\$70.86
	Balance due		\$3,681.77

22

Page 3



Invoice submitted to:

ROGER GROVES 7 MARBELLA DANA POINT, CA 92629

September 23, 1998 #2171 In reference to: FERRARI LUSSO

			X.
		Hours	Amount
8/24/98	TRY TO INSTALL SMALLER BOLTS IN STEERING COLUMN IN ORDER TO ALIGN LOCK WITH UPHOLSTERY, NEED TO MAKE SOME MODIFICATIONS TO DASH FOR PROPER ALIGNMENT. CLEAN UP RIVETS ON PASSENGER SIDE AIR VENT. TOUCH UP BRAKE NOSE, CHECK THAT TURN SIGNALS CANCEL, ALIGN HOOD.	2.00	No Charge
	CANCED, ADIGN HOOD .		
8/25/98	CHANGE OIL FILTERS AND DRAIN OIL. ADD 10 QTS. 20/50. INSTALL FUSE COVER DECALS. REMOVE BUMPERS AND INSTALL RUBBER STRIPPING AS REQUESTED. CLEAN OIL FILM FROM WINDOWS AND CLEAN WINDOWS.	4.00	No Charge
	For professional services rendered	6.00	\$0.00
	Additional charges		
8/25/98	OIL		24.34
8/26/98	OIL FILTERS		56.16
	OVERRIDER SEAL		2.52

GIR

ROGER GROVES

September 23, 1998

		Amount
8/26/98	RIGHT FUSE PLATE	48.00
	LEFT FUSE PLATE	48.00
	SHIPPING	28.33
	Total costs	\$207.35
	Sales tax	\$13.87
	Total time and expense charges	\$221.22
9/1/98	-CC PAYMENT INV #2152	(\$1,820.89)

FOR YOUR CONVENIENCE WE NOW ACCEPT VISA, MASTER CARD AND DISCOVER CARD

Page 2



Invoice submitted to:

ROGER GROVES 7 MARBELLA DANA POINT, CA 92629

August 24, 1998 #2152 In reference to: FERRARI 330

		Hours	Amount
7/31/98	BEGIN TO REPAIR REQUESTED PART OF CAR, WHEELS NOT SEATING PROPERLY, CLEAN UP KNOCK OFFS TO REPAIR WOBBLE. ADJUST STEERING BOX.	5.00	250.00
8/3/98	COMPLETE SEALING OF DRIVE FLANGES. SET UP RIGHT HALF SHAFT TO ALIGN U-JOINTS. INSTALL AXLE AND TIGHTEN ALL MOUNTING BOLTS. REPLACE WHEELS. ORDER PARTS NEEDED FOR 1000 MILE CHECK UP.		No Charge
8/10/98	REPAIR DASH BOARD LEATHER. REMOVE LEATHER GLUE AROUND EDGE, TACK LEATHER UNDER DASH. REPAIR LEFT SEAT, REMOVE TOP CUSHION, RE-INSTALL SEAT ON FRAME. REMOVE CENTER CONSOL TO REPAIR LEATHER AROUND SHIFT LEVER. REMOVE TOP PANEL AND REPAIR LEATHER AROUND WINDOW SWITCHES. REPAIR HEAD LINER PANEL, REPAIR REAR LEFT QUARTER PANEL, KICK PANEL AND INSTALL RIVETS ON RIGHT PANEL.	8.00	No Charge
8/11/98	REMOVE ENGINE COMPONENTS TO DO HEAD RETORQUE AND VALVE ADJUSTMENT. REMOVE RIGHT DISTRIBUTOR AND INSTALL SMALLER	4.00	200.00

ROGER GROVES

August 24, 1998

Page 2

		<u>Hours</u>	Amount
	O-RING IN TACH. DRIVE. ADJUST VALVES TO .20MM INTAKE AND .25 EXHAUST. TORQUE HEADS TO 61 FT. LBS.		
8/12/98	FINISH INSTALLING CENTER CONSOL, CHECK SHIFT AREA FOR BETTER FIT. INSTALL WIRES ON SWITCH, CHECK FOR FIT, REPAIR REAR CHELVE TRUNK AREA, FINISH INSTALLING SCREW FRONT LEFT KICK PANEL.	3.50	No Charge
	COMPLETE ADJUSTING VALVES AND REINSTALL VALVE COVERS. INSTALL LARGER O-RINGS ON DISTRIBUTOR DRIVES AND INSTALL DISTRIBUTOR ASSEMBLIES. SET UP CAP/WIRE ASSEMBLIES AND COMPLETE WIRING ON ENGINE, START CAR AND CHECK FOR LEAKS, TUNE CARBS.	4.00	200.00
8/17/98	REMOVE DUCT TAPE FROM AIR INLETS AND TORQUE WHEELS WITH SPECIAL WRENCH AND TORQUE WHEELS WITH SPECIAL WRENCH. SET UP CARBURETOR AND CHECK TIMING. SET GOOD IDLE AND SET MIXTURE. INSTALL AIR CLEANER AND TEST DRIVE, REPAIR WIRING ON WINDOW AWITCH. CHECK FUEL VENTS IN TRUNK AND FOUND THEM ALL TO BE INTACT. INSTALL NEW SQUIRTER PUMP AND CHECK WIRING. MAKE NEW TABS ON BATTERY HOLD DOWN AND INSTALL BATTERY. CHECK THAT SQUIRTERS WORK AND ADJUST LOCATION.	8.00	400.00
8/20/98	ORDER PARTS AS REQUWSTED BY ROGER, INSTALL REFINISHED STEERING WHEEL. INSTALL KICK PLATE ON DRIVERS SIDE NEAR GAS PEDAL. REMOVE TRUNK AND GASKET, SHAVE FOR CLOSE FIT.	3.00	150.00
8/21/98	DRAIN COOLING SYSTEM AND INSTALL FUNCTIONING THERMAL FAN SWITCH. REMOVE MORE MATERIAL FROM TRUNK GASKET TO ALLOW TRUNK TO CLOSE ALL THE WAY. ADJUST HOOD FOR BETTER FIT. CHECK STEERING WHEEL AND ALIGN.	4.00	200.00
	For professional services rendered	43.00	\$1,400.00

2

ROGER GROVES

August 24, 1998

Page 3

Additional charges

		Amount
8/11/98	GASKET SET	65.00
	SHIPPING	12.23
	VENTS	25.18
	SHIPPING	5.45
8/17/98	WASHER KIT	28.58
8/20/98	RESTORE STEERING WHEEL	258,75
	SHIPPING	16.50
	Motol costs	÷111 CO
	Total costs	\$411.69
	Sales tax	\$9.20
	Total time and expense charges	\$1,820.89
8/5/98	-C.C. PAYMENT #2131/#2132	(\$847.17)

FOR YOUR CONVENIENCE WE NOW ACCEPT VISA, MASTER CARD AND DISCOVER CARD



Invoice submitted to:

ROGER GROVES 7 MARBELLA DANA POINT, CA 92629

July 21, 1998 #2131 In reference to: FERRARI 330

			X	
		Hours	Amount	
6/26/98	TEST DRIVE, MAKE LIST OF ALL NEEDED REPAIRS. BLEED BRAKES, REMOVE MASTER TO UNSTICK PISTON, REPLACE MASTER CYLINDER AND ATTACH BRAKE LINES, BLEED BRAKES AGAIN AND LEAVE FOR WHEEL WELL UNDER COATING.	4.00	No Charge	
6/29/98	REPLACE LEFT WIPER BLADE, PAINT TALL PIPE TIP INNERS ORANGE. CUT AND INSTALL RED TAPE BANDS ON TAIL PIPE TIPS. DISASSEMBLE TRUNK PULL MECHANISM AND RE-ADJUST AND LUBE FOR BETTER OPERATION. START DISASSMBLING SAFETY CABLE.	6.00	300.00	
	REPAIR LEATHER ON LEFT A POST PILLAR, REPAIR SILL LEFT AND RIGHT. REPAIR SWITCH ON CENTER CONSOL. REPAIR CARPET ON REAR HUMP, FINISH LEFT FLOOR MAT, SEW BINDING AND RUBBER HEAL PAD, CLEAN GLUE AROUND DOOR PANELS LEFT AND RIGHT.	2.50	No Charge	
6/30/98	INSTALL NEW TUBING ON HOOD SAFETY CABLE. INSTALL MISSING BOLT IN LEFT HEADER SHIELD. ADJUST HOOD FOR BETTER FIT. RE ASSEMBLE	2.50	No Charge	

ROGER GROVES July 21, 1998

1998						
CENTER	CONSOLE.	TEST	BOTH	HOOD	RELEASES.	

TOP OFF BRAKE FLUID. TEST LIGHTS AND DASH

SWITCHES FOR OPERATION

For professional services rendered15.00\$300.00Additional charges7/1/982 CANS LACQUER PAINT9.48BODY SUPPLIES12.00ANTI FREEZE10.86BRAKE FLUID9.867/2/98KONI PAINT11.40ANSA EXHAUST STICKERS24.00. Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.616/26/98-CC PAYMENT #2116(\$13,805.58)				
7/1/982 CANS LACQUER PAINT9.48BODY SUPPLIES12.00ANTI FREEZE10.86BRAKE FLUID9.867/2/98KONI PAINT11.40ANSA EXHAUST STICKERS24.00Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.61		For professional services rendered	15.00	\$300.00
BODY SUPPLIES12.00ANTI FREEZE10.86BRAKE FLUID9.867/2/98KONI PAINTANSA EXHAUST STICKERS24.00Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.61		Additional charges		
ANTI FREEZE 10.86 BRAKE FLUID 9.86 7/2/98 KONI PAINT 11.40 ANSA EXHAUST STICKERS 24.00 Total costs \$77.60 Sales tax \$6.01 Total time and expense charges \$383.61	7/1/98	2 CANS LACQUER PAINT		9.48
BRAKE FLUID9.867/2/98KONI PAINT11.40ANSA EXHAUST STICKERS24.00Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.61		BODY SUPPLIES		12.00
BRAKE FLUID9.867/2/98KONI PAINT11.40ANSA EXHAUST STICKERS24.00Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.61				
7/2/98KONI PAINT11.40ANSA EXHAUST STICKERS24.00. Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.61		ANTI FREEZE		10.86
ANSA EXHAUST STICKERS 24.00 . Total costs \$77.60 Sales tax \$6.01 Total time and expense charges \$383.61		BRAKE FLUID		9.86
Total costs\$77.60Sales tax\$6.01Total time and expense charges\$383.61	7/2/98	KONI PAINT		11.40
Sales tax\$6.01Total time and expense charges\$383.61		ANSA EXHAUST STICKERS		24.00
Sales tax\$6.01Total time and expense charges\$383.61				
Total time and expense charges \$383.61		. Total costs		\$77.60
And the second		Sales tax		\$6.01
6/26/98 -CC PAYMENT #2116 (\$13,805.58)		Total time and expense charges		\$383.61
	6/26/98	-CC PAYMENT #2116	(\$	13,805.58)

FOR YOUR CONVENIENCE WE NOW ACCEPT VISA, MASTER CARD AND DISCOVER CARD

Page 2

Amount

Hours



Invoice submitted to:

ROGER GROVES 7 MARBELLA DANA POINT, CA 92629

June 25, 1998 #2116 In reference to: FERRARI 330

		Hours	Amount
5/21/98	UNDERCOAT ENGINE COMPARTMENT.	4.00	200.00
	DEGREASE ENGINE AND CLEAN ENGINE COMPARTMENT.	2.00	100.00
5/20/98	FINISH INSTALLING SEAT COVER ON RIGHT BOTTOM CUSHION. SECURE REAR OF CUSHION. INSTALL PADDING ON FRONT AND TIE FRONT TOGETHER. PULL LEATHER TO SIDES TO FINISH INSTALL CUSHION ON FRAME AND CHECK FOR PROPER FIT. CUT LEATHER INSERT FOR RIGHT TOP CUSHION. SEW LINES AND CUT SIDE PANEL PIECES AND SEW TOGETHER. FINISH SEWING PIPING TO SIDE PANEL. FIT CUSHION FOR FIT.	8.00	400.00
	INSTALL PADDING TO CUSHION SIDES. REINSTALL COVER TO CHECK FOR FIT. INSTALL STRING ON CENTER INSERT.		
5/21/98	REMOVE RIGHT TOP CUSHION SEAT COVER. TIE STRING TO HOLD CENTER LINE. GLUE CENTER INSERT IN POSITION. INSTALL MORE PADDING ON SIDES. INSTALL COVER AND CHECK FIT. CHECK BACK PART OF COVER FOR FIT. FINISH SIDES AND INSTALL CHROME HARDWEAR BRACKETS ON RIGHT AND LEFT SIDES. CHECK TO SEE THAT	7.00	350.00

June 25, 1998

		Hours	Amount
	THEY WORK PROPERLY. PUT TOP AND BOTTOM CUSHIONS TOGETHER TO CHECK THAT LINES MATCH.		
5/22/98	CLEAN EXPOSED WIRING IN ENGINE COMPARTMENT. CAD PLATE HOOD LATCH. RESTORE, INSTALL AND WIRE UNDER HOOD LIGHTS AND SWITCH. INSTALL BRAKE PEDAL ASSY AND BRAKE BOOSTER.	4.00	200.00
	INSTALL TURNED FLYWHEEL AND TORQUE BOLTS TO SPEC. SET UP CLUTCH AND INSTALL ON FLYWHEEL WITH INPUT SHAFT TO ALIGN. ORGANIZE FUEL AND OIL HOSE ENDS FROM PLATER.	2.00	100.00
5/25/98	COMPLETE ASSEMBLY OF BELLHOUSING BY INSTALLING INPUT SHAFT AND RETAINING PLATE. MAKE UP FUEL AND OIL HOSES, INSTALL HOSE ENDS AND FITTINGS. INSTALL OIL HOSE IN CAR AND SET UP CLUTCH ARMS, REBUILD CLUTCH MASTER AND MOUNT ON CAR. INSTALL CLUTCH AND BRAKE RESERVOIR BOTTLES AND BRACKET.	8.00	400.00
5/26/98	REBUILD BRAKE MASTER AND INSTALL IN CAR. SET UP RESERVOIRS AND HOSES AND CLAMP IN PLACE, BLEED BRAKE SYSTEM AND FIL RESERVOIRS. DISASSEMBLE CARBURETORS ONE BY ONE AND CLEAN. BLAST BRASS COMPONENTS AND HARDWARE TO BE PAINTED OR PLATED. ASSEMBLE CARBURETORS WITH NEW GASKETS AND OLD NEEDLE AND SEATS. COMPLETED 2 CARBS AND BEGAN THIRD.	8.00	400.00
5/27/98	START CUTTING LEATHER FOR WHEEL ARCH, SEW PIECES TOGETHER AND SEW TOP STITCH. INSTALL WHEEL ARCH ON CAR, GLUE TO FINISH LEFT AND RIGHT. FIT REAR CARPET MATERIAL, TRIM TO FIT, CHECK FOR PROPER FIT AROUND WHEEL ARCH, SEW CARPET BINDING ALL AROUND CARPET. BEGIN TO INSTALL IN PLACE, GLUE AROUND WHEEL ARCH AND TOP PART, CHECK FOR PROPER FIT.	5.00	250.00
	COMPLETE THIRD CARBURETOR, PAINT ALL HARDWARE FOR CARBS AND PLATE ALL HARDWARE AS NEEDED. INSTALL ALL FINISHED HARDWARE ON CARBS AND SET UP FOR INSTALLATION.	8.00	400.00

12

		Hours	Amount	
	SAFETY WIRE VENTURI SCREWS AND COTTER CHOKE ARM. INSTALL FRONT SEAL AND FRONT PULLEY WITH BELTS, ROLL A/C BELTS ON AND INSTALL ALTERNATOR WITH BELT. REMOVE DISTRIBUTOR AND CAP WIRE ASSEMBLIES, SEAL VALVE COVERS AND ONE CAM COVER, REMOVE HEATER VALVE AND PREPARE ENGINE FOR INSTALLATION.			
5/28/98	REMOVE ENGINE FROM STAND AND PLACE ON DOLLEY. PAINT ENGINE MOUNTS AND INSTALL. INSTALL MOTOR IN CAR. SECURE MOTOR MOUNTING BOLTS. WIRE STARTER, A/C COMPRESSOR AND OIL TEMP SWITCH. MOUNT FUEL FILLER AND INSTALL YELLOW FUEL LINES IN ENGINE BAY. INSTALL CARBURATORS AND SET UP CHOKE CABLE. ATTACH OIL PRESSURE LINE AT BACK OF ENGINE. INSTALL FAN MOTORS AND COOLANT CATCH TANK. POLISH AIR HORNS AND INSTALL MOTOR HORN ASSEMBLY.	8.00	400.00	
5/29/98				
5/28/98	FINISH GLUING REAR CARPET. FINISH GLUING AROUND WHEEL ARCH COVERS. GLUE CENTER CONSOLE BACK HUMP. GLUE SIDES AND CHECK FOR PROPER FIT AROUND QUARTER PANEL. REMOVE OLD LEATHER FROM REAR QUARTER PANELS. INSTALL NEW PADDING ON BOTH PANELS. CUT LEATHER FOR QUARTER PANELS. GLUE AND INSTALL.	8.00	400.00	
5/29/98	FINISH ASSEMBLY OF RIGHT BOTTOM SEAT CUSHION, INSTALL CUSHION ON FRAME. INSTALL SEAT TRACKS ASSEMBLY, TOP CUSHION, AND PUT SEAT TOGETHER. DISASSEMBLE LEFT SEAT, REMOVE BOTTOM CUSHION FROM FRAME. REMOVE OLD COVER FROM CUSHION, CUT LEATHER TO MAKE NEW CUSHION, SEW LINES OF CENTER INSERT AND SEW CUSHION TOGETHER AND FIT SEAT ON CUSHION TIE STRING.	8.00	400.00	
	MOUNT FUEL LINES AT FUEL TANK. SECURE REAR FUEL FILLER AND ATTACH FUEL FEED LINE MOUNT ELECTRIC PUMPS AND RUN FUEL LINES TO COMPLETE FUEL SYSTEM.	8.00	400.00	

June 25, 1998

		Hours	Amount
6/1/98	REMOVE HARDWARE FROM TOP LEFT CUSHION, OLD COVER FROM CUSHION, FINISH INSTALLING SEAT COVER FROM BOTTOM CUSHION. INSTALL PADDING ON SIDE TIE STRING ON BOTTOM, PULL LEATHER TO BACK AND FINISH TO FRONT THEN FINISH TO SIDES. INSTALL CUSHION ON FRAME TO CHECK FOR PROPER FIT. START SEWING LINES FOR TOP CUSHION, CUT LEATHER FOR SIDE PANEL, SEW PIECES TOGETHER, SEW PIPING ON SIDE PANEL AND SEW CUSHION TO FINISH. INSTALL PADDING ON TOP CUSHION, FIT SEAT COVER, CHECK FOR FIT, TIE STRINGS AND PULL LEATHER FOR PROPER FIT. REMOVE COVER AND INSTALL EXTRA PADDING ON SIDES.	8.00	400.00
	MAKE MEASUREMENTS ON CLUTCH AND FLYWHEEL OF CAR AND DETERMINE THAT ALL PARTS ARE CORRECT. BLEED HYDRAULICS TO CLUTCH AND ENSURE PROPER FUNCTION. INSTALL TORQUE TUBE AND FASTEN TO BELLHOUSING. INSTALL DRIVE SHAFTS AND FASTEN IN PLACE. INSTALL TRANS AXLE.	8.00	400.00
6/2/98	INSTALL SEAT COVER ON LEFT TOP CUSHION, ADD PADDING ON SIDES TO COVER, CHECK FIT, FINISH BACK OF SEAT, ALIGN PIPING ON SEAT. CHECK HARDWARE, CLEAN AND POLISH, INSTALL CHROME SIDE BRACKETS, INSTALL ROD ON BRACKETS AND TIE BOLTS TO HOLD BRACKETS IN PLACE. FINISH BOTTOM AND TOP OF SEAT. FINISH INSTALLING BOTTOM CUSHION AND ASSEMBLE TWO CUSHIONS TOGETHER. CUT LEATHER FOR REAR COVER PANEL, GLUE LEATHER TO FINISH AND INSTALL COVER ON PANEL SEAT TO FINISH, CUT LEATHER FOR LEFT DOOR PANEL, SEW LINES AND INSTALL ON DOOR PANEL, TRIM PADDING ON DOOR PANEL AND GLUE LEATHER AROUND DOOR PANEL.	8.00	400.00
	COMPLETE INSTALLATION OF REAR END, TIGHTEN ALL DRIVE FLANGE BOLTS AND TORQUE TUBE ATTACHMENTS, REMOVE CLUTCH MASTER AND CHECK FOR PROBLEMS, REPLACE CLUTCH MASTER AFTER CLEANING AND ASSEMBLING. BLEED CLUTCH AND ADJUST FREEPLAY, INSTALL ALL A/C HOSES AND SECURE ALL CONNECTIONS, G0 OVER SYSTEM WITH	8.00	400.00

2

June 25, 1998

		Hours	Amount
	A/C REPAIR PERSON AND REPAIRED ALL LEAKS AS NEEDED. INSTALL WHEELS WITH CENTER CAPS. CONNECT FUEL RAIL AND ENGINE COMPARTMENT HOSES. PRESSURIZE FUEL SYSTEM AND CHECK FOR LEAKS.		
6/3/98	REPAIR LEAK AT FUEL FILTER AND RE-CHECK FUEL SYSTEM FOR LEAKS. INSTALL HEADERS WITH NEW GASKETS, SURFACED HEADER FLANGES IN ORDER TO HAVE A GOOD SEAL. INSTALL O-RINGS ON SPARK PLUG TUBES. INSTALL LEFT AND RIGHT DISTRIBTORS AND SET TO 10 DEGREES ADVANCE ON EACH. INSTALL CAP AND WIRE ASSEMBLIES, MAKE UP UPPER RADIATOR HOSE.	8.00	400.00
6/4/98	MAKE UP LOWER RADIATOR HOSE AND BLOCK OFF HEATER. FILL CRANKCASE WITH OIL AND FILL COOLING SYSTEM. FILL DIFFERENTIAL WITH OIL AND ADD LIMITED SLIP ADDITIVE. FINISH CLEANING EXHAUST AND PAINT WITH WRINKLE PAINT. INSTALL EXHAUST.	7.25	362.50
6/5/98	FINISH INSTALLING CHROME STRIP ON LEFT DOOR PANEL. INSTALL CLIPS TO HOLD CHROME IN PLACE. CUT LEATHER FOR RIGHT DOOR PANEL. MARK AND SEW LINES. INSTALL COVER. GLUE LINES IN PLACE AND TRIM PADDING. GLUE LEATHER AND FINISH BACK . INSTALL CHROME PLATES.	4.00	200.00
6/8/98	INSTALL HEAD LINER LEFT SIDE PANEL, ALL BOLTS SIDE RIGHT CHROME HOOKS, LEFT REAR CENTER TRIM POST PANEL, QUARTER WINDOW UPPER PANEL. REPEAT FOR RIGHT SIDE PANEL HEADLINER. INSTALL FRONT HEAD LINER PANEL, INSTALL REAR MIRROR, CHROME BRACKETS FOR SUN VISORS, CLEAN SUN VISORS AND INSTALL ROD. INSTALL SUN VISORS IN PLACE. INSTALL RIGHT OUTSIDE, WIPE ON DOOR WINDOW, INSTALL UPPER PANEL IN PLACE. INSTALL PIPING AROUND DOOR PANEL, AND DOOR PANEL IN PLACE.	8.00	400.00
6/5/98	REPAIR ELECTRICAL SYSTEM AND SET UP TEMPORARY IGNITION WIRES, TURN ENGINE OVER TO BUILD UP PRESSURE IN TOP END AND PREPARE TO START. WORK ON CARBURETORS TO START CAR	4.00	200.00

Hours Amount AND BRING TO TEMPERATURE. TAKE CAR OUTSIDE AND CHECK TIMING, ADJUST CARBS. AND SET IDLE. TEST DRIVE AROUND LOT TO MAKE SURE ALL GEARS FUNCTION. 6/9/98 FINISH INSTALLING ARM REST ON RIGHT DOOR 6.00 300.00 PANEL, REMOVE FRAME FROM LEFT DOOR, ALL BOLTS AND WINDOW FRAME. REMOVE WINDOW, INSTALL NEW OUTSIDE WIPER, INSTALL SCREWS TO HOLD WIPER IN PLACE. REMOVE TRACK FROM OLD WINDOW, CLEAN TRACK AND INSTALL ON NEW WINDOW, INSTALL WINDOW ON FRAME, RE-INSTALL FRAME IN PLACE, TIE ALL BOLTS AND TIE WINDOW IN PLACE, CHECK THAT WINDOW WORKS PROPERLY. FINISH INSTALLING BOLTS TO HOLD FRAME, CHECK WINDOW WORKS, INSTALL UPPER DOOR PANEL IN PLACE. INSTALL PIPING ON DOOR PANEL, FIT DOOR PANEL.

> REMOVE DISTRIBUTORS AND INSTALL MARELLI TAGS. REMOVE HEATER VALVE AND INSTAL NEW DIAHPRAM. TIGHTEN ALL EXHAUST NUTS AND INSTALL HEAT SHIELDS. MAKE UP NEW HOOD RELEASE CABLE, INSTALL HEATER VALVE AND SET UP HEATER CABLE. REMOVE FRONT RIGHT SHOCK AND REMOVE OLD BUSHINGS, PAINT SHOCK KONI ORANGE.

6/10/98 COMPLETE ASSEMBLY OF RIGHT SIDE SHOCK 8.00 400.00 ABSORBER WITH NEW BUSHINGS. PAINT SPRING AND RETAINING PLATES. ASSEMBLE COIL OVER AND SHOCK. ASSEMBLE FRONT RIGHT SUSPENSION AND SECURE ALL HARDWARE. REPEAT PROCEDURE ON LEFT SIDE AND COMPLETE LEFT SUSPENSION. PAINT SWAY BAR AND INSTALL NEW BUSHINGS.

> FINISH INSTALLING LEFT DOOR PANEL. FIT AND 8.00 400.00 INSTALL ARM REST. PURCHASE MATERIAL TO FIX REAR SPEAKER SHELF. REPAIRED AND REINSTALLED REAR SPEAKERS. FINISH INSTALLING REAR TRIM PANEL TO FINISH CARPET ON BACK. REMOVED SILL PANEL ON LEFT AND INSTALLED NEW RUBBER. REISTALLED SILL PANEL AND CHROME PIECE.

Page 6

8.00 400.00

June 25, 1998

		Hours	Amount
6/11/98	REMOVED SILL PANEL ON RIGHT SIDE. INSTALLED NEW RUBBER. REINSTALLED SILL PANEL AND CHROME PIECE. INSTALL CHROME BRACKETS TO HOLD NEW BELTS AROUND REAR PANEL. REMOVE RIGHT DOOR PANEL TO INSTALL CHROME RINGS, INSTALL LEATHER ON BOTTOM TO COVER CHROME RINGS. FINISH INSTALLING REAR COVER ON RIGHT SEAT.REMOVE LEFT REAR UPPER PANEL AND QUARTER PANEL TO WORK ON CABLE.	8.00	400.00
	PLUMB BOTH LEFT AND RIGHT HEATER CORES INSIDE FENDERS. ATTACH 4" DUCT AND SECURE TO CENTER MOUNT. ATTACH INNER WHEEL PANELS. REINSTALL WHEELS. FILL SYSTEM WITH WATER AND PRESSURE CHECK. FINISH PUTIING DISTRIBUTORS BACK. MOUNT W/WASHER PUMP ON FUSE PANEL BEHIND BATTERY. MOUNT VOLTAGE REGULATOR AND ATTACH WIRING. INSTALL CLIP ON SHIFTER. DRAIN GAS TANK AND REMOVE. INSPECT CABLES FOR TRUNK. EMERGENCY RELEASE CABLE NEEDS TO BE REPLACED.	8.00	400.00
	COMPLETE REPAIR OF TRUNK RELEASE CABLES AND TEST, PUT GAS TANK BACK IN PLACE WITH NEW HOSE ON CONNECTOR TUBE AND NEW CLAMPS, CONNECT ALL VAPOR HOSES AND CONNECT FILLER TUBE, REMOVE SHIFTER AND HOUSING, SHIM UNTIL HOLE MATCHES WITH CENTER CONSOL.	3.50	175.00
6/15/98	CORRECT WIRING TO AMP METER FOR CORRECT OPERATION. HOOK UP HOT ALWAYS LEAD FOR RADIO. INSTALL WINDOW SWITCHES IN CENTER CONSOL. WIRE UP SWITCHES AND CIGAR LIGHTER. CIGAR LIGHTER IS SHORTED, REMOVED WIRING. TEST RADIO, NO ANTENNA, FOUND BROKEN WIRE AND REPAIRED. NO SOUND, FOUND SPEAKER LEADS PULLED LOOSE UNDER DECK SHELF. TEST PARKING LIGHTS, HEADLIGHTS, WIRES, BRAKE LIGHTS. TURN SIGNALS, LICENSE LIGHTS, RADIO, ANTENNA, AND WINDOW OPERATION.	5.50	275.00

1

June 25, 1998

		Hours	Amount
6/15/98	REMOVE LEATHER CENTER PANEL FROM CENTER CONSOL TO FINISH LEATHER SHIFT BOOT. INSTALL LEATHER ON BOOT, GLUE TO FINISH RE-INSTALL CENTER PANEL ON CONSOL AND FIT ON CAR.	2.00	100.00
6/17/98	FINISH INSTALLING CENTER CONSOLE. INSTALL CARPET FLOOR MATS RIGHT AND LEFT. INSTALL SEATS RIGHT AND LEFT.	3.00	150.00
	ADD 5 GALLONS FUEL. RESET IGNITION TIMING, TEST DRIVE. BEGIN INSTALLING EXHAUST HANGERS	1.50	75.00
6/18/98	FINISH INSTALLING EXHAUST HANGERS. INSTALL FRONT RADIATOR PROTECTOR. POLISH STEERING WHEEL RING AND INSTALL TEMPORARY STEERING WHEEL. CHECK ALL ELECTRICALS.	4.00	200.00
6/19/98	SET UP HOOD SPRING RODS AND INSTALL. CLEAN ALL HARDWARE FOR HOOD. INSTALL HOOD AND ADJUST FOR BEST FIT. FINE TUNE CARBURETORS AND TEST DRIVE. INSTALL AIR CLEANER HOUSING AND BOLT IN PLACE.	4.00	200.00
6/22/98	COMPLETE REPAIRING MASTER CYLINDERS AND INSTALL. FILL FLUID RESERVOIRS AND BLEED HYDRAULIC SYSTEM. TAKE CAR FOR TEST DRIVE. REPAIR CLUTCH HYDRAULICS AND ADJUST FOR PROPER FREEPLAY. STRAIGHTEN STEERING WHEEL, INSTALL TRUNK LATCH COVER, ADJUST HOOD HOOD CABLE AND CATCH, SET UP MECHANICAL FUEL PUMPS TO FUNCTION PROPERLY.	7.50	375.00
6/23/98	INSTALL SPEEDO CABLE AND TEST TO MAKE SURE IT WORKS. REMOVE CHOKE CABLE ARM AND REMOVE BROKEN CABLE HOUSING, SET UP SO THAT OLD CABLE CAN STILL BE USED. ENSURE PROPER CHOKE CABLE FUNCTION.	2.00	100.00
	Adjustments made to services		(\$32.96)
	- For professional services rendered	230.25	\$11,479.54

25

June 25, 1998

Page 9

Additional charges

		Amount
5/22/98	RESURFACE FLYWHEEL	28.75
	ZINC PLATE MISC PARTS	36.23
5/27/98	BRAKE FLUID	5.99
	SEAL	6.40
5/28/98	SHIPPING OF SEAL	4.47
6/1/98	OIL SEAL	16.84
	GROMMETS	18.00
	SPARK PLUGS RESISTORS	\ 38.28
	FIRING ORDER PLATE	45.00
	SHIPPING	11.13
	CHROME PLATE WHEEL RINGS	125.00
	, CHROME PLATE KNOCK OFFS	720.00
	CHROME PLATE VISOR	40.00
	CHROME PLATE RAIL	80.00
	CHROME PLATE SHIFTER	40.00
	CHROME PLATE SILL	90.00
6/3/98	CHARGE AIR CONDITIONER	143.75
6/4/98	10 QTS OIL	13.08
	5 QTS GEAR OIL	23.85
		E (2)
	1 TUBE GEAR ADDITIVE	5.63
8	1 LWR RAD HOSE	16.35

17

Page 10

		Amount
6/8/98	SHIFT ROD	49.95
	SHIPPING	17.05
	SHIPPING	3.85
	SCREW	1.83
	CARB CLEANER	8.90
6/15/98	UPHOLSTERY MATERIAL	7.20
6/9/98	4" DUCTING HOSE	37.44
5/26/98	BELTS	44.80
6/2/98	RUBBER LOWER DOOR	39.90
	INNER DOOR SEAL PER FOOT	90.00
	TRUNK UPPER SEAL	64.35
	HOOD AND TRUNK EDGE SEAL	25.35
	EXHAUST HANGER STRAPS	99.40
	STICKER "DUNLOP"	16.95
	CAVIS HOSE	21.00
	DISTRIBUTOR ID PLATE	32.00
	HEATER VLV DIAPHTAM 60 MM	18.95
	SHOCK BUSH.	65.00
	OIL FILTER FRAM	29.90
	PRIMARY WIRE "BOOT"	5.94
	SHIPPING	32.56
6/22/98	BRAKE FLUID	8.22
6/23/98	SPEEDOMETER CABLE	28.19

the state

Page 11

	Amount
Total costs	\$2,257.48
Sales tax	\$68.56
Total time and expense charges	\$13,805.58
5/26/98 -CC PAYMENT #2087	(\$21,144.80)

22

FOR YOUR CONVENIENCE WE NOW ACCEPT VISA, MASTER CARD AND DISCOVER CARD