

NUMBER	DESCRIPTION	PRICE
1 901-613-302-24 SWT		51.75
1 911-635-101-00 HORN		14.15

PORSCHE AUDI DEALER NO. 401/A09

CHASSIS NO. 9113102030	DELIVERY DATE 6/23	REPAIR DATE 7-17-73	MILEAGE 3011
LICENSE NO. 245-488	RECEIVED 9/2	PROMISED 3/2	ADD. REPAIRS YES ☐ NO ☐
INVOICE LIMIT	PHONE BUS ☐ RES ☐	ENGINE OIL ☐	TRANS. OIL ☐
\$	CHARGE	OIL CHANGE SERVICE ☐	
☐ CASH ☐ INTERNAL	QUALITY CONTROL	MAINTENANCE ☐	
ESTIMATE \$			
SERVICE ADVISER	OK'D BY	SERVICE ADVISER	

OPER. NO.	TIME UNITS	DESCRIPTION	SUB-TOTAL
		Horn Blows When Wheel is turned (automatic)	
	A2 80	R & R splash	
	91391010 20	Replaced Wheel Sw.	
	73011010 40	Replaced One Horn	

QUARTS @	ENGINE OIL
PINTS @	TRANSMISSION OIL
PINTS @	A.T.F.

TOTAL GAS & OIL:

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

REPAIR ORDER No. 15085

CONTROL NO.

COMMONWEALTH PORSCHE AUDI, INC.

884 COMMONWEALTH AVE.

BOSTON, MASS. 02215

TEL - (617) 277-4336

PORSCHE AUDI

Thank You

DESCRIPTION	SALE
MECH. LABOR/LUBE	
OTHER SHOP LABOR & MATERIAL	
P/A PARTS	
P/A ACCESSORIES	
OTHER PTS. & ACCESS.	
GAS, OIL & GREASE	
SUBLET	
SALES TAX	
TOTAL CHARGE SALES	
TOTAL CASH SALES	

INVOICE NO. 15085

QUAN.	NUMBER	DESCRIPTION	PRICE
2	241-101	W/W 59	95.190
1	916-107	754-00	5.55
2	901-101	391.00	32.64
2	Amso blades	3.10	6.20

PORSCHE AUDI DEALER NO. 401/A09

CHASSIS NO. 9113102030 DELIVERY DATE June 73 REPAIR DATE FEB 8 MILEAGE 10461
 LICENSE NO. 205488 RECEIVED 8:30 AM PROMISED 5:30 AM ADD. REPAIRS YES NO
 INVOICE LIMIT PHONE ENGINE OIL TRANS. OIL
 \$ CHANGE PRICE
☐ CASH ☐ INTERNAL CHARGE QUALITY CONTROL MAINTENANCE
 ESTIMATE \$ 140-
 SERVICE ADVISER OK'D BY SERVICE ADVISER

OPER. NO.	TIME UNITS	DESCRIPTION	SUB-TOTAL
	50	10,000 mile check. Change oil & filter	7.00
		Install Amso Blades.	
	42 50	free up & lube 4/ front window	14.00
ACCESSORIES			
SUBLET REPAIRS			

10	QUARTS @ 1.00	ENGINE OIL	10.00
	PINTS @	TRANSMISSION OIL	
	PINTS @	A.T.F.	

TOTAL GAS & OIL:

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

REPAIR ORDER No. 18956 CONTROL NO.

COMMONWEALTH PORSCHE AUDI, INC.

884 COMMONWEALTH AVE.

BOSTON, MASS. 02215

TEL - (617) 277-4336

PORSCHE AUDI

Thank You

DESCRIPTION	SALE
MECH. LABOR/LUBE	7.00
OTHER SHOP LABOR & MATERIAL	
P/A PARTS	6.19
P/A ACCESSORIES	1.70
OTHER PTS. & ACCESS.	6.20
GAS, OIL & GREASE	10.00
SUBLET	
SALES TAX	7.32
TOTAL CHARGE SALES	
TOTAL CASH SALES	32.02

INVOICE NO. 18956

QUAN.	NUM	DESCRIPTION	PRICE
1	911-110-185-01	fitting	850
1	911-107-754-00	fitting	866
2	901-105-194-03	V/C	190
2	901-105-195-04	V/C	190
2	901-101-391-00	stop	190
6	211-121-107	stop	270
1	911-110-184-00	fitting	1550
2	211-241-101	stop	190
1	901-602-960-00	stop	270
1	911-110-365-00	stop	76

DEALER NO. 401/A09

CHASSIS NO. 9113102030		DELIVERY DATE 4/22/73		REPAIR DATE 2/21/74		MILEAGE 10910	
LICENSE NO. 265488		RECEIVED		AM PM 3 30		ADD. REPAIRS YES ☒ NO	
INVOICE LIMIT		PHONE		ENGINE OIL		TRANS. OIL	
\$				CHANGE RVICE		☒	
☐ CASH ☐ INTERNAL		CHARGE		QUALITY CONTROL		MAINTENANCE ☒	
ESTIMATE \$						☒	
SERVICE ADVISER		OK'D BY		SERVICE ADVISER		☐	

				OPER. NO.	TIME UNITS	DESCRIPTION	SUB-TOTAL
						10,000 ch.	78.00
						no oil change - just done	
						Clean + Re paint heater	6.00
						tapes	
ACCESSORIES							
SUBLET REPAIRS							

QUARTS @	ENGINE OIL	
PINTS @	TRANSMISSION OIL	
PINTS @	A. T. F.	
TOTAL GAS & OIL:		

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES
LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE
BEYOND OUR CONTROL.

REPAIR ORDER No. 19186

CONTROL NO.

COMMONWEALTH PORSCHE AUDI, INC.

884 COMMONWEALTH AVE.

BOSTON, MASS. 02215

TEL - (617) 277-4336

PORSCHE | AUDI

Thank You

DESCRIPTION	SALE
MECH. LABOR/LUBE	24.50
OTHER SHOP LABOR & MATERIAL	
P/A PARTS	50.32
P/A ACCESSORIES	1.90
OTHER PTS. & ACCESS.	
GAS, OIL & GREASE	6.00
SUBLET	
SALES TAX	1.72
TOTAL CHARGE SALES	
TOTAL CASH SALES	146.47

SOURCE 30

510

DATE 1/25/

Z (NO SERVICE FOLLOW-UP)

MILEAGE		PHONE	
CHASSIS NO.		BUS	
REPAIR DATE		MODEL	
DEL. DATE		MODEL YR.	
SELLING DIST. DEALER		QUALITY CONTROL INSPECTOR	
PARTS SUBMIT Y = YES X = NO		SV TYPE SERVICE	
SERV. ADV.		LICENSE NUMBER	
USED VEHICLE STOCK NO.		1 OIL CHANGE	
		2 DIAGNOSIS	
		3 RECOMMENDED MAINTENANCE	
		4 OTHER LISTED BELOW	
		SUB-TOTAL	

4-C Blowing Hot. 20,000 mi maintenance check change Eng TRANS oil. Replace Air cleaner struts. Replace Valve Cover gaskets. Throttle - set to spec. Do all checks & inspections under Maintenance Schedule. Recharge A.C. System. Repair Test & Recharge. Replace windshield.

DEALER NO. 401/A16

LIBON PORSCHE-AUDI INC.

884 COMMONWEALTH AVE.
BOSTON, MASS. 02215
TEL. A/C (617) 738-0220



IF OUR SERVICE IS SATISFACTORY
TELL YOUR FRIENDS!
IF NOT - PLEASE TELL US!

THANK YOU

[illegible]

EXPERT COLLISION REPAIRS ON ALL MAKES OF CARS

LIBON PORSCHE-AUDI INC.
BOSTON, MASS. 02215

August 21, 1974

Mr. John R. Kasper
DeLand, Gibson & Moore
40 Broad Street
Boston, MA 02109

Dear John,

Enclosed is a copy of the bill to repair my windshield in the amount of \$250.55.

The windshield was broken on August 8, 1974, by debris flying from a passing truck while I was traveling north on Route 3 in Braintree, Massachusetts.

Yours truly,

DEALER NO. 401/A16
LIBON PORSCHE-AUDI INC.
884 COMMONWEALTH AVE.
BOSTON, MASS. 02215
TEL. A/C (617) 738-0220



IF OUR SERVICE IS SATISFACTORY
TELL YOUR FRIENDS!
IF NOT - PLEASE TELL US!

THANK YOU

DESCRIPTION		PRICE	DATE	TIME	UNIT
WINDSHIELD REPAIR		250.55	8/21/74		
SUB TOTAL		250.55			
TAX					
TOTAL		250.55			

NAME, ADDRESS, ZIP CODE	DATE	TIME	UNIT
Mr. John R. Kasper DeLand, Gibson & Moore 40 Broad Street Boston, MA 02109	8/21/74		

DESCRIPTION	PRICE	DATE	TIME	UNIT
WINDSHIELD REPAIR	250.55	8/21/74		
SUB TOTAL	250.55			
TAX				
TOTAL	250.55			

11276

VW DEALER NO.

DATE 6/25/75
(NO SERVICE FOLLOW-UP)

QTY	P/ NUMBER/	DESCRIPTION	P \$ PRICE
1	911-107-754-00	filter	975
1	911-531-063-00	handle	3250
2	N-11-005-2	NUTS	14
1	6442	WIRE NUTS & BOLTS	150

d	MILEAGE	34880
e	CHASSIS NO.	
f	REPAIR DATE	6-25-75
g	DEL. DATE	
h	MODEL YR.	911
i	SELLING DIST./DEALER	NW
j	PARTS SUBMIT	
k	Y = YES X = NO	
l	SERV. ADV.	
m	CENSE NO.	265-488
n	USED VEHICLE STOCK NO.	

☐ CASH ☐ CHARGE OK'D BY

QUALITY CONTROL INSPECTOR

SV	TYPE SERVICE	1	2	3	4
1	OIL CHANGE				
2	VW DIAGNOSIS				
3	VW MAINTENANCE				
4	OTHER - LISTED BELOW				

SUB-TOTAL

OTHER P & A

ACCESSORIES

CHANGE OIL & FILTER
 REPLACE LEFT DOOR HANDLE
 RECODE LOCK
 ADJUST DOOR STRIKER

E /COMMENTS/

T C TOWING CHARGE



CUSTOMER NO. 1

MECH. LABOR	24 00
OTHER SHOP	
OIL & GREASE	10 00
SUBLET	
PARTS	42 39
ACCESS.	3 50
OTHER P & A	
6442	1 50
TAX	1 73
SUB TOTAL	
CHARGE	
CASH	93 12

THANK YOU

SOURCE 30

CUSTOMER NAME, ADDRESS, ZIP CODE

ATLANTA • CHICAGO • SAN FRANCISCO • LOS ANGELES • OKLAHOMA CITY • HONOLULU

VW 22-99-30321-2 (11-73)

ATAMIAN PORSCHE AUDI, Inc.

300 Grove Street Worcester, Mass. 01609 Phone 617-798-8881


March 12, 1975

The following is a list of the labor operations that you requested I forward to you.

1. Replaced exploded starter
2. Remove and install engine and transmission
3. Separate engine from transmission- .25T.U.
4. Remove and install both crankshaft housings
5. Remove and install both crankshafts
6. Adjust timing both sides
7. Remove and install one camshaft sprocket
8. Remove and install intermediate shaft
9. Remove and install both chain tensioners
10. Recondition one chain tensioner
11. Replace chain guide ramps on one side
12. Remove and install both chain housings
13. Replace both chain housing covers
14. Replace one rocker arm shaft
15. Replace three rocker arms
16. Replace and install one valve spring
17. Remove and install both cylinder banks
18. Diagnosis Time 2.00 T.U.
19. Check cylinder compression
20. Remove and install Air conditioner compressor 1.50 T.U.

The following page contains a list of parts and description. If I may be of further help in this matter, please call at your convenience.

Sincerely,


Michael Delouchey
Service Manager

MD:gh
enc

ATAMIAN PORSCHE AUDI, Inc.

300 Grove Street Worcester, Mass. 01609 Phone 617-798-8881

1- # 91110090100	Gasket
3- # 91110541500	Exhaust Valves
3- # 90110504300	Rocker arms
1- # 90110537002	Rocker Arm Screws
2- # 90110522202	Chain Sliders
1- # 91110590100	Chain Tensioner Kit
1- # 90110558301	Flange
16	Sealing Nuts
1- # 91110775400	Oil Filter
1- # 90024500100	Pin
1- # 90002802101	Washer
1- # 90160410203	Starter

- KEN CAR -

408/076 DEALER NO.

681

Z

(NO SERVICE FOLLOW-UP)

DATE 12/16/75

QTY	P/NUMBER/	DESCRIPTION	P \$ PRICE
1	901 107 754 00	O.I. Filter	9 75
2	911 341 913 03	Shocks	135 00
2	911 333 051 01	"	128 00

MILEAGE 45535

CHASSIS NO. 9113102030

REPAIR DATE 9/11/75

DEL. DATE 9/11/75

MODEL 3

MODE YR. 3

SELLING DIST./DEALER

PARTS SUBMIT Y= YES X= NO

SERV. ADV. LICENSE NO.

USED VEHICLE STOCK NO.

TIME PROMISED 4 PM

QUALITY CONTROL INSPECTOR

SV TYPE SERVICE 1 3 4

1 OIL CHANGE

3 MAINTENANCE

4 OTHER - LISTED BELOW

SUB-TOTAL

OTHER P & A

ACCESSORIES

WILL NEED CHANTENSIONER ON RT. SIDE

1200 - 25

PTS - 90

TAX - 132

E /COMMENTS/

T C TOWING CHARGE

PAID

DEC 16 1975

PORSCHE AUDI OF AVON, INC.

L \$ PRICE	L/OPERATION/	#TIME UNITS
36 00	✓	200
7 20		040

SUBLET

P. O.

P. O.

W / DAMAGE CODE /

W / DAMAGE CODE /

PORSCHE + AUDI

PORSCHE AUDI OF AVON, INC.

262 WEST MAIN STREET

AVON, CONN. 06001

Telephones AVON: 678-0880 - HARTFORD 246-1888

CUSTOMER NO. f	
MECHANICAL LABOR	43 20
OTHER SHOP	2 00
OIL & GREASE	11 25
SUBLET	
P + A PARTS	272 25
P + A ACCESSORIES	
OTHER PARTS & ACCESS.	
TAX	19 88
SUB TOTAL	
CHARGE SALES	
CASH SALES	349 08

LIMIT

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

MATE

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

349.08

41271

Q QUAN.	P / NUMBER /	DESCRIPTION	UNIT	TOTAL
1	901-108-735-00	ATF		0.95
2	901-105-1740-3	V/C	1.35	2.70
2	901-105-195-04	V/C	1.35	2.70
2	901-101-391-20	S/H	50	1.00
1	911-110-184-00	#/A		2.25
1	901-351-912-3	13505	3.90	31.20
1	911-109-754-00	O/A		9.95
2	900-123-011-20	200	24	48
1	911-110-185-01	filter		11.25
1	911-618-7-3-2		W	4.73
1	911-305-4-2	Clamp	W 32	1.99
ACCESSORIES				
1	911-232-101	W/Solvent		1.30
1	911-232-101	2 1/2" dia. blr	W	16.40
1	911-232-101	2 1/2" dia. blr	W	16.40

ET			GAL. GAS @		
			QTS. ENG. OIL @	10	
			PTS. TRANS. OIL @	16	

[illegible]

I hereby authorize the above repair work to be done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. TERMS: STRICTLY CASH

I UNDERSTAND THAT STORAGE WILL BE CHARGED 24 HOURS AFTER REPAIRS ARE COMPLETED.
PLEASE REMOVE ALL VALUABLES FROM YOUR CAR

SIGNED

CUSTOMER NAME, ADDRESS, ZIP CODE

MILEAGE		SERIAL NO.	
e 29,115		s	
DELIVERY DATE		SELLING DIST. DEALER	
: /		AM PM AM PM	
YEAR		MODEL	
7-3		8-2 per 9115	
LICENSE NO. AND STATE		WARRANTY	
265-488		YES NO	
SERVICE ADVISOR		MECHANIC #	
1A ✓			

☐ FILTER ☐ LUBE ☐ CHANGE ENGINE OIL ☐ CHANGE TRANS. OIL ☐ CHANGE A.T. FLUID

L/OPERATION/	#TIME UNITS	
	220	Major maint repl. vent cap repl vent & h pads
		Note: needs 2.5 hrs & 4 sig.
		healer & ps
H-D-075	60	HDCamp

E / COMMENTS /

DESCRIPTION	SALE
MECH. LABOR	115.00
P-A PARTS	149.80
P-A ACCESSORIES	
MISC. SUPPLIES	6.00
OIL	10.00
BODY REPAIRS	
TOWING	
SUBLET	
TAX	5.97
TOTAL	316.77

LIBON PORSCHE-AUDI INC.

884 Commonwealth Ave. • BOSTON, MASS. 02215

Dial 738-0220

**IF OUR SERVICE IS SATISFACTORY
TELL YOUR FRIENDS!
IF NOT — PLEASE TELL US!**

THANK YOU

PORSCHE
AUDI

PORSCHE
AUDI

THIS REPAIR ORDER DESIGNED BY BERTRAM LIBON

55-6989-2 Norick Oklahoma City

EXPERT COLLISION REPAIRS ON ALL MAKES OF CARS
THIS REPAIR ORDER DESIGNED BY BERTRAM LIBON
Tulahoma City

- RIGHT CAMSHAFT SPROCKET NUT BROKE OFF
40 HOURS

$$\begin{array}{rcl} 3 \times 26 & \blacksquare & 100 \text{ VALVES} \\ 40 \times 14 & = & 560 \text{ LABOR} \\ \text{PARTS} & & \end{array}$$

SPROCKET	12
CHAIN RAILS	10
GASKET	103
	1000

- NUT ON CAMSHAFT BROKE OFF ON RIGHT SIDE
CAMSHAFT SPROCKET BECAME DISCONNECTED + GROUND UP
RUINED 3 TIMING CHAIN GUIDES
QUITE POSSIBLY BENT 3 VALVES
SHAVINGS THROUGHOUT ENGINE

6 MONTHS WARRANTY 6000 MILES

VW America N.E. Region → June '73 Purchase
140 Furthest Rd. 28,800 miles
Wilmington, Mass.

617-656-6700

- MGR. CUSTOMER RELATIONS - Mrs. Linda Savini Called on 1/31
General Service Mgr. - Mr. SOMMERSCHMIDT
- EARLIEST Friday 7 LATEST 15

Pres - ARNOLD BENTHOLDT

1/28 - Can TARD - 2 Calls

1/29 - 2 Calls

1/30 - 2 Calls

1/31 - DeLongury, Savini

2/5 - DeLongury Call @ 4 PM

4 PM Call

My Estimate - \$900-

2/6 - DeLongury says Parsons pay parts only

Savini says can't do any more

Not accepting guilt, this is GOOD WILL.

Pursue on ~~different~~ basis - Mr. Dörr

Cust. Rel. Mgr. - USA

201-567-7600

DATE - / /

SOURCE 30

846

☐ Z (NO SERVICE FOLLOW-UP)

SOURCE 30

WORLD TIRE & APPLIANCE CO.

DISTRIBUTORS

FIRESTONE • GOODYEAR • U.S. • DUNLOP • MICHELIN • TOYO

NO CASH REFUNDS
ON
USED TIRES

TIRES - SALES & SERVICE - TUBES

ALL TYPES RADIAL TIRES IN STOCK

15% HANDLING
CHARGE ON RETURN
OF NEW MERCHANDISE

85 Commercial Ave. Off Cambridge Pkwy.

Cambridge, Mass. 02142

Customer's Order No. 309421 Phone No.

Date 10-7-1975

Sold To

Address

City

State

Zip

QUAN.	TIRE SIZE	DESCRIPTION	PRICE	AMOUNT
2	185/70/15	DUNLOP SP57		
		RADIAL TIRE	50.00	100.00
		FED TAX	2.18	4.36
		SALES TAX		3.12
2		MAC WHEELS		
		CHANGED & BALANCED	10.00	20.00
				127.48
		TAX		
		TOTAL		

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL
DEPOSITS NOT REFUNDABLE AFTER 30 DAYS. \$5.00 SERVICE CHARGE ON ALL ADJUSTMENTS.

G 004647

Salesman

Received By

THIS IS YOUR INVOICE

WORLD TIRE & APPLIANCE CO.

DISTRIBUTORS

FIRESTONE • GOODYEAR • U.S. • DUNLOP • MICHELIN • TOYO

NO CASH REFUNDS
ON
USED TIRES

TIRES - SALES & SERVICE - TUBES

15% HANDLING
CHARGE ON RETURN
OF NEW MERCHANDISE

ALL TYPES RADIAL TIRES IN STOCK

85 Commercial Ave. Off Cambridge Pkwy.

Cambridge, Mass. 02142

Customer's
Order No.

Phone
No.

Date

8-18-1975

Sold To

Address

City

State

Zip

QUAN.	TIRE SIZE	DESCRIPTION	PRICE	AMOUNT
1	185/70-15	DUNLOP CB57		
		BUS T.T.		
		RADIAL TIRE		50.00
		FCO TAX		2.48
		3-1/2 SALES TAX		1.58
		LABOR MOUNTING & TY		
		MAG Wheel		5.00
2		MAG WHEELS DYNAMIC		
		BALANCE		10.00
		PLUS WEIGHTS		2.00
		TAX		
		MASTER CHARGE TOTAL		71.06

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS BILL
DEPOSITS NOT REFUNDABLE AFTER 30 DAYS. \$5.00 SERVICE CHARGE ON ALL ADJUSTMENTS.

G 003402

Salesman

Received By

THIS IS YOUR INVOICE

408/076 DEALER NO.

7201

Z

SERVICE FOLLOW-UP)

DATE

6 Jan '76

QTY	P/NUMBER/	DESCRIPTION	P \$ PRICE
1	90110504902	Ch. Tens.	89 60
1	90110519203	gasht	49
1	N177222	bulb	60

90 69

e	MILEAGE	46305
s	CHASSIS NO.	9113102030
i	REPAIR DATE	9/11
:	DEL. DATE	73
:	MODEL YR.	73
%	SELLING DIST. DEALER	
P	PARTS SUBMIT	Y= YES X= NO
so	SERV. ADV.	MASS
	LICENSE NO.	265-488
v	USED VEHICLE STOCK NO.	

☐ CASH ☐ CHARGE ORDER BY

QUALITY CONTROL INSPECTOR

SV TYPE SERVICE 1 3 4

1 OIL CHANGE

3 MAINTENANCE

4 OTHER—LISTED BELOW

SUB-TOTAL

L \$ PRICE L/OPERATION/ # TIME UNITS

Replace noisy r/t chain
Tensioner Remove & Reinstall 1/2 cond

31 50
9 00

175
050

Severe smoking & oil consumption
ONLY IN cold weather.

✓ Repair tach light, it sick

13 50

075

E /COMMENTS/

T C TOWING CHARGE

Ch oil level.

SUBLET		GAL. GAS	
P. O.		2 QTS. ENG. OIL @	2 50
P. O.		PTS. TRANS. OIL @	

W / DAMAGE CODE /	WTY. CODE	W / DAMAGE CODE /

LIMIT

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

MATE

X to [Signature]

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

PORSCHE + AUDI

PORSCHE AUDI OF AVON, INC.

262 WEST MAIN STREET

AVON, CONN. 06001

Telephones AVON: 678-0880 — HARTFORD 246-1888

CUSTOMER NO.	
MECHANICAL LABOR	54 00
OTHER SHOP	
OIL & GREASE	2 50
SUBLET	
P + A PARTS	90 69
P + A ACCESSORIES	
OTHER PARTS & ACCESS.	
TAX	6 52
SUB TOTAL	
CHARGE SALES	
CASH SALES	153 71

SLV 911

408/076 DEALER NO.

1750

DATE 5/19/76

QTY	P/NUMBER	DESCRIPTION	P.S. PRICE
1	911 107 75400	Oil Filter	10.25
1	911 110 185 01	Air	11.95
1	911 354 901 00	Fuel	25.60
1	901 602 960 00	PTs	3.85
6	2PP121107	Plugs	37.50
2	901 105 19403	VC6	2.80
2	901 105 19504	VC6	2.80
2	901 301 39100	OS6	1.00
6	901 602 39900	Connector	36.60
2	901 609 30900	Connector	12.20
1	N177512	BULB	70
2	ACCESSORIES		
		WSW Solv.	1.80
		Freon	4.50
Needs: Left heat exchanger			
SUBLET		GAL. GAS @	
P.O.		11 QTS. ENG. OIL	125 13.75
P.O.		6 PTS. TRANS. OIL	100 6
			19.75
W/DAMAGE CODE	WTY CODE	W/DAMAGE CODE	
LIMIT			I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.
RATE			NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL

MILEAGE 50912

CHASSIS NO. 911B102030

REPAIR DATE 5/11/76

MODEL 911-T

DEL. DATE 5/11/76

MODEL YR. 3

SELLING DIST. DEALER

PARTS SUBMIT Y= YES X= NO

SERV. ADV. LICENSE NO. 825-6645

USED VEHICLE STOCK NO.

TIME PROMISED 4 pm

QUALITY CONTROL INSPECTOR

SV TYPE SERVICE 1 3 4

1 OIL CHANGE

3 MAINTENANCE

4 OTHER LISTED BELOW

SUB-TOTAL

L.S. PRICE	L/OPERATION/	#TIME UNITS
96	50,000	400
15.00		080
7.60		040
9.50		050
/COMMENTS/		
T.C. TOWING CHARGE		

PORSCHE + AUDI

PORSCHE AUDI OF AVON, INC.

262 WEST MAIN STREET
AVON, CONN. 06001

Telephones AVON: 678 - 0880 - HARTFORD 246 - 1888

CUSTOMER NO. f

MECHANICAL LABOR 108.30

OTHER SHOP 5

OIL & GREASE 19.75

SUBLET

P+A PARTS 108.65

P+A ACCESSORIES 6.30

OTHER PARTS & ACCESS.

TAX 9.78

SUB TOTAL

CHARGE SALES

CASH SALES 257.78

DATE 7/21/76
(UP)

[illegible]

Owed 1.28
Shond
Guthrie

E	/COMMENTS/
TC	TOWING CHARG

[illegible]

~~\$~~18.72

INTERNATIONAL AUTOMOBILE ENTERPRISES

608 EAST MAIN STREET
NEW BRITAIN, CONNECTICUT 06051
TELEPHONE 203-224-0253

NO.

665

DATE

SEPT 29/74

CUSTOMER'S
ORDER NO.

665

SOLD TO

SHIP TO

SAME

1973 PORSCHE 911T SILVER

SOLD BY	CASH	C. O. D.	CHARGE	ON ACCT.	MDSE. RETD.	PAID OUT	
QUAN.	DESCRIPTION						PRICE AMOUNT
	REPAIR, STRIP & PAINT CAR (SILVER)						LABOR 1472 00
	R&R NEW WINDSHIELD CASSETS						PARTS 57 00
	R&R NEW REAR WINDOW CASSETS						PAINT 138 00
	BUB & BLISH						MATERIALS 13 65
	CLEAN WHEELS						TAX 50 00
	NOTE :						WARRANTY 50 00
	CAR MUST LOOK LIKE NEW						TOTAL 1,730 65
	INSIDE & OUT						

ALL claims and returned goods MUST be accompanied by this bill.



SNAP-A-PART
47-103
MADE IN U. S. A.

Received by

DUPLICATE

SLV COUPE

408/076 DEALER NO.

6210

DATE

1/28/77

NO SERVICE FOLLOW-UP

QTY	P/NUMBER/	DESCRIPTION	P \$ PRICE	MILEAGE	CHASSIS NO.	REPAIR DATE	DEL. DATE	SELLING DIST. DEALER	PARTS SUBMIT	SERV. ADV.	USED VEHICLE STOCK NO.
1	91111091710	W.U. REG (CL)		56180	9113102530				Y= YES X= NO		
1	91110775400	G-F.1762	12.25								

CASH CHARGE OK'D BY

Time provided

QUALITY CONTROL INSPECTOR

SV TYPE SERVICE

1 OIL CHANGE

3 MAINTENANCE

4 OTHER LISTED BELOW

SUB-TOTAL

L S PRICE

L/OPERATION/

TIME UNITS

CL CAMP (Warm up Reg)

CAMP

CL-#12

030

HEAVY OIL OUT EXHAUST W/ STOPPED
COLD & DRIVEN BEFORE WARM

O/K & FILT

E /COMMENTS/

CK BATTERY, FLUID, T.P. etc

10.00

050

T C TOWING CHARGE

NO A/C - ABS FUSES (COMPRESSOR LOCKS UP)

4.09

020

CUSTOMER NO.

MECHANICAL LABOR

OTHER SHOP

OIL & GREASE

SUBLET

P+A PARTS

P+A ACCESSORIES

OTHER PARTS & ACCESS.

TAX

SUB TOTAL

CHARGE SALES

CASH SALES

PORSCHE + AUDI

PORSCHE AUDI OF AVON, INC.

262 WEST MAIN STREET

AVON, CONN. 06001

Telephones AVON: 678 - 0880 - HARTFORD 246 - 1888

LIMIT

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

DATE

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

January 28, 1977

Ann Langran
Porsche Audi Eastern
Greenbush Road
Orangeburg, NY 10962

Dear Ann:

Enclosed please find documentation to support my customer's claim for full retail reimbursement for replacement of the headlamp dimmer switch 911 613 301 30 on his 1973 911 chassis number 9113102030. The work was done by Libon Porsche Audi, October 8, 1975 on their R.O. 13888. The customer's complaint was loss of headlamps after turning corners. This problem is the subject of recall campaign CN as covered in S.C.L. 107/73C and should have been done without charge.

Mr. Teirney's request comes at this time as a result of my letter to him after his name appeared on the recall print-out of October 25, 1976. I also enclose the "CN" page from the August 11, 1976 print-out to show that Porsche Audi of Avon was not remiss in following up its requirements under federal campaign law.

Your help in correcting this problem between Mr. Teirney and Libon Porsche Audi would be greatly appreciated.

Sincerely,

Gerard J. McCarthy
Service Manager

GJM:db

EXPERT COLLISION REPAIRS ON ALL MAKES OF CARS

☐ CASH ☐ CHARGE

D.K. BY

409/1401 DEALER NO.

25718

SERVICE FOLLOW-UP

DATE

3/20/74

QTY	P/NUMBER/	DESCRIPTION	P S PRICE
2930	10519400	VC Gaskets	8 80
2930	10519500	"	9 20
62PP	121107	Plugs	32 70
1911	60293600	Points	7 80
1930	10776400	Filter	20 70
1911	11018502	Air Filter	29 15
1900	12301120	DP Seal	52
2900	08401402	Nuts	7 92
1901	60296000	Point	6 60
1810	133511	Fuel Filter	13 95
			129 54
OTHER P & A			
ACCESSORIES			
SUBLET			
P.O.		11 QTS. ENG OIL	16 50
P.O.		6 PTS. TRANS OIL	6 00
W / DAMAGE CODE /		WTY CODE	W / DAMAGE CODE /

MILEAGE 83461

CHASSIS NO. 4113102030

REPAIR DATE 3/11/74

DEL. DATE 6/73

SELLING DIST. DEALER 401909

PARTS SUBMIT Y: YES X: NO

SERV. ADV. 34

LICENSE NO. 1305

USED VEHICLE STOCK NO. 1305

COLOR SILVER

QUALITY CONTROL INSPECTOR

TYPE SERVICE 1 2 3 4

1 OIL CHANGE ☐ TRANS. ☐

2 LUBE SERVICE

3 VW DIAGNOSIS

4 VW MAINTENANCE

5 OTHER - LISTED BELOW

SUB TOTAL

156 00

CHECK FOR OIL LEAK CLEAN.

HEADLIGHT DIMMER SWITCH OUT

RECALL HEN.

CHANGE TRANS OIL

COMPRESSION TEST. REPORT.

1 2 3 4 5 6

Oil 125 - 110 - 90 - 130 - 120 - 115

STEAM CLEAN PO# 9526

PORSCHE + AUDI



11020 Main Street
FAIRFAX, VIRGINIA 22030
Telephone (703) 591-1820

THANK YOU

ADDITIONAL WORK NEEDED:

CUSTOMER NO. 1	
MECHANICAL LABOR	164 00
LABOR O.M.	
OTHER SHOP	4 92
OIL & GREASE	22 50
SUBLET REPAIRS	12 00
PARTS	129 54
ACCESSORIES	
OTHER PARTS & ACCESSORIES	
SALES TAX	6 28
SUB TOTAL	
TOTAL	339 24


E LIMIT

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

MATE

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.



P.O. #

PHONE
FAIRFAX - 273-4443
VIENNA - 938-7388

UNIROYAL
U.S. RUBBER
BATTERIES

WEBER TIRE CO., INC.

10900 W. MAIN ST.
FAIRFAX, VA. 22030

BRAKES
BATTERIES
BALANCING
WHEEL ALIGNMENT
AIR CONDITIONING

24647

PHONE
WHEN READY ☐

NAME	YEAR	LICENSE	DATE 4/30/79
ADDRESS	MAKE	SPEEDOMETER	PROMISED
CITY	MODEL	SERIAL NO.	ORDER WRITTEN BY

ACCT'G.	QUAN.	PART NO.	MATERIAL USED	EACH	EXT.	INSTRUCTIONS	LABOR CHARGE	
							EACH	EXT.
	1		14" Radial Tube	7.77	7.77	1 state park May		4.50
	1		FIET		.28	Notcapin for May		
I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. X _____							TOTAL LABOR	4.50
							TOTAL PARTS	
							ACCESSORIES	8.05
							GAS, OIL & GREASE	
							(PO. NO. OUTSIDE REPAIRS)	
							TAX	32
TOTAL							TOTAL AMOUNT	12.87

NOT RESPONSIBLE
FOR LOSS OR DAM-
AGE TO CARS OR
ARTICLES LEFT IN
CARS IN CASE OF
FIRE, THEFT OR ANY
OTHER CAUSE BE-
YOND OUR CON-
TROL

OTS. OIL @

LBS. GREASE @

TOTAL GAS, OIL
and GREASE

ALL BILLS PAYABLE 10th PROX.

BILLS NOT PAID IN 30 DAYS SUBJECT TO 1 1/2% PER MONTH = 18% PER YEAR INTEREST CHARGE



Auto Inspection Service of San Francisco

3 WEST 37TH AVE., RM 17 PHONE: (415) 573-9414
SAN MATEO, CALIFORNIA 94403



CLUB 2-7-80

OWNER:

MAKE
FOR

DATE:

2-6-80
2-06-0256

73 PERCH 911-T 68,738 PW-6654

YEAR MAKE BODY STYLE MODEL MILEAGE LICENSE

APPRAISER

Bill West

VEHICLE

IDENTIFICATION #

Power Steering ☐ Brakes Power ☐ Factory Air Cond. ☐ Under Dash Air Cond. ☐ Radio ☐ Vinyl Roof ☐ Stereo ☐ Elec. Seats ☐ Windows ☐
Transmission Automatic ☐ 3 Speed Standard ☐ 4 Speed Standard ☐ Floor Shift ☐ MOTOR: 8 cyl. ☐ 6 cyl. ☐Cyl. ☐

FRONT NET HRS. PARTS FRONT NET HRS. PARTS

Bumper				Headlamp			
Arms				Lamp Door			
Guard				S. Beam			
				Housing			
Shield				Ring			
				Parklamp			
Grill				Hood			
Panel				Mould			
Emb. Mldg.				Lock			
Extension				Hinge			
Extn. Mldg.				Ornament			
				Fender Right			
				Extn.			
Radiator				Moulding			
Support				Name Plate			
Baffle				Skirt			
Shroud				Antenna			
Fan Blade							
Clutch				Fender Left			
Water Pump				Extn.			
Coolant				Moulding			
Air Cond				Name Plate			
Condenser				Skirt			
Recharge				Cowl			
				Windshield			
Battery				Frame			
Horn				Front System			
				Control Arm			
Tire	Black			Steering Wheel			
	White			Motor Support			
Hub	Cap			Shift Linkage			
Wheel	Disc						

The Below Agrees To Make Repairs As Per Appraisal. When Authorized By Owner.

Accepted By:

Signature: [Signature]

APPRAISER'S REPORT OF DAMAGE

OH-Overhaul S-Straighten A-Align 1-New R-Repair

REAR	NET	HRS.	PARTS
Bumper			
Arms			
Lower Panel			
Floor			
Quarter R. Inner Outer			
Quarter L. Inner Outer			
Quarter Ext.			
Wheelhouse			
Moulding			
Trunk Lid			
Tail Light			
Tail Pipe			
Gas Tank			
Door			
Glass			
Handle			
Moulding			
Roof			
Center Pillar			
Door			
Glass			
Moulding			
Seat			
Track			
Rocker Panel			
Mould.			
Side Sill			
Painting & Mt Under Coat			
GROSS TOTAL	30.00	38	
LABOR	3.8	HRS. @ 30.	\$ 114.00
PARTS LESS			\$
NET			\$ 30.00
TAX	67. (30.2.)		\$ 180
TOWING			\$
APPRAISAL TOTAL			\$ 145.80
DEDUCTIBLE			\$
SUGGESTED DEP'R'N			\$


THIS IS NOT AN AUTHORIZATION FOR REPAIRS

PLEASE READ APPRAISER'S REPORT
ON REVERSE SIDE.

Auto Inspection Service of San Francisco

AUTOMOTIVE DAMAGE APPRAISERS

APPRAISER'S REPORT



APPRAISED FOR: **Consumer Claims**

ADJUSTER: **Mr. Darwin Hardy**

INSURED: CLAIMANT:

TYPE OF LOSS: Collision ☐ Upset ☐ Fire ☐ Flood ☐ Vandalism ☐ Theft ☐ Shipping ☒

THIS VEHICLE SHOULD BE CONSIDERED: Repairable ☒ Borderline Total Loss ☐ Total Loss ☐

LOCATION AT TIME OF INSPECTION: **Res., 183 Buchanan, Sausalito, Ca.**

REPAIR SHOP AGREEING TO THIS APPRAISAL: **Marin Auto Body, 16 Lagoma, Mill Valley, Ca.**

AGREEING REPAIR SHOP IS: Where Vehicle is Located ☐ Owner's Choice Yes ☒ No ☐ Owner's Choice Unknown ☐

DEPRECIATION is recommended on the following items, and should be deducted from the appraisal total:
TIRE: \$ Gauge Reading /32 ; BATTERY: \$ Based on Month Battery

OTHER:

PAINT CONDITION **silver** Very Good ☒ Good ☐ Fair ☐ Poor ☐ Very Poor ☐

INSIDE TRIM CONDITION Very Good ☒ Good ☐ Fair ☐ Poor ☐ Very Poor ☐

GENERAL CONDITION Very Good ☐ Good ☒ Fair ☐ Poor ☐ Very Poor ☐

TIRE CONDITION: Left Front Right Front Left Rear Right Rear Spare
(#1—Excellent—New to 25% Wear) (#2—Good—25% to 50% Wear) (#3—Fair—50% to 75% Wear) (#4—Poor—75% to 100% Wear)

PREVIOUS DAMAGE: Evidence indicates that items in this column are not part of this loss. **None detected - very nice appearance.**

IF TOTAL LOSS the following should be considered: Kelley Book Wholesale \$ Book Retail \$ Local Value \$ **9500.00** Salvage Value \$
LOCAL VALUE IS BASED ON THE CONDITION OF THIS VEHICLE JUST PRIOR TO THIS LOSS.

A SIMILAR VEHICLE HAS BEEN LOCATED: Yes ☐ No ☐ By Phone ☐ Personal Inspection ☐

MOTOR COMPANY SALES REPRESENTATIVE ADDRESS PHONE

COMPANY CONTACT: Who Date Time

This is new dent on rear lid. It is a typical soft shipping dent and not previous. Car under cloth cover. We raised cover and checked all sides of car but no other damage found.

DATE: 5-9-80



SALES ORDER



electrodyne inc.

NO.

2445

QUALITY MOTOR ACCESSORIES

P. O. BOX 358 • 2316 JEFFERSON DAVIS HIGHWAY • ALEXANDRIA, VA. 22313 • (703) 836-4641

SHIP TO:

ADDRESS

CITY, STATE & ZIP

PHONE NO.

SALESMAN

REMARKS

PURCHASE ORDER NO.

SHIP VIA

TERMS

FREIGHT

☐ PPD.☐ COLL.

DATE

ORD.	SHIP'D	B.O.	DESCRIPTION	CATALOG NO.	UNIT PRICE	AMOUNT
1	1		Car Cover	43MGD		7795
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						

NO RETURNS ON ELECTRICAL PARTS
15% RESTOCKING ON ALL RETURNS

NO RETURNS ON SALE MERCHANDISE

BUYER

STATE
SALES TAX

TOTAL

3/2

8107

CUSTOMER COPY

