

Pimentel Innovations
BAR Registration
No.ARD00281643
1680 West Winton Avenue #15
Hayward, CA 94545
(510) 295-7593
ryan@pimentelinnovations.com



Porsche 1951

INVOICE

BILL TO
[REDACTED]

INVOICE # 1103
DATE 07/09/2017
DUE DATE 07/10/2017
TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Labor			
All 4 Chrome Wheels:	8	100.00	800.00
Bead blast and sand smooth			
Prep for paint and wrap with wire			
Apply direct to metal sealer and scuff			
Apply sealer			
Apply silver base coat and matt clear coat			
Paint And Material	1	500.00	500.00
Glass beads, direct to metal sealer, scuff pads (500-600 grit), sealer, base and clear coat, flattening agent			

1951 Porsche

BALANCE DUE

\$1,300.00

I acknowledge notice and oral approval of an increase in the original estimated price.

Client Signature: _____

Thank you for your business!

Client Signature

Pimentel Innovations
BAR Registration
No.ARD00281643
1680 West Winton Avenue #15
Hayward, CA 94545
(510) 295-7593
ryan@pimentelinnovations.com



Porsche 1951

INVOICE

BILL TO
[REDACTED]

INVOICE # 1116
DATE 10/19/2017
DUE DATE 10/19/2017
TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Body Labor	22	100.00	2,200.00
Clean damaged areas			
Sand all paint off to metal and hammer & dolly the damaged areas.			
Apply light filler to both spots and block sand in 80,120,180,240,400 grit sand paper			
Mask areas for primer and prime			
Block primer in 240-400			
Wet sand in 600 grit			
1500 the hole back of the car and the right front fender			
Clean and put in the booth			
Mask for paint final wax & grease, tack			
Make the color, blend the color and clear			
Nib and polish			
Paint And Material	2	100.00	200.00
Filler,sand paper,primer,base coat,clear coat, Masking tape,masking paper,polishing supplies.			

1951 Porsche

BALANCE DUE

\$2,400.00

I acknowledge notice and oral approval of an increase in the original estimated price.

Client Signature: _____

Thank you for your business!

Client Signature

Pimentel Innovations
BAR Registration
No.ARD00281643
1680 West Winton Avenue #15
Hayward, CA 94545
(510) 295-7593
ryan@pimentelinnovations.com



Porsche 1951

INVOICE

BILL TO

[REDACTED]

INVOICE # 1143
DATE 09/23/2018
DUE DATE 09/24/2018
TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Labor	13	100.00	1,300.00
Repair right front fender gouge and rear bumper corner			
Prime, sand and wet sand both spots			
Color match			
Mask, paint and wet sand			
Paint And Material	1	100.00	100.00
Light filler, primer, sandpaper, masking paper, tape, and plastic, base coat, clear coat, wet sandpaper			

1951 Sauter Porsche 356 Roadster

BALANCE DUE

\$1,400.00

I acknowledge notice and oral approval of an increase in the original estimated price.

Client Signature: _____

Thank you for your business!

Pimentel Innovations
BAR Registration
No.ARD00281643
1680 West Winton Avenue #15
Hayward, CA 94545
(510) 295-7593
ryan@pimentelinnovations.com



Invoice

BILL TO



INVOICE # 1163
DATE 03/07/2019
DUE DATE 05/15/2019
TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Labor			
Match paint color	190	100.00	19,000.00
Disassemble entire car			
Block sand entire car			
Dig out cracks, feather edge spots and fill			
Block out, mask and prime spots			
Wet sand and clean			
Mask and degrease			
Apply base coat and clear coat			
Nib and polish			
Clean mask of the car and freshen up the black			
Reassemble entire car			
Paint And Material	1	2,800.00	2,800.00
Tape, masking paper, wet sand paper, sand paper, primer, sealer, base coat, clear coat,satin black, and polish supplies			
 1951 Sauter Porsche 356 Roadster	 TOTAL	 21,800.00	
	DEPOSIT	6,800.00	
I acknowledge notice and oral approval of an increase in the original estimated price.	PAYMENT	15,000.00	
	BALANCE DUE		\$0.00

Client Signature: _____

Thank you for your business!

PAID

*CODE N-NEW U-USED R-REBUILT

QTY	PART NO. OR DESCRIPTION	SALE													
1	6V FLASHER	9895													
EPA #CAL 000398238															
BAR # ARD275257															
Name [REDACTED]															
Address [REDACTED]															
City [REDACTED]															
Year-Make-Model 51 SAUER TORCH		License No. [REDACTED]	Odometer [REDACTED]	ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE.											
Estimate Amount \$		Engine Size	VIN Number	SAVE <input type="checkbox"/> DISCARD <input checked="" type="checkbox"/>											
Revised Estimate \$		Date	Time	Description										Authorized By	INITIAL
Revised Estimate \$		Date	Time	Description										Authorized By	INITIAL
TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.															
OPER NO. REPAIR ORDER — LABOR INSTRUCTION															LABOR CHG.
CHECK TURN SIGNALS ~ REPLACE FLASHER AFTER TEST															
CLEAN ENGINE COMPARTMENT - PAINT AIRCLEANERS															
CLEAN BATTERIE TRAY AND TRUNK - PAINT GASCAP															

TIRE PRESSURE CHECK SERVICE COMPLETED
 TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)
 DECLINED Initial REASON: _____

SUBLET REPAIRS

WARRANTY ON PARTS & LABOR

- 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
- 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
- 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
- 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
- NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).

WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS

QTY.	SALE
QTS. OIL	
QTS. OIL	
LBS. GREASE	
TOTAL OIL, GREASE	

RECOMMENDED SERVICE:

- 1.
- 2.
- 3.

TOTAL LABOR ►	360.00
PARTS	98.95
SUBLET REPAIRS	
OIL & GREASE	
GAS	
SALES TAX	94.00
HAZARDOUS WASTE DISPOSAL FEE	
TOTAL AMOUNT ►	468.35

THIS CHECK
\$103

7.19.19

TOTAL SUBLET REPAIRS ►

020946

INVOICE COPY

Pimentel Innovations
1680 W Winton #15
Hayward, CA 94545 US
(510) 295-7593
ryan@pimentelinnovations.com



INVOICE

BILL TO

[REDACTED]

INVOICE # 1280
DATE 07/15/2021
DU DATE 07/15/2021
TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Labor			
Sand out the damaged paint	7	100.00	700.00
Prep the bumper in 1500			
Mask the area			
Prime the spot			
Block the primer			
Clean			
Apply base coat and clear coat			
Nib and polish			
Paint And Material	1	100.00	100.00
Sand paper, primer, tape, masking paper, clear coat, polish supplies			

Sauter Porsche	SUBTOTAL	800.00
	TAX	9.75
I acknowledge notice and oral approval of an increase in the original estimated price.	TOTAL	809.75
	BALANCE DUE	
		\$809.75

Client Signature: _____

Thank you for your business!

4ell5
'57 Porsche
7/15/21