

10/4/15



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/30/2015
Invoice #	201609
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	5.25	Fill transmission with 1.5 quarts SWEPCO 201 80-90 gear lube. Paint mark the fill and drain plugs. Install shifter and adjust linkage. Install transmission and bolt it in. Remove drive shaft slip yoke. Grease u-joints and bolt it in. Install cross member and transmission mount. Re-install shift handle, knob, cover plate, shift boot and console cover on car. Re-install right rear shock and all wheels. Put car on ground and clean.	95.00	498.75
Labor	2	Deliver Vette to customer.	95.00	190.00
		Labor Subtotal		688.75
Parts	1.5	Quarts SWEPCO 201 80-90 gear lube	15.54	23.31T
Parts	2	Wheel bearings - rear wheel - outer	18.21	36.42T
Parts	1	Bearing	16.86	16.86T
Parts	1	Seal	16.18	16.18T
Parts	1	Wheel bearing cone - rear wheel - inner	21.58	21.58T
Parts	1	Wheel bearing cup - rear wheel - inner	9.84	9.84T
Parts	1	Wheel seal - rear wheel - inner	22.26	22.26T
Parts	1	Wheel seal - rear wheel - outer	29.01	29.01T
Parts	5	Heavy duty toggle switches	8.74	43.70T
		Parts Subtotal		219.16
Reimbursables	1	Shipping of heavy duty toggle switches	13.88	13.88

Pay online at: <https://ipn.intuit.com/q7v3jpth>

Due Upon Receipt	Subtotal	\$921.79
	Sales Tax (8.25%)	\$18.08
	Total	\$939.87
	Payments/Credits	\$0.00
	Balance Due	\$939.87



9/18/15

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/15/2015
Invoice #	201595
Project	
1964 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Parts	1	SRF brake fluid used at Laguna Seca (just received invoice from supplier)	97.20	97.20T
Parts	4	Vinyl numbers used at Laguna Seca	9.45	37.80T
Parts	2	Wheel bearings	18.21	36.42T
Parts	2	Wheel bearings	16.86	33.72T
Parts	2	Seals	16.18	32.36T
Parts	1	Differential gasket kit	5.22	5.22T
Parts	1	Repair parts for transmission	385.33	385.33T
Parts	2	Quarts SWEPCO 201 80-90 gear oil	15.54	31.08T
Parts	1	Bottle posi additive	13.50	13.50T
Parts	2	Brake line fittings	5.84	11.68T
Parts	2	Brake fittings	6.75	13.50T
Parts	1	Straight brake hose	14.09	14.09T
Parts	1	Brake fitting	6.87	6.87T
Parts	1	Ring gear bolt kit	37.70	37.70T
		Parts Subtotal		756.47
Labor	5.5	Remove front brake calipers in order to pull hubs and inspect bearings. Bearings are a bit worn and burned. Order new bearings, seals and races. Press out seals and races. Clean hubs for installation of new races, bearings and seals. Remove bad right front brake hose. Remove valve covers in order to repair leaks. Clean well and discover several pin holes in the welds which need welding up. Prep for welding. Due to oil soaking cast aluminum, it is necessary to weld, grind and clean several times for a good seal. Also due to covers not being completely flat, hammer and surface them with belt sander. Grind more clearance on the inside of the covers so the rocker arms are hitting them a bit. Clean valve covers and install back on car.	95.00	522.50
Labor	2.75	Press races into front hubs. Pack bearings. Install seal and put hubs back on car. Re-install brakes. Remove leaky right rear shock to be fixed.	95.00	261.25

Pay online at: <https://ipn.intuit.com/072915.asp>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/15/2015
Invoice #	201595
Project	
1964 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Labor	4.25	Test and trouble shoot the rear end pump and fan electrical system. Remove console cover, shift boot, shifter handle, cross member, transmission mount, breather hose and transmission bolts. Pull transmission and remove shifter and linkage. Remove side cover off transmission for inspection. Scrape old gasket off side cover and housing.	95.00	403.75
Labor	9.25	Disassemble rear end and install new clutch pack in posi unit and shim for clearance. Tear down and inspect transmission. Clean parts. Order new second and third gear.	95.00	878.75
Labor	8.25	Rewire rear end cooler fan and pump to keep it from blowing the fuse. Replace a power wire by making a new bigger one. Re-assemble and test. Begin going through the prep check list and nut and bolting the car. Complete the majority of the list except the transmission and rear end which are being rebuilt. Discover that head rest support for seat mount is broken. Remove seat and some of the belts to get to the head rest mount. Fabricate a new stronger mount out of angle iron by measuring, cutting, sanding and drilling it. Cut and grind off old broken support. Clean and blast new support to prep for welding. Weld head rest seat mount bracket onto the rollbar. Clean and paint it black. Discover that seat side of the head rest mounting bracket is also cracked. Fabricate a new one by measuring, cutting, sanding, milling a slot, drilling, blasting and painting it black. Re-install seat and belts in car. Bolt support bracket on seat and put cover back on. Clean and JB weld a crack on the rear end housing cover. Shorten 2 bolts for the rear leaf spring mount. Clean surface of the old gasket. Order a new gasket.	95.00	783.75

Pay online at: <https://ipn.intuit.com/699151mp>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/15/2015
Invoice #	201595
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	3.5	Install rear end cover with silicone and a gasket. Replace some of worn out hardware for front rear end mount. Add posi additive and 2 quarts of SWEPCO 201 80-90 gear oil to rear end. Add a few more coats of exhaust paint on the side pipes to cover thin spots. Install rear end breather line and put rear end in car. Begin hooking up half shafts, mounts and struts.	95.00	332.50
Labor	2	Install new brake line and fittings on right front of car. Clean out threads of strut mount holes on rear end with a tap. Finish bolting mount on. Hook up rear end cooler lines and install rear spring. Bleed brakes.	95.00	190.00
		Labor Subtotal		3,372.50
Reimbursables	1	Shipping of repair parts for transmission	34.42	34.42
		Reimbursables Subtotal		34.42

Pay online at: <https://ipn.intuit.com/699j5tmp>

Due Upon Receipt	Subtotal	\$4,163.39
	Sales Tax (8.25%)	\$62.41
	Total	\$4,225.80
	Payments/Credits	\$0.00
	Balance Due	\$4,225.80



9/4 Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	8/31/2015
Invoice #	201591
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	0.5	Make work list for Corvette.	95.00	47.50
Labor	0.5	Collect all Corvette spares for return.	95.00	47.50
Labor	1.25	Remove wheels and inspect brakes. Drain water and oil catch cans. Start cleaning oil from motor and motor compartment.	95.00	118.75
Labor	4.5	Remove #1 decals from car. Remove labels for switches and clean it all off. Apply new labels. Determine that rear end pump and fan aren't working because fan and pump draw so much power that it eventually blows the fuse. Drain oil from motor, transmission and rear end. Dump oil in waste containers. Re-wire tie drain plug. Remove side pipes and clean them along with the headers. Paint all with high temp white paint.	95.00	427.50
Labor	5	Clean more oil from under side of car. Attempt to determine why rear end pump and fan fuse is heating up. Apply more coats on the exhaust pipes. Cut open old oil filter and inspect - good. Install new filter with 8 quarts SWEPCO 20-50 motor oil in motor. Install side pipes. Remove half shafts, drive line, leaf spring, oil lines and mounts in order to remove rear end.	95.00	475.00
		Labor Subtotal		1,116.25
Parts	8	Quarts SWEPCO 20-50 motor oil	8.86	70.88T
		Parts Subtotal		70.88

Pay online at: <https://ipn.intuit.com/tvk7ph4k>

Due Upon Receipt	Subtotal	\$1,187.13
	Sales Tax (8.25%)	\$5.85
	Total	\$1,192.98
	Payments/Credits	\$0.00
	Balance Due	\$1,192.98

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

Roger Kraus Tires, Inc.

2896 Grove Way
 Castro Valley, CA 94546
 (510) 582-5031
 BAR # 102319

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # **83439**

2015 GOODYEAR VINTAGE

Inv Date: 7/22/2015 @ 8:44am

Jeffrey Abramson
 181 South Ave
 Alamo, CA 94507

VIN:
 Engine:
 Trans:
 ODO In: 0 Out: 0
 Color:
 License #

Service Writer: Brandon Kraus
 Status: Posted
 Driver: Abramson, Jeffrey
 Mfg. Date:
 Unit #
 PO #

(925) 314-3823 Home

(925) 855-1926 Home

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
------------------	----------------------	--------------------	-----	-----	-------	-----

Customer states that: Requests for Service & Vehicle Problems -

Labor Service - Usage tax tires ca only BK			16.00		1.75	28.00
New VSCLP22000	Chrome Valve Stem Low Profile 22000			4.00	5.00	20.00
Labor Service - Mount & bal vin. W/ sale TL			12.00		28.00	336.00
New GYR1724	Gyr 600-15 D1724 R655			16.00	331.00	5,296.00
New STDLS	Race Tire Disposal Laguna			12.00	7.00	84.00
Labor Service - MOUNT AND BALANCE CLEAN WHEELS TL			4.00		19.00	76.00
Labor Service - Credit Card On File RK						0.00

Notes

DONE AT LAGUNA SECA REUNION RACE
 2 SETS PER CAR 15 AND 165

BILLED 8/17/2015 RK

50/50 6T350 / Corvette M&N

Warranty

All returned race tires are subject to a 20% restocking charge. Returned Goods Authorization's are required for all returns. All returns must be made in 60 days.

Posted 8/18/15 9:34AM

Master Card

6,332.75

Invoice Summary

Parts 5,400.00
 Labor 440.00

X

Customer acknowledges receipt of merchandise and services

Sub Total 5,840.00
 Sales Tax (LS) 492.75



7/5/15

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	6/30/2015
Invoice #	201554
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	1	Machining of bell housing	135.00	135.00
Labor	8.25	Install clutch, bell housing, transmission, engine, headers and side pipes	95.00	783.75
Labor	6.5	Cut and weld alternator bracket for better fit. Install belts and hoses. Make new bushing for exhaust mount and install. Install shifter and boot. Connect drive shaft, rear end, alternator bracket.	95.00	617.50
Labor	1.75	Tig-weld alternator adjusting mount. Install car on lift. Install front sway bar and fill rear end with gear lube (prepaid).	95.00	166.25
Labor	8.5	Run rear end pump and add bottle of friction modifier. Check transmission fluid. Install clutch rod and adjust. Tighten motor mount bolts, fittings, rear end hardware and oil lines. Install carburetor and related parts. Install dipstick and new oil filter. Add 11 quarts Swepeco 20/50 race oil. Add water in radiator and 1 pint Napa Kool. Hook up alternator wires. Hook up oil pressure gauge, return springs and tack cable. Adjust right height and put on scales to check and adjust corner weights. Prime oiling system and time the car. Install hood and dust car. Set timing, run motor and check fluids.	95.00	807.50
		Labor Subtotal		2,510.00
Parts	1	Oil filter	35.07	35.07T
Parts	11	Quarts of SWEPCO 20/50 race oil	33.77	371.47T
Parts	1	Pint of Napa Kool	8.57	8.57T
Parts	1	Bottle of Posi additive	13.50	13.50T
		Parts Subtotal		428.61

Pay online at: <https://ipn.intuit.com/t4z43w3r>

Due Upon Receipt	Subtotal	\$2,938.61
	Sales Tax (8.25%)	\$35.36
	Total	\$2,973.97
	Payments/Credits	\$0.00
	Balance Due	\$2,973.97

5/8/15



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/30/2015
Invoice #	201502
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	5.5	Prepare to remove engine. Remove drive shaft, cross member, tranny mount, clutch linkage components, oil, coolant, hoses, fuel lines, oil lines, wiring, sending units, carb and air cleaner, throttle linkage, radiator, breather lines, hood, headers, alternator and brackets, shifter, console cover, motor mount hardware, starter, z-bar, dipstick, plugs, springs and front frame support. Bag and bolt everything. Clean oil off of some parts.	95.00	522.50
Labor	0.5	Remove oil pump for differential to reverse flow.	95.00	47.50
Labor	2.5	Remove rear end pump, dismantle and reclock inlet and outlets. Reassemble and install. Install different fittings on pump. Remake 2 different ends on two of the rear end hoses. Install hoses.	95.00	237.50
		Labor Subtotal		807.50
Parts	1	94 Amp alternator	168.61	168.61T
Parts	3	GM 10 and 12 bolt ring gear bolt kits	37.70	113.10T
Parts	1	Can red paint for bell housing	10.80	10.80
		Parts Subtotal		292.51

Pay online at: <https://ipn.intuit.com/w7j7fjrc>

Due Upon Receipt	Subtotal	\$1,100.01
	Sales Tax (8.25%)	\$23.24
	Total	\$1,123.25
	Payments/Credits	\$0.00
	Balance Due	\$1,123.25



4/19/15

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/15/2015
Invoice #	201486
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Differential gasket	5.38	5.38T
Parts	4	Differential oil cooler fittings	8.05	32.20T
Parts	4	Differential oil cooler fittings	2.25	9.00T
Parts	3	Bushings	4.86	14.58T
Parts	1	Square head plug	0.59	0.59T
Parts	3	SWEPCO 201 80/90 gear lube	15.54	46.62T
Parts	1	Bottle posi additive	13.50	13.50T
Parts	1	Bell housing	400.00	400.00T
Parts	1	Posi clutch	100.00	100.00T
Parts	1	Bearing kit	78.15	78.15T
Parts	1	GM 10 & 12 bolt ring gear bolt kit	37.70	37.70T
Parts	1	Electric. pump	195.26	195.26T
Parts	2	Bearing kit with shims	137.55	275.10T
Parts	1	1/2-20 double end nt	20.23	20.23T
Parts	2	2 piece flair cap	11.46	22.92T
Parts	2	3/8 npt 90 degree #8 male blk	13.48	26.96T
Parts	2	#8 straight hose end	12.10	24.20T
Parts	1	#8 90 degree double swivel hose end	31.18	31.18T
Parts	12	#8 stainless steel hose	7.83	93.96T
Parts	2	Rear axle U-joint	31.50	63.00T
Parts	2	Lower ball joint	47.50	95.00T
Parts	2	Posi-traction parts/clutches	170.10	340.20T
Parts	2	Posi-traction parts/clutches	176.85	353.70T
		Parts Subtotal		2,279.43
Labor	4	Clean and paint spring and transmission bracket. Run two wires to rear oil cooler pump and fan. Drill holes in steel plate for bolts to be welded on. Paint and mount plate to body. Solder and shrink wrap ground wire for pump. Trim holes in body for oil hoses. Shrink wrap ends on pump wire. Connect wires to front panel solenoid switch.	95.00	380.00
Labor	1	Tig-weld nuts on back of pump mounting bracket. Measure and make one of the 3 lines. Install fitting in rear end pump.	95.00	95.00

Pay online at: <https://ipn.intuit.com>

Due Upon Receipt

Subtotal

Sales Tax (8.25%)

Total

Payments/Credits

Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/15/2015
Invoice #	201486
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	8.25	Measure for hoses for oil lines. Tie wrap electrical wiring for oil pump / fan. Cut more fiberglass to fit oil fittings better. Install fittings in oil cooler. Connect oil lines to pump and cooler. Fabricate aluminum protection plate for oil cooler. Drill and tap differential covers for oil inlet. Solder connectors to oil pump and fan. Fasten with clips to body. Put shrink tubing on all soldered connectors.	95.00	783.75
Labor	2.5	Figure out routing and fittings needed for cooler / pump lines. Make lines and install temporarily to mark and drill for adel clamps. Clean oil mess from motor on bottom of car. Locate leak and a crack in bell housing. New bell housing needed.	95.00	237.50
Labor	0.25	Install cover plate on differential.	95.00	23.75
Labor	4.5	Tear down and replace posi clutches.	95.00	427.50
Labor	4	Assemble 4:33. Set up posi. Replace bearings.	95.00	380.00
Labor	1.5	Put axles in rear end. Clean and install rear cover with better bolts and new gasket and torque it down. Add 3 quarts SWEPCO 201 80/90 gear lube in rear end with a bottle of posi additive. Top off rear end with fluid. Pull out one used for mocking up lines and bolt in new one.	95.00	142.50
Labor	5	Cut bell housing for ground clearance. De-burr bell housing. Sandblast bell housing. Assemble positraction unit. Clean under carriage.	95.00	475.00
Labor	8.25	Finish hooking up wires to solenoid switch. Cut larger holes for differential bolt accessing back trunk area. Shorten braided oil line. Install differential and half shafts, then remove due to clip coming off half shaft inside differential. Drain oil. Remove rear of differential. <small>675 Hartz Avenue, #300 Danville, CA 94526</small>	95.00	783.75
Labor	3	Assemble transmission.	95.00	285.00

Pay online at: <https://ipn.intuit.com/675Hartz>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/15/2015
Invoice #	201486
Project	
1964 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Labor	0.25	Install differential bracket bolt to frame. Tighten differential mounting bolts.	95.00	23.75
		Labor Subtotal		4,037.50
Reimbursables	1	Shipping of posi-traction parts/clutches	14.35	14.35
		Reimbursables Subtotal		14.35

Pay online at: <https://ipn.intuit.com/64fv7w44>

Due Upon Receipt	Subtotal	\$6,331.28
	Sales Tax (8.25%)	\$188.05
	Total	\$6,519.33
	Payments/Credits	\$0.00
	Balance Due	\$6,519.33



4/1/15

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	3/31/2015
Invoice #	201480
Project	1964 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	2	Custom mufflers	168.73	337.46T
Parts	4	Muffler exhaust straps	5.40	21.60T
Parts	1	Muffler parts	60.00	60.00T
Parts	2	Liters Castrol SRF racing brake fluid	85.72	171.44T
Parts	1	Oil cooler with fan	283.43	283.43T
Parts	1	HMSA Spring Event race day parts	153.34	153.34T
				1,027.27
Labor	3	Remove driver side pipe and fit up new pipe. Brackets are bent to incorrect contour. Bend to correct contour. Re-install pipe and bolt in. Same procedure for passenger side pipe. Mufflers too loud for noise restriction at Laguna Seca. Remove and order new mufflers.	95.00	285.00
Labor	9.25	Pick up muffler bends to make side pipe. Straighten new mufflers by hammering back into shape. Measure, cut, sand and fit turn down tips for the new muffled side pipes. Measure, cut, bend and sand mounting brackets. Remove old side pipes. Tack weld new side pipes together then test fit and check for sound. Tig-weld together. Drill holes and install inserts on tip of right pipe for an extra baffle. Make baffle and install.	95.00	878.75
Labor	5.75	Remove leaf spring. Disconnect half shaft. Remove alignment bracket. Disconnect driveshaft. Remove differential. Cut out hole for differential cooling fan. Reverse fan direction.	95.00	546.25
				1,710.00
Reimbursables	1	Shipping of mufflers and straps	19.35	19.35
Reimbursables	2	Cans flame proof paint	9.85	19.70
				39.05

Pay online at: <https://ipn.intuit.com/nbkxzrwk>

Due Upon Receipt	Subtotal	\$2,776.32
	Sales Tax (8.25%)	\$84.75
	Total	\$2,861.07
	Payments/Credits	\$0.00
	Balance Due	\$2,861.07

3/24/15



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	3/23/2015
Invoice #	201482
Project	
Transport / Track Support	

Item Code	Quantity	Description	Rate	Amount
Transport	1	Transport Corvette race car from Sonoma, CA to Mazda Laguna Seca Raceway and return to Sonoma.	700.00	700.00
				700.00
Track Support	2	Track support, HMSA Spring Club Event (Corvette - 2 days @ \$500/day/vehicle)	500.00	1,000.00
				1,000.00
Reimbursables	2	Hotel lodging for crew (Comfort Inn Monterey Peninsula - 2 nights @ \$200.44/night)	200.44	400.88
Reimbursables	2	Crew per diem (2 days @ \$45/per day/crew member divided by total cars or \$45/car/day)	45.00	90.00

Pay online at: <https://ipn.intuit.com/x2j55nvw>

Due Upon Receipt	Subtotal	\$2,190.88
	Sales Tax (8.25%)	\$0.00
	Total	\$2,190.88
	Payments/Credits	\$0.00
	Balance Due	\$2,190.88



1/19/15

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	1/15/2015
Invoice #	201443
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Prepaid Labor	1	Deposit for 327 motor reassembly (will include new pistons, valves, valve springs, crank shaft, vibration damper, rings and bearings).	7,500.00	7,500.00
				7,500.00
Parts	1	327 race block (for spare motor)	2,798.00	2,798.00T 2,798.00

Pay online at: <https://ipn.intuit.com/t65hk445>

Due Upon Receipt	Subtotal	2,798	\$10,298.00
	Sales Tax (8.25%)		\$230.84
	Total	3,028.84	\$10,528.84
	Payments/Credits		\$0.00
	Balance Due	3,028.84	\$10,528.84



12/2/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	11/30/2014
Invoice #	201413
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Transmission mount	35.06	35.06T
Parts	1	Motor mount	45.83	45.83T
Parts	1	Pulley	81.68	81.68T
Parts	1	Lower pulley	73.91	73.91T
				236.48
Labor	6.5	Inventory and document all spares for Corvette, Morgan, and Ferrari. Box, label, and wrap and crate all spares.	95.00	617.50
				617.50
Shipping	1	Customs duty for Ferrari motor shipping	60.95	60.95
				60.95

Pay online at: <https://ipn.intuit.com/jk59cbx3>

Due Upon Receipt	Subtotal	\$914.93
	Sales Tax (8.25%)	\$19.51
	Total	\$934.44
	Payments/Credits	\$0.00
	Balance Due	\$934.44

11/12/14



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue. #300 Danville, CA 94526

Date	10/31/2014
Invoice #	201404
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Parts	1	Paint for side pipes	60.68	60.68T
Parts	2	Belt	22.26	44.52T
Parts	2	Belt	16.19	32.38T
Parts	1	Torque starter	285.99	285.99T
Parts	2	Vertical loom (spare)	48.72	97.44T
Parts	2	Wire set (spare)	78.48	156.96T
Parts	2	Fitting, -3 to 1/8 NPT Steel	1.92	3.84T
Parts	2	Fittings	13.80	27.60T
Parts	1	Water pump (spare)	283.43	283.43T
Parts	1	Fitting, water pump, steel 3/4 hose (spare)	5.71	5.71T
Parts	1	Carburetor open insulator gasket 1/4"	11.57	11.57T
Parts	1	Chrome dual throttle return kit (spare)	8.34	8.34T
Parts	1	Exhaust gasket (spare)	38.48	38.48T
Parts	1	Stainless braided hose -10	62.67	62.67T
Parts	1	Dipstick (spare)	6.68	6.68T
Parts	1	Stainless tube, 3/16"	49.95	49.95T
				1,176.24
Labor	10.5	Remove hood. Drain fluids. Remove (tight and rusted) side exhaust pipes. Remove headers, wiring, radiator, hoses, support bar, linkage, spring, carburetor, shifter, console, transmission mount, drive shaft, motor mount bolts, fuel and oil lines etc. to pull motor. Cap all oil lines. Remove motor and transmission. Remove manifold. Box, bag and label parts.	95.00	997.50

Pay online at: <https://ipn.intuit.com/tt5vjb7r>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	10/31/2014
Invoice #	201404
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	10.25	Remove fuel pump block from plate, pulleys, water pump, thermostat housing and transmission, clutch, bellhousing, clutch fork, throwout bearing, lift plate, from motor. Clean old gaskets from thermostat housing, water pump and fuel pump. Remove plate from old motor. Install on new motor. Add threads to start mounting bolt holes. Adjust and install starter. Install oil pressure gauge fitting and injection unit fitting. Install adapter for remote oil filter. Install upper alternator mount, spring mount, clutch, lift plate and pilot bearings. Clean clutch fork and bellhousing. Install pulleys and belt. Lift motor from stand and install motor mounts. Scrape and beadblast old paint from bell housing. Paint bellhousing. Install bellhousing, clutch fork, throw-out bearing, transmission and vent. Fabricate dipstick tube to fit new block: measure, cut, flare and bend tube. Grind section of block for clearance. Install dipstick tube.	95.00	973.75
Labor	3.25	Clean and sandblast headers in preparation for paint.	95.00	308.75
Labor	5.75	Install motor that was removed on stand for transport to engine shop. Install new motor assembly into car. Remove 3 sections of brake lines in need of replacement. Identify and order needed fittings and parts. Make brake line from master cylinder to firewall: measure, cut, flare, and bend. Install. Begin making line from inside of firewall to adjuster valve: measure, cut, flare and bend.	95.00	546.25

Pay online at: <https://ipn.intuit.com/tt5vjb7r>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	10/31/2014
Invoice #	201404
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Labor	11.25	Complete second brake line. Install car on lift. Open rear section behind seat to access 3rd section of bracket line to be replaced. Remove line from valve to splitter on rear end. Make 3rd brake line. Install. Remove plug on oil pan and install oil temp fitting. Remove all oil and cooler lines. Clean lines. Find one line in need of replacement. Reinstall oil cooler and two of three lines. Paint exhaust pipes and headers. Reinstall headers. Remove floor panel. Clean and paint. Install alternator mount. Grease, plug a hole, and install clutch z-bar. Hook up clutch. Adjust clutch. Install oil dip stick tube and starter wires. Remove lift plate and install spark plug wires and loom. Tighten motor mounts.	95.00	1,068.75
Labor	5	Apply final coat of paint to headers. Clean intake manifold. Install carburetor. Drill holes for radiator support and prep for welding. Install crossbar support rod. Grind welds on bell housing. Weld radiator supports. Tighten radiator hoses. Connect valve cover hoses. Install radiator and fill.	95.00	475.00
Labor	7.5	Bleed brakes. Inspect lines. Find leak. Remove line and inspect fitting. (Failed fitting.) Install new fitting. Bleed brakes again and test for leaks. Zip-tie and install adel clamps to brake lines. Reinstall wheels. Install oil pressure light switch onto back of gauge and connect wiring. Zip-tie wire and cables under dash. Install shifter, know, cover and console. Zip-tie wires.	95.00	712.50

Pay online at: <https://ipn.intuit.com/tt5vjb7r>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	10/31/2014
Invoice #	201404
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	8.5	Install crossmember and transmission mount. Hook up driveshaft. Install and adjust alternator, alternator mount, and belt. Install plug wire looms. Shorten bolts in order to valve covers to tighten. Install alternator wires, temperature sending unit and oil filter. Install rear brake adjuster valve and master cylinder fittings. Hook up lines, zip-tie and install adel clamps. Install painted foot grate. Hook up throttle linkage and retaining springs. Fill motor with oil. Install oil temp and oil pressure gauge. Adel clamp and zip-tie oil pressure and oil temp lines. Hook up fuel lines. Make lower cooler to motor line. Remove oil filter remote adapter plate from old motor and install on new. Zip tie oil lines to prevent rubbing.	95.00	807.50
Labor	4.5	Install oil pressure line, dipstick. Measure and cut dipstick tube for proper reading on dipstick. Prime motor with oil and check for fluid leaks. Add oil. Hook up tach. Test run car. Adjust timing. Install air cleaner. Install hood. Torque wheels. Tape off around side pipes and apply two more coats of paint. Remove tap and paper. Wipe vehicle clean.	95.00	427.50
Labor	1.25	Deliver car to Alamo.	95.00	118.75
Reimbursables	1	Shipping for water pump, stainless, and fittings	20.00	20.00
				20.00
Pay online at: https://ipn.intuit.com/tt5vjb7r				

Due Upon Receipt	Subtotal	\$7,632.49
	Sales Tax (8.25%)	\$97.04
	Total	\$7,729.53
	Payments/Credits	\$0.00
	Balance Due	\$7,729.53



10/9/14

Invoice


PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/30/2014
Invoice #	201395
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	2	Racing brake pads and cotter pins (spare set)	241.65	483.30T
Parts	2	Distributor shaft bushing, upper and lower	10.46	20.92T
Parts	1	Main distributor shaft	60.74	60.74T
Parts	1	SBC reluctor wheel	24.37	24.37T
Parts	1	Magnetic pick up bill	33.74	33.74T
Parts	4	Caliper kit	24.96	99.84T
				722.91
Labor	1.5	Pick motor up from machine shop. Transport, unload, install on cart and store.	95.00	142.50
Labor	1	Disassemble distributor. Clean and bead blast. (Distributor for 2nd motor to be converted to MSD.)	95.00	95.00
Labor	1.5	Install valve covers from new motor to engine on car. Locate and install new hardware for valve covers to fit with wire looms. Remove carburetor. Install new carburetor.	95.00	142.50
Labor	3.5	Pick up items stored at Hank's shop. (Sent crew members to Albany to retrieve items.)	95.00	332.50
Labor	1.5	Install bushing for throttle linkage. Fabricate new carburetor stud and install. Remove distributor cap and mark where ported for new distributor installation. Install fuel rail on carburetor. Check and adjust for full throttle.	95.00	142.50
Labor	8	Install new bushings in distributor. Hone bushings to size. Install new main shaft. Machine distributor housing for MSD. Pick up and install machine for reluctor wheel. Drill, tap housing for set screws to set tach gear end play shim and assemble. Install in Corvette. Set timing. Load in trailer.	95.00	760.00
				1,615.00
Pay online at: https://ipn.intuit.com/rd9vvgph				
Shipping	1	Shipping on brake pads	9.86	9.86
Shipping	1	Shipping on distributor parts	11.10	11.10
				20.96

Due Upon Receipt	Subtotal	\$2,358.87
	Sales Tax (8.25%)	\$59.64
	Total	\$2,418.51
	Payments/Credits	\$0.00
	Balance Due	\$2,418.51



9/9/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	8/31/2014
Invoice #	201366
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	2	Gallon SWEPCO Hi performance motor oil.	33.78	67.56T
Parts	2	Quart transmission oil.	15.03	30.06T
Parts	2	Brake pads, front and rear	269.93	539.86T
Parts	2	Brake caliper kit	20.51	41.02T
Parts	2	Brake caliper kit	17.29	34.58T
		Parts subtotal.		713.08
Labor	4	Put car on jacks and remove tires. Check bolts for tightness. Change oil and oil filter. Change transmission oil.	95.00	380.00
Labor	1	Remove brake calipers and lines. Drain.	95.00	95.00
Labor	4.25	Remove valve covers and deliver to machine shop. Check top half of engine and front end for loose bolts. Check interior for loose bolts. Remove bottom aluminum guards.	95.00	403.75
Labor	6	Disassemble brake calipers and remove all seals. Put all parts through washer. Mark and cut old pad mounting holes from rear brake calipers. Sand tops. Clamp pads to calipers and drill holes for new style brake pad mounts. Remove carburetor and distributor.	95.00	570.00
Labor	3.5	Clean rear calipers. Rebuild front calipers and re-install. Finish up nut and bolting car.	95.00	332.50
Labor	0.5	Tape off floor plate and rocker panel. Touch up paint.	95.00	47.50
Labor	2.5	Rebuild brake calipers. Install calipers. Clean and re-paint right rear swing arm.	95.00	237.50
Labor	3.5	Fabricate stainless brake pad pins for rear caliper. Tighten rotors. Bleed brakes. Check for leaks. Install wheels and torque lug nuts. Air tires.	95.00	332.50
Labor	3.5	Clean carburetor and distributor. Install on motor. Fill fluids. Hook up wires, springs, linkage and fuel lines. Check for fuel leaks and check timing. Test run. Set timing. Install valve cover with breather on left side. Install air cleaner. Top off motor oil.	95.00	332.50
		Labor subtotal.		2,731.25

Due Upon Receipt	Subtotal	\$3,444.33
	Sales Tax (8.25%)	\$58.83
	Total	\$3,503.16
	Payments/Credits	\$0.00
	Balance Due	\$3,503.16

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

Roger Kraus Tires, Inc.

2896 Grove Way
 Castro Valley, CA 94546
 (510) 582-5031
 BAR # 102319

Conatto

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # 79085

Jeffrey Abramson
 181 South Ave
 Alamo, CA 94507

2014 GOODYEAR BLUE STREAK

VIN:
 Engine:
 Trans:
 ODO In: 0 Out: 0
 Color:
 License #

Inv Date: 6/27/2014 @ 9:27am

Service Writer: Shawn Bennett
 Status: Posted
 Driver: Abramson, Jeffrey
 Mfg. Date:
 Unit #

(925) 314-3823 Home

(925) 855-1926 Home

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Customer states that: Requests for Service & Vehicle Problems -						
Labor Service - Thank You For Choosing Roger Kraus Racing SB						0.00
New	GYR1724	Gyr 600-15 D1724 R655		4.00	322.00	1,288.00 ⁷⁵
New	STDLS	Race Tire Disposal Laguna		8.00	7.00	56.00 ⁷⁵
New	HOO50015H	Hoosier 5.00-15 VIN TD 44400		4.00	248.00	992.00 ¹⁴⁵
Labor Service - Usage tax tires ca only SB			8.00		1.75	14.00 ⁷
Labor Service - Mount & bal Laguna w/sale TL			8.00		28.00	224.00 ¹¹²
Labor Service - CREDIT CARD ON FILE SB						0.00

es
 DONE ATY PRE REUNION 2014

#75 1463 + 106.22 = 1569.22
 BODIV 1,111 + 80.66 = 1191.66
 \$ 2760.88

BILLED 8/11/14 RK

PA m/c

Warranty
 All returned race tires are subject to a 20% restocking charge. Returned Goods Authorization's are required for all returns. All returns must be made in 60 days.

Posted 8/11/14 2:22PM
 Master Card \$2,760.88

Invoice Summary
 Parts 2,336.00
 Labor 238.00

Sub Total 2,574.00
 Sales Tax (LS) 186.88

Customer acknowledges receipt of merchandise and services.

Total 2,760.88



9/26/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/25/2014
Invoice #	201388
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Engine parts	15,093.45	15,093.45
Labor	1	Engine labor	6,771.50	6,771.50
Shipping	1	Shipping on engine parts	356.76	356.76
Prepaid Labor	-1	Deposit paid for new engine	10,000.00	-10,000.00

Pay online at: <https://ipn.intuit.com/5cfpj55g>

Due Upon Receipt	Subtotal	\$12,221.71
	Sales Tax (8.25%)	\$1,245.21
	Total	\$13,466.92
	Payments/Credits	\$0.00
	Balance Due	\$13,466.92



9/20/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	9/15/2014
Invoice #	201382
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	3	Work with machine shop to install fuel injection unit on 327 motor prior to dyno testing. Run dyno and adjust for maximum rpm.	95.00	285.00
Labor	4.5	Scotch brite disc on angle grinder and prep valve covers and spacers for welding. Further clean and level mating valve cover surfaces in preparation for welding. Tig weld spacers to valve covers.	95.00	427.50

Pay online at: <https://ipn.intuit.com/rv2tjdkd>

Due Upon Receipt	Subtotal	\$712.50
	Sales Tax (8.25%)	\$0.00
	Total	\$712.50
	Payments/Credits	\$0.00
	Balance Due	\$712.50



8/29/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	8/15/2014
Invoice #	201359
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Wire Loom Kit	51.23	51.23T
Parts	1	Intake manifold gasket	25.64	25.64T
				76.87
Labor	0.75	Install spark plug wire holders.	95.00	71.25
Labor	1.25	Wax car.	95.00	118.75
		Labor subtotal.		190.00

Pay online at: <https://ipn.intuit.com/dzgtg5w7>

Due Upon Receipt	Subtotal	\$266.87
	Sales Tax (8.25%)	\$6.34
	Total	\$273.21
	Payments/Credits	\$0.00
	Balance Due	\$273.21



Invoice

8/4/14

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	7/31/2014
Invoice #	201341
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	6	Tear down and inspect transmission. Check end play. Fabricate shim. Shim end play. Install new spacer in cluster gear. Set clearances. Reassemble super T-10 billet midplate. Box and secure for transport.	95.00	570.00

Pay online at: <https://ipn.intuit.com/7xn6m34w>

Due Upon Receipt	Subtotal	\$570.00
	Sales Tax (8.25%)	\$0.00
	Total	\$570.00
	Payments/Credits	\$0.00
	Balance Due	\$570.00

6/6/14



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	6/30/2014
Invoice #	201339
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	7	Quarts motor oil.	8.36	58.52T
Parts	1	Pivot ball.	13.35	13.35T
Parts	1	T-6 billet midplate	388.73	388.73T
Parts	4	Steel banded brass syncro ring	133.25	533.00T
Parts	1	T10 gasket set	17.48	17.48T
		Parts subtotal.		1,011.08
Labor	3.25	Remove clutch rods, fork, boot, pedal bracket and Z-bar pivot balls and replace parts with ones. Install bellhousing, transmission and crossmember.	95.00	308.75
Labor	4.25	Install car on lift. Remove clutch linkage, crossmember, driveshaft and transmission to access clutch fork pivot ball and throw out bearing.	95.00	403.75
Labor	5.25	Install new clutch pivot ball. Cut, grind and tig weld stops on throw out bearing to keep it from rotating. Re-install bearing, transmission, crossmember, shifter, driveshaft and shifter coverings. Install and adjust clutch linkage. Fill engine oil. Wire tie oil drain plug. Remove wheels and bleed brakes.	95.00	498.75
Labor	5.75	Nut and bolt whole car. Adjust headlight brackets. Remove shifter and add spacer. Adjust shifter. Run car and check oil level. Test fit rear of car with wheels. Labor subtotal.	95.00	546.25
Shipping	1	Shipping on billet midplate, syncro rings and gasket set	19.48	19.48

Pay online at: <https://ipn.intuit.com/hvnx98s>

Due Upon Receipt	Subtotal	\$2,788.06
	Sales Tax (8.25%)	\$83.41
	Total	\$2,871.47
	Payments/Credits	\$0.00
	Balance Due	\$2,871.47



pd 6/20/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Received

JUN 16 2014

Pacific Union Land Company

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	6/15/2014
Invoice #	201336
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1.5	Gear lube.	14.00	21.00T
Parts	1	Rocker arms from Maeco.	850.00	850.00T
Parts	1	Fork.	76.83	76.83T
Parts	1	Shaft kit.	119.48	119.48T
Parts	1	Clutch pedal bracket.	29.11	29.11T
Parts	1	Clutch rod boot at firewall.	6.08	6.08T
Parts	1	Clutch pedal rod.	29.48	29.48T
Parts	1	Clutch fork rod.	19.91	19.91T
Parts	1	Accelerator lever.	34.40	34.40T
		Parts subtotal.		1,186.29
Labor	2	Jack up car and put on stands. Cut wires for transmission and engine oil plugs. Drain and inspect transmission and motor oil. Replace oil filter with new and fill engine oil. Remove console to access shifter cover and shifter and remove.	95.00	190.00
Labor	3	Remove transmission, clutch, linkage and inspect	95.00	285.00
Labor	7.5	Inspect pilot bearing and clutch. Replace stripped bolt on clutch assembly. Install and align the clutch and torque bolts. Clean bellhousing and crossmember. Fill transmission with gear lube. Paint mark the plugs. Install the shifter brackets, new shifter, shift rods and new hardware (do alot of adjusting to get correct fit). Test. Remove throttle lever. Straighten out a different throttle lever and install. Adjust and test.	95.00	712.50
		Labor subtotal.		1,187.50
Reimbursables	1	Shipping of rocker arms.	15.00	15.00
Reimbursables	1	Shipping of rods, lever, bracket and boot.	16.42	16.42
		Reimbursables subtotal.		31.42

Due Upon Receipt	Subtotal	\$2,405.21
	Sales Tax (8.25%)	\$97.87
	Total	\$2,503.08
	Payments/Credits	\$0.00
	Balance Due	\$2,503.08

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and/or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

Roger Kraus Tires, Inc.

2896 Grove Way
 Castro Valley, CA 94546
 (510) 582-5031
 BAR # 102319

6/1/14

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Invoice # **77912**

Jeffrey Abramson
 181 South Ave
 Alamo, CA 94507

2014 GOODYEAR VINTAGE

Inv Date: 4/11/2014 @ 9:15am

VIN:
 Engine:
 Trans:
 ODO In: 0 Out: 0
 Color:
 License #

Service Writer: Shawn Bennett
 Status: Posted
 Driver: Abramson, Jeffrey
 Mfg. Date:
 Unit #

(925) 314-3823 Home

(925) 855-1926 Home

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Customer states that: Requests for Service & Vehicle Problems -						
Labor Service - Usage tax tires ca only SB			8.00		1.75	14.00
New GYR1724 Gyr 600-15 D1724 R655				8.00	322.00	2,576.00
Used STDRT Race Tire Disposal Track				8.00	5.00	40.00
Labor Service - Mount & bal race w sale TL			16.00		24.00	384.00
Labor Service - CREDIT CARD ON FILE SB						0.00
Labor Service - Spin balance race TL			2.00		10.00	20.00

Notes

ONE AT SONOMA CLASSIC MAY 16-18 2014

BILLED 5/19/14 RK

Warranty

All returned race tires are subject to a 20% restocking charge. Returned Goods Authorization's are required for all returns. All returns must be made in 60 days.

Posted 5/19/14 2:07PM

Master Card

\$3,249.82

Invoice Summary

Parts 2,616.00
 Labor 418.00

Sub Total 3,034.00
 Sales Tax (SP) 215.82

Customer acknowledges receipt of merchandise and services

Total 3,249.82



5/30/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue. #300 Danville, CA 94526

Date	5/31/2014
Invoice #	201321
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Muncie 4 speed transmission, race prepared	2,700.00	2,700.00T
Parts	1	Muncie shifter	344.21	344.21T
Parts	1	Shifter installation kit	203.81	203.81T
Parts	1	Shifter spring repair parts	26.61	26.61T
Parts	2	Pit Pack, steel clips, steel bushings, mastershift kit	16.16	32.32T
Parts	2	Bushing kit.	16.16	32.32T
		Parts subtotal.		3,339.27
Reimbursables	1	Shipping of transmission	112.00	112.00

Pay online at: <https://ipn.intuit.com/vn95tvgd>

Due Upon Receipt	Subtotal	\$3,451.27
	Sales Tax (8.25%)	\$275.49
	Total	\$3,726.76
	Payments/Credits	\$0.00
	Balance Due	\$3,726.76



5/30/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue. #300 Danville, CA 94526

Date	6/1/2014
Invoice #	201327
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Labor	1	Deposit on new engine	10,000.00	10,000.00

Pay online at: <https://ipn.intuit.com/login/qb>

Due Upon Receipt	Subtotal	\$10,000.00
	Sales Tax (8.25%)	\$0.00
	Total	\$10,000.00
	Payments/Credits	\$0.00
	Balance Due	\$10,000.00



5/21/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	5/15/2014
Invoice #	201303
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Parts	8	Quarts motor oil.	8.36	66.88T
Parts	1	Differential parts.	1,879.34	1,879.34T
Parts	1	Clutch.	680.24	680.24T
Parts	1	Clutch discs.	309.15	309.15T
Parts	1	Flywheel.	220.25	220.25T
Parts	1	Bolt kit.	24.26	24.26T
Parts	1	Ring gear bolt kit.	34.10	34.10T
Parts	2	Oil pressure fitting.	3.36	6.72T
Parts	1	Oil pressure fitting.	3.63	3.63T
Parts	1	Positraction additive.	9.44	9.44T
Parts	2	Quarts gear oil.	14.00	28.00T
		Parts subtotal.		3,262.01
Labor	5.5	Finish throttle linkage installation and adjustment. Install, tape and zip tie injection connectors. Install air filter assembly. Clean bellhousing and crossmember. Create temporary fix for cracked front spoiler. Inspect rotors. Drain oil. Disassemble rear camber links. Fabricate spacers for rod ends. Install new rod ends. Install water temperature sending unit. Fabricate water restrictor plate for substitute manifold. Clean surfaces and install water neck.	95.00	522.50
Labor	4.5	Mark off rearend support where new vent line will connect. Notch support for clearance. Tape rearend housing for vent line fittings and install. Press apart pinon bearing. Press out races, bearings and seals from rearend housing. Press out pin and rotate gear on distributor so it will clock correctly. Install distributor.	95.00	427.50
Labor	3.5	Install new fitting on back of block. Install oil line from new fitting to distributor. Install new flywheel. Set up and install clutch. Install bellhousing, clutch fork and throwout bearing. Install new oil filter. Fill engine oil.	95.00	332.50
Labor	1	Tighten and wire tie oil drain plug. Repair oil pan.	64.26	64.26

Pay online at: <https://ipn.intuit.com/42hwgs>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	5/15/2014
Invoice #	201303
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Labor	8	Disassemble new positraction unit and de-burr and polish differential carrier. Install new positraction and spider gears. Install bearing. Set gear pattern and backlash.	95.00	760.00
Labor	2	Install transmission and rearend. Install stop for clutch pedal.	95.00	190.00
Labor	2	Install MSD parts in distributor.	95.00	190.00
Labor	6	Install upper radiator hose and last plug in front of intake manifold. Fill radiator with water. Install gasket and cover on rearend. Install breather fitting on rearend. Drill and tap 4 of the bottom holes to 7/16 for strut/camber rod mounts. Clean and paint rearend. Bolt driveshaft onto rearend. Tig weld nut to a washer and then tack weld washer to frame for front rearend mount. Install front rearend mount. Fill rearend with gear oil and positraction additive. Drill and wire tie both plugs. Inspect new transmission. Press plug into speedo hole. Fill with oil. Drill and wire tie plugs. Install and adjust shifter with mounts.	95.00	570.00
Labor	3.25	Install last shifter bushing and clip. Install transmission. Hook up clutch linkage and adjust. Fabricate hold down tab for speedo plug and install. Reinstall shift handle knob, boot and trim pieces on console. Bolt transmission mount and crossmember in place. Install rearend in car. Grind front mount hole for proper fit.	95.00	308.75
Labor	6.75	Connect half shaft back to rearend. Reinstall camber links, mount, shocks and rear leaf spring. Set rear camber and adjust front camber and caster. Fabricate new upper control arm spacers and install.	95.00	641.25
Labor	3	Detail car and clean wheels. Vacuum. WD40 motor, rollers and engine bay.	95.00	285.00
		Labor subtotal.		4,291.76
Reimbursables	1	Shipping of clutch, discs, flywheel, bolt kit, ring gear bolt kit.	18.88	18.88

Pay online at: <https://ipn.intuit.com/paymyinvoice>

Due Upon Receipt	Subtotal	\$7,572.65
	Sales Tax (8.25%)	\$269.12
	Total	\$7,841.77
	Payments/Credits	\$0.00
	Balance Due	\$7,841.77



5/7/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/30/2014
Invoice #	201314
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Parts	1	Super T-10 4 speed transmission	2,500.00	2,500.00T
Parts	1	Triple disc clutch	1,259.59	1,259.59T
Labor	6.25	Put car on jack stands. Remove oil and dirt from bottom of car. Remove drive shaft, camber rods, spring and mounts and rearend. Remove transmission, shifter, bellhousing and clutch. Remove carburetor and intake. Reinstall fuel injection system.	95.00	593.75
Labor	2	Disassemble 4.11 rear end and clean. Order replacement parts.	95.00	190.00
Labor	3	Disassemble T10 transmission. Clean, inspect, and order replacement parts	95.00	285.00
Labor	0.5	Disassemble clutch. Inspect. Find clutch to not be serviceable. Order new clutch.	95.00	47.50
				4,875.84
Reimbursables	1	Shipping for transmission	98.00	98.00
				98.00

Pay online at: <https://ipn.intuit.com/3r9t5fqb>

Due Upon Receipt	Subtotal	\$4,973.84
	Sales Tax (8.25%)	\$310.17
	Total	\$5,284.01
	Payments/Credits	\$0.00
	Balance Due	\$5,284.01



4/15/14

Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/10/2014
Invoice #	201299
Project	1963 Corvette #5

Item Code	Quantity	Description	Rate	Amount
Parts	1	Throttle return kit.	8.34	8.34T
Parts	1	Carburetor pivot bushing.	7.15	7.15T
Parts	1	Pan gasket.	59.40	59.40T
Parts	1	Miscellaneous fasteners.	6.55	6.55T
Parts	1	Sway bar	219.00	219.00T
Parts	2	-6 check valve	62.06	124.12T
Parts	2	3/16" male inverted flared fitting	8.06	16.12T
Parts	1	1/4" male inverted flare fitting	8.06	8.06T
Parts	1	5/16" male inverted flare fitting	8.06	8.06T
Parts	1	3/8" male inverted flare fitting	8.06	8.06T
Parts	4	-6 straight fitting	10.76	43.04T
Parts	2	-6 bulkhead union flared	6.71	13.42T
Parts	1	-6 AN locknut pr	8.06	8.06T
Parts	2	Toggle switch	14.81	29.62T
Parts	3	Distributor cap	36.40	109.20T
Parts	2	Rod end, RH	182.25	364.50T
Parts	2	Rod end, LH	182.25	364.50T
Parts	1	Sport mirror, convex	53.93	53.93T
Parts	1	Sport mirror base	49.88	49.88T
Parts	1	Rear view mirror	28.30	28.30T
Parts	1	Rear view mirror bracket	64.76	64.76T
Parts	1	Screw set	27.81	27.81T
		Parts subtotal.		1,621.88
Labor	6	Pressurize motor to locate oil leak. Remove starter, oil line, sending unit and steering to access oil pan. Drain oil and remove oil pan. Check oil level by filling the pan with oil drained. Looked good. Measure for oil pick up height. Locate cracks in windage tray. Install new, longer oil pickup. Clean oil pan mounting surface. Install new oil pan and reassemble all parts previously removed. Drain water and remove intake manifold and fix oil leak. Reinstall intake and fill motor with oil and water. Reinstall distributor. Measure for and set up square of string around car and check rear toe.	95.00	570.00

Pay online at: <https://ipn.intuit.com/ipn/pk155>

Due Upon Receipt	Subtotal
	Sales Tax (8.25%)
	Total
	Payments/Credits
	Balance Due



Invoice

PETERSON MOTORSPORTS, LLC
 22255 ARNOLD DRIVE SONOMA, CA 95476
 PH 707-996-7764

Bill To
Jeffrey Abramson 675 Hartz Avenue, #300 Danville, CA 94526

Date	4/10/2014
Invoice #	201299
Project	
1963 Corvette #5	

Item Code	Quantity	Description	Rate	Amount
Labor	6	Jack up car and put on stands. Pump out all fuel. Remove panels behind seat to disconnect fuel filler and lines. Remove back lower valance for access. Remove fuel cell. Remove top plate and inspect. Inspect fuel lines and find no check valves. Measure and mark to trim fiberglass on new fuel cell for correct installation. Grind fiberglass. Determine wiring and switches for fuel cell. (Need 2 new switches.) Remove obsolete fan switches. Tape and label wires.	95.00	570.00
Labor	0.5	Remove left rear wheel, caliper, and rotor to machine rotor for greater wheel clearance. Not enough material on rotor.	95.00	47.50
Labor	2	Install new fuel switches and test. Measure and drill new fuel pick up box for fittings. Cut and machine fittings for fuel cell. Install fittings into box.	95.00	190.00
Labor	5	Install new fuel pick up box in fuel cell. Size fuel cell foam and install. Measure for and fabricate fuel lines from pick up to fuel cell plate. Install lines and plate. Measure for, cut and install fuel check valves in fuel lines. Reinstall lines and zip tie. Reinstall fuel cell. Hook up lines and hoses. Reinstall rear valance and inner covers.	95.00	475.00
Labor	5	Refill cell with fuel. Test fuel system. Remove air cleaner and adjust carburetor. Jack up car and remove front springs. Fabricate pieces to keep springs centered: cut, bend, weld, beadblast, weld in place and paint. Reinstall front springs. Install rear view mirror: drill and countersink mirror base; drill, screw and silicon the mirror in place. Torque wheels, check air pressure in tires.	95.00	475.00
Pay online at: https://ipn.intuit.com/m2pdkjb5				2,327.50
Reimbursables	1	Shipping on sport mirrors	18.75	18.75
Reimbursables	1	Shipping on mirror, mirror bracket, and screw set	14.86	14.86

Due Upon Receipt	Subtotal	\$3,982.99
	Sales Tax (8.25%)	\$133.81
	Total	\$4,116.80
	Payments/Credits	\$0.00
	Balance Due	\$4,116.80