

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

68 PORSCHE 911

ODO Read in:49065 out:
 Lic: NONE 6Cyl 2.0 Eng
 Vin: 11800179
 Eq:
 Last in 7/2/2019

Quotes

1 09/18/14 01:51pm95013.89

Job01 Body Work-AN

Labor: \$20,854.87

PP230A	Front Latch Panel-N	1.0 @	522.50 =\$	522.50	
NPN	Shipping/Duty-S	1.0 @	55.39 =\$	55.39	
911-531-202-00-G	Door Skin RS-N	1.0 @	444.06 =\$	444.06	
NPN	Shipping Expidite-S	1.0 @	80.00 =\$	80.00	
W FA 0893301900	Fixall, Wurth-N	1.0 @	43.18 =\$	43.18	1145.13

Total Price For paint work \$22,000 with parts.

Job Subtotal: \$22,000.00

Job02 Cosmetic Exterior Trim

Labor: \$15,535.00

901-505-155-20	T Stud-N	18.0 @	2.97 =\$	53.46	
900-145-043-00	Screw 3mm-N	18.0 @	0.62 =\$	11.16	
901-559-106-53	Rubber Rocker Molding-N	2.0 @	55.92 =\$	111.84	
NPN	Bumper Guard Used-U	2.0 @	80.00 =\$	160.00	
NPN	Lic. Panel Used-U	1.0 @	125.00 =\$	125.00	
SUBLET	Metal polishing-S	1.0 @	826.00 =\$	826.00	
SUBLET	Anodizing-S	1.0 @	486.95 =\$	486.95	
SUBLET	Chrome Plating-S	1.0 @	900.00 =\$	900.00	
901-731-111-02	Door Mirror-N	1.0 @	81.51 =\$	81.51	
SMC-543-016	1/4 Window Hardware ki-N	2.0 @	38.31 =\$	76.62	
SMC-543-001-00	Latch Screw Kit-N	1.0 @	5.41 =\$	5.41	
SMC631-900-00	Screw 4x16mm-N	12.0 @	0.33 =\$	3.96	
901-631-417-00	Gasket-N	1.0 @	17.27 =\$	17.27	
901-631-418-00	Gasket-N	1.0 @	17.27 =\$	17.27	
901-631-413-00	Seal-N	1.0 @	17.33 =\$	17.33	
901-631-414-00	Seal-N	1.0 @	17.27 =\$	17.27	
914-631-491-00	Boot-N	1.0 @	9.92 =\$	9.92	
NPN	Shipping-S	1.0 @	10.30 =\$	10.30	
4700313244	Mesh 3/16 x .032 x 1ft-N	1.0 @	51.11 =\$	51.11	

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job02 Cosmetic Extensions Trim-N	1.0 @	169.92 =\$	169.92	
901-531-632-21 Seal Door Handle Rr-N	2.0 @	42.03 =\$	84.06	
911-531-631-00 Seal Door Handle Ft-N	2.0 @	7.11 =\$	14.22	
SMC-505-433-05 Beading Deco Trim Mtr-N	15.0 @	7.88 =\$	118.20	
SMC-559-003-00 Screw Kit-N	1.0 @	9.67 =\$	9.67	
NPN Shipping-S	1.0 @	10.25 =\$	10.25	
901-505-405-51 Front Bumper Molding-N	1.0 @	229.94 =\$	229.94	
SMC-505-048-50 Rear Bumper Molding-N	2.0 @	93.14 =\$	186.28	
901-505-903-21 Guard Rubber Rr-N	2.0 @	62.35 =\$	124.70	
999-703-043-40 Bumperette Plug-N	4.0 @	0.55 =\$	2.20	
901-559-431-23 Grill ,Horn-N	1.0 @	99.96 =\$	99.96	
901-559-432-23 Grill, Horn Rt-N	1.0 @	99.96 =\$	99.96	
NPN Shipping-S	1.0 @	10.28 =\$	10.28	
911-545-225-00 Seal,Rear Window-N	1.0 @	151.30 =\$	151.30	
901-545-911-20 Window Trim Left-N	1.0 @	70.48 =\$	70.48	
901-545-912-20 Window Trim Right-N	1.0 @	73.62 =\$	73.62	
644-541-921-06 Trim Connector-N	2.0 @	4.09 =\$	8.18	
901-541-911-20 Windshield Trim-N	1.0 @	77.96 =\$	77.96	
901-541-912-20 Windshield Trim-N	1.0 @	77.96 =\$	77.96	
901-531-481-22 Door Lock Guide-N	2.0 @	7.50 =\$	15.00	4616.52

Job Subtotal: \$20,151.52

Job03 Cosmetic Engine Restoration	Labor: \$5,605.00
-----------------------------------	-------------------

SUBLET Powder coating-S	1.0 @	475.00 =\$	475.00	
SUBLET Powder Coat-S	1.0 @	175.00 =\$	175.00	
SUBLET Yellow Zinc-S	1.0 @	245.00 =\$	245.00	895.00

Cosmetics only. Total price \$6500

Disassemble the engine down to a long block for a cosmetic restoration. On inspection major ware found on much of the engine requiring a complete overhaul.

Job Subtotal: \$6,500.00

Job04 AC system Update	Labor: \$6,020.00
------------------------	-------------------

13X1125 AC Belt-N	1.0 @	14.66 =\$	14.66	
NPN A/C Comp RB-S	1.0 @	200.00 =\$	200.00	
911-DUEHL-COND Duel Side Condenser Ki-N	1.0 @	550.00 =\$	550.00	

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job04-AC system update	Compressor Oil 1oz-N	1.0 @	2.30 =\$	2.30	
17430DR	V-Belt 13x1090-N	1.0 @	14.79 =\$	14.79	
911-KUEL-SPEED3	Kuel Variable Speed-N	1.0 @	320.00 =\$	320.00	
55-6984-010	R-134 Freon-N	3.0 @	12.49 =\$	37.47	
VTA-49059-VUL	Air Louvers-N	3.0 @	22.50 =\$	67.50	
NPN	Shipping-S	1.0 @	11.44 =\$	11.44	
NPN	Shipping-S	1.0 @	150.99 =\$	150.99	
911-573-057-02	Condensor A/C Rear-N	1.0 @	489.65 =\$	489.65	
911-613-121-00	Thermostat-N	1.0 @	63.50 =\$	63.50	
911-KUEL-COND	Basic AC kit,Hoses,Dry-N	1.0 @	2100.00 =\$	2100.00	
911-KUEHL507	Compressor Update-N	1.0 @	549.00 =\$	549.00	
235-1514	Hose End 90d-N	1.0 @	7.14 =\$	7.14	
235-660	Hose End 90d 10-N	1.0 @	7.50 =\$	7.50	4585.94

Install upgraded condensers. We do not have to do all of these parts. We can pick some and not the others. This is what we do when a customer wants there car to work If we do it makes the tempeture out the registers about 35-40 degrees. It add twice as much freon to the system.

Job Subtotal: \$10,605.94

Job05 Oil Tank	Labor: \$1,195.00
----------------	-------------------

SUBLET	Overhaul Tank-S	1.0 @	337.50 =\$	337.50	
999-701-100-50-S	O-Ring,Oil Filt Cons.-N	1.0 @	2.63 =\$	2.63	
901-107-694-00	Rubber Sleeve-N	1.0 @	17.15 =\$	17.15	
901-107-291-00	Oil Filt Mt Seal-N	1.0 @	42.40 =\$	42.40	
901-107-696-00	O Ring-N	1.0 @	16.54 =\$	16.54	
930-107-272-01	Cap Seal-N	1.0 @	4.24 =\$	4.24	
901-107-203-09	Oil Filter OC-61-N	1.0 @	13.52 =\$	13.52	
802244	Total 10W-50 oil 1L-N	11.0 @	10.45 =\$	114.95	
901-107-693-01	Oil Tank Mount Buffer-N	2.0 @	5.67 =\$	11.34	
901-107-692-00	Oil Tank Mount Buffer-N	2.0 @	5.33 =\$	10.66	
914-201-891-00	Sending Unit Gasket-N	1.0 @	6.90 =\$	6.90	
911-504-111-02	Engine Comp Seal Long-N	1.0 @	157.49 =\$	157.49	
901-107-281-00	Spring Clip-N	1.0 @	6.67 =\$	6.67	741.99

Remove the oil tank. It was leaking. Replace the seals.

Job Subtotal: \$1,936.99

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job06 Interior/ Under Hood Work

Labor: \$19,840.00

RESTORE GAUGES	911 S-S	1.0 @	2064.72 =\$	2064.72
901-531-311-20	Bushing-N	8.0 @	8.48 =\$	67.84
771-03-10014	Shrink wrap-S	2.0 @	1.99 =\$	3.98
05589925	Spade Female 14-16-N	30.0 @	1.80 =\$	54.00
901-741-632-01	Sensor Temp-N	1.0 @	218.62 =\$	218.62
10-1792-423	Bronze Bushing Set-N	1.0 @	20.98 =\$	20.98
P 1974830	Paint Semi-Gls Blk-N	0.3 @	10.25 =\$	3.08
901-551-419-50	Carpet trim Plate-N	2.0 @	69.41 =\$	138.82
901-551-115-50	Sill Plate Lt-N	1.0 @	88.76 =\$	88.76
901-551-116-50	Sill Plate Rt-N	1.0 @	87.15 =\$	87.15
901-613-311-01	Column Cover T-N	1.0 @	106.85 =\$	106.85
901-613-312-01	Column Cover B-N	1.0 @	106.85 =\$	106.85
923-424-591-00	Hand Brake Boot-N	1.0 @	14.34 =\$	14.34
901-424-523-01	Brake Button-N	1.0 @	3.91 =\$	3.91
901-424-593-01	Seal Ring-N	1.0 @	7.18 =\$	7.18
901-424-521-01	Hand Brake Handle-N	1.0 @	14.49 =\$	14.49
901-424-323-01	Knob-N	1.0 @	18.29 =\$	18.29
901-552-871-40-0	Coat Hook-N	2.0 @	3.86 =\$	7.72
901-542-495-21	Seal Ring-N	2.0 @	11.62 =\$	23.24
901-552-891-20	Rosette-N	2.0 @	4.48 =\$	8.96
911-542-471-00	Window Crank Handle-N	2.0 @	87.43 =\$	174.86
999-703-077-40	Screw Plug-N	2.0 @	1.26 =\$	2.52
901-531-671-21	Lock Knob-N	2.0 @	6.59 =\$	13.18
901-424-014-00	Shift Knob-N	1.0 @	187.72 =\$	187.72
901-613-160-02	Hider-N	1.0 @	141.22 =\$	141.22
901-552-853-00	Knob-N	2.0 @	56.56 =\$	113.12
SMC-531-701-23	Striker Lt-N	1.0 @	42.50 =\$	42.50
SMC-531-702-23	Striker Rt-N	1.0 @	42.50 =\$	42.50
644-701-107-00	ID Plate Color Code-N	1.0 @	15.33 =\$	15.33
695-347-725-00	Steering Support-N	1.0 @	35.93 =\$	35.93
901-531-935-20	Door Glass Felt Left-N	1.0 @	150.53 =\$	150.53
901-531-936-20	Door Glass Felt Right-N	1.0 @	150.53 =\$	150.53
911-531-951-01	Door Glass Felt-N	2.0 @	24.42 =\$	48.84
999-591-326-01	Door Moulding Clip-N	14.0 @	3.05 =\$	42.70
999-703-119-40	Stopper-N	4.0 @	0.71 =\$	2.84
SMC-531-005-00	Screw Striker-N	4.0 @	8.21 =\$	32.84
477-857-511-B	Mirror Interior-N	1.0 @	135.17 =\$	135.17
901-542-482-20	Window Crank Cover-N	2.0 @	31.91 =\$	63.82
NPN	Ship Expedite-S	1.0 @	28.55 =\$	28.55
DYC-19405	Dynamat Sound Pad-N	3.0 @	193.15 =\$	579.45

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
EPA # CAL000361950
5505 Moreno Street
Montclair, CA 91763-6235
Phone: 909-982-9111 FAX: 909-982-9112

900-561-Interior/Under Hood Work		20.0 @	1.67 =\$	33.40	
SMC-551-001-00	Screw Set-N	1.0 @	3.26 =\$	3.26	
901-521-915-10	Recliner Cover Set-N	1.0 @	125.82 =\$	125.82	
901-521-916-10	Recliner Cover Set-N	1.0 @	125.82 =\$	125.82	
644-521-015-00	Seat Hardware Set-N	1.0 @	102.38 =\$	102.38	
901-531-093-23	Door Seal Early-N	2.0 @	78.79 =\$	157.58	
901-552-501-21	Glove Box-N	1.0 @	256.28 =\$	256.28	
NPN	Shipping-S	1.0 @	10.30 =\$	10.30	
NPN	Turn Sig Parts-S	1.0 @	79.95 =\$	79.95	
19318	Screw 6m x 19-N	8.0 @	1.05 =\$	8.40	
911-531-889-00	Door Panel Seal-N	1.0 @	46.70 =\$	46.70	
911-531-890-00	Door Panel Seal-N	1.0 @	46.70 =\$	46.70	
900-270-049-07	Screw 5m x20 CS-N	8.0 @	5.41 =\$	43.28	
911-731-331-00	Sun Visor Clip-N	2.0 @	5.48 =\$	10.96	
9750K31	plastic round plug-S	1.0 @	11.61 =\$	11.61	
N-014-122-8	Screw M4x8-N	2.0 @	1.32 =\$	2.64	
901-559-330-01	Insignia-N	1.0 @	40.94 =\$	40.94	
914-347-831-00	Horn Contact Pin-N	1.0 @	24.11 =\$	24.11	
964-731-031-42	CA9 Sun Visor-N	1.0 @	201.11 =\$	201.11	
900-143-111-07	Screw 3.9x13-N	2.0 @	0.37 =\$	0.74	
N-014-093-3	Tapping Screw 4-N	8.0 @	1.78 =\$	14.24	
SIC-572-911-20	Tube Defroster-N	2.0 @	36.90 =\$	73.80	
964-731-032-40	CA9 Sun Visor-N	1.0 @	201.13 =\$	201.13	
999-702-040-50	Rear Defrost Gr-N	2.0 @	6.23 =\$	12.46	
NPN	Alum Trim Polishing-S	1.0 @	52.00 =\$	52.00	
644-613-342-10	Relay Flasher-N	1.0 @	45.66 =\$	45.66	
WINDOW FRAME	Used-S	1.0 @	450.00 =\$	450.00	7245.20

Repair gauge wiring, replace all the door pin bushings then ream them to size. Remove the pedal assembly. Clean and paint the misc parts as needed. Replace the bushings. Install the assembly. Rebuild the shifter. Rebuild the emergency brake. Refurbish the heater parts. Make the missing rear defroster parts.

Job Subtotal: \$27,085.20

Job07 Chassis Recondition	Labor: \$10,157.50
---------------------------	--------------------

901-331-026-00	Wheel Brg-N	2.0 @	157.94 =\$	315.88
900-052-030-00	Wheel Brg-N	2.0 @	50.24 =\$	100.48
999-113-085-40	Seal-N	2.0 @	20.38 =\$	40.76
999-113-046-50	Seal-N	2.0 @	42.08 =\$	84.16
2290003	Spring Plate bush. Erl-N	1.0 @	100.00 =\$	100.00

----->---->---->---Continued on the next page--->---->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

2290070	Chassis Recondition	Bush Ft Er-N	1.0 @	225.00 =\$	225.00
2290034	Camber Plate bush 2 pt-N		1.0 @	100.00 =\$	100.00
2290026	T Arm Bush St-N		1.0 @	190.00 =\$	190.00
901-343-783-00	Drop Link Bushing-N		4.0 @	9.81 =\$	39.24
901-333-793-03	Sway bar Bushing-N		4.0 @	28.58 =\$	114.32
NPN	Shipping-S		1.0 @	14.95 =\$	14.95
86-1308	Shock Insert-N		2.0 @	167.75 =\$	335.50
8040-1083	Shock,Rr Koni-N		2.0 @	194.78 =\$	389.56
NPN	Shipping-S		1.0 @	21.85 =\$	21.85
477-405-641	Wheel Bearing Seal-N		2.0 @	16.27 =\$	32.54
999-059-065-00	Wheel Bearing Inner-N		2.0 @	22.16 =\$	44.32
999-059-098-00	Wheel Bearing Outer-N		2.0 @	25.52 =\$	51.04
901-341-047-00	Ball Joint,Early-N		2.0 @	198.32 =\$	396.64
999-701-084-50	O-Ring-N		2.0 @	1.40 =\$	2.80
901-343-754-01	Mount,Sway Bar Ft-N		2.0 @	50.00 =\$	100.00
901-352-041-15	Disc.Rr-N		2.0 @	313.79 =\$	627.58
477-405-083-D	Rotor,Ft-N		2.0 @	56.23 =\$	112.46
999-701-091-50	O Ring-N		2.0 @	9.32 =\$	18.64
PAE320	Brake Hard Line 20"-N		2.0 @	10.08 =\$	20.16
PAE340	Brake Hard Line3/16x40-N		2.0 @	14.99 =\$	29.98
911-347-031-01	Tie Rod-N		2.0 @	162.98 =\$	325.96
901-341-475-00	gasket-N		2.0 @	3.26 =\$	6.52
900-082-142-01	Motor Mount Bolts-N		1.0 @	5.11 =\$	5.11
SUBLET	Powder Coat Black-S		1.0 @	925.00 =\$	925.00
SUBLET	Zinc Plating-S		1.0 @	525.00 =\$	525.00
PAE320	Brake Hard Line 20"-N		6.5 @	10.08 =\$	65.52
901-424-317-00	Lever Arm-N		1.0 @	22.66 =\$	22.66
901-424-704-01	Heat Cable Guide Tube-N		2.0 @	21.16 =\$	42.32
914-356-201-00	Rubber Sleeve-N		2.0 @	6.57 =\$	13.14
SH 41-04R	Shrink Tube 1/2", Ft-N		2.0 @	1.64 =\$	3.28
901-741-291-00	Speedo Bellow-N		1.0 @	13.81 =\$	13.81
13-53-7-563-456	Fuel Hose 8.0 X 13.0 F-N		0.1 @	73.62 =\$	7.36
W CC 0541155	Crimp Clamp 15.5-N		2.0 @	3.90 =\$	7.80
W N 031708	Nut M8x13-N		1.0 @	0.54 =\$	0.54
W W 04110824	Fender Washer M8x24-N		1.0 @	0.56 =\$	0.56
W B 00671230	Bolt 12x30 1.5a-N		4.0 @	2.99 =\$	11.96
W W 0407012	Flat Washer M12-N		8.0 @	0.72 =\$	5.76
W N 031701015	Hex Nut M12-N		4.0 @	2.13 =\$	8.52
W W 0441010	Lock Washer M12-N		4.0 @	0.89 =\$	3.56
3M	Contact Cement-N		1.0 @	12.95 =\$	12.95
W B 00570516	Bolt M5x16-N		5.0 @	0.46 =\$	2.30
W W 040705	Flat Washer M5-N		5.0 @	0.40 =\$	2.00

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job 07608	Chassis Recondition	M8-N	6.0 @	0.75 =\$	4.50
W W 040708	Flat Washer	M8-N	12.0 @	0.45 =\$	5.40
W W 044108	Lock Washer	M8-N	2.0 @	0.57 =\$	1.14
W B 00570835	bolt	M8x35-N	4.0 @	1.32 =\$	5.28
W B 0084820	key bolt	M8x20-N	2.0 @	0.72 =\$	1.44
930-512-052-00	latch	Upper-N	1.0 @	182.96 =\$	182.96
901-512-052-00	Latch	Lower-N	1.0 @	283.49 =\$	283.49
911-504-115-00	Eng. Comp.	Rubber Seal-N	1.0 @	54.57 =\$	54.57
W 089391040	Seam Sealer,	No Sag-N	0.5 @	70.50 =\$	35.25
W B 6908410	Brush Acid	1/2 in-N	5.0 @	0.35 =\$	1.75
901-628-183-00	Rubber Grommet	-N	1.0 @	18.81 =\$	18.81
928-628-074-01	Washer Pump,	OE-N	1.0 @	116.08 =\$	116.08
901-628-720-26	Washer Fluid	Tank-N	1.0 @	125.94 =\$	125.94
911-628-167-00	Reservior Cap	-N	1.0 @	4.94 =\$	4.94
901-628-730-23	Reservior Connection	-N	1.0 @	19.32 =\$	19.32
901-611-311-00	Batt Cable End	-N	1.0 @	13.33 =\$	13.33
000-043-203-66	Brake Fluid	ATE,SL-N	1.0 @	36.99 =\$	36.99
W B 00570816	bolt	M8x16-N	3.0 @	0.88 =\$	2.64
W W 044108	Lock Washer	M8-N	3.0 @	0.57 =\$	1.71
900-123-011-30	Sealing Ring	22X27-N	1.0 @	2.23 =\$	2.23
999-702-076-50	Grommet	-N	2.0 @	5.36 =\$	10.72
999-702-065-50	Grommet	-N	2.0 @	1.48 =\$	2.96
SUBLET	Fuel Tank Strip	-S	1.0 @	350.00 =\$	350.00
900-219-001-30	Plug	-N	1.0 @	11.38 =\$	11.38
901-201-023-04	Fuel Tank Strainer	-N	1.0 @	76.28 =\$	76.28
W 98-125	Wire	16ga Bk-N	1.0 @	0.23 =\$	0.23
SH 41-02R	Shrink Tube	1/4"-N	1.0 @	1.32 =\$	1.32
155991338	Eyelet	3/8 Crimp-N	2.0 @	3.52 =\$	7.04
W N 036805	Nylock Nut	M5-N	2.0 @	0.38 =\$	0.76
W W 043505	Spring Washer	M5-N	2.0 @	0.51 =\$	1.02
901-501-913-21	Washer.	Seal-N	2.0 @	7.10 =\$	14.20
901-504-079-00	Torsion Bar Cap	-N	2.0 @	43.45 =\$	86.90
914-201-891-00	Sending Unit	Gasket-N	1.0 @	6.90 =\$	6.90
901-201-271-01	Fuel Cap	-N	1.0 @	57.23 =\$	57.23
911-201-515-00	Filler Boot	-N	1.0 @	38.95 =\$	38.95
901-201-591-21	Filler Neck	Boot-N	1.0 @	40.70 =\$	40.70
911-201-279-01	Fuel Flap	-N	1.0 @	16.83 =\$	16.83
999-152-004-00	C Ring	-N	1.0 @	5.48 =\$	5.48
911-201-593-00	Overflow Socket	-N	1.0 @	5.17 =\$	5.17
964-201-153-00	Overflow Hose	-N	1.0 @	24.54 =\$	24.54
901-543-902-20	Quarter Glass	Seal-N	1.0 @	145.26 =\$	145.26
901-543-901-20	Quarter Glass	Seal-N	1.0 @	145.26 =\$	145.26

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job 542 Chassis Recondition				
901-542-931-23	Seal Vent Glass-N	1.0 @	91.30 =\$	91.30
901-542-932-23	Seal Vent Glass-N	1.0 @	90.41 =\$	90.41
901-543-191-20	Quarter Glass Seal-N	2.0 @	67.11 =\$	134.22
999-703-140-41	Hood Buffer Stop-N	4.0 @	2.40 =\$	9.60
914-628-203-10	Windshield Washer Nozz-N	2.0 @	28.60 =\$	57.20
911-511-331-00	Hood Shock HD-N	2.0 @	32.88 =\$	65.76
911-512-331-02	Decklid Shock-N	1.0 @	30.23 =\$	30.23
901-511-073-20	Hood Cable-N	1.0 @	22.13 =\$	22.13
901-511-051-21	Hood Catch-N	1.0 @	218.18 =\$	218.18
901-511-052-20	Hood Lock Lower-N	1.0 @	371.46 =\$	371.46
901-504-385-20	Cable Pull Tube-N	1.0 @	7.03 =\$	7.03
999-166-043-02	Shock Bolt-N	6.0 @	0.81 =\$	4.86
N-012-645-2	Lock tab-N	6.0 @	0.61 =\$	3.66
999-703-033-40	Cap-N	4.0 @	0.55 =\$	2.20
901-543-921-25	Quarter Trim L-N	1.0 @	87.81 =\$	87.81
901-543-922-25	Quarter Trim Rt-N	1.0 @	77.84 =\$	77.84
900-144-009-00	Screw 2.9x13-N	16.0 @	0.35 =\$	5.60
901-543-419-20	Plastic Washer-N	10.0 @	1.73 =\$	17.30
911-424-024-04	Shift Rod Coupling-N	1.0 @	118.10 =\$	118.10
914-424-224--00	Shifter bushing-N	1.0 @	9.75 =\$	9.75
911-424-139-00	Ball Cup Bushing-N	1.0 @	12.07 =\$	12.07
901-424-229-00	Shift Coupling Screw-N	1.0 @	5.05 =\$	5.05
901-543-791-21	Base Seal-N	2.0 @	5.04 =\$	10.08
999-911-041-00	Protective Edging-N	2.0 @	17.45 =\$	34.90
901-543-423-00	Trim-N	2.0 @	4.28 =\$	8.56
964-613-601-00	Contact Switch-N	3.0 @	25.22 =\$	75.66
901-615-616-20	Light Switch Cap-N	2.0 @	3.98 =\$	7.96
999-611-920-20	Ground strap-N	1.0 @	22.82 =\$	22.82
901-423-010-01	Accel Pedal-N	1.0 @	97.81 =\$	97.81
901-424-293-02	Shift Rod Boot-N	1.0 @	27.05 =\$	27.05
901-424-292-02	Boot-N	1.0 @	54.93 =\$	54.93
901-343-782-00	Sway bar Link Bushing-N	2.0 @	3.87 =\$	7.74
901-333-753-01	Sway Bar Clamp-N	2.0 @	14.07 =\$	28.14
901-333-731-01	Drop Link Lt-N	1.0 @	44.83 =\$	44.83
901-333-732-01	Drop Link Rt-N	1.0 @	44.63 =\$	44.63
901-611-025-20	Battery Strap-N	1.0 @	61.18 =\$	61.18
901-505-091-20	Bumper Rubber Trim-N	1.0 @	69.27 =\$	69.27
901-505-092-20	Bumper Rubber-N	2.0 @	17.50 =\$	35.00
901-505-497-20	Bumper Seal-N	1.0 @	14.56 =\$	14.56
901-512-901-00	Decklid Seal-N	1.0 @	36.97 =\$	36.97
PCG-911-182-40	Piping-N	2.0 @	37.70 =\$	75.40

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job 511 Chassis Recondition				
		1.0 @	83.29 =\$	83.29
911-531-095-03	Door Seal-N	2.0 @	191.17 =\$	382.34
901-333-701-04	Sway Bar-N	1.0 @	271.83 =\$	271.83
SUBLET	Zinc Plating G&S-S	1.0 @	695.00 =\$	695.00
999-704-157-40	Washer Fiber-N	10.0 @	0.37 =\$	3.70
901-511-791-21	Washer Rubber-N	8.0 @	2.86 =\$	22.88
999-591-211-01	Speed Nut-N	18.0 @	1.24 =\$	22.32
901-632-291-00	Seal Light-N	1.0 @	12.95 =\$	12.95
901-632-201-01	Luggage Comp. Lamp-N	1.0 @	15.49 =\$	15.49
901-631-601-01	Light-N	2.0 @	54.03 =\$	108.06
900-631-104-90	Bulb 12V 5W-N	1.0 @	4.42 =\$	4.42
W HC 0539812	Hose clamp 8-12-6mm he-N	8.0 @	2.91 =\$	23.28
230-476-87-26	Fuel Hose 7.5x13.5FT-N	5.0 @	9.50 =\$	47.50
W TS 6991104	Time Sert M6x9.4-N	2.0 @	1.93 =\$	3.86
W B 00570620	bolt M6x20-N	2.0 @	0.46 =\$	0.92
W W 040706	Flat Washer M6-N	5.0 @	0.20 =\$	1.00
W W 044106	lock washer M6-N	3.0 @	0.16 =\$	0.48
W N 031706	Hex Nut M6-N	3.0 @	0.42 =\$	1.26
W EC 05589920	Spade Fem 14ga-N	4.0 @	2.07 =\$	8.28
W HC 05391016	Hose Clamp 10-16-6mm h-N	4.0 @	2.37 =\$	9.48
901-573-140-00	Mount Strap-N	1.0 @	28.48 =\$	28.48
N-013-961-11	Screw 3x15-N	2.0 @	0.24 =\$	0.48
901-531-035-20	Door Stop-N	2.0 @	93.64 =\$	187.28
900-088-009-02	Pin, Stop-N	2.0 @	5.16 =\$	10.32
N-012-239-1	Washer-N	1.0 @	0.43 =\$	0.43
900-078-007-02	Nut-N	1.0 @	2.37 =\$	2.37
900-014-069-02	Screw 3x8mm-N	4.0 @	1.52 =\$	6.08
901-741-293-00	Grommet,Cable-N	1.0 @	9.78 =\$	9.78
NPN	Shipping-S	1.0 @	3.44 =\$	3.44
900-148-014-02	Screw 6x16 CS-N	6.0 @	2.97 =\$	17.82
999-230-002-02	Clamp-N	1.0 @	1.37 =\$	1.37
914-504-319-00	Grommet-N	1.0 @	3.68 =\$	3.68
911-025-679-00	Buffer Fuel Door-N	1.0 @	6.09 =\$	6.09
NPN	Vent Glass Used-S	1.0 @	380.00 =\$	380.00
901-503-394-22	Fender to Cowel Trim-N	2.0 @	10.27 =\$	20.54
901-504-317-21	Fuel Door Cable-N	1.0 @	8.24 =\$	8.24
921-060-004	Antenna (Chrome)-N	1.0 @	19.02 =\$	19.02
901-631-900-35	Screw 4x35-N	8.0 @	0.45 =\$	3.60
999-507-311-12	Speed Nut 4mm-N	8.0 @	9.56 =\$	76.48
911-541-011-00	Windshield-N	1.0 @	936.15 =\$	936.15
NPN	Shipping-S	1.0 @	150.00 =\$	150.00
911-541-225-04	Seal, Windshield-N	1.0 @	169.54 =\$	169.54

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

911-071-Chassis Recondition	Field-N	1.0 @	169.54 =\$	169.54
1HO-953-227	Relay Flasher-N	1.0 @	28.95 =\$	28.95
NPN	Shipping-S	1.0 @	2.34 =\$	2.34
999-532-003-00	Retainer Sleeve-N	1.0 @	9.13 =\$	9.13
902-505-153-20	Piping /Gasket-N	2.0 @	7.39 =\$	14.78
901-571-288-21	Drain Hose-N	1.0 @	16.41 =\$	16.41
902-505-055-21-G	Bumper cap-N	1.0 @	86.22 =\$	86.22
902-505-145-21	Retaining Strap-N	2.0 @	8.51 =\$	17.02
902-505-056-21	Bumper Cover Rt-N	1.0 @	86.22 =\$	86.22
902-635-115-20	Clamp-N	2.0 @	60.26 =\$	120.52
911-701-101-00	Chassis ID plate-N	1.0 @	183.82 =\$	183.82
SMC-006-SET	Decal Set 911 S-N	1.0 @	56.70 =\$	56.70
NPN	Shipping-S	1.0 @	10.28 =\$	10.28
911-423-081-02	Throttle Coupling-N	1.0 @	104.35 =\$	104.35
901-423-223-01	Accele Extension-N	1.0 @	4.14 =\$	4.14
NPN	Shipping-S	1.0 @	28.50 =\$	28.50
N-015-521-3	Ball Socket-N	1.0 @	20.89 =\$	20.89
901-424-701-06	Heater Cable-N	1.0 @	133.21 =\$	133.21
914-504-319-00	Grommet-N	2.0 @	3.68 =\$	7.36
901-631-119-01	Screw Head lamp-N	2.0 @	3.85 =\$	7.70
911-631-108-00	Connector Head lamp-N	2.0 @	1.78 =\$	3.56
N-017-498-A	Connector HL Electric-N	6.0 @	0.89 =\$	5.34
964-628-901-02	Wiper Blade 13"-N	1.0 @	17.46 =\$	17.46
2110-0300	Hose 4.8mm 100mm-N	1.0 @	0.60 =\$	0.60
914-628-313-10	Wiper Arm Left-N	1.0 @	41.75 =\$	41.75
914-628-314-10	Wiper Arm Right-N	1.0 @	41.76 =\$	41.76
901-505-018-03	Bumper Guard FR-N	1.0 @	99.59 =\$	99.59
11715	Bolt 8mx60-S	2.0 @	1.50 =\$	3.00
11718	Bolt 8mx80-S	2.0 @	1.70 =\$	3.40
09208	Screw CS Phip 5x16-N	6.0 @	0.75 =\$	4.50
901-505-017-03	Bumper Guard FL-N	1.0 @	99.59 =\$	99.59
999-591-423-03	Speed Nut-N	18.0 @	2.40 =\$	43.20
7L5-853-611-B	Hood Emblem Seal-N	1.0 @	7.98 =\$	7.98
901-559-210-27	Hood Badge Orange-N	1.0 @	188.38 =\$	188.38
901-628-341-00	Wiper Arm Cap Nut-N	2.0 @	5.48 =\$	10.96
901-628-926-00	Wiper Nut Cap-N	2.0 @	4.33 =\$	8.66
999-591-460-01	Speed Nut 3.9-N	4.0 @	0.24 =\$	0.96
900-143-041-00	Screw 3.9x19-N	4.0 @	1.34 =\$	5.36
901-505-251-20	Bumper End Cap Lt-N	1.0 @	50.22 =\$	50.22
901-505-252-20	Bumper End Cap Rt-N	1.0 @	50.22 =\$	50.22
901-701-051-01	Lic Plate Mount-N	1.0 @	21.06 =\$	21.06
NPN	Shipping-S	1.0 @	5.12 =\$	5.12 15362.20

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job07 Chassis Recondition

Remove the following items,

- 1.Fuel tank
- 2.Front suspension with struts, torsion bars and brakes
- 3.Front under tray
- 4.All horn and bumper brackets for the bumpers
- 5.Partially remove the wire harness
- 6.Complete rear suspension
- 7.All fuel and brake lines
- 8.All the vent system for the fuel system
- 9.Complete rear suspension with torsion bars and brakes
- 10.Fuel pump all the items for the heater system coming from the engine
- 11.The complete emergency brake system
- 12.Sound pad
- 13.Fresh air system from under the hood
- 14.Fuel filling components
- 15.Oil tank and oil lines

Scope of work

- 1.Replace all suspension bushings
- 2.Powder coat all components that are now black. Blast them and powder coat them 30 percent satin black to match the OEM color and finish
- 3.Remove all suspension components and fasteners and either replace them or have them cadmium plated
- 4.Replace the shocks and struts
- 5.Have the brakes rebuilt
- 6.Replace all the rubber lines including brake and fuel lines
- 7.Strip all the loose under coating and install new Wurth under coating from the wheel wells, engine compartment, under hood area and the bottom of the car.
- 8.Install new brake rotors
- 9.Replace all the brake hard lines
- 10.Texture coat the fuel tank
- 11.Replace all wheel bearing

Re install al the parts, set the alignment and ride height to customers specifications. Total price \$25000.

At this point the car will look like the day it left the factory for delivery aside from rebuilding the engine and transmission.

Job Subtotal: \$25,519.70

Job08 Engine Rebuild

Labor: \$10,538.00

901-100-902-01	Engine Gasket Set-N	1.0 @	834.00 =\$	834.00
911-101-901-00	Main Bearing Set-N	1.0 @	283.33 =\$	283.33
901-103-141-00	Rod Bearings-N	1.0 @	218.28 =\$	218.28
901-103-172-00	Rod Bolt-N	12.0 @	20.08 =\$	240.96
901-103-173-00	Rod Nut-N	12.0 @	2.76 =\$	33.12
901-103-901-01	Piston Ring Set-N	6.0 @	56.70 =\$	340.20
993-105-529-00	Timing Chain-N	2.0 @	113.71 =\$	227.42

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job-08-Engine Rebuild					
911-105-222-06	Timing Chain Rail-N	1.0 @	63.67 =\$	63.67	
911-105-222-06	Timing Chain Rail-N	5.0 @	36.04 =\$	180.20	
930-105-053-00	Tensioner-N	2.0 @	461.91 =\$	923.82	
99-0458-053	Saftey Stop-N	2.0 @	29.75 =\$	59.50	
930-105-509-00	Tensioner Arm Lt-N	1.0 @	310.03 =\$	310.03	
930-105-510-00	Tension Arm Rt-N	1.0 @	310.03 =\$	310.03	
901-105-055-00	Idler Sprocket Assy.-N	2.0 @	132.35 =\$	264.70	
901-105-546-02	Cam Sprocket-N	2.0 @	106.54 =\$	213.08	
901-105-125-04	Timing Chain Sprocket-N	2.0 @	91.69 =\$	183.38	
901-105-056-02	Sprocket Shaft-N	2.0 @	45.12 =\$	90.24	
930-105-043-02	Rocker Arm-N	12.0 @	140.24 =\$	1682.88	
911-099-103-52	Rocker Shaft Seals-N	24.0 @	3.99 =\$	95.76	
911-609-061-00	Ignition Wire Set-N	1.0 @	395.03 =\$	395.03	
901-105-361-02	Restrictor Fitting-N	2.0 @	16.69 =\$	33.38	
W-C-3S	Spark Plug-N	6.0 @	9.98 =\$	59.88	
05-200-149	Regrind Cams 911S-N	1.0 @	550.00 =\$	550.00	
901-107-351-01	Oil Return Tube-N	4.0 @	28.88 =\$	115.52	
911-107-008-05	Oil Pump-N	1.0 @	1013.19 =\$	1013.19	
930-101-902-00	Sump Plate-N	1.0 @	54.52 =\$	54.52	
901-105-407-00	Valve,Intake 42mm-N	6.0 @	120.84 =\$	725.04	
901-105-408-50	Valve,Exst 38mm-N	6.0 @	134.56 =\$	807.36	
HP 109	HP Valve Springs-N	1.0 @	390.00 =\$	390.00	
901-211-194-01	Hot Air Tube-N	2.0 @	46.32 =\$	92.64	
901-107-348-00	Oil Line-N	1.0 @	67.00 =\$	67.00	
901-108-391-05	Intake Gasket S-N	6.0 @	3.01 =\$	18.06	
930-105-116-05	Valve Cover, Lower-N	2.0 @	140.18 =\$	280.36	
901-603-421-01	Pully half Alt.-N	1.0 @	23.00 =\$	23.00	
901-107-347-02	Cam Line-N	1.0 @	67.76 =\$	67.76	
901-609-591-00	Wire Holder-N	2.0 @	7.17 =\$	14.34	
901-609-581-00	Wire Holder Frame-N	2.0 @	37.11 =\$	74.22	
999-702-029-50	3 Hole Holder-N	2.0 @	4.45 =\$	8.90	
NPN	Shipping-S	1.0 @	13.83 =\$	13.83	
911-111-025-05	Muffler, Stock-N	1.0 @	915.82 =\$	915.82	
901-111-157-04	Muffler Clamp-N	2.0 @	69.68 =\$	139.36	
SUBLET	Inspect Crankshaft-S	1.0 @	200.00 =\$	200.00	
SHIPPING MISC	Engine Rebuild-S	1.0 @	274.66 =\$	274.66	
COA	PCNA-S	1.0 @	110.00 =\$	110.00	
2122-0600	Fuel Hose 7.5m Cloth F-N	7.0 @	2.64 =\$	18.48	
000-043-205-16	Breather Hose 25mm(1m)-N	2.0 @	57.78 =\$	115.56	
55107	Tee 5/16/8mm Metal-N	1.0 @	13.99 =\$	13.99	
901-602-953-00	Dist. Cap Mirelli-N	1.0 @	117.88 =\$	117.88	
901-602-928-01	Ign Rotor-N	1.0 @	87.64 =\$	87.64	

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job08 Engine Rebuild	Rebuild Set-N	1.0 @	6.06 =\$	6.06	
930-211-622-01	Heater Hose-N	2.0 @	49.68 =\$	99.36	
911-375-043-00	Engine Mount-N	2.0 @	113.34 =\$	226.68	
901-305-311-00	Engine Mount Washer-N	4.0 @	6.11 =\$	24.44	
911-556-891-01	Engine Insulation Pad-N	1.0 @	109.10 =\$	109.10	
901-108-291-00	Hot Air Hose 35mm (1m) -N	2.0 @	12.38 =\$	24.76	13842.42

Clean and Inspect all parts. Replace worn parts as needed. Reassemble the complete engine.
 \$7170 Labor Overhaul Engine
 \$1200 Labor Valve job
 \$1300 Labor Rebuild Rods
 \$868 Labor additional time to repair wire harness

Job Subtotal: \$24,380.42

Job09 1965-71 Transmission Repair	Labor: \$1,434.00
-----------------------------------	-------------------

901-300-901-00	Trans Gasket Set-N (List 111.00)	1.0 @	111.00 =\$	111.00	
911-302-301-06	Synchro Ring-N	5.0 @	113.56 =\$	567.80	
911-302-226-00	Shift Sleeve 1st-Rv-N	1.0 @	475.69 =\$	475.69	
10-1550-315	Gear Teeth 3rd-5th-N	3.0 @	187.88 =\$	563.64	
G 9920-35	Gear Oil (pint)-N	7.0 @	16.99 =\$	118.93	
000-043-203-73	Drei Bond 30mL-N	1.0 @	24.51 =\$	24.51	
HAZMAT	Waste Disposal Fee-N	2.0 @	4.00 =\$	8.00	
NPN	Shipping-S	1.0 @	9.75 =\$	9.75	
NPN	5th Gear "Z" Used-U	1.0 @	700.00 =\$	700.00	
901-332-275-11	Diff Flange Bolt-N	1.0 @	14.04 =\$	14.04	
901-423-317-00	Spring, Clutch Return-N	1.0 @	7.15 =\$	7.15	
901-332-026-11	Axle Assembly-N	2.0 @	120.59 =\$	241.18	
901-611-902-20	Ground Strap-N	1.0 @	68.49 =\$	68.49	
901-423-421-02	Bowden Tube-N	1.0 @	59.14 =\$	59.14	
901-423-401-01	Clutch Cable-N	1.0 @	54.51 =\$	54.51	
901-741-111-01	Speedo Cable-N	1.0 @	135.60 =\$	135.60	3159.43

Disassemble and reassemble the transmission. Clean and inspect then repair as needed.

Job Subtotal: \$4,593.43

Job10 Tail/Turn Signal Rebuild	Labor: \$1,736.00
--------------------------------	-------------------

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job10 Tail/Turn Signal Rebuild

SMC-631-403-00	Lenz Lt Ft-N	1.0 @	73.45 =\$	73.45	
SMC-631-404-00	Lens Rt Ft-N	1.0 @	73.45 =\$	73.45	
SMC-631-415-00	lens Tail Lt-N	1.0 @	83.95 =\$	83.95	
SMC-631-416-00	Lens Tail Rt-N	1.0 @	83.95 =\$	83.95	314.80

Job Subtotal: \$2,050.80

Job11 Dash Restoration

Labor: \$6,915.48

PCG-615-101-10	Relay-S	1.0 @	60.71 =\$	60.71	
901-552-031-22	Dash Top-N	1.0 @	1256.56 =\$	1256.56	
901-552-021-21	Dash Front-N	1.0 @	524.00 =\$	524.00	
NPN	Shipping-S	1.0 @	82.90 =\$	82.90	
999-591-310-40	Clips-N	11.0 @	1.46 =\$	16.06	
901-741-632-01	Sensor Temp-N	1.0 @	218.62 =\$	218.62	2158.85

Make missing trim parts. Install all the dash parts.

Job Subtotal: \$9,074.33

Job12 BodyShop-Refinish A.A.

Labor: \$0.00

Job Subtotal: \$0.00

Job13 Wheels

Sublet: \$3,500.00

Includes refinnish full set of wheelsand caps. Purchase one additional 5.5" wheel as a spare.
 Includes Shipping
 Inv 243442

Job14 Parking Brake Restoration

Labor: \$1,215.20

Job Subtotal: \$1,215.20

Job15 Mount, Balance & 5 tires

Sublet: \$120.00

Mount, Balance 5 tires (insluding the spare tire)

Job16 Tires

Labor: \$0.00

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
 EPA # CAL000361950
 5505 Moreno Street
 Montclair, CA 91763-6235
 Phone: 909-982-9111 FAX: 909-982-9112

Job16 Tires

165/R15	Tire Vredestein Class-N	5.0 @	162.20 =\$	811.00	
NPN	Shipping-S	1.0 @	57.50 =\$	57.50	
DPORSCHE01	Lug Nut Alloy Black-N	20.0 @	15.86 =\$	317.20	1185.70

Replace the lug nuts with new nuts.

Job Subtotal: \$1,185.70

Job17 Seat Restoration

Labor: \$6,615.00

644-521-191-00	Seat Buffer-N	4.0 @	6.85 =\$	27.40	
911-521-163-00	Handle, Seat, Recaro-N	8.0 @	23.76 =\$	190.08	
NPN	Shipping-S	1.0 @	10.35 =\$	10.35	227.83

Straighten the seat frames. Weld the cracks. Take them apart, replace the damaged parts.
 Take the retract mechanisms apart and rebuild them. Plate all the parts.

Job Subtotal: \$6,842.83

Job18 Chrome

Sublet: \$950.00

Repair and chrome
 Light buckets, Bumper Guards, Head light rings, Door Handles

Job19 Powder Coat Seats

Sublet: \$310.00

Powder coat seat and interior parts 20% black

Job20 Paint Door Black Trim, Interior

Labor: \$378.00

Job Subtotal: \$378.00

Job21 Zinc Plate Seat Parts

Sublet: \$386.00

Silver Zinc misc seat parts for interior.

Job22 Chrome plate, Seats

Sublet: \$1,170.00

Job23 Head Lights Restore

Labor: \$1,350.00

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
EPA # CAL000361950
5505 Moreno Street
Montclair, CA 91763-6235
Phone: 909-982-9111 FAX: 909-982-9112

Job23 Head Lights Restore

911-631-115-02	Headlight Rim Seal-N	2.0 @	7.64 =\$	15.28	15.28
----------------	----------------------	-------	----------	-------	-------

Take them apart and rebuild the entire assemblies. Chrome the bezels and paint inside them.

Job Subtotal: \$1,365.28

Job24 65-73 Alignment 4 wheel	Labor: \$810.00
-------------------------------	-----------------

Perform a 4 wheel alignment. We would like .7 degrees of camber and 3 MM total toe in in the rear and .8 degrees of camber and 1 mm total toe in in the front. This is much longer that a standard alignment since the whole car was apart.

Job Subtotal: \$810.00

Job25 Anodize Clear	Sublet: \$70.00
---------------------	-----------------

Clear anodize dash parts
Inv#111607

Job26 65-68 Seat Belts,Retractable	Labor: \$97.30
------------------------------------	----------------

505710	Seat Belt Kit-N	1.0 @	376.00 =\$	376.00	
NPN	Shipping-S	1.0 @	20.00 =\$	20.00	396.00

Job Subtotal: \$493.30

Job27 Carbs	Labor: \$1,306.60
-------------	-------------------

FUEL	91 Octane Fuel (Gallon-N	10.0 @	5.90 =\$	59.00	59.00
------	--------------------------	--------	----------	-------	-------

Get the mixture set correctly. Replace the jets to compensate for the ethenol that is in today gas. The old 911's dont run well on modern fuel without re jetting them.

Job Subtotal: \$1,365.60

Job28 Distributor R&R	Labor: \$278.00
-----------------------	-----------------

Remove it. Package it and ship it. Re install it and set the timing.

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
EPA # CAL000361950
5505 Moreno Street
Montclair, CA 91763-6235
Phone: 909-982-9111 FAX: 909-982-9112

Job28 Distributor R&R

Job Subtotal: \$278.00

Job29 Distributer Recurve

Sublet: \$295.95

Custom recurve and overhaul dist.

Job30 Trunk Carpet

Labor: \$347.50

TS6568GP	Carpet Trunk Perlon-N	1.0 @	220.00 =\$	220.00	
NPN	Shipping-S	1.0 @	18.50 =\$	18.50	238.50

German OE Perlon for 1968. Remove the fender bolts and make the correct holes for the hood carpet. Glue it in place where Porsche glued it and use the fender bolts to hold it in the other spots. Make it match the OEM installation.

Job Subtotal: \$586.00

Job31 LED Head Light Upgrade

Labor: \$300.00

SMD	LED Headlights-S	1.0 @	250.00 =\$	250.00	250.00
-----	------------------	-------	------------	--------	--------

Job Subtotal: \$550.00

Job32 Towing

Sublet: \$248.00

Tow to LA for interior
Inv# 121065

Job33 Towing

Sublet: \$244.00

Tow back to 911Design
Inv118117

Job34 Finish AC

Labor: \$1,946.00

Install vents and wiring after interior work

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
EPA # CAL000361950
5505 Moreno Street
Montclair, CA 91763-6235
Phone: 909-982-9111 FAX: 909-982-9112

Job34 Finish AC

Job Subtotal: \$1,946.00

Job35 Charging System

Labor: \$0.00

Check for proper operation. Working correctly. No charge

Job Subtotal: \$0.00

Job36 Transmission Oil leak

Labor: \$0.00

No charge. Replace the shift cover plate gasket

Job Subtotal: \$0.00

Job37 65-68 Battery

Labor: \$187.65

NBTX1	Battery fee-N	2.0 @	1.00 =\$	2.00	
MT-51-R	Battery-N	1.0 @	120.85 =\$	120.85	122.85

Remove and replace the battery

Job Subtotal: \$310.50

Job38 Carburetors

Labor: \$695.00

Clean them. The jets where clogged after sitting

Job Subtotal: \$695.00

Job39 65-73 lic. Plate holder

Labor: \$0.00

901-701-051-24	Lic. Plate Holder Set-N	1.0 @	27.23 =\$	27.23	
----------------	-------------------------	-------	-----------	-------	--

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
EPA # CAL000361950
5505 Moreno Street
Montclair, CA 91763-6235
Phone: 909-982-9111 FAX: 909-982-9112

Job39 65-73 license plate holder	1.0 @	11.95 =\$	11.95	39.18
----------------------------------	-------	-----------	-------	-------

Install front lic plate holder
labor start at .99 5/28/19

Job Subtotal: \$39.18

Job40 Detail Car	Labor: \$0.00
------------------	---------------

No charge

Job Subtotal: \$0.00

Job41 Horn	Labor: \$0.00
------------	---------------

No charge

Job Subtotal: \$0.00

911 Design will warranty all repairs for 12 months or 12,000 miles (commencing on the date of the customer's original invoice) against defective parts and workmanship, provided the vehicle has been properly driven and maintained according to the manufacturer's recommended schedule. This warranty excludes used parts, parts not purchased from 911 Design and parts used for off-road or racing purposes. 911 Design will warranty only the defective parts or labor and is not liable for incidental damages beyond the defective parts or labor.

Warranty is non-transferable.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

----->----->----->---Continued on the next page--->----->----->----->

000007027

Order Date 06/27/14 11:36 am
Closed/Paid: 05/30/19 11:00 am

BAR #: ARD212945
EPA # CAL000361950
5505 Moreno Street
Montclair, CA 91763-6235
Phone: 909-982-9111 FAX: 909-982-9112

(Signature) _____

"I acknowledge notice and oral approval of an increase in the original
estimated price"

(Signature or initials) _____

Payments to 911 Design

Cost Summary

Status: Closed Work Order

Payments: \$183,257.30

1	07/21/14	5000.00	Check	9216
2	10/16/14	20000.00	Other	ACH/Wire
3	06/03/15	20000.00	Other	12/26/14 ACH/Wire
4	06/09/15	20000.00	Other	ACH 6/10/15
5	04/11/16	30000.00	Other	WIRE
6	06/02/16	25000.00	Other	ACH
7	03/07/17	29881.04	Other	ACH
8	08/16/17	20000.00	Other	Wire
9	05/30/19	13376.25	Other	wire

Labor	115357.10
Parts	50584.36
Non Taxable	6017.45
Sublet	7293.95
Discount	42.32
Tax	4046.75
Total	\$183257.30
Payments	183257.30
Bal Due	0.00

Thank you for choosing 911 Design



AAA BATTERY INVOICE

For Your Next Battery, Call: 800-AAA-HELP | To Join AAA, Call: 800-JOIN-AAA or Visit AAA.com



QUALITY



CONVENIENCE



PEACE OF MIND

Member			
Address			
Phone #			
Year <u>1968</u>	Make <u>Porsche</u>	Model <u>911s</u>	Engine
License Plate <u>BS692</u>		Odometer	

QUANTITY	PART #	PARTS / LABOR DESCRIPTION	PARTS	LABOR
1	51R	Battery Price	\$	<u>INC</u>
		Battery Serial Number		
		Standard Installation	<u>INC</u>	\$ Included
		Charging Systems Check	<u>Yore</u>	\$ Included
		Non-Standard Installation (if applicable)	\$	\$
		Non-Recycling Fee (If a core is not returned, a non-recycling fee will be charged)		\$
		<u>Terminals is clean and tight.</u>		
		Subtotal	\$	\$
		Sales Tax	\$	<u>INC</u>
		State Disposal Fee (if applicable)	<u>INC</u>	\$
		TOTAL	\$ <u>161.98</u>	



36-Month Free Replacement Period + 36-Month Discount Period = 72-Month Limited Warranty

Original Part # _____ Original Battery Serial # _____ Original Purchase Date _____

☐ **Free Warranty:** _____ months of free warranty period remaining + 36-month discounted period

☐ **Discounted Warranty:** Battery age is _____ months. Replacement cost is _____.

☒ I understand and acknowledge that my battery may not require immediate replacement; however I am authorizing replacement of my battery at this time.

☒ I understand that my vehicle may require additional repairs and/or service based on the following:

Professionally installed by:

Technician Name

Matthew A

Technician ID

135455

Facility ID

1201200

Signed _____

Date 9/18/21