

Hi [REDACTED],

Here are the estimates for the various items in need of repair on your car.

### 1 )TRANS-AXLE REPAIR

Remove axle shafts from Trans axle,

Disconnect shift rod , drive shaft coupler, wiring for reverse light switch , torque tube ,motor mounts.

Remove Trans Axle from chassis .

Perform initial inspection ,drain gear oil, remove side cover, found shift fork hold down bolt was sheared off, also it appears to have excessive wear on synchro sleeves ,no resistance when engaging gears .

Recommend Trans axle tear-down for inspection ,and advise , approximate labor for complete overhaul 60.0 HOURS. plus parts to be determined upon disassembly.

### 2) REPAIR OIL LEAKS,

Upon inspection We found , oil leaks into spark plug gully cause by leaking valve cover gaskets, front cover o rings ,distributor housings.

Remove air cleaner assembly , distributors ,IGN wiring , distributor housings ,valve covers ,adj valve clearance as needed ,remove idler gear bolts ,replace o rings , replace all gaskets ,o rings ,end plate gaskets.

Re-Assemble all components ,Approximate labor 40.0 - 45.50 HOURS . plus parts.

### 3) MOTOR MOUNTS, HEADERS ,HEAT SHIELDS.

We also found that engine motor mounts are collapsed and of the wrong type , causing exhaust headers to rest on the sub-frame ,missing heat shields for top of mufflers .

Recommend ,remove exhaust system , lift motor from motor mounts , remove motor mounts ,remove headers for repair , cut collapsed sections ,weld new sections , sub let for media blast and jet-coat re-Finnish ,replace exhaust gaskets,re-install headers, install new motor mounts,fabricate heat shields for mufflers

Labor is Approximately 35.0 - 40.0 HOURS plus parts.

Labor Rate \$225.0 per Hour

# F R Z A M T R S M N T E R E Y I N C.

113 AVIATION LN

MONTEREY CA 93940

TELEPHONE (831) 655-4943

SERVICE RDER

Page 1 out of 3

200978

1 Nov 2024

BUSINESS LICENSES

2757122

CAL000325293

Our Business hours are 8:am to 5:pm M-F. CASH OR CHECKS ONLY NO CRED...

Monday - Friday 8:am to 5:pm

ORIGINAL DATE :

Thursday, 22 Aug 2024

C MPANY 560

CUST MER

ADDRESS

TELEPH NE(S)

E AIL

DUE BY

PARK#

WRITER

22 Aug 24 09:42

UNIT

?

YEAR 1969

MAKE FERRARI

M DEL 365 GTB/4 DAYTONA

LICENSE # 560 - 200978

V.I.N. 560-200978

MILES IN AND UT 0 / 0

H URS IN AND UT /

C L R

SUBT TAL TIRES

ENGINE

TYPE LAB R PERF RMED

H URS TECH. LIST PRICE SALE EACH SUBT TAL

- 1 L CAR TOWED IN WITH GEAR SELECTOR, INSPECT CAR, FOUND INTERNAL PROBLEM IN TRANSAXLE, FOUND , ENGINE MOTOR MOUNTS COLLAPSED , CAUSING EXHAUST HEADERS TO REST ON SUBFRAME, FUEL LINES CRAKED IN REAR AT FUEL FILTERS,CARB FUEL RAIL,HEAT SHIELDS ABOVE MUFFLERS MISSING OIL LEAKS,COOLANT LEAKS FROM HEAD GASKETS,FRONT TIMING COVER, DISTRIBUTOR HOUSINGS, \$ 500.00
- 2 L REPAIR TRANSAXLE, REMOVE EXHAUST SYSTEM, DISSCONNECT DRIVE SHAFT COUPLER ,SHIFT ROD ,DRIVE AXLES, REVERSE LIGHT SWITCH, REMOVE TRANSAXLE FROM CHASSIS. TEARDOWN AND INSPECT TRANSAXLE , FOUND SHEARD BOLT FOR GEAR SELCTOR FORK, EXCESSIVE WEAR IN SYNCROS, REMOVE SHIFT RODS, FRONT COVER, DIFF, OIL PUMP ,REMOVE CLUSTER GEAR SHFTS , TEARDOWN AND INSPECT ALL PARTS , REPLACE ALL SYNCROS AND, 2-3 ,4-5 OPERATING SLEEVES, REASSEMBLE CHECK CLEARANCES ,REPLACE ALL SEALS ,O RINGS , \$ 13,500.00
- 3 L REPLACE COLLAPSED MOTOR MOUNTS ,USE SCREW JACK TO LIFT MOTOR TO GAIN ACCESS TO MOTOR MOUNTS ,REMOVE HEADERS FOR REPAIR , REPLACE MOTOR MOUNTS,REPLACE MUFFLER GASKETS ,RE-INSTALL REPAIRED HEADERS , INSTALL CUSTOM HEAT SHIELDS FOR MUFFLERS, , INSTALL EXHAUST SYSTEM \$ 9,675.00
- 4 L REPLACE FUEL LINES AT REAR FUEL FILTERS ,REPLACE FILTERS ,REPLACE CONNECTING FUEL LINES ,MAIN FUEL LINE FROM REAR TO CARB FUEL RAIL \$ 1,800.00

TYPE PARTS S LD

QTY TECH. LIST PRICE SALE EACH SUBT TAL

P 95860096 - OR 4075	1.00		\$ 4.56	\$ 4.56
P 95850001 - OR 1019/7	4.88		\$ 1.25	\$ 6.10
P 102645 - CPR. WASHER	2.00		\$ 3.34	\$ 6.68
P 95850105 - SEAL	1.00	\$ 29.25	\$ 26.03	\$ 26.03
P 522982 - GASKET	1.00		\$ 36.25	\$ 36.25
P 521767/S - SYNCHRO RING SET	1.00		\$ 2,108.00	\$ 2,108.00
P 522457 - SYNCRO SLEEVE	2.00		\$ 946.00	\$ 1,892.00
P 522506 - RING NUT	1.00		\$ 126.00	\$ 126.00
P 95860010 - OR 119	1.00		\$ 3.00	\$ 3.00
P 95860060 - OR116	2.00		\$ 1.56	\$ 3.12
P 113087 - OIL RING	1.00		\$ 55.35	\$ 55.35
P 934418 - LOCK TB	27.66			
P 520651 - GASKET	1.00	\$ 51.50	\$ 41.36	\$ 41.36
P 101032 - OR65/205	1.28			
P 131252 - TRANAXLE/MOTOR MOUNT	4.00		\$ 158.45	\$ 633.80
P 103587 - LOCKTAB	5.00	\$ 8.06	\$ 4.50	\$ 22.50

# F R Z A M T R S M N T E R E Y I N C.

113 AVIATION LN

MONTEREY

CA 93940

TELEPHONE (831) 655-4943

SERVICE RDER

P ge 2 out of 3

200978

1 Nov 2024

BUSINESS LICENSES

2757122

CAL000325293

Our Business hours are 8:am to 5:pm M-F. CASH OR CHECKS ONLY NO CRED...

Monday - Friday 8:am to 5:pm

RIGINAL DATE :

Thursday, 22 Aug 2024

C MPANY	560	YEAR	1969
CUST MER		MAKE	FERRARI
ADDRESS		M DEL	365 GTB/4 DAYTONA
		LICENSE #	560 - 200978
TELEPH NE(S)		V.I.N.	560-200978
E AIL		MILES IN AND UT	0 / 0
DUE BY	22 Aug 24 09:42	H URS IN AND UT	/
PARK#		C L R	
WRITER		SUBT TAL TIRES	
	UNIT	ENGINE	
	?		

P 133628 - SEAL	1.00		\$ 109.56	\$ 109.56
P 141509 - SEAL	1.00		\$ 109.56	\$ 109.56
P 104279 - BOLT	1.00		\$ 38.94	\$ 38.94
P 99098 - SPEEDI SLEEVE19MM	1.00		\$ 65.80	\$ 65.80
P 101639 - GRUB SCREW	1.00		\$ 1.85	\$ 1.85
P 95180050 - FUEL FILTER	1.00		\$ 38.72	\$ 38.72
P 95180053 - FUEL FILTER	1.00		\$ 36.15	\$ 36.15
P 94803 - NUT BR. EXH. HDR.	20.00		\$ 8.36	\$ 167.20
P 147697 - EXHAUST GASKETS	2.00		\$ 7.04	\$ 14.08
P 147630 - EXHAUST GASKET	4.00		\$ 26.65	\$ 106.60
P 147631 - EXHAUST GASKET	4.00		\$ 17.46	\$ 69.84
P 6X1X8 - SHIELD BOLTS	16.00		\$ 1.05	\$ 16.80
P 6X20 PAN - FENDER WASHERS	32.00	\$ 22.43	\$ 1.25	\$ 40.00
P 6X1 LK - LOCK WASHERS	16.00		\$ 0.45	\$ 7.20
P 9.5 MM - FUEL LINE	12.00		\$ 3.50	\$ 42.00
P 75/90 - SWEPKO GEAR OIL	5.00		\$ 16.50	\$ 82.50
P 7333178 - EXHAUST CLAMPS	4.00		\$ 5.30	\$ 21.20

TYPE	SUBLET	S	LD	QTY	TECH.	LIST PRICE	SALE EACH	SUBT TAL
S	ADVANCE	\$15,000.00	9/18/24 WIRE TRANSFER					
	ADVANCE	\$10,000.00	10/8/24 WIRE TRANSFER					
S	REPAIR HEADERS, WELD HOLES IN PIPES ,REPLACE ENDS, REPAIR DENTS						\$ 680.00	\$ 680.00
S	JET COAT HEADERS						\$ 395.00	\$ 395.00
S	MUFFLER SHIELDS						\$ 663.00	\$ 663.00

RIGINAL ESTIMATE \$ 5,359.23

X:\_\_\_\_\_



# F R Z A M T R S M N T E R E Y I N C.

113 AVIATION LN

MONTEREY

CA 93940

TELEPHONE (831) 655-4943

SERVICE RDER

P ge 3 out of 3

200978

1 Nov 2024

BUSINESS LICENSES

2757122

CAL000325293

Our Business hours are 8:am to 5:pm M-F. CASH OR CHECKS ONLY NO CRED...

Monday - Friday 8:am to 5:pm

RIGINAL DATE :

Thursday, 22 Aug 2024

C MPANY 560

CUST MER

ADDRESS

TELEPH NE(S)

E AIL

DUE BY

22 Aug 24 09:42

PARK#

WRITER

UNIT

?

YEAR 1969

MAKE FERRARI

M DEL 365 GTB/4 DAYTONA

LICENSE # 560 - 200978

V.I.N. 560-200978

MILES IN AND UT 0 / 0

H URS IN AND UT /

C L R

SUBT TAL TIRES

ENGINE

I hereby authorize the above named to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft, or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of not more than \_\_\_\_ \$ per day, will be charged unless otherwise agreed to in writing.

Signature: \_\_\_\_\_ Date: \_\_\_\_\_

UNDER WARRANTY

DEP SIT

N CHARGE T THE CUST...

PAY ENT :

\$ 10,000.00

CHECK

\$ 15,000.00

CHECK

SUBT TAL - LAB R \$ 25,475.00

SUBT TAL - PARTS \$ 3,396.42

SUBT TAL TIRES \$ 2,536.33

SUBT TAL - MISCELLANE US \$ 1,738.00

Shop Supply \$ 50.00

Enviromental Fee \$ 45.00

SUBT TAL - THERS \$ 95.00

T TAL TAX \$ 455.80

T TAL SALES \$ 33,696.55

T TAL C LLECTED \$ 25,000.00

AM UNT DUE \$ 8,696.55



RetroSpec Inc  
769 West Battery Street  
San Pedro, CA 90731  
(310) 897-7224  
retrospecla@gmail.com  
retrospec.la

## Invoice #1427

Created: 08/10/2023  
Invoiced: 08/30/2024  
Payment Term: On Receipt  
Payment Due: 08/30/2024  
Service Writer: Tommy Adam

1969 Ferrari 365 GTB/4 Daytona  
VIN: 12923

Daytona				
Description	Price	QTY	HRS	Subtotal
Labor: Install electric power steering system			12	\$1,800.00
Labor: Install Plexi Headlight Cover			1	\$150.00
Labor: Remove calipers and sent out for rebuild. Remove front hubs, inspect, repack bearings. Install new inner seal. Resurface rotors, install rebuilt calipers with new pads. Bleed/flush fluid.			8	\$1,200.00
Part: Michelin XWX 215/70/15	\$499.00	2		\$998.00
Part: Michelin XWX 225-70/15	\$529.00	2		\$1,058.00
Part: Brake Pads Front	\$140.00	1		\$140.00
Part: Brake Pads Rear	\$120.00	1		\$120.00
Part: Front Wheel Seals	\$5.00	2		\$10.00
Subcontract: Rebuilt Brake Calipers. Disassemble, plating, reassemble and bench test.	\$1,200.00			\$1,200.00
Estimated Tax (9.5%): \$220.97			Total: \$6,896.97	

Thank you for your business. Your payment is due upon vehicle pickup.

Signature \_\_\_\_\_

Labor .....	\$3,150.00
Parts .....	\$2,326.00
Subcontracts .....	\$1,200.00
Subtotal .....	\$6,676.00
Tax .....	\$220.97
Grand Total .....	\$6,896.97
Paid to Date .....	(\$6,896.97)

**REMAINING BALANCE \$0.00**

Payments		
8/31/2024	Other	\$6,896.97
Total Payments		\$6,896.97



RetroSpec Inc  
769 West Battery Street  
San Pedro, CA 90731  
(310) 897-7224  
retrospecla@gmail.com  
retrospec.la

Invoice #1393

Created: 04/04/2023  
Invoiced: 04/10/2025  
Payment Term: On Receipt  
Payment Due: 03/06/2025  
Service Writer: Tommy Adam

1969 Ferrari 365 GTB/4 Daytona  
VIN: 12923

Daytona				
Description	Price	QTY	HRS	Subtotal
Labor: Replace fouled spark plugs			2	\$300.00
Labor: Replace engine oil & filter			1.5	\$225.00
Labor: While running engine to check oil level, noticed engine was running hot, fans not turning on. Drained coolant from block and radiator, found no rust or debris. Checked fan switch, found bad connection & repaired. Filled and pressure checked. Ran to operating temp, confirmed correct operation of thermostat and fans			2.5	\$375.00
Part: Spark Plug NGK BPR6ES	\$5.99	12		\$71.88
Part: Oil Filter, B253	\$28.96	2		\$57.92
Part: Motul Classic Engine Oil	\$14.89	17		\$253.13
Part: Coolant 50/50 Mix	\$24.89	4		\$99.56
Part: Power Steering Conversion Kit Deposit	\$4,800.00	1		\$4,800.00
Estimated Tax (10.25%): \$541.46			Total: \$6,723.95	

Thank you for your business. Your payment is due upon vehicle pickup.

Signature \_\_\_\_\_

Labor .....	\$900.00
Parts .....	\$5,282.49
Subtotal .....	\$6,182.49
Tax .....	\$541.46
Grand Total .....	\$6,723.95
Paid to Date .....	(\$6,723.95)

REMAINING BALANCE	\$0.00
-------------------	--------

Payments		
3/6/2025	Other	\$6,723.95
Total Payments		\$6,723.95





RetroSpec Inc  
769 West Battery Street  
San Pedro, CA 90731  
(310) 897-7224  
retrospecla@gmail.com  
retrospec.la

Invoice #1437

Created: 10/06/2023  
Invoiced: 11/02/2023  
Payment Term: On Receipt  
Payment Due: 03/06/2025  
Service Writer: Tommy Adam

1969 Ferrari 365 GTB/4 Daytona  
VIN: 12923

Daytona Service				
Description	Price	QTY	HRS	Subtotal
Labor: Remove rusted exhaust system. Replace with new replacement exhaust including center and rear sections along with new hangers and hardware. Align			7	\$1,050.00
Part: Exhaust Hanger	\$24.85	20		\$497.00
Part: Exhaust Strap Spacer	\$2.85	40		\$114.00
Part: 6x1x35 Bolt	\$1.85	40		\$74.00
Part: Exhaust System 365 GTB4 Daytona Exhaust Euro	\$5,285.00	1		\$5,285.00
Subcontract: Tire mount and balance with new Michelin Tubes	\$600.00			\$600.00
Estimated Tax (9.5%): \$567.15			Total: \$8,187.15	

Thank you for your business. Your payment is due upon vehicle pickup.

Signature \_\_\_\_\_

Labor .....	\$1,050.00
Parts .....	\$5,970.00
Subcontracts .....	\$600.00
Subtotal .....	\$7,620.00
Tax .....	\$567.15
Grand Total .....	\$8,187.15
Paid to Date .....	(\$8,187.15)

REMAINING BALANCE	\$0.00
-------------------	--------

Payments		
3/6/2025	Other	\$8,187.15
Total Payments		\$8,187.15



RetroSpec Inc  
769 West Battery Street  
San Pedro, CA 90731  
(310) 897-7224  
retrospecla@gmail.com  
retrospec.la

## Invoice #1491

Created: 03/01/2024  
Invoiced: 03/20/2025  
Payment Term: On Receipt  
Payment Due: 03/06/2025  
Service Writer: Tommy Adam

1969 Ferrari 365 GTB/4 Daytona  
VIN: 12923

Description	Price	QTY	HRS	Subtotal
Labor: R&R brake booster/ master cylinder assembly. Swap reservoir. Flush/bleed system.			2.5	\$375.00
Part: Ferrari Daytona Brake Booster Assembly, complete with master cylinder	\$2,890.00	1		\$2,890.00
Part: Dot4 Brake Fluid	\$18.99	1		\$18.99
Estimated Tax (9.5%): \$276.35			Total:	\$3,560.34

Thank you for your business. Your payment is due upon vehicle pickup.

Signature \_\_\_\_\_

Labor .....	\$375.00
Parts .....	\$2,908.99
Subtotal .....	\$3,283.99
Tax .....	\$276.35
Grand Total .....	\$3,560.34
Paid to Date .....	(\$3,560.34)

REMAINING BALANCE	\$0.00
-------------------	--------

Payments		
3/9/2024	Other	\$3,560.34
Total Payments		\$3,560.34