

11:01 AM

02/28/17

Accrual Basis

Coachsmithing Sales by Customer Detail All Transactions

| Type | Date | Num | Memo | Name | Item | Qty | Sales Price |
|-------------------|------------|--------|---------------------|------|-------|-----|-------------|
| David Rose | | | | | | | |
| Invoice | 4/23/2010 | 52729A | Ferrari Rebody | | Labor | 1 | 8,000.00 |
| Invoice | 5/27/2010 | 52731A | Ferrari rebod... | | Labor | 1 | 6,500.00 |
| Invoice | 7/27/2010 | 52751A | Aluminum Sh... | | Labor | 1 | 11,478.50 |
| Invoice | 8/27/2010 | 52754A | Frame Repai... | | Labor | 1 | 9,017.88 |
| Invoice | 9/27/2010 | 52759A | Ferrari Chass... | | Labor | 1 | 12,931.27 |
| Invoice | 10/29/2010 | 52764A | Body Sheet ... | | Labor | 1 | 7,634.27 |
| Invoice | 11/27/2010 | 52766A | Ferrari Rebo... | | Labor | 1 | 8,945.87 |
| Invoice | 12/30/2010 | 52768A | Ferrari Under... | | Labor | 1 | 7,230.00 |
| Invoice | 2/1/2011 | 52773A | FERRARI U... | | Labor | 1 | 5,975.83 |
| Invoice | 3/1/2011 | 52776A | FERRARI SU... | | Labor | 1 | 9,058.00 |
| Invoice | 4/3/2011 | 52786A | FERRARI RE... | | Labor | 1 | 7,326.32 |
| Invoice | 6/28/2010 | 52790A | Ferrari Rebo... | | Labor | 1 | 10,000.00 |
| Invoice | 5/1/2011 | 52798A | Aluminum Bo... | | Labor | 1 | 8,384.38 |
| Invoice | 6/5/2011 | 52814A | -Final shaped... | | Labor | 1 | 6,112.77 |
| Invoice | 7/5/2011 | 52829A | * Finished wi... | | Labor | 1 | 8,938.34 |
| Invoice | 8/3/2011 | 52838A | -Adjusted ho... | | Labor | 1 | 10,147.61 |
| Invoice | 9/6/2011 | 52847A | *Dash Board ... | | Labor | 1 | 7,097.64 |
| Invoice | 10/9/2011 | 52850A | -Metal finishe... | | Labor | 1 | 6,055.00 |
| Invoice | 11/12/2011 | 52857A | Ferrari rebo... | | Labor | 1 | 6,000.00 |
| Invoice | 12/19/2011 | 52861A | Ferrari rebody: | | Labor | 1 | 6,074.18 |
| Invoice | 1/16/2012 | 52865A | Ferrari rebody: | | Labor | 1 | 6,025.00 |
| Invoice | 2/17/2012 | 52867A | Ferrari rebody: | | Labor | 1 | 6,275.00 |
| Invoice | 3/12/2012 | 52868A | Ferrari rebody: | | Labor | 1 | 6,000.00 |
| Invoice | 4/22/2012 | 52872A | Ferrari rebody: | | Labor | 1 | 6,153.42 |
| Invoice | 6/3/2012 | 52876A | Ferrari rebody: | | Labor | 1 | 6,037.39 |
| Invoice | 6/22/2012 | 52877A | Ferrari Rebody: | | Labor | 1 | 6,272.69 |
| Invoice | 7/27/2012 | 52880A | Ferrari rebody: | | Labor | 1 | 6,046.00 |
| Invoice | 10/6/2012 | 52885A | Ferrari Rebody: | | Labor | 1 | 6,081.00 |
| Invoice | 11/9/2012 | 52888A | *Ferrari final f... | | Labor | 1 | 6,000.00 |
| Invoice | 12/18/2012 | 52890A | * Ferrari - | | Labor | 1 | 6,031.65 |
| Invoice | 4/5/2013 | 52897A | * Ferrari | | Labor | 1 | 6,718.00 |
| Invoice | 5/9/2013 | 52903A | Ferrari body ... | | Labor | 1 | 7,234.94 |
| Invoice | 6/22/2013 | 52907A | Ferrari rebody: | | Labor | 1 | 6,806.42 |
| Invoice | 8/17/2013 | 52910A | Ferrari Rebody: | | Labor | 1 | 9,274.39 |
| Invoice | 10/16/2013 | 52914A | Ferrari rebody: | | Labor | 1 | 10,697.20 |
| Invoice | 11/29/2013 | 52916A | Ferrari rebody: | | Labor | 1 | 9,531.41 |
| Invoice | 2/1/2014 | 52928A | Ferrari rebody: | | Labor | 1 | 7,967.23 |
| Invoice | 3/7/2014 | 52932A | Ferrari rebody: | | Labor | 1 | 9,092.48 |
| Invoice | 4/18/2014 | 52935A | Ferrari rebody: | | Labor | 1 | 10,394.10 |
| Invoice | 6/14/2014 | 52937A | Ferrari rebody : | | Labor | 1 | 10,827.67 |
| Invoice | 8/6/2014 | 52943A | Ferrari Rebo... | | Labor | 1 | 9,514.29 |
| Invoice | 9/27/2014 | 52948A | Ferrari rebody | | Labor | 1 | 10,478.53 |
| Invoice | 10/31/2014 | 52950A | Ferrari : | | Labor | 1 | 7,671.38 |
| Invoice | 12/22/2014 | 52957A | Ferrari : | | Labor | 1 | 11,398.26 |
| Invoice | 2/21/2015 | 52961A | Ferrari trim a... | | Labor | 1 | 13,227.16 |
| Invoice | 4/8/2015 | 52963A | Ferrari : | | Labor | 1 | 9,399.39 |
| Invoice | 8/14/2015 | 52971A | Ferrari: | | Labor | 1 | 8,157.55 |
| Invoice | 12/22/2015 | 52977A | - Final metal... | | Labor | 1 | 0.00 |
| Invoice | 12/22/2015 | 52981A | -Final metal fi... | | Labor | 1 | 8,361.91 |
| Invoice | 3/26/2016 | 52988A | Ferrari interio... | | Labor | 1 | 8,340.12 |
| Invoice | 6/3/2016 | 52993A | Ferrari interio... | | Labor | 1 | 9,353.06 |
| Invoice | 7/29/2016 | 52995A | Ferrari interio... | | Labor | 1 | 7,109.68 |
| Invoice | 1/3/2017 | 52998A | Ferrari | | Labor | 1 | 5,592.72 |

11:01 AM
02/28/17
Accrual Basis

Coachsmithing
Sales by Customer Detail
All Transactions

| Amount | Balance |
|-------------------|-------------------|
| 8,000.00 | 8,000.00 |
| 6,500.00 | 14,500.00 |
| 11,478.50 | 25,978.50 |
| 9,017.88 | 34,996.38 |
| 12,931.27 | 47,927.65 |
| 7,634.27 | 55,561.92 |
| 8,945.87 | 64,507.79 |
| 7,230.00 | 71,737.79 |
| 5,975.83 | 77,713.62 |
| 9,058.00 | 86,771.62 |
| 7,326.32 | 94,097.94 |
| 10,000.00 | 104,097.94 |
| 8,384.38 | 112,482.32 |
| 6,112.77 | 118,595.09 |
| 8,938.34 | 127,533.43 |
| 10,147.61 | 137,681.04 |
| 7,097.64 | 144,778.68 |
| 6,055.00 | 150,833.68 |
| 6,000.00 | 156,833.68 |
| 6,074.18 | 162,907.86 |
| 6,025.00 | 168,932.86 |
| 6,275.00 | 175,207.86 |
| 6,000.00 | 181,207.86 |
| 6,153.42 | 187,361.28 |
| 6,037.39 | 193,398.67 |
| 6,272.69 | 199,671.36 |
| 6,046.00 | 205,717.36 |
| 6,081.00 | 211,798.36 |
| 6,000.00 | 217,798.36 |
| 6,031.65 | 223,830.01 |
| 6,718.00 | 230,548.01 |
| 7,234.94 | 237,782.95 |
| 6,806.42 | 244,589.37 |
| 9,274.39 | 253,863.76 |
| 10,697.20 | 264,560.96 |
| 9,531.41 | 274,092.37 |
| 7,967.23 | 282,059.60 |
| 9,092.48 | 291,152.08 |
| 10,394.10 | 301,546.18 |
| 10,827.67 | 312,373.85 |
| 9,514.29 | 321,888.14 |
| 10,478.53 | 332,366.67 |
| 7,671.38 | 340,038.05 |
| 11,398.26 | 351,436.31 |
| 13,227.16 | 364,663.47 |
| 9,399.39 | 374,062.86 |
| 8,157.55 | 382,220.41 |
| 0.00 | 382,220.41 |
| 8,361.91 | 390,582.32 |
| 8,340.12 | 398,922.44 |
| 9,353.06 | 408,275.50 |
| 7,109.68 | 415,385.18 |
| 5,592.72 | 420,977.90 |
| 420,977.90 | 420,977.90 |
| 420,977.90 | 420,977.90 |

SERVICE REPAIR ORDER

THE
BOSTON
SPORTSCAR
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 7/31/1999 | 1315 |

PAID
08/24/1999

CUSTOMER NAME & ADDRESS

TEL-(Bus)

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | 5924 FI |


| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|---------|---------|
| Towing | | FLATBED SERVICE CHARGES FROM WESTBORO TO WESTON. | 185.00 | 185.00T |
| Ferrari Labor | 8 | ENGINE DOES NOT RUN ON 12 CYLINDERS AND WILL NOT RESTART. Found open ballast resistor for 1/6 ignition coil. Replace both ignition coils and ballast resistors. Remove distributors and replace ignition points. Adjust phasing of points and set base ignition timing. Replace spark plugs. Adjust carburetors and synchronize as necessary. | 80.00 | 640.00 |
| 100262 | 2 | Ignition Coil | 189.71 | 379.42T |
| 95300289 | 2 | Ignition Rotor | 80.16 | 160.32T |
| 95300084 | 2 | Ignition Points - Long - R2 | 49.17 | 98.34T |
| A4174 | 12 | Spark Plug - N7YC | 3.41 | 40.92T |
| Cust.Disc. | | Discount on Labor | -80.00 | -80.00 |
| Cust.Disc. | | Discount on Parts - 15% | -101.85 | -101.85 |
| | | Sales Tax | 5.00% | 40.27 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Total \$1,362.42

X _____

SERVICE REPAIR ORDER



596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 8/23/1999 | 1334 |

PAID
8/24/1999


| | |
|------------------------------------|-------------------|
| CUSTOMER NAME & ADDRESS | |
| | |
| TEL-(Bus) | TEL-(Home) |

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|--------|----------|
| Ferrari Labor | 20 | VEHICLE DOES NOT STOP WELL AND HAS A LONG BRAKING DISTANCE. Front brake rotors are scored and worn excessively. Remove front wheel hub assemblies and replace front brake rotors. Repack front wheel bearings. Rebuild front brake calipers and replace caliper pistons. Replace front brake hoses. Remove rear brake calipers and rebuild. Replace rear caliper pistons. Replace rear brake hoses. Adjust parking brake. Flush and bleed brake system. | 80.00 | 1,600.00 |
| 6810005 | 2 | Front Brake Rotor | 495.00 | 990.00T |
| 2577000 | 1 | Brake Overhaul Kit | 118.67 | 118.67T |
| 95691104 | 1 | Rear Caliper Repair Kit | 209.40 | 209.40T |
| GDB593AM | 1 | Front Brake Pads | 118.67 | 118.67T |
| 6432611900 | 1 | Rear pads | 83.75 | 83.75T |
| 7404740000 | 2 | Brake Hose | 108.88 | 217.76T |
| 7404740300 | 2 | Brake Hose | 91.60 | 183.20T |
| 106778 | 2 | Seal | 70.54 | 141.08T |
| 64320163 | 2 | Brake Piston 365 2+2 | 163.41 | 326.82T |
| 64325111 | 4 | Brake Piston 365 2+2 | 98.38 | 393.52T |
| 64326017 | 4 | Brake Piston 365 2+2 | 78.62 | 314.48T |
| 64320434 | 2 | Brake Piston 365 2+2 | 153.26 | 306.52T |
| Misc. Fast. | 48 | Nuts, Bolts, Washers, etc. | 0.40 | 19.20T |
| TutelaBF | 2 | Tutela Brake Fluid | 19.64 | 39.28T |

Total

SERVICE REPAIR ORDER



596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 8/23/1999 | 1334 |

PAID
08/24/1999

| | |
|------------------------------------|-------------------|
| CUSTOMER NAME & ADDRESS | |
| | |
| TEL-(Bus) | TEL-(Home) |

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|---------|---------|
| Ferrari Labor | 2 | CHECK FOR ENGINE OVERHEATING. Replace thermostat and radiator cap. | 80.00 | 160.00 |
| 1014992 | 1 | Radiator Cap | 40.08 | 40.08T |
| 95400600 | 1 | Thermostat | 13.36 | 13.36T |
| Cust.Disc. | | Discount on Labor | -220.00 | -220.00 |
| Cust.Disc. | | Discount on Parts - 15% | -527.39 | -527.39 |
| | | Sales Tax | 5.00% | 158.22 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-------------------|
| Total | \$4,686.62 |
|--------------|-------------------|

X _____

SERVICE REPAIR ORDER

THE
BOSTON
SPORTSCAR
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 4/11/2000 | 1568 |

PAID
04/13/2000

CUSTOMER NAME & ADDRESS

TEL-(Bus)

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|--------|---------|
| Towing | 1 | Flatbed Service: Flatbed Service of 365 GT 2+2 from Bolton MA to Weston MA. | 139.00 | 139.00 |
| Ferrari Labor | 9 | VEHICLE WILL NOT START: Starter inop. Remove 1/6 exhaust header. Remove starter and sent out to be rebuilt. Reinstall starter and exhaust manifold. Replace battery which failed load test. | 80.00 | 720.00 |
| MT34R | 1 | Interstate Battery MT-34R | 89.00 | 89.00T |
| RRSpring | 1 | Repair RR Spring | 310.00 | 310.00T |
| Ferrari Labor | 6 | REPLACE BOTH REAR EXHAUST PIPES: R&R both rear tailpipe sections, realign tailpipes and brackets. Replaced exhaust gaskets an 12 exhaust hangers. | 80.00 | 480.00 |
| 101497 | 12 | Exhaust Strap Hanger | 5.00 | 60.00T |
| 147630 | 1 | Gasket Exh Port (ex 10201) | 5.19 | 5.19T |
| 147631 | 1 | Exhaust Port Gasket | 6.27 | 6.27T |
| FE0927 | 1 | Tail Pipe 365 GT 2+2 | 547.50 | 547.50T |
| FE0937 | 1 | Tail Pipe 365 GT 2+2 | 547.50 | 547.50T |
| Misc. Fast. | 12 | Nuts, Bolts, Washers, etc. | 0.40 | 4.80T |

Total

SERVICE REPAIR ORDER

THE
**BOSTON
SPORTSCAR**
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 4/11/2000 | 1568 |

PAID
04/13/2000

CUSTOMER NAME & ADDRESS

TEL-(Bus)

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|--------|-------------|------|-------|-------|---------|----------|
| Ferrai | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |


| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|--|-------|----------|
| Ferrari Labor | 20 | REBUILD REAR SUSPENSION: R&R all four shocks and load levelers. R&R upper and lower A- Arms, stip down and repaint. Install new 8 inner bushings. Clean and relube outer multi metallic bushings. R&R rear sway bar, replace sway bar bushings and sway bar mount bushings. Install new shock absorber bushings. | 80.00 | 1,600.00 |
| 100773 | 2 | Stablizer Bushing | 22.65 | 45.30T |
| 100984 | 4 | Stablizer Bushing | 2.00 | 8.00T |
| 154539 | 8 | Suspension Bushing (Old PN 134883) | 64.13 | 513.04T |
| 100810 | 4 | Bushing Shock | 16.50 | 66.00T |
| 108745 | 2 | Bushing Sway Bar Mount | 34.55 | 69.10T |
| | | Sales Tax | 5.00% | 113.59 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Total \$5,324.29

X _____

SERVICE REPAIR ORDER



596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|----------|----------|
| 5/9/2000 | 1601 |

PAID
5/11/2000

CUSTOMER NAME & ADDRESS

TEL-(Bus) TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|--|-------|----------|
| Ferrari Labor | 6 | REMOVE LEFT AND RIGHT CAM COVERS TO ADJUST VALVE CLEARANCES. Remove both cam covers and found damage to camshafts and rollers because of broken valve adjuster screws. There was also damage to valve stems (mushroomed). Temporarily replaced broken screws and reassemble until customer decides on repairs. | 85.00 | 510.00 |
| Ferrari Labor | 24 | REMOVE ENGINE FROM VEHICLE. Unbolt differential assemble in order to remove gearbox. Remove various accessories and exhaust manifolds. Remove engine from vehicle. | 85.00 | 2,040.00 |
| Ferrari Labor | 20 | DISASSEMBLE ENGINE FOR INSPECTION. Completely disassemble engine. Remove cylinder heads, front cover. Remove pistons and crankshaft. Perform preliminary cleaning of engine block. | 85.00 | 1,700.00 |
| | | Sales Tax | 5.00% | 0.00 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-------------------|
| Total | \$4,250.00 |
|--------------|-------------------|

X _____



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| | |
|-----------|----------|
| DATE | INV. NO. |
| 5/23/2000 | 1616 |

| | | |
|-----------------|------------------|---------------|
| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
| | | |
| | | TELEPHONE NO. |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|------|----------------------------|----------|-----------|
| 4 | Motor Mount | 89.50 | 358.00T |
| 1 | Kit Clutch Pac V12 B&B 275 | 1,250.64 | 1,250.64T |
| 1 | Timing Chain 330/365 | 147.36 | 147.36T |
| 1 | Flywheel Pilot Bearing | 23.38 | 23.38T |
| 1 | Oil Pickup Hose 365 | 9.54 | 9.54T |
| 24 | Bearing Rod STD | 13.78 | 330.72T |
| 1 | Main Bearing Kit 365 | 591.90 | 591.90T |
| 24 | Cam Roller w/ Pins 365 | 57.62 | 1,382.88T |
| 24 | Valve Adjusting Screw | 11.69 | 280.56T |
| 2 | Oil Sending Unit 365 | 13.23 | 26.46T |
| 2 | Head Gasket 365 | 214.60 | 429.20T |
| 24 | Connecting Rod Nuts | 8.70 | 208.80T |
| 2 | Water Pump Bearings 365 | 41.13 | 82.26T |
| | Sales Tax | 5.00% | 256.09 |

The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-------------------|
| Total | \$5,377.79 |
|--------------|-------------------|



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| | |
|-------------|-----------------|
| DATE | INV. NO. |
| 6/23/2000 | 1649 |

| | | |
|------------------------|-------------------------|----------------------|
| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
| | | |
| | | TELEPHONE NO. |
| | | |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|-------------|-----------------------|--------------|--------------|
| 12 | Intake Valve V 12 | 119.89 | 1,438.68T |
| 12 | Exhaust Valve V 12 | 123.33 | 1,479.96T |
| 1 | Valve Spring Set V 12 | 666.67 | 666.67T |
| 24 | Valve Guides 330/365 | 14.78 | 354.72T |
| | Sales Tax | 5.00% | 197.00 |

The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-------------------|
| Total | \$4,137.03 |
|--------------|-------------------|

SERVICE REPAIR ORDER

THE
**BOSTON
SPORTSCAR**
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 6/30/2000 | 1660 |

PAID
07/14/2000

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |


| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|-------|----------|
| Ferrari Labor | 20 | CONTINUATION OF MAJOR ENGINE RESTORATION: Cleaned various disassembled engine parts. Disassembled heads. Removed camshafts. Removed valves. Punched out valve guides. Removed and cleaned all carbon from heads and ports. Cleaned all surfaces on engine block and began scraping of engine block. | 85.00 | 1,700.00 |
| | | Sales Tax | 5.00% | 0.00 |

Total \$1,700.00

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

X _____

SERVICE REPAIR ORDER



596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|----------|----------|
| 9/8/2000 | 1731 |

PAID
9/11/2000

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|--|-------|----------|
| Ferrari Labor | 65 | CONTINUATION OF COMPLETE ENGINE REBUILD: Continued hand scraping of engine block, and straightining of engine block after bolting on and torquing of heads. Completed final straightining of engine block with boring bar. Checked and fitted main caps. Completed truing of block with lapping bar. Completed line boring of block. Checked bearing crush. Corrected cap height as necessary, measured main bearing I.D. Fitted crank and spun. Removed crank and heads for block cleaning. Honed cylinder liners, found three that must be replaced. Removed all cylinder liners from block and cleaned and honed remaining liners. Removed oil gallery plugs from block, soaked block in cleaning solution. Finished cleaning of block after soaking and cleaned all cylinder liner seats in block. Installed valve guides in heads and reamed out valve guides for proper fit with valves. | 85.00 | 5,525.00 |
| | | Sales Tax | 5.00% | 0.00 |

Total \$5,525.00

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

X _____



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| | |
|-------------|-----------------|
| DATE | INV. NO. |
| 10/3/2000 | 1746 |

| | | |
|------------------------|-------------------------|----------------------|
| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
| | | |
| | | TELEPHONE NO. |
| | | |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|-------------|----------------------------------|--------------|--------------|
| 4 | Valve Guides 330/365 | 14.78 | 59.12T |
| 2 | Used Camshaft for 330/365 Engine | 1,166.00 | 2,332.00T |
| 1 | Piston Ring 81mm set 365 2 | 1,282.83 | 1,282.83T |
| 4 | Cyl. Liner, 81, 0mm V12 | 417.00 | 1,668.00T |
| | Sales Tax | 5.00% | 267.10 |

The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Total **\$5,609.05**

SERVICE REPAIR ORDER

THE
**BOSTON
SPORTSCAR**
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|------------|----------|
| 11/17/2000 | 1799 |

PAID
11/18/2000

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|-------|----------|
| Ferrari Labor | 65 | CONTINUATION OF MAJOR ENGINE RESTORATION: Rework cylinder heads, ream guides, check cocentricity of valve contact surfaces. cut valve seats, lapped valves,. assembled heads, with new springs and seals. Test assembly with cams and replaced 4 stripped out cam cap studs. Set ring-end gaps for new piston rings, cleaned all piston ring grooves, and re ringged pistons. Assembled short block. Cleaned out and re threaded all bad threads in front case. Rebuilt chain tensioner. Rebuilt water pump. Extracted splined distributor drive ends from old cams, installed in new camshafts and staked cam end pins. Painted engine block and heads. Painted front cover and engine assembly pieces. Bolted cylinder heads to block, torqued heads, assembled and attached front cover to engine block. | 85.00 | 5,525.00 |
| | | Sales Tax | 5.00% | 0.00 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Total \$5,525.00

X _____



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| DATE | INV. NO. |
|-----------|----------|
| 12/6/2000 | 1817 |

| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
|-----------------|------------------|---------------|
| | | |
| | | TELEPHONE NO. |
| | | |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|------|------------------------------------|----------|-----------|
| 24 | Snap Ring | 1.49 | 35.76T |
| 1 | Gasket, Oil Filter, Hsg. 330/365GT | 5.53 | 5.53T |
| 1 | Gasket with Pump | 5.01 | 5.01T |
| 1 | Lock Tab | 3.09 | 3.09T |
| 1 | Gasket with Pump | 3.76 | 3.76T |
| 1 | O-Ring Seal | 4.01 | 4.01T |
| 1 | Gasket, Chain Tens. Hsg. | 4.01 | 4.01T |
| 5 | Stud, Rocker Stand | 16.25 | 81.25T |
| 1 | Gasket Set 365 2+2 | 1,210.75 | 1,210.75T |
| 8 | Valve Guides 330/365 | 14.78 | 118.24T |
| 1 | Gasket, Submerged F/Pump 53 | 11.21 | 11.21T |
| 18 | Washer | 1.97 | 35.46T |
| 20 | Washer | 2.51 | 50.20T |
| 1 | Oil Seal | 12.44 | 12.44T |
| 1 | Water Pump Spacer | 153.28 | 153.28T |
| 1 | Acorn Nut water pump | 7.14 | 7.14T |
| 1 | Lock Tab | 3.09 | 3.09T |
| 1 | O-ring | 2.00 | 2.00T |
| 4 | Pin | 3.89 | 15.56T |
| 3 | Carb Gasket-DF1 | 5.85 | 17.55T |
| 3 | Accelerator Pumps Carb. | 18.47 | 55.41T |
| 3 | Carburetor washer, fibre 12x18 | 1.34 | 4.02T |
| 3 | Carb Intake Gasket | 2.14 | 6.42T |
| 1 | Seal Ring | 0.82 | 0.82T |
| 7 | Sealing Ring | 1.29 | 9.03T |
| 1 | Waterpump Seal | 86.84 | 86.84T |
| 1 | Oil Pump Screen | 22.98 | 22.98T |

| |
|--------------|
| Total |
|--------------|



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| DATE | INV. NO. |
|-----------|----------|
| 12/6/2000 | 1817 |

| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
|-----------------|------------------|---------------|
| | | |
| | | TELEPHONE NO. |
| | | |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|------|-------------|-------|-------|
| 12 | Lock Ring | 0.70 | 8.40T |
| | Sales Tax | 5.00% | 98.66 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-------------------|
| Total | \$2,071.92 |
|--------------|-------------------|



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| DATE | INV. NO. |
|------------|----------|
| 12/20/2000 | 1831 |

| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
|-----------------|------------------|---------------|
| | | |
| | | TELEPHONE NO. |
| | | |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|------|-------------------------------|--------|---------|
| 2 | Motor and Fan assembly | 339.36 | 678.72T |
| 6 | Exhaust Nuts 365 GT 8x1 mm | 8.40 | 50.40T |
| 2 | Drive Belt 365 GT 2+2 | 38.74 | 77.48T |
| 2 | Drive Belt 365 GT 2+2 | 44.09 | 88.18T |
| 1 | Air Conditioning Belt 11Mx925 | 40.00 | 40.00T |
| | Sales Tax | 5.00% | 46.74 |

The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-----------------|
| Total | \$981.52 |
|--------------|-----------------|

SERVICE REPAIR ORDER

THE
**BOSTON
SPORTSCAR**
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|------------|----------|
| 12/20/2000 | 1832 |

PAID
12/20/2000

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|--|-------|----------|
| Ferrari Labor | 45 | CONTINUATION OF MAJOR ENGINE RESTORATION: Sent out flywheel to machine shop for resurfacing. Bolted flywheel to crankshaft. Installed new head gaskets and cylinder heads for final torqueing to specification. Performed cam timing procedure and adjusted valves. had to retard timing on 1/6 cam to achieve proper timing. Plugged all water outlets, filled block with coolant and pressure tested. Fit gaskets and seals for lower sump, installed oil pick-up tube. Time Serted 2 stripped valve cover studs on 7/12 cylinder head. Replaced all main valve cover studs, as most were bent and not straight. Checked point gaps for both distributors, and properly timed both distributor drive housings to the camshafts. Fitted brackets, spacers and drive accessories to the engine. Trimmed and fitted new valve cover gaskets and installed valve covers. Cleaned entire engine bay and repainted interior surfaces. Reinstalled the engine into vehicle, reinstalled exhaust headers. Sent out radiator to be refurbished. | 85.00 | 3,825.00 |
| Rad Repair | 1 | Radiator Repair: Cleaned and bolied radiator, pressure checked. | 87.50 | 87.50T |

Total

SERVICE REPAIR ORDER



596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|------------|----------|
| 12/20/2000 | 1832 |

PAID
12/20/2000

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|--------------|------|----------------------|-------|-------|
| Misc. Sublet | 1 | Resurfaced Flywheel. | 74.99 | 74.99 |
| | | Sales Tax | 5.00% | 4.38 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Total \$3,991.87

X _____

SERVICE REPAIR ORDER

THE
BOSTON
SPORTSCAR
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 1/25/2001 | 1860 |

PAID
1/25/2001

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|--|-------|----------|
| Ferrari Labor | 46 | <p>COMPLETED MAJOR ENGINE RESTORATION: Engine was previously installed back into vehicle. Installed radiator back in to vehicle. Replaced all coolant hoses and lines to the radiator. Straightened any bent or crushed cooling fins on radiator. Reassembled carburetors and refit onto engine, hooked up throttle linkages and properley adjusted. Reattached main crome fuel rail and checked for fuel leaks. Reinstalled gearbox, torque tube and final drive assembly back in vehicle. Reattached rear driveshafts to final drive.. Replaced engine mounts and mounts for the rear drive assembly. Refilled engine with engine oil, coolant and fresh gearbox oil. Installed all new valve cover acorn nuts, 46 total. Assembled and installed new main yellow fuel line to carbureator fuel rail, including new hose, fittings and connections. Installed new rubber bellows at each end of clutch cable and replaced worn linkage pins, readjusted clutch. Installed new spark plugs and new sets of spark plug wires for each bank of cylinders, also replaced coil wires. Reassembled vehicle</p> | 85.00 | 3,910.00 |

Total

SERVICE REPAIR ORDER

THE
BOSTON
SPORTSCAR
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 1/25/2001 | 1860 |

PAID
01/25/2001

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------|-------------|------|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|------|------|--|-------|-------|
| | | <p>interior including installation of center console, shift lever and dashboard underpanels. Re- Heli Coiled shift knob for proper fit to shifter lever.</p> <p>Installed all four exhaust headers. Rewelded joint at exhaust header and exhaust pipe for seven through nine cylinders. Replaced six broken exhaust hangers. Repainted and reinstalled exhaust header heat shields. Reinstalled hood on vehicle.</p> <p>Performed safety inspection on vehicle. Cleaned and re-oiled horn compressor. Repaired bad electrical connection at rear license plate lights. Refitted crooked oil pressure gauge in dash. Resorted indicator lights on the bottom of the tachometer, including high beam indicator light.</p> <p>Performed basic engine set up. Set final ignition timing. Set mixtures for carburetors. Set idle speeds, final adjustment of throttle linkage. Set idle air flows and balanced carburetors. Set CO mixtures.</p> <p>Recharged air conditioning system. Replaced schrader valves on A/C compressor. Tested system for leaks.</p> | | |

Total

SERVICE REPAIR ORDER

THE
**BOSTON
SPORTSCAR**
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| | |
|-----------|----------|
| DATE | R.O. NO. |
| 1/25/2001 | 1860 |

PAID
01/29/2001

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------------|-------------|--|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 43,011 | |
| ITEM | QTY. | DESCRIPTION | | | PRICE | TOTAL |
| Ferrari Labor | 16 | REPLACED COOLING SYSTEM RADIATOR FANS: Fabricated two bracket sets to properly mount updated cooling fans. Cut steel stock, fabricated brackets and painted. Installed updated fans in brackets and mounted assemblies in vehicle. Road Tested vehicle and checked operation of cooling fans. | | | 85.00 | 1,360.00 |
| | | Sales Tax | | | 5.00% | 0.00 |

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Total \$5,270.00

X _____



Fax: (781) 647-7335
 596 Boston Post Road
 Weston, Mass. 02493

www.bostonsportscar.com

PARTS INVOICE

| | |
|-------------|-----------------|
| DATE | INV. NO. |
| 2/7/2001 | 1875 |

| | | |
|------------------------|-------------------------|----------------------|
| BILLING ADDRESS | SHIPPING ADDRESS | P.O./REF NO. |
| | | |
| | | TELEPHONE NO. |
| | | |

| QTY. | DESCRIPTION | PRICE | TOTAL |
|-------------|----------------------------------|--------------|--------------|
| 2 | Valve Cover Gasket 330/365 | 40.08 | 80.16T |
| 10 | Cam Cover Stud 6x55 | 1.67 | 16.70T |
| 4 | Cam Cover Stud 6x65 | 1.67 | 6.68T |
| 4 | Cam Cover Nut Long | 1.65 | 6.60T |
| 1 | Temp. Switch | 66.80 | 66.80T |
| 1 | Gasket Heater Valve Base | 3.12 | 3.12T |
| 1 | By-pass Hose (was#26694) | 123.45 | 123.45T |
| 2 | Collar 8mm Fuel Line 18mm | 7.10 | 14.20T |
| 2 | Fitting 6*8 Female | 42.69 | 85.38T |
| 12 | Fuel Line Yellow 8mm | 6.10 | 73.20T |
| 2 | Fan Motor/Shroud Assembly | 90.68 | 181.36T |
| 1 | Black Winkle Finish Paint | 26.72 | 26.72T |
| 1 | Radiator Hose | 13.61 | 13.61T |
| 1 | Radiator Hose | 18.24 | 18.24T |
| 44 | Cam Cover Nut Long | 1.65 | 72.60T |
| 4 | Gasoline | 5.00 | 20.00 |
| 8 | Time-Sert | 7.11 | 56.88T |
| 28 | Zebra Hose Clamp | 1.50 | 42.00T |
| 269 | Nuts, Bolts, Washers, etc. | 0.46 | 123.74T |
| 7.5 | Agip Rotra SX 75W90 Gear Oil | 9.08 | 68.10T |
| 10 | Pennzoil GT Perf. Mtr. Oil 20W50 | 3.25 | 32.50T |
| 1.5 | Tutela Brake Fluid | 19.64 | 29.46T |
| 2 | Pennzoil Antifreeze | 11.65 | 23.30T |
| | Sales Tax | 5.00% | 58.24 |

The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

| | |
|--------------|-------------------|
| Total | \$1,243.04 |
|--------------|-------------------|

SERVICE REPAIR ORDER

THE
**BOSTON
SPORTSCAR**
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| DATE | R.O. NO. |
|-----------|----------|
| 3/16/2001 | 1912 |

PAID
3/21/2001

CUSTOMER NAME & ADDRESS

TEL-(Home)

| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
|---------------|-------------|---|-------|-------|---------|----------|
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 45,385 | |
| ITEM | QTY. | DESCRIPTION | | | PRICE | TOTAL |
| Ferrari Labor | 2.25 | HEADLIGHTS INOP: Checked operation of headlights, disassembled headlight switch to check operation of switch contacts. Switch o.k. Traced short in wiring to a corroded connection at fuse box. Cleaned contacts on fuse block and cleaned connections. | | | 85.00 | 191.25 |
| Ferrari Labor | 2.5 | BATTERY DEAD: Recharged battery overnight, Battery passed load test. Tested alternator and charging system. Checked for draw on battery. Found excessive draw, repaired wiring in harness. Draw on battery brought down to 40 milliamps. | | | 85.00 | 212.50 |
| Towing | 1 | Flatbed Service: Vehicle picked up at customer's home in Bolton Mass, and transported to Boston Sportscar in Weston, MA. | | | 174.00 | 174.00 |
| | | Sales Tax | | | 5.00% | 0.00 |

Total \$577.75

I authorize you to perform the above repairs and furnish necessary materials. Your employees may operate the vehicle for inspection, testing and delivery at my risk. BSC is not responsible for articles left in vehicle. The seller hereby disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

X _____

SERVICE REPAIR ORDER

THE
BOSTON
SPORTSCAR
COMPANY

596 Boston Post Road
Weston, MA 02493
tel: (781) 647 - 7300

| | |
|----------|----------|
| DATE | R.O. NO. |
| 9/5/2001 | 3051 |

PAID
9/05/2001

CUSTOMER NAME & ADDRESS

TEL-(Home)

| | | | | | | |
|---------|-------------|------|-------|-------|---------|----------|
| MAKE | MODEL | YEAR | COLOR | VIN | MILEAGE | LIC. NO. |
| Ferrari | 365 GT 2... | 1970 | Red | 13153 | 46,049 | |

| ITEM | QTY. | DESCRIPTION | PRICE | TOTAL |
|---------------|------|---|-------|----------|
| Ferrari Labor | 16 | MINOR SERVICE: Road Tested vehicle. Removed valve covers and scraped heads clean of gasket material, cleaned valve covers. Adjusted valve clearances cold, to Ferrari specification. Repaired oil leak at top of valve cover. Replaced valve cover gaskets and distributor housing o rings. Reassembled vehicle. Checked gearbox oil level. Checked brake fluid level and antifreeze level. Removed spark plugs and replaced with Champion N7YC's. Drive belts making noise. Attempted to tighten alternator belt but travel was limited due to pulley itting power steering assembly. Removed bothe alternators and replaced both alternator belts with smaller sized belt, retensioned and reassembled. Replaced Power steering belts. Changed engine oil and filters. Completely checked over entire vehicle. Road Tested vehicle. | 92.50 | 1,480.00 |
| 160479 | 2 | Valve Cover Gasket 330/365 | 40.08 | 80.16T |
| 101024 | 2 | O-ring | 2.25 | 4.50T |
| 100325 | 2 | Oil Filter - Fram 2804/1 | 24.05 | 48.10T |
| EngOil20W50 | 12 | Pennnzoil GT Perf. Mtr. Oil 20W50 | 3.25 | 39.00T |
| 4174 | 12 | Spark Plug Champion N7YC | 3.51 | 42.12T |
| 127132 | 1 | Belt Alternator | 17.61 | 17.61T |

Total