

10/27/97 MON 14:34

001

# S. K. R E S T O R A T I O N

893A FOLSOM STREET SAN FRANCISCO, CALIFORNIA 94107  
TELEPHONE 415-777-0626 / FACSIMILE 415-777-0627

27 October 1997

## RUF® PERFORMANCE HAUS

P.O. Box 249

Jupiter, Florida 33468

Telephone 561-743-3201 Fax 561-743-3260

Re. **REQUEST FOR QUOTATION**  
**RUF® Speedline Alloy Wheels (17") for 1983 911SC**

In July, you were kind enough to send a package of information about the CTR2 in reply to our inquiry on behalf of one of our customers, Makoto Saito who currently owns a BTR.

You mentioned that you have several sets of 17" RUF® Speedline Alloy Wheels for pre-1990 Porsche 911s. If I recall correctly, you quoted \$500 per wheel (same price for front and rear widths).

Please confirm the following and fax back to 415-777-0627.

ITEM	UNIT PRICE	EXTENSION
1. FRONT WHEELS <u>8</u> " X 17	\$ _____ X 2	} \$ <u>1990</u>
2. REAR WHEELS <u>9</u> " X 17	\$ _____ X 2	
SHIPPING & HANDLING.....	<u>ups ground ins \$98</u>	
NO SALES TAX FOR OUT OF STATE SHIPMENT.....	\$ _____	
TOTAL.....	\$ _____	

*for all 4 with  
with caps*

Please advise if you offer tire/wheel packages. Please call if you have any questions. Thank you.

Sincerely,  
SK Restoration

011980

# Brannan Auto Experts, Inc.

518 Brannan Street • Phone (415) 957-8776  
SAN FRANCISCO, CA 94107

B.A.R. No. AF-140482



Date	3-28-01
Time Received	A.M. P.M.
OPERATION	Lubrication <input type="checkbox"/>
Promised	Change Oil <input type="checkbox"/>
Written By	Change Oil Filter Cart. <input type="checkbox"/>
	Service Air Cleaner <input type="checkbox"/>
	Change Trans. Oil <input type="checkbox"/>
	Adjust Transmission <input type="checkbox"/>
	Hazardous Waste <input type="checkbox"/>
	Pack Front Wheel Brgs. <input type="checkbox"/>
	Rotate Tires <input type="checkbox"/>
	Adjust Brakes <input type="checkbox"/>
	Retain Parts <input type="checkbox"/>
	Destroy Parts <input type="checkbox"/>

Name

Address

Vin. No.

Year/Make/Model

License No.

Odometer

ESTIMATE AMT. *1360*

ADD'L AUTH. AMT.

REVISED ESTIMATE

DATE:

APPROVED BY

Authorized By

TIME:

IN PERSON  PHONE

I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

(SIGNATURE OR INITIALS)

OPER. NO.

REPAIR ORDER LABOR INSTRUCTION

INTERNAL

*Replace Summit VIT*  
*attach CIG receipt to Summit*

*1360*  
*N/A*

Additional Materials from reverse side

TOTAL PARTS

QTY.

SALE

BILLING

TEARDOWN ESTIMATE - PARTS AND LABOR

Total Labor

GALS. GAS

CASH

ORIGINAL ESTIMATES

AUTHORIZED BY

Hazardous Waste Disposal

QTS. OIL

CHARGE

PHONE

DATE

TIME

Special Repairs

LBS. GREASE

INTERNAL

REVISED ESTIMATES

REASON

Parts

TOTAL GAS OIL GREASE

ADDITIONAL COSTS

AUTHORIZED BY

Tires

1.

IN PERSON PHONE #

DATE

TIME

Gas, Oil & Grease

SPECIAL REPAIRS

2.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_\_\_ days of the date shown above if I choose not to authorize the services recommended.

Paint & Body Shop

3.

4.

5.

Sales Tax

TOTAL SPECIAL REPAIRS

TOTAL *1360*

Return Old Parts  Yes  No

OFFICE COPY



**CTI distributing**

# Invoice

CONVERSION TECHNIQUES, INC  
 9845 BIGGE ST. OAKLAND, CA  
 94603  
 Tel: (510)-639-0911

DATE INVOICE #  
 4/14/2000 4042

**BILL TO**

**SHIP TO:**

P.O. NO.	PAYMENT TERMS	CTI REP	SHIP DATE	SHIP VIA	F.O.B.	RECEIVED BY
1980-91...		JS	4/14/2000	UPS GRD	OAKLAND	

QTY	PART NO.	DESCRIPTION	STATUS	YOUR PRICE	AMOUNT
2	PO-PARTS	930 347 313 01 SPACER		12.60	25.20T
2	PO-PARTS	930 347 191 02 BOOT		8.02	16.04T
2	PO-PARTS	930 347 031 01 TIE ROD		86.70	173.40T
1	PO-PARTS	STEERING RACK SPACERS		15.00	15.00T
8	LABOR	INSTALL ADJUSTABLE SPRING PLATES IN REAR. SET RIDE HEIGHT FRONT & REAR		68.00	544.00
1	LABOR	INSTALL STEERING RACK SPACERS, SET BUMP STEER		68.00	68.00
2	LABOR	INSTALL TURBO TIE RODS		68.00	136.00
3	ALN LABOR	4-WHEEL ALIGNMENT		68.00	204.00
2	M/B LABOR	MOUNT/BALANCE LABOR:		20.00	40.00
		CA sales tax		8.25%	18.95

*Pho USA  
 4/14/00 \$ 1,240.59*

*Total* \$1,240.59

ALL RETURNS ARE SUBJECT TO A 20% RESTOCKING FEE + S/H ~ SPECIAL ORDER ITEMS ARE NON REFUNDABLE

**CTI distributing**

CONVERSION TECHNIQUES  
 9845 BiggE St.  
 Oakland, CA 94603-2052

# Invoice

DATE INVOICE #

12/29/200 12096

BILL TO

SHIP TO

P.O. #

TERMS

REP

SHIP DATE

SHIP VIA

F.O.B.

REC'D BY

COD CO. ...

DT

12/29/2000 WILL CA...

OAKLAND

QTY	PART NO.	DESCRIPTION	STATUS	YOUR PRICE	AMOUNT
1	P91134104233	R/S FRONT STRUT, BILSTEIN SHOCK, SUGG RETAIL 670.60		499.00	499.00T
1	P91134104133	L/S FRONT STRUT, BILSTEIN, SUGG RETAIL 670.60		499.00	499.00T
0.4	LABOR	R&R FRONT WHEELS		75.00	30.00
2.4	LABOR	R&R BOTH FRONT STRUTS		75.00	180.00
1.3	ALN LABOR	FRONT WHEEL ALIGNMENT		75.00	97.50
		CA sales tax		8.25%	82.34

*Total***\$1,387.84**

ALL RETURNS SUBJECT TO A 20% RESTOCKING FEE + S/H. NO RETURNS OR REFUNDS ON ELECTRICAL ITEMS, SPECIAL ORDER ITEMS OR ITEMS NOT RETURNED IN ORIGINAL PACKAGING.



GERMANY'S BEST INC.  
 5291 COLLEGE AVENUE  
 OAKLAND  
 (510) 658-8948

CA 94618

R.O.  
 107879

B.A.R. # AG11146

\* ORIGINAL \*

ORIGINAL ESTIMATE \$ 0.00  
 REV# 1 05/25/01 00:00 ..... \$ 0.00  
 REV# 2 05/25/01 00:00 ..... \$ 0.00

YEAR : 80 LICENSE: 1CARMEL  
 MAKE : POR MILEAGE: 64198  
 MODEL: 911SC PR.DATE:  
 VIN.#: 91A0142559  
 ENG #: 3.0

R.O. DATE : 5/25/ 1  
 LABOR/hour : 89.00  
 WRITTEN BY :  
 READY-BY : 5/25/ 1  
 ACCOUNT : PAYMENT: CARD

QTY	PART NUMBER	PART DESCRIPTION	PRICE
1	X 0654	OIL FILTER	0.65
2.0	KENDELL	20/50 MOTOR OIL	37.80
2.0	DP	D P WASHER	1.80
1.0	1-583-386-514	CHECK VALVE	27.20
1.0	MTP-91	BATTERY	108.20

LABOR DESCRIPTION	AMOUNT
HARD START WHEN WARM	
OIL SERVICE	89.00
DIAGNOSED HARD START AS RESIDUAL FUEL PRESSURE LOSS R/R CHECK VALVE AT FUEL PUMP	267.00
CHECK CHARGING SYSTEM FOR DRAW, FOUND 400mA DRAW AT WIRING UNDER DASH CORRECTED WIRING, CHARGED BATTERY. DRAW DOWN TO 30mA REPLACED BATTERY	267.00

All PARTS are new unless otherwise specified

THANK YOU FROM: GERMANY'S BEST INC.

TOTAL LABOR: 623.00

TOTAL PART TOTALS 184.65

SUBLET WORK:

ENVIR PARTS:

CERTIFICATE:

ENVIR. CHG.: 3.20

SHOP SUPPLY:

TOTAL TAX : 14.77

TOTAL R.O. : 825.62

SUBLET

EMISSION WAIVER: I understand that I have the right to have emission service and/or adjustments done elsewhere.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The company is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control.

X AUTHORIZED BY: *PIONEER*

SAVE PARTS

CALLED



GERMANY'S BEST INC.  
 5291 COLLEGE AVENUE  
 OAKLAND  
 (510) 658-8948

R.O.  
 108909

CA 94618

B.A.R. # AG11146

\* ORIGINAL \*

YEAR : 80 LICENSE: 1CARMEL  
 MAKE : POR MILEAGE: 64922  
 MODEL: 911SC PR. DATE:  
 VIN.#: 91A0142559  
 ENG #: 3.0

ORIGINAL ESTIMATE \$ 2,000.00  
 REV# 1 05/01/02 09:39 ..... \$ 3,069.97  
 REV# 2 05/01/02 09:39 ..... \$ 0.00

R.O. DATE : 1/24/ 2  
 LABOR/hour : 95.00  
 WRITTEN BY :  
 READY-BY : 1/24/ 2  
 ACCOUNT : PAYMENT: CARD

QTY	PART NUMBER	PART DESCRIPTION	PRICE
1.0	11-047	OXYGEN SENSOR	116.14
1.0	0C54	OIL FILTER	9.65
1.0	SUMP	SUMP KIT	3.00
1.0	DP	D P WASHER	.90
12.0	KENDBL	20/50 MOTOR OIL	37.80
1.0	477-955-481	WASHER SYS VALVE	3.15
1.0	914-628-433-00	CHECK VALVE "T"	5.12
1.0	0 438-170-031	PUBL ACCUMULATOR	133.00
1.0	911-541-225-03	WINDSHIELD SEAL	62.00
1.0		MOULDING	68.20
2.0		MOULDING CLIP	8.40
1.0	911-541-011-05	WINDSHIELD	788.17
1.0	911-731-035-08	MIRROR GLASS	58.30
1.5	PREON	PREON	108.30

LABOR DESCRIPTION	AMOUNT
OIL LEAKS AS NEC	
O2 SENSOR	47.50
ESTIMATE ON WINDSHIELD REPLACEMENT	
HARD START AFTER WARMED UP	380.00
CAR SITS 2-3 HRS	
R/R FUEL ACCUMULATOR	
NON OP COURTESY LIGHTS	142.50
BY OPENING DOORS	
(HAS OWN DOOR SWITCHES IN PASS DOOR POCKET IF NEC	
REPAIR OPEN CIRCUIT AT FUSE PANEL	
REPLACE SIDE VIEW GASKETS	285.00
SERVICE AC	142.50
R & I REAR SUSP BUSHINGS TO CORRECT SQUEEKING	427.50

ALL PARTS are new unless otherwise specified

THANK YOU FROM: GERMANY'S BEST INC.

WINDSHIELD INSTALLATION  
 SUBLET

EMISSION WAIVER: I understand that I have the right to have emission service and/or adjustments done elsewhere.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The company is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control.

TOTAL LABOR: 1,425.00  
 TOTAL PART : 1,404.13  
 SUBLET WORK: 125.00  
 ENVIR PARTS:  
 CERTIFICATE:  
 ENVIR. CHG.:  
 SHOP SUPPLY:

TOTAL TAX : 115.84  
 TOTAL R.O. : 3,069.97

THANK YOU FOR STOPPING TO  
 GERMANY'S BEST. BUCKLE-UP  
 FOR SAFETY, IT'S THE LAW!



GERMANY'S BEST INC.  
 5291 COLLEGE AVENUE  
 OAKLAND  
 (510) 658-8948

CA 94618 R.O. 11177

B.A.R. # AG11146

\* ORIGINAL \*



YEAR : 80 LICENSE: 1CARMEL  
 MAKE : POR MILEAGE: 66885  
 MODEL: 911SC PR.DATE: 03/80  
 VIN.#: 91A0142559  
 ENG #: 3.0

ORIGINAL ESTIMATE \$ 110.00  
 REV# 1 02/16/04 15:53 PV/WK..... \$ 3,300.00  
 REV# 2 02/17/04 11:48 PV/WK..... \$ 4,600.00

R.O. DATE : 2/16/ 4  
 LABOR/hour : 110.00  
 WRITTEN BY : 01  
 READY-BY : 2/16/ 4  
 ACCOUNT : PAYMENT: CARD

I acknowledge notice and oral approval of an increase in the original estimated price.

QTY	PART NUMBER	PART DESCRIPTION	PRICE
1.0	915-300-911 01	GASKET SET	136.03
1.0	915-302-241 14	GEAR TEETH	163.27
1.0	915-302-242 00	GEAR TEETH	168.73
1.0	930-302-411 02	SHIFTING SLEEVE	219.79
1.0	915-302-301 06	SYNCHRO 1ST	82.77
1.0	915-302-301 04	SYNCHRO 2ND	60.38
3.0	911-302-301 06	SYNCHROS 3RD-5TH	181.14
1.0	928-302-318 02	SYNCHRO BAND	30.57
1.0	915-302-315 01	SYNCHRO ENERGIZE	45.07
1.0	928-302-321 00	ANCHOR BLOCK	10.64
1.0	915-302-401 02	GUIDE SLEEVE	174.25
7.0	90WT	GEAR OIL	35.00
14.0	KENDELL	20/50 MOTOR OIL	52.50
2.0	DP	D P WASHER	1.80
1.0	OC54	OIL FILTER	9.75
1.0		CLUTCH KIT	925.75
1.0	915-116-087 03	GUIDE TUBE	201.54
1.0	999-110-146-00	ROLLER BRG.	203.88
9.0	900.067-090-02	CHEESE HEAD BOLT	32.76
8.0	930-102-206-00	FLYWHEEL BOLT	24.40
2.0	930-107-040-01	OIL RET TUBE,EX	135.80
3.0	930-111-191-13	EX. GASKET	36.00
1.0	930-111-121-10	EX. GASKET	12.95

LABOR DESCRIPTION	AMOUNT
DIAGNOSE NO 2ND GEAR	110.00
R&I ENGINE & TRANSAXLE OVERHAUL TRANSAXLE	1,650.00
MACHINE FINISH DAMAGED REVERSE GEAR	121.00
REPLACE OIL RETURN TUBES ON LEFT SIDE OF MOTOR FOR OIL LEAKS	451.00

ALL PARTS are new unless otherwise specified

THANK YOU FROM: GERMANY'S BEST INC.

SUBLET

EMISSION WAIVER: I understand that I have the right to have emission service and/or adjustments done elsewhere.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. The company is not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond our control.

TOTALS

TOTAL LABOR:	2,332.00
TOTAL PART :	2,944.77
SUBLET WORK:	
ENVIR PARTS:	
CERTIFICATE:	
ENVIR. CHG.:	15.00
SHOP SUPPLY:	
TOTAL TAX :	242.94
TOTAL R.O. :	5,534.71

RECOMMENDED SERVICE

EPA#CAL000060754  
 BUCKLE-UP FOR SAFETY

SAVE PARTS  CALLED



# Germany's Best inc.

5291 College ave  
Oakland, California 94618  
510-658-8948

E-Mail  
Fax #

Our Business hours are 8:am to 5:pm M-F. We accept VISA/MC

R.O. 100402

Page: 1

Monday - Friday 8:am to 5:pm

Date 21 DEC 2004  
Lic. B.A.R. # AG11146  
CAL000060754

Make PORSCHE License 1CARMEL  
Model 911SC Eng. Type 6 CYL  
Miles 0 Eng. No. 3.0  
Vin 91A0142559 Prod.  
Year 80 Sales: 001 Unit  
Cell. # (415) 314-7260 Color: BLU/2

E-Mail/Pager/Remarks/PO:

Open Date 21 DEC 2004 00:00 Ready By: 21 DEC 2004 11:25

### Description of Labor / Service Provided

Hrs. Tech. Amount

OIL SERVICE  
CHECK OIL LEAK FROM RIGHT SIDE OF ENGINE  
SERVICE AS NESS. FOLLOW UP ON RECENT TRANS OVERHAUL

001 495.00

Original Estimate: \$ 550.00 X: \_\_\_\_\_ X: \_\_\_\_\_  
 I acknowledge notice and give oral approval of an increase in the original estimate

Revision #1	.00	Revision #2	.00	Revision #3	.00
Increase	0.00	Increase	0.00	Increase	0.00

I hereby authorize the above named to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of not more than \_\_\_\_\_ \$ per day, will be charged unless otherwise agreed to in writing.

Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Labor	\$ 495.00
Parts	\$ 0.00
Enviromental:	\$ 0.00
Shop Supply	\$ 0.00
Sub Total Charges	\$ 0.00
SubLet	\$ 0.00
Total Sales Tax	\$ 0.00

Total Before Sales Tax \$ 495.00

X: \_\_\_\_\_ Account # 435 Key# SW2  
Payment 1: 0.00 Payment 2: 0.00

**Total Sale \$ 495.00**  
**Total Due \$ 495.00**

Thanks From : Germany's Best inc.



Monday - Friday 8:am to 5:pm

College ave  
**Oakland, California 94618**  
**510-658-8948**

E-Mail  
 Fax #

Our Business hours are 8:am to 5:pm M-F. We accept VISA/MC

Date 24 DEC 2004  
 Lic. B.A.R. # AG11146  
 CAL000060754

Make **PORSCHE**  
 Model **911SC**  
 Miles **68681**  
 Vin **91A0142559**  
 Year **1980** Sales: **001**  
 Cell. # **(415) 314-7260**

License **1CARMEL**  
 Eng. Type **6 CYL**  
 Eng. No. **3.0**  
 Prod. **03/80**  
 Unit  
 Color: **BLU/2**

E-Mail/Pager/Remarks/PO:  
 Open Date 21 DEC 2004 00:00 Ready By: 21 DEC 2004 11:25

Description of Labor / Service Provided	Hrs.	Tech.	Amount
OIL SERVICE CHECK OIL LEAK FROM RIGHT SIDE OF ENGINE SERVICE AS NESS. FOLLOW UP ON RECENT TRANS OVERHAUL		001	495.00

Parts / Material	Description	Qty	Price	Amount
New	GEAR OIL	7.00	5.00	35.00
New	OIL FILTER	1.00	12.50	12.50
New	20/50 MOTOR OIL	11.00	3.75	41.25
New	OIL SUMP KIT	1.00	3.00	3.00
New	DRAIN PLUG WASHER	2.00	0.95	1.90
New	WASHER ADDITIVE	1.00	5.00	5.00
New	OIL RETURN TUBE	2.00	37.50	75.00
New	MARKER LIGHT BULB	1.00	1.75	1.75

Original Estimate: \$ 550.00 X: \_\_\_\_\_ X: \_\_\_\_\_  
 I acknowledge notice and give oral approval of an increase in the original estimate  
 Revision #1 .00 Increase 0.00  
 Revision #2 .00 Increase 0.00  
 Revision #3 .00 Increase 0.00

I hereby authorize the above named to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft, or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of not more than \_\_\_ \$ per day, will be charged unless otherwise agreed to in writing.

Signature: \_\_\_\_\_ Date: \_\_\_\_\_

X: \_\_\_\_\_ Account # 435 Key# SW2  
 Payment 1: VISA 689.88 Payment 2: 0.00

Thanks From : Germany's Best inc.

Labor	\$ 495.00
Parts	\$ 175.40
Enviromental:	\$ 4.13
Shop Supply	\$ 0.00
Sub Total Charges	\$ 4.13
SubLet	\$ 0.00
Total Sales Tax	\$ 15.35
Total Before Sales Tax	\$ 674.53
<b>Total Sale</b>	<b>\$ 689.88</b>
<b>Total Due</b>	<b>\$ 0.00</b>





PORSCHE



Audi

Of Oakland

2345 Broadway  
Oakland, CA 94612  
(510) 893-7282

PORSCHE AUDI OF OAKLAND WILL ACCEPT PARTS FOR REFUND OR EXCHANGE PROVIDED THE PART IS A NORMALLY STOCKED NON-ELECTRICAL OR CARBURETOR PARTS PURCHASED WITHIN 30 DAYS AND IS ACCOMPANIED BY THIS INVOICE. ALL PARTS ACCEPTED FOR RETURN MUST MEET THE MANUFACTURER'S CURRENT PACKAGE GUIDELINES AND ARE SUBJECT TO A 30% RESTOCKING CHARGE. SPECIAL ORDERED ITEMS NOT PICKED UP WITHIN 90 DAYS WILL BE RETURNED TO NORMAL STOCK.

**SUBJECT TO WARRANTY TERMS AND CONDITIONS LISTED ON REVERSE SIDE.**

DATE ENTERED 22 MAY 06	YOUR ORDER NO.	DATE SHIPPED 22 MAY 06	INVOICE DATE 22 MAY 06	INVOICE NUMBER 513624
---------------------------	----------------	---------------------------	---------------------------	--------------------------

S  
O  
L  
D  
  
T  
O

S  
H  
I  
P  
  
T  
O

CODE 11 PAGE 1 OF 1  
COMP CODE:

SHIP VIA	SLSM. 935	B/L NO.	TERMS CASH	F.O.B. POINT OAKLAND CA
----------	--------------	---------	---------------	----------------------------

QTY	SHIP	BIN	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	928-803-126-09	SEAT BELT	228.86	228.86	228.86

**PAID**

CK. NO. V1 #5  
DATE May 22/06  
*my*

*Thank  
You  
For  
Your  
Business*

THANK YOU FOR CHOOSING PORSCHE/AUDI OF OAKLAND. WE TRULY APPRECIATE YOUR BUSINESS. THANK YOU AND HAVE A GREAT DAY.

PARTS	228.86
SUBLET	
FREIGHT	0.00
SALES TAX	0.00
<b>TOTAL</b>	<b>\$228.86</b>

CUSTOMER'S SIGNATURE  
X



5291 College ave  
Oakland, California 94618  
510-658-8948

E-Mail  
Fax #

Our Business hours are 8:am to 5:pm M-F. We accept VISA/MC

Monday - Friday 8:am to 5:pm

Date 6 JUN 2006  
Lic. B.A.R. # AG11146  
CAL000060754

Make **PORSCHE** License **1CARMEL**  
Model **911SC** Eng. Type **6 CYL**  
Miles **72148** Eng. No. **3.0**  
Vin **91A0142559** Prod. **03/80**  
Year **1980** Sales: **001** Unit  
Cell. # **(415) 314-7260** Color: **BLU/2**

E-Mail/Pager/Remarks/PO:  
Open Date 6 JUN 2006 00:00

Fax:  
Ready By: 6 JUN 2006 10:51

Description of Labor / Service Provided	Hrs.	Tech.	Amount
INSTALL FRONT ROTORS AND PADS, REPLACE FRONT HUB SEALS AND REPACK FRONT WHEEL BEARINGS		001	330.00

Parts / Material	Description	Qty	Price	Amount
New	SPORT BRAKE DISC CROSS DRILLED	2.00	175.00	350.00
New	BRAKE PAD	1.00	47.52	47.52
New	SEAL	1.00	13.69	13.69
New	BRAKE CLEANER	1.00	6.50	6.50
New	ANTISQUEAK	1.00	7.50	7.50

Original Estimate: \$ 0.00 X: \_\_\_\_\_ X: \_\_\_\_\_  
I acknowledge notice and give oral approval of an increase in the original estimate

Revision #1	Increase	Revision #2	Increase	Revision #3	Increase
	.00		.00		.00
	0.00		0.00		0.00

I hereby authorize the above named to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft, or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of not more than 30.00\$ per day, will be charged unless otherwise agreed to in writing.

Signature: \_\_\_\_\_ Date: \_\_\_\_\_

X: \_\_\_\_\_ Account # 435 Key# SW2  
Payment 1: VISA 792.42 Payment 2: 0.00

Thanks From : Germany's Best inc.

Labor	\$ 330.00
Parts	\$ 425.21
Enviromental:	\$ 0.00
Shop Supply	\$ 0.00
Sub Total Charges	\$ 0.00
SubLet	\$ 0.00
Total Sales Tax	\$ 37.21
Total Before Sales Tax	\$ 755.21
<b>Total Sale</b>	<b>\$ 792.42</b>
<b>Total Due</b>	<b>\$ 0.00</b>

BAR:AG1955350  
 EPA:CAD982003303  
 Date: 8/1/2008  
 Time: 4:43:39PM

# Brooks Motor Cars

9829 Bigge St.  
 Oakland, CA 94603  
 (510)-632-8901

RO #003592

Final Bill Page 1 of 5

Home:	Make: 1980 Porsche	*Unknown Insurance*
Work:	Model: 911	
Est.: DANIEL KIM	Style: 2D Cpe	
Scheduled: 5/27/2008	License: 1CARMEL	
Arrival: 5/27/2008	Color:	Adjuster: LORI HAZZARD 1-800-
	VIN: 91A0142559	Ins. Co. Phone
	Mileage: 72,512	Claim #: 10000569313
	Hat No.:	Date of Loss:
	Unit No.:	Source: Mitchell UltraMate® EMS

\*\*\* Thank you for coming to our shop for your repairs. \*\*\*

Line	Line Items	Price	Labor	Paint	Other
1	Repl REAR REPLACE BUMPER	437.50 U			
2	LINE MARKUP %25.00				
3	*** END OF ATG SECTION ***				
4	Repl Remanufactured WHEEL	250.00 O	22.50 B		
5	PACIFIC RIMS 1-800-928-6746				
6	Repl MOUNT & BALANCE TIRE	12.00 F			
7	Repl 4 WHEEL ALIGNMENT	80.00 F			
8	R&I R W/SHIELD WIPER BLADE ARM		15.00 B		
9	R&R Time Used in R&I Operation				
10	R&I L W/SHIELD WIPER BLADE ARM		15.00 B		
11	R&R Time Used in R&I Operation				
12	R&I R W/SHIELD WASHER NOZZLE		15.00 B		
13	R&R Time Used in R&I Operation				
14	R&I L W/SHIELD WASHER NOZZLE		15.00 B		
15	R&R Time Used in R&I Operation				
16	Blend L ROCKER PANEL			52.50 R	
17	R&I R ROCKER MOULDING		45.00 B		
18	R&R Time Used in R&I Operation				
19	R&I L ROCKER MOULDING		45.00 B		
20	R&R Time Used in R&I Operation				
21	R&I L FRT DOOR TRIM PANEL		60.00 B		
22	Repr L FRT DOOR SHELL		75.00 B		
23	Refin L FRT DOOR OUTSIDE			165.00 R	
24	R&I L FRT DOOR OUTSIDE HANDLE		75.00 B		
25	R&R Time Used in R&I Operation				
26	R&I L FRT DOOR REAR VIEW MIRROR		112.50 B		
27	R&R Time Used in R&I Operation				
28	Repl L FRT DOOR WEATHERSTRIP	141.31 F	30.00 B		
29	Repl CREST	65.36 F			
30	Repl SEAMSEAL 3 TUBES @ 25.99 EACH	77.96 F	37.50 B		
31	R&I L FRT DOOR BELT MOULDING		30.00 B		
32	R&R Time Used in R&I Operation				
33	Blend ROOF PANEL			75.00 R	
34	R&I SUNROOF SLIDING PANEL		45.00 B		
35	R&R Time Used in R&I Operation				
36	Repl REAR SUNROOF PANEL W/STRIP	21.52 F			
37	Repl FRONT SUNROOF SEAL	57.40 F			



# Brooks Motor Cars

BAR:AG1955350  
 EPA:CAD982003303  
 Date: 8/1/2008  
 Time: 4:43:43PM

9829 Bigge St.  
 Oakland, CA 94603  
 (510)-632-8901

RO #003592

Final Bill Page 2 of 5

Line	Line Items	Price	Labor	Paint	Other
38	R&I HEATED BACK WINDOW GLASS		67.50 G		
39	R&R Time Used in R&I Operation				
40	Blend R QUARTER PANEL OUTSIDE			75.00 R	
41	Repl L QUARTER OUTER PANEL	1,081.88 F	1,590.00 B		
42	Refin L QUARTER PANEL OUTSIDE			157.50 R	
43	Refin L QUARTER PANEL EDGE			37.50 R	
44	Refin L ADD FOR PILLAR			37.50 R	
45	R&I R QTR GLASS MOVEABLE Sublet				65.00 L
46	R&R Time Used in R&I Operation				
47	Repl ENGINE LID EMBLEM	33.78 F			
48	Refin ENGINE LID			135.00 R	
49	Repl ENGINE LID PANEL	1,166.48 F	150.00 B		
50	Refin ENGINE LID UNDERSIDE			82.50 R	
51	R&I L REAR SUSP SHOCK ABSORBER -M		48.00 M		
52	R&R Time Used in R&I Operation				
53	CLEAN & RETAPE EMBLEM		22.50 B		
54	Repl 4 DECALS ON REAR BODYPANEL	60.00 F	30.00 B		
55	R&I ENGINE ASSY -M		480.00 M		
56	Repl W/AIR COND -M		32.00 M		
57	R&I EXHAUST MUFFLER		60.00 B		
58	R&R Time Used in R&I Operation				
59	LOOSEN AND PULL BACK COOLING LINE		37.50 B		
60	ON LEFT FRAME RAIL				
61	Repl OIL FOR REMOVAL OF COOLER AND LINES	96.00 F	22.50 B		
62	APPROX 12 QUARTS @ 8.00 EACH				
63	R&I ENGINE OIL COOLER -M				
64	R&I AIR COND RECEIVER/DRIER -M		56.00 M		
65	Repl EVACUATE & RECHARGE A/C -M		112.00 M		
66	R&R Time Used in R&I Operation				
67	Repl L REAR FRAME SIDEMEMBER -S	858.68 F	1,462.50 B		
68	R&I FUSE PANEL		37.50 B		
69	R&I VOLTAGE BOX		37.50 B		
70	Refin UPR REAR BODY PANEL			45.00 R	
71	Refin LWR REAR BODY PANEL			45.00 R	
72	Repl UPR REAR BODY PANEL	86.88 F			
73	Refin REAR BODY EDGE			37.50 R	
74	Repl REAR BODY PANEL	346.59 F			
75	Repl REAR BODY PANEL REINFORCEMENT	346.59 F	675.00 B		
76	Repl L COMBINATION LAMP LENS	116.09 F	15.00 B		
77	R&I R COMBINATION LAMP REFLECTOR		165.00 B		
78	R&R Time Used in R&I Operation				
79	Repl L COMBINATION LAMP REFLECTOR M 25.00 %	812.50 F	165.00 B		
80	STOCKTON AUTO DISMANTLERS 800-235-8733				
81	LINE MARKUP %25.00				
82	Repl MUFFLER GASKETS 2 @ 17.50 EACH	35.00 F			
83	Repl REAR BODY REFLECTOR	67.47 F			
84	Refin REAR FACE BAR			157.50 R	

BAR:AG1955350  
 EPA:CAD982003303  
 Date: 8/1/2008  
 Time: 4:43:43PM

# Brooks Motor Cars

9829 Bigge St.  
 Oakland, CA 94603  
 (510)-632-8901

RO #003592

Final Bill Page 3 of 5

Line	Line Items	Price	Labor	Paint	Other
85	A-GERMAN AUTO PARTS AND SERVICE 408-993-				
86	Overhaul REAR BUMPER ASSY		187.50 B		
87	Repl L REAR BUMPER GUARD	430.42 F			
88	Repl LICENSE PLATE	10.00 F	15.00 B		
89	FLEX ADDITIVE	7.00 O			
90	WELD THRU PRIMER	12.00 O			
91	FRAME/RACK SET UP		112.50 F		
92	SHEETMETAL PULL		300.00 F		
93	CLEAR COAT			255.00 R	
94	UNDERCOATING		37.50 B		26.00 D
95	RESTORE CORROSION PROTECTION		7.50 B		5.62 D
96	CHIP RESISTANT MATERIAL APPLICATION			15.00 R	10.00 D
97	FINISH SAND AND BUFF			450.00 R	
98	MASK FOR OVERSPRAY			15.00 R	
99	PAINT/MATERIALS				591.60 P
100	HAZARDOUS WASTE DISPOSAL				3.00 Z



BAR:AG1955350  
EPA:CAD982003303  
Date: 8/1/2008  
Time: 4:43:43PM

# Brooks Motor Cars

9829 Bigge St.  
Oakland, CA 94603  
(510)-632-8901

RO #003592

Final Bill Page 4 of 5

Totals	Total \$			
Parts, Foreign (F)	6,003.91			
QUALITY REPLACEMENT (U)	437.50			
Parts, Other (O)	269.00			
<b>Parts Total</b>	<b>6,710.41</b>			
Labor, Body (B)	5,355.00			
Labor, Frame (F)	412.50			
Labor, Glass (G)	67.50			
Labor, Mechanical (M)	728.00			
Labor, Refinish (R)	1,837.50			
<b>Labor Total</b>	<b>8,400.50</b>			
Hazardous Waste (Z)	3.00			
Labor, Misc (D)	41.62			
Paint (P)	591.60			
Sublet Labor (L)	65.00			
<b>Other Total</b>	<b>701.22</b>			
<b>Subtotal</b>	<b>15,812.13</b>			
SALES TAX (Rate =8.750%)	639.19			
<b>Total</b>	<b>16,451.32</b>			
<b>Insurance Total</b>	<b>16,451.32</b>			

BAR:AG1955350  
EPA:CAD982003303  
Date: 8/1/2008  
Time: 4:43:43PM

## Brooks Motor Cars

9829 Bigge St.  
Oakland, CA 94603  
(510)-632-8901

RO #003592

Final Bill Page 5 of 5

All part prices in the Price column that are marked as (D) Domestic or (F) Foreign are new and made by the original equipment manufacturer (OEM). Part prices marked as (A) are aftermarket, new, non-OEM. Part prices marked as (U) are Used. Part prices marked as (O) are Other parts as described. See Totals area for additional price details. Other terms: Repl or R&R = Remove and Replace, O/H = Overhaul, R&I = Remove and Install.

ALL REPLACEMENT PARTS ARE O.E.M. UNLESS OTHERWISE SPECIFIED AS "AFTERMARKET/NEW." YOU ARE HEREBY AUTHORIZED TO MAKE THE ABOVE SPECIFIED REPAIRS: I UNDERSTAND THAT PAYMENT IN FULL WILL BE DUE UPON RELEASE OF VEHICLE, INCLUDING ADDITIONAL SUPPLEMENTAL DAMAGE CHARGES AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES, PERMISSION TO OPERATE THE VEHICLE HERIN DESCRIBED ON STREETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSE OF TESTING OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THRETERO. WE WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. THIS REPAIR ORDER INCLUDES FULL POWER AND AUTHORITY TO SIGN MY NAME TO ALL CHECKS, DRAFTS, OR NEGOTIABLE INSTRUMENTS RELATED TO OR ARISING OUT OF WORK PERFORMED. PARTS PRICES ARE SUBJECT TO INVOICE.

SIGNED X \_\_\_\_\_ DATE \_\_\_\_\_



### Auto Options

1445 San Pablo Ave.  
Berkeley, CA 94702  
Shop Phone: (510) 526-9800

Invoice

7671

Estimate Ref #0  
Date Printed: 01/17/2019  
Printed Time: 4:46 pm  
BAR #ARD133175  
EPA #CAD000057740

Web Address: autooptionstires.com

Hat/Ref: Auto Options Time Promised:

1980 PORSCHE 911 SC H6 3.0L 2999CC FI GAS N

VIN:

License: 1CARMEL

Mileage In: 0

Date Written: 02/03/2017

Unit #:

Mileage Out: 76,903

Written By: Bill

DOM:

Save Old Parts: No

Cell:

Job Name	Description	Technician	Qty	List	Extended
<b>4 Tires</b>	<b>Mount &amp; balance 4 tires</b>				
Part 2254018YMIPSAS3+	225/45-18 92Y Michelin Pilot Sport A/S 3 + 4MK600VX0217 (x 2)		2.00	185.00	370.00
Part 2553518YMIPSAS3+	255/35-18 94Y Michelin Pilot Sport A/S 3 + B9CR02RX3616 B9CR02RX4616		2.00	225.00	450.00
Labor Rate 1	Work Requested - Mount & Balance				110.00
Misc DISP	Work Requested - Tire disposal fee		4.00	3.25	13.00
Misc CRF	Work Requested - Calif. Recycle Fee		4.00	1.75	7.00

Alignment	Align as nec.	
Labor Rate 1	Work Requested - 4 wheel alignment	250.00
Work Performed - L/R & L/R camber is max positive - matched right side to left		

Payment Date	Type	Method	Amount
2/8/2017	Credit		1,027.90
<b>Payment Totals:</b>			<b>\$1,027.90</b>
<i>PR cash</i>			

Parts: \$820.00  
Labor: \$360.00  
Sublet: \$0.00  
Misc: \$20.00  
  
Hazmat: \$0.00  
Supplies: \$0.00

Tax Total: \$75.85  
**Invoice Total: \$1,275.85**  
Less Paid: 1,027.90  
**Balance Due: \$247.95**

Thank you, we appreciate your business.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_



www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 12/05/2018@14:48:20

Model Year:	1980	Make:	PORSCHE	Model:	911 SC
License:	1CARMEL	State:	CA	VIN:	91A0142559
Engine Size:	3.00 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	3000	Cylinders:	6
Odometer:	76,895	Certification:	California	VLT Record #:	13940
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

## Overall Test Results

**Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.**

**Smog Check Certificate Number: HX417346**

**DMV ID Number: 5901X252H419**

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Not applicable	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB05	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

## ASM Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	2480	15.4	0.3	214	40	40	1.36	0.17	0.21	1364	520	559	Pass
25 mph	2402	15.4	0.3	181	31	24	1.16	0.15	0.17	1224	452	447	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

AUTO ROW SMOG  
3060 Broadway Oakland, CA 94611  
5104517664  
Station Number: RC232209

Technician Name/Number: AMBLE, BRIAN/EO045185  
Repair Tech Name/Number:  
Software Version/EIS Number: 1805 / EP729201

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date 12/5/18

Technician's Signature



**ABP REPAIR INC**

Invoice No.

Page 1

BAR #: AH 141375

000021712

Order Date 01/28/19 11:00 am

EPA # CAL 000168351

Completed: 02/04/19 01:44 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

80 PORSCHE 911 BLUE

76924 Mi.

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

**ELECTRICAL**

Labor: \$149.00

CUSTOMER WOULD LIKE WIRING FOR ADDITIONAL CIGARETTE OUTLETS REMOVED FROM UNDER THE DASH. REMOVED AFTER MARKET WIRING, AND INSULATED EXPOSED WIRING THAT WAS TAPPED INTO.

ELECTRICAL	ELECTRICAL-N	1.0 @	5.00 =\$	5.00	5.00
					Job Subtotal: \$154.00

**DRIVERS SIDE MIRROR**

Labor: \$149.00

DRIVERS SIDE MIRROR IS LOOSE. SECURE DRIVERS SIDE MIRROR.

Job Subtotal: \$149.00

**STEERING WHEEL PLAY**

Labor: \$536.40

STEERING WHEEL HAS UP AND DOWN PLAY. CHECK AND ADVISE. INSPECTED AND FOUND THAT THE UPPER STEERING COLUMN BEARING IS WORN. REPLACED DEFECTIVE UPPER AND LOWER STEERING COLUMN BEARINGS.

91134777102	STER/COLUM BEARG UPP-N	1.0 @	65.55 =\$	65.55	
90005203100	STEER/COLUM BEARG LOWE-N	1.0 @	38.47 =\$	38.47	104.02
					Job Subtotal: \$640.42

**IGNITION LOCK CYLINDER**

Labor: \$0.00

IGNITION LOCK CYLINDER DOES NOT TURN EASILY WITH KEY. CHECK AND ADVISE. INSPECTED AND FOUND THAT IF THE KEY IS PUSHED UP SLIGHTLY PRIOR TO TURNING, TURNS EASIER. IN ORDER TO REPAIR COMPLETELY IGNITION LOCK ASSEMBLY WOULD HAVE TO BE REPLACED.

Job Subtotal: \$0.00

**INSPECTION**

Labor: \$0.00

PERFORM INSPECTION OF THE CAR. CAR HAS MOSTLY SAT OVER THE PAST 7 YEARS, DRIVEN OCCASIONALLY.

Job Subtotal: \$0.00

**BRAKE FLUID CHANGE**

Labor: \$149.00

DRAIN BRAKE FLUID FILL AND BLEED SYSTEM

00004430501	-----> BRAKE FLUID-N	2.0 @	23.69 =\$	47.38	47.38
					Job Subtotal: \$196.38

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees the right to enter my car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_

Continued on the next page



**ABP REPAIR INC**

Invoice No.

Page 2

BAR #: AH 141375

000021712

Order Date 01/28/19 11:00 am

EPA # CAL 000168351

Completed: 02/04/19 01:44 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**STERO**

Labor: \$149.00

STERO DOES NOT WORK. CHECK AND ADVISE.

RAN TEST PLAN, TRACED PROBLEM TO A BLOWN FUSE IN THE AMPLIFIER. REPLACED BLOWN FUSE AND TESTED. STERO IS WORKING NOW.

FUSE	FUSE-N	1.0 @	0.77 =\$	0.77	0.77
					Job Subtotal: \$149.77

**HEATER HOSE**

Labor: \$29.80

REPLACED TORN HEATER HOSE FROM THE LEFT HEAT EXCHANGER TO THE ENGINE SHEET METAL.

91121155300	HEATER HOSE 911-N	1.0 @	17.67 =\$	17.67	17.67
					Job Subtotal: \$47.47

**MAJOR SERV 911 78-89 30K**

Labor: \$1,043.00

MAJOR SERVICE 30-60-90000 MILES AS PER MANUFACTURER

REPLACED FAN, AND A/C BELTS.

REPLACED WIPER BLADES.

REPLACED BURNT OUT RIGHT FRONT SIDE MARKER LIGHT BULB.

BOTH HIGH BEAMS ARE OUT, FILAMENTS IN HEADLIGHT BULBS FOR HIGH BEAMS ARE BURNT. REPLACED BOTH HEADLIGHT BULBS.

LICENCE PLATE LIGHT ASSEMBLIES ARE DETERIORATED AND BROKEN. REPLACED BOTH REAR LICENCE PLATE LIGHT ASSEMBLIES.

WASHER SOLVENT	WINDSHIELD WASHER FL.-N	1.0 @	3.00 =\$	3.00	
93010519501	Valve Cover Gasket-N	2.0 @	8.31 =\$	16.62	
93010519404	Valve Cover Gskt. Uppe-N	2.0 @	15.91 =\$	31.82	
90003101430	Valve Cover Washer-N	34.0 @	0.58 =\$	19.72	
90008400403	Valve Cover Nut-N	34.0 @	0.54 =\$	18.36	
93010139101	GASKET SUMP PLATE-N	2.0 @	7.94 =\$	15.88	
90012301120	Oil Drain Plug Gasket-N	1.0 @	0.97 =\$	0.97	
93010776401	OIL FILTER OC 54-N	1.0 @	20.34 =\$	20.34	
WR5DC+	Spark Plug-N	6.0 @	4.46 =\$	26.76	
91111018502	Air Filter 911 LX 261-N	1.0 @	42.17 =\$	42.17	
0450905016	Fuel Filter-N	1.0 @	59.59 =\$	59.59	
194706	20W-50 TOTAL CLASSIC-N	11.0 @	5.50 =\$	60.50	
SWEPCO TRANS OIL	SWEPCO TRANS OIL-N	7.0 @	14.38 =\$	100.66	
CLEANER	PARTS CLEANER-N	1.0 @	5.00 =\$	5.00	
9991921765A	Belt 9.5X710-N	1.0 @	16.00 =\$	16.00	
13X1100	V-Belt 13x1100-N	1.0 @	16.03 =\$	16.03	
40713	Wiper Blade 13"-N	2.0 @	13.35 =\$	26.70	
3893	LIGHT BULB 12V 4W-N	1.0 @	1.68 =\$	1.68	
5008	LIGHT BULB 12V 10W-N	1.0 @	2.26 =\$	2.26	
HELLA H4	HEADLIGHTS H4-N	2.0 @	59.95 =\$	119.90	
91163162004	LICENCE PLATE LIGHT-N	2.0 @	25.39 =\$	50.78	654.74
					Job Subtotal: \$1,697.74

**CAM LINE**

Labor: \$223.50

REPLACED LEAKING RIGHT CAM LINE.

93010734812	Cam Lube Line 84+-N	1.0 @	98.24 =\$	98.24	
-------------	---------------------	-------	-----------	-------	--

-----&gt;-----&gt;-----&gt;-----Continued on the next page-----&gt;-----&gt;-----&gt;-----&gt;



**ABP REPAIR INC**

Invoice No.

Page 3

BAR #: AH 141375

000021712

Order Date 01/28/19 11:00 am

EPA # CAL 000168351

Completed: 02/04/19 01:44 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**CAM LINE**

CLEANER	PARTS CLEANER-N	1.0 @	5.00 =\$	5.00	103.24
---------	-----------------	-------	----------	------	--------

Job Subtotal: \$326.74

**DECK LID SHOCK**

Labor: \$29.80

REPLACED WORN DECK LID SHOCK.

91151233102	HOOD SHOCK REAR 911-N	1.0 @	32.66 =\$	32.66	32.66
-------------	-----------------------	-------	-----------	-------	-------

Job Subtotal: \$62.46

**POWER ANTENNA**

Labor: \$149.00

REPLACED FAULTY POWER ANTENNA.

91164503306	Power Antenna-N	1.0 @	126.36 =\$	126.36	126.36
-------------	-----------------	-------	------------	--------	--------

Job Subtotal: \$275.36

**Payments to ABP REPAIR INC****Cost Summary**

Status: Completed Work Order

Labor 2607.50

Parts 1091.84

Haz Waste 18.00

Tax 101.00

Total \$3818.34

Payments 0.00

Bal Due 3818.34

Payments:

Thank you for choosing ABP REPAIR INC

# Uptown Body & Fender

Taking out life's little wrinkles, one car at a time.  
 401 26th Street, Oakland, CA 94612  
 Phone: (510) 251-8009  
 FAX: (510) 251-0605

Workfile ID: de358b95  
 State EPA: CAL000434559  
 BAR: AB165372

## Final Bill

**RO Number: 64260**

Customer:	Insurance:	Adjuster:	Estimator: Steve Villa
		Phone:	Create Date: 2/11/2019
		Claim:	
		Loss Date:	
		Deductible:	

1980 GENERIC CAR 2D CPE BLUE

VIN: 91A0142559	Interior Color: BLACK	Mileage In: 76,944	Vehicle Out: 3/1/2019
License: 1CARMEL	Exterior Color: BLUE	Mileage Out: 76,945	
State: CA	Production Date:	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor \$	Type	Paint
1	E01	Remove/Install	FRONT BUMPER LOWER SPOILER 2 PIECE				225.00	Body	
2	E01	Repair	STRIP 2 PIECE SPOILER AND REFINISH 2 PIECE				225.00	Body	180.00
3	E01	Refinish	2 STAGE						72.00
4	E01	Sublet	Hazardous waste removal	1	3.50	Other			
5	E01	Remove/Replace	Flex additive	1	5.00T	Other			
6	E01		Color tint				45.00	Body	
7	E01	Remove/Replace	Misc clips	1	10.00T	Other			

Estimate Totals	Discount \$	Markup \$	Rate \$	Total \$
Parts				15.00
Sublet/Miscellaneous				3.50
Labor, Body			90.00	495.00
Labor, Refinish			90.00	252.00
Material, Paint				131.60
<b>Subtotal</b>				<b>897.10</b>
Sales Tax				13.56
<b>Grand Total</b>				<b>910.66</b>
<b>Net Total</b>				<b>910.66</b>

Estimate Version	Total \$
Original	910.66

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



Final Bill

RC Number: 64260

1980 GENERIC CAR 2D CPE BLUE

Insurance Total \$:	910.66
Received from Insurance \$:	0.00
<hr/> Balance due from Insurance \$:	<hr/> 910.66
Customer Total \$:	0.00
Received from Customer \$:	0.00
<hr/> Balance due from Customer \$:	<hr/> 0.00

REPAIR AUTHORIZATION

I hereby authorize the above work to be performed and grant permission to operate this vehicle on city streets and elsewhere for the purpose of road testing. I acknowledge your right to a mechanic's lien and I authorize you to retain possession of this vehicle until all work that is performed is paid in full. I will not hold Uptown Body & Fender or its agents for loss or personal damage to personal property left in the vehicle in case of fire, theft or any circumstance beyond your control. I acknowledge that the Estimate is based on a SURFACE INSPECTION and ESTIMATED prices for parts / sublet labor, etc., therefore may be subject to supplementation. I hereby authorize Uptown Body & Fender to be my sole representative in any insurance claims settlement negotiations regarding the safe and complete restoration of this vehicle to pre-accident condition.

I also acknowledge that any damaged parts removed from the car will not be saved unless I instruct the shop to do so in writing prior to commencement of work. I further acknowledge that removal of any damaged parts from the vehicle will preclude the reinstallation of those parts.

LIMITED POWER OF ATTORNEY

That the undersigned does hereby constitute and appoint Uptown Body & Fender my true and lawful Attorney to sign name, place and stead of the undersigned on any insurance check or drafts issued by \_\_\_\_\_ (Insurance Company) covering any repairs to my automobile authorized by myself in whatever manner is necessary to place or draft in a cashable position. I hereby approve and confirm whatever action said attorney shall or may take by virtue hereof in these premises.

Authorized by: \_\_\_\_\_ Date: \_\_\_\_\_

To approve repairs please reply to email of origin or fax back signed document to 510-251-0605.  
Thank you.

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

**ABP REPAIR INC**

Invoice No.

Page 1

BAR #: AH 141375

000022073

Order Date 09/11/19 08:53 am

EPA # CAL 000168351

Completed: 09/11/19 12:30 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

80 PORSCHE 911 BLUE

76924 Mi. Last in 1/28/2019

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

Quotes

1 09/11/19 05:11pm 314.29

SCOTT in person.

**BATTERY**

Labor: \$74.50

REPLACE BATTERY. BATTERY HOLD DOWN CLAMP WAS MISSING, INSTALLED NEW BATTERY HOLD DOWN CLAMP.

MTP-H8	BATTERY-N	1.0 @	203.72 =\$	203.72	
91161120900	BATTERY HOLD DOWN CLAMP-N	1.0 @	15.77 =\$	15.77	219.49
					Job Subtotal: \$293.99

**Payments to ABP REPAIR INC****Cost Summary**

Status: Completed Work Order

Labor	74.50
Parts	219.49
Tax	20.30
Total	\$314.29
Payments	0.00
Bal Due	314.29

Payments:

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_





www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 09/16/2019@09:59:30

Model Year: 1980	Make: PORSCHE	Model: 911 SC
License: 1CARMEL	State: CA	VIN: 91A0142559
Engine Size: 3.00 L	Type: Passenger Car	Transmission: Manual
GVWR: N/A	Test Weight: 3000	Cylinders: 6
Odometer: 77,176	Certification: California	VLT Record #: 13940
Fuel Type: Gasoline	Exhaust: Single	Inspection Reason: Change of Ownership

## Overall Test Results

**Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.**

**Smog Check Certificate Number: IH111086**

**DMV ID Number: 5363H3561769**

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Not applicable	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB05	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

## ASM Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	1539	14.6	0.0	214	40	32	1.36	0.17	0.19	1364	520	415	Pass
25 mph	2420	14.5	0.1	181	31	26	1.16	0.15	0.18	1224	452	316	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

TEST ONLY SMOG STATION II  
5200 Telegraph Ave, Oakland, Ca 94609  
(510)653-8646  
Station Number: TC236306

Technician Name/Number: ORTIZ, JEFFREY/EO638354  
Repair Tech Name/Number:  
Software Version/EIS Number: 1805 / EP729366

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date

Technician's Signature

**ABP REPAIR INC**

Invoice No.

Page 1

BAR #: AH 141375

000022143

Order Date 10/16/19 09:56 am

EPA # CAL 000168351

Completed: 10/21/19 08:40 am

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**80 PORSCHE 911 BLUE**

77184 Mi. Last in 9/11/2019

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

**STARTING ISSUE**

Labor: \$894.00

CUSTOMER STATED THAT INTERMITTENTLY WHEN TURNING THE KEY TO START THE ENGINE, CUSTOMER JUST HEARS A CLICK. THEN IF THE KEY IS CYCLED OFF, AND TURNED TO START AGAIN, ENGINE CRANKS OVER AND STARTS FINE, HAS NEVER LEFT HIM STRANDED. POSSIBLE PROBLEM WITH THE STARTER OR STARTING SYSTEM? CHECK AND ADVISE.

TESTED THE CAR, GOT THE PROBLEM TO DUPLICATE ONCE, WHILE TURNING THE KEY VERY SLOWLY. SUSPICIOUS OF A PROBLEM WITH HE IGNITION SWITCH.

REPLACED THE ELECTRICAL PORTION OF THE IGNITION SWITCH, AND TESTED THE CAR SEVERAL TIMES, PROBLEM IS STILL OCCURING. PROBLEM IS IN THE STARTER.

REPLACED THE STARTER WITH A REBUILT STARTER AS PER CUSTOMER REQUEST. NO WARRANTY ON LABOR FOR A REBUILT STARTER.

TESTED CAR SEVERAL TIMES AFTER REPLACING THE STARTER. PROBLEM DID NOT OCCUR AGAIN.

96461301200	IGNITION SWITCH-N	1.0 @	161.70 =\$	161.70	
911604101BX	Starter Reb.-N	1.0 @	506.11 =\$	506.11	667.81
					Job Subtotal: \$1,561.81

**Payments to ABP REPAIR INC****Cost Summary**

Status: Completed Work Order

Labor 894.00

Parts 667.81

Tax 61.77

Total \$1623.58

Payments 0.00

Bal Due 1623.58

Payments:

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_





www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 12/05/2018@14:48:20

Model Year:	1980	Make:	PORSCHE	Model:	911 SC
License:	1CARMEL	State:	CA	VIN:	91A0142559
Engine Size:	3.00 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	3000	Cylinders:	6
Odometer:	76,895	Certification:	California	VLT Record #:	13940
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

## Overall Test Results

Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.

Smog Check Certificate Number: HX417346

DMV ID Number: 5901X252H419

Your Smog Check certificate has been electronically transmitted to DMV.

Your certificate is valid for 90 days from date of issuance.

Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Not applicable	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PB05	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

## ASM Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	2480	15.4	0.3	214	40	40	1.36	0.17	0.21	1364	520	559	Pass
25 mph	2402	15.4	0.3	181	31	24	1.16	0.15	0.17	1224	452	447	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

AUTO ROW SMOG  
 3060 Broadway Oakland, CA 94611  
 5104517664  
 Station Number: RC232209

Technician Name/Number:  
 Repair Tech Name/Number:  
 Software Version/EIS Number:

AMBLE, BRIAN/EO045185  
 1805 / EP729201

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date 12/5/18

\_\_\_\_\_  
Technician's Signature

**Auto Options**

1445 San Pablo Ave.  
 Berkeley, CA 94702  
 Shop Phone: (510) 526-9800

Invoice

12098

Estimate Ref #0  
 Date Printed: 12/18/2019  
 Printed Time: 5:33 pm  
 BAR #ARD133175  
 EPA #CAD000057740

Web Address: autooptionstires.com

Hat/Ref:

Auto Options

Time Promised:

1980 PORSCHE 911 SC H6 3.0L 2999CC FI GAS N

VIN:

License: 1CARMEL

Mileage In: 0

Date Written: 12/18/2019

Unit #:

Mileage Out: 77,345

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Wheel Repair	Repair Wheel				
Labor Rate 1	Work Requested - Check for leak in 2 front tires, repair as nec.				250.00
Work Performed - Cleaned and sealed bead area of all 4 wheels					

Payment Date	Type	Method	Amount
<b>Payment Totals:</b>			

Parts: \$0.00  
 Labor: \$250.00  
 Sublet: \$0.00  
 Misc: \$0.00  
 Hazmat: \$0.00  
 Supplies: \$0.00

Tax Total: \$0.00  
**Invoice Total: \$250.00**

Thank you, we appreciate your business.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By \_\_\_\_\_

Date \_\_\_\_\_

Time \_\_\_\_\_



**ABP REPAIR INC**

Invoice No.  
**000022909**

BAR #: AH 141375  
EPA # CAL 000168351  
1009 7th Street  
Oakland, CA 94607  
Phone: 510-834-2772 FAX: 510-834-2776

Order Date 03/17/21 09:22 am  
Paid: 03/17/21 04:45 pm

**80 PORSCHE 911 BLUE**  
78648 Mi. Last in 10/16/2019  
Lic: 1CARMEL/CA H6Cyl 3.0  
Vin: 91A0142559  
Eq: AC FI

Quotes  
1 03/17/21 04:46pm 342.45  
SCOTT in person.

**TEST BATTERY** **Labor: \$169.00**

CHARGED BATTERY. BATTERY TOOK A BETTER PART OF THE DAY TO FULLY CHARGED. TESTED BATTERY, BATTERY PASSED LOAD TEST. TESTED CHARGING SYSTEM, CHARGING SYSTEM IS WORKING CORRECTLY. FISHED OUT BATTERY TERMINAL CAP WHICH HAD FALLEN BEHIND THE BATTERY.

Job Subtotal: \$169.00

**DOME LIGHT** **Labor: \$50.70**

REPLACED DRIVERS SIDE DOME LIGHT.

90163210128 Interior Light-N 1.0 @ 112.36 =\$ 112.36 112.36

Job Subtotal: \$163.06

Recommendations: \*MAJOR SERVICE\*

**Payments to ABP REPAIR INC** **Cost Summary**

Status: Paid Work Order	Labor	219.70
Payments: \$342.45	Parts	112.36
1 03/17/21 342.45 Visa	Tax	10.39
	Total	\$342.45
	Payments	342.45
	Bal Due	0.00

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_

**ABP REPAIR INC**

Invoice No.

Page 1

BAR #: AH 141375

000023234

Order Date 10/11/21 10:51 am

EPA # CAL 000168351

Paid: 10/11/21 03:09 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**80 PORSCHE 911 BLUE**

79718 Mi. Last in 3/17/2021

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

**Quotes**

1 10/11/21 03:05pm 545.19

SCOTT in person.

**NO START****Labor: \$283.50**

CUSTOMER STATED THAT THE ENGINE STARTED, AND BACK FIRED, THEN DIED, AFTER THAT ENGINE CRANKS BUT WILL NOT START. CHECK AND ADVISE.

INSPECTED AND FOUND THAT THE POP OFF VALVE HAD BLOWN OUT OF THE AIR BOX. EPOXIED POP OFF VALVE BACK INTO THE AIR BOX, AND LET CURE.

ADJUSTED FAN BELT TENSION.

TESTED CAR, ENGINE IS STARTING CORRECTLY NOW.

37513	LOCTITE EPOXY CUP-N	1.0 @	2.80 =\$	2.80	2.80
					<b>Job Subtotal: \$286.30</b>

**OIL+FILTERS 911 74-89****Labor: \$132.50**

CHANGE ENG OIL AND FILTERS, VISUAL INSPECTION OF CAR, CHECK LIGHTS AND WIPERS, SET TIRE PRESSURE.

93010776401	OIL FILTER OC 54-N	1.0 @	20.34 =\$	20.34	
90012301120	Oil Drain Plug Gasket-N	1.0 @	0.97 =\$	0.97	
194706	20W-50 TOTAL CLASSIC-N	11.0 @	6.99 =\$	76.89	
CLEANER	PARTS CLEANER-N	1.0 @	7.29 =\$	7.29	105.49
					<b>Job Subtotal: \$237.79</b>

Recommendations: \*MAJOR SERVICE\*

**Payments to ABP REPAIR INC****Cost Summary**

Status: Paid Work Order

Payments: \$545.19

1 10/11/21 545.19 Visa

Labor	415.80
Parts	108.29
Haz Waste	10.00
Tax	11.10
<b>Total</b>	<b>\$545.19</b>
Payments	545.19
Bal Due	0.00

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_



**ABP REPAIR INC**

Invoice No.

Page 1

BAR #: AH 141375

000023311

Order Date 11/30/21 11:41 am

EPA # CAL 000168351

Paid: 11/30/21 12:36 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**80 PORSCHE 911 BLUE**

79755 Mi. Last in 10/11/2021

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

**OIL LEAK**

Labor: \$1,701.00

REMOVED ENGINE AND TRANSMISSION, REPLACED LEAKING OIL PRESSURE SWITCH, AND THERMOSTAT O-RING. CLEANED AREA. REPLACED WORN BELL CRANK BUSHINGS. REPLACED LEAKING OIL LINES FROM THE EXTERNAL OIL THERMOSTAT TO THE OIL RESERVOIR, AND TO THE ENGINE. REPLACED HARD AND BRITTLE "S" HOSE FROM THE ENGINE OIL COOLER TO THE OIL RESERVOIR. REPLACED SUMP PLATE GASKETS, AND WASHERS. REPLACED OIL FILTER, FILLED ENGINE WITH FRESH OIL.

91160623000	Oil Pressure Switch-N	1.0 @	25.14 =\$	25.14
99970731440	THERMOSTAT O-RING-N	1.0 @	4.61 =\$	4.61
90142325300	Bushing-N	2.0 @	4.82 =\$	9.64
91110773013	OIL HOSE 911 RES-THERM-N	1.0 @	231.03 =\$	231.03
91110774312	HOSE OIL THERM 911SC-N	1.0 @	239.74 =\$	239.74
91110723300	OIL RES HOSE-N	1.0 @	72.32 =\$	72.32
93010139101	GASKET SUMP PLATE-N	2.0 @	7.94 =\$	15.88
90003101130	ALUMINUM WASHER-N	12.0 @	1.08 =\$	12.96
90012301120	Oil Drain Plug Gasket-N	2.0 @	0.97 =\$	1.94
93010776401	OIL FILTER OC 54-N	1.0 @	20.34 =\$	20.34
194706	20W-50 TOTAL CLASSIC-N	12.0 @	6.99 =\$	83.88
CLEANER	PARTS CLEANER-N	2.0 @	7.29 =\$	14.58
				732.06
Job Subtotal:				\$2,433.06

**CLUTCH**

Labor: \$189.00

WHILE THE ENGINE AND TRANSMISSION WAS REMOVED, INSPECTED CLUTCH, CLUTCH IS WORN, AND SHOULD BE REPLACED.

REMOVED FLYWHEEL AND SENT OUT TO BE SURFACED. REPLACED THE REAR MAIN SEAL. INSTALLED SURFACED FLYWHEEL. INSTALLED NEW PILOT BEARING. INSTALLED NEW CLUTCH KIT CONSISTING OF A CLUTCH DISC, PRESSURE PLATE, AND THROW OUT BEARING. REPLACED THROW OUT BEARING GUIDE TUBE, GUIDE TUBE O-RING, GUIDE TUBE BOLTS, AND TRANSMISSION MAIN SHAFT SEAL. CLEANED AREA.

99911342641	Rear Main Seal-N	1.0 @	44.85 =\$	44.85
93010204200	CLUTCH PILOT BEARING-N	1.0 @	60.40 =\$	60.40
91511691100	Clutch Kit-N	1.0 @	920.95 =\$	920.95
91511608706	Guide Tube-N	1.0 @	162.74 =\$	162.74
99970135940	SEAL GUIDE TUBE 915-N	1.0 @	7.78 =\$	7.78
99927007001	BOLT, GUIDE TUBE-N	2.0 @	2.90 =\$	5.80
99911332740	Oil Seal-N	1.0 @	19.46 =\$	19.46
CLEANER	PARTS CLEANER-N	1.0 @	7.29 =\$	7.29
				1229.27
Job Subtotal:				\$1,418.27

**SURFACE>FLYWHEEL->---Continued on the next page--->----Sublet:>\$135.00>**

SURFACE FLYWHEEL TO SPEC to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_

**ABP REPAIR INC**

Invoice No.

Page 2

BAR #: AH 141375

000023311

Order Date 11/30/21 11:41 am

EPA # CAL 000168351

Paid: 11/30/21 12:36 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**SURFACE FLYWHEEL****ENGINE INSULATION MAT**

Labor: \$189.00

WHILE ENGINE AND TRANSMISSION WERE REMOVED REPLACED DETERIORATING ENGINE INSULATION MAT.  
REPLACED WORN REAR DECK LID SHOCK.

91155689101	ENG INSULATION PAD-N	1.0 @	90.22 =\$	90.22	
2383478	SPRAY ADHESIVE-N	1.0 @	8.49 =\$	8.49	
91151233102	HOOD SHOCK REAR 911-N	1.0 @	31.35 =\$	31.35	130.06
					Job Subtotal: \$319.06

Recommendations: \*MAJOR SERVICE\*

**Payments to ABP REPAIR INC****Cost Summary**

Status: Paid Work Order

Payments: \$4,529.76

1 11/30/21 4529.76 Visa

Labor	2079.00
Parts	2091.39
Sublet	135.00
Haz Waste	10.00
Tax	214.37
Total	\$4529.76
Payments	4529.76
Bal Due	0.00

Thank you for choosing ABP REPAIR INC



**ABP REPAIR INC**

Invoice No.

BAR #: AH 141375

000023914

Order Date 02/27/23 10:22 am

EPA # CAL 000168351

Paid: 02/27/23 03:23 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**80 PORSCHE 911 BLUE**

81028 Mi.Last in 11/30/2021

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

**Quotes**

1 02/27/23 03:22pm 455.62

SCOTT in person.

**RUNNING ROUGH**

Labor: \$189.00

CUSTOMER STATED THAT THE ENGINE IS RUNNING ROUGH, NOTICED AT IDLE. CHECK AND ADVISE. TESTED CAR, VERIFIED COMPLAINT. RAN TEST PLAN, FOUND CRACKED VACUUM HOSE THE VACUUM UNIT AT THE DISTRIBUTOR. REPAIRED VACUUM LEAK, AND SET CO%. ENGINE IS RUNNING MUCH SMOOTHER NOW.

Job Subtotal: \$189.00

**OIL+FILTERS 911 74-89**

Labor: \$132.30

CHANGE ENG OIL AND FILTERS, VISUAL INSPECTION OF CAR,CHECK LIGHTS AND WIPERS, SET TIRE PRESSURE.

93010776401	OIL FILTER OC 54-N	1.0 @	20.34 =\$	20.34	
90012301120	Oil Drain Plug Gasket-N	1.0 @	0.97 =\$	0.97	
194706	20W-50 TOTAL CLASSIC-N	10.0 @	7.99 =\$	79.90	
05050	PARTS CLEANER-N	1.0 @	11.55 =\$	11.55	112.76

Job Subtotal: \$245.06

Recommendations: \*MAJOR SERVICE\*

**Payments to ABP REPAIR INC**

**Cost Summary**

Status: Paid Work Order

Labor 321.30

Payments: \$455.62

Parts 112.76

1 02/27/23 455.62 Visa

Haz Waste 10.00

Tax 11.56

Total \$455.62

Payments 455.62

Bal Due 0.00

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_



www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 12/19/2024@14:49:51

Model Year:	1980	Make:	PORSCHE	Model:	911 SC
License:	1CARMEL	State:	CA	VIN:	91A0142559
Engine Size:	3.00 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	3000	Cylinders:	6
Odometer:	82,641	Certification:	California	VLT Record #:	13940
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	High Emitter Profile

## Overall Test Results

**Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.**

**Smog Check Certificate Number: UG757762**

**DMV ID Number: 5342G953U229**

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Pass	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Not applicable	Air Injection	Not applicable	OBD System Checks
Not applicable	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PA05	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

## ASM Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	2506	15.2	0.2	214	40	12	1.36	0.17	0.15	1364	520	306	Pass
25 mph	2356	15.2	0.2	181	31	11	1.16	0.15	0.15	1224	452	287	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

SAN PABLO SMOG TEST ONLY CENTER  
6305 San Pablo Ave  
(510) 655-1888  
Station Number: TC270621

Technician Name/Number:  
Repair Tech Name/Number:  
Software Version/EIS Number:

SAE PHAN, KAO/EO639899  
2402 / EP525942

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

12-19-24  
Date

Technician's Signature



**ABP REPAIR INC**

Invoice No.

Page 1

BAR #: ARD00306268

000024670

Order Date 10/03/24 09:30 am

EPA # CAL000432920

Paid: 10/03/24 01:04 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

80 PORSCHE 911 BLUE  
 82531 Mi. Last in 2/27/2023  
 Lic: 1CARMEL/CA H6Cyl 3.0  
 Vin: 91A0142559  
 Eq: AC FI

Quotes

1 10/03/24 01:04pm 336.67  
 SCOTT in person.

**OIL+FILTERS 911 74-89****Labor: \$156.80**

CHANGE ENG OIL AND FILTERS, VISUAL INSPECTION OF CAR,CHECK LIGHTS AND  
 WIPERS, SET TIRE PRESSURE.

93010776401	OIL FILTER OC 54-N	1.0 @	20.34 =\$	20.34	
90012301120	Oil Drain Plug Gasket-N	1.0 @	0.97 =\$	0.97	
06147	CASTROL GTX 20W50-N	11.0 @	11.02 =\$	121.22	
CLEANER	PARTS CLEANER-N	1.0 @	11.55 =\$	11.55	154.08
					<b>Job Subtotal: \$310.88</b>

Recommendations: \*MAJOR SERVICE\*

**Payments to ABP REPAIR INC****Cost Summary**

Status: Paid Work Order

Labor 156.80

Payments: \$336.67

Parts 154.08

1 10/03/24 336.67 Visa

Haz Waste 10.00

Tax 15.79

Total \$336.67

Payments 336.67

Bal Due 0.00

Thank you for choosing ABP REPAIR INC

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_

**ABP REPAIR INC**

Invoice No.

BAR #: ARD00306268

000024793

Order Date 02/03/25 04:25 pm

EPA # CAL000432920

Completed: 02/03/25 04:44 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

**80 PORSCHE 911 BLUE**

82655 Mi.Last in 10/3/2024

Lic: 1CARMEL/CA H6Cyl 3.0

Vin: 91A0142559

Eq: AC FI

**RUNNING ROUGH**

Labor: \$2,240.00

CUSTOMER HAD THE CAR SMOGGED, EVER SINCE THE ENGINE IS RUNNING ROUGH. CHECK AND ADVISE. TESTED CAR, ENGINE IS MISFIRING. CHECKED FOR SPARK, ALL CYLINDERS ARE GETTING SPARK. NOTICED THAT THE OXYGEN SENSOR RELAY IS CLICKING AWAY WHILE THE ENGINE IS RUNNING. REPLACED OXYGEN SENSOR RELAY, AND TESTED. RELAY IS NO LONGER CLICKING AWAY, BUT THE ENGINE IS STILL MISFIRING.

CYLINDER #5 IS MISFIRING. REMOVED CYLINDER 2 FUEL INJECTOR, AND TESTED, FUEL INJECTOR IS OK. INSTALLED NEW CYLINDER #5 FUEL INJECTOR SLEEVE, AND O-RING. INSTALLED FUEL INJECTOR WITH NEW O-RING.

FURTHER INSPECTED AND TRACED THE MISFIRE TO THE FUEL DISTRIBUTOR.

REMOVED FUEL DISTRIBUTOR AND SENT OUT TO BE REBUILT.

INSTALLED REBUILT FUEL DISTRIBUTOR. INSTALLED NEW AIR BOX SENSOR PLATE GASKET. CHECKED FUEL PRESSURES, FUEL PRESSURE IS TOO HIGH. TRACED HIGH FUEL PRESSURE ISSUE TO THE WARM UP REGULATOR.

REMOVED WARM-UP REGULATOR, AND SENT OUT TO NE REBUILT.

INSTALLED REBUILT WARM UP REGULATOR. REPLACED FUEL FILTER.

SET FUEL PRESSURES, AND FUEL MIXTURE. TEST DROVE CAR, ENGINE IS NO LONGER MISFIRING.

PCG95125300	OXYGEN SENSOR RELAY-N	1.0 @	35.60 =\$	35.60
99970144640	O-ring-N	1.0 @	2.15 =\$	2.15
91111088603	Insert Sleeve-N	1.0 @	8.53 =\$	8.53
99970142340	Fuel Injector Seal-N	1.0 @	2.60 =\$	2.60
91111039402	AIR BOX GASKET SC-N	1.0 @	16.94 =\$	16.94
93011019600	Fuel Filter-N	1.0 @	60.26 =\$	60.26
93011019800	Fuel Hose Fitting-N	1.0 @	7.15 =\$	7.15
93011019900	Fuel Hose Fitting-N	1.0 @	7.60 =\$	7.60
				140.83

Job Subtotal: \$2,380.83

**FUEL DISTRIBUTOR / WARM UP REG.**

Sublet: \$845.00

REBUILT FUEL DISTRIBUTOR.

REBUILT WARM UP REGULATOR.

Recommendations: \*MAJOR SERVICE\*

----->----->----->-----Continued on the next page----->----->----->----->

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_\_\_\_\_



**ABP REPAIR INC**

Invoice No.

BAR #: ARD00306268

000024793

Order Date 02/03/25 04:25 pm

EPA # CAL000432920

Completed: 02/03/25 04:44 pm

1009 7th Street

Oakland, CA 94607

Phone: 510-834-2772 FAX: 510-834-2776

Payments to ABP REPAIR INC	Cost Summary	
Status: Completed Work Order	Labor	2240.00
Payments:	Parts	140.83
	Sublet	845.00
	Fright	92.72
	Tax	14.44
	Total	\$3332.99
	Payments	0.00
	Bal Due	3332.99

Thank you for choosing ABP REPAIR INC