

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 1	Out	Fleet #
				Body Style Cabriolet	Ext. War.	Written By: KB

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Parts

Part Description	Status	Qty	Price Ea.	Total
Sun Visor	N	1.00	\$183.31	\$183.31
			Parts Total	\$183.31

Pre-Pay		Payment	Total Tax	Taxable Parts \$183.31	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date
\$0.00	Cash		\$14.57	NonTax Parts \$0.00		8/27/2015
\$0.00	Check	\$197.88		Total Parts \$183.31		RO #
	Chk #		Supplies	Labor \$0.00		8796
\$0.00	Credit		\$0.00	Sublet \$0.00		RO Total
	Type		Disposal	NonTax Labor \$0.00		\$197.88
	Expires		Environ.	NonTax Sublet \$0.00		Balance Due
\$0.00	Paid	\$197.88		Total Labor \$0.00		\$0.00
				Signature or Initial		Date

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 45494	Out	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: FB

Problem Statements

Wont start, believes battery is fully charged
 Vehicle is still leaking oil (July 2015 we resealed case bolt and cleaned and resealed axle boots).
 Change the oil.

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
zFL	Sub	Towing.	\$123.00
	Lab	Wont start, believes battery is fully charged. Check battery. (ok).....N/C	\$0.00
LB	Lab	Vehicle is still leaking oil (July 2015 we resealed case bolt and cleaned and resealed axle boots). R&R axle tubes, reseal side plates and axle tube retainer plates. Replace left carrier bearing.	\$1,490.71
FB	Lab	Oil, filter change. Includes checking of fluids, tire pressures and wear, lights, windshield wiper systems, brake wear, gear oil where applicable, and fluid leaks.	\$137.60
LR	Lab	Drain old fuel. Add 5 gallons of high octane fuel additive.	\$172.01
LR	Lab	Fuel not getting to carbs. R&R fuel pump, rebuild. No charge on labor. Goodwill.	\$0.00
LR	Lab	Diagnose plugged fuel passages in carbs. R&R carbs and rebuild. Adjust carburetors.	\$573.35
zFL	Sub	4 wheel alignment.	\$114.67
Labor Total			\$2,611.34

Parts

Part Description	Status	Qty	Price Ea.	Total
Fuel Pump Repair Kit (Discounted price.)	N	1.00	\$67.90	\$67.90
Fuel Additive 100	N	5.00	\$9.99	\$49.95
Fuel Filter	N	1.00	\$11.58	\$11.58
Carburetor kit	N	2.00	\$111.56	\$223.12
Wheel Seal Kit	N	2.00	\$15.27	\$30.54
Carrier Bearing	N	1.00	\$111.30	\$111.30
Flywheel Gasket	N	1.00	\$2.67	\$2.67
Rear Main Seal	N	1.00	\$26.33	\$26.33
Gear Oil (pints)	N	7.50	\$4.95	\$37.13
Transmission Gasket Set	N	1.00	\$141.67	\$141.67
Fuel Additive 100	N	9.00	\$9.99	\$89.91
Oil Filter	N	1.00	\$23.21	\$23.21
Strainer Gasket	N	1.00	\$7.50	\$7.50
Brad Penn 20-50	N	4.00	\$9.00	\$36.00
Parts Total				\$858.81

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
				In Mileage 45494	Out Fleet #	P.O. Number
Prod Date 03/62	Turbo/Non	Color Black	Body Style Cabriolet	Ext. War.	Written By: FB	

Pre-Pay		Payment	Total Tax	Taxable Parts \$858.81	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date 12/29/2016
\$0.00	Cash		\$73.45	NonTax Parts \$0.00		RO # 10334
\$0.00	Check		Supplies	Total Parts \$858.81		RO Total \$3,706.52
	Chk #		\$64.97	Labor \$2,373.67		Balance Due \$0.00
\$0.00	Credit	\$3,706.52	Disposal	Sublet \$237.67		
	Type	AmEx	\$7.73	NonTax Labor \$0.00		
	Expires		Environ.	NonTax Sublet \$0.00		
\$0.00	Paid	\$3,706.52	\$90.22	Total Labor \$2,611.34		Signature or Initial _____
						Date _____

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 1	Out	Fleet #
				Body Style Cabriolet	Ext. War.	Written By: FB

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
SM	Lab	R&R transaxle.	\$898.12
zFL	Sub	Rebuild transmission with tubes, clean, weld shift finger, gaskets & seals, ring gear bolts, ground strap, 4G gear set, wheel bearing washers, axle boot clamps.	\$3,950.00
FB	Lab	Install Optima dry cell battery. Fab bracket.	\$295.34
zFL	Sub	Four Wheel Alignment. (Alignments have free recheck within 1 year; if adjustment is necessary will be done at a reduced rate. Does not carry traditional 12/12 warranty as alignments can be knocked out by hitting things such as potholes or curbs.)	\$225.00
zFL	Lab	Touch up and buffing of front hood.	\$75.00
Labor Total			\$5,443.46

Parts

Part Description	Status	Qty	Price Ea.	Total
Gear Oil (pints)	N	9.00	\$4.95	\$44.55
Optima Battery	N	1.00	\$263.00	\$263.00
Parts Total				\$307.55

Pre-Pay	Payment	Total Tax	Taxable Parts	NonTax Parts	Total Parts	Labor	Sublet	NonTax Labor	NonTax Sublet	Total Labor	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date
\$0.00	Cash	\$29.41	\$307.55	\$0.00	\$307.55	\$1,268.46	\$4,175.00	\$0.00	\$0.00	\$5,443.46		11/29/2018
\$0.00	Check	\$62.33										RO #
	Chk #	\$7.72										11799
\$0.00	Credit	\$149.53										RO Total
	Type											\$6,000.00
	Expires										Balance Due	
\$0.00	Paid										\$0.00	
										Signature or Initial	Date	

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 46055	Out 55	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: FB

Problem Statements

Engine rebuild.

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
zFL	Sub	Powdercoating of sheetmetal for engine and transmission.	\$460.00
zFL	Sub	Inspect engine case, remove head studs, check main bearing bore (ok), machine deck, R&R oil plugs, hot tank case.	\$1,100.00
zFL	Sub	Complete valve job, replace guides, resurface heads.	\$1,080.00
zFL	Sub	Polish crankshaft.	\$50.00
zFL	Sub	Balance crankshaft, rods, pistons, flywheel and pressure plate.	\$150.00
zFL	Sub	Clear Zinc plating.	\$200.00
FB	Lab	R&R engine and transaxle.....N/C	\$0.00
FB	Lab	Disassemble engine. Clean, measure, inspect parts. Reassemble as nec with new parts, gaskets, seals, and o-rings.	\$6,825.15
FB	Lab	Replace engine compartment weather stripping.	\$227.51
FB	Lab	Adjust throttle linkage at cluster pedal. R&R mat and toe board.	\$227.51
FB	Lab	R&R speedo, disassemble, zero odometer, and reassemble.	\$303.34
FB	Lab	Replace battery.	\$75.84
zFL	Sub	Align suspension after reinstalling transaxle.	\$225.00
	Lab	Valve adjustment and oil change due in 600 miles.	\$0.00
Labor Total			\$10,924.35

Parts

Part Description	Status	Qty	Price Ea.	Total
356A, B & C Head set (Zenith Carbs)	N	1.00	\$89.90	\$89.90
Engine Gasket Set (Case set)	N	1.00	\$154.00	\$154.00
Rod Bearing Set (Std)	N	1.00	\$90.00	\$90.00
Main bearing set (Std crank/.25 case)	N	1.00	\$745.13	\$745.13
New set Porsche connecting rods (NOS)	N	1.00	\$999.00	\$999.00
86mm high comp. Nikosil clys, JE pistons	N	1.00	\$3,000.00	\$3,000.00
Push Rod Tube	N	8.00	\$38.57	\$308.56
Camshaft	N	1.00	\$435.71	\$435.71
Fuel Pump Block	N	1.00	\$34.19	\$34.19
Engine Shroud Screw	N	20.00	\$0.64	\$12.80
Engine Compartment Seal Left/Right	N	2.00	\$15.95	\$31.90
Engine Compartment Seal (Long Section)	N	2.00	\$48.09	\$96.18
Generator Belt	N	1.00	\$13.58	\$13.58
Oil Cap Gasket	N	1.00	\$4.63	\$4.63
Fuel Filter	N	1.00	\$10.29	\$10.29
Air Filter	N	2.00	\$32.20	\$64.40

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 46055	Out 55	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: FB

Parts				
Part Description	Status	Qty	Price Ea.	Total
Gasoline	N	1.00	\$71.25	\$71.25
Battery - Bosch S4 Quality BCI Group 19L (6V), 540 CA / 440 CCA.	N	1.00	\$262.82	\$262.82
Lifters	N	8.00	\$34.46	\$275.68
Seal Ring	N	1.00	\$5.70	\$5.70
Air Cleaner Decal	N	2.00	\$9.71	\$19.42
H-Filter Oil Filter Canister Top Cover Decal	N	1.00	\$7.94	\$7.94
Valve Clearance Decal	N	1.00	\$5.66	\$5.66
Muffler Support	N	1.00	\$125.97	\$125.97
Oil Filter	N	1.00	\$25.06	\$25.06
40 W Non-Detergent Oil	N	4.50	\$8.32	\$37.44
Oil Filter	N	1.00	\$25.06	\$25.06
Oil Strainer Gasket Kit 356 & 912 (Graphite)	N	1.00	\$8.99	\$8.99
40 W Non-Detergent Oil	N	4.50	\$8.32	\$37.44
Parts Total				\$6,998.70

Pre-Pay		Payment	Total Tax	Taxable Parts \$6,998.70	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date 10/31/2019
\$0.00	Cash		\$580.71	NonTax Parts \$0.00		RO # 11807
\$0.00	Check		Supplies	Total Parts \$6,998.70		RO Total \$19,045.77
	Chk #		\$214.97	Labor \$7,659.35		Balance Due \$0.00
\$0.00	Credit	\$19,045.77	Disposal	Sublet \$3,265.00		
	Type	AmEx	\$147.73	NonTax Labor \$0.00		
	Expires		Environ.	NonTax Sublet \$0.00		
\$0.00	Paid	\$19,045.77	\$179.31	Total Labor \$10,924.35		Signature or Initial _____
						Date _____

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 556	Out 668	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: KB

Problem Statements

Roof at windshield seal, screws are loose, wood is bad.
 Install new belts on front seat.
 Every time you let the clutch out there is a super squeak.
 600 mile service, adjust valves, break in oil change.
 FB drive, clutch releases too low? If is where it should be then leave it.

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
FB	Lab	Roof at windshield seal, screws are loose, wood is bad. Repair as nec. Replace front convertible top seal.	\$303.34
ML	Lab	Install 3-point seat belts for front seats. (Provided by owner.)	\$303.34
FB	Lab	Exhaust rattle. Adjust tailpipes.....N/C	\$0.00
JB	Lab	Oil, filter change. Includes checking of fluids, tire pressures and wear, lights, windshield wiper systems, brake wear, gear oil where applicable, and fluid leaks. Non-Detergent oil for the next 987 miles.	\$204.75
JB	Lab	Adjust valves. Replace valve cover gaskets. (600 mi)	\$265.42
FB	Lab	Check clutch release point. (Ok)	\$0.00
MS	Lab	Nasty brake pull to the left. Left front wheel cylinders are leaking. Replace both cylinders, repack left front wheel bearings. Bleed brakes, adjust all shoes. Arc grind front brake shoes. Replace right rear brake cylinder. Bleed system 3x.	\$1,061.69
MP	Lab	Replace right rear wheel seal.....n/c.	\$0.00
MP	Lab	Front suspension noise. Tighten link pins.	\$151.67
zFL	Sub	PDR (Paintless Dent Repair) ding during transport back to AZ.	\$200.00
Labor Total			\$2,490.21

Parts

Part Description	Status	Qty	Price Ea.	Total
Convertible Top Seal	N	1.00	\$30.00	\$30.00
Oil Filter	N	1.00	\$25.06	\$25.06
Oil Strainer Gasket Kit 356 & 912 (Graphite)	N	1.00	\$8.99	\$8.99
40 W Non-Detergent Oil	N	4.00	\$8.32	\$33.28
Valve Cover Gasket	N	1.00	\$49.25	\$49.25
Castrol Dot 4 Brake Fluid	N	2.00	\$16.00	\$32.00
Wheel Cylinder - Front	N	1.00	\$323.39	\$323.39
Wheel Cylinder- Front	N	1.00	\$304.15	\$304.15
Front Wheel Seal	N	1.00	\$5.00	\$5.00
Wheel Cylinder, Rear	N	1.00	\$272.16	\$272.16
Wheel Seal	N	1.00	\$4.31	\$4.31
Fuel Additive 95 (Unleaded)	N	1.00	\$70.00	\$70.00
Parts Total				\$1,157.59

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 556	Out 668	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: KB

Pre-Pay		Payment	Total Tax	Taxable Parts \$1,157.59	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date 4/29/2020
\$0.00	Cash		\$98.42	NonTax Parts \$0.00		RO # 13871
\$0.00	Check		Supplies	Total Parts \$1,157.59		RO Total \$3,933.76
	Chk #		\$64.97	Labor \$2,290.21		Balance Due \$0.00
\$0.00	Credit	\$3,933.76	Disposal	Sublet \$200.00		
	Type	AmEx	\$27.73	NonTax Labor \$0.00		
	Expires		Environ.	NonTax Sublet \$0.00		
\$0.00	Paid	\$3,933.76	\$94.84	Total Labor \$2,490.21		Signature or Initial
						Date

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
		Make Porsche		Model 356B		
		Engine 1.6L		Transmission Manual		
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 922	Out 931	Fleet # P.O. Number
			Body Style Cabriolet	Ext. War.		Written By: FB

Problem Statements

Leak from trans axle area?
 Front drivers leaking brake fluid.
 Second oil change.
 Please put 1 qt oil in trunk.
 Clear Bra up to doors.
 Cover for soft top, black stain on the drivers side. It is chapstick.

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
JB	Lab	Oil, filter change. Includes checking of fluids, tire pressures and wear, lights, windshield wiper systems, brake wear, gear oil where applicable, and fluid leaks.	\$204.75
	Lab	Please put 1 qt oil in trunk.	\$0.00
MP	Lab	Check oil leaks. Inspect, clean. Tighten/re-seal trans intermediate housing bolts.....N/C	\$0.00
	Lab	Front drivers leaking brake fluid. "Leak" was grease from front axle beam. Wiped down.	\$0.00
zFL	Sub	Clear Bra up to doors.	\$2,500.00
zFL	Sub	Clean cover for soft top, black chapstick stain on the drivers side.	\$75.00
MP	Lab	Check engine "oil leak". Leak is actually fuel leaking from carburetors. Attempt to tighten; housings warped. Install rebuilt Zenith carburetors. Adjust linkage and mixture.....N/C.	\$0.00
zFL	Sub	Rebuild Zenith 32NDIX Carburetors.	\$1,200.00
Labor Total			\$3,979.75

Parts

Part Description	Status	Qty	Price Ea.	Total
Oil Filter	N	1.00	\$25.06	\$25.06
Oil Strainer Gasket Kit 356 & 912 (Graphite)	N	1.00	\$8.75	\$8.75
Brad Penn 20-50	N	4.00	\$9.87	\$39.48
Brad Penn 20-50	N	1.00	\$9.87	\$9.87
Parts Total				\$83.16

Authorization

Date/ Time	Spoke to/ Phone	Amount/ Emp.	Comment/ Reason
10/21/2020 11:01am	Tony 619-518-5000 cell	\$2,500.00 KC	Verbal authorization to Clear Bra front end to the doors.

Pre-Pay	Payment	Total Tax	Taxable Parts	NonTax Parts	Total Parts	Supplies	Disposal	Environ.	Total Labor	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date
\$0.00	Cash	\$11.92	\$83.16	\$0.00	\$83.16	Labor	\$27.73	\$85.64	\$3,979.75	Signature or Initial _____ Date _____	10/30/2020
\$0.00	Check		\$64.97	\$3,775.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00		RO #
\$0.00	Chk #	\$27.73	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	RO Total		14546
\$0.00	Credit	\$27.73	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00		\$4,253.17
\$0.00	AmEx	\$85.64	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00		\$0.00
\$0.00	Paid	\$4,253.17	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	Balance Due
\$0.00	Paid	\$4,253.17	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
		Make Porsche		Model 356B		
		Engine 1.6L		Transmission Manual		
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 2243	Out 2255	Fleet # P.O. Number
		Body Style Cabriolet		Ext. War.		Written By: FB

Problem Statements

Push to start
 Squeak went away and now its back, (chrome extension on tail pipe) sounds like a body rattle
 Passenger headlight not working
 Wire to starter has power.
 Car is now idling at 2,100 rpms. 3500 RPM at idle
 Replace wiper blades
 Passenger seat belts need to be replaced
 Rear hatch bushing 3/4 are there, please replace.

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
MP	Lab	Starter has a sticking solenoid. Diagnose, remove and replace starter and bushing.	\$389.18
FB	Lab	Car is now idling at 2,100 rpms. 3500 RPM at idle. Right side air cleaner clamp is tight but rotated enough to hang up the throttle. FB repaired clamp on air cleaner.....n/c.	\$0.00
MP	Lab	Replace battery. Battery under warranty.	\$77.84
FB	Lab	Replace wiper blades.	\$38.92
MP	Lab	Squeak went away and now its back, (chrome extension on tail pipe), repair.....n/c.	\$0.00
FB	Lab	Passenger headlight not working. Remove right headlight and fix connection. Reinstall headlight.	\$155.67
zFL	Sub	Passenger seat belt needs to be repaired.	\$150.00
FB	Lab	One engine lid rubber stop/snubber is missing. Install new one.....n/c.	\$0.00
MP	Lab	Oil cap gasket ripped, replace.....n/c.	\$0.00
Labor Total			\$811.61

Parts

Part Description	Status	Qty	Price Ea.	Total
Starter	R	1.00	\$220.00	\$220.00
Battery - Bosch S4 Quality BCI Group 19L (6V), 540 CA / 440 CCA.	N	1.00	\$0.00	\$0.00
NOS Windshield Wiper Blade	N	2.00	\$25.00	\$50.00
Engine Lid Rubber Stop/Snubber	N	1.00	\$11.00	\$11.00
Oil Cap Gasket	N	1.00	\$8.72	\$8.72
Fuel Additive 95 (Unleaded)	N	3.00	\$7.99	\$23.97
Parts Total				\$313.69

Pre-Pay	Payment	Total Tax	Taxable Parts	NonTax Parts	Total Parts	Labor	Sublet	NonTax Labor	NonTax Sublet	Total Labor	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date
\$0.00	Cash	\$28.84	\$313.69	\$0.00	\$313.69	\$661.61	\$150.00	\$0.00	\$0.00	\$811.61		1/20/2021
\$0.00	Check											RO #
	Chk #	\$44.64										RO Total
\$0.00	Credit	\$1,235.77										\$1,235.77
	Type	AmEx										Balance Due
\$0.00	Paid	\$1,235.77	\$29.26	\$29.26	\$29.26						Signature or Initial	Date
	Expires											\$0.00

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 2310	Out 2311	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: KB

Problem Statements

Repair drivers door.
 Will pick up next Friday 3-19
 Pull off the stickers, Hand wash

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
MP	Lab	Driver's door is locked and will not open from the outside or inside of vehicle. Remove driver's door panel. Replace Bowden wire. Reinstall door panel.	\$351.34
zFL	Sub	Hand wash, remove stickers.	\$175.00
Labor Total			\$526.34

Parts

Part Description	Status	Qty	Price Ea.	Total
Bowden Wire	N	1.00	\$42.17	\$42.17
Parts Total			\$42.17	

Pre-Pay		Payment	Total Tax	Taxable Parts \$42.17	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date 3/29/2021
\$0.00	Cash		\$5.72	NonTax Parts \$0.00		RO # 14937
\$0.00	Check		Supplies	Total Parts \$42.17		RO Total \$628.54
	Chk #		\$28.95	Labor \$351.34		Balance Due \$0.00
\$0.00	Credit	\$628.54	Disposal	Sublet \$175.00		
	Type	AmEx	\$9.73	NonTax Labor \$0.00		
	Expires		Environ.	NonTax Sublet \$0.00		
\$0.00	Paid	\$628.54	\$15.63	Total Labor \$526.34		Signature or Initial _____
						Date _____

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 2758		License GMS356	VIN 158698	Year 1963
				Make Porsche	Model 356B	
				Engine 1.6L	Transmission Manual	
Prod Date 03/62		Turbo/Non	Color Black	In Mileage 2325	Out 2343	Fleet # P.O. Number
				Body Style Cabriolet	Ext. War.	Written By: KB

Problem Statements

Oil, Filter change with inspection.

Recommended Services

Date	Mileage	Description
12/20/2016	45494	Due to low number of miles driven, recommend high octane fuel to help prevent problems in the future
10/31/2019	46055	Customer acknowledges: Oil change for break-in oil due within 600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil change with non-detergent oil performed by Beck's European 2-17-2020 Mileage: 00556
10/31/2019	46055	Customer acknowledges: Second oil change due within 1,600 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Brad Penn Oil change with Brad Penn performed by Beck's European 10-20-2020 Mileage: 00922
10/31/2019	46055	Customer acknowledges: Oil change intervals of 3,000 miles or 12 months, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's X: _____
10/31/2019	46055	Break in vehicle on 95 octane or 1/2 and 1/2 with 100 and 91.
4/29/2020	556	Frank Beck says customer can "let the dogs run" now.
10/7/2021	2325	Tire Tread Remaining: Front 9/32. Rear 9/32. Tires are typically replaced at 4/32 or wear bars.
10/7/2021	2325	Brake fluid tests at 0% water, good.

Labor Operations

Tech	Type	Description	Price
zFL	Sub	Towing.	\$185.00
RG	Lab	Oil, filter change. Includes checking of fluids, tire pressures and wear, lights, windshield wiper systems, brake wear, gear oil where applicable, and fluid leaks.	\$223.66
RG	Lab	Lubricate accelerator pedal.....n/c.	\$0.00
Labor Total			\$408.66

Parts

Part Description	Status	Qty	Price Ea.	Total
Oil Filter	N	1.00	\$25.06	\$25.06
Oil Strainer Gasket Kit 356 & 912 (Graphite)	N	1.00	\$8.75	\$8.75
Oil - Brad Penn 20-50	N	3.50	\$11.08	\$38.78
Parts Total				\$72.59

Pre-Pay		Payment	Total Tax	Taxable Parts \$72.59	Invoices paid in full carry a 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in parts and workmanship to the vehicle in this facility only. Does not include racing, fabrication or performance products/services. Towing not included.	Date 10/7/2021
\$0.00	Cash		\$7.65	NonTax Parts \$0.00		RO # 15521
\$0.00	Check			Total Parts \$72.59		RO Total \$534.34
	Chk #		Supplies \$22.48	Labor \$223.66		Balance Due \$0.00
\$0.00	Credit	\$534.34	Disposal \$9.73	Sublet \$185.00		
	Type	AmEx	Environ. \$13.23	NonTax Labor \$0.00		
	Expires			NonTax Sublet \$0.00		
\$0.00	Paid	\$534.34		Total Labor \$408.66		Signature or Initial
						Date

MAKE: ROSSCHL MODEL: LAD2100C IN: 2775 MILEAGE: 145,858 LICENSE NO.: FAS-BS3 VEHICLE IDENTIFICATION NUMBER: OPER. NO. DATE: SERVICE ADVISOR: R.O. NUMBER: 58151

QTY	CODE	PART NUMBER AND DESCRIPTION	PRICE	NAME	AM	PM	DATE	TIME RECEIVED	IN	OUT	1	2	3	4	5	6	7	8	9
4.5		ROW 50 OIL (CONET)	10.99																
		4 feet FUEL LINE	20.50																
		Oil Filter																	
		OWNER'S PARTS 1/4																	
4		Hose Clamps	5.80																
		Electric Fuel Pump 1/4																	
		OWNER'S PARTS																	
		ALSO PARTS/REPAIRS CODED:																	
		USED R=REBUILT																	
		RC=RECONDITIONED																	
		NO=NO CHG/WARRANTY																	
		RO=REDUCED WARRANTY																	
		SUBLET REPAIRS																	

REPAIR ORDER - LABOR INSTRUCTIONS
 OIL CHANGE SERVICE / OIL FILTER REPLACEMENT 62.50
 An engine of suspension Bolt (check)
 Marine Oil Pump installation
 changing of water meter
 the ever added water clamps
 310.50

ORIGINAL ESTIMATE	ADDITIONAL AUTHORIZED AMOUNT	REVISED AUTHORIZED ESTIMATE	DATE	DESIGNEE	DESCRIPTION OF ADDITIONAL WORK AUTHORIZED	CONTACT PHONE
\$	\$	\$				

SIGNED: _____ **DATE:** _____

MEMBER

OCEAN REEF CLUB SERVICE STATION
 KEY LARGO, FL 33037
 (305) 367-5811
 MV27813 Thank You

TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL & GREASE	SUBLET REPAIRS	TAX	TOTAL
375.00	97.29		491.18		56.84	528.10