

Customer's reason for bringing in vehicle

SEARS

Auto Center

VALUED CUSTOMER INFORMATION

VEHICLE INFORMATION

NAME

PHONE

CSA NOTES:

100 ft lbs max
on by hand.

YEAR:

75

LIC. PLATE:

263 PAU

MAKE:

Jensen

COLOR:

Blk

MODEL:

Interceptor

ENGINE SIZE:

ODOMETER IN:

115476

WHEEL LOCKS: Y / N

VIN#

WHEEL KEY LOCATION

(if required for commercial customer)

CURRENT RIDE CONDITIONS

Is the steering wheel straight?

Y / N

Is the vehicle pulling?

Y / N Left/Right

Is the vehicle vibrating?

Y / N At what speed?

During braking?

Y / N If Yes, refer to Current
Brake Conditions (below)

CURRENT BRAKE CONDITIONS

Is brake light on?

Y / N

Is ABS light on?

Y / N

Is there a noise when braking?

Y / N

Does vehicle pull when braking?

Y / N

Does pedal pulsate?

Y / N

Is brake pedal low?

Y / N

Are tires Good / Fair / Poor?

If Poor, refer to Current Tire
Conditions (on right)

OIL SERVICE

Is Oil indicator light on?

Y / N Quick Lube Guide: Pg #: _____

of Quarts: _____


Drain Plug Torque: _____

Oil Type: _____

CURRENT TIRE CONDITIONS

FRONT TIRE SIZE: P/XL/LT

205/70/15

Performance
Rating

RWL

BW

WW

REAR TIRE SIZE: P/XL/LT

Performance
Rating

LF

RF

SAVE OLD TIRES Y / N

LR

RR

COMMENTS:

NO scratches on wheels

SP

✓	ITEM/PART	FINDINGS/COMMENTS	RECOMMEND EVALUATION
✓	BRAKES	LIGHTS	PEDAL
✓	CV BOOTS	PADS	ROTORS
✓	SHOCKS - STRUTS - SPRINGS	TORN	CRACKED
✓	FRONT END	BROKEN	CRACKED
		LOOSE	COMMENT
	Service Technician(s) Initials	Service Technician(s) Comments:	

DieHard® Express Battery Service

- ☐ DIEHARD SERVICE AND ADVISE (SABRE Printout)
- ☐ IN-WARRANTY BATTERY AND DIEHARD SERVICE

CUSTOMER AUTHORIZATION: I hereby authorize the repair facility to operate my vehicle and perform DieHard Service as described above.

I acknowledge that the charge for this service, if any, is disclosed below

CUSTOMER SIGNATURE

DieHard Service Fee

(DieHard Service Only)

\$

DieHard Service includes:

- Full analysis of your battery's condition - Its state of charge and ability to hold a charge
- Inspection and analysis of your vehicle's starting and charging system, including the starter, alternator, and regulator (Most vehicles)
- Inspection of the alternator belt, and tightening if necessary
- Cleaning of the battery's connections and cable ends
- Application of corrosion protection and terminal protectors
- Installation of new battery, if necessary

CUSTOMER INFORMATION		TAG #	VEHICLE INFORMATION		YEAR / MAKE / MODEL	INITIAL ESTIMATE	REVISED ESTIMATE	CREATED BY
NAME: [REDACTED]			NO VEHICLE			PARTS \$447.92	\$587.92	472324
ADDRESS: [REDACTED]			LICENSE #		COLOR	LABOR \$39.96	\$39.96	
CITY/ST/ZIP:			V.I.N.		LOCATION	OTHER \$0.00	\$0.00	INVOICED BY
HOME PHONE:			TIME IN		TIME OUT	TAX \$40.49	\$52.11	522987
STORE INFORMATION			05/12/2004 10:08 AM		05/12/2004 11:33 AM	TOTAL \$528.37	\$679.99	
6779 - SEARS 1302 SE Everett Mall Way Everett, WA 98208 (425) 356-6775			ODOMETER IN 115476		ODOMETER OUT	DATE/TIME OF ESTIMATE 05/11/2004 04:54 PM	DATE/TIME OF REVISED 05/12/2004 11:36 AM	PAYMENT TYPE
EPA Number: WAD173263591 Repair Number: 409-000-001								CASH ☐ CREDIT ☐ CHECK ☐
WAITING YES	DROP-OFF NO	PROMISED TIME 05/12/2004 11:30 PM	TIRE INSTALLATION INSTRUCTIONS		LOCKS Y	PHONE AUTHORIZATION ☐ PHONE NUMBER CALL		
REFERENCE NUMBER IN4625367 LPP# 625367	PRINTED ON 05/12/2004 11:37 AM	TIRE INSTALLATION INSTRUCTIONS		SAVE OLD TIRES Y	ROWL	CONTACTED BY DATE TIME		
CUSTOMER COMMENTS		AIR PRESSURE FRONT / REAR		REFER TO TIRE GUIDE - NON O.E. APPLICATION		See reverse for important warranty terms and other information.		
60 FT LBS MAX TORQ PUT BACK ON BY HAND ONLY. TAPE W EIGHTS INSIDE ONLY.		WHL TORQUE SPECIFICATION		REFER TO TIRE GUIDE		CUST. [REDACTED]		
QTY.	ITEM #	DESCRIPTION OF MERCHANDISE	PRICE EA.	EXTENSION	TECH.	RETAIN FOR COMPARISON WITH MONTHLY STATEMENT OR FOR RETURN OR EXCHANGE		
4	PS 09549379	TIRE, P21565V15 MN PX6TV4B	\$141.99	\$567.96		09549379 QTY:4		
4	PS 09598741	VALVE, RUBBER STEM	\$2.99	\$11.96		TIRE, P21565V15 M \$567.96T		
4	AC 189021	LOCAL TIRE DISPOSAL	\$2.00	\$8.00		09598741 QTY:4		
4	LB 19012000	TIRE BALANCE, PERFORMANCE	\$9.99	\$39.96	663252	VALVE, RUBBER STE \$11.96T		
						189021 QTY:4		
						LOCAL TIRE DISPO \$8.00T		
						19012000 QTY:4		
						TIRE BALANCE, PER \$39.96T		
						Parts SubTotal : \$587.92		
						Labor SubTotal : \$39.96		
						Reductions SubTotal : \$0.00		
						SubTotal : \$627.88		
						Tax : 8.300% \$52.11		
						Total : \$679.99		
						Check Tendered : \$679.99		
						SALES CHECK # 067790446249		
						SATISFACTION GUARANTEED		
ALL NEW, NON-OEM PARTS UNLESS OTHERWISE SPECIFIED. ITEM / WARRANTY INFORMATION / CSA COMMENTS / TECHNICIAN COMMENTS WARRANTY: 09549379 : NONE; Tread Depth: 10 ALL LUG NUTS ON CUSTOM AND ALLOY WHEELS MUST BE RE-TORQUED AFTER 25 MILES AND CHECKED PERIODICALLY. ITEM COMMENTS: 19012000: For the Life of the Tire, to address an uneven or imbalanced tire, we will: adjust tire pressure, remove old weights, computer spin balance. Priced EACH								
Thank you for the opportunity to serve you. Our goal is to provide Fast, Expert Service. Please keep us in mind for your future automotive needs.								
(Page 1 of 1)								
RETURN OLD PARTS TO CUSTOMER ☒ ☐								



Portola Valley Garage
 4170 Alpine Road
 Portola Valley, CA 94028
 650-851-7442



Repair Order #0025608

Date : 7/19/2013

Page : 1

Center :



BAR#ARD191344 SMOG #RC191344 EPA# CAL000046757

Customer :

Address :

City :

Home :

His Work :

Vehicle : 1975 JENS INTERCEPTOR

License : 263PAU

P/D :

VIN : 2311174

Engine : 440 CU

Trans : AUTO

Mileage : 16087

Tag :

Op	Tech	Description	Part Number	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
01 030		6 10W/30 OIL SERVICE & SAFETY INSPECTION: ** Service or Inspect ** Lights, tires, fluid levels, drive belts, hoses, cooling system, exhaust, suspension components, brakes, steering linkages. Test anti-freeze concentration, test battery (digital & load test) & clean connections as necessary. Lube chassis, including: hood, trunk, & door hinges. Replace oil & filter. Reset service indicator if applicable. Rotate Tires if necessary. Road test. . Tire pressure check in PSI LF 32 RF 32 LR 30 RR 30 Spare (if equipped)				223.50	196.47	419.97
	6.00	10/30		MOTOR OIL			32.10	
	1.00	DF		DISPOSAL FEES			7.00	
	1.00	DG		DRAIN PLUG GASKET			1.21	
	1.00	M506		WINDSHIELD WASHER SO			3.91	
	1.00	51085		OIL FILTER			13.25	
	1.00	MT34		BATTERY			139.00	
0		6 Replace sparkplugs				163.90	45.20	209.10
	8.00	63		CHAMPION PLUG			45.20	
		6 Flush brake fluid				119.20	8.00	127.20
	1.00	BF		BRAKE FLUID			8.00	

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation
----	-----	----------------	----	-----	----------------	----	-----	----------------

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY 2 YEARS OR 24K MILES WHICH EVER OCCURS FIRST, SEE BACK FOR DETAILS. FRICTION MATERIAL NOT COVERED.

X

Labor :	\$665.80
Parts :	\$297.67
Sublet :	\$0.00
Other Fees :	\$0.00
	\$0.00
Subtotal :	\$963.47
Sales Tax :	\$26.16
Paid By :	Total : \$989.63
Pay Ref :	Paid : \$0.00
	Due : \$989.63



Portola Valley Garage
 4170 Alpine Road
 Portola Valley, CA 94028
 650-851-7442



Repair Order #0025608

Date : 7/19/2013

Page : 2

Center :



BAR#ARD191344 SMOG #RC191344 EPA# CAL000046757

Customer :

Address :

City :

Home :

His Work :

Vehicle : 1975 JENS INTERCEPTOR

License : 263PAU

P/D :

VIN : 2311174

Engine : 440 CU

Trans : AUTO

Mileage : 16087

Tag :

Op	Tech	Description	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
0		6 Drain and fill cooling system			119.20	48.00	167.20
	6.00	COOL	COOLANT			48.00	
T1 097		6 Purigen98 Nitrogen tire conversion			40.00		40.00

OK Bad

Recommendation

OK Bad

Recommendation

OK Bad

Recommendation

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY 2 YEARS OR 24K MILES WHICH EVER OCCURS FIRST, SEE BACK FOR DETAILS. FRICTION MATERIAL NOT COVERED.

X

Labor : \$665.80

Parts : \$297.67

Sublet : \$0.00

Other Fees : \$0.00

Subtotal : \$963.47

Sales Tax : \$26.16

Paid By : Total : \$989.63

Pay Ref : Paid : \$0.00

Due : \$989.63



Portola Valley Garage

4170 Alpine Road
Portola Valley, CA 94028
650-851-7442

BAR#ARD264088 RC#264088 EPA# CAL46757



Repair Order #0040162
Original Estimate #0045660

Date : 11/2/17

Page : Page 1 of 1

Center : eScrip



Customer :
Address :
City :
Home :
His Work :



Vehicle : 1975 JENS INTERCEPTOR

License : 263PAU

P/D :

VIN : 2311174

Engine : 440 CU

Trans : AUTO

Mileage : 16314

Tag :

Op	Tech	Description	Labor	Parts	Subtotal
Quan	Part Number	Part Description		Price	
01	041	5SERVICE & SAFETY INSPECTION: ** Service or Inspect ** Lights, tires, fluid levels, drive belts, hoses, cooling system, exhaust, suspension components, brakes, steering linkages. Test antifreeze concentration, test battery (digital & load test) & clean connections as necessary. Lube chassis, including: hood, trunk, & door hinges. Replace oil & filter, rotate tires, Road test. Tire pressure check in PSI LF 32 RF 32 LR 32 RR 32 Spare(if equipped) .	149.00	240.31	389.31
1.00		TRANS FLUID		8.95	
1.00		DRAIN PLUG GASKET		1.21	
1.00		WINDSHIELD WASHER SO		3.91	
1.00		DISPOSAL FEES		7.00	
1.00		OIL FILTER		11.85	
6.00		OIL		35.40	
1.00		BATTERY		155.99	
1.00		FUEL CAP		16.00	

OK Rcnd

Recommendation

OK Rcnd

Recommendation

OK Rcnd

Recommendation

Auth:

Ref:

Exp:

Signature X

Agrees to Pay Total Amount According to Card Issuer Agreement

I acknowledge notice and oral approval of an increase in the original estimated price.

(signature or initials)

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY IS 36 MONTHS OR 36K MILES SEE BACK OF THIS INVOICE, FRICTION MATERIAL NOT COVERED.

X

Labor : \$149.00
Parts : \$240.31
Sublet : \$0.00
Other Fees : \$0.00
Subtotal : \$389.31
Sales Tax : \$20.41
Total : \$409.72
Paid By :
Paid Ref :
Paid : \$0.00
Due : \$409.72



Portola Valley Garage

4170 Alpine Road

Portola Valley, CA 94028

650-851-7442

BAR#ARD264088 RC#264088

EPA# CAL46757



Repair Order #0047147

Date : 2/25/2020

Page : 1

Center : 1 eScrip



Customer :

Address :

City :

Home :

His Work :



Vehicle : 1975 JENS INTERCEPTOR

License : 263PAU

P/D :

VIN : 2311174

Engine : 440 CU

Trans : AUTO

Mileage : 16450

Tag :

Op	Tech	Description	Part Number	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
EL 0		Check fuel filler door Fabricate sleeve for switch				90.00		90.00
01 020		** Service or Inspect ** Lights, tires, fluid levels, drive belts, hoses, cooling system, exhaust, suspension components, brakes, steering linkages. Test anti-freeze concentration, test battery (digital & load test) & clean connections as necessary. Lube chassis, including: hood, trunk, & door hinges. Replace oil and filter. Rotate tires as needed. Road test. Tire pressure check in PSI				180.00	67.39	247.39
		LF 35 RF 35						
		LR 35 RR 35						
		OK Spare(if equipped)						
1.00		M506		WINDSHIELD WASHER SO			3.91	
1.00		DG		DRAIN PLUG GASKET			1.21	
1.00		DF		DISPOSAL FEES			7.00	
6.00		5W30		OIL			41.40	
1.00		1085		OIL FILTER			13.87	
EL 0		Replace right lic plate light				36.00	27.27	63.27
1.00		LPB790A		LIC PLATE LENS/BULB			25.86	
1.00		194		BULB			1.41	
EN 0		Replace engine and trans mounts (pressed in)				630.00	139.53	769.53
2.00		CT2078		ENGINE MOUNT			91.74	

OK Bad	Recommendation	OK Bad	Recommendation	OK Bad	Recommendation
--------	----------------	--------	----------------	--------	----------------

Brakes at 90% Wipers will not shut off at times (needs wiper motor or rebuild) Very slight oil pan leaks.

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY IS 36 MONTHS OR 36K MILES SEE BACK OF THIS INVOICE, FRICTION MATERIAL NOT COVERED.

x

Labor :	\$1,260.00
Parts :	\$253.03
Sublet :	\$0.00
Other Fees :	\$0.00
	\$0.00
Subtotal :	\$1,513.03
Sales Tax :	\$21.49
Paid By :	Total : \$1,534.52
Pay Ref :	Paid : \$0.00
	Due : \$1,534.52

Portola Valley Garage

4170 Alpine Road

Portola Valley, CA 94028

650-851-7442

BAR#ARD264088 RC#264088 EPA# CAL46757

Repair Order #0047147

Date : 2/25/2020

Page : 2

Center : 1

Customer :

Address :

City :

Home :

His Work :

Vehicle : 1975 JENS INTERCEPTOR

License : 263PAU

P/D :

VIN : 2311174

Engine : 440 CU

Trans : AUTO

Mileage : 16450

Tag :

Op	Tech	Description	Part Number	Part Description	Reason for Replacement	Labor	Parts Price	Subtotal
	1.00		CT6983	TRANS MOUNT			35.44	
	1.00			FEDEX			12.35	
		Remove & Replace Oil Pump gaskets				234.00	18.84	252.84
	1.00		GS33770	OIL PUMP GASKET SET			18.84	
EL 0		Lights were dim. Removed all fuses and cleaned contacts.				90.00		90.00

OK Bad

Recommendation

OK Bad

Recommendation

OK Bad

Recommendation

Brakes at 90% Wipers will not shut off at times (needs wiper motor or rebuild) Very slight oil pan leaks.

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY IS 36 MONTHS OR 36K MILES SEE BACK OF THIS INVOICE, FRICTION MATERIAL NOT COVERED.

x _____

Labor :	\$1,260.00
Parts :	\$253.03
Sublet :	\$0.00
Other Fees :	\$0.00
	\$0.00
Subtotal :	\$1,513.03
Sales Tax :	\$21.49
Paid By :	Total : \$1,534.52
Pay Ref :	Paid : \$0.00
	Due : \$1,534.52

Portola Valley Garage

4170 Alpine Road

Portola Valley, CA 94028

650-851-7442

BAR#ARD264088 RC#264088 EPA# CAL46757

Repair Order #0053446

Date : 10/31/2022

Page : 1

Center : 1

Customer :

Address :

City :

Home :

His Work :

Vehicle : 1975 JENS INTERCEPTOR

License : 263PAU

P/D :

VIN : 2311174

Engine : 440 CU

Trans : AUTO

Mileage : 16540

Tag :

Op	Tech	Description	Labor	Parts	Subtotal
Quan	Part Number	Part Description	Reason for Replacement	Price	
O1 020		** Service or Inspect ** Lights, tires, fluid levels, drive belts, hoses, cooling system, exhaust, suspension components, brakes, steering linkages. Test anti-freeze concentration, test battery (digital & load test) & clean connections as necessary. Lube chassis, including: hood, trunk, & door hinges. Replace oil and filter. Road test. Tire pressure check in PSI LF 30 RF 30 LR 34 RR 34 OK Spare (if equipped)	235.00	89.92	324.92
1.00		OIL FILTER XP		27.10	
6.00		OIL		46.80	
1.00		WINDSHIELD WASHER SO		3.91	
1.00		DRAIN PLUG GASKET		1.21	
1.00		DISPOSAL FEES		7.00	
1.00		GREASE		3.90	
EL 0		LF marker inop, correct wiring.. Mis wired. Wiper motor needs attention.. Rebuild or replacement. Shim fuel door switch	235.00		235.00

OK Bad

Recommendation

OK Bad

Recommendation

OK Bad

Recommendation

Brakes 90% Trans and engine oil pan seeping. Rear diff pinion seal seeping. LS outer tie rod boot torn.

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control. WARRANTY IS 36 MONTHS OR 36K MILES SEE BACK OF THIS INVOICE, FRICTION MATERIAL NOT COVERED.

X _____

Labor :	\$470.00
Parts :	\$89.92
Sublet :	\$0.00
Other Fees :	\$0.00
	\$0.00
Subtotal :	\$559.92
Sales Tax :	\$7.41
Paid By :	Total : \$567.33
Pay Ref :	Paid : \$0.00
	Due : \$567.33