



FCA Pacific Region Vintage Concours @ Concorso Italiano • August 20th 2022

CLASS: 5		DATE:		CHASSIS SERIAL NUMBER: 2023 GT					
JUDGE: Brandon Lawrence		JUDGE:		ENTRANT:					
EXTERIOR:		INTERIOR:		ENGINE & CHASSIS:					
JUDGE:		JUDGE:		JUDGE:	Greg Jones				
A	COACHWORK body & fenders	1/2	A	INTERIOR top or headliner	1/2	A	ENGINE Correct Engine Type	0	
B	DOORS, HOOD & TRUNK	1/2	B	UPHOLSTERY Seats, Console, Door & Shelf Panels	1/2	B	ENGINE Correct Serial Number	0	
C	TOP originality & condition	0	C	CARPET, Pedals & Shifter	0	C	ENGINE & DRIVE TRAIN Transmission, Transaxle, Differential, Auxiliaries	0	
D	PAINT	0	D	DASHBOARD Instruments & Components Condition	0	D	FUEL LINES Oil, Fuel, Water and Leaks	0	
E	PLATING Chrome	1/2	E	STEERING WHEEL, Levers, Controls & Column	0	E	ELECTRICAL SYSTEM Components & Battery	1/2	
F	LIGHTS type & fittings	0	F	INSTRUMENTS Clock, Radio, Interior lights operation	0	F	COOLING SYSTEM Radiator, Clamps, Cap, Expansion Tank, etc	0	
G	TRIM & EMBLEMS	1/2	G	TRIM & EMBLEMS		G	FUEL SYSTEM Carburetors, Injection, Linkages	0	
H	GLASS & PLEXIGLASS	1	H	WINDOWS Side, Vent, Rear Operation	1	H	UNDERSIDE Fenders & Frame	0	
I	RUBBER & WINDOW FELT	0	I	TRUNK Carpet, Paint, Decals, Hardware Originality	0	I	CHASSIS Brakes, Suspension Components	0	
J	WHEELS & TIRES	0	J	TOOLS Spare, Manual, Jack, Window Crank, Trouble Light	1	J	EXHAUST Mufflers, Pipes, Cats, Hangers, Manifolds, Resonators	0	
			K	EXTERIOR LIGHTS Operation	0	K	ENGINE OPERATION & CONDITION Smoothness, Condition of Compartment	1/2	
<b>Judges Comments:</b>								<b>Deductions:</b>	
<b>Exterior:</b> Greg - exhaust heat shields from another car, non original coils, radiator shade cable missing, battery cables and terminals, steering box lead seal, oil filter tool, fuel pressure regulator lead seal, oil breather catches right and left missing, engine compartment condition poor, books missing.								EXTERIOR	5
<b>Interior:</b> Brandon - poor chrome, gas cap lock, windshield delaminating, trunk lid pad pulling away, fit of gas cap cover to body, back support on driver's seat marred leather, headliner wrinkled, rubber cracked on bumper overrides								INTERIOR	
<b>Engine &amp; Chassis:</b>								ENG/CHASSIS	2
								TOTAL POINTS DEDUCTED	7
								SCORE (100-TPD)	93
								Platinum Minimum	97
								Gold Minimum	92
								Silver Minimum	87