

# INVOICE

Eason Auto Works

#287U  
P.U. 21.21

Eason Auto Works BAR AG200637

3423 Harlan Street  
OAKLAND, CA 94608  
Phone (510)-420.1262  
FAX (510)-985.2899

DOCUMENT # 0002663 DATE 06/14/2021

CUSTOMER INFORMATION	
NAME	Licence
Fantasy Junction	4PZU402
ADDRESS	
1145 Park Ave	
EMERYVILLE, CA 94608	
TELEPHONES	
(510)-653.7555 / Cel.:	

VEHICLE INFORMATION			
MAKE	MODEL	COLOR	YEAR
PORSCHE	356C		1964
TYPE	VIN NUMBER	ODOMETER	LICENSE PLATE
SEDAN		34,181MI.	120W

**Summary:** get sunroof closed, get car running better, clean driver's side carb, adj valves. Replace oil pressure sender, retorque heads. ign switch adj

LABOR						
DESCRIPTION	LABOR RATE	HOURS:MIN	DISC.%	TOTAL DISC.	TOTAL	
VALVE ADJUSTMENT	195.00	1:0	0.00	0.00	195.00TF	
RETORQUE HEADS	195.00	0:45	0.00	0.00	146.25TF	
REMOVE/REPLACE SPARK PLUGS	195.00	0:30	0.00	0.00	97.50TF	
REMOVE/REPLACE ADJ IGN SWITCH	195.00	0:15	0.00	0.00	48.75TF	
REPLACE SENDER OPS	195.00	0:15	0.00	0.00	48.75TF	
REMOVE/REPLACE SUNROOF ADJ	195.00	0:15	0.00	0.00	48.75TF	
REMOVE/REPLACE OIL PRESSURE SENDER	195.00	0:15	0.00	0.00	48.75	
				<b>TOTAL</b>	<b>\$633.75</b>	

PARTS						
CONDITION	QTY.	DESCRIPTION	PRICE	DISC.%	TOTAL DISC.	TOTAL
OEM New	4.00	SPARK PLUGS	6.00	0.00	0.00	24.00TF
OEM New	2.00	VALVE COVER GASKET	3.00	0.00	0.00	6.00TF
OEM New	1.00	OIL PRESSURE SENDER	40.00	0.00	0.00	40.00TF
OEM New	1.00	ENGINE CLEANER	12.00	0.00	0.00	12.00TF
				<b>TOTAL</b>	<b>\$82.00</b>	

OUTSOURCE JOBS						
DESCRIPTION	PRICE	DISC.%	TOTAL DISC.	TOTAL		
shipping	10.00	0.00	0.00	10.00TF		
				<b>TOTAL</b>	<b>\$10.00</b>	

NOTES:	
QUOTED BY	
palo alto speedometer	
DONE BY	REPAIR ORDER DATE
Bill	

TOTAL SUM	\$725.75
DISCOUNT	- \$0.00
SUB-TOTAL	\$725.75
TAX 9.7500%	+ \$4.75
<b>TOTAL</b>	<b>\$730.50</b>
<b>BALANCE DUE</b>	<b>\$730.50</b>

I authorize Eason Auto Works to perform the above repairs with the necessary materials. I authorize any Eason Auto Works employee to operate the vehicle for testing purposes and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. I agree to pay a storage fee of \$50 per day on vehicle left more than 3 working days after notification that the job is completed.

**THE STABLE**

1700 PINE ST

San Francisco, CA. 94109

Phone: 415-776-2707 Fax: 415-776-2708

**INVOICE****438**

Org. Est. # 000466

BAR 280352

EPA CAL000386368

**INVOICE**

Print Date: 08/10/2015

**Moatz, Aaron**

207 Maple St

1965 Porsche - 356C -

Lic # 1 2AKE669 - CA

Odometer In 30167

Office : 415-354-7289 Cellular : 415-813-9853

VIN # : 222323

Cust ID : 313

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
LENS, FRONT POSITION LIGHT 644 631 411 06	1.00	80.00	80.00	SUNROOF - Release stuck headliner, lubricate and adjust cables, diagnose weak motor	1.20	192.00
DISTRIBUTOR CAP, BREMI REPRO NLA 602 215 00	1.00	26.50	26.50	TUNE UP - Engine backfiring	1.20	192.00
IGNITION ROTOR 616 602 221 01	1.00	14.86	14.86	Points burned, ignition cap worn Service ignition system		
IGNITION POINTS, 2-PIECE 616 602 226 01	1.00	9.54	9.54	Install points and set gap and ignition timing Re-attach loose tail pipe, new hardware		
CONDENSER, IGNITION 616 602 907 02	1.00	12.12	12.12	ENGINE OIL AND FILTER - Replace	0.50	80.00
ENGINE OIL, Kendall GT1 20W50 KENDALL GT1 20w50	4.00	7.00	28.00			
OIL FILTER 546 07 827	1.00	12.60	12.60			
Shop Supplies			2.75			

Org. Estimate 666.68 Revisions 0.00 Current Estimate 666.68

**Labor: 464.00****Parts: 186.37****Sub: 650.37****Tax: 16.31****Total: 666.68****Bal Due: \$666.68**

[ Payments - ]

**WE APPRECIATE YOUR BUSINESS**

Parts and labor are covered by a 1 year unlimited mileage warranty.  
Warranty repair costs shall in no case exceed the cost of the original repair or service.  
This warranty does not in any way include incidental or consequential damages.  
Vehicle must be returned to The Stable for any warranty repairs.