

Interstate Batteries of North Arizona
9021 East Florentine Rd
Prescott Valley
(928) 772-4511

AZ 86314



DEALER NBR. 167
GB FINE BRITISH CARS, LTD
8785 E FLORENTINE RD
PRESCOTT VALLEY AZ 86314-8773
(602) 315-4715
Payment Type: CASH/HOLD

Invoice Nbr :76760
Location of Sale :W01
Sales Person Name :GEOFFRY CARVER
Sales Person Nbr :045
PO Number :
Date :5/25/2021
Time :11:52 AM

Type	Qty	Part Number/Desc	Age	Rate	Price	Amount
Sale	3	630693			5.19	\$15.57
		Sales Total				\$15.57
		Sub Total				\$15.57
Tax ID --> PVL		2300 PRESCOTT VALLEY TAX				\$1.43
		Sub Total				\$17.00
		Invoice Total				\$17.00
		Invoice Payment Amount				\$17.00
Payment apply to 76760		CASH				\$17.00
		Net Invoice				\$0.00
***** DEALER AGING *****						
Dealer Aging - Current Balance					Total	\$17.00
		0 to 30 days				\$17.00
		31 to 60 days				\$0.00
		61 to 90 days				\$0.00
		91 days or more				\$0.00
Invoices		63808				\$50.42
		63825				(\$50.42)
		76760				\$17.00

PRINT NAME HERE _____

SIGNATURE _____

LAFAYETTE MOTORS

3470 GOLDEN GATE WAY
LAFAYETTE CA, CA 94549
PH: 925-284-4852
FX: 925-284-1466
CAL000382942
BAR# 271136



WWW.LAFAYETTEMERCEDESMOTORS.COM

REPAIR ORDER# **330322002**

DATE: 03/22/23 04:06 pm

PAGE: 1

TERMS:

CUSTOMER: FANTASY, JUNCTION	VEHICLE: 16 MercedesBenz E63 AMG
ADDRESS: 1145 Park Ave	LICENSE: CSJ5829/ FLEET:
CITY: Emeryville, CA 94608	VIN: WDDHH7GBXGB233870
PH #:(Bus)(Res):	ENGINE: Cyl V8 Disp 5.5
Cell Phone: 510-653-7555	MILEAGE: 29057 COLOR: WHI

SERVICE REPAIR INSTRUCTIONS/CONCERNS

VEHICLE TOWED IN REAR AIR SUSPENSION COLLAPSED, VEHICLE INSPECTION/DIAGNOSTIC SUSPENSION ISSUES

TECH	QTY	PART NO	REPAIR / SERVICE DESCRIPTION	PARTS	LABOR
001			AIRMATIC COMPRESSOR RELEASE AIR PRESSURE AT THE AIRMAITC SYSTEM, REMOVE UNDER VEHICLE PANELING, REPLACE AIRMATIC COMPRESSOR AND RELAY REASSEMBLE COMPONENTS, CLEAR DIAGNOSTIC TROUBLE CODES, CALIBRATE AIRMATIC SUSPENSION TOWERS, ROAD TEST OK.		722.00
	1.0	212 327 07 45	Compressed Air Line	48.00	
	1.0	212 320 04 04-80	Suspension Compressor	945.00	
	1.0	39160-37110	Relay	42.08	
001			DIAGNOSTIC / INSPECTION DIAGNOSTIC OF AIRMATIC SUSPENSION MALFUNCTION, FOUND MAIN AIR FEED LINE BROKEN CAUSING CONTINUOUS AIR COMPRESSOR ACTIVATION, FAULTY AIR PUMP AND RELAY. ADVISE AND REPAIR.		N/C

3892
P. 3.22.23

CUSTOMER REQUEST RETURNED PARTS YES NO	PAYMENTS / SURCHARGE DETAIL	TOTALS
RECOMMENDATIONS	1 03/22/23 1847.65 Check 3892 4:06 pm	LABOR:\$ 722.00 PARTS:\$ 1,035.08 SURCHRG:\$ 0.00 SUBLET:\$ 0.00 SUPPLIES:\$ 0.00 DISCOUNT:\$ 0.00 HAZMAT:\$ 0.00
TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____	I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. WARRANTY: 12,000 MILES OR 12 MONTHS ON PARTS (Signature) _____	TAX:\$ 90.57 TOTAL:\$ 1847.65 PAID:\$ 1847.65 DUE:\$.00