


TFB PERFORMANCE INC  
29703 Arnold Dr  
CA US  
(415)205-2222  
tfbperformance@gmail.com  
<http://www.tfbperformance.com/>



## INVOICE

**BILL TO**

Fantasy Junction  
1145 Park Ave  
Emeryville, CA 94608  
United States

**SHIP TO**

Fantasy Junction  
1145 Park Ave  
Emeryville, CA 94608  
United States

**INVOICE # 9627****DATE 11/16/2023****VEHICLE**

Ford GT

DATE	ACTIVITY	QTY	RATE	AMOUNT
11/16/2023	<b>Labor</b> Labor - remove drivers side half shaft to take pictures and send to The Drive Shaft Shop who said they could make replacement shafts, but final quote showed they were going to re-use the joints and boots so I ordered replacement hardware to remedy problem. Drill new hardware for safety wire. Repack inner CV joints and replace hardware in CV hub and inner CV joint and safety wire. Required removing entire suspension corner on each side of car. Remove diffuser to clean all grease from engine bay. Reassemble and test drive car.	12	150.00	1,800.00
11/16/2023	<b>Reimbursement</b> 10x1.5x50 and 8x1.25x25 hardware, CV grease, mutli purpose solvent	1	97.98	97.98
11/20/2023	<b>Reimbursement</b> Cool tech rear hatch gas strut pair includes tax and shipping	1	218.96	218.96

SUBTOTAL	2,116.94
TAX	0.00
TOTAL	2,116.94
BALANCE DUE	<b>\$2,116.94</b>