

Atlas Motorcars LLC
 3300 SW 14th Place Units 4-6,
 Boynton Beach, FL 33426

Invoice

Bill To

Date	Invoice No.	P.O. Number	Terms	Project
10/16/23	26		Net 15	1993 PORSCHE...

Item	Description	Quantity	Rate	Amount
Service Income	Perform vehicle inspection upon arrival. Road test vehicle post completion of work.	1	215.00	215.00
Service Income	Vehicle arrived with broken glove box. Repair as needed.	0.5	215.00	107.50
Service Income	Perform oil change service. Change oil and filter, fill with new fluid.	2	215.00	430.00
Service Income	Change fuel filter.	0.5	215.00	107.50
Parts	Fuel filter	1	46.62	46.62
Parts	Drain plug sealing ring	1	2.61	2.61
Parts	Oil filter	1	15.82	15.82
Parts	Motor oil	8	12.60	100.80
Service Income	Replace door speakers. Modify speaker housing and adapt to new speakers for OEM look for use of stock grills. Modify speaker connection to fit aftermarket speaker.	1.5	215.00	322.50
Parts	Kenwood door speakers pair	1	65.00	65.00
Service Income	Install customer supply original muffler.	0.5	215.00	107.50
Service Income	Install front shock bump stops and bellows. Removal and disassembly of front socks in order to facilitate repair. Road test.	3	215.00	645.00
Parts	Strut bump stops	2	21.88	43.76
Parts	Strut bellows	2	34.00	68.00
Service Income	R&R sway bar links.	0.5	215.00	107.50
Parts	Sway bar links	2	245.04	490.08

Subtotal	\$3,607.69
Sales Tax (0.0%)	\$0.00
Total	

Atlas Motorcars LLC
 3300 SW 14th Place Units 4-6,
 Boynton Beach, FL 33426

Invoice

Bill To

Date	Invoice No.	P.O. Number	Terms	Project
10/16/23	26		Net 15	1993 PORSCHE...

Item	Description	Quantity	Rate	Amount
Service Income	Bleed breaking system and top off fluid as needed. System opened during suspension install.	0.5	215.00	107.50
Outside Service	Alignment	1	350.00	350.00
Parts	Bypass pipe	1	275.00	275.00
Service Income	*NOTE: Vibration at steering wheel at 40 mph +. Even though tires are dated 2022, tires are out of round. Possibly due to prolonged storage without movement*		0.00	0.00
			Subtotal	\$3,607.69
			Sales Tax (0.0%)	\$0.00
			Total	\$3,607.69

Work Order: 97010
 VIN: WP0AB2967RS419126
 Date: 10/19/23 3:53 PM



WP0AB2967RS419126

Porsche 1994 911 Carrera RS America
 ExpressAlign Total Alignment

Front : Left

Actual	Before	Specified Range
-0.1°	-2.1°	-0.4° -0.1°
3.7°	3.4°	3.9° 4.7°
0.26°	0.50°	0.17° 0.33°
20.4°	19.9°	
20.3°	17.8°	
		-1.83° -0.83°

Front : Right

Actual	Before	Specified Range
-0.3°	-2.0°	-0.4° -0.1°
4.1°	3.9°	3.9° 4.7°
0.26°	0.55°	0.17° 0.33°
20.2°	20.3°	
19.9°	18.4°	
		-1.83° -0.83°

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0.1°	-0.2°	-0.2° 0.2°
-0.4°	-0.5°	-0.3° 0.3°
0.2°	-0.4°	
0.53°	1.06°	0.33° 0.67°

Rear : Left

Actual	Before	Specified Range
-0.6°	-1.2°	-0.9° -0.3°
0.31°	0.28°	0.17° 0.33°

Rear : Right

Actual	Before	Specified Range
-0.6°	-0.6°	-0.9° -0.3°
0.27°	0.09°	0.17° 0.33°

Camber
 Toe

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0.0°	-0.6°	-0.3° 0.3°
0.58°	0.36°	0.33° 0.67°
0.02°	0.10°	-0.17° 0.17°

The steering wheel is currently level.