

PATRICK OTTIS
1220 TENTH STREET
BERKELEY, CALIFORNIA 94710
BAR NO AK120777

INVOICE

©1998 REDIFORM 72721

INVOICE NO.

00268

① RT REAR SMALL ART. LOCATE NO PROBLEM
② SECOND WORK COULD FIX
③ KNOCK NOT OCTANE
④ NOT WORKING 2-3 HOURS A PROBLEM HURT ENGINE BEATER
⑤ ELECTRIC PUMP

SC [REDACTED]
AD [REDACTED]
CI [REDACTED]

SHIP TO: [REDACTED]
ADDRESS: [REDACTED]
CITY, STATE, ZIP

CUSTOMER'S ORDER	SOLD BY:	TERMS:	F.O.B.	DATE:
7506TE/CAUFSPY	4487	THANK YOU	12860 KHS	12 JUNE 02

7 JUNE	1	ROAD TEST CAR, ASSESS OPERATION AND BRING DRIVELINE OILS TO
	2	TEMPERATURE. LIFT CAR, DRAIN MOTOR OIL. INSPECT CHASSIS AND
	3	BRAKES. CHECK ELECTRIC FUEL PUMP OPERATION - OK. CHECK
	4	FOR CAR HARD TO START COLD & WARM - OK. CHECK FOR MOTOR
	5	KNOCKS ON STARTS - NONE HEARD, BUT CAN INDUCE SLIGHT KNOCKING
	6	ON STEEP UPHILL WITH REDUCED ENGINE SPEED. CLEAN SLIGHT
	7	OIL RESIDUE FROM RIGHT REAR ROAD WHEEL AND HUB. SECURE
	8	GRILL SURROUND RUBBER TRIM TO GRILL WITH SUPER GLUE.
	9	ADD 9 QTS KENDALL W/50. REPLACE OIL FILTERS. TOP UP COOLANT
	10	LEVEL. TOP UP BATTERY ELECTROLYTE LEVEL. SET TIRE

PATRICK OTT S

INVOICE

©1998 REDIFORM® 7L721

INVOICE NO.

0027

SOLD BY:	[REDACTED]
ADDRESS:	
CITY, STATE, ZIP	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER 750 CAUF	SOLD BY: 4487	TERMS:	F.O.B.	DATE: 12 JUNE 02
------------------------------	------------------	--------	--------	---------------------

1	PRESSURE TO 32 LB F&R. ATTEMPT TO CHECK SPARE TIRE PRESSURE
2	CANNOT PULL SPARE OUT, FOULING ON HOSE CLAMP FOR PULL
3	TANK FUL HOSE. REPOSITION HOSE CLAMP. SET SPARE TIRE
4	PRESSURE. ADJUST STEERING GRAMBOX. ROAD TEST CAR - STEERING
5	MUCH IMPROVED. NOTE HORN IS NOT VERY LOUD, HARD TO ACTIVATE.
6	LUBRICATE HORN COMPRESSOR. REPLACE KINKED HOSE TO ONE
7	HORN). CHECK FUNCTION - HIGH TONE HORN IS STILL INOPERATIVE.
8	NEEDS CLEANING OR ADJUSTMENT OF SWAMPOT TO BODY AGAINST REED.
9	REPAIR STEERING WHEEL. ADJUST HORN CONTRAST - REINSTALL
10	STEERING WHEEL

PATRICK OTIS

INVOICE

©1998 REDIFORM® 7L721

INVOICE NO.

0028

SOLD TO	[REDACTED]
ADDRESS	[REDACTED]
CITY, STATE, ZIP	[REDACTED]

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER 250 CAUF	SOLD BY: 4487	TERMS:	F.O.B.	DATE: 12 JUNE 02
------------------------------	------------------	--------	--------	---------------------

1	SHOP LABOR 5.5 HRS @ 90 ⁰⁰		495 ⁰⁰
2			
3	9 QTS KENDALL GT. 120/50 MOTOR OIL @ 30 ⁰⁰		27 ⁰⁰
4	FRAM PH 2815 OIL FILTER		19 ⁹⁵
5	FRAM PB 50 OIL FILTER		10 ⁰⁰
6	PAINT WORK		56 ⁹⁵
7	TAX ON PAINT		4 ⁶⁹
8	91 OZONE ROLL		23 ⁰⁰
9	WASH DETAIL	NO OUTLINE	
10	JOB TOTAL		579 ⁶⁴

PATRICK OTT S
1220 TENTH STREET
BERKELEY, CALIFORNIA 94710
BAR NO AK 120777

INVOICE NO.

6588

PO
6/4/03
C-13028

SOL

ADD

CITY

CUSTOMER'S ORDER

250 GTE/CAUF SPY

SOLD BY:

4487

TERMS:

THANK YOU

F.O.B.

13801 KMS

DATE:

03 JUNE 03

QUANTITY

DESCRIPTION

PRICE

AMOUNT

30 MAY

- 1 INVESTIGATE "SHORT" INABILITY TO POWER UP IGNITION COILS WORK
- 2 IGNITION SWITCH. CHECK POWER TO IGNITION SWITCH. TRACE
- 3 FAULT TO FAILED FUSE. REPLACE FUSE, CHECK IGNITION FUNCTION
- 4 OK. CONTINUE ELECTRICAL INVESTIGATION, DISCOVER BRAKES
- 5 TAIL TOGGLE TO FARE RIGHT WHEN SWITCHED CAUSES THIS
- 6 FUSE TO FAIL. REPLACE FUSE - INSTALL IGNITION SWITCH BACK
- 7 INTO DASH. INVESTIGATE "GREEN WIRE" WIRING UNDER DASH
- 8 (HEADLAMP PRIMARY WIRE) PLUG BACK INTO HEADLAMP SWITCH
- 9 UNDER DASH. ROAD TEST CAR, ASSESS OPERATION, BRING
- 10 MOTOR OIL BACK TO TEMP, LEFT CAR, DRAIN FUTURE OIL.

PATRICK OTTIS

INVOICE NO.

6589

SOLD TO:

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CMW

SOLD BY:

4487

TERMS:

F.O.B.

13801 VMS

DATE:

03 JUNE 03

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1 REPLACE OIL FILTERS, REPLENISH SUMP WITH KENDALL MARZOL

2 REMOVE ROAD WHEELS, INSPECT CHASSIS BRAKES. FLUSH BRAKE

3 SYSTEM INCLUDING BRAKE BOOSTER, LUBRICATE FRONT SUSPENSION

4 STEERING. INSTALL ROAD WHEELS - TORQUE WHEEL NUTS. 5.0

03 JUNE 5 CONTINUE WITH RECURRENT INVESTIGATION - SHORT AT FOG LIGHT

6 SWITCH. REMOVE BOAT FOG LAMP LENSES. TRACE CAUSE OF SHORT

7 TO THE RIGHT FOG LIGHT CONNECTION TOUCHING THE LAMP HOUSING

8 REROUTE WIRES TO BULB SOCKET AND INSULATE INSIDE OF LAMP

9 WORKING. REASSEMBLE FOG LAMPS - TEST GOOD. 1.0

10 SHOP LABOR 6.0 HRS @ 90 540 -

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS

INVOICE NO.

6590

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250GT CAMEL

SOLD BY:

4487

TERMS:

F.O.B.

13801KMS

DATE:

03 JUNE 03

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1 8 QTS KENDALL GT. 120/50 MOTOR OIL @ 3

24 -

2 FRAM PH 2815 OIL FILTER

19 95

3 FRAM PB 50 OIL FILTER

10 -

4 CASTROL LMA BRAKE FLUID

12 -

5 FUSES

2 -

6 PARTS TOTAL

67 95

7 TAX ON PARTS

5 60

8 91 OCTANE FUEL

25 -

9 WASH DETAIL CAR

NO CHARGE

10 JOB TOTAL

638 55

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS
1220 TENTH STREET
BERKELEY CALIFORNIA 94740
BAR NO AK120777

INVOICE NO.

8387

SO

AD

CIT

CUSTOMER'S ORDER

250 GTR/CAUF SPY

SOLD BY:

4487

TERMS:

THANK YOU

F.O.B.

17,918 KMS

DATE:

25 OCTOBER 05

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1400T.	1 GO OVER LIST OF ISSUES SUPPLIED WITH CAR. ATTEMPT TO START		
	2 MOTOR. NO POWER AT ELECTRIC FUEL PUMP. BATTERY IS		
	3 DISCONNECTED FROM IGNITION SWITCH. CONNECT BATTERY, NOW		
	4 FUEL PUMP WORKS, BUT MOTOR DOESN'T START. REMOVE AIR		
	5 FILTER LID AND CHECK CARB FUNCTION. NO ACCELERATOR PUMP		
	6 FUNCTION ON #2, #3 CARBS. CHECK FUEL PRESSURE AT FUEL		
	7 RAIL WITH ELECTRIC PUMP. 3 - 3 1/2 PSI. NOTE PRESSURE REGULATOR		
	8 GLASS BOWL HAS 1/4 INCH SOOT ON BOTTOM, FUEL IS MILKY. REMOVE		
	9 AIR FILTER HOUSING. REMOVE CARB TOPS. CARBS HAVE SEDIMENT		
	10 IN BOTTOMS OF ALL FUEL BOWLS. DISCHARGE NOZZLES CLOGGED 3.0		

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS

INVOICE NO.

8388

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

2506TR/CAL SP4

SOLD BY:

4487

TERMS:

F.O.B.

17918KHS

DATE:

25 OCTOBER 2005

INVOICE

71721 ©2001 REDFORM® 030901

QUANTITY	DESCRIPTION	PRICE	AMOUNT
17 OCT	1 INSTALL NEW WEBBER NEEDLE/SEAT ASSEMBLY WITH NEW SEAL		
	2 RINGS. SET FLOAT HEIGHTS. CLEAN MUD OUT OF CARB FLOAT		
	3 BOWLS. REPLACE CARB TOP GASKETS. INSTALL CARB TOPS.		
	4 FILL FLOAT BOWLS WITH FUEL AND CHECK ACCELERATOR PUMP		
	5 FUNCTION ON ALL CARBS - OK. DRAIN FUEL TANK, FUEL LOOKS		
	6 CLEAN. REMOVE REAR FUEL BOWL AND INSPECT - VERY SLIGHT		
	7 SEDIMENT AT BOTTOM OF BOWL - FUEL LOOKS CLEAN. REPLACE		
	8 FRONT AND REAR FUEL FILTER ELEMENTS. CHECK FUEL		
	9 GAUGE READING WITH TANK EMPTY - WARNING LIGHT IS ON -		
	10 NEEDLE IS JUST ABOVE THE "O" LINE. NOTE FUEL FUEL		

Pharmas Oils

INVOICE NO.

8389

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTF/CM SP4

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 08

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	PUMP IS MOUNTED UPSIDE DOWN - THIS AFFECTS PUMP FUNCTION		
2	AS CHECK VALVE IS DESIGNED TO HAVE GRAVITY HELP IT CLOSE.		
3	PUT 10 GALLONS OF FUEL IN TANK. FUEL GAUGE NOW READS		
4	1/8 TANK AND THE LIGHT IS OFF. TURN FUEL PUMP ON		
5	AND CHECK FLOW. NO FLOW, PUMP WILL NOT PRIME. APPLY AIR		
6	PRESSURE TO FILTER TO ASSIST PUMP IN PRIMING - STILL WON'T		
7	PRIME. REMOVE FUEL PICK UP STALK - FUEL LEVEL IS ABOVE		
8	BOTTOM OF PICK UP TUBE - OK, BUT PICK UP HAS NO FUEL SOCK/		
9	SCREEN ON IT AS ORIGINAL - DRAWER TO NORMAN RACING WORK		
10	AN ORIGINAL SAMPLE FOR COPYING. CHECK SECTION AT FUEL		

INVOICE

71721 02001 REDFORM 030901

PATRICK OTTIS

INVOICE NO.

8390

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR / CMR SPN

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 05

INVOICE

7L721 ©2001 REDIFORM® 030901

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	TANK HOSE TO FILTER, WITH FURZTAL PUMP ON, NO SWOON!		
2	BENCH TEST ANOTHER FIPA FURZTAL PUMP. RIGHT SIDE UP		
3	PUMP GENERATORS ONE INCH OF MERCURY, UPSIDE DOWN PUMP		
4	GENERATORS 0 VACUUM. RECOMMEND REPAIRING MOUNT		
5	AND PIPES TO FURZTAL FUEL PUMP SO THAT PUMP IS IN CORRECT		
6	ORIENTATION. INSPECT UNDER CAR. WATER PUMP IS LEAKING.		
7	7.12 CM COVER IS LEAKING OIL. REMOVE, DISASSEMBLE. IGNITION		
8	SWITCH. CHECK SWITCH CONTACTS AND REASSEMBLE SWITCH 6.0		
1800T	REPLACE POOR QUALITY, LOOSE CRIMP CONNECTORS AT WIRING		
10	WIRING TO IGNITION SWITCH. CHECK FOR RESISTANCE / BREAK		

PATRICK OTTAS

INVOICE NO.

8391

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR/CAMP SPY

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 05

INVOICE

7L721 ©2001 REDIFORM® 030901

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	IN BLUE WIRE FROM IGNITION SWITCH TO PULSEBOX - OK. INTERNAL		
2	IGNITION SWITCH IN DASH. (CHECK BRAKE LIGHT FUNCTION,		
3	MUST DEPRESS PEDAL FAIRLY HARD IN ORDER FOR BRAKE		
4	LIGHTS TO WORK.) CHECK STEERING FOR PLAY - LOOSE ON CENTER.		
5	CHECK FOR PLAY IN TIE RODS, IDLER ARM, KING PINS - OK.		
6	CHECK STEERING WHEEL ORIENTATION, WHEEL IS OFF SET		
7	TO THE RIGHT ON THE HUB. STEERING GEARBOX IS WITH OFF		
8	ON STRAIGHT AHEAD POSITION, WHEEL IS LOCKED TO THE LEFT		
9	WHEN BOX IS STRAIGHT AHEAD, PITMAN ARM INSTALLED IN		
10	INCORRECT ORIENTATION. REMOTE AIR HORNS AND COMPRESSOR		

ATruck OTIS

INVOICE NO.

8392

SOLD TO: [REDACTED]
ADDRESS:
CITY, STATE, ZIP

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER 250 GTR/CAMP SPY **SOLD BY:** 4487 **TERMS:** **F.O.B.** 17918 KMS **DATE:** 2500203R20S

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 IN ORDER TO REPAIR STEERING GEARBOX - OIL LEAK IN STEERING		
	2 BOX W/ CURVE RECORD TIE ROD LENGTHS AS FOUND. REMOVE		
	3 AND DISASSEMBLE STEERING GEARBOX. OIL WAS LIKE GLASSES. 5.5		
19 OUT.	4 CURVE GASKET SUPPLERS ON STEERING BOX HOUSING AND COVER.		
	5 CURVE ALL CASTINGS. INSTALL NEW WORM GEAR BEARINGS/ SHAFT		
	6 AND SHIM. INSTALL NEW SEALS IN HOUSING. FINISH ASSEMBLY		
	7 STEERING GEARBOX. INSTALL PITMAN ARM, TORQUE NUT. FULL		
	8 WITH GEAR OIL. ADJUST RECORD SHAFT. 4.5		
20 OUT.	9 SET STEERING GEARBOX TO CENTER POSITION. MARK NEW		
	10 WORM GEAR SHAFT. REMOVE STEERING WHEEL FROM HUTS -		

INVOICE

7L721 02001 REFORM 030901

PATRICK OTMS

INVOICE NO.

8393

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR/CHUMSPY

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 2005

INVOICE

71721 ©2001 REDFORM® 030901

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	OFF ONE HOLE. ORIENT STEERING WHEEL CORRECTLY ON HUBS AND		
2	REINSTALL. CURVE OFF MOUNTING STUDS FOR STEERING GRAMBOX.		
3	REPLACE GRAMBOX MOUNTING NUTS AND WASHERS. INSTALL		
4	STEERING GRAMBOX. CHECK GRAMBOX ADJUSTMENT AFTER.		
5	INSPECTION - OK. NOTE STEERING GRAMBOX U-JOINT COUPUNG		
6	HAS BEEN RUBBING ON ONE HEATER HOSE - ALMOST WORN THROUGH.		
7	RECOMMEND REPLACEMENT OF HEATER HOSE. CONTROL TIE RODS.		
8	INSTALL HORN COMPRESSOR. INSTALL LEFT FRONT WHEEL. CHECK.		
9	ADJUST TIRE PRESSURES. CHECK FRONT TOR WITH DUNLOP GAUGES.		
10	STEERING WHEEL IS COCKED TO THE RIGHT. READJUST CENTER.		

PATRICK OTIS

INVOICE NO.

8394

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR/CAUSEWAY

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 05

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 AND LEFT TIRE RODS TO STOCK LENGTHS. ADJUST FRONT TOE IN.		
	2 BALANCE LEFT FRONT ROAD WHEEL.		6.0
21 OUT.	3 BALANCE OTHER THREE ROAD WHEELS. FRESH BURNED BRAKES		
	4 HYDRAULIC SYSTEM TO INCLUDE BRAKE POWER BOOSTER ASSEMBLY.		
	5 REMOVE HYDRAULIC PULL PUMP, REMAIN MAIN FUEL PUMP ASSEMBLY		
	6 HOSES AND PIPE. CUT NON ORIGINAL PUMP BRACKET OFF OF		
	7 REMAIN RAIL. GRIND FRAME TUBE SMOOTH.		4.0
24 OUT	8 CURRY UP BOTTOM PORTION OF ORIGINAL FUEL PUMP BRACKET		
	9 CUT OFF OLD GUSSETS. FABRICATE NEW SIDE BRACKET AND		
	10 GUSSET TO DUPLICATE ANOTHER 250 SWB CAUSEWAY IN OUR SHOP.		

INVOICE

7L721 02001 REFORM 030901

PATRICK OTTIS

INVOICE NO.

8395

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR/CMRSP4

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 05

QUANTITY

DESCRIPTION

PRICE

AMOUNT

2500T

- 1 WELD BOTTOM, SIDE AND GUSSET TO GETHER. CLEAN UP AREA
- 2 ON FRAME RAIL FOR MOUNT. TACK WELD MOUNT TO FRAME
- 3 RAIL. HAVE DENNIS / NORMAN RACING PERFORM RAIL WELD TO
- 4 FRAME. DESOLDER ORIGINAL FITTINGS FROM FILTER TO PUMP
- 5 PIPE. CLEAN UP INSIDE OF FITTINGS. CLEAN AND PAINT BRACKET/
- 6 WELDING AREA 5.5
- 7 REMOVE MASKING TAPE. MOUNT FUEL PUMP. CLEAN
- 8 FUEL FILTER HOUSING AND NOTE FUEL PUMP IS ALFA ROMEO
- 9 APPLICATION, THAT IS FUEL FLOW ORIENTATION IS REVERSED FROM
- 10 PERMANENT PRACTICE. ORDER USED FUEL PUMP HOUSING. INSTALL

INVOICE

71721 G2001 REFORM 030501

PATRICK OTTIS

INVOICE NO.

8396

SOLD TO:

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTE/CAMP SPR

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

25 OCTOBER 05

INVOICE

7L721 ©2001 REDFORM® 030901

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	REMOVE EXISTING AS A MOCK UP. FABRICATE / BEND NEW PIPING FOR		
2	FULL FUTURE OUTLET TO FULL PUMP INLET. DISCONNECT PIPE		
3	FROM FUTURE TO MECHANICAL PUMP. BLOW FULL OUT OF PIPE.		
4	CUT BANDO FITTING OFF OF PIPE. RESOLDER PIPE FROM BANDO		
5	FITTING AND CLEAN UP FITTING. FABRICATE FEMALE / FEMALE		
6	UNION FOR JOINING TWO PIPES TOGETHER. CUT AND BEND		
7	SMALL SECTION OF PIPE TO EXTEND EXISTING PIPE FROM FUTURE		
8	PUMP TO FULL RAIL. SOLDER BANDO FITTINGS ONTO PIPE		
9	FROM FUTURE TO ELECTRICAL PUMP AND ONTO SMALL PIPE		
10	REVISION		S.S

PATRICK OTIS

INVOICE NO.

8397

SOLD TO

ADDRESS

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTE/CANF SPN 4487

SOLD BY:

TERMS:

F.O.B.

17918KMS

DATE:

2500708M205

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1	SHOP LABOR TO DATE 40.0 HRS @ 100		4000 ⁻
2			
3	3 WEBER TOP COVER GASKETS 41705.011 @ 12		36 ⁻
4	3 WEBER NEEDLE SEAT ASSEMBLIES 79503.175 @ 17 ⁹⁵		53 ⁸⁵
5	3 WEBER NEEDLE SEAT SEAL RINGS 41535.015 @ 2 ⁵⁰		7 ⁵⁰
6	REAR MAIN FUEL FILTER 95180050		24 ⁹⁵
7	FUEL PRESSURE REGULATOR FILTER 95180053		12 ⁹⁵
8	COPPER PLATED AL OIL. FUEL LINES LINE MATERIAL		50 ⁻
9	PAINT FOR CAMELS TO MATCH AT NEW FUEL PUMP MOUNT		12 ⁻
10	CASTROL LMA BRMKE PWID		12 ⁻

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTIS

INVOICE NO.

8398

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR/ENR-SM 4487

SOLD BY:

TERMS:

F.O.B.

17918 KMS

DATE:

2500703M205

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1 STEERING GEARBOX TOP COVER GASKET 8161033104

10 -

2 STEERING GEARBOX SEAL SET 8161033800

58 75

3 STEERING WORM GEAR/PIN SET (FROM THE NETHERLANDS)

2200 -

4 STEERING GEARBOX 140 HYPOID GEAR OIL

10 -

5 NEW HARDWARE CHANGE, STEERING & ROLL

25 -

6 PARTS TOTAL TO DATE

2513 00

7 TYPON PARTS

219 88

8

9

10

JOB TOTAL TO DATE

6732 88

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS

1220 TINTA STREET

BERKELEY, CALIFORNIA 94710

BAR NO AK 120777

INVOICE NO.

8417

SO [REDACTED]
AI [REDACTED]
CI [REDACTED]

CUSTOMER'S ORDER: 2506TE/CAUFSPY
SOLD BY: 4487
TERMS: THANK YOU
F.O.B. 17,918 KHS
DATE: 09 NOVEMBER 2005

QUANTITY	DESCRIPTION	PRICE	AMOUNT
26 OCT	1 SOLDER EXTENSION PIPE ONTO FUEL PIPE IN CAR. CLEAN UP		
	2 SOLDER JOINT. PRESSURE/VACUUM TEST ALL PIPES FOR LEAKS.		
	3 INSTALL ELECTRIC FUEL PUMP. CONTROL WIRING AND PIPE.		
	4 CLEAN OFF OLD TAPE AND RESIDUE FROM TAILPIPE TIPS. LEFT		
	5 PIPES HAD 10MM WIDE TAPE, RIGHT HAD 13MM WIDE. CUT NEW		
	6 TAPE TO 13MM WIDE AND INSTALL ON TAILPIPES. CLEAN CHROME		
	7 TIPS. REMOVE INSIDE WINDOW WIPPER GUIDE FROM DOOR. CLEAN		
	8 GLUE RESIDUE OFF OF DOOR. STRAIGHTEN BOTH WINDOW		
	9 WIPERS.		S.O
27 OCT	10 DRAIN COOLING SYSTEM. REMOVE FAN SUPPORT. REMOVE LOWER		

INVOICE
71721 ©2001 REDIFORM® 030901

Patrick Otis

INVOICE NO.

8418

SOLE

ADDRESS

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CMF SPY

SOLD BY:

4487

TERMS:

F.O.B.

17918 KHS

DATE:

09 NOV 1985

QUANTITY

DESCRIPTION

PRICE

AMOUNT

- 1 RADICORZ HOSE AND WATERPUMP INLET. PUMPE OUTLET CASTING.
- 2 PUMPE WATERPUMP COVER. PUMPE IMPURER, SEPARATOR IMPURER
- 3 BACKING FROM IMPURER. INSPECT SEAL - CARBON SEAL FACE HAS
- 4 DECONTAMINATED FROM RUBBER, CAUSING CRACK. CURN WATER
- 5 PUMP PARTS. 4.0
- 28 OCT. 6 ATTEMPT DRILLING A HOLE IN IMPURER BACKING FOR PUMP. ATTEMPT
- 7 SURFACING IMPURER BACKING - GROOVED & PITTED. CURN GASKE
- 8 MATING SURFACES ON WATERPUMP HOUSING, INLET TUBE, OUTLET
- 9 CASTING, BLOCK & FRONT COVER. SODA BLAST INLET TUBE,
- 10 BADLY POTTED. FULL DAMAGED AREA WITH J.B. WELD EPOXY.

INVOICE

7L721 ©2001 REDFORM 030901

Patrick Otis

INVOICE NO.

8419

SOLD TO: [REDACTED]

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER 250 CAMP SPY **SOLD BY:** 4487 **TERMS:** **F.O.B.** 17918 KHS **DATE:** 09 NOV 05

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 REMOVE BANK 7-12 IGNITION WIRES, REMOVE 7-12 CAM COVER		
	2 REMOVE FUEL PUMP, BEGIN REMOVAL OF FUEL PUMP DRIVE S.O		
31 OUT.	3 REMOVE STOCK! FUEL PUMP DRIVE, REMOVE 7-12 CHAIN COVER,		
	4 CLEAN UP FUEL PUMP DRIVE GASKET MATING SURFACES. BENCH		
	5 TEST MECHANICAL FUEL PUMP, NOT FUNCTIONING CORRECTLY.		
	6 DISASSEMBLE PUMP. CHECK DIAPHRAM OK. MACHINE ALL		
	7 SURFACES FLAT. REPLACE HARD/CRAKED VALVE SEALS AND		
	8 COVER SEAL. ASSEMBLE AND BENCH TEST PUMP - GOOD. CLEAN		
	9 NEWLY RECEIVED REAR MAIN FUEL FILTER HOUSING. ASSEMBLE		
	10 HOUSING WITH CUSTOMERS FILTER BOWL AND HARDWARE.		

INVOICE
7L721 02001 REDFORM 030901

PATRICK OTTIS

INVOICE NO.

8420

SOLD BY: [REDACTED]

ADDRESS: [REDACTED]

CITY, STATE, ZIP: [REDACTED]

SHIP TO:

ADDRESS:

CITY, STATE, ZIP:

CUSTOMER'S ORDER: 250 CMR SP4

SOLD BY: 4487

TERMS:

F.O.B. 17918 KHS

DATE: 09 NOV 05

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	INSTALL FILTER. ASSEMBLE FUEL FILTER HOSE/PIPE.		
2	INSTALL HOSE FROM TANK TO FILTER.		6.0
01 NOV, 3	INSTALL PIPE/HOSE FROM FILTER TO HARD LINE TO FRONT		
4	OF CAR. CHECK ALL FUEL HOSE CONNECTIONS AT REAR OF CAR.		
5	OK. CUT GASKETS FOR FUEL PUMP DRIVE. CURRY GASKET		
6	MATING SURFACES ON 7/12 CAM COVER, CAM COVER, CYLINDER		
7	HEAD AND TIMING CASE. CURRY 510 WOTITE SEALANT OFF ALL		
8	THREADS/STUDS. MOCK UP WATER PUMP IMPULSER/IMPULSER		
9	BACKING. EXHAUSTER TO HOUSING TOO SMALL - RECOMMEND NEW		
10	IMPULSER BACKING.		6.0

INVOICE

71721 ©2001 REDIFORM® 030901

PATRICK OTIS

INVOICE NO.

8421

SOLD BY:

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CAMP SPR

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

09 NOVEMBER 05

QUANTITY

DESCRIPTION

PRICE

AMOUNT

02 NOV.

1 INSTALL NEW ORIGINAL THICK SPRING TYPE WATER PUMP SEAL.

2 ASSEMBLE IMPELLER WITH NEW IMPELLER BACKING AND COIL PLATE.

3 CUT CAM COVER GASKETS TO FIT. CLEAN OFF OIL AND GASKET

4 SEALANT (510 RESINOR) INSTALL FUEL PUMP DRIVE, CAM COVER

5 AND 7-12 CAM COVER. INSTALL WATER PUMP HOUSING, INLET

6 AND OUTLET PIPES. CONNECT ALL WATER HOSES. INSTALL

7 MECHANICAL FUEL PUMP, CONNECT FUEL HOSES. INSTALL FAN

8 SUPPORT AND FAN BRUT. INSTALL NEW FAN BRUSH. 6.0

03 NOV.

9 TENSION FAN BRUT AND SECURE GENERATOR. REPLACE DAMAGED

10 WATER HOSE. REINSTALL DRAWN FUEL. FILL COOLING SYSTEM

INVOICE

71721 ©2001 REDIFORM® 030901

PATRICK OTIS

INVOICE NO.

8422

SOLD

ADDRESS

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CAMP SP4

SOLD BY:

4487

TERMS:

F.O.B.

17918 KHS

DATE:

09 NOVEMBER 2005

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1	(3 GALLONS COOLANT) RUN PIROTRIC PULP PUMP, CHECK PULP PRESSURE		
2	(3.5 PSI) NOTE PRESSURE REGULATOR DIAPHRAM IS LEAKING.		
3	REMOVE PRESSURE REGULATOR, DISASSEMBLE CURAN; RESURFACE		
4	WARPED MATING SURFACES. REPLACE DIAPHRAM AND BOWL		
5	SEALS. ASSEMBLE AND INSTALL. RUN MOTOR, CHECK PULP		
6	PRESSURE FROM MECHANICAL PUMP 4 PSI - OK. INSTALL ROAD		
7	WHEELS, CHECK TIRE PRESSURES, TORQUE WHEEL NUTS. ROAD		
8	TEST CAR. STEERING WHEEL COCKED SLIGHTLY TO THE LEFT.		
9	CHECK ADJUST CARBURETOR SYNCHRONIZATION AND MIXTURES		
10	LIFT CAR, DRAIN MOTOR OIL		5.5

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS

INVOICE NO.

8423

SOLD BY

ADDRESS

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CAMF SPY

SOLD BY

4487

TERMS:

F.O.B.

17918 KHS

DATE

09 NOVEMBER 2005

QUANTITY

DESCRIPTION

PRICE

AMOUNT

04 NOV.

1 REPLACE OIL FILTERS. SECURE LEAKING HOSE CONNECTION AT

2 LOWER RADIATOR HOSE. INSTALL/ SAFETY WIRE MOTOR SUMP

3 PWB. RESEAL LEAKING OIL TEMPERATURE SENDING UNIT. GREASE

4 LUBRICATE FRONT SUSPENSION, PEDALS, DRIVESHAFT. NOTE ALL

5 4 SUSPENSION/CONTROL ARM PINS WERE HEAVILY GREASED? REPAIR.

6 THROTTLE PEDAL SHAFT HAD NO GREASE. FIRM. INSTALL MODERN

7 STYLE 90° FIRM ON SHAFT. REMOVE AND CLEAN BELOW PAN.

8 CHECK PARK BRAKE ADJUSTMENT. INTERNAL BELOW PAN. CANNOT

9 ACCESS IDLER ARM GREASE PUTTING (STRAIGHT) INSTALL 90° FIRM

10 ON IDLER ARM AND LUBRICATE ARM. ADJUST THE RODS IN

INVOICE

71721 ©2001 REDFORD 030901

PATRICK OTTIS

INVOICE NO.

INVOICE NO.

8424

INVOICE
71721 ©2001 REDFORD 030901

SOL

ADD

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CAMP SPY

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

09 NOV. 05

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1	ORDER TO STANBURN STEERING WHIRL. FULL MOTOR WITH		
2	8 QTS OIL. INTERNAL AIR BOX ASSEMBLY. ROAD TRIP CAR. STANBURN		
3	WHIRL IMPROVED (BUT NOT PREPARED) PREPARE OIL LEVEL HOT,		
4	ADD 1 QT RIN A TOTAL OF 9. ADJUST TIE RODS AGAIN WITH DUNLOP		
5	GAUGES - ROAD TRIP CAR - STEERING WHIRL <u>NOW STRAIGHT</u> . GUE		
6	NEW UPPER WINDOW GUIDE SEALS TO UPPER EDGES OF		
7	DOOR/PANEL.		
08 NOV	8 FULL CAR AND DRAWING TO BRIAN HOYT FOR PAINTWORK		5.5
9			1.0
10	SHOP LABOR 44.0 hrs @ 100		4400

PATRICK OTTIS

INVOICE NO.

8425

SO	
AD	
CITY, STATE, ZIP	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER 250 CAMP SPR	SOLD BY: 4487	TERMS:	FOR 17918 KHS	DATE: 09 NOV 05
----------------------------------	------------------	--------	------------------	--------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	WATER PUMP HOUSING GASKET 26496		10 ¹⁸
2	WATER PUMP LOCK TAB 100434		6 ⁹⁶
3	3 WATER PUMP INLET, OUTPUT RUNNER GASK 26498 e 3		9 ⁻
4	WATER PUMP SPAL 95850601 (ORIG. STYLE)		110 ⁻
5	WATER PUMP IMPROVED BACKING 26644		80 ³⁰
6	3 GALLONS ANTIFREEZE C 8 ⁵⁰		25 ⁵⁰
7	1/2 INCH HITCH HOSE		10 ⁻
8	COOLING FAN BRUSH HOLDER ASSY		40 ⁻
9	LEFT CAM COVER GASKET 160477		44 ⁵⁰
10	USED RAMP MAIN PORT FUEL CANISTER		150 ⁻

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS

INVOICE NO.

8426

SOLD TO

ADDRESS

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CAMP SPY

SOLD BY:

4487

TERMS:

F.O.B.

17918 KMS

DATE:

09 NOV 05

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1 FISPA MTRBE MECHANICAL PULL PUMP TOP COVER KIT

45 -

2 FUEL PRESSURE REGULATOR DIAPHRAGM 95180133

65 -

3 FUEL PRESSURE REGULATOR BOWL GASKET 95180049

4 50

4 FRAM PB-50 OIL FILTER

10 -

5 FRAM PH 2815 OIL FILTER

21 95

6 9 QTS KENDALL 6T.1 20-50 MOTOR OIL @ 3 50

31 50

7 2 MBARES PUZZY STRIP FOR DOOR GLASS AS ORLG @ 30

60 -

8

9

PARTS TOTAL

724 39

10

TAX ON PARTS

63 38

INVOICE
71721 ©2001 K&N FORM 030901

PATRICK OTTIS

INVOICE NO.

8427

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CAMP SPY

SOLD BY:

TERMS:

F.O.B.

DATE:

QUANTITY

DESCRIPTION

PRICE

AMOUNT

SUBJECT

1

2

3

4

5

6

7

8

9

10

FABRICATE NEW BRASS "SOCK" FOR END OF FUEL TANK PICK-UP

TUBE AS ORIGINAL - NORMAN RACING

60 -

91 OUTLINE FUEL

40 -

JOB TOTAL

528.77

W/18/05
107 (WTS)
PDD

INVOICE

71721 02001 REDFORM 030901

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS
1220 TENTH STREET
BERKELEY, CALIFORNIA 94710
BAR NO AK 120777

INVOICE NO.

0677

SC	
AD	
CI	

CUSTOMER'S ORDER 250 GTR/CALIFSPY	SOLD BY: 4487	TERMS: THANK YOU	F.O.B. 18,252 KMS	DATE: 21 March 06
--------------------------------------	------------------	---------------------	----------------------	----------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	LIFT CARZ, INSPECT CHASSIS, GO OVER CONCERNS WITH CUSTOMER		
2	REPLACE BRAKE LIGHT PRESSURE SWITCH WITH NEW SWITCH		
3	AND ADAPTER FITTING. BUROD BRAKE HYDRAULIC SYSTEM		
4	CHECK RIDE HEIGHT VISUALLY - SEEMS OK. RECOMMEND		
5	REPOSITIONING TAILPIPER FOR MORE GROUND CLEARANCE.		95
6	FUNCTION OF RUDERAL PULL PUMP - SEEMS TO FUNCTION		95
7	NORMALLY. CHECK BRAKE LIGHT FUNCTION - GOOD. CHECKED		55
8	LOOKS AT NEW BRAKE LIGHT SWITCH MONT. DRAWER AMOUNT		
9	BLOCK WITH CUSTOMER. ORDER NEW BATTERY		
10	SHOP LABOZ 2.5 HRS @ 100		505 50

PATRICK OTTIS

INVOICE NO.

0678

SOLD

ADDRESS

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

2506TR/CMUF SP4

SOLD BY:

4487

TERMS:

F.O.B.

18,252 KMS

DATE:

21 March 06

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1				
2	MODERN BRAKE LIGHT PRESSURE SWITCH SL 30071		15	-
3	SPECIALLY MANUFACTURED 9 CADMIUM PLATED ADAPTOR FOR SWITCH		125	-
4	CASTROL LHM BRAKE FLUID		5	-
5	INTERSTATE MT. 41 BATTERY		89	95
6	PARTS TOTAL		234	95
7	TAX ON PARTS		20	55
8				
9				
10	JOB TOTAL		505	50

PP
4/16/06
#3737
9

INVOICE

7/L721 ©2001 REDIFORM® 030901

PATRICK OTIS

1220 TENTH STREET

BERKELEY, CALIFORNIA 94710

BAR NO AK120777

INVOICE NO.

0889

[REDACTED]	
[REDACTED]	
[REDACTED]	

CUSTOMER'S ORDER 250 GTR/CAUFSPH	SOLD BY: 4487	TERMS: THANK YOU	F.O.B. 18505 KMS	DATE: 01 JUNE 06
-------------------------------------	------------------	---------------------	---------------------	---------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
30 MAY	1 CHECK FUEL PUMP FUNCTION. DASH LIGHT COMES ON		
	2 BUT FUEL PUMP DOESN'T WORK/CLICK. CHECK POWER AT PUMP - OK		
	3 REMOVE FUEL PUMP. BENCH TEST PUMP - IN OP. TRACER PROBLEM		
	4 TO COIL WIRE BROKEN OFF FUSE WITH COIL BODY. DISASSEMBLE		
	5 PUMP. REMOVE COIL FROM COIL BODY. REPAIR BROKEN		
	6 WIRING.		3.5
31 MAY	7 REINSTALL COIL IN COIL BODY. ASSEMBLE COIL BODY. CURRY		
	8 CONTACTS. INSTALL STATIONARY CONTACT ON COIL BODY. CUT COIL		
	9 WIRING TO CORRECT LENGTHS AND CURRY INSULATION. SOLDER		
	10 TERMINAL ENDS ONTO COIL WIRES. ASSEMBLE TOP PORTION		

PATRICK OTTIS

PATRICK OTTIS

INVOICE NO.

0890

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 GTR/CMF SPY

SOLD BY:

4487

TERMS:

F.O.B.

18505 KMS

DATE:

01 JUNE 06

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1	OF ELECTRIC PUMP. DISASSEMBLE AND CURRY LOWER PORTION OF		
2	PUMP. REPLACE PUMP DIAPHRAM. REASSEMBLE PUMP. BENCH		
3	TEST/ADJUST PUMP - OK. INSTALL PUMP ON CAR. CHECK FUNCTION -		
4	OK, BUT PUMP DOESN'T STOP. START RUN MOTOR - OK. 5.0		
01 JUNE	5	CHECK ROLL PRESSURES - ELECTRIC PUMP (3 - 3 1/2 PSI). ELECTRIC	
	6	PUMP + MECH. PUMP (3 - 4 PSI). MECHANICAL PUMP (INTERMITTENT	
	7	FUNCTION) - SOME TIMES OK 3-4 PSI - SOMETIMES 0-1 PSI	
	8	ELECTRIC PUMP SOMETIMES SHUTS OFF, SOME TIMES RUNS ON.	
	9	POSSIBLE BAD CHECK VALVES IN MECHANICAL PUMP? REMUNE	
	10	INLET LINE TO MECHANICAL PUMP. RUN ELECTRIC PUMP	

INVOICE

7/1721 ©2001 REDIFORM® 030901

PATRICK OTTIS

INVOICE NO.

0891

SOLD

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER

250 CMW

SOLD BY:

4487

TERMS:

F.O.B.

18505 KMS

DATE:

01 JUNE 06

QUANTITY

DESCRIPTION

PRICE

AMOUNT

- | | | | |
|----|--|--|--|
| 1 | AND CHECK FOR LEAKAGE. - INLET CHECK VALVES ON MECHANICAL | | |
| 2 | PUMP ARE LEAKING. BLOCK OFF INLET TO MECHANICAL PUMP, | | |
| 3 | RUN ELECTRIC PUMP - NOW ELECTRIC PUMP STOPS PROPERLY AFTER | | |
| 4 | PRESSURE BUILDS. REMOVE MECHANICAL FUEL PUMP. BENCH TEST | | |
| 5 | CHECK VALVES - LEAKING. DISASSEMBLE MECH FUEL PUMP. REPLACE | | |
| 6 | ALL FOUR CHECK VALVES. BENCH CHECK PUMP - GOOD. INSTALL MECH | | |
| 7 | FUEL PUMP. CHECK FUEL PRESSURES. ELECTRIC PUMP - 4 PSI, | | |
| 8 | STOPS CLICKING AFTER PRESSURE BUILDS. MECHANICAL PUMP 4 PSI. | | |
| 9 | TEST DRAW CAVS ON MECHANICAL PUMP WITH 1/2 INCH PURL - OK. | | |
| 10 | REMOVE STRENGTH WHEEL, ADJUST AND GLUE CENTRAL HORN | | |

INVOICE

7L721 ©2001 REDIFORM® 030901

PATRICK OTTIS

INVOICE NO.

0892

SOLD TO	
ADDRESS	
CITY, STATE, ZIP	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER 250 CMT	SOLD BY: 4487	TERMS:	F.O.B. 18505 KMS	DATE: 01 JUNE 06
-----------------------------	------------------	--------	---------------------	---------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	CONTACT IN PLACE, INTERNAL STEERING WHEEL.	CHECK	HORN
2	FUNCTION - GOOD.		5.0
3	SHOP LABOR 13.5 HRS @ 100		1350 -
4	FISPA EUROPE FUEL PUMP KIT 95180313		75 -
5	4 FISPA MECHANICAL FUEL PUMP CHECK VALVES @ 10		40 -
6	PARTS TOTAL		115 -
7	TAX ON PARTS		10 06
8			R.D. 3852
9	WASH DETAIL CAR		NO CHARGE
10	JOB TOTAL		1475 06

INVOICE

7/1721 ©2001 REDIFORM® 030901

PATRICK OTTIS

1220 TENTH STREET

BERKELEY, CALIFORNIA 94710

BAR NO AK 120777

INVOICE NO.

0957

OK
y

SO	
AD	
CI	

CUSTOMER'S ORDER 250 GTR / CNUF SPH	SOLD BY: 4487	TERMS: THANK YOU	F.O.B. 18555 KMS	DATE: 21 JUNE 06
--	------------------	---------------------	---------------------	---------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	CHECK FOR POWER AT IGNITION SWITCH TRR 30 - OK, TRR 15		
2	OK, 54, 50 - ALL OK. SWITCH FUNCTION IS GOOD. CHECK POWER		
3	AT FUSEBOX TO IGNITION COILS - GOOD. CHECK POWER AT		
4	FUSEBOX TO STARTER MOTOR - GOOD. POSSIBLE BAD STARTER /		
5	SOLENOID OR BAD CONNECTION. LEFT CAR. TRACER PAINT TO		
6	LOOSE CONNECTION AT TRR 50 OF STARTER SOLENOID. SCREW		
7	AT TRR 50 IS TIGHT, BUT WIRE IS TOO SMALL, SO SCREW		
8	DON'T TIGHTEN DOWN ON WIRE. REMOVE WIRE. DOUBLE		
9	AND SOLDER END - INSTALL WIRE AND TIGHTEN GRUB SCREW.		
10	CHECK STARTER FUNCTION - GOOD. NOTE IGNITION SWITCH		

PATRICK OTTIS

INVOICE NO.

0958

SOLD TO:	[REDACTED]
ADDRESS:	
CITY, STATE, ZIP	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER 250 GTR / CALL SPY	SOLD BY: 4487	TERMS:	F.O.B. 18555 KMS	DATE: 21 JUNE 06
--	------------------	--------	---------------------	---------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	IS WIRED INCORRECTLY - YELLOW AND BLUE WIRES WERE SWAPPED.		
2	INSTALL WIRES CORRECTLY. FIND "LOST" IGNITION SWITCH BRZL		
3	NUT, LOST BY OWNER. CHECK TIRE PRESSURES - OK. CHECK		
4	COOLANT AND ENGINE OIL LEVELS - OK.		
5			
6			
7			
8			
9			
10	SHOP LABOR 3.0 HRS @ 100		300

6/21/06
#3882

PATRICK OTTIS
1220 TENTH STREET
BERKELEY, CALIFORNIA 94710
BAR NO AK 120777

INVOICE NO.

505169



CUSTOMER'S ORDER:

250 GTR/CAM-SPY 4487

SOLD BY:

TERMS:

THANK YOU

E.O.B.

20805 KMS

DATE:

14 FEBRUARY 07

QUANTITY	DESCRIPTION	PRICE	AMOUNT
07 FEB	1 ROAD TEST CAR TO SAN RAFAEL BRIDGE TO ASSESS AND BRING		
	2 MOTOR OIL TO TEMPERATURE. GO OVER CUSTOMER SUPPLIED		
	3 LIST. HIT LIFT CAR, DRAIN REPLACE MOTOR OIL WITH FILTERS.		
	4 NOTE OIL LEAKAGE AT LEFT FRONT OF CAM COVER GASKET?		
	5 LUBRICATE FRONT SUSPENSION. CHECK TIRE PRESSURES - COOLANT		
	6 LEVEL. LUBRICATE HORN COMPRESSOR. INSPECT HOOD RELEASE		
	7 LEVER - PIVOT BOLT IS MISSING. WIPER BLADES NEED		
	8 REPLACEMENT.		2.5
08 FEB	9 DEGREASE MOTOR. ROAD TEST CAR AGAIN. CHECK FOR OIL		
	10 LEAKS. OIL LEAK IS AT 7:12 CAM COVER. REMOVE		

INVOICE

7L721/7L721S ©2004 REDIFORM®

PATRICK OTTIS

INVOICE NO.

505170

SOLD TO:

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER:

250 CAMF

SOLD BY:

4487

TERMS:

F.O.B.

20805 KHS

DATE:

14 FEBRUARY 07

QUANTITY

DESCRIPTION

PRICE

AMOUNT

	1	7.12 CAM COVER/CHAIN COVER. CURRY ALL GASKET MATING		
	2	SURFACES. PUT NEW CAM CHAIN GASKET. SURFACE CHAIN		
	3	COVER GASKET MATING SURFACE ON LAPPING PLATE. REINSTALL		
	4	CHAIN COVER/CAM COVER. RIGHT COVER. 11.5		5.5
09 FEB	5	REMOVE AND INSPECT SPARK PLUGS - GMP INSTALL NEW SPARK		
	6	PLUGS. INSTALL THROTTLE LINKAGE - 7.12 SPARK PLUG WIRTS -		
	7	BREATHING PIPE. CUT PIVOT BOLT FOR HOOD RELEASE LEVER		
	8	AND INSTALL.		3.0
12 FEB	9	ROAD TEST CAM AGAIN FOR OIL LEAKS. 7.12 CAM/CHAIN COVER		
	10	NOW COMPLETELY DONE. VERY SLIGHT SEEPAGE AT TIMING		

INVOICE

7L721/7L721S ©2004 REDIFORM®

PATRICK OTTIS

INVOICE NO.

505171

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER:

250 CMT

SOLD BY:

4487

TERMS:

F.O.B.

20805 KMS

DATE:

14 FEBRUARY 07

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	COVER/ SUMP GASKET - NORMAL. LIFT CAR. REMOVE CURTAIN		
2	REINSTALL BEAM PAN OR OIL. REMOVE ROAD WHEELS. RWH		
3	BRAKE HYDRAULIC SYSTEM. REINSTALL ROAD WHEELS. TORQUE		
4	WHEEL NUTS. CHECK LIGHTS - RIGHT LICENSE PLATE LIGHT IS		
5	OUT - REPLACE BULB. REINSTALL HOOD. CHECK HOOD RELEASE		
6	FUNCTION - OK		2.5
7	SHOP LABOR 13.5 HRS @ 100		1350
8			
9	10 QTS KENDALL GT. 120. 50 WGT OIL @ 3 ⁵⁰		35
10	FRAM PH 2815 OIL FILTER		21 ⁹⁵

INVOICE

7L721/7L721S ©2004 REDIFORM®

PATRICK OTTIS

INVOICE NO.

505172

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER:

250 CAFE

SOLD BY:

4487

TERMS:

FO.B.

20805 KMS

DATE:

14 FEBRUARY 07

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	PRIM PB. 50 OIL FILTER		10 -
2	CASTROL LMA BRAKE FLUID		12 -
3	LEFT CAM COVER GASKET		45 -
4	12 NGK BRPES BLUE SPARK PLUGS @ 3 ⁵⁰		42 -
5	2 12 INCH WIPPER BUDDY INSERTS @ 7 ⁵⁰		15 -
6	PARTS TOTAL 180 ⁹⁵ TAX ON PARTS		15 ⁸³
7	91 OCTANE FUEL		22 -
8	WASH DREIN CAR	NO CHARGE	
9			
10	JOB TOTAL		1568 ⁷⁸

PO 212407
#4077

INVOICE
7L721/7L721S ©2004 REDIFORM®

PATRICK OTTIS
1220 TENTH STREET
BERKELEY, CALIFORNIA 94710
BAR NO AK 120777

INVOICE NO.

000785

SOI

AD

CIT

CUSTOMER'S ORDER:

250 GTR / CALIF

SOLD BY:

4487

TERMS:

THANK YOU

FOR

22808 KHS

DATE:

05 NOVEMBER 07

QUANTITY

DESCRIPTION

PRICE

AMOUNT

15 OCT

1

ROAD TEST CAR TO ASSESS AND BRING MOTOR OIL TO TEMPERATURE

16 OCT

2

LIFT CAR, DRAIN MOTOR OIL. NOTE WATER PUMP IS LEAKING

3

COOLANT FROM WEED HOLE. INSTALL MOTOR SUMP PUG / SARTAN

4

WIRE, REPLACE OIL FILTERS, FILL MOTOR SUMP WITH KENDALL

5

REPAIR ROAD WHEELS. DRAIN SUMP TO DON'S TIRE WITH

6

NEWLY RECEIVED MICHELIN TIRES FOR MOUNTING / BALANCING.

7

REPAIR HOOD, DRAIN ENGINE COOLANT, BEGIN DISASSEMBLY

8

REMOVAL OF WATER PUMP.

5.5

16 OCT

9

FINISH DISASSEMBLY OF WATER PUMP, CLEAN SOA BUST ALL

10

REMOVED PARTS. DRAIN IMPROPER WITH BACKING FOR

INVOICE

7L721 ©2004 REDIFORM®

PATRICK OTTIS

INVOICE NO.

000786

SOLD TO	
ADDRESS	
CITY, STATE, ZIP	

SHIP TO:	
ADDRESS:	
CITY, STATE, ZIP	

CUSTOMER'S ORDER: 250 CALIF	SOLD BY: 4487	TERMS:	FOR 22808 KHS	DATE: 05 NOVEMBER
--------------------------------	------------------	--------	------------------	----------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	1 MACHINE WORK.		2.0
18 OUT.	2 RETRIEVE NEWLY MACHINED / REPAIRED WATER PUMP IMPELLER		
	3 AND MOUNTED TIRES / WHEELS. ASSEMBLE INSTALL NEW GENERATION		
	4 WATER PUMP CARBON SEAL FROM FRANKLIN NORTH AMERICA.		
02 IN	5 INSTALL HOUSING, CONNECTING WATER PUMP ETC. FINISH BLEND		
	6 BRAKE HYDRAULIC SYSTEM TO INCLUDE BRAKE BOOSTER. REMOVE		
	7 REMAINING EXHAUST HEAT SHIELD FOR WRINKLE FINISH. INSTALL		
	8 ROAD WHEELS, TORQUE WHEEL NUTS.		5.5
19 OUT	9 FINISH WATER PUMP, INSTALL NEW 50.50 COOLANT MIX. RUN		
	10 MOTOR. CLEAN OIL STORAGE FROM BOTTOM OF CAR. ROAD		

INVOICE
7L721 ©2004 REDIFORM®

PATRICK OTTIS

INVOICE NO.

000787

SOLD TO: [REDACTED]
ADDRESS: [REDACTED]
CITY, STATE, ZIP: [REDACTED]

SHIP TO:
ADDRESS:
CITY, STATE, ZIP:

CUSTOMER'S ORDER: 250 CAMP	SOLD BY: 4487	TERMS:	F.O.B. 22808 KHS	DATE: 05 NOVEMBER
----------------------------	---------------	--------	------------------	-------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	TEST CARZ TO SAN RAPAZZ, BRIDGE, RETURN, LEFT CARZ, ASSURE		
2	WATERZ PUMP IS DRY. TORQUE MOTOR CASTING HARDWARE IN		
3	ATTEMPT TO REDUCE SOME SLIGHT OIL SEEPAGE. (FRONT OF SUMP,		
4	TIMING CASE).		3.0
5	INVESTIGATE REMAINING SEATS TO SWAP LEFT TO RIGHT. LEFT CARZ.		
6	REMOVE BRUM PAN. UNBOUT REMOVE SEATS, VACUUM INTERIOR.		
7	INSTALL SEATS LEFT TO RIGHT. REINSTALL BRUM PAN. SECURE		
8	BOTH WINDSHIELD WASHERZ. SQUIRTERS. ADJUST BRAKE MASTER		
9	CYLINDERZ PUSH ROD. ROAD TEST CARZ. BRAKE PEDAL FEELS		
10	SOFT WHEN APPLIED SLOWLY, OK. ON FAST APPLICATION; WILL		

INVOICE
71721 ©2004 REDIFORM®

PATRICK OTTIS

PATRICK OTTIS

INVOICE NO.

000788

SOLD TO	[REDACTED]
ADDRESS:	
CITY, STATE, ZIP	

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER: 250 CALIF	SOLD BY: 4487	TERMS:	FOR 22808 KMS	DATE 05 NOVEMBER 07
--------------------------------	------------------	--------	------------------	------------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
1	REQUIRE DISASSEMBLY OF MASTON BOOSTER TO INVESTIGATE		
2	FURTHER:		2.0
03 HRS.	INSTALL BOTH NEW WINKLEFINISHED EXHAUST HEAT SHIELDS,		
4	NOW WITH ORIGINAL STYLE BLACKENED HARDWARE. FIT INSTALL		
5	NEW REPRODUCED RIBBED PIRELLI DOWN DROUGHT TUBES AS		
6	ORIGINAL		1.5
7			
8	SHOP LABOY 19.5 HRS @ 100		1950
9			
10			

PATRICK OTTUS

INVOICE NO.

000789

SOLD TO:

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER:

250 CAMP

SOLD BY:

4487

TERMS:

FOR

22808 KMS

DATE:

05 NOVEMBER 2007

QUANTITY

DESCRIPTION

PRICE

AMOUNT

1	NEW GENERATION WATER PUMP CARBON SEAL 95850601	110	-
2	WATER PUMP HOUSING GASKET 26496	10	80
3	3 WATER PUMP CONNECTING PIPING GASKETS 26498 @ 3 ⁰⁰	9	-
4	WATER PUMP SHAFT LOCK TAB 101434	6	90
5	1.5 GALLONS ANTIFREEZE @ 9 ⁻	13	50
6	CASROL LMA BRAKE FLUID	12	-
7	FRAM PB 50 OIL FILTER	10	-
8	FRAM PA 2815 OIL FILTER	21	95
9	9 QTS KENDALL 20-50 MOTOR OIL @ 3 ⁵⁰	31	50
10	4 MICHELIN 15 INCH TUBE TYRES @ 18 ⁹⁵	75	80

INVOICE
7L721 ©2004 REDIFORM®

Patrick Ottis

INVOICE NO.

000790

SOLD TO

ADDRESS:

CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER:

250 CAUF

SOLD BY:

4487

TERMS:

FOR

22808KHS

DATE:

05 NOVEMBER

QUANTITY

DESCRIPTION

PRICE

AMOUNT

	1	2 RIBBED PIRALI DOWN DRAUGHT TUBES @ 60			120	-
	2	PARTS TOTAL			421	15
	3	TAX ON PARTS			36	85
SUBST	4	DISMOUNT/MOUNT BALANCE CUSTOMER TUBES - DON'S @ 25			100	-
SUBST	5	EDM BORE RIVET HOUR IN HARDENED W.P. IMPROVED BACKING - MANUFACTURE				
	6	SPRC RIVET, 8 INSTAL IMPELL BACKING TO IMPELL AS ORIG - NORMAN			150	-
SUBST	7	PREP WRINKLE FINISH EXHAUST HEAT SHIELDS - PERF REPEROT			150	-
	8	91 OUTANK FUEL			50	-
	9	WASH DETAIL CAR				
	10	JOB TOTAL				

P.O.
4/7/07

#4275

NO CHARGE

2858⁰⁰

INVOICE

7L721 ©2004 REDIFORM®