

(203) 377-6745 Fax (203) 386-0486



DATE

9/27/12

INV#

WS71M-27

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 8/31/2012 TO 9/27/2012 BODY WORK		
	Hand block wet sand primer coats on body & parts 320,400,600 to 800 grit abrasives. Sharpen body lines.		
	Apply seam seal as/where needed. Final and prep for top coats. Mask for top coats.		
63.5	Apply undercoat to inside of trunk and engine bay where necessary. HOURS	85.00	5,397.50
	COOLING Pick up recored radiator.		
1.5	HOURS	65.00	97.50
	PAINT WORK		
	Apply (5) coats 285 primer to fuel fill doors and head light buckets. Apply (3) coats MAS CODE 106A20 STK#526915 - Celeste Chiaro followed by (3) coats 923-550 clear coat.		
13.2	HOURS Bake time all operations	100.00	1,320.00
11.5	HOURS Prep and paint interior and trunk floor with POR15 conversion coating to address surface rust conditions and provide stable base.	65.00	747.50
1.6	HOURS .	100.00	160.00
	FINISH ENHANCEMENT		
Make ch	necks payable to Automotive Restorations, Inc. TOTAL D		

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

9/27/12

INV#

WS71M-27

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Hand block wet sand exterior: Body, hinged panels and misc panels to 5000 grit, composite. Unmask. Compound and polish headlight covers & fuel doors. Clean inside and out free of compound dust. Power wash engine bay and underbody to eliminate compound and residual body work Final machine glaze to follow assy.		
34.5	HOURS	85.00	2,932.50
12.2	UPHOLSTERY Remove old headlings, visors and hardware. Fabricate and install new headlining. Install visors and hardware. HOURS	100.00	1,220.00
	ASSEMBLY		1,220.0
15.1	Prep front and rear windshield channels for glass installation. Assemble, fit and align doors. Install fuel tanks and pumps. Install windows, window tracks & motors Install door handles and locks. Prepare front windshield for installation: Fit seal and locking chrome trim channel. HOURS	25.22	
	Labor Subtotal	85.00	1,283.5 13,158.5
	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES	5.00	83.00
Make ch	necks payable to Automotive Restorations, Inc.	DTAL DUE	

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

9/27/12

INV#

WS71M-27

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
63.5	HRS ASST BODY SUPPLIES	10.00	635.00
26.3	HRS ASST PAINT SUPPLIES	35.00	920.50
34.5	HRS ASST COMPOUND/POLISH SUPPLIES	7.50	
12.2	HRS ASST UPHOLSTERY SUPPLIES		258.75
2	CAM COVER GASKET (FORWARD)	10.00	122.00
2	CAM COVER GASKET (LH AND RH)		The state of the s
2	CAM END SEAL (HALF MOON)	36.83	
32	SEALING WASHER- COPPER CAM COVER	19.49	
1	OIL FILTER		26.88
1	DEGREASER	24.54	24.54
1	POR15-BLK P/QT	12.99	
8	DOOR WEATHERSTRIPPING (DOOR) (EIGHT METERS)	35.00	
7	DOOR WEATHERSTRIPPING (WINDOW FRAME) (SEVEN METERS)	59.53	476.24
1	FUEL DOOR BUMPER	24.12	168.84
4	ENGINE COMPARTMENT TRIM (FOUR METERS)	12.78	12.78
1	WINDSHIELD GLAZING COMPOUND	11.75	47.00
1	FUEL HOSE FOR TANK	40.64	
2	HEADLINER MATERIAL (TWO YARDS)	45.26	45.26
2	ANTI-FREEZE/COOLANT	165.30	330.60
	Parts Subtotal	18.95	37.90
			3,467.12
	SUBLET		
1	RE-CORE RADIATOR ASSEMBLY		
4	POWER COAT WHEEL ASSEMBLIES	2,102.50	2,102.50
4	MEDIA BLAST WHEELS	146.00	584.00
	Sublet Subtotal	101.50	406.00
			3,092.50

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

9/27/12

INV#

WS71M-27

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011		19,718.12 00% 197.18 35% 1,264.62
Make ch	ecks payable to Automotive Restorations, Inc.	TOTAL DUE	\$21,179.92

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

10/25/12

INV#

WS71M-28

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 9/28/2012 TO 10/25/2012 METAL WORK Fabricate new right side floor panel. Fit and weld. Grind & dress welds. Seam seal. Paint cockpit.		
14.2	Zinc prime & undercoat body in repair area. HOURS	100.00	1,420.00
	BODY WORK Prep radiator cover and rocker moldings for paint. Remove seam seal from left and right door jambs. Remove body fill from fastener holes. Mask for primer. Sand door jamb primer and prep for paint. Apply self leveling seam sealer as necessary.		
10.7	HOURS	85.00	909.50
1.1	PAINT WORK Mask prep and paint hood area for grill install. Apply 5 coats 285 primer to door jambs. Epoxy seal rocker moldings, radiator cover & rear pinch weld molding. Follow with (2) coats SC804 matte black paint. HOURS	100.00	110.00
	UNDERBODY Prep underside of hood and apply coating as original. Mask underbody for O.E.M. type sealant application.	100.00	110.00
Make ch	necks payable to Automotive Restorations, Inc. ce charges are assessed monthly at 1.0% TOTAL I		

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

10/25/12

INV#

WS71M-28

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
13.7	Scuff and prep lower quarter panels and apply single stage UNO 804, chip guard. Treat interior doors with 3M Rustfighter. Apply underbody coatings and chassis paint to protest and dress underbody as requested. HOURS	100.00	1,370.0
	REASSEMBLY Install interior and trunk carpets & underfelts Replace fuel drain hoses. Install rear quarter glass and seals. Install door seals, door jamb trim, striker plates and guides. Install tail lights, front fender lights, badges & wiper bezels. Refit radiator and A/C condensor. Refit front and rear glass. Assemble and install headlight buckets. Install front doors and adjust. Install hood jamb finish trim. Install front bumper.		
98	Prep and install all side moldings and rocker trim. Install interior door panels and kick panels. HOURS	85.00	8,330.0
0.4	MECHANICAL Note: Clutch inop. Diagnose Faulty clutch master and slave cylinder. Found. Advise. Both leaking. HOURS	100.00	40.00
NA - 1 1	Pick up and deliver parts for Scheffler Maserati at dry stripper.		
Make ch	necks payable to Automotive Restorations, Inc. nee charges are assessed monthly at 1.0% TOTAL I	SIIE	

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486

1971 Maserati Ghibli



DATE

10/25/12

INV#

WS71M-28

Due Upon Receipt

	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
2	HOURS	65.00	130.00
	Labor Subtotal		12,309.50
	PARTS/SUPPLIES		
98.4	HRS ASST MECH/ASSY SUPPLIES	5.00	492.00
14.2	HRS ASST METAL WORK/FAB/WELD SUPPLIES	10.00	142.00
10.7	HRS ASST BODY SUPPLIES	10.00	107.00
1.1	HRS ASST PAINT SUPPLIES	35.00	38.50
13.7	HRS ASST STRIP/UNDERBODY/POWER WASH SUPPLIES	7.50	102.75
1	WEATHERSTRIP ADHESIVE	32.40	32.40
2	DOOR GUIDE	31.32	62.64
1	RADIATOR CAP	35.20	35.20
2	FUEL NECK RUBBER GROMMET	33.21	66.42
4	TRUNK AND HOOD RUBBER BUMPERS	19.12	76.48
	TRUNK SEAL	61.66	61.66
	FUEL FILL UP	48.01	48.01
4	3M RUBBER UNDER BODY SEALANT	11.50	46.00
	Parts Subtotal		1,311.06
	SUBLET		
1	MEDIA BLAST ROCKER MOLDING TRIM AND TRUNK PANEL	116.00	116.00
	Sublet Subtotal	110.00	116.00

Make checks payable to Automotive Restorations, Inc. Finance charges are assessed monthly at 1.0%

6.35% CT SALES TAX - effective 07/01/2011

TOTAL DUE

\$14,751.88

1.00%

6.35%

116.00

137.37

877.95

13,736.56

www.automotiverestorations.com

Waste Disposal Fee



(203) 377-6745 Fax (203) 386-0486



DATE

11/29/12

INV#

WS71M-29

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 10/26/2012 TO 11/29/2012 TRANSMISSION		
5.2	Replace clutch master cylinder, slave cylinder and rubber flexible hose. Bleed clutch hyd HOURS	raulics.	520.00
	SERVICE Change oil and filter. Change transmission oil. Change differential oil. Gather oil samples for lab testing. Flush and bleed brake system. Lubricate suspension. Remove & refit alternator and steering shaft removed for valve cover access. Remove cam covers. Check valve clearancesOK Adjust timing chains to factory spec. Refit covers with new seals.		
15.4	HOURS ENGINE DETAIL (XTRA) Solvent soak, degrease and strip finish from valve covers. Prep for painting. Prep, prime & paint valve covers with wrinkle finish. Refit alternator and steering shaft removed for valve cover access. Remove brake reservoir, clean, prep, paint and refit. Scuff, prep, prime and paint air cleaner housing. HOURS	100.00	1,540.00
-3.9	Estimate Adjustments	100.00 100.00	1,790.00 -390.00
Make ch	necks payable to Automotive Restorations, Inc. nee charges are assessed monthly at 1.0%	TAL DUE	15.0

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

11/29/12

INV#

WS71M-29

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	CHROME/TRIM		
	Install door mirror.		
	Install Euro plate bracket.		
1.3	HOURS	85.00	110.50
	FINICHENHANCEMENT		
	FINISH ENHANCEMENT		
	Complete hand block wet sand to 5000 grit. Compound & polish.		
4.5	Adjust window frames on doors to clearance rear window chrome trim when closing doors. HOURS		
	Labor Subtotal	85.00	382.5
			3,953.00
	PARTS/SUPPLIES		
21.9	HRS ASST MECH/ASSY SUPPLIES	5.00	109.50
4.5	HRS ASST COMPOUND/POLISH SUPPLIES	7.50	33.75
14	HRS ASST CLEANING SUPPLIES	5.00	70.00
4	QT DA SAE 90	7.50	30.00
1	CASTROL GT/LMA BRAKE FLUID	17.50	17.50
1	BRAD PENN 20W50 DIFFERENTIAL OIL LAB	8.95	8.9
1	ENGINE OIL LAB	49.00	49.00
1	TRANSMISSION LAB	49.00	49.00
1	CLUTCH MASTER CYLINDER	49.00	49.00
1	CLUTCH SLAVE CYLINDER	252.10	252.10
1	CLUTCH HOSE	111.64	111.64
	Parts Subtotal	66.23	66.23
			846.67

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

11/29/12

INV#

WS71M-29

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	4,799.67 48.00 307.83
NA o L	necks payable to Automotive Restorations, Inc.		

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

12/20/12

INV#

WS71M-30

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
1.9	LABOR WORK PERFORMED 11/30/2012 TO 12/20/2012 ASSEMBLY Remove rear bumper and disassemble for replating. HOURS Labor Subtotal	85.00	161.5 161.5
1.9	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES Parts Subtotal	5.00	9.5 9.5
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	171.0 1.7 10.9
Make ch			
Finan	necks payable to Automotive Restorations, Inc.	Invoice Total	\$183.68
	www.automotiverestorations.com	Payments/Credits	\$0.00
	www.vintageracingservices.com	BALANCE DUE	\$183.68



(203) 377-6745 Fax (203) 386-0486



DATE

1/31/13

INV #

WS71M-31

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 12/21/2012 TO 01/31/2013		
1.1	COLLECTOR SERVICES Create large shipping crate to ship parts to be rechromed. Load and secure bumper assembly for UPS. HOURS	65.00	71.5
20.3	UPHOLSTERY Remove drivers seat. Disassemble seat and remove covers. Remove interior panels and carpet set. Begin fabrication of patterns for seats. HOURS	100.00	
	INTERIOR PANELS	100.00	2,030.0
11.6	Test all dash functions and listed inoperable items. Repair small connection and adjustment problems. Removed entire dash structure and diagnosed all inoperable items and handed in addendum. HOURS	100.00	1,160.0
	ENGINE BAY Source necessary parts and items needed to complete engine bay detail. Prep engine bay for detail. Remove cooling hoses, power steering hoses, reservoir and necessary brackets. Prep parts and components for paint.		
Make cl	necks payable to Automotive Restorations, Inc. TOTAL D		

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

1/31/13

INV#

WS71M-31

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Remove all drive belts to be replaced (A/C has to be removed to change drive belts) Replace points, condenser, and spark plug set. Reassemble engine bay. Install new hoses and clamps. Progress invoice. (not yet complete)		
25.7	HOURS	85.00	2,184.50
	CLEAN AND DETAIL SERVICES Stage car in wash bay.		
5.5	Degrease and power wash engine bay. Prep for engine bay detailing. HOURS	25.00	057.50
	Labor Subtotal	65.00	357.50 5,803.50
	PARTS/SUPPLIES		
38.4	HRS ASST MECH/ASSY SUPPLIES	5.00	192.00
20.3	HRS ASST UPHOLSTERY SUPPLIES	10.00	203.00
5.5	HRS ASST STRIP/UNDERBODY/POWER WASH SUPPLIES	7.50	41.25
1	SHIPPING CRATE FOR BUMPER AND OVER-RIDERS	115.66	115.66
1	POWER STEERING HOSE (BLACK CLOTH)	28.58	28.58
1	EMISSION AND BRAKE BOOSTER HOSE (BLACK CLOTH)	54.30	54.30
	SHIPPING and INSURANCE: BUMPER SENT FOR RECHROME	136.31	136.31
	DISTRIBUTOR CAP	118.40	118.40
1	DISTRIBUTOR ROTOR	44.91	44.91
1	DISTRIBUTOR POINTS	57.97	57.97
2	IGNITION WIRE SET	188.50	188.50
1	RESERVOIR CAP	38.27	76.54
	UPPER RADIATOR HOSE	188.10	188.10

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

1/31/13

INV#

WS71M-31

Due Upon Receipt

1971	Maserati	Ghibli

RO # 2021

	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1 2 1 1 1	PROP ROD SUPPORT BLOCK LOWER RADIATOR HOSE SHIPPING: HOSE CLAMPS FOR RESTORATIONS COOLING BY-PASS HOSE DEGREASER SILVER CADMIUM PLATE HOSE CLAMPS Parts Subtotal	62.45 42.85 6.93 27.95 12.99 227.65	62.45 85.70 6.93 27.95 12.99 227.65 1,869.19
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	7,672.69 76.73 492.09

Make checks payable to Automotive Restorations, Inc.

Finance charges are assessed monthly at 1.0%

TOTAL DUE

\$8,241.51

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486





DATE

2/28/13

INV#

WS71M-32

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 02/01/2013 TO 02/28/2013		
	ENGINE SERVICE Install new cooling hoses with new clamps. Install drive belts. Replace power steering hoses. Inspect vehicle for any necessary or recommended repairs to complete and make reliate Prepare mechanical report and advise. Approved-Begin repairs. Adjusted brake pedal linkage. Machine spacer/adapter. Miscellaneous service per list.	ole.	
15.1	HOURS	100.00	1,510.00
0.8	COOLING SYSTEM Examine cooling system for leaks. Reset all clamps. Run to check fluid levelsOK HOURS	100.00	80.00
4.2	ELECTRICAL Replaced broken battery switch. Removed ignition switch, corrected connections, re-install switch. Hook up rear window defroster. Replace decal on alternator. HOURS	100.00	400.00
	FUEL SYSTEM Replace fuel pump and test. Note: low fuel pressure. Found fuel check valve is sticking. valve, disassemble, clean and install-OK.	100.00 Remove	420.00
Make ch	necks payable to Automotive Restorations, Inc. nce charges are assessed monthly at 1.0%	OTAL DUE	

www.automotiverestorations.com

www.vintageracingservices.com

Daga 1



(203) 377-6745 Fax (203) 386-0486





DATE

2/28/13

INV#

WS71M-32

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
TY/HRS	DESCRIPTION	COST	AMOUNT
2.7	HOURS	100.00	270.00
15.2	INSTRUMENTS/CONTROLS Removed, disassembled and cleaned bezels and lenses of all gauges. Refit and adjust. Repair steering wheel horn ring. Weld a block on top of the jack to fit the jack points. Replaced broken brake light switch. Fabricated covers for opening slots on steering column. Checked all dash functions. Repaired connection at air horn compressor. HOURS	100.00	1,520.00
	GLASS/SEALS Replace window channels in both doors. Remove door glass, old window channel. Affix and install. Repaired drivers doors seal and rear glass seal.		
9	HOURS	100.00	900.00
3.9	CHROME/TRIM Install front and rear bumpers. HOURS	85.00	224 50
	SEATING/INTERIOR PANELS/CARPETS Fabricate and cut new door panel backings from 1/8"masonite and assemble to top metal fra Fabricate and install rear arch panel covers. Fabricate and install rear quarter panel covers. Install new leather to wheel arches. Upholster right and left kick panels, dash fascia and dash side panels.		331.50
Make ch	necks payable to Automotive Restorations. Inc	AL DUE	

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486





DATE

2/28/13

INV#

WS71M-32

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Pad and upholster center console.		
	Fabricate new compartment lids and upholster in leather.		
	Upholster trunk lid panel and lower trunk panel.		
	Prepare front seat covers for installation.		
	Fabricate new rear seat base covers.		
	Cut new trunk base panel from 1/2" plywood.		
	Clean and vacuum interior carpets and insulation to prepare for carpet installation.		
	Complete assembly of dash and console panels.		
	Fabricate and install carpet set. Install lining inside rear compartment.		
	Install door handles.		
	Install new window rub strips.		
	Install kick panels.		
	Replace seat belt webbing. Install seat belts.(extra)		
	Paint seat belt metal cap.(extra)	-	
	Make over mats. (extra)		
	Install compartment lids.		
	Refresh A&B roof post leather.		
	Install door panels.		
	Install leather to door pulls.		
142.5	HOURS	100.00	14,250.0
	METAL WORK (EXTRA)		~
	Fabricate (2) pieces of aluminum pipe for the air cleaner assembly.		
1.5	HOURS		
		100.00	150.0
	REASSEMBLY		
	Install new heat valve fill system.		
Make cl	necks payable to Automotive Restorations, Inc.		
Finar	nce charges are assessed monthly at 1.0%	TOTAL DUE	

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486





DATE

2/28/13

INV#

WS71M-32

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
23.3	Install battery. Remove and re-install A/C pump and water pump cable drive in order to change the be alternator. Replace power steering hoses. R&R left front inner wheel house and all hose mounting brackets to steering cooler. HOURS Labor Subtotal	Its. R&R 85.00	1,980.50
			21,412.00
75.7	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES		
142.5	HRS ASST UPHOLSTERY SUPPLIES	5.00	378.50
1	SEW FOAM (1/4") (ONE ROLL)	10.00	1,425.00
1	SEW FOAM (1/2") (ONE ROLL)	118.18	118.18
4	SOUND DEADENING MATERIAL (21"X29" SHEETS)	122.85	122.85
1	UPPER RADIATOR HOSE	40.23	160.92
2	SILL PLATE	55.97	55.97
2	WINDOW SWITCH	198.25	396.50
1	INTERIOR LIGHT SWITCH	59.26	118.52
1	FUEL PUMP SWITCH	47.82	47.82
1	HEADLIGHT SWITCH	57.97	57.97
1	INTERIOR HEATER BLOWER SWITCH	57.97	57.97
1	REAR WINDOW DEFROST SWITCH	54.47 62.05	54.47
1	HEADLIGHT LIFT MOTOR	243.60	62.05
2	WATER PUMP/AIR CONDITIONING BELTS	46.41	243.60
1	POWER STEERING BELT	30.74	92.82
1	INTERIOR PANEL BOARD	13.85	30.74
1	FUSE PANEL BACKING (IN ENGINE BAY)	25.99	13.85 25.99
1	HEATER VALVE (UNDER HOOD)	75.95	75.95
Make cl	hecks payable to Automotive Restorations, Inc.		
Finar	nce charges are assessed monthly at 1.0%	OTAL DUE	

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486





DATE

2/28/13

INV#

WS71M-32

Due Upon Receipt

	1971 Maserati Ghibli			
	RO # 2021			
QTY/HRS	DESCRIPTION		COST	AMOUNT
2	BOSCH RELAY		42.05	84.10
1	DEFROST DUCT HOSE		30.89	30.89
1	SIGNAL FLASHER		13.48	13.48
1	BATTERY DISCONNECT SWITCH		43.19	43.19
295	INTERIOR LEATHER (SEATS AND PANELS-295 SQ FT)		10.30	3,038.50
1	FUEL PUMP WITH FITTINGS		191.97	191.97
1	BATTERY		127.59	127.59
1	BRAKE LIGHT SWITCH		13.79	13.79
1	FUEL FILL UP		74.31	74.31
1	DOOR TO GLASS FELT STRIP	- 1	139.20	139.20
1	TRUNK LINING MATERIAL		183.45	183.45
1	CASTROL GT/LMA BRAKE FLUID		17.50	17.50
2	POLISH SILL TRIMS		36.25	72.50
1	GENERATOR DECAL		43.50	43.50
	Parts Subtotal			7,613.64
192	SUBLET			
1	EXPEDITED RETURN SHIPPING AND INSURANCE FOR BUMPER		235.00	235.00
1	CHROME PLATE REAR BUMPER AND BUMPER GUARDS		4,090.32	4,090.32
1	SHIPPING: SILL SENT FOR POLISHING		6.93	6.93
	Sublet Subtotal		0.00	4,332.25
				,,002.20
	Waste Disposal Fee			33,357.89
	6.35% CT SALES TAX - effective 07/01/2011		1.00%	333.58
	0.00 % OT OALLO TAX - ellective 07/01/2011		6.35%	2,134.69
Make ch	necks payable to Automotive Restorations, Inc.			
Finar	ice charges are assessed monthly at 1.0%	TOTAL DUE	\$:	35,826.16

www.automotiverestorations.com

L	L > A	I B	I C	l n		
	SORTING PUNCHÎLIST &		C	U		<u> </u>
1	ESTIMATE			222		**
2	DATE: March 15, 2013 REV 1, 3-19-13	1		1 1	VIVIX	1
3	·	1		11/1	INVERS	1/
4	JOB#:2728, Post Amelia Island Punch list	AUT	OMOTI	VE REST	ORATIO	NS INC.
5	OWN	1		1 1	TIXIT	11 1
6	ADDI	1		1	rn /	
7	CITY	1				
8	PHON]			No. of Concession, Name of Street, or other Designation, Name of Stree	
10]		ive Restorat		
12	SCHEDULE; Must be completed and VERY TESTED by 4/30 for NE 1000 participation NOTE ON LABOR RATES			00 Lupes Dri		
13	Labor Rate: High skill: Mech Tech/Metalwork/Paint/Fabrication/Lipholsten/ \$100,00/b	nur	Strattoro	, Connecticu 745 fax 203	it, 06615	
14	Mid Skill: Body & Assembly \$85/hour. Base Skill: Polishing, Gen Prep, Detail \$65/hou	ır	www.autor	notiverestor	ations.com	
15						
	This is an estimate for the work described. It is not to be constructed and the potture of rectanglish work described.	ued as a	firm auot	e for the nr	ice contai	ned herein
	The nature of restoration work often requires disassembly beyon	d visual	inspection	at which t	imo oomn	ananta aan
16	be fully evaluated. Additional work discovered during this pro	cess is	beyond th	e scone of	thie initia	l actimate
	Flease note our 47- 20% contingency included to address the	nature c	f our wor	k per our t	erme and	conditions
	statement above the acceptance signature area of this estimate	Additio	nal time ar	d/or narta	and mater	ala manulas
	needed to properly complete the job. Should this occur, we vestimate accordingly. For this reason, the final price of the	vill advi	se you, re	quest appr	oval, and	amend the
	estimate accordingly. For this reason, the final price of the comdate.	pleted w	ork may d	iffer from th	ne estimate	e as of this
17	100.0.00000					
	I. GENERAL NOTES Now what is needed to make this car not only look but perform like a prize winn	ing Maser	ati Ghihli SS	Go and show	v roliobility i	the feet
18	I. GENERAL NOTES Now what is needed to make this car not only look but perform like a prize winn	ing Maser	ati Ghibli SS.	Go and show	v reliability is	s the focus.
22		ing Maser	ati Ghibli SS.	Go and show	v reliability is	s the focus.
18	Now what is needed to make this car not only look but perform like a prize winn	L	abor	Parts &	v reliability is	Total
22 23 24 25	Now what is needed to make this car not only look but perform like a prize winn					
22 23 24 25	Now what is needed to make this car not only look but perform like a prize winn Item II. EVALUATION & ROAD TEST L01a/L12	L	abor	Parts &		Total
22 23 24 25	Now what is needed to make this car not only look but perform like a prize winn Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip.	L	abor	Parts &		Total
22 23 24 25	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of	L	abor	Parts &		Total
22 23 24 25 26	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us	L	abor	Parts &		Total
22 23 24 25 26	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and one	L	abor	Parts &	Sublet	Total L + P&M + S
22 23 24 25 26	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us	L Hrs.	abor Amount	Parts & Materials		Total
22 23 24 25 26 27 42 43	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL	L Hrs.	abor Amount	Parts & Materials	Sublet	Total L + P&M + S
22 23 24 25 26 27 42 43	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows: Remove, blast to clean and silver cad plate bood latches	0.00	abor Amount 0.00	Parts & Materials	Sublet 0.00	Total L + P&M + S
22 23 24 25 26 27 42 43 44	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows: Remove, blast to clean and silver cad plate hood latches Purchase correct silver quilted insulation, sew and fit under bood pad. Charlies	L Hrs.	abor Amount	Parts & Materials	Sublet	Total L + P&M + S
22 23 24 25 26 27 42 43 44	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows:	0.00	abor Amount 0.00	Parts & Materials	Sublet 0.00	Total L+P&M+S 0.00
22 23 24 25 26 27 42 43 44	Item II. EVALUATION & ROAD TEST LO1a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows: Remove, blast to clean and silver cad plate hood latches Purchase correct silver quilted insulation, sew and fit under hood pad. Charlie found it in Holland of all places	0.00 2.50	abor Amount 0.00	Parts & Materials 0.00	Sublet 0.00	Total L + P&M + S
22 23 24 25 26 27 42 43 44	Item II. EVALUATION & ROAD TEST LO1a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any fallings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows: Remove, blast to clean and silver cad plate hood latches Purchase correct silver quilted insulation, sew and fit under hood pad. Charlie found it in Holland of all places	0.00 2.50	abor Amount 0.00	Parts & Materials 0.00	Sublet 0.00	Total L+P&M+S 0.00
22 23 24 25 26 27 42 43 44 45 46	Item II. EVALUATION & ROAD TEST L01a/L12 Pre NE 1000 extensive test and tune time program to insure a good trip. Address any failings fully replacing any component that gives any sign of issues. Guesstiamte assuming nothing major noted. Well just drive it and see if we note any issueson us EVALUATION & ROAD TEST TOTAL IV. VEHICLE DISASSEMBLY - REASSEMBLY L01c Remove and refit as follows: Remove, blast to clean and silver cad plate hood latches Purchase correct silver quilted insulation, sew and fit under bood pad. Charlies	0.00 2.50	abor Amount 0.00	Parts & Materials 0.00	Sublet 0.00	Total L+P&M+S 0.00

	A	В	С	D	E	F
49	Purchase and fit correct WS washer system. Lucas and same as Jag E	2.50	250	340		590
	DISASSEMBLY TOTAL	19.00	1,470.00	1,100.00	200.00	2,620.00
60	V DDIVETDAIN LOO					
	V. DRIVETRAIN L02 Engine L02a					
02	Eligille Loza					
63	Diagnose and correct apparent fuel starvation and/or intermittent ignition malfunction causing stumble then power drop at constant 2500+ RPM speeds in top gears and occasional shutdown. Note that fuel pump switch seems to periodically rectify. Time assigned is a guesstimate until problem found/fixed.	8.00	800	200		1,000
66	The Jury is in: the cam covers should be black per AQ article and MIA tech guidelines (a few SS models left the factory with heads unpainted but chassis numbers were never recorded). Refinish upper heads in crinkle finish best possible in situ. Remove plugs/wires and other components as needed; reassemble. Note that this is a top end cosmetic approach only as the entire engine assembly was painted in factory as a unit prior to final assy.	10.00	850	100		95
67	EBES PARTIES OF THE P		- 000 60		A.	
78	ENGINE TOTAL	18.00	1,650.00	300.00	0.00	1,950.0
79	Tune L02b					
	Check all basics and (if not fitted) purchase and fit Petronix electronic ignition module to enhance running and reliability. Assuming still on point system. Paint coil as needed to appear correct. Spec Petronix coil is part of system.					
95	TUNE TOTAL	5.00 5.00	500.00	290 290.00	0.00	
95	Delete cost of line 48 if undertaken.		500 500.00		0.00	790.0
95 96 97	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL	7.50	500.00 750	290.00 150		790.0
95 96 97 112 81	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN	7.50 7.50	750 750.00	290.00 150 150.00	0.00	90.0 900.0
95 96 97 112 181 253	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN	7.50	500.00 750	290.00 150		790.0
95 96 97 112 181 253 254	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation.	7.50 7.50 31.10	750 750.00 2,960.00	150 150.00 770.00	0.00	90.0 900.0 3,730.0
95 96 97 12 181 253 273 289	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS	7.50 7.50 31.10	750 750.00 2,960.00	150 150.00 770.00	0.00	90.0 900.0 3,730.0
95 96 97 12 81 253 254 273 89	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS	7.50 7.50 31.10	750 750.00 2,960.00	150 150.00 770.00	0.00	90.0 900.0 3,730.0
95 96 97 112 181 253 254 273 289 291	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06	7.50 7.50 31.10	750 750.00 2,960.00	150 150.00 770.00	0.00	900.0 3,730.0
95 96 97 12 81 253 254 273 89 90 91 92 93	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch)	7.50 7.50 31.10 3.00 3.00	750 750.00 2,960.00	150 150.00 770.00	0.00	900.0 900.0 3,730.0 330.0
95 96 97 112 81 253 254 273 89 90 91 92 93 94	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop 4 way flashers (assumed related to showe	7.50 7.50 31.10 3.00 3.00	750 750.00 2,960.00 300.00	150 150.00 770.00	0.00	99 900.1 3,730.4 33 330.1
95 96 97 12 81 253 254 273 89 91 92 93 94 95	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp	7.50 7.50 31.10 3.00 3.00 3.00	750 750.00 2,960.00 300.00	150 150.00 770.00 30 30.00	0.00	99.0.0 99.0.0 3,730.0 330.0
95 96 97 12 81 253 254 273 89 90 91 92 93 94 95 08	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop 4 way flashers (assumed related to showe	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	990.0 900.0 3,730.0
95 96 97 12 81 253 254 273 89 90 91 92 93 94 95 08	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp	7.50 7.50 31.10 3.00 3.00 3.00	750 750.00 2,960.00 300.00	150 150.00 770.00 30 30.00	0.00	99 900.1 3,730.1 33 330.1
95 96 97 12 81 253 254 273 89 90 91 92 93 94 95 08	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	99 900.1 3,730.1 33 330.1
95 96 97 112 181 253 254 273 289 90 291 292 293 294 95 608 609	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp TOTAL WIRING & ELECTRICAL	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	99 900.1 3,730.1 33 330.1
95 96 97 112 181 253 254 273 289 290 291 292 293 294 295 809 809	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp TOTAL WIRING & ELECTRICAL	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	99 900.1 3,730.1 33 330.1
95 96 97 112 181 253 254 273 290 291 292 293 294 295 808 809 609	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp TOTAL WIRING & ELECTRICAL	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	33 330.0
95 96 97 112 181 253 254 273 289 291 293 293 293 293 293 293 293 293 293 293	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp TOTAL WIRING & ELECTRICAL	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	90.0 900.0 3,730.0
95 96 97 112 181 253 254 273 290 291 292 293 294 295 808 809 609	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp TOTAL WIRING & ELECTRICAL	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	33 330.0
95 96 97 112 181 253 254 273 289 90 291 293 293 294 295 608 609 609 601 602	Delete cost of line 48 if undertaken. TUNE TOTAL Cooling System L02c Repair overheating at idle. Check system and flow check radiator. Check fan sensor, replace as needed. Fit hidden lower dash mounted fan over-ride switch system with bright hidden "system on" warning light to allow driver manual fan control as and when needed. COOLING SYSTEM TOTAL TOTAL DRIVETRAIN VIII. INSTRUMENTS & CONTROLS Service HVAC to insure all working properly and that A/C holds charge perfectly over extended period. Advise any work needed to insure long term operation. TOTAL INSTRUMENTS & CONTROLS IX. WIRING & ELECTRICAL L06 Repair inop rt tail lamp Repair inop turn signals (assumed switch) Repair inop rear marker lamp TOTAL WIRING & ELECTRICAL	7.50 7.50 31.10 3.00 3.00 0.50 3.00	750 750.00 2,960.00 300.00	290.00 150.00 770.00 30 30.00 5 5550	0.00	99 900.1 3,730.1 33 330.1

Α	В	1 0 1	D I	F 1	F
Total Labor		5,110,00			
Total Parts & Materials			2.460.00		
Total Sublet			_,	0.00	
Amount Subject to Sales Tax				0.00	7,570
Sales Tax			6.35%		481
Grand Total			0.0070		8,051
	Total Parts & Materials Total Sublet Amount Subject to Sales Tax Sales Tax	Total Labor Total Parts & Materials Total Sublet Amount Subject to Sales Tax Sales Tax	Total Labor Total Parts & Materials Total Sublet Amount Subject to Sales Tax Sales Tax	Total Labor	Total Labor

ACCEPTANCE

I do hereby authorize the preceding repair/restoration work to be done along with all necessary parts and materials. You and your employees may operate the vehicle for purposes of testing, inspection and delivery at my risk. An express mechanics lien is acknowledged on the vehicle to secure or partially secure the amount of repairs thereto. It is understood that I will be held responsible for any cost of collection or legal expense in any way relating to these repairs. I agree to that any controvers y or claim rising out of or relating to this agreement, or the breach of this agreement, shall be settled by arbitration in accordance with the rules of the American Arbitrations Association. A judgment of a court having jurisdiction may be entered upon the arbitrator's award. I agree to pay interest on any balances remaining unpaid after 30 days at the standard Automotive Restorations Inc. invoicing rate applicable to the period of time the debt exists. It is also understood that Automotive Restorations Inc. it's officers, age nts or employees will not be held responsible for loss or damage to cars or articles left in cars due to fire, theft, or any other cause beyond their control. I will maintain insurance on the vehicle for the period of time it is in the custody of Automotive Restorations Inc. Parts, materials and labor prices are current and subject to change. Occasionally worn or damaged parts/areas are discovered which are not evident on initial inspection. For these reasons the above prices are not guaranteed. The figures provided are an estimate of the time needed invoiced at our labor rate, plus the cost of parts and materials expected to be required. Due to the nature of restoration work all figures given are offered as guidelines only and are subject to a +/- 20% cost range for the specific parts/labor/materials described in this document. We may find work, parts and materials needed that are not described in this document. Should this occur, we will advise of any additional work needed not described herein to seek authorization prior to undertaking repair.

I HAVE READ THE FOREGOING AND AGREE TO THE TERMS STATED THEREIN.

Signature	Date
Print name	



MASERATI SPA

A SOCIO UNICO

CAPITALE SOCIALE € 40,000,000,00

VIALE CIRO MENOTTI, 322 - 41100 MODENA

PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010

TEL. 059 590511 - FAX 059 226765

DIREZIONE E COORDINAMENTO: FIAT SPA

N. Fattura/Invoice n° Data/Date 01309103 22-03-2013	Cod. Cliente/Client 094346	Pag.
Descriz. Documento/Doc. description Fattura	Vs. Partita Iva/V.A.T.	Registration n°
Modalità di Spedizione/Shipping Company	Porto/Shipment terms	
Condizioni di Pagamento/Payment Terms JO GS D.F.F.M.	Banca d'Appoggio/Ba BANCA POPOLARE DE IT46L 05387 12900	LL'EMILIA ROMAGNA

SWIFT BPM01722

Annt(FIR)

Appt(IISD)

	5#1F (BFMU1122					Aant(EUX)	Amnt(U5D)		
Cod. Art. Art. N.	Descrizione Description	U.M. U.M.	Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Net Unit Price Currency:	Iva	Orig
	in this Convention on International	Trade	in Endang	ered Species of	4il				
	Fauna and Flora, done at Washingtho	n on Ma	arch 3, 19	73, and ratified	in				
	Italy by the Law nr.874 Of 19/12/19	75, and	d followin	ig amendments.					
			in t	aith					
					1				
					7 /				
		MA.							
		4							
			7						
						1			

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/To	otal Amount
Goods total	740,00	740,00	IVA 21%	155,40	(EUR)	895,40
Note		Scat	30-04-2013 A	205 8		



MASERATI SPA
A SOCIO UNICO
CAPITALE SOCIALE € 40.000.000,00
VIALE CIRO MENOTTI, 322 - 41100 MODENA
PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010
TEL. 059 590511 - FAX 059 226765
DIREZIONE E COORDINAMENTO: FIAT SPA

		a tout tout	T _n
N. Fattura/Invoice n° 01309103	Data/Date 22-03-2013	Cod. Cliente/Client 094346	Pag.
Descriz. Documento/E Fattura	Ooc. description	Vs. Partita Iva/V.A.T.	Registration n°
Modalità di Spedizion	e/Shipping Company	Porto/Shipment terms	
Condizioni di Pagame	nto/Payment Terms	Banca d'Appoggio/Ba	ank references
30 89-0.F.F.N.		BANCA POPOLARE DE	LL'EMILIA ROMAGNA
		IT46L 05387 12900	000000894454
		BUTTER BEWEITER	

Dank/FIID)

Asside District

	SWIFT BPMOIT22					Annt(EUR)	Annt(USD)		
Cod. Art. Art. N.	Descrizione Description		Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Net Unit Price Currency:	Iva	Orig
	Internal num. :VA3/34003743 Our Group Code : 0	Y	our Group	Code :	0				
910040023	Classic vehicles documentation MASERATI SHIBLI SS COUPE' CHASSIS AM115/49*2246* 1 ENVELOPE CM 35X27X0.1 GROSS WEIGHT KOS 0.190	#1R	1	740,00		740,00	0,00		
	THE WODDEN PALLETS, WOODEN CRATES OF FREE FROM BARK AND ARE APPARENTLY FF				ARE				
	DOSANA DI COMPETENZA Si dichiara che la merce descritta i stata confezionata con parti di peli	e di	pecie an	mali			/P.		
	elencate, o cumunque citate, mella (internazionale delle specie amimali firmata a Washingthon il 3 marzo 197 nr.874 del 19/12/1973, e successive	e vege	tali in tificata	via di estinzione					
			in	ede					
	TO THE COMPETENT CUSTOMS								
	We declare that the goods indicated made of leather parts of animal spec				ď,				

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/Total Amount
Note					



(203) 377-6745 Fax (203) 386-0486





DATE

3/28/13

INV#

WS71M-33

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 03/01/2013 TO 03/28/2013	3301	AWOON
3.3	PANEL WORK Adjust hood to close with ease. (new chrome finishing edge in the jam is hitting the hood) Remove chrome and file pinch weld. Install chrome and adjust. HOURS		
	DE ACCES AND ACC	100.00	330.0
3.7	REASSEMBLY Install air intake box and ducting. Adjust brake pedal height. Connect rear window defroster. Top off all fluids for road test. Check out safety list. HOURS		
		85.00	314.50
	EXHIBIT PREP DETAIL Car show clean and detail exterior of vehicle. Car show clean and detail interior for Amelia Island Event. HOURS		
100000	Labor Subtotal	85.00	1,037.00 1,681.50
7	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES		1,001.00
12.2	HRS ASST CLEANING SUPPLIES Parts Subtotal	5.00 5.00	35.00 61.00 96.00
Make ch	ecks payable to Automotive Restorations, Inc. se charges are assessed monthly at 1.0% TOTAL		

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486





DATE

3/28/13

INV#

WS71M-33

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2021		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00 6.35	

www.automotiverestorations.com

www.vintageracingservices.com

Daga 2



(203) 377-6745 Fax (203) 386-0486



DATE

3/28/13

INV#

WS71M-34

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
TY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 03/01/2013 TO 03/28/2013		
	ROAD TEST		
	Road test, but failed to duplicate stalling or lack of power concern.		
0.9	HOURS	100.00	90.00
	COOLING SYSTEM		
	Added circuit and light to activate radiator cooling fan from cockpit.		
3	HOURS	100.00	300.0
	ELECTRICAL		
	Correct inoperable brake lights.Cleaned fuse block-OK		
	Correct inoperable turn signals and hazard lights. Cleaned fuse block-OK.		
	Diagnose inoperable right rear park and plate lights. Repair plate light socket. Must replace right	t	
	rear park socket. (not yet complete)		
	Removed tail lights for replacement match up. ****Progress invoice, not yet complete.****		
6.9	HOURS		
0.0	Tiodic	100.00	690.0
	FUEL SYSTEM		
	Diagnose poor running due to fuel supply. Run on single pump to test valves.		
	Service sticking cross over valve.		
	Connect fuel pump for right fuel tank.		
4.2	Road test 30 miles. Fixed. HOURS		
4.2	HOUNG	100.00	420.0

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

3/28/13

INV#

WS71M-34

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Labor Subtotal		1,500.00
11.5 8 1	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES CARPET (BLACK WILTON II, 8 YARDS)-omitted from previous bill COOLING FAN SWITCH Parts Subtotal	5.00 95.70 6.50	57.50 765.60 6.50 829.60
	Waste Disposal Fee 6.35% CT SALES TAX - effective 07/01/2011	1.00% 6.35%	2,329.60 23.30 149.41

www.automotiverestorations.com

Finance charges are assessed monthly at 1.0%

www.vintageracingservices.com

\$2,502.31

TOTAL DUE



(203) 377-6745 Fax (203) 386-0486



DATE

4/25/13

INV#

WS71M-35

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
TY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 03/29/2013 TO 04/25/2013 Repair items per KB punch list.		
	LIGHTING/FIXTURES		
	Repair intermittent rear lighting.		
	Install (6) new light sockets in left and right tail lamp assemblies.		
6.5	Assembled, installed and tested tail lamps. All OK. HOURS		
0.0	HOUNS	100.00	650.00
	FUEL SYSTEM		
	Tested fuel pumps. Road test with fuel pressure gauge. Vehicle runs out of rule at	high RPM's	
	Attempted to by pass fuel tank check valve and road test but still a problem. Road	test with both	
	talks fullling at the same time, but still not working		
	Fit a 3/8" rubber fuel hose from pumps to carburetors and tested. Better but not fixe	ed.Remove air	
	box assembly and carburetor tops to check float levels and to see what size needle seat. Currently 175, change to 200, per Ghibli spec. Replumb to run single L&R tan	e and	
	systems. Pressure maintains. Replace both pumps w/ OEM. Test. Problem persists	k fuel	
	rue valves. Replace both pumps with facet SS units. Problem eliminated Pressure	s. Service all	
00.7	1 logiess invoicenot yet complete.	o mamam.	
29.7 -21.7	HOURS COURTESY CREDIT	100.00	2,970.00
-21.7	COURTEST CREDIT	100.00	-2,170.00
	CHROME/TRIM		
	Remove hood latches to send out for chroming.		
1	HOURS	85.00	85.00
Make ch	necks payable to Automotive Restorations, Inc.		
Finan	ce charges are assessed monthly at 1.0%	TOTAL DUE	

www.automotiverestorations.com



100 Lupes Drive Stratford, CT 06615 (203) 377-6745 Fax (203) 386-0486



DATE

4/25/13

INV#

WS71M-35

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
QTY/HRS	DESCRIPTION	COST	AMOUNT
1.9	COLLECTOR SERVICES Thoroughly clean vehicle for Gooding photo shoot.(assist photographer) HOURS Labor Subtotal	70	.00 133.00 1,668.00
17 6 2 1 1 3 2 4 2 2	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES TAILLIGHT SOCKETS EPOXY CUPS FUEL FILTER TAIL LIGHT LENS HARDWARE (STAINLESS STEEL) STARTRON-FUEL ADDITIVE FUEL FILL UP-TESTING NEEDLE AND SEAT (200) FUEL PUMPS OEM RETURNED (20% RESTOCKING FEE) FUEL PUMP FACET SS Parts Subtotal	5 3 9 62 6 55 22	
	Waste Disposal Fee 6.35% CT SALES TAX	1.00	
Make ch	necks payable to Automotive Restorations, Inc.	TOTAL DUE	\$2,561.11

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

5/30/13

INV#

WS71M-36

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
TY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR PRE NE 1000 RALLY WORK PERFORMED 04/26/2013 TO 05/30/2013		
	ENGINE MECHANICAL Diagnose and repair odd occasional running issue. Replace fuel pumps. Replace needle and seats in carburetors and set float height.		
	Narrow down to fuel delivery. Bench test original pumps or refit 2X. Problem persists. Fit after fuel gauge to monitor pressures. Conclusion/Problem reproduction OEM pumps have bypass valves which in concert with "T" valve caused fuel to return to tank on varied flow demand! Replace pumps with non OEM. Fixed		
24.7 -12.7	HOURS COURTESY DISCOUNT	105.00 105.00	2,593.5 -1,333.5
	SERVICE Replace window washer pump and wiper blades. Evacuate and recharge A/C system.		
5	HOURS	105.00	525.0
4.0	CHROME/TRIM Remove left door panel and repair sticking handle. Shim armrest and re-install door panel.		020.0
1.8	nours	90.00	162.0
6.5	INTERIOR PANELS Repair and install trunk panels into vehicle. Detail and align. HOURS	105.00	682.50
	ROAD TEST	, 55.55	002.00
Make ch	necks payable to Automotive Restorations, Inc. ace charges are assessed monthly at 1.0% TOTAL DI		

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

5/30/13

INV#

WS71M-36

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
TY/HRS	DESCRIPTION	COST	AMOUNT
1.4	Extensive road test after fuel pump replacements to monitor and insure repair. HOURS	105.00	147.00
2.4	FINAL CHECK OUT Perform final check out per ARI format. Clean vehicle inside and out and prep for NE rally. HOURS Labor Subtotal	90.00	216.00 2,992.50
22.6 6.5 2 1 1 1 1 4 1 1 1 2	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES HRS ASST UPHOLSTERY SUPPLIES FUEL PUMP, ELECTRIC LUCAS SCREEN JET WINDSHIELD WASHER SHIPPING: SENT HOOD HARDWARE FOR PLATING FUEL FILL UP WIPER BLADE SET (18") FUEL LINE FITTING, AN-6 X 90 DEG ENGINE PAINT (BLACK WRINKLE) FUEL FILL UP STARTRON-FUEL ADDITIVE DURACOOL Parts Subtotal	5.00 10.00 158.89 321.86 6.83 50.00 95.01 17.80 22.45 57.42 6.90 24.95	113.00 65.00 317.78 321.86 6.83 50.00 95.01 71.20 22.45 57.42 6.90 49.90 1,177.35
1	SUBLET SILVER CADMIUM PLATE UNDERHOOD LATCHES Sublet Subtotal	217.50	217.50 217.50

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

5/30/13

INV#

WS71M-36

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2728		
QTY/HRS	DESCRIPTION	COST	AMOUNT
	Waste Disposal Fee 6.35% CT SALES TAX	1.00	
Make ch	necks payable to Automotive Restorations, Inc.	TOTAL DUE	\$4,705.78

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

6/27/13

INV#

WS71M-37

Due Upon Receipt

	1971 Maserati Ghibli		
	RO # 2842		
TY/HRS	DESCRIPTION	COST	AMOUNT
	LABOR WORK PERFORMED 05/31/2013 TO 06/27/2013		
14.9	EXHIBIT PREP DETAIL FOR PRE AUCTION DISPLAY Remove all necessary parts to access cylinder heads for refinish. Refinish cylinder heads with crinkle black. Detail engine bay best possible within time assigned per estimate. HOURS	90.00	1,341.00
	ENGINE/MISCELLANEOUS Diagnose running issues to faulty fuel pumps. Remove and replace fuel pumps. Repair horn button. Remove and replace speedometer cable. Diagnose customer complaint of sticky gas pedal. Miscellaneous details per list to prep for sale. ***Progress invoice not yet complete. Head and and and areal it to be a selected and areal it to be	00.00	1,041.00
17	***Progress invoice-not yet complete. Hood pad and small items remain to be completed.*** HOURS Labor Subtotal	105.00	1,785.00 3,126.00
31.9 2 1 1 1 8	PARTS/SUPPLIES HRS ASST MECH/ASSY SUPPLIES FUEL PUMP (FACET) SPEEDOMETER CABLE FUEL FILL UP ENGINE PAINT SPARK PLUG (NGK) Parts Subtotal	5.00 88.74 159.69 20.63 15.48 3.09	159.50 177.48 159.69 20.63 15.48 24.72 557.50

www.automotiverestorations.com



(203) 377-6745 Fax (203) 386-0486



DATE

6/27/13

INV#

WS71M-37

Due Upon Receipt

	1971 Maserati Ghibli			
	RO # 2842			
QTY/HRS	DESCRIPTION		COST	AMOUNT
	Waste Disposal Fee 6.35% CT SALES TAX		1.00% 6.35%	3,683.50 36.84 234.93
Make ch	ecks payable to Automotive Restorations, Inc.	TOTAL		

www.automotiverestorations.com