

Mailed 12/27/2011 *SA*

CUSTOMER #: 1148977

3692904

**MERCEDES-BENZ OF BELLEVUE**  
A Barrier Motors Company

11950 Bellevue-Redmond Road, Bellevue, Washington 98005  
(425) 455-8535

\*INVOICE\*

DUPLICATE 2  
PAGE 1

OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE REQUIRED TIME.

SERVICE ADVISOR: 60050 MARC LARSON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	57	Mercedes-Benz 190	A1210406500875	8038	42289/42291	T6482
DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT
01JAN57 DD			17:00 29OCT11			
R.O. OPENED	READY	PREPARED BY	DLR: N/A		CASH	26DEC11
15:04 30SEP11	11:24 26DEC11					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A VISUAL INSPECTION  
VI VISUAL INSPECTION  
141 CT1  
PARTS: 0.00 LABOR: 594.00 OTHER: 0.00 TOTAL LINE A: 594.00  
42291 PERFORM VISUAL INSPECTION TECH 141, 00-0000-6 0 6 00 PERFORM VISUAL INSPECTION OF VEHICLE. R&R WHEELS, R&R BRAKE DRUMS INSPECT BRAKES FOUND FRONT AND REAR BRAKE SHOES @ 90%. INSPECT VEHICLE FOR FLUID LEAKS, FOUND LEAKS AT REAR AXLE. TRANSMISSION. LEAK AT ENGINE AREA INCLUDE. COOLANT LEAK AT ENGINE BLOCK SIDE COVER. VALVE COVER GASKETS WET, OIL FILTER AND DRAIN PLUG WET. BRAKE RESERVOIR CAP WET. FUEL SEEPAGE AT CARBS. FOUND GENERATOR MOUNTING NOT ALIGNED PROPERLY. FOUND POOR ELECTRICAL CONNECTORS AT ENGINE AREA AND GENERATOR. CHOKE CABLE MOUNT AT ENGINE MISSING. DRIVERS DOOR TRIM LOOSE. FOUND SUPPORT ARM FOR TRANSMISSION SHIFTER BROKEN. R&R BRACKET AND REPAIR MOUNTING BRACKET.

B DO NOT WASH THIS VEHICLE  
NOWASH DO NOT WASH THIS VEHICLE  
99 CDEF  
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

C NO ALTERNATE TRANSPORTATION NEEDED AT THIS TIME.  
5 NO ALTERNATE TRANSPORTATION NEEDED AT THIS TIME.  
99 CDEF  
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

D\*\* PERFORM REPAIRS PER CUSTOMER AUTHORIZATION  
000000 GROUP 00 - NO OPERATION NO. AND TIME GIVEN  
USE ACTUAL TIME (PUNCH CARD) WITH 00-0000/01  
AS OPERATION NO.  
141 CT1  
1 000-180-00-09 FILTER ELEME 2079.00 2079.00  
1 121-010-03-10 CYLINDER SID 23.38 23.38 23.38  
235.40 235.40 235.40


Any controversy or claim arising out of or relating to this contract or breach thereof, shall be settled in accordance with the arbitration rules of the consumer-business arbitration tribunal of the Better Business Bureau.

The factory warranty constitutes all of the warranties with respect to the sale of the item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. The information contained on the estimate, worksheet, and/or repair order is incorporated here in by reference.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY



CUSTOMER #: 1148977

3692904

# MERCEDES-BENZ OF BELLEVUE

A Barrier Motors Company

11950 Bellevue-Redmond Road, Bellevue, Washington 98005  
(425) 455-8535

\*INVOICE\*

DUPLICATE 2  
PAGE 2

OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE REQUIRED TIME.

SERVICE ADVISOR: 60050 MARC LARSON

YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG		
57	Mercedes-Benz 190	A1210406500875	8038	42289/42291	T6482		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	RATE	PAYMENT	INV. DATE
01JAN57 DD			17:00 29OCT11			CASH	26DEC11
R/O. OPENED	READY	PREPARED BY	DLR:N/A				
15:04 30SEP11	11:24 26DEC11						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	121-015-06-21	GASKET	VALVE		33.08	33.08	33.08
38	000000-001475	SCREW			5.10	5.10	193.80
1	002-997-57-92-64	V-BELT			18.00	18.00	18.00
2	180-991-06-40	SPACER PIPE,			26.25	26.25	52.50
4	120-155-00-81	RUBBER PAD			5.53	5.53	22.12
4	120-155-00-82	PLATE WASHER			9.72	9.72	38.88
2	121-991-04-40	SPACER PIPE,			27.75	27.75	55.50
4	121-155-00-81	RUBBER PAD			72.60	72.60	290.40
4	121-155-00-82	PLATE WASHER			4.05	4.05	16.20
1	121-155-00-72	COUPLING NUT			19.50	19.50	19.50
1	121-155-02-28	CLAMP			99.00	99.00	99.00
1	121-155-13-23	TIGHTENING S			261.80	261.80	261.80
1	000-431-54-33	CAP, BRAKE FL			13.65	13.65	13.65
1	000-997-29-40	SEAL RING VL			5.60	5.60	5.60
1	Q-1-03-0002	ANTI-FREEZE			26.55	26.55	26.55
1	CDISP	COOLANTDISP			5.57	5.57	5.57

LUBE OIL

CT1

PARTS: 1410.93 LABOR: 2079.00 OTHER: 20.88 TOTAL LINE D: 3510.81

42291 PERFORM REPAIRS PER CUSTOMERS AUTHORIZATION TECH 141,  
00-0000-21 0 21 00 REPAIR BROKEN SHIFT LINKAGE, R&R GENERATOR REPAIR  
ELECTRICAL AND MOUNTING. FABRICATE NEW CABLE MOUNT. R&R WHEEL INSPECT  
BRAKE SYS AND REPLACE LEAKING SEAL AT CAP. REPLACED LEAKING ENGINE SIDE  
COVER. REMOVE THREE BROKEN BOLTS AND RETAP CLEAN ALL THREADS. RESEAL  
ENGINE OIL DRAIN PLUG AND FILTER. CLEAN UNDER VEHICLE

\*\*\*\*\*

EST: 0.00 30SEP11 15:04 SA: 60050

CUSTOMER PAY SHOP SUPPLIES FOR REPAIR ORDER

23.22

Any controversy or claim arising out of or relating to this contract or breach thereof, shall be settled in accordance with the arbitration rules of the consumer-business arbitration tribunal of the Better Business Bureau.

The factory warranty constitutes all of the warranties with respect to the sale of the item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for any liability in connection with the sale of this item/items. The information contained on the estimate, worksheet, and/or repair order is incorporated here in by reference.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER SIGNATURE

CUSTOMER COPY



Siegfried Linke  
16533 - 89th Ave NW  
Stanwood, WA 98292

1956 Mercedes Benz 190SL

Vin: 219216502641

make car drivable  
fix brakes - hang up etc.  
fix electrical wiring  
fix and replace heater pipes  
replace brake reservoir and mounting bracket  
replace floor mats with OEM rubber mats  
replace softtop canvas  
repair heater hose (leaking etc.)  
repair shorter hosing  
install missing rear mohr knob bolts  
replace brakehoses  
replace master brake cylinder  
replace right front brake lining  
Arc front brake shoes  
turn front brake drums  
fix charging system  
R + R radiator  
4 new tires

Paint work

hand rub off old overspray  
color sand original paint  
rub out mud wax  
detail all

repair heater core as necessary  
replace core  
master brake cylinder  
battery  
hose  
hose rt.  
hose lf.  
brake flood reservoir  
arc front brake drums  
welding  
shift knob  
new softtop - rebuild, frame, liner  
replace heater core  
softtop OEM  
install softtop top knit  
fix only clear header frame  
replace heater seal  
spiral under side cables and tensions LH + RH  
spiral under roof ledge for bow  
chrome mold tip