

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
3/19/2012	239

Bill To

**PAID**  
**03/23/2012**

P.O. No.	Terms	Project
Sprite		

Description	Qty	Rate	Amount
2/27/2012 Winning Ebay bid on 1961 Austin Healey Sprite, Deposit		1,000.00	1,000.00
3/09/2012 Intercity Transport from Cedar Rapids to Albany		1,527.00	1,527.00
3/04/2012 American Airlines SFO to Cedar Rapids to SFO		546.20	546.20
3/13/2012 Bank Check for Balance on Sprite		21,101.00	21,101.00
3/14/2012 American Airlines ticket change		99.00	99.00
3/14/2012 Long Term Parking		15.00	15.00
3/14/2012 Check out vehicle for purchase	2.5	60.00	150.00
3/15/2012 Standard commission on vehicle sale, 8% of price.		1,768.00	1,768.00

<b>Total</b>		\$26,206.20
<b>Payments/Credits</b>		-\$26,206.20
<b>Balance Due</b>		\$0.00

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
3/31/2012	243

Bill To

**PAID**  
**04/11/2012**

P.O. No.	Terms	Project
Austin Healey Sprite		

Description	Qty	Rate	Amount
3/30/2012 Install two comp floor mount seat belts. Make new runners for driver's seat to allow adjustment.	3	90.00	270.00
3/30/2012 Two Competition seat belts, floor mount 62"	2	127.80	255.60

<b>Total</b>	\$525.60
<b>Payments/Credits</b>	-\$525.60
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
8/13/2012	253

**PAID**  
**08/20/2012**

Bill To

P.O. No.	Terms	Project
Sprite		

Description	Qty	Rate	Amount
Tonneau Cover, Black		398.00	398.00
Tool Kit		50.00	50.00
Absorbent pads, 100'		120.00	120.00
Wash mitt		6.95	6.95
Wash mitt		2.11	2.11
Pedal box seal		4.15	4.15
Flare, high note		48.95	48.95
Flare, low note		48.95	48.95
Flare work first piece, two pedals and two plates		150.00	150.00
Remove engine and transmission from car	4.0	90.00	360.00
Replace safety first brake pads		90.00	90.00
Disassemble transmission on bench and inspect. Check for availability on parts.		90.00	90.00
Check threads for pedal boxes. Replace old belts with S.A.E. lower right plate, adjust seat		90.00	90.00
Assemble backstretch pedal box. Install new brake master cylinder (verify bottom for clearance). Install left pedal plus complete with new link.	1.5	90.00	135.00

<b>Total</b>		\$568.00
<b>Payments/Credits</b>		-\$568.00
<b>Balance Due</b>		\$0.00

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
3/31/2013	267

**PAID**  
**04/18/2013**

Bill To

P.O. No.	Terms	Project
AH Sprite		

Description	Qty	Rate	Amount
Car cover N/B	1	365.00	365.00
door lock, L/R		21.95	43.90
replace right and left door latches. Adjust software		90.00	90.00
Oil Gauge		95.00	95.00
Replace faulty oil gauge	0.1	99.00	9.90
5-Speed Conversion Kit		2,270.00	2,270.00
Converting vehicle from 4-speed to 5-speed.	24	90.00	2,160.00
oversize flywheel		43.75	43.75
fill and cap oil housing to fit starter motor cover		73.00	73.00
repair release lock at top deck		118.75	118.75
move shifter hole to panel		380.00	380.00
Paint for tower		19.85	19.85
Towing to and from body shop		127.00	127.00
oil filter		13.00	13.00
2000 Volvo Racing		9.85	9.85
anti-dive swivel		20.05	20.05
Shell synthetic gear oil		16.70	16.70
Locks, Bywheel		6.95	6.95
repair oil leak at front crank seal with engine out		90.00	90.00
front crank gasket		1.80	1.80
front crank seal		1.80	1.80
front crank lockup		1.20	1.20
speed-sensor, front pulley		72.35	72.35
CV axle SMP Y219 1/2" inner		13.40	13.40
spark plugs NGK BPR7S		1.00	1.00
oil filter		4.00	4.00

<b>Total</b>	\$365.00
<b>Payments/Credits</b>	-\$365.00
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
5/21/2013	270

**PAID**  
**05/31/2013**

Bill To

P.O. No.	Terms	Project
Sprite		

Description	Qty	Rate	Amount
Door latch, R/H	1	52.95	52.95
Door latch, L/H	1	52.95	52.95
Replace right and left door latches. Adjust strikers.	2	90.00	180.00
Gas Gauge	1	95.95	95.95
Replace faulty gas gauge	0.5	90.00	45.00
5-Speed Conversion Kit	1	3,920.00	3,920.00
Converting vehicle from 4-speed to 5-speed.	24	90.00	2,160.00
Re-surface flywheel		43.75	43.75
Drill and tap bell housing to fit starter motor cover.		75.00	75.00
Repair radiator leak at top neck.		118.75	118.75
Move shifter hole in tunnel.		300.00	300.00
Paint for tunnel	1	19.45	19.45
Towing to and from body shop		125.00	125.00
Oil filter	1	13.00	13.00
20w50 Valoline Racing	4	9.85	39.40
Anti-freeze coolant	1	20.95	20.95
75w90 synthetic gear oil	2	16.30	32.60
Locktab, flywheel	1	6.95	6.95
Repair oil leak at front crank seal with engine out.	2	90.00	180.00
Front cover gasket	1	3.80	3.80
Front crank seal	1	3.80	3.80
Front crank locktab	1	1.20	1.20
Speedi-sleeve, front pulley	1	77.35	77.35
PCV valve SMP V329 Intermotor	1	11.30	11.30
Spark Plugs NGK BP6ES	4	3.00	12.00
Gasoline	5	4.00	20.00

<b>Total</b>	\$7,611.15
<b>Payments/Credits</b>	-\$7,611.15
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
7/25/2013	274

**PAID**  
**07/30/2013**

Bill To

P.O. No.	Terms	Project
A/H Sprite	Due on receipt	

Description	Qty	Rate	Amount
7/16/2013 Remove rear wheels, brake drums and both axles. Right axle is broken off inside differential.	1.5	90.00	135.00
7/17/2013 Remove ring and pinion gears from differential housing. Drill broken piece to fit slide hammer for removal.	2	90.00	180.00
7/19/2013 Clean gasket surfaces. Re-assemble differential. Install right axle. Replace left axle hub seal. Re-assemble left axle. Add gear oil.	5	90.00	450.00
7/19/2013 Axle Shaft, Nitrided	1	386.95	386.95
7/19/2013 O-ring	1	1.90	1.90
7/19/2013 Oil Seal, Rear Hub	1	3.20	3.20
7/19/2013 Tab Washer, Hub Nut	1	2.50	2.50
7/19/2013 Gasket Rear Hub	2	1.00	2.00
7/19/2013 Gasket, Differential	1	1.90	1.90
7/20/2013 Drain and remove gas tank. Install new sender. Re-install tank. Gauge reads full when tank is empty. Remove tank. Negative ground makes positive ground sender backwards. Build prototype sender. Reads 1/2 when empty but full when full.	5	90.00	450.00
7/22/2013 Build finish sender and test. Install in tank.	3	90.00	270.00
7/19/2013 Sending Unit, Fuel Tank	1	74.75	74.75
7/19/2013 Gasket Set, Fuel Sender	1	2.50	2.50
7/23/2013 Install fuel tank. Fill with fuel. Torque wheels. Check levels. Road test	2	90.00	180.00

<b>Total</b>	\$2,140.70
<b>Payments/Credits</b>	-\$2,140.70
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
8/5/2013	276

**PAID**  
**08/09/2013**

Bill To

P.O. No.	Terms	Project
Sprite	Due on receipt	

Description	Qty	Rate	Amount
Shop Manual	1	69.60	69.60
8/02/2013 Remove old rear road springs and install new heavy duty units. Rear ride height too high.	3	90.00	270.00
8/03/2013 Remove new springs and dis-assemble to flip third leaf over. Re-assemble springs and re-install in car. Rear ride height now close to stock. Remove and replace front shocks with new units.	5	90.00	450.00
leaf springs, updated	2	128.95	257.90
Shock, lever, front, R/H	1	245.00	245.00
Shock, lever, front, L/H	1	245.00	245.00

<b>Total</b>		\$1,537.50
<b>Payments/Credits</b>		-\$1,537.50
<b>Balance Due</b>		\$0.00

Henk Boverhuis  
 2490 Hilgard Avenue  
 Berkeley, CA 94709

# Invoice

Date	Invoice #
11/28/2016	408

**PAID**  
 12/02/2016

Bill To

P.O. No.	Terms	Project
A/H Sprite	Due on receipt	

Description	Qty	Rate	Amount
Replace sharp hardware for door pockets. Place car on stands. LF axle leaks.	2	110.25	220.50
Cut to fit rubber mats for driver and passenger. Remove gas gauge and dis-assemble to clean inside glass. Re-install gauge.	2.5	110.25	275.63
Drain gas tank and remove. Inspect sending unit for erratic readings. Test new unit, same.	3	110.25	330.75
Order Mk II tank sender and test, OK. Install voltage stabilizer for gas gauge. Install fuel tank with new sender. Fill tank with five gallons of fuel removed. Fuel gauge now reads just less than 3/4.	4	110.25	441.00
Replace left axle hub gasket. Adjust rear brake shoes. Order new exhaust hanger. Secure rubber floor mats. Check levels and tire pressures.	3.5	110.25	385.88
Sending unit MK II	1	46.50	46.50
Voltage Stabilizer	1	21.85	21.85
Floor mats	1	50.70	50.70
Gasket rear hub	1	0.90	0.90
Mount, exhaust	1	3.75	3.75

<b>Total</b>	\$1,777.46
<b>Payments/Credits</b>	-\$1,777.46
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
12/31/2016	411

**PAID**  
01/05/2017

Bill To

P.O. No.	Terms	Project
Austin Healy Sprite	Due on receipt	

Description	Qty	Rate	Amount
Car looks to be leaning. Checked ride height. Rear sits higher than front. Removed both rear springs. Dis-assembled leaf springs and flip an additional leaf. Re-assemble springs and install. Road test and checked ride height. Rear now sits 3/4" lower and front came up 1/4". Car looks level.	6	110.25	661.50
Low sump oil, Noisiness	1	12.00	12.00
Front sump oil, check	1	7.50	7.50
Oil filter element, felt	1	7.00	7.00
Re-oiling oil canister	1	2.10	2.10
Shell Valvoline Loring	1	8.15	8.15

<b>Total</b>		\$661.50
<b>Payments/Credits</b>		-\$661.50
<b>Balance Due</b>		\$0.00

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
1/13/2017	412

Bill To

**PAID**  
01/19/2017

P.O. No.	Terms	Project
Austin Healy Sprite	Due on receipt	

Description	Qty	Rate	Amount
Repair oil leaking from rear of engine. Drain oil and remove oil pan. Clean sludge from bottom of pan. Clean gasket surfaces and replace front and rear oil pan seals. Re-install oil pan and torque bolts to 6 ft/lbs. Replace oil filter. Fill with oil and run in shop. No leaks. Will road test when weather get better.	5.5	110.25	606.38
Rear sump seal, Neoprene	1	12.65	12.65
Front sump seal, cork	1	7.85	7.85
Oil filter element, felt	1	7.70	7.70
Seal ring oil canister	1	2.10	2.10
20w50 Valvoline Racing	4	8.15	32.60

<b>Total</b>	\$669.28
<b>Payments/Credits</b>	-\$669.28
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
1/21/2017	413

Bill To

**PAID**  
**01/27/2017**

P.O. No.	Terms	Project
Austin Healy Sprite	Due on receipt	

Description	Qty	Rate	Amount
Remove both front road spring and test. Both springs tested 280 lb/sq". Installed 3/16" coil over spacer. Road tested, raised LF.	4	110.25	441.00
3" coil over spring spacer	1	55.90	55.90
Replace exhaust pipe hanger with correct unit. Shorten clutch slave cylinder rod for more free play.	1	110.25	110.25
Exhaust Steady	1	12.70	12.70

<b>Total</b>	\$619.85
<b>Payments/Credits</b>	-\$619.85
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
2/22/2017	415

Bill To

**PAID**  
**02/27/2017**

P.O. No.	Terms	Project
Austin Healy Sprite	Due on receipt	

Description	Qty	Rate	Amount
Remove tachometer and speedometer fro repairs.	1	115.75	115.75
Shipping and handling		30.00	30.00
Rebuild Mech Tachometer RN2313/00		230.00	230.00
Rebuild Mech Speedometer SN6125/00		230.00	230.00
Shipping and handling		30.00	30.00
Re-install tachometer and speedometer	1.6	115.75	185.20

<b>Total</b>	\$820.95
<b>Payments/Credits</b>	-\$820.95
<b>Balance Due</b>	\$0.00

Albany Annex

Henk Boverhuis  
2490 Hilgard Avenue  
Berkeley, CA 94709

# Invoice

Date	Invoice #
1/16/2018	436

**PAID**  
**01/24/2018**

Bill To

P.O. No.	Terms	Project
A/H Sprite	Due on receipt	

Description	Qty	Rate	Amount
Prepare car for going home. Charge battery, check oil and water. Set tire pressures to 28psi. Torque wheel nuts. Start and warm up. Check for leaks. Road test to bridge and back. Check for leaks. Install top frame. Install top fabric. Adjust top frame. Prepare car for pick up.	2	133.80	267.60

<b>Total</b>	\$267.60
<b>Payments/Credits</b>	-\$267.60
<b>Balance Due</b>	\$0.00