

1983 Ferrari 308 GTS Quattrovalvole

Chassis No. ZFFMA13A6D004696546965

9-26-83 - Purchased New By Robert K. Post, 3754 Fort Donelson, Stockton, CA 95209

12-27-83 – Service by Walnut Creek Ferrari @ 1,528 miles
Performed 1,500-mile service
Changed oil and filter
Stud for top cover missing
Boot for top pin missing
Sticky Throttle
Fan Noisy
Tighten screw back of driver's seat
Adjusted windshield wipers
Tightened emblem on back deck lid
Fuse cover latch ordered

8-21-84 – Service by Walnut Creek Ferrari @ 3,523 miles
7,500-mile service
Replaced right air conditioner vent
Throttle sticking
Tighten screw at back of seat

9-11-85 – Serviced by Walnut Creek Ferrari @ 5,245 miles
Minor Service
New seat belt switch
Changed oil and filter
Changed brake fluid
Cleaned relay contacts

6-19-86 - Serviced by Walnut Creek Ferrari @ 5,830
Changed oil and filter
Bleed cooling system
Cleaned contacts on relays
Throttle sticking
Repair radio and Amp

8-20-86 – Serviced by Walnut Creek Ferrari @ 6,049
Installed radio
Repaired connection to door switch

8-12-87 – Service at Auto Care Stockton @ 7,800 miles
Smog inspection

9-12-87 – Serviced by Walnut Creek Ferrari @ 7,040
Changed oil and filter
Changed brake fluid
Changed coolant
New spark plugs
New alternator belt
New air filter

5-16-89 – Service by Mike Buckenham's Stuttgart West Inc., Stockton @ 7,470 miles

TOWED IN

Replaced belts – overheating
Change oil and filter
Changed coolant
Changed brake fluid

6-6-89 – Service by Walnut Creek Ferrari @ 7,575 miles

Charge air conditioning
Install right side mirror
Tighten right rear side marker and replace broken light

1-31-02 – Serviced by Mike Buckenham's Stuttgart West Inc., Stockton @ 11,606 miles

Changed oil and filter
Cleaned and lubricated radio antenna
Speedometer and clock checked
Lubricated windows

3-29-02 – Purchased by Frank Bishop, 26 Sylvian Way, Los Altos, CA 94022
12,002 miles

4-3-02 – Frank Bishop replaced
Brake light switch
Both engine hood struts

4-04-02 – Bishop Purchased
Pt No. 101663 switch
Gset
Touch up paint

4-15-02 – Del at Highway 1
New radiator cap

New Battery cover nut

4-29-02 – Palo Alto Speedometer Repaired clock

8-23-02 – Serviced by Prancing Horse, 1390 Rollins Road, Burlingame, CA

12,317 miles with new timing belts

30K mile service

Mount and balance new tires

Rebuild water pump

Check oil leak passenger side

Replace cooling hoses

Replace all cam seals and o-rings

Replace rear axel boot

7-12-06 – Purchased by Roy Riccetti, 856 Cathedral Dr., Sunnyvale, CA 94087

14,626 miles

7-06 – Milano Imports, Gilroy - Changed all fluids and complete inspection

11-15-06 – Pro Trim, San Jose – Spot dyed seats

12-15-06 – Milano Imports, Gilroy – Repair radiator leak and add new foam pad kit around radiator

9-18-07 – Replace fuel filler neck bib

9-27-07 – The Pit Stop, 130 Industrial Way, Brisbane, CA 94005 – 16,770 miles

Charge A/C

Change oil and filter

Replace A/C switch

Complete detail

10-22-07 – Italian Design and racing, Phoenix, AZ 85027

Replace hose clamps

5-1-08 - The Pit Stop, 130 Industrial Way, Brisbane, CA 94005 – 17,520 miles

Overhaul all brakes

Replace front wheel bearings and seals

Repair lower spoiler

Refinish wheel

Detail

Change oil and filter

8-7-08 – Pro Trim San Jose, CA 95118

Spot dye driver's seat

9-23-08 – America's Tire Store
Replace spare tire – 205/55ZR-16

9-8-08 – Certified Auto Care, 16540 Railroad Ave. Suite 170, Morgan Hill, CA
95037 – 17,988
Passed Smog Inspection

6-6-10 – The Pit Stop 130 Industrial Way, Brisbane, CA 94005 @ 11,100
Complete fluid change
Fix crack bottom of hood
Replace air intake boot
Recharge A/C
Repair bottom of passenger door
Paint wheels

7-14-10 – The Pit Stop 130 Industrial Way, Brisbane, CA 94005 @19,244
Replace A/C compressor

8-9-10 – The Pit Stop 130 Industrial Way, Brisbane, CA 94005 @ 19,511
Replace smog pump drive shaft

8-16-10 – The Pit Stop 130 Industrial Way, Brisbane, CA 94005 @ 19,650
Repair end of camshaft and replace seal

9-17-10 – Certified Auto Care, 16540 Railroad Ave. Suite 170, Morgan Hill, CA
@19,990 Pass smog inspection

8-17-11 – Coppa Bella Motors 684 B Ponderosa St., Seaside, CA 93955 @
20,203
Replace right fuse box and fuses

5-22-12 – Coppa Bella Motors 684 B Ponderosa St., Seaside, CA 93955 @
20,767
Major belt service
Replace left fuse box
Rewired radio antenna
Tightened A/C hose connections and charged system
Rebuilt both rear brake calipers

8-8-12 – Detailed by Pacific Auto Detail – Seaside

8-8-12 – Coppa Bella Motors @ 22,584 miles
Replaced Battery with smaller (stock) unit and added a positive terminal cover
Changed valve stem caps to metal – Changed back to black plastic at next show

2013 – No service or repairs

7-30-14 – Coppa Bella Motors @23,382 miles

Changed all fluids, charged A/C, crimped exhaust pipe shield and resealed dip stick tube.

8-5-14 – Detailed by Pacific Auto Detail - Seaside

2015 – No service or repairs – detailed for International Ferrari Meet by owner

8-2-16 – New tires at 24,520 miles

5-30-17 – Fluid change, charge A/C