

**Hurley Engine Service Co., Inc.**  
 200 24th Street S.  
 Birmingham, Al.. 35233  
 Phone - 205-323-3136 Fax - 205-252-9904  
**SPEED COSTS MONEY---HOW FAST DO YOU WANT TO GO?**

INVOICE

**43550**

**INVOICE FROM HISTORY**

Work Completed Date : 02/21/2013

Invoice Date : 02/21/2013

Print Date : 03/15/2019

2003 FERRARI - 575 MARANELLO

Lic # : 1B25C60

Odometer In : 12061

Unit # :

12118

Vin # : **ZFFBV55A530133710**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
THERMOSTAT				01-04-12 CHECK OVERHEATING.	4.00	460.00
183758	1.00	150.02	150.02	SERVICE.		
THERMOSTAT GASKET				CHECK OVERHEATING. REPLACE		
137873	1.00	7.59	7.59	THERMOSTAT & BLEED SYSTEM.		
O-RING				CHECK OVER FOR MAJOR SERVICE		
149279	1.00	7.95	7.95	& WHISTLING NOISE.		
COVER GASKET				TOWING	N/A	150.00
182931	2.00	95.63	191.26	TOWING		
CAM SEAL				FREIGHT-THERMOSTAT	N/A	19.92
163987	4.00	85.29	341.16			
CAM ORING				01-31-13 START MAJOR SERVICE	10.50	1,207.50
158349	4.00	7.40	29.60	START MAJOR SERVICE. ORDER		
COVER GASKET				OTHER NEEDED PARTS FOUND		
182406	1.00	23.23	23.23	DURING DISSASSEMBLY &		
GASKET				INSPECTION		
182127	3.00	24.45	73.35	FREIGHT-ACELERATOR SENSOR	N/A	19.83
CAM BOLT ORING						
114808	4.00	8.78	35.12	2/1/13 TO 2/8/13 FINISH MAJOR	10.50	1,207.50
TIMING BELT				SERVICE		
187744	2.00	170.00	340.00	FINISH MAJOR SERVICE		
CAM BELT TENSIONER				2/1/13 TO 2/8/13 INSTALL SENSOR	1.50	172.50
171057	2.00	180.00	360.00	INSTALL LEFT ACCELERATION		
AIR FILTER				SENSOR		
180935	2.00	90.25	180.50	02-11-13 REPLACE MISSING FASTENER	0.50	57.50
OIL FILTER 02 FERRARI				REPLACE MISC. MISSING		
206166	2.00	40.00	80.00	FASTENERS		
PUMP BELT				02-11-13 REPAIR BRAKE TUBE	2.00	230.00
201456	1.00	61.47	61.47	REPAIR LEFT BRAKE COOLING		
ALT & COMPRESSOR BELT				TUBE		
201444	1.00	59.95	59.95	02-11-13 REPLACE STEERING HOSE	1.50	172.50
ORING				REPLACE POWER STEERING LOW		
142599	4.00	3.02	12.08	PRESSURE HOSE		
GASKET				freight-struts	N/A	20.00
181064	2.00	103.71	207.42			
GASKET				2/15/13 HOOD STRUTS	0.50	57.50
225462	2.00	23.00	46.00	REPLACE HOOD STRUTS		
COMPLETE AIR FILTER				2/15/13 HEADLIGHTS	4.50	517.50
63897800	1.00	194.52	194.52	REPAIR HEADLIGHTS		



**Hurley Engine Service Co., Inc.**  
 200 24th Street S.  
 Birmingham, Al.. 35233  
 Phone - 205-323-3136 Fax - 205-252-9904  
**SPEED COSTS MONEY---HOW FAST DO YOU WANT TO GO?**

INVOICE  
**43550**

**INVOICE FROM HISTORY**

Work Completed Date : 02/21/2013

Invoice Date : 02/21/2013  
 Print Date : 03/15/2019

2003 FERRARI - 575 MARANELLO

Lic # : 1B25C60 Odometer In : 12061  
 Unit # : 12118  
 Vin # : **ZFFBV55A530133710**  
 Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
IRIDIUM SPARK PLUGS				FREIGHT-H/LAMP BALLAST	N/A	20.00
DCPR9EIX	12.00	12.89	154.68			
FRONT ACELERATOR SENSOR				WASH & VAC	N/A	N/C
232676	1.00	182.48	182.48	WASH & VAC		
OIL HESCOLUBE 0W40				TIRE MONITORING SYSTEM WON'T		
G4 0W40	12.00	12.95	155.40	CALIBRATE. WILL REPAIR WHEN		
SPRAYCLEAN				NEW TIRES ARE INSTALLED		
4800	1.00	6.95	6.95	Hazardous Materials		15.00
A T F FLUID-MOBIL 1						
MOBIL	1.00	11.99	11.99			
HOSE SILICONE 3" 3 PLY						
7701-300	4.00	5.25	21.00			
DECK LID STRUTS						
64577300	2.00	45.00	90.00			
RH HEADLAMP BALLAST CONTROL						
220442	1.00	1,138.22	1,138.22			
WINDSHIELD WASHER SOLVENT						
CONCENTRATE						
WSW-12	1.00	3.78	3.78			
Shop Supplies		60.00	60.00			

[ Technicians : Hamaker, Ed GEH ]

Org. Estimate \$0.00	Revisions \$0.00	Current Estimate \$ 0.00	Additional Cost	Revised Estimate	<b>Labor:</b>	<b>4,097.50</b>
					<b>Parts:</b>	<b>4,225.72</b>
					<b>Sublet:</b>	<b>229.75</b>
						<b>-----</b>
					<b>Sub:</b>	<b>8,552.97</b>
					<b>Tax:</b>	<b>422.57</b>
					<b>Total:</b>	<b>8,975.54</b>
					<b>Bal Due:</b>	<b>\$0.00</b>

[ Payments - Visa - \$6975.54, Applied Credits - \$2000.00 ]

*PLEASE READ CAREFULLY, AND SIGN BELOW.*

I hereby acknowledge that I have verified to my satisfaction the work and pricing on this invoice. I agree to resolve any disputes regarding this invoice or the work through the Arbitration Program of the Birmingham Better Business Bureau, and to pay any attorneys fees incurred by HESCO in the collection hereof.

No warranty on high performance or customer-furnished parts. All returns subject to 20% restocking charge. NO RETURNS AFTER 30 DAYS. Removal of HESCO heat tabs precludes any credit for any reason.

SIGNATURE..... Date..... Time.....

**Hurley Engine Service Co., Inc.**  
 200 24th Street S.  
 Birmingham, Al.. 35233  
 Phone - 205-323-3136 Fax - 205-252-9904  
**SPEED COSTS MONEY---HOW FAST DO YOU WANT TO GO?**

INVOICE

**48008**

**INVOICE FROM HISTORY**

Work Completed Date : 08/15/2014

Invoice Date : 08/15/2014

Print Date : 03/15/2019

2003 FERRARI - 575 MARANELLO

Lic # : 1B25C60

Odometer In :

Unit # :

12951

Vin # : **ZFFBV55A530133710**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
CONNECTOR ELECTRICAL				CHECK TSTAT. CHECK	0.75	86.25
BP-217	1.00	1.10	1.10	OVERHEATING. CHECK BATTERY.		
BATTERY NAPA				REPLACE BATTERY.		
7591	1.00	175.92	175.92	CHECK FOR COOLANT LEAK.	1.50	172.50
RADIATOR				CHECK FOR COOLANT LEAK.		
171772	1.00	2,905.00	2,905.00	PRESSURE TEST SYSTEM. R&I		
HOSE CLAMP 1 5/16"				UNDER BELLY COVER TO LOOK		
91028	4.00	1.50	6.00	FOR TRACE - NONE FOUND AT THIS		
Shop Supplies		60.00	60.00	TIME.		
				FUEL	N/A	98.50
				PREMIUM FUEL		
				FREIGHT	N/A	250.00
				FREIGHT - RADIATOR FROM UK		
				TRANSACTION FEE	N/A	65.00
				CURRENCY TRANSACTION FEE		
				REPLACE RADIATOR	7.00	805.00
				FOUND LEAK IN RADIATOR.		
				REPLACE RADIATOR.		
				CHECK TIRE MONITOR, SUSPENSION	1.50	172.50
				LIGHT & TAIL LIGHTS.		
				TIRE PRESSURES ARE GOOD -		
				MONITORS ARE NOT WORKING		
				PROPERLY.		
				CHECK SUSPENSION LIGHT- FOUND		
				NO FUSES BLOW. CHECK WIRING		
				TO FRT SHOCKS GOOD. COULD NOT		
				FIND THE PROBLEM AT THIS TIME.		
				TAIL LIGHTS ON LEFT REAR - LIGHT		
				SOCKETS WERE INSTALL		
				BACKWARDS. CORRECTED		
				SOCKETS.		
				E-BRAKE HANDLE	N/A	N/C
				CLEAN BLACK E-BRAKE HANDLE &		
				SECURE TO E-BRAKE ARM. **NO		
				CHARGE**		
				Hazardous Materials		25.00



**Hurley Engine Service Co., Inc.**  
200 24th Street S.  
Birmingham, Al.. 35233  
Phone - 205-323-3136 Fax - 205-252-9904  
SPEED COSTS MONEY---HOW FAST DO YOU WANT TO GO?

INVOICE

**48008**

**INVOICE FROM HISTORY**

Work Completed Date : 08/15/2014

Invoice Date : 08/15/2014

Print Date : 03/15/2019

2003 FERRARI - 575 MARANELLO

Lic # : 1B25C60

Odometer In :

Unit # :

12951

Vin # : **ZFFBV55A530133710**

Hat # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
---------------------------	-----	------	----------	-------------------	-------	----------

[ Technicians : TEER, DAVID DT; Ostenson, Haakon; LEMASTER, JEFF ]

Org. Estimate \$0.00	Revisions \$0.00	Current Estimate \$ 0.00	Additional Cost	Revised Estimate
----------------------	------------------	--------------------------	-----------------	------------------

<b>Labor:</b>	<b>1,261.25</b>
<b>Parts:</b>	<b>3,148.02</b>
<b>Sublet:</b>	<b>413.50</b>
	<b>-----</b>
<b>Sub:</b>	<b>4,822.77</b>
<b>Tax:</b>	<b>314.80</b>
<b>Total:</b>	<b>5,137.57</b>
<b>Bal Due:</b>	<b>\$0.00</b>

[ Payments - American Express - \$5137.57 ]

*PLEASE READ CAREFULLY, AND SIGN BELOW.*

I hereby acknowledge that I have verified to my satisfaction the work and pricing on this invoice. I agree to resolve any disputes regarding this invoice or the work through the Arbitration Program of the Birmingham Better Business Bureau, and to pay any attorneys fees incurred by HESCO in the collection hereof.

No warranty on high performance or customer-furnished parts. All returns subject to 20% restocking charge. NO RETURNS AFTER 30 DAYS. Removal of HESCO heat tabs precludes any credit for any reason.

SIGNATURE..... Date..... Time.....

MOLINA, JOE (ServiceWriter)