



TopHydraulics
Making the best better

INVOICE
04/20/2018
#IN020412

Delivery Address

Billing Address

Top Hydraulics, Inc.
3235 Pacific View Drive
Florence, Oregon 97439
United States

Order Number	Invoice Number	Invoice Date	Order date
000020732	#IN020412	04/20/2018	04/20/2018

Reference	Product	Tax Rate	Unit Price (Tax excl.)	Qty	Total (Tax excl.)
	New Bentley Azure Hydraulic Lines/Hoses		\$2,999.99	1	\$2,999.99

Tax Detail	Tax Rate	Base price	Total Tax
No taxes			

Total Products	\$2,999.99
Shipping Cost	\$55.00
Total (Tax excl.)	\$3,054.99
Total	\$3,054.99

Payment Method	Payment by Paypal Pro	\$3,054.99

AZURE

JUNE 14	DELIVER BENTLEY - STORAGE IN MEYER - DRIVE TO JOHN BLIZZARD (PRESCOTT) RETURN TO PRESCOTT VALLEY	1.9.
JUNE 15	BLIZZARD LOCATE HYDRAULIC LEAK (G.L. HOSE FAILURE) ORDER NEW HOSE	1.8
JUNE 20	BLIZZARD REPLACE G.L. HOSE & REPLACE LOCKING RAMS	<u>3.8.</u> 7.5

7.5 x 75	\$562 ⁵⁰
ROB	<u>87⁵⁰</u>
	\$650 ⁰⁰

BLIZZARD'S TOP SHOP

1050 Willow Creek Rd. Suite 9
 PRESCOTT, AZ 86301
 (928) 445-1220

CUSTO						DATE	7/26/18
NAME							
ADDRESS							
97 Bentley Azure							
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MDSE. RET'D.	PAID OUT	
QTY.	DESCRIPTION					PRICE	AMOUNT
1	top # 3458-luu/STE						2774.00
	12x12 top + misc repairs — labor						2500.00
							5274.00
	Shipping						20.00
	Pd in advance July 2018						5299.00
						TAX	252.89
						TOTAL	5551.89
RECEIVED BY							5000.00

C PRODUCT 610

All claims and returned goods must be accompanied by this bill.

5236

55189
 Thank You



BENTLEY SCOTTSDALE
 7171 E. Chauncey Lane
 Phoenix, AZ 85054
 480-538-4300



21011BEC527503

CUSTOMER NO 11464	ADVISEE DOUBLAS ARRIOLA	99230	TAG NO 7429	INVOICE DATE 04/09/20	INVOICE NO BECS27503
LABOR RATE	LICENSE NO	MILEAGE 34,971	COLOR	STOCK NO	
YEAR / MAKE / MODEL 97 / BENTLEY / AZURE			DELIVERY DATE	DELIVERY MILES	
VEHICLE I.D. NO. S C B Z K 1 4 C 1 V C X 6 1 0 7 4			SELLING DEALER NO	PRODUCTION DATE	
P.T.E. NO.	P.O. NO.	R.O. DATE 03/09/20			
COMMENTS					MO: 34978

JOB# 1 CHARGES

LABOR
J# 1 10BEZ **DRIVEABILITY** **TECH(S):9880** **1470.00**
 customer states all hoses for convertible top were replaced and top is now inop - check and advice
 CHECK ALL WIRING CONNECTIONS. CHECK ALL HOSE CONNECTIONS AT PUMP. INSTALL TEST BOX TO FIND UNABLE TO CLOSE TOP DUE TO FAULTY SWITCH FUNCTIONS AND TOP TOO TIGHT TO CLOSE ON ITS OWN.
 MANUALLY CLOSE TOP TO STRETCH OUT OVER NIGHT. TEST OPERATION OF TOP. HEADER LATCH FAILS TO OPERATE. DISASSEMBLE HEADER LATCH TRIM AND INSPECT HOSES TO FIND 4 HOSE INSTALL IN INCORRECT LOCATION. REMOVED AND REFIT HOSES TO CORRECT LOCATION. REASSEMBLE FRONT AND REAR OF VEHICLE. TEST OPERATION. OPERATES NOW WITH SWITCH. 7.0

SUBLET-----PO#-----VEND INV#-INV.DATE-DESCRIPTION-----
 16461 47016 04/07/20 Replace cable on right rear 250.00
 TOTAL - SUBLET 250.00

JOB# 1 TOTALS-----
 LABOR 1470.00
 SUBLET 250.00

JOB# 1 JOURNAL PREFIX BECS JOB# 1 TOTAL 1720.00

JOB# 2 CHARGES

LABOR
J# 2 00BEZONLINEPAY **FREE ONLINE BILL PAY** **TECH(S):999** **0.00**

JOB# 2 TOTALS-----

JOB# 2 JOURNAL PREFIX BECS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR
J# 3 10BEZ08 **WONT START** **TECH(S):9880** **205.00**
 CUSTOMER STATES ENGINE WONT START - USED INCORRECT BATTERY TO GET CAR TO DEALER
 REPLACED BATTERY, 1.0

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----LIST PRICE-UNIT PRICE-
 1 MT34 MEGATRON BATTERY 144.72 144.72
 TOTAL - PARTS 144.72

JOB# 3 TOTALS-----
 LABOR 205.00
 PARTS 144.72

JOB# 3 JOURNAL PREFIX BECS JOB# 3 TOTAL 349.72

JOB# 4 CHARGES

LABOR-----



DISCLAIMER OF WARRANTIES
 Any warranties on the products sold hereby are those of the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

5/4/21 Full replacement

The Republic and Republic Company EPART014E CC743005 Q (10/19)



BENTLEY

BENTLEY SCOTTSDALE

7171 E. Chauncey Lane
Phoenix, AZ 85054
480-538-4300



BENTLEY



21011BECS27503

11464	DUBLAS ARIOLA	99230	TAG NO. 7429	INVOICE DATE 04/09/20	INVENTORY # BECS27503
LABOR RATE	LICENSE NO.	MILEAGE 34,971	COLOR	STOCK NO.	
97/BENTLEY/AZURE			DELIVERY DATE	DELIVERY MILES	
VEHICLE I.D. NO. SCBZK14C1VCX61074			SELLING DEALER NO.	PRODUCTION DATE	
F.T.E. NO.	P.O. NO.	R.O. DATE 03/09/20			
COMMENTS					MO: 34978

OBEZ01 DRIVEABILITY CONCERN TECH(S):9880 0.00
 customer states found drops of a fluid on garage floor.
 check and advice
 FOUND PAS RETURN HOSE LEAKING, TIGHTEN, TOP FLUID AND CLEAN.
 LET SITE OVERNIGHT.
 PAS HOSE NOW NOT LEAKING. LEAK AT REAR OF VEHICLE, LEFT SIDE
 NOW AND BRAKE PUMP SEEPING.

QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
1	GMF-1023	O RING BRAKE PUMP	15.23	15.23	15.23
TOTAL - PARTS					15.23
4 TOTALS-----					15.23
PARTS					15.23

JOB# 4 JOURNAL PREFIX BECS JOB# 4 TOTAL 15.23
 5 CHARGES-----

JR-----
 S+40BEZ BRAKES TECH(S):9880 1383.75
 customer states front brake pump seeping
 REMOVED FRONT PUMP AND REPLACED HOUSING O-RINGS. BLEED BOTH
 BRAKING SYSTEMS. 6.75

QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
1	GMF-1023	O RING BRAKE PUMP	15.23	15.23	15.23
IN STOCK					
2	GMF-1022	O RING BRAKE PUMP	24.00	24.00	48.00
SOP 3-5					
1	UE-75094	HOSE AIR PUMP CHE	134.28	134.28	134.28
SOP CREWE					
1	UE-74154	HOSE AIR INTAKE B	129.12	129.12	129.12
SOP 3-5					
2	RH-15215	OIL HSMO PLUS	19.63	19.63	39.26
IN STOCK					
1	RH-15233	LVS TUBE ASSEMBLY	24.27	24.27	24.27
IN STOCK					
2	UE-75095	HOSE T PIECE CHEC	77.37	77.37	154.74
SOP 3-5					
TOTAL - PARTS					544.90

JOB# 5 TOTALS-----
 LABOR 1383.75
 PARTS 544.90

JOB# 5 JOURNAL PREFIX BECS JOB# 5 TOTAL 1928.65
 JOB# 6 CHARGES-----

LABOR-----
 S+10BEZZ DRIVEABILITY CONCERN TECH(S):9880 615.00
 CUSTOMER STATES STRUT HOSE TO REMOTE VALVE LEAKING
 REMOVED HOSE FOR REBUILD
 FIT NEW HOSE AND BLEED SYSTEM. 3.0



DISCLAIMER OF WARRANTIES
 Any warranties on the products sold hereby are those of the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

The Reynolds and Reynolds Company ETBANK 10/18

BENTLEY

WINDALE
171 E. Chauncey Lane
Phoenix, AZ 85054
480-538-4300



CUSTOMER NO 21011BECS27503

11464

LABOR RATE	99230	TAX NO	7429	INVOICE DATE	04/09/20	STOCK NO	BECS27503
LICENSE NO	DUBLAS ARRIOLA		MILEAGE	34,971	DELIVERY DATE		
977/BENTLEY/AZURE							
VEHICLE NO	S C B Z K 1 4 C 1 V C X 6 1 0 7 4		DELIVERY DATE		SELLING DEALER NO		
FT E NO		P O NO			R O	03/09/20	PRODUCTION DATE
COMMENTS							

MO: 34978

JOB# 6 TOTALS

JOB# 7 CHARGES
LABOR
J# 7+40BEZZ

LABOR

LABOR	JOB# 6	JOURNAL PREFIX	BECS	JOB# 6	TOTAL	615.00
						615.00

TECH(S):9880

BRAKE CONCERN
CUSTOMER STATES BRAKES SPHERES ARE LOW PRESSURE
REMOVED BRAKE SPHERES, REPLACE AND BLEED. 3.6

PARTS

QTY	FP-NUMBER	DESCRIPTION	LIST	PRICE-UNIT	PRICE
6	RH-15215	OIL HSMO PLUS	19.63	19.63	117.78
2	CD60000HFR	SPHERE	140.00	140.00	280.00
2	GF122SR	O-RING	14.73	7.00	14.00
1	16430	hyd. hose	111.85	111.85	111.85
TOTAL - PARTS					523.63

JOB# 7 TOTALS

JOB# 8 CHARGES
LABOR
J# 8+40BEZ04

LABOR

LABOR	JOB# 7	JOURNAL PREFIX	BECS	JOB# 7	TOTAL	738.00
						523.63

TECH(S):9880

BRAKE SERVICE
CUSTOMER REQUESTS BRAKE BLEED
SEE LINE #7, INCLUDED IN SPHERES

JOB# 8 TOTALS

MISC
JOB # A
JOB # A

MISC

MISC	JOB# 8	JOURNAL PREFIX	BECS	JOB# 8	TOTAL	0.00
						0.00

SHM SERVICE HISTORY ADMIN
SS ENVIRONMENTAL FEE / SHOP SUPPLY

JOB# 8 TOTALS

TOTAL - MISC

1.49
92.00
93.49

Thank you for this opportunity to serve you. If our service was satisfactory tell your friends: If not please tell us immediately.

DISCLAIMER OF WARRANTIES
Any warranties on the products sold hereby are those of the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

BENTLEY

SCOTTSDALE
7171 E. Chauncey Lane
Phoenix, AZ 85054
480-538-4300



BENTLEY



21011BEC527503

11464

LABOR RATE	99230	TRAILER NO.	7429	INVOICE NO.	04709/20	STOCK NO.	BEC527503
LICENSE NO.	97/BENTLEY/AZURE	MILEAGE	34,971	COLOR		DELIVERY MILES	
SALES TAX	S C B Z K 1 4 C 1 V C X 6 1 0 7 4	DELIVERY DATE		SELLING DEALER NO.		PRODUCTION DATE	
F.T.E. NO.		IP/O NO.		R TO	03/09/20		
COMMENTS							

 [] CASH [] CHECK CK NO. [] *
 [] VISA [] MASTERCARD [] DISCOVER *
 [] AMERICAN XPRESS [] OTHER [] CHARGE *
 * CASHIER. ***** DATE. ***** *
 * THANK YOU FOR YOUR BUSINESS!! *

TOTAL LABOR..... 4411.75
 TOTAL PARTS..... 1228.48
 TOTAL SUBLET..... 250.00
 TOTAL G.O.G..... 0.00
 TOTAL MISC CHG. 93.49
 TOTAL MISC DISC 0.00
 TOTAL TAX..... 113.69
TOTAL INVOICE \$ 6097.41

MO: 34978

Thank you for this opportunity to serve you. If our service was satisfactory tell your friends: If not please tell us immediately.

DISCLAIMER OF WARRANTIES
 Any warranties on the products sold

CUSTOMER SIGNATURE

0006313 Office AU # 11-24 1210(g)

Remitter: Purchaser: Operator I.D.: Funding Source:

PAY TO THE ORDER OF ***BENTLEY SCOTTSDALE***

CASHIER'S CHECK

SERIAL # 0631306736
ACCOUNT # 4861-511400

April 10, 2020

**Six Thousand Ninety-Seven and 41/100 - US Dollars **

\$6,097.41

Payee Address: Memo:

WELLS FARGO BANK, N.A.
14595 N SCOTTSDALE RD
SCOTTSDALE, AZ 85254
FOR INQUIRIES CALL (480) 394-3122

VOID IF OVER US \$ 6,097.41

NON-NEGOTIABLE

Purchaser Copy

FB004 INCS 60406728

PAGE 4 OF 4

CUSTOMER COPY

[END OF INVOICE] 12:13pm

Cabriolet Hydraulics

High Performance Hydraulic Top Solutions

2111 72nd Terrace E P/T/F: (941) 756-1300
Sarasota, FL 34243 Info@CabHyd.com
CabHyd.com

INVOICE

Invoice Date 3/19/2021
Invoice # 210961
Work Order # 5869

1208/01-150
3/19/2021

Bill To

Ship To

Terms Prepaid
Customer Phone
Customer P.O. No.
Ship Date 3/19/2021
Ship Via UPS

Qty	Item Code	Description	Price Each	Amount
1	B/RR-P	Pump rebuild, 1996-2003 B/RR **With electric motor replacement**	1,100.00	1,100.00
1	SH	Shipping & Handling - \$10000 Insurance	113.00	113.00

Thank you!

Subtotal \$1,213.00
Sales Tax (7.0%) \$0.00
Total \$1,213.00

Parts Warranty:

Our cylinders carry a 3-year warranty. If a cylinder fails within the 3-year warranty period we will repair or replace the cylinder at no charge.
Damages not covered by the warranty:
Hydraulic cylinder and/or line (where applicable) damage caused by mishandling, improper installation, malfunctioning convertible top system components and corrosion.

Thank you for your business!

