

1-30-19 Bill

Chassis no: 404/X/3073
Engine no: BS1/MK11/274
Body 5875
Orig paint Paramatti Red Corsa 106
Orig upholstery s_Antonio Beige 0104/1

GBP 16,762
263hr labor -10,520

Arnolt Bristol 1954
Reg. no.419 KEC
Mileage: 54182

Date in: 22/01/2018
Date out: Feb 2019?

WORKSHOP REPORT	Labour	Materials	Outwork	Total cost of task
1.	<u>Exhaust system</u>			
	Collect silencer box and pipe and make up system from collector back to tail inc mounting brackets and rubbers.			
2.	<u>Heater</u>			

6.	<u>Fuel tank</u>				
	<p>Fuel tank had in a previous life been treated with an internal sealing solution (tank slosh?) this after a few weeks of having petrol with 5% ethanol in started to react and swelled to about twice its volume. Not being able to remove this sealer from the tank a new tank was made from aluminium and fitted.</p>				
7.	<u>Toeing eye</u>				
	<p>Make and fit towing eye to the centre of the front cross member. (hopefully never to be needed)</p>				

8.	<u>Over drive wiring</u>				
	Wire up overdrive & switch using a latching relay controlled by enabling switch and dash switch.				
9.	<u>Overdrive gear box tunnel</u>				
	Make up gear box tunnel to accommodate overdrive and fit.				
10.	<u>Head lights</u>				
	Wire in head lights using 2 new bulb sockets to suit halogen bulbs.				
11.	<u>Spring gators & clamps (missing)</u>				

14.	<u>Engine & gear box</u>				
	Fit up engine, gear-box, prop shaft and connect up.				
15.	<u>Accessory sockets</u>				
	Fit and wire in a cigar lighter and USB socket to under the passenger dash.				
16.	<u>Extra fuse box</u>				

Fit extra fuse box to side of passenger foot well, this fuse box is ignition controlled through a relay sited on the left hand side of the heater unit above the yellow overdrive relay. Fuses 1-4 are spare. 5 is cigar lighter, 6 USB, 7 Heater unit, 8 Overdrive, 9 wipers, 10 cooling fan feed to relay sited front LH side of engine bay. Original fuse box LH fuse operates horn and RH fuse is ignition controlled and does indicators,

	<u>Parts used</u>				
	Regulator box lid (Lucas RF95)		45.00		
	Horn relay		38.00		
	Horn		40.00		
	Floor board screws X 52		18.72		
	TIG welding & rods		40.00		
	BA screws & nuts		12.00		
	Steering column draught excluder rubber		38.40		
	Pedal rubbers		33.60		
	P&P		10.95		
	Steering wheel		200.00		
	Steering column cover spring		36.00		
	Heater take off banjo union		20.71		
	Heater take off banjo bolt		12.60		
	Axle pinion bearing outer		35.85		

	Pinion bearing inner		58.12		
	Crown wheel bearings x2		38.40		
	Pinion seal		7.22		
	Lucas battery cut off switch		21.00		
	Clock repair (transistor switching)		106.00		
	Oil pressure feed pipe & unions		14.00		
	<u>Parts used cont</u>				
	Ignition coil and clamp		42.00		
	Hose clips for oil cooler pipes		9.60		
	Exhaust mountings		25.00		
	¼ mounting bolts & nuts		7.00		
	Aluminium for boot floor & tool store		29.00		
	Aluminium for petrol tank		36.00		

	Manufac- ture of tank filler neck		110.00		
	Tank drain bung		4.00		
	Hose clips for heater		16.00		
	Petrol tank bault head union		4.48		
	Bonnet buffers		9.48		
	Engine machining				
	Bore out old liners, bore block for new lin- ers and bore and hone to size.				
	Machine block to accept main bear- ing locating tabs.				
	Reface top deck of block.				
	Crack test crank and polish.				
	Modify bearings to suit rods and block & test fit crank.				

	Make and fit small end bushes and true rods.				
	Modify fly-wheel dowels to suit diaphragm clutch cover.				
	Balance crank assembly.				
	Line bore block to suit cam bearings and fit bearings.				
	Machine scallops at top of bores to line up with valve openings.				
	Clean block.				
	Ream valve guides to suit new valves.				
	Reface cylinder head.				
	Reface valve seats.			3667.20	
	Overdrive switch		12.00		

	Overdrive gearbox enabling switch		10.39		
	Overdrive relay and socket		32.00		
	Cotton covered wire for extras		24.00		
	Electric fan override switch		4.80		
	Extra fuse box operating relay & socket		6.80		
	Electric fan thermostatic switch		24.36		
	Piano hinge for tool box lid		12.00		
	Engine cooling hose clips x6		10.92		
	Oil cooler mounting rubbers		16.00		
	Calibration of Speedo and RPM		132.00		
	<u>Parts used cont</u>				
	Petrol		45.00		
	Brake fluid		4.93		
	Anti freeze		5.40		

New oil pump internals	115.50		
Ignition points	16.00		
Distributor cap	55.00		
Distributor rotor arm	21.00		
Gearbox oil x2 valvoline 20/50	26.00		
Overdrive ATF	3.00		
Spark plugs	21.88		
Oil filter x 2	14.60		
Millers running in oil	45.00		
Top axle rubber swivel gator	52.14		
Spark plug caps	22.00		
Spark plug HT lead	10.90		
Leather spring gators	77.00		
Cylinder head push rod tube "O" ring conversion	320.00		
Speedo and RPM postage	17.70		
Battery	105.00		
Exhaust silencer & pipe	58.00		

	Bottom hose adaptor for heater take off		36.00		
	Radiator mounting rubbers		7.20		
	Battery terminals		9.60		
	Battery cut off switch terminals		2.40		
	Speedo internals		45.00		
	Dinitrol rust preventative		11.00		
	Rubber boot mat		24.00		
	Labour	10520.00			
	263hrs @ £40.00/hr				
		<i>LABOUR</i>	<i>PARTS</i>	<i>OUTWORK</i>	
		10520.00	2575.65	3667.20	16762.85

Cheques payable to Charles Russell
or Bank Transfer HSBC Sort Code: 40-21-19 Account No: 91346334 Branch
BIC HBUKGB4131R IBAN GB78HBUK40211991346334 SWIFT BIC
HBUKGB4B

Charles Russell
Vintage Sports Car Engineers

Date: 30/01/2019

44 Whitbourne Moor, Corsley, Warminster, Wiltshire BA12 7QL

Tel: 01373 832220 Mob: 07714 330683 Email: vsc_engineers@lineone.net

Chassis no: 404/X/3073
 Engine no: BS1/MK11/274
 Body 5875
 Orig paint Paramatti Red Corsa 106
 Orig upholstery s_Antonio Beige 0104/1

Arnolt Bristol 1954
 Reg. no.419 KEC
 Mileage: 54182

WORKSHOP REPORT	Labour	Materials	Outwork	Total cost of task
<u>Summary of restoration costs</u>				
<u>Invoice dated 22/01/2018</u>	10280.00	1970.35		12250.35 ✓
Work carried out detailed in workshop report				
<u>Invoice dated 10/08/2018</u>	8640.00	4342.67		12982.67 ✓

	Work carried out detailed in workshop report				
	<u>Invoice dated 12/10/2018</u>	6460.00	4984.40		11444.40 ✓
	Work carried out detailed in workshop report				
	<u>Invoice dated 04/12/2018</u>	12880.00	5573.54		18453.54 ✓
	Work carried out detailed in workshop report				
	<u>Invoice dated 30/01/2018</u>	10520.00	6242.85		16762.85 ✓
	Work carried out detailed in workshop report				
	Labour 1219.5hrs @ £40.00/hr	48780.00			
		48780.00	23113.81		71893.81

Charles Russell
Vintage Sports Car Engineers

Date: 13/05/2019

44 Whitbourne Moor, Corsley, Warminster, Wiltshire BA12 7QL
Tel: 01373 832220 Mob: 07714 330683 Email: vsc_engineers@lineone.net

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

Roger Kraus Racing Ent, Inc.

2896 Grove Way
 Castro Valley, CA 94546
 (510) 582-5031
 BAR # 102319

X

Vehicles left after repair is completed may be subject to a storage fee.

Repair Order # 99147



VIN:
 Engine:
 Trans:
 ODO In: 0
 Color:
 License #

Inv Date: 7/16/2020 @ 10:08am

Service Writer: Brandon Kraus

Status: BILL OUT

Driver:

Mfg. Date:

Unit #

PO #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Customer states that: Requests for Service & Vehicle Problems -						
Labor Service - Thank You For Choosing Roger Kraus Racing BK						0.00
New BLOT55016	Blockley TUBE 550-16 TR11C			5.00	90.00	450.00
Labor Service - UPS GROUND BK			1.00		36.90	36.90
Labor Service - Credit Card On File BK						0.00

ROGER KRAUS TIRES
 2896 GROVE WAY
 CASTRO VALLEY, CA 94546
 510/582-5031

SALE

MID: 070004992285
 TID: 002 REF#: 00000003
 Batch #: 198001 RRN: 019298372
 07/16/20 10:45:29
 AVS: Z CVC: M
 Invoice #: 3
 APPR CODE: 052251
 VISA Manual CP
 *****8111

AMOUNT \$527.40

APPROVED

Thank You
 Please Come Again

CUSTOMER COPY

Warranty
 All returned race tires are subject to a 20% restocking charge. Returned Goods Authorization's are required for all returns. All returns must be made in 60 days.

X

Customer acknowledges receipt of merchandise and services.

Sub Total 486.90
 Sales Tax (SCL) 40.50

BURK ENGINE MOTORS
BURK ENGINE MOTORS
BURK ENGINE, LT 94010
650-343-8858

07/07/2021 14:07:33
Merchant ID: *****0320
Device ID: 1228
Terminal ID: PPT1

Credit Sale:

Transaction #: 2
Card Type: Visa
Account: *****4596
Expiry: 08/18

STAR: 002
Auth. Code: 072871
Response: 6078/TKT
ACT Code: E
TRANS ID: 301106900494542

Issuer:
AID: #0000000031010
TR: 0080108000
LAD: 06021203602002
TSI: 8900
ARC: 00
Foreign Visa

QTY SALE

BURLINGAME MOTORS, INC.

Since 1979
Independent Mercedes Benz Dept.
1295 Rollins Road
BURLINGAME, CA 94010-2416
(650) 343-8858 Fax (650) 343-9261
Since 1979

Date	7-7-21	Written By	ADU	021579
Time Received	12 P.M.	Phone when ready	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Authorized By		Called		
Promised				

EPA Name Address City Year-Make-Model License No. Odometer

Estimate Amount \$ Revised Estimate \$ Revised Estimate \$

Engine Size Date Time Description

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

OPER NO. REPAIR ORDER — LABOR INSTRUCTION LABOR CHG.

TIRE PRESSURE CHECK SERVICE COMPLETED IN _____ REASON: _____ (96)

DECLINED BY: INITIAL: _____

TOTAL PARTS	
TOTAL OIL, GREASE	
TOTAL SUBLET REPAIRS	

QTY.	SALE	RECOMMENDED SERVICE:	TOTAL LABOR
		1. 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.	180.00
		2. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.	
		3. 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.	
		4. 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.	
8	QTS. OIL VPA 2015s 1250 1000	REPAIRS	1200
	LBS. GREASE	OIL & GREASE	100.00
		GAS	
		SALES TAX	95
		HAZARDOUS WASTE DISPOSAL FEE	
		TOTAL AMOUNT	2015

Oil Services
Dieck Changing System - Alternator
Check For Leaks Rear Engine Cover

Parts Visa

QTY * SALE

MARK INCANDE MOTORS
 MARK INCANDE MOTORS
 MARK INCANDE CA 94010
 (510) 343-8858

07/13/2021
 Merchant ID: *****0320
 Device ID: 1228
 Terminal ID: PPK1

13:51:18
 Card Type: Visa
 Account: *****4391
 Filter: Date

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.
 1296 Rollins Road
 BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

Date **7.13.21** Written By **Zene**

Time Received **9:00** Cust. Order No.

Authorized By P.M. Phone when ready **No**

Authorized By P.M. Yes No

Call Phone

EPA
 Name
 Address
 City

Year/Make-Model **2013 Buick** License No. **228 Z** Odometer **6603**

Estimate Amount \$ **54.00** Engine Size **2.8** VIN Number **7G603**

Revised Estimate \$ **54.00** Date **7/13/21** Time **9:00** Description **REPAIR GASKETS**

Revised Estimate \$ **54.00** Date **7/13/21** Time **9:00** Description **REPAIR GASKETS**

ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE SAVE DISCARD

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

REPAIR ORDER — LABOR INSTRUCTION

OPER. NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	<i>REPLACE PLATE MOUNTING HOLES BANCHETS</i>	
	<i>REPLACE GASKETS @ BENCH COVER</i>	
	<i>PAID VISA</i>	
	<i>7.13.21</i>	

3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
 NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).
 WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.

I hereby authorize the repair work above to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By **[Signature]**

TOTAL LABOR	PARTS	SUBLET REPAIRS	OIL & GREASE	GAS	SALES TAX	HAZARDOUS WASTE DISPOSAL FEE	TOTAL AMOUNT
54.00		10.00					64.00
							97
							550.97

TIRE PRESSURE CHECK SERVICE COMPLETED BY _____
 TIRE PRESSURE: LF _____ RR _____
 DECLINED BY Initial _____ REASON _____ (SEE) _____

TOTAL PARTS **10.00**
 TOTAL SUBLET REPAIRS **97**
 TOTAL OIL, GREASE **550.97**

HURL INDIANE MOTORS
 HURL INDIANE MOTORS
 HURL INDIANE, CA 94010
 (550) 343-8858

09/02/2021 10:20:31
 Merchant ID: *****0320
 Device ID: 1228
 Terminal ID: PFX1

Credit Sales

R-REBUILT
 ON SALE

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.
 1295 Rollins Road
 BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

Since 1979

Date	8/21/2021	Written By	BAF
Time Received	9:15	Cust. Order No.	
Promised		Phone when ready	No
		Yes	Yes

021624

EPA
 Name
 Address
 City

Year/Make-Model: Passat License No. 278Z VIN Number 96006 Odometer 278Z

Estimate Amount: \$ _____ Engine Size _____

Revised Estimate \$ _____ Date _____ Time _____ Description _____

Revised Estimate \$ _____ Date _____ Time _____ Description _____

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

REPAIR ORDER — LABOR INSTRUCTION

REPLACE VALVE COVER GASKETS
 FABRICATE OIL DROPSKETS, MATEQUIN
 CHECK EL. WIRING TO FAN - WIRE TRAY TO LOGGE
 CHECK EL. WIRING TO OIL DRIVE - NEED DIAGNOSIS
 ORDER USES PART OR FOR ONE SHOT

TOTAL PARTS

5350

WARRANTY ON PARTS & LABOR

- 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
- 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
- 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
- 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
- NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).
- WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.

RECOMMENDED SERVICE:

- 1.
- 2.
- 3.

TIRE PRESSURE CHECK SERVICE COMPLETED BY	LF	RF	LR	RR	(adj)
DECLINED \$					
REASON:					
SUBLET REPAIRS					
TOTAL SUBLET REPAIRS					

QTS. OIL		SALE	
QTS. OIL			
LBS. GREASE			
TOTAL OIL, GREASE			

TOTAL LABOR	540.00
PARTS	5350
SUBLET REPAIRS	
OIL & GREASE	
GAS	
SALES TAX	514
HAZARDOUS WASTE DISPOSAL FEE	
TOTAL AMOUNT	598.64

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.
 1295 Rollins Road
 BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

Date: 2 9 2002 Written By: Paul 021782
 Time Received: 1 P.M. Cust. Order No.
 Promised: 1 P.M. Phone when ready Yes No
 Call Phone

EPA Name Address City
 Year-Make-Model License No. Odometer
 Estimate Amount \$ Engine Size VIN Number
 Revised Estimate \$ Date Time Description Authorized By INITIAL
 Revised Estimate \$ Date Time Description Authorized By INITIAL

Year-Make-Model: 98 Pontiac License No.: 2782 Odometer:
 Estimate Amount \$: 1000 Engine Size: VIN Number:
 Revised Estimate \$: Date: Time: Description:
 Revised Estimate \$: Date: Time: Description:

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.
 OPER NO. REPAIR ORDER — LABOR INSTRUCTION LABOR CHG.

*Lower car - check front spring remove corners
 modify safety straps on front spring
 lower rear torsion bar (low at max load)*

*check oil level oil level low
 check battery charge and charge rate
 replace air filter 10.9 volt under 50 mph load
 rear struts clean, lubricate and adjust
 passenger side and test
 Paid VCA*

QTY	* PART NO. OR DESCRIPTION	SALE
TOTAL PARTS		
TOTAL OIL, GREASE		
TOTAL SUBLET REPAIRS		
TOTAL AMOUNT		

WARRANTY ON PARTS & LABOR
 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.
 NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).
 WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.

TIRE PRESSURE CHECK SERVICE COMPLETED @
 TIRE PRESSURE: LF _____ RR _____ (PSI)
 DECLINED @ Initial REASON: _____

SUBLET REPAIRS

RECOMMENDED SERVICE:
 1.
 2.
 3.

TOTAL LABOR: 7200
 PARTS:
 SUBLET REPAIRS:
 OIL & GREASE:
 GAS:
 SALES TAX:
 HAZARDOUS WASTE DISPOSAL FEE:
 TOTAL AMOUNT: 7200

RITEWAY ELECTRIC, INC

261 6TH STREET
SAN FRANCISCO, CA 94103

INVOICE

Invoice Number: 99607
Invoice Date: Jul 18, 2022
Page: 1

Voice: 415-882-4444

8325140007028210
Rite Way Electric
San Francisco, CA 94103
4158824444

07/18/2022 10:48

Sale

Trans #: 3 Batch #: 329

VISA CHIP Contactless
*****2925 **/**

PAGE AMT: 0412.00

Ship to:

Customer PO	Payment Terms	
	C.O.D.	
Shipping Method	Ship Date	Due Date
		7/18/22

Quantity	Item	Description	Unit Price	Amount
1.00	25022M	12V LUCAS STARTER REPAIR WITH NEW FIELDS	412.90	412.90
Subtotal				412.90
Sales Tax				
Freight				
Total Invoice Amount				412.90
Payment/Credit Applied				
TOTAL				412.90

Check/Credit Memo No:

BURLINGAME MOTORS
 BURLINGAME MOTORS
 BURLINGAME, CA 94010
 650-343-8858

09/01/2022 11:19:25
 Merchant ID: *****0320
 Device ID: 1228
 Terminal ID: PPK1.

Credit Sale:

Transaction #: 3
 Card Type: Visa
 Account: *****8327
 Entry: Chip

Amount: \$421.92

SALE

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.
 1295 Rollins Road
 BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

Since 1979

Date	8/27/25	Written By	
Time Received		Cust. Order No.	
Promised		Phone when ready	
		Yes <input type="checkbox"/>	No <input type="checkbox"/>

Year/Make/Model
 Estimate Amount \$
 Revised Estimate \$
 Revised Estimate \$

Engine Size
 Date
 Date

Time
 Description

License No.
 VIN Number

Year/Make/Model
 Estimate Amount \$
 Revised Estimate \$
 Revised Estimate \$

Engine Size
 Date
 Date

Time
 Description

License No.
 VIN Number

Year/Make/Model
 Estimate Amount \$
 Revised Estimate \$
 Revised Estimate \$

Engine Size
 Date
 Date

Time
 Description

License No.
 VIN Number

Year/Make/Model
 Estimate Amount \$
 Revised Estimate \$
 Revised Estimate \$

Engine Size
 Date
 Date

Time
 Description

License No.
 VIN Number

Year/Make/Model	Estimate Amount \$	Revised Estimate \$	Revised Estimate \$	Engine Size	Date	Date	Time	Description	License No.	VIN Number	Odometer	ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE	SAVE <input checked="" type="checkbox"/>	DISCARD <input checked="" type="checkbox"/>
Rollins	400													

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

REPAIR ORDER — LABOR INSTRUCTION

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	Replace WIPER BLADES WITH GREAT FITTING	
	ADJUST CARBURETORS	

WARRANTY ON PARTS & LABOR

- 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.
- 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.
- 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.
- 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST.

RECOMMENDED SERVICE:

QTY.	QTS. OIL	QTS. OIL	LBS. GREASE	TOTAL OIL, GREASE	TOTAL LABOR	PARTS	SUBLET REPAIRS	OIL & GREASE	GAS	SALES TAX	HAZARDOUS WASTE DISPOSAL FEE	TOTAL AMOUNT
					15.00							421.92

SUBLET REPAIRS

TIRE PRESSURE CHECK SERVICE COMPLETED @
 TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)
 DECLINED R. Initial REASON:

QTY * SALE

05/26/2023 14:02:19
 Merchant ID: *****0320
 Device ID: 1228
 Terminal ID: PPXI.

3 Visa
 Transaction #: *****8327
 Card Type: Chip
 Account:

BURLINGAME MOTORS
 BURLINGAME MOTORS
 BURLINGAME, CA 94010
 650-343-8858

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.
 1295 Rollins Road
 BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

Date	5/26/2023	Written By	Beve
Time Received		Cust. Order No.	
		Phone when ready	No
		Yes	No

Year/Make/Model: **2012**

Estimate Amount: \$

Revised Estimate: \$

Revised Estimate: \$

Year/Make/Model	Engine Size	VIN Number	Year	License No.	Odometer	ALL PARTS REMOVED WILL BE DISCARDED UNLESS INSTRUCTED OTHERWISE.	SAVE	DISCARD
<i>Social</i>	<i>2.3L</i>	<i>2K3232</i>	<i>2012</i>	<i>96009</i>	<i>06009</i>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

REPAIR ORDER - LABOR INSTRUCTION

OPER. NO.	DESCRIPTION	LABOR CHG.
DISERVICE	LUBE CHANG	20000
CLEAR RECORD		82792
WARRANTY ON PARTS & LABOR		
<input checked="" type="checkbox"/> 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.		
RECOMMENDED SERVICE:		
1. <i>VALVE COVERS OR GASKET LEAK</i> 2. 3.		
TOTAL LABOR PARTS		20000
SUBLET REPAIRS OIL & GREASE		82792
GAS		
SALES TAX		292
HAZARDOUS WASTE DISPOSAL FEE		600
TOTAL AMOUNT		76991

TIRE PRESSURE CHECK SERVICE COMPLETED @

TIRE PRESSURE: LF _____ RF _____ LR _____ RR _____ (psi)

DECLINED BY Initial REASON:

SUBLET REPAIRS

QTY	REPAIRS	AMOUNT
TOTAL SUBLET REPAIRS		

022064

QTY SALE

BURLINGAME MOTORS
 BURLINGAME MOTORS
 BURLINGAME, CA 94010
 650-343-8858

10:24:22
 Merchant ID: *****0320
 Device ID: 1228
 Terminal ID: PPK1

Credit Sale:

Transaction #: 1
 Card Type: Visa
 Account: *****6357
 Entry: Chip

BURLINGAME MOTORS, INC.

Independent Mercedes Benz Dept.
 1295 Rollins Road
 BURLINGAME, CA 94010-2416
 (650) 343-8858 Fax (650) 343-9261

Date: 7/1/92
 Time Received: 10:24:22
 Written By: [Signature]
 Cust. Order No.: 022225
 Promised: [Blank]
 A.M. P.M. Phone when ready: [Blank]
 A.M. P.M. Yes No: [Blank]
 Cell Phone: [Blank]

Year-Make-Model: [Blank]
 License No.: [Blank]
 Odometer: [Blank]

Estimate Amount \$	Engine Size	Year	Month	Day	Time	Description	Authorized By	Authorized By	INITIAL
Revised Estimate									
Revised Estimate									
Revised Estimate									

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in _____ days shown here if I choose not to authorize the service recommended.

REPAIR ORDER — LABOR INSTRUCTION

OPER NO.	REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	PAV SPEAR AND CABLE SAND OUT FOR REPAIR AND NEW CABLE	
	SWITCH GAGES AND CHANGES	
	CLEAN UP ENGINE COMPARTMENT (FRESH OIL LEAKS)	
	CHANGE OIL AND FILTER - FIVE OIL DRIVE - CHECK DIESEL	
	CURSE CLASSA	
	CHANGE VALVE COVER GASKETS	
	CLEAN UP BIRLING	

WARRANTY ON PARTS & LABOR	RECOMMENDED SERVICE:	TOTAL LABOR	TOTAL PARTS	TOTAL SUBLET REPAIRS	TOTAL OIL & GREASE	TOTAL AMOUNT
<input checked="" type="checkbox"/> 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. <input checked="" type="checkbox"/> NOT GUARANTEED - NEED ADDITIONAL SERVICE(S) WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS.	1. [Blank] 2. [Blank] 3. [Blank]	2000.00	8.00	1000.00	5.00	3019.75

TIRE PRESSURE CHECK SERVICE COMPLETED #	TIRE PRESSURE LF	RF	LR	RR	DECLINED @	REASON	QTY	SALE
SUBLET REPAIRS								
PAC + SPEAR + CABLE								1000.00
TOTAL SUBLET REPAIRS								1000.00
TOTAL OIL, GREASE								5.00
TOTAL AMOUNT								3019.75