1-30-19 Bill

Chassis no: 404/X/3073 Engine no: BS1/MK11/274

Body 5875

Orig paint Paramatti Red Corsa 106 Orig upholstery s_Antonio Beige 0104/1 6BP 16,762 263hr labor -10,520

Arnolt Bristol 1954 Reg. no.419 KEC Mileage: 54182

Date in: 22/01/2018 Date out: Feb 2019?

WORKSHO REPORT	Р	Labour	Mate	rials	Outwork	Total cost of task
1.	Exh syst	aust tem				
	lend and up s from lecto to ta mou	ect si- cer box pipe make system n col- or back ail inc unting ckets rub-				
2.	Hea	ter				

	Make up brackets for unit and pipe work, fit up and wire in.		
3.	Potton		
3.	Battery Make up new bat- tery clamp, collect bat- tery and fit.		
4.	Oil pres- sure gauge Make up new oil pressure gauge pipe work and fit.		
5.	Radiator Fit new aluminium radiator with new rubber mounts, also install an electric fan and wire & plumb up.		

6.	Fuel tank	
	Fuel tank	
	had in a	
	previous	
	life been	
	treated	
	with an in-	
	ternal seal-	
	ing solution	
	(tank	
	slosh?) this	
	after a few	
	weeks of	
	having	
	petrol with	
	5% ethanol	
	in started	
	to react	
	and	
	swelled to	
	about twice	
	its volume.	
	Not being	
	able to re-	
	move this	
	sealer from	
	the tank a	
	new tank	
	was made	
	from alu-	
	minium	
	and fitted.	
7.	Toeing eye	
	Make and	
	fit towing	
	eye to the	
	centre of	
	the front	
	cross	
	member.	
	(hopefully	
	never to be	
	needed)	

8.	Over drive	
	wiring Wire up overdrive & switch us- ing a latch- ing relay controlled by en- abling switch and dash switch.	
9.	Overdrive gear box tunnel	
	Make up gear box tunnel to accommodate overdrive and fit.	
10.	Head lights Wire in head lights using 2 new bulb sockets to suit halo- gen bulbs.	
11.	Spring gators & clamps (missing)	

	Fit new leather front spring gators using refurbished clamps.		
12.	Speedo and RPM counter		
	After test drive both were found to be under reading, send to specialist for recalibration along with replacement internals to repair a broken spindle.		
13.	Rust pre- venting		
	Spray Dinitrol ML in to chassis legs and sills & wheel arches.		

14.	Engine & gear box	
	Fit up engine, gear- box, prop shaft and connect up.	
15.	Accessory sockets	
	Fit and wire in a cigar lighter and USB sock- et to under the pas- senger dash.	
16.	Extra fuse box	

Fit extra fuse box to side of passenger foot well, this fuse box is ignition controlled through a relay sited on the left hand side of the heater unit above the yellow overdrive relay. Fuses 1-4 are spare. 5 is cigar lighter, 6 USB, 7 Heater unit, 8 Overdrive, 9 wipers, 10 cooling fan feed to relay sited front LH side of engine bay. Original fuse box LH fuse operates horn and RH fuse is ignition controlled and does indicators.

	Parts used		
	Regulator box lid (Lu- cas RF95)	45.00	
	Horn relay	38.00	
	Horn	40.00	
	Floor board screws X 52	18.72	
	TIG weld- ing & rods	40.00	
	BA screws & nuts	12.00	
*	Steering column draught ex- cluder rub- ber	38.40	
	Pedal rub- bers	33.60	
	P&P	10.95	
	Steering wheel	200.00	
	Steering column cover spring	36.00	
	Heater take off banjo union	20.71	
	Heater take off banjo bolt	12.60	
	Axle pinion bearing outer	35.85	

	nion earing in- er	58.12	
wh	rown neel earings	38.40	
Pi	nion seal	7.22	
ter	cas bat- y cut off ritch	21.00	
pa sis	ock re- ir (tran- stor vitching)	106.00	
su pir	pres- re feed be & ions	14.00	
	rts ed cont		
	nition coil d clamp	42.00	
Ho for	se clips oil cool- pipes	9.60	
Ex	haust	25.00	
1/4	mount- bolts &	7.00	
Alu for	minium boot or & tool	29.00	
100000	minium petrol k	36.00	

Manufac- ture of tank filler neck	110.00	
Tank drain bung	4.00	
Hose clips for heater	16.00	
Petrol tank baulk head union	4.48	
Bonnet buffers	9.48	
Engine machining		
Bore out old liners, bore block for new liners and bore and hone to size.		
Machine block to accept main bearing locating tabs.		
Reface top deck of block.		
Crack test crank and polish.		
Modify bearings to suit rods and block & test fit crank.		

Make and fit small end bushes and true rods.			
Modify fly- wheel dow- els to suit diaphragm clutch cover.			
Balance crank as- sembly.			
Line bore block to suit cam bearings and fit bearings.			
Machine scallops at top of bores to line up with valve openings.			
Clean block.			
Ream valve guides to suit new valves.			
Reface cylinder head.			
Reface valve seats.		3667.20	
Overdrive switch	12.00		

Overdrive gearbox enabling switch	10.39	
Overdrive relay and socket	32.00	
Cotton covered wire for ex- tras	24.00	
Electric fan override switch	4.80	
Extra fuse box operat- ing relay & socket	6.80	
Electric fan thermostat- ic switch	24.36	
Piano hinge for tool box lid	12.00	
Engine cooling hose clips x6	10.92	
Oil cooler mounting rubbers	16.00	
Calibration of Speedo and RPM	132.00	
Parts used cont		
Petrol	45.00	
Brake fluid	4.93	
Anti freeze	5.40	

New oil pump inter- nals	11550	
Ignition points	16.00	
Distributor cap	55.00	
Distributor rotor arm	21.00	
Gearbox oil x2 valvoline 20/50	26.00	
Overdrive ATF	3.00	
Spark plugs	21.88	
Oil filter x 2	14.60	
Millers run- ning in oil	45.00	
Top axle rubber swivel gator	52.14	
Spark plug caps	22.00	
Spark plug HT lead	10.90	
Leather spring gators	77.00	
Cylinder head push rod tube "O" ring conversion	320.00	
Speedo and RPM postage	17.70	
Battery	105.00	
Exhaust si- lencer & pipe	58.00	

Bottom hose adap- tor for heater take		36.00		
off Radiator mounting rubbers		7.20		
Battery ter- minals		9.60		
Battery cut off switch terminals		2.40		
Speedo in- ternals		45.00		
Dinitrol rust preventa-tive		11.00		
Rubber boot mat		24.00		
Labour 263hrs @ £40.00/hr	10520.00	pmis	OUTWAK	
	10520.00	2575.65	3667.20	16762.85

Charles Russell Vintage Sports Car Engineers

Date: 30/01/2019

44 Whitbourne Moor, Corsley, Warminster, Wiltshire BA12 7QL
Tel: 01373 832220 Mob: 07714 330683 Email: vsc_engineers@lineone.net

Chassis no: 404/X/3073 Engine no: BS1/MK11/274 Body 5875 Orig paint Paramatti Red Corsa 106 Orig upholstery s_Antonio Beige 0104/1

Arnolt Bristol 1954 Reg. no.419 KEC Mileage: 54182

WORKSHOP REPORT		Labour	Materials		als	Outwork		otal cost of task
	of	mmary restora- n costs						
	dat	roice ted /01/2018	1028	30.00	1970	.35		12250.35
	rie tail wo	ork car- d out de- ed in rkshop oort						
	dat	oice ted /08/2018	864	0.00	4342	.67		12982.67

	Work car-			
	ried out de- tailed in workshop report			
-	Investor	0.400.00		
	<u>Invoice</u> <u>dated</u> <u>12/10/2018</u>	6460.00	4984.40	11444.40
	Work car- ried out de- tailed in workshop report			
	Invoice dated 04/12/2018	12880.00	5573.54	18453.54 >
	Work car- ried out de- tailed in workshop report			
	Invoice dated 30/01/2018	10520.00	6242.85	16762.85
	Work car- ried out de- tailed in workshop report			
	Labour 1219.5hrs @ £40.00/ hr	48780.00		
		48780.00	23113.81	71893.81

Charles Russell Vintage Sports Car Engineers

Date: 13/05/2019

44 Whitbourne Moor, Corsley, Warminster, Wiltshire BA12 7QL
Tel: 01373 832220 Mob: 07714 330683 Email: vsc_engineers@lineone.net

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and for attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and hardling fee (including researchly) may be chanced. However event and expressions are agnostic and handling fee (including reassembly) may be charged. I have read and understand the love and acknowledge receipt of an estimate.

Roger Kraus Racing Ent, Inc.

2896 Grove Way Castro Valley, CA 94546 (510) 582-5031 BAR # 102319

Vehicles left after repair is completed may be subject to a storage fee.

Repair Order # 99147

Inv Date: 7/16/2020 @ 10:08am

Service Writer: Brandon Kraus

Status: BILL OUT

Driver: Mfg. Date: Unit#

PO#

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price	Ext
Customer states that: F	Requests for Service & Vehicle	e Problems -		-	Maria Property and August	
Labor Service - Than New BLOT5	nk You For Choosing Roger Kra 5016 Blockley TUB	us Racing BK BE 550-16 TR11C		5.00	90.00	0.00 450.00
Labor Service - UPS	GROUND BK		1.00		36.90	36.90
Labor Service - Cred	lit Card On File BK					0.00

VIN:

Engine:

Trans:

Color:

ODO In: 0

License #

ROGER KRAUS TIRES 2896 GROVE WAY CASTRO VALLEY, CA 94546 510/582-5031

SALE

MID: 070004992285

TID: 002 Batch #: 198001

REF#: 00000003 RRN: 019298372 10:45:29

07/16/20 AVS: Z

Invoice #: 3 APPR CODE: 052251

VISA

AMOUNT

Manual CF

CVC: M

*************8111

\$527.40

APPROVED

Thank You Please Come Again

CUSTOMER COPY

Warranty

Customer acknowledges receipt of merchandise and services.

All returned race tires are subject to a 20% restocking charge. Returned Goods Authorization's are required for all returns. All returns must be made in 60 days.

> Sub Total Sales Tax (SCL)

486.90 40.50

TRANS ID: 381188803494542	Since 1295 Rollins Road Since 1979 RIPLINGAME CA 94010-2416	ARDED SAVE Sized	DISCARD INITIAL INITIAL
Mode: Issuer AID: A0000000031010 URAN AID: A0000000031010 URAN AID: A0000000031010 URAN AID: A000000000000000000000000000000000000	OFFICE CHARGING SYSTEM - ALTERNATOR		
	CHECK FOR LEAKS REAR ENGINE CONCR		
	WARRANTY ON PARTS & LABOR RECOMMENDED SERVICE.	TOTAL LABOR	180 00
TOTAL PARTS TIRE PRESSURE CHECK SERVICE COMPLETED 89	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 2.	PARTS	
TIRE PRESSURE: LFRFLRRR(psi) DECLINED III Initial REASON:	9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3,	SUBLET REPAIRS OIL &	
SUBLET REPAIRS	NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOW. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS, WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5.	GREASE	1000
	PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED FI hereby authorize the repair work above to be done along with the necessary vehicle is NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS material, and hereby grant you and/or your employees permission to operate	GAS	
	QTY. SALE the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby	SALES TAX	950
	QTS. OIL QTS. OIL acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond	HAZARDOUS WASTE DISPOSAL FEE	Dimo
TOTAL SUBLET REPAIRS	LBS. GREASE your control. Authorized By	TOTAL AMOUNT	3015

	QTY *	### BURLINGSME MOTORS #### BURLINGSME MOTORS ####################################	SALE	Since 1979 EPA Name Address City Year-Make- Estimate Ar	Independent Mercedes Benz Dept. 1295 Rollins Road BURLINGAME, CA 94010-2416 (650) 343-8858 Fax (650) 343-9261 E-Model License No. Odometer ALL PARTS REMOVED WILL BE DISCARDED SAVE Engine Size VIN Number Time Received Written By Cust. Order No. Promised A.M. Phone when rea Yes II No. Cell Phone ALL PARTS REMOVED WILL BE DISCARDED SAVE II UNLESS INSTRUCTED OTHERWISE.	21583 e dy b b b c c dy
		faccount: Chie		Revised Estin \$ Revised Estin	Ву	INITIAL
		0	*	\$	Ву	INITIAL
				OPER NO.	WN ESTIMATE: I understand that my vehicle will be reassembled in days shown here if I choose not to authorize the service re REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	4				KEI AIK OKBEK EABOK ING KOOTION	CHG.
		h			REPURCE PUTERNATOR MODIFIE BANGKETS	
				1		
1						
1					REPURCE GASKIET @ RENT COVEZ	
			1	6		
			9		D New	
-					(AII) VISA	
1			1		The state of the s	
-						
			200	WARRA	ANTY ON PARTS & LABOR RECOMMENDED SERVICE: TOTAL LABOR	CH
		TOTAL PARTS	100	and the	THS OR 4,000 M LES WHICHEVER COMES FIRST. THS OR 6,000 M LES WHICHEVER COMES FIRST. PARTS PARTS	54000
	TIRE PRESS	SURE CHECK SERVICE COMPLETED ID SURE: LF RF LR RR ((osi) I week	■ 9 MONTH	THS OR 9,000 MILES WHICHEVER COMES FIRST.	1010
	DECLINED (I Initial REASON:			THS OR 12,000 MILES WHICHEVER COMES FIRST. 3. REPAIRS	
	EAST	SUBLET REPAIRS		WARRANTY V	ARANTEED - NEED ADDITIONAL SERVICE(S). WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. W CHARGES OR CUSTOMER SUPPLIED PARTS OR USED	
				PARTS, WARR	AMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF I hereby authorize the repair work above to be done along with the necessary	
				VEHICLE IS NO	of PICKED OF AFTER 43 HIS OF COMPLETION OF REPAIRS material, and hereby grant you and/or your employees permission to operate GAS	İ
				QTY.	TS. OIL the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby SALES TAX	
				-	TS. OIL thereto. You will not be held responsible for loss or damage to vehicle or waste pisposal.	07
-				LE	BS. GREASE articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.	7/
(TOTAL SUBLET REPAIRS		TOTAL	L OIL, GREASE Authorized By AMOUNT	550 92

## R-REBUILT ON SALE ### BURLINGAME MOTORS #### BURLINGAME MOTORS ### BURLINGAME MOTORS	BURLINGAME MOTORS, INC. Independent Mercedes Benz Dept. Since 1295 Rollins Road BURLINGAME, CA 94010-2416 (650) 343-8858 Fax (650) 343-9261 EPA Name Addres City	Written By Cust. Order No. Phone when ready Yes Yes No E
Credit Sale:	Year-Make-Model License No. Odgmeter ALL PARTS REMOVED WILL BE DIS UNLESS INSTRUCTED OTHERS	SCARDED SAVE DISCARD
	Estimate Amount \$ Engine Size VIN Number	
	\$ By	horized
	Revised Estimate S Date Time Description Aut	norized \ INITIAL
	TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in days shown here if I choose not to author	
	OPER NO. REPAIR ORDER — LABOR INSTRUCTION	LABOR CHG.
	Pro at them to a to a contain	
	REPURCE VALVE COVER GASKETS	
	FRANCISTE DOS OFFENSIONET MINTERIAL	
	CHECK EL WIRING TO FAN - WILL FAN TO I	oggit Till 14
	CHECK FL WIRING TO OVER PRIVE - NEED DIAG	PAMI
	ORDER LUBRI PLATE ON FOR OWE SHOT	
		J. J.
		5
		50
TOTAL PARTS	WARRANTY ON PARTS & LABOR RECOMMENDED SERVICE: 3 MONTHS OR 4 000 MILES WHICHEVER COMES FIRST.	TOTAL LABOR 546 00
TOTAL PARTS TIRE PRESSURE CHECK SERVICE COMPLETED IS	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 1. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST.	PARTS 53 TO
151	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3.	PARTS 53 10 SUBLET REPAIRS
TIRE PRESSURE CHECK SERVICE COMPLETED IS TIRE PRESSURE: LF RF LR RR (psi)	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 13. 14 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 15 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 16 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 17 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 18 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 19 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 17 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 18 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 19 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 10 MONTHS OR 12,000 MILE	PARTS 53 50
TIRE PRESSURE: LF RF LR RR (psi) DECLINED 8 Initial REASON:	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 1. 2. 12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3. NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS WARRANTY VOID IF DEFECT CAUSED BY MISSISE ARUSE OR 5.	PARTS 53 100 SUBLET REPAIRS OIL &
TIRE PRESSURE: LF RF LR RR (psi) DECLINED 8 Initial REASON:	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 1. 2. 2. 3. NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NO™. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5. PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED F1 hereby authorize the repair work above to be done along with the necessary VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS. material, and hereby grant you and/or your employees permission to operate	PARTS 53 100 SUBLET REPAIRS OIL &
TIRE PRESSURE: LF RF LR RR (psi) DECLINED 8 Initial REASON:	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 4 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 5 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 1 2 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 1 2 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 2 3. NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5. PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS QTY. SALE 1. 1. 1. 2. 3. WHICHEVER MISUSE, ABUSE OR 5. PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS Material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby	PARTS 53 100 SUBLET REPAIRS OIL & GREASE
TIRE PRESSURE: LF RF LR RR (psi) DECLINED 8 Initial REASON:	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 1 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 1 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 2 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NO™. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PARTS. WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5. PERSONAL DAMAGE. A 252 PER DAY STORAGE FEE WILL BE CHARGED FI hereby authorize the repair work above to be done along with the necessary VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for	PARTS SUBLET REPAIRS OIL & GREASE

## BURLINGAME MOTORS BURLINGAME	Since 1295 Rollins Road 1979 BURLINGAME, CA 94010-2416 1979 EPA Name Addres City Year-Make-Model Estimate Amount \$ Engine Size VIN Number Revised Estimate \$ Date Time Description Date Date	Written By Cust. Order No. Phone when ready Yes No No S CARDED SAVE DISCARD NO INITIAL Drized INITIAL
	TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in days shown here if I choose not to authoric OPER NO. REPAIR ORDER — LABOR INSTRUCTION CHECK FLECTRICAL FAN = KEER FROME ON OVER DAMPE PRICE (YELDOW) 10,06.2/	
TOTAL PARTS	WARRANTY ON PARTS & LABOR 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.	TOTAL ► 180 ∞
TIRE PRESSURE CHECK SERVICE COMPLETED 8 TIRE PRESSURE: LF RF LR RR (DSII) DECLINED 10 Initial REASON: SUBLET REPAIRS	MACCOLARANTEED MEED ADDITIONAL SERVICES	PARTS SUBLET REPAIRS OIL & GREASE GAS
TOTAL SUBLET REPAIRS	QTS. OIL the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles lead in vehicle in case of fire, theft, accident or any other cause beyond voice control.	SALES TAX HAZARDOUS WASTE DISPOSAL FEE TOTAL AMOUNT /XO

-	* CODE N-NEW U-USED R-RE	RIIIIT			DUDLINGAME MOTODS INC. Date	7 00	21782
QTY :		BOILT		SALE	BURLINGAME MOTORS, INC. Date 2 9	The state of the s	1106
QTY :	FART NO. OR DESCRIPTION			SALE	Independent Mercedes Benz Dept. Since A.M.	Written By	-
		-			1295 Rollins Road 1070 P.M.	Cust. Order No.	
		15 13			BURLINGAME, CA 94010-2416 Promised A.M.		dy_
					(650) 343-8858 Fax (650) 343-9261 Cell Phone	Yes 🖾 No	10
					EPA		7
					Name		
					Address		
					Addres:		
	3	1			City		
	A A A A A A A A A A A A A A A A A A A				V		THE STATE OF
					Year-Make-Model License No. Odometer ALL PARTS REMOVED WILL BE DI UNLESS INSTRUCTED OTHER	MISE. SAVE	DISCARD
					Estimate Amount S Engine Size VIN Number		
					foo		
		1			Revised Estimate Date Time Description Aut	horized	
		1 19	*	1 1		horized	INITIAL
					\$ By	ionzed	INITIAL
100					TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled in days shown here if I choose not to author	rize the service rec	
				-	OPER NO. REPAIR ORDER — LABOR INSTRUCTION	AND DOM	LABOR CHG.
					LOWER CAR - CHECK FRONT SPRING REMOVE G	25079	
		P		76	MODIFIE SAFETY STRAIT ON FRONT SPRING		
						S 1	
					LOWER RENZ TORSION BAZ (NOW AT MAX POST)	on)	
		1		100		1	
			1	000			
		74					NGu7
			7 3 -		CHECK ONE SHOT SYSTEM ORDER GREASE WIRPLE	REPURCE!	1607
			4715		0 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		1
					CHECK BATTERIE CHARGE AND CHARGE RATE		
					RATTERIE OK HOLDS 10,9 VOLT LUBER 500 A	12 1000	i
					THE STARTER CLEAN COMMUNITATION AND ARMATURE		
		1 9		6 3	AKSEMPLE STARTED AND TEST -		
		0.70	THE PA		Philo Vich		
-		17	-		TAIDVIA		
		1				I	j
		TY III			WARRANTY ON PARTS & LABOR RECOMMENDED SERVICE:	TOTAL LABOR	7700
	TOTAL PARTS	16.0		- 4	☐ 3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST.		15000
TIRE PRE	SSURE CHECK SERVICE COMPLETED Ø	To Kar		10-97	Months or 6,000 Miles whichever comes first.	PARTS	
	SSURE: LF RF LR RR		(psi)		9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST.	SUBLET	
DECLINE	D III Initial REASON:		ALI O		12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3.	OIL &	
	SUBLET REPAIRS				NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT.	GREASE	
			A.		INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED		
		11124			PARTS, WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5. PERSONAL DAMAGE, A \$25 PER DAY STORAGE FEE WILL BE CHARGED FI hereby authorize the repair work above to be done along with the necessary		
					VEHICLE IS NOT PICKED UP AT TEX 48 HIS OF COMPLETION OF REPAIRS material, and hereby grant you and/or your employees permission to operate	GAS	
					QTY. SALE the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby	SALES TAX	
		37 8			QTS. OIL Ine purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs		
			196		QTS OIL thereto. You will not be held responsible for loss or damage to vehicle or	HAZARDOUS WASTE DISPOSAL FEE	
					LBS. GREASE articles left in vehicle in case of fire, theft, accident of any other cause beyond your control.	TOTAL	7
	TOTAL SUBLET REPAIRS		1		TOTAL OIL, GREASE Authorized By	AMOUNT	Polon

RITEWAY ELECTRIC, INC 261 6TH STREET

261 6TH STREET SAN FRANCISCO, CA 94103

Voice: 415-882-4444

INVOICE

Invoice Number: 99607 Invoice Date: Jul 18, 2022

Page:

Ship to:

1

8325140007028210 Rite Way Electric San Francisco, CA 94103 4158824444 07/18/2022 10:48			
Sale	Customer PO	Payment Te	erms
Trans #: 3 Batch #: 329		C.O.D.	
	Shipping Method	Ship Date	Due Date
VISA CHIP Contactless ********2925 **/**			7/18/22
DACE MATTER C112 AA	Description	Unit Price	Amount
1.00 25022M	12V LUCAS STARTER REPAIR WITH	412.90	Amount 412.90
	NEW FIELDS		
	Subtotal		412.90
	Sales Tax		
	Freight		
	Total Invoice Amount		412.90
Check/Credit Memo No:	Payment/Credit Applied		
	TOTAL		412.90

BURLINGAME MOTORS BURLINGAME MOTORS BURLINGAME MOTORS BURLINGAME MOTORS BURLINGAME, CA 94010 650-343-8858	1979 BURLINGAME, CA 94010-2416 Promised A.M. P.M. Cell Phone	orized orized ize the service rec	DISCARD⊠ INITIAL INITIAL
	WARRANTY ON PARTS & LABOR RECOMMENDED SERVICE:	TOTAL LABOR	made of
TOTAL PARTS > // m	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 6,000 MILES WHICHEVER COMES FIRST. 1,	PARTS	40000
TIRE PRESSURE CHECK SERVICE COMPLETED (0) TIRE PRESSURE: LF RF LR (psi)	9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 2.	SUBLET	7 100
DECLINED IS Initial REASON:	12 MONTHS OR 12,000 MILES WHICHEVER COMES FIRST. 3. NOT GUARANTEED - NEED ADDITIONAL SERVICE(S).	REPAIRS OIL &	
SUBLET REPAIRS	WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NOT. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED	GREASE	5 120
	PARTS, WARRANTY VOID IF DEFECT CAUSED BY MISUSE, ABUSE OR 5. PERSONAL DAMAGE. A \$25 PER DAY STORAGE FEE WILL BE CHARGED IF I hereby authorize the repair work above to be done along with the necessary.		
	VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS. Material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for	GAS	
	the purpose of testing and/or inspection. An express mechanic's lien is hereby	SALES TAX	
	acknowledged on above car, truck or vehicle to secure the amount of repairs QTS, OIL thereto. You will not be held responsible for loss or damage to vehicle or	HAZARDOUS WASTE DISPOSAL FEE	1195
	LBS. GREASE articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.	A CONTRACTOR OF THE PARTY OF TH	1112
TOTAL SUBLET REPAIRS	Your control.	AMOUNT >	42150

BURLINGAME MOTORS BURLINGAME M	EPA Name Address City Year-Make-Model Estimate Amount \$ Revised Estimate \$ Revised Estimate \$ TEAR DOWN ESTI	1295 Rollins R BURLINGAME, CA 9 (650) 343-8858 Fax (6	S Benz Dept. Road Since 1979 Prom Cell I Se No. Odometer VIN Number The Description The Descri	Time Received A.M. P.M. Cust, Order No. Phone when re P.M. Phone when re P.M. Phone when re P.M. Authorized By Authorized By Authorized By Authorized By Authorized By	DISCARD NITIAL
TOTAL PARTS TIRE PRESSURE CHECK SERVICE COMPLETED 80 TIRE PRESSURE: LF RF LR RR DECLINED 82 Initial REASON: SUBLET REPAIRS	(psil) 3 MONTHS OR 4,0 6 MONTHS OR 6,0 9 MONTHS OR 9,0 12 MONTHS OR 12 NOT GUARANTE WARRANTY WORK MUS INCLUDE TOW CHARGE PARTS. WARRANTY VOI PERSONAL DAMAGE, A 9 VEHICLE IS NOT PICKED II QTY. QTS. OIL	SALE	PII. ED a 5. FI hereby authorize the repair work above to be done a material, and hereby grant you and/or your employed the car, truck or vehicle herein described on streets, in the purpose of testing and/or inspection. An express acknowledged on above car, truck or vehicle to secu	PARTS SUBLET REPAIRS OIL & GREASE along with the necessary as permission to operate ighways or elsewhere for mechanic's lien is hereby SALES TAX	20000
TOTAL SUBLET REPAIRS	LBS. GRE		thereto. You will not be held responsible for loss of articles left in vehicle in case of fire, theft, accident or your control. Authorized By		2600

BURLINGAME MOTORS BURLINGAME, CA 94010 650-343-8858 05/08/2024 10:24:22 Merchant ID: 0320 Device ID: 1228 Terminal ID: PPX1. Credit Sale: Transaction #: 1 Card Type: Account: Entry: Chip	Since 1295 Rollins Road Since 1979 BURLINGAME, CA 94010-2416 (650) 343-8858 Fax (650) 343-9261 EPA #CAL coccessor Name Addres: City Year-Make-model Estimate Amount \$ Engine Size VIN Number ALL PARTS REMOVED WILL BE DISC VIN Number Revised Estimate Since 1979 Promised A.M. P.M. Cell Phone ALL PARTS REMOVED WILL BE DISC VIN Number Auth By	orized INITIAL orized INITIAL ize the service recommended. LABOR CHG.
TOTAL PARTS TIRE PRESSURE CHECK SERVICE COMPLETED BY TIRE PRESSURE LF RF LR RR (psi) DECLINED BI Initial REASON: SUBLET REPAIRS	3 MONTHS OR 4,000 MILES WHICHEVER COMES FIRST. 6 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 9 MONTHS OR 9,000 MILES WHICHEVER COMES FIRST. 1. 2. 1. NOT GUARANTEED - NEED ADDITIONAL SERVICE(S). WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NO™. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PERSONAL DAMAGE. A 525 PER DAY STORAGE FEE WILL BE CHARGED FT hereby authorize the repair work above to be done along with the necessary VEHICLE IS NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS. 1. 1. 2. 3. WARRANTY WORK MUST BE DONE AT THIS FACILITY AND DOES NO™. INCLUDE TOW CHARGES OR CUSTOMER SUPPLIED PARTS OR USED PERSONAL DAMAGE. A 525 PER DAY STORAGE FEE WILL BE CHARGED FT hereby authorize the repair work above to be done along with the necessary vehicle is NOT PICKED UP AFTER 48 HRS OF COMPLETION OF REPAIRS. material, and hereby grant you and/or your employees permission to operate	TOTAL LABOR PARTS SUBLET REPAIRS OIL & GREASE GAS
TOTAL SUBLET REPAIRS > 000000	QTS. OIL the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.	SALES TAX HAZARDOUS WASTE DISPOSAL FEE TOTAL AMOUNT