

PARTS TOOLS ACCESSORIES
FOR IMPORTED AUTOMOBILES

ECONOMY IMPORTS INC

CUPERTINO • 95014
10133 So. Saratoga Sunnyvale Rd.
Phone 408/996-1212

PALO ALTO • 94306
3929 El Camino Real
Phone 415/493-5115

SAN JOSE • 95125
2980 Almaden Expressway
Phone 408/267-1161

SAN JOSE • 95117
285 Tyler Ave.
Phone 408/243-6400

SAN RAFAEL • 94901
509-B Francisco Blvd.
Phone 415/457-3515

SAN JOSE • 95123
867 Blossom Hill Rd.
Phone 408/578-5700

SUNNYVALE • 94086
592 S. Mary Ave.
Phone 408/738-2882

Sold To _____

Date

9/27/74

Address _____

215466

QUAN.	PART NUMBER	DESCRIPTION	UNIT PRICE	
2	710071-02	ROTOR	9.20	18.40
1	70-3880-01	ROTOR		8.45
	MARCEL NUMBER			26.85
	K-710671-07	one has short		
	K-710071-06	leads; the other long		

Willats S. F. N8080

P.B. CHECK # 823

CORE CHARGE	
SALES TAX	1.61
TOTAL	28.46

NO REFUND OR EXCHANGE ON ELECTRICAL PARTS

FERRARI Lube & P/M Record

	KM	
7-20-74	61990	CHG OIL (20W-40) + OIL FILTER
7-23-74	62000	NEW SPARK PLUGS (NGY)
8-18-74		CHASSIS LUBE (INCLUDING SPEEDMETER CABLES)
9-28-74		NEW POINTS & ROTORS
10-1-74		NEW SPARK PLUGS (LEFT SIDE 1/2 CARB) (LOOKS RICH)
10-3-74	62025	FIX SPEEDOMETER
10-28-74	62678	CHG OIL (QS10W-30) + OIL FILTERS
12-7-74	63452	CLEAN SPARK PLUGS (FAILED: 4, 7, 10)
1-1-75	63906	INSTALL NEW THERMOSTAT (80-85)
1-12-75	64039	Change Transmission & Rear Axle oil
1-19-75	64492	Clean Spark plugs, Adjust Carbs, NEW Air filters
1-20-75		
1-20-75	64501	INSTALL NEW TIRES
1-31-75	64868	NEW SPARK PLUGS WIRES
1-31-75	64868	NEW SPARK PLUGS
2-3-75	64928	CHASSIS LUBE
3-7-75	65618	CHG OIL (QS20W-40) AND OIL FILTERS
3-10-75	65637	NEW SPARK PLUGS
5-8-75	68850	NEW BATTERY
5-12-75	68890	NEW SHIFT LEVER BUSHING
7-5-75	69788	NEW SPARK PLUGS. (BROKE BOLT ON LEFT DISTRIBUTOR MOUNT.) COMMISSION TEST: 1-0, 2-80, 3-0, 4-58, 5-OK, 6-0, 7-0, 8-0, 9-90, 10-0, 11-85, 12-95

7-24-75	69799	PREPARE FOR STORAGE. CHANGE OIL (QS 30), oil filters, CHARGING SYSTEM IS OVERCHARGING BATTERY (LOW WATER)
5-8-77	69799	RETURN TO SERVICE; VALVE JOB, GUIDE SEAL LUBE, RECORE RADIATOR, NEW COOLANT (2 GAL ZERO) ROTATE TIRE F \leftrightarrow R, CHANGE BRAKE (CASTROL LMA) FLUID, NEW AIR FILTERS, NEW EXHAUST SYSTEM, NEW SPARK PLUGS, PACK FRONT WHEEL BEARINGS, NEW FAN BELT, FIX VOLTAGE REGULATOR, SET TOE-OUT
5-22-77	70325	RETORQUE HEADS, CHG OIL (QS 40) & OIL FILTERS
8-1-77	71128	NEW FRONT BRAKE PADS + REBUILD CYLINDERS
9-3-77	73137	NEW SPARK PLUGS (RICH INDICATION)
10-15-77	73764	CHG OIL (QS 30) & OIL FILTERS
12-26-77	75137	NEW FRONT + REAR FUEL FILTERS
1-6-78	75154	CHASSIS LUBE
3-23-78	76455	NEW SPARK PLUGS (NGY), TUNE UP IGNITION
3-26-78	76702	CHG OIL (QS 40), OIL FILTERS AND TRANSMISSION AND REAR AXLE OIL
7-15-78	78201	NEW AIR FILTERS (FRAM CA-656), CLEAN SPARK PLUG
10-19-78	80962	CHG OIL (QS 40 RACING), OIL FILTERS, CHASSIS LUBE
11-11-78	81456	NEW SPARK PLUGS (NGY)
12-22-78	81602	CHG OIL (QS 20W-50)
2-15-79	82971	PREPARE FOR STORAGE
9-27-79	82971	REACTIVATE FOR ROAD USE; NEW SPARK PLUGS (N7Y), REBUILD CARBS, CHASSIS LUBE
12-19-79	82980	SLEEVE & REBUILD LT-FRONT BRAKE CYLS. NEW UPPER A-ARM BUSHINGS - LT SIDE

<u>DATE</u>	<u>KM</u>	
5-27-80	86308	INSTALL NEW BATTERY
7-1-80	86480	CHG OIL (20W-50), oil filters, CHASSIS LUBE
1-24-81	88479	NEW FRONT BRAKE PADS
5-10-81	88500	NEW LF BRAKE HOSE
11-9-81	91093	CHG OIL (20W-50), oil filters, chassis lube, AIR FILTERS, Adjust PARKING brake, CARBS to "winter"
4-21-82	93141	CARBS TO "SUMMER"
5-3-82	94579	Install Ford 61 Amp ALTERNATOR
8-21-82	96502	CHG OIL (20W-50), oil filters, chassis lube
11-12-82	96579	CARBS TO "WINTER", INSTALL REPAIRED FUEL GAUGE, NEW SPARK PLUGS (N-7Y)
5-9-83	96608	CARBS TO "SUMMER"
7-24-83	96693	REPLACE RT-FRONT AND REAR BRAKE HOSES.
10-17-83	96842	CARBS TO "WINTER"

Factory Trained **Ferrari & MASERATI** Technician (310) 445-8956
 3104458964

License **BJV599**
 Eng. Type **3.9L**
 Eng. No. **12CYL**
 Prod.
 Year **1965**
 Sales:
 Color: **LIGHT BLUE**

Make **FERRARI**
 Model **330GT 2+2 - 21,533.0**
 Miles/Km In Out **21,533.0**
 Ext. Vin **7119**
 Cell. # **(512) 789-1490**

Open Date 16 SEP 2016 00:00 Ready By: 16 SEP 2016 09:48

Description of Labor / Service Provided

H. T/L Tech. Amount

CUSTOMER REPORTS;
 EXCESSIVE SMOG FROM EXHAUST.
 INSPECT AND ADVISED. SHOP N/C

UPON INSPECTION, CONFIRMED CUSTOMER'S COMPLAINT.
 PERFORMED COMPRESSION AND LEAK DOWN TEST: SHOP 420.00

COMPRESSION / LEAK DOWN:

- 1) 150 / 30%
- 2) 140 / 41%
- 3) 140 / 40%
- 4) 130 / 50%
- 5) 140 / 42%
- 6) 115 / 80%
- 7) 155 / 30%
- 8) 155 / 30%
- 9) 110 / 80%
- 10) 150 / 30%
- 11) 120 / 80%
- 12) 155 / 35%

RESULTS OF TESTS, WE RECOMMENDED ENGINE OVERHAUL. CUSTOMER
 WAS ADVISED AND AUTHORIZED COMPLETE ENGINE OVERHAUL.

WILL NOT CHARGE FOR (\$420) INSPECTION AND DIAGNOSIS LABOR

COMPLETE ENGINE OVERHAUL: SHOP 14,000.00

DRAIN ALL FLUIDS AND DISCONNECT ALL HOSES AND CABLES FROM ENGINE.
 REMOVE GEARBOX AND REMOVE ENTIRE ENGINE FROM VEHICLE.
 DISASSEMBLE ENTIRE ENGINE. SEND ENGINE BLOCK CYLINDER HEADS AND
 CRANK SHAFT TO MACHINE SHOP. MACHINE SHOP FOUND THAT THE
 CYLINDERS WERE WORN AND OUT OF ROUNDS, NEEDING NEW PISTONS TO
 BE MADE FOR ENGINE. MACHINE SHOP REPLACE ALL VALVE GUIDES AND
 RECTIFIED THE CRANK. AND BORED ENGINE FOR NEW PISTONS.
 WE PERFORMED COMPLETE VALVE JOB.
 REPLACED ALL HOSES.
 REASSEMBLE ENTIRE ENGINE WITH NEW PISTONS AND INSTALL IN VEHICLE.
 REPLACED ALL FILTERS AND REFILLED ALL FLUIDS.
 REASSEMBLE ALL COMPONENTS.

DURING SERVICE, NOTICED THAT THE CLUTCH NEEDED TO BE REPLACED. N/C
 CLUTCH REPLACEMENT:
 REMOVE AND REPLACE CLUTCH ASSEMBLY, T.O. BEARING AND T.O. BEARING
 COLLAR.

REMOVED HOOD AND SEND TO UPHOLSTERY SHOP TO INSTALL NEW PAD. N/C

	Parts / Material	Description	Qty	Each \$	Extended \$
New	S ORDR 78MM COMP.	PISTON SET W/ RINGS CLIPS PINS	1.00	4708.00	4,708.00
New	..	COMPLETE GASKET AND SEALS SET	1.00	1650.00	1,650.00
..	..	ROD BEARING SET	1.00	732.00	732.00
..	..	MAIN BEARING SET	1.00	914.00	914.00
..	..	3 ROLLERS TIMING CHAIN	1.00	590.00	590.00
..	..	VALVE ADJUST SCREWS	24.00	14.10	338.40
..	..	SPARK PLUGS	12.00	7.50	90.00
..	..	OIL FILTER	2.00	44.20	88.40
..	..	VALVOLINE ALL CLIMATE, OIL	10.00	7.95	79.50
..	..	FUEL FILTER	1.00	29.90	29.90
..	..	SHELLZONE, COOLANT	2.00	24.95	49.90

Factory Trained **Ferrari & MASERATI** Technician (310) 445-8956
 3104458964

License **BJV599**
 Eng. Type **3.9L**
 Eng. No. **12CYL**
 Prod.
 Year **1965**
 Sales:
 Color: **LIGHT BLUE**

Open Date	16 SEP 2016 00:00	Ready By:	16 SEP 2016 09:48	Make	FERRARI
				Model	330GT 2+2 - 21,533.0
				Miles/Km In Out	21,533.0
				Ext. Vin	7119
				Cell. #	(512) 789-1490

..	ALTERNATOR BELT	1.00	29.95	29.95
..	CLUTCH ASSEMBLY	1.00	450.14	450.14
..	T.O. BEARING	1.00	189.50	189.50
..	T.O. COLLAR	1.00	432.68	432.68

Miscellaneous/Sublet Charges

	Amount
MACHINE SHOP: ENGINE AND HEADS WORK	4,250.00
ELECTRICAL SHOP: REBUILD ALTERNATOR	180.00
ELECTRICAL SHOP: REBUILD STARTER MOTOR	380.00
RADIATOR SHOP: REPAIR AND REFINISH RADIATOR	460.00
UPHOLSTERY SHOP: HOOD	600.00
DISCOUNT: \$420 LABOR FOR INSPECTION/DIAGNOSIS/TESTING	0.00

Original Estimate: \$ 30,000.00 X: _____ X: _____
 I acknowledge notice and oral approval of an increase in the original estimated price

Revision #1	Increase	Revision #2	Increase	Revision #3	Increase
	.00		.00		.00
	0.00		0.00		0.00

PAID c.c. J.H.

I hereby authorize the above named to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft, or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of \$30.00 per day, will be charged unless otherwise agreed to in writing.

Signature: _____ Date: _____

X: _____
 Payment 1: CHECK 18000.00 DEPOSIT
 Thank You From: F & M MotorSport

Account # 675
 Payment 2:
 Key# 0.00

Labor	\$ 14,420.00
Parts	\$ 10,372.37
Environmental:	\$ 0.00
Shop Supplies	\$ 25.00
Sub Total Charges	\$ 25.00
Sublet	\$ 5,450.00
Total Sales Tax	\$ 933.51
Total Discount	\$ 420.00
Tot. Before Sales Tax	\$ 30,267.37
Total Sale	\$ 31,200.88
Total Due	\$ 13,200.88

(310) 445-8956
 3104458964

Factory Trained **Ferrari & MASERATI** Technician

License **BJV599**
 Eng. Type **3.9L**
 Eng. No. **12CYL**
 Prod.
 Year **1965**
 Sales:
 Color: **LIGHT BLUE**

Make **FERRARI**
 Model **330GT 2+2 - 21,533.0**
 Miles/Km In Out **21,533.0**
 Ext. Vin **7119**
 Cell. # **(512) 789-1490**

Open Date 29 SEP 2016 00:00 Ready By: 29 SEP 2016 11:55

Description of Labor / Service Provided	H.	T/L	Tech.	Amount
DURING ROAD TEST BRAKES DID NOT PERFORM WELL. CAR WAS PULLING TO THE RIGHT AND LEFT. INFORMED CUSTOMER. CUSTOMER APPROVED REPAIRS.			SHOP	N/C
FRONT BRAKES: REMOVE FRONT WHEELS, BRAKE CALIPERS & ROTORS. MACHINE ROTORS AND REPLACE BRAKE PADS. REINSTALL ALL COMPONENTS & AIRBLEED BRAKES. RESECURE WHEELS.			SHOP	420.00
REAR BRAKES: REMOVE REAR WHEELS, BRAKE CALIPERS & ROTORS. MACHINE ROTORS & REPLACE BRAKE PADS. REINSTALL ALL COMPONENTS & AIRBLEED BRAKES. RESECURE WHEELS			SHOP	420.00
DURING BRAKE SERVICE, WE REBUILT BRAKE CALIPERS. FRONT BRAKE CALIPERS: DISASSEMBLE FRONT BRAKE CALIPERS. CLEAN AND REBUILD BRAKE CALIPERS, AS NECESSARY. REMOVE AND REPLACE BRAKE HOSES. REMOVED AND REPLACED FRONT HUB SEAL RINGS. REASSEMBLE ALL COMPONENTS.			SHOP	560.00
REAR BRAKE CALIPERS: DISASSEMBLE REAR BRAKE CALIPERS. CLEAN AND REBUILD CALIPERS AS NECESSARY. REMOVE AND REPLACE BRAKE HOSE. REMOVED AND REPLACED REAR SEAL RINGS TO REAR AXEL SHAFTS. REASSEMBLE ALL COMPONENTS. ROAD TEST CAR. BRAKES NOW PERFORM AS EXPECTED.			SHOP	560.00

Parts / Material	Description	Qty	Each \$	Extended \$
New ..	ATE TYPE 200, BRAKE FLUID	2.00	21.95	43.90
New ..	F BRAKE PADS KIT	1.00	132.98	132.98
New ..	R BRAKE PADS KIT	1.00	98.00	98.00
..	F CALIPER REBUILD KIT	1.00	273.23	273.23
..	R REBUILD BRAKE CALIPER KIT	1.00	160.21	160.21
..	BRAKE HOSE	3.00	66.00	198.00
..	OUTER REAR SEAL RING	2.00	94.17	188.34
..	INNER REAR SEAL RING	2.00	25.45	50.90
..	FRONT HUB SEAL RING	2.00	165.03	330.06
..	PISTON & CYLINDER	1.00	354.29	354.29

Miscellaneous/Sublet Charges Amount
 MACHINE SHOP: REFINISH ROTORS 180.00

Original Estimate: \$ 3,800.00 X: _____ X: _____
 I acknowledge notice and oral approval of an increase in the original estimated price

Revision #1	.00	Revision #2	.00	Revision #3	.00
Increase	0.00	Increase	0.00	Increase	0.00

F & M Motorsports
Ferrari / MASERATI
Independent Service

11797 West Pico Blvd.
Los Angeles, CA 90064

R.O. 102282 Page: 2
Date 20 OCT 2016
Lic. ARD00255600
EPA-YYYYYYY

Factory Trained Ferrari & MASERATI Technician
(310) 445-8956
3104458964

License BJV599
Eng. Type 3.9L
Eng. No. 12CYL
Prod.
Year 1965
Sales:
Color: LIGHT BLUE

Open Date 29 SEP 2016 00:00	Ready By: 29 SEP 2016 11:55	Make FERRARI Model 330GT 2+2 - 21,533.0 Miles/Km In Out 21,533.0 Ext. Vin 7119 Cell. # (512) 789-1490
-----------------------------	-----------------------------	---

PAID C.E. JL

I hereby authorize the above named to operate and store the above vehicle for the purpose of testing, inspection, repair and delivery, at my own risk. I understand that the above named is not responsible for loss or damage equipment or articles left on or in vehicles in case of fire, theft, or any cause beyond their control. I understand that if I wish to retain worn and damaged parts that request will be made at the time of authorization or repairs. I understand that two (2) days after notice of completion of services rendered, that a storage charge of \$30.00 per day, will be charged unless otherwise agreed to in writing.

Signature: _____ Date: _____

X: _____

Payment 1: 0.00

Thank You From: F & M MotorSport

Account # 675

Payment 2:

Key#

0.00

Labor	\$ 1,960.00
Parts	\$ 1,829.91
Environmental:	\$ 0.00
Shop Supplies	\$ 25.00
Sub Total Charges	\$ 25.00
Sublet	\$ 180.00
Total Sales Tax	\$ 164.69

Tot. Before Sales Tax \$ 3,994.91

Total Sale \$ 4,159.60

Total Due \$ 4,159.60

Francorchamps of America, Inc.

Costa Mesa, Ca 92627

Invoice

Date	Invoice #
3/22/2018	47461a

Bill To

P.O. No.	Terms	Project

Quantity	Description	Rate	Amount
	axle nut	123.15	123.15T
1	axle Parts-Taxable	750.00	750.00T
2	rear axle bearing Parts-Taxable	235.0228	470.05T
2	rear seal Parts-Taxable	22.45	44.90T
4	points Parts-Taxable	27.78	111.12T
2	valve guide seals Parts-Taxable	2.55	5.10T
1	Towing	175.00	175.00
	Freight	25.00	25.00
1	shims for rockers Parts-Taxable	18.10	18.10T
1	head gasket Parts-Taxable	239.71	239.71T
1	vc gasket set Parts-Taxable	71.80	71.80T
5	synco's Parts-Taxable	217.04	1,085.20T
3	sliders Parts-Taxable	937.972	2,813.92T
2	brake rings Parts-Taxable	120.00	240.00T
1	trans gasket set Parts-Taxable	35.00	35.00T
1	trans seal kit Parts-Taxable	38.45	38.45T
1	input shaft bearing Parts-Taxable	164.656	164.66T
1	lock tab set Parts-Taxable	17.00	17.00T
1	Freight	47.00	47.00
2	distributor seals Parts-Taxable	31.50	63.00T
1	tach drive seal Parts-Taxable	7.56	7.56T
2	radiator fans Parts-Taxable	81.00	162.00T
4	distributor plate pin Parts-Taxable	12.80	51.20T
2	distributor weight Parts-Taxable	39.00	78.00T
1	oil filter Parts-Taxable	28.00	28.00T
1	bypass filter Parts-Taxable	18.00	18.00T
2	fan install kits Parts-Taxable	8.68	17.36T
1	clutch cover Parts-Taxable	345.00	345.00T
1	flywheel dowel Parts-Taxable	45.00	45.00T
1	5 th gear Parts-Taxable	635.851	635.85T
1	clutch flex line Parts-Taxable	108.511	108.51T
1	surface flywheel and balance	125.00	125.00T
1	install trim ring on speedo	60.00	60.00T
Total			

Francorchamps of America, Inc.

Costa Mesa, Ca 92627

Invoice

Date	Invoice #
3/22/2018	47461a

Bill To

P.O. No.	Terms	Project

Quantity	Description	Rate	Amount
1	5 gear driven side Parts-Taxable	444.074	444.07T
1	5th gear bush Parts-Taxable	30.00	30.00T
2	pedal pads Parts-Taxable	28.054	56.11T
2	coolant Parts-Taxable	17.85	35.70T
10	engine oil Parts-Taxable	6.99	69.90T
6	gear oil Parts-Taxable	15.44	92.64T
1	brake fluid Parts-Taxable	15.00	15.00T
156.32	Labor Car came in on flat bed with collapsed left rear axle, remove rear brake caliper and rotor, replace axle bearing, seal and installed used axle. road tested car, No power on road test. noise in right rear, brakes pulling, exhaust falling off, oil coming out of exhaust on cylinder #5. remove right cylinder head, #5 piston. check rings for problems, Replace seals on valve guides number #5, Reinstall piston, rebuild both distributors, weights worn out and points fried, reshim all rockers for side clearance, adjust valves, Clean out carburetors and set float heights, rejet to compensate for worn throttle shafts, change oil and filter, replace seal in tach drive, pull transmission for rebuild, replace both 5th gears, and bushing, replace 5 syncro, 3 slider and 2 brake rings, replace clutch cover and have unit balanced, replace clutch hydraulic hose, replace front differential seal, replace electric fuel pump with modern pump. replace both radiator fans., reshim mechanical fuel pump, remove master cylinder for rebuild, bleed brakes, replace clutch master, CA Sales Tax, Orange County	130.00	20,321.60 0.00
		7.75%	675.49
Total			\$29,960.15

Detailed Time Report

Timeframe 09/23/2013 — 06/28/2018
 Total 156.32 Hours
 0.00 Uninvoiced Billable Hours

1 Client
 1 Project 330
 Tasks All Tasks
 Team Everyone

Client	Project	Task	Roles	Person	Hours
03/20/2018					6.36
	330	Admin	mechanic	Chris Bemmer	6.36
03/21/2018					3.30
	330	Admin	mechanic	Chris Bemmer	3.30
03/28/2018					4.62
	330	Admin	mechanic	Chris Bemmer	4.62
05/09/2018					5.56
	330	Admin	mechanic	Patrick Blankenship	5.56
05/16/2018					5.78
	330	Admin	mechanic	Patrick Blankenship	5.78
05/17/2018					0.89
	330	Admin	mechanic	Patrick Blankenship	0.89
05/21/2018					7.00
	330	Admin	N/A	Roger Hall	7.00
		<i>install new valve guide seals on 1-6 head, prep parts and engine surface for assembly.</i>			
05/22/2018					7.00
	330	Admin	N/A	Roger Hall	7.00
		<i>install #5 piston and begin engine assembly</i>			
05/23/2018					3.00
	330	Admin	N/A	Roger Hall	3.00
		<i>continue assembly, go home with bad cold</i>			
05/24/2018					7.00
	330	Admin	N/A	Roger Hall	7.00
		<i>continue assembly, clean rust debris out of carbs and filter bowl, install new fuel filter.</i>			
05/25/2018					7.00
	330	Admin	N/A	Roger Hall	7.00
		<i>rebuild 1-6 distributor, deal with out of phase points.</i>			
05/29/2018					7.00
	330	Admin	N/A	Roger Hall	7.00
		<i>finish up engine assembly.</i>			
05/30/2018					8.77
	330	Admin	mechanic	Patrick Blankenship	1.77
	330	Admin	N/A	Roger Hall	3.00
		<i>install oil pan, engine up and running.</i>			
	330	Admin	N/A	Roger Hall	4.00
		<i>r&r pinion seal, remove clutch and flywheel, remove radiator fans and prepare to install new electric fans.</i>			
05/31/2018					12.20
	330	Admin	mechanic	Patrick Blankenship	5.20
	330	Admin	N/A	Roger Hall	7.00
		<i>rebuild leaking fuel pump, install elect fans</i>			
06/01/2018					8.37
	330	Admin	mechanic	Patrick Blankenship	4.37

Client	Project	Task	Roles	Person	Hours
	330	Admin	N/A	Roger Hall	4.00
		<i>continue with fuel pump problems</i>			
06/02/2018					0.38
	330	Admin	mechanic	Patrick Blankenship	0.38
06/04/2018					8.06
	330	Admin	mechanic	Patrick Blankenship	6.06
	330	Admin	N/A	Roger Hall	2.00
		<i>hook up last few things related to engine install, remove car from rack.</i>			
06/05/2018					0.12
	330	Admin	mechanic	Patrick Blankenship	0.12
06/06/2018					3.03
	330	Admin	mechanic	Patrick Blankenship	3.03
06/07/2018					0.95
	330	Admin	mechanic	Patrick Blankenship	0.95
06/13/2018					0.30
	330	Admin	mechanic	Patrick Blankenship	0.30
06/15/2018					3.54
	330	Admin	mechanic	Patrick Blankenship	3.54
06/18/2018					8.01
	330	Admin	mechanic	Patrick Blankenship	8.01
06/19/2018					8.49
	330	Admin	mechanic	Patrick Blankenship	8.49
06/20/2018					7.14
	330	Admin	mechanic	Patrick Blankenship	7.14
06/21/2018					6.79
	330	Admin	mechanic	Patrick Blankenship	6.79
06/22/2018					4.67
	330	Admin	mechanic	Patrick Blankenship	3.24
	330	Admin	mechanic	Chris Bemmer	1.43
06/26/2018					1.57
	330	Admin	mechanic	Patrick Blankenship	1.57
06/27/2018					7.10
	330	Admin	mechanic	Patrick Blankenship	7.10
06/28/2018					2.32
	330	Admin	mechanic	Patrick Blankenship	2.32
				Total	156.32

Francorchamps of America, Inc.

Costa Mesa, Ca 92627

Invoice

Date	Invoice #
10/5/2018	47505a

Bill To

P.O. No.	Terms	Project

Quantity	Description	Rate	Amount
1	window motor Parts-Taxable	386.97	386.97T
2	relays Parts-Taxable	12.00	24.00T
1	valve cover gasket set Parts-Taxable	30.00	30.00T
1	polish quarter window front frame.	25.00	25.00T
20.09	pull vlave covers and retorque heads, pressure test cooling system, remove both quarter windows, take window frames apart, unweld broken bolts, make up t bolts to support window frames, replace window motor with unit from 308, install flip flop relays	150.00	3,013.50
	CA Sales Tax, Orange County	7.75%	36.11
		Total	\$3,515.58

CUSTOMER #: F4830
 UNIT# 330

55708

INVOICE

PAGE 1



FERRARI OF HOUSTON

6100 Southwest FWY
 Houston TX 77057
 (713) 772-3868
 www.ferrariofhouston.com

SERVICE ADVISOR: 629 MICHAEL ELLINGTON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
SILVER	65	FERRARI 330 GTC	XXXXXXXXXXXX7119	330GT	24442/24442	T509	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN65 DD		01JAN1965	16:30 05AUG22			CASH	24JUN22
R.O. OPENED	READY	OPTIONS:					
08:47 07JUN22	10:54 24JUN22						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER REPORTS THE FUEL LEVEL GAUGE READS FULL ALL OF THE TIME
 505 062422.FUEL.
 633 CS 1050.00 1050.00
 1 MC3701 FUEL SENDING UNIT 256.33 256.33 256.33
 PARTS: 256.33 LABOR: 1050.00 OTHER: 0.00 TOTAL LINE A: 1306.33
 24442 CONFIRMED THE CUSTOMER COMPLAINT; FUEL GAUGE READS FULL AT ALL TIME; REMOVED FUEL TANK TO INSPECTED FUEL SENDING UNIT AND FUEL GAUGE; FOUND FAULTY FUEL SENDING UNIT AND WHEN REMOVED FUEL TANK FOUND A CORROSION BUILD UP INSIDE THE TANK; SEND THE TANK TO BE CLEAN UP.

B CUSTOMER REPORTS THE DRIVERS DOOR IS INTERMITTENTLY INOPERABLE
 606 061522.DRIVER'S AND PASSENGER'S DOOR LOCKS.
 633 CS 1050.00 1050.00
 606 062422.EXTERIOR.) 210.00 210.00
 PARTS: 0.00 LABOR: 1260.00 OTHER: 0.00 TOTAL LINE B: 1260.00
 24442 CONFIRMED THE CUSTOMER COMPLAINT NEITHER DOOR WILL LOCK WITH THE KEY; REMOVED BOOTH DOOR PANELS AND FOUND THAT THE LOCKING MECHANISM IS LOOSE AND WORN OUT; KEY IS ALSO WORN OUT; FIX LOCKING MECHANISM; BOTH DOORS WILL LOCK AND UNLOCK.

C CUSTOMER REPORTS THE PASSENGER SUN VISOR DOES NOT STAY UP
 600 INTERIOR
 633 CS 0.00 0.00
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
 24442 TIGHTEN SUN-VISOR LOOSE SCREWS

D CUSTOMER REQUESTS TECHNICAL INSPECTION FOR CLASSICHE APPLICATION
 206 061322.TECHNICAL INSPECTION FOR CLASSICHE CERTIFICATION.
 633 CS 3150.00 3150.00

SUBL FORSYTHE FOTOGRAHY #0004059. FOTO SESSION FOR CLASSICHE CERTIFICATION.
 CS 1275.00 1275.00

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

*SHOP SUPPLY COSTS:
 We have added a charge of 15% of labor with a minimum of \$4.75 and not to exceed \$89.95 for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001: The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with s. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

CUSTOMER #: F4830
UNIT# 330

55708

INVOICE

PAGE 2



FERRARI OF HOUSTON

6100 Southwest FWY
Houston TX 77057
(713) 772-3868
www.ferrariofhouston.com

SERVICE ADVISOR: 629 MICHAEL ELLINGTON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
SILVER	65	FERRARI 330 GTC	XXXXXXXXXXXX7119	330GT	24442/24442	T509	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN65 DD		01JAN1965	16:30 05AUG22			CASH	24JUN22
R.O. OPENED	READY	OPTIONS:					
08:47 07JUN22	10:54 24JUN22						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL			
PARTS:				0.00	LABOR:	3150.00	OTHER:	1275.00	TOTAL LINE D:	4425.00

PERFORMED A COMPLETE TECHNICAL INSPECTION FOR A CLASSICHE APPLICATION; CUSTOMER APPROVED CLASSICHE APPLICATION; PREPARE CAR FOR PICTURES TAKEN; CLASSICHE DEPARTMENT REQUESTED ORIGINAL EXHAUST SYSTEM AND ORIGINAL TIRE SIZE.
FERRARI FEE FOR CLASSICHE CERTIFICATION WILL BE BILLED OUT ON NEXT RO, AFTER RECEIVING THE RIGHT AMOUNT FROM THE FACTORY.

E** TIRES: REPLACE ALL 4 TIRES, AS PER CLASSICHE REQUEST.

400 062422. TIRES.							
633 CS						294.00	294.00
4 57974 MICH XWX 205/70VR15					492.00	492.00	1968.00
4 85364 185/195 TUBE					42.88	42.88	171.52
PARTS:	2139.52	LABOR:	294.00	OTHER:	0.00	TOTAL LINE E:	2433.52

24442 REPLACED ALL 4 TIRES AS PER CLASSICHE REQUESTED TO HAVE THE ORIGINAL TIRE SIZE

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 89.95

<p>WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.</p> <p>By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.</p>	<p>*SHOP SUPPLY COSTS: We have added a charge of 15% of labor with a minimum of \$4.75 and not to exceed \$89.95 for shop supplies used in connection with this repair.</p>	DESCRIPTION	TOTALS
	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	LABOR AMOUNT	5754.00
		PARTS AMOUNT	2395.85
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	1275.00
		MISC. CHARGES *	89.95
		TOTAL CHARGES	9514.80
		LESS INSURANCE	0.00
		SALES TAX	205.08
		PLEASE PAY THIS AMOUNT	9719.88

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE S. 70.001: The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

DealerCAP 2014 CDK Global, LLC (08/17) SERVICE INVOICE TYPE 2 - 2512C - *AS-IS* - TX - 9698039

CUSTOMER COPY

DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

CUSTOMER #: F4830
UNIT# 330

55806

INVOICE

PAGE 1



FERRARI OF HOUSTON

6100 Southwest FWY
Houston TX 77057
(713) 772-3868
www.ferrariofhouston.com

SERVICE ADVISOR: 621 GIUSEPPE DIBLASIO

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
SILVER	65	FERRARI 330 GTC	XXXXXXXXXXXX7119	330GT	24443/24445	T509	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN65 DD		01JAN1965	16:30	15JUL22		CASH	20JUL22
R.O. OPENED	READY	OPTIONS:					
09:34	29JUN22	11:56	20JUL22				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A FUEL: CUSTOMER REPORTS FUEL LEVEL GAUGE READS FULL ALL THE TIME.							
505 071522. FUEL.							
			633	CS		1050.00	1050.00
1	32303761772801	FUEL FILTER			35.54	35.54	35.54
1	95180050A	FUEL FILTER FISPA			83.98	83.98	83.98
1	16315240	GROMMET			68.22	68.22	68.22
1	101462	SENDER SEAL			48.71	48.71	48.71
1		METAL TANK SERVICE			320.00	320.00	320.00
PARTS: 556.45 LABOR: 1050.00 OTHER: 0.00					TOTAL LINE A:		1606.45

24443 CONFIRMED THE CUSTOMER COMPLAINT; FUEL GAUGE READS FULL ALL THE TIME; INSPECTED FUEL GAUGE FOUND A MISSING GROUND CONNECTION BEHIND THE GAUGE; RECONNECTED THE LOOSE GROUND BUT THE GAUGE STILL READING FULL; AS PER CUSTOMER AUTHORIZATION WE REMOVED THE FUEL TANK TO INSPECTED THE FUEL SENDING UNIT FOUND THAT THE SENDING UNIT WAS CORRODED; ALSO THE FUEL TANK WAS FULL O CORROSION SENT THE FUEL TANK TO BE CLEAN UP; REPLACED THE FUEL SENDING UNIT BUT THE GAUGE STILL READING FULL; FOUND A MALFUNCTIONING FUEL GAUGE.

B EXTERIOR: CUSTOMER REPORTS THE DRIVER'S DOOR IS INTERMITTENTLY INOPERABLE.							
606 EXTERIOR							
			633	CS		0.00	0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00					TOTAL LINE B:		0.00
24443 THIS ISSUE WAS ADDRESSED ON PREVIOUS RO.							

C CLASSIQUE: CUSTOMER AUTHORIZED CLASSICHE APPLICATION.							
206 CLASSIQUE							
			633	CS		0.00	0.00
SUBL FERRARI FEE FOR CLASSICHE CERTIFICATION, AS PER ACTUAL PRICE LIST.						5904.78	5904.78
PARTS: 0.00 LABOR: 0.00 OTHER: 5904.78					TOTAL LINE C:		5904.78

24443
COMING FROM PREVIOUS RO:55708.
FERRARI FEE HAS BEEN CHARGED AS PER ACTUAL PRICE LIST.

DESCRIPTION	TOTALS
*SHOP SUPPLY COSTS:	
We have added a charge of 15% of labor with a minimum of \$4.75 and not to exceed \$89.95 for shop supplies used in connection with this repair.	
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: F4830
UNIT# 330

55806

INVOICE

PAGE 2



FERRARI OF HOUSTON

6100 Southwest FWY
Houston TX 77057
(713) 772-3868
www.ferrariofhouston.com

SERVICE ADVISOR: 621 GIUSEPPE DIBLASIO

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
SILVER	65	FERRARI 330 GTC	XXXXXXXXXXXX7119	330GT	24443/24445	T509	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN65 DD		01JAN1965	16:30	15JUL22		CASH	20JUL22
R.O. OPENED	READY	OPTIONS:					
09:34	29JUN22	11:56	20JUL22				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

IT IS POSSIBLE THAT FERRARI WILL INCREASE THIS FEE DURING THE PROCESS OF EVALUATION FOR THE CLASSICHE CERTIFICATION. THE DIFFERENCE WILL BE CHARGED ACCORDINGLY, IF THERE I'LL BE ANY.

D EXHAUST: RE-INSTALL ORIGINAL EXHAUST SYSTEM AS PER CLASSICHE REQUEST.
504 071522. EXHAUST.

633 CS		2520.00	2520.00
1 11130041 4L G48 READYMIX BLUE/GRN	37.80	37.80	37.80
1 FR0704 RH DOWNPIPE330 GT	1982.00	1982.00	1982.00
1 FR0714 LH DOWNPIPE 330GT	1982.00	1982.00	1982.00
1 FR07025 RH CENTRAL MUFFLER 330GT	2819.73	2819.73	2819.73
1 FR07035 LH CENTRAL MUFFLER 330GT	2819.73	2819.73	2819.73
1 FR0727 RH TAILPIPE330GT	2208.00	2208.00	2208.00
1 FR0737 LH TAILPIPE 330GT	2208.00	2208.00	2208.00
4 20268 GASKET	34.18	34.18	136.72
24 16315720 STRAP HANGER	34.56	34.56	829.44
2 5057 57MM CLAMP	20.72	20.72	41.44
4 5345 45MM CLAMP	23.01	23.01	92.04
4 147630 2EA GASKET	53.22	53.22	212.88
4 147631 GASKET	39.88	39.88	159.52

PARTS: 15529.30 LABOR: 2520.00 OTHER: 0.00 TOTAL LINE D: 18049.30
24443 AS PER CLASSICHE REQUESTED AND AS PER CUSTOMER AUTHORIZATION;
WE REMOVE EXHAUST AND REPLACED WITH THE ORIGINAL EXHAUST; FABRICATED A HEAT SHIELD FOR THE LEFT AND RIGHT HAND EXHAUST.

E LIGHTS: RE-INSTALL ORIGINAL REVERSE LIGHT AS PER CLASSICHE REQUEST.
305 072022. LIGHTS.

633 CS		630.00	630.00
1 FR275081 REVERSE LAMP	929.60	929.60	929.60

PARTS: 929.60 LABOR: 630.00 OTHER: 0.00 TOTAL LINE E: 1559.60
24443 FABRICATE A BRACKET TO INSTALL THE BACK UP LIGHT AND RECONNECTED ELECTRICAL CONNECTION; REVERSE LIGHT IS NOT WORKING CHECK WIRING AND FOUND THAT THERE IS NO POWER GOING IN TO THE REVERSE SWITCH; WILL NEED MORE TIME TO CHECK ELECTRICAL WIRING HARNESS; CUSTOMER WILL

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

*SHOP SUPPLY COSTS:	DESCRIPTION	TOTALS
We have added a charge of 15% of labor with a minimum of \$4.75 and not to exceed \$89.95 for shop supplies used in connection with this repair.	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES *	
	TOTAL CHARGES	
ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001: The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

CUSTOMER #: F4830
 UNIT# 330

55806

INVOICE

PAGE 3



FERRARI OF HOUSTON

6100 Southwest FWY
 Houston TX 77057
 (713) 772-3868
 www.ferrariofhouston.com

SERVICE ADVISOR: 621 GIUSEPPE DIBLASIO

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
SILVER	65	FERRARI 330 GTC	XXXXXXXXXXXX7119	330GT	24443/24445	T509	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN65 DD		01JAN1965	16:30 15JUL22			CASH	20JUL22
R.O. OPENED	READY	OPTIONS:					
09:34 29JUN22	11:56 20JUL22						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

BRING THE CAR BACK FOR FURTHER DIAGNOSIS.

F** TRIM: CUSTOMER APPROVED REPLACEMENT OF BOTH DOORS AND TRUNK SEALS.
 602 071522. TRIM.

633 CS					1470.00	1470.00
1 16315190 LID SEAL					97.44	97.44
2 16315160 DOOR SEAL					201.72	403.44
PARTS: 500.88	LABOR: 1470.00	OTHER: 0.00	TOTAL LINE F:			1970.88

24443 REPLACED ALL RIPPED OFF DOOR WEATHER STRIPS ON BOTH DOORS AND
 ALSO REPLACED OLD TRUNK SEAL AS PER CUSTOMER AUTHORIZATION

CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 89.95

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

***SHOP SUPPLY COSTS:**
 We have added a charge of 15% of labor with a minimum of \$4.75 and not to exceed \$89.95 for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	5670.00
PARTS AMOUNT	17516.23
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	5904.78
MISC. CHARGES *	89.95
TOTAL CHARGES	29180.96
LESS INSURANCE	0.00
SALES TAX	1452.51
PLEASE PAY THIS AMOUNT	30633.47

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

NOTICE OF WORKER'S LIEN PURSUANT TO TEXAS PROPERTY CODE s. 70.001: The undersigned, being the person who has paid for repairs to the vehicle described in this Repair Invoice, understands that if the Dealership relinquishes possession of the vehicle in return for payment via a check, money order or credit card transaction that is stopped or dishonored due to insufficient funds, no funds, or because the account does not exist or has been closed, the worker's lien continues to exist and the Dealership is entitled to possession of the vehicle in accordance with S. 9.609 of the Texas Business & Commerce Code until the amount due is paid.

CUSTOMER COPY