

CUSTC	YEAR: 1988	TRANS/DRIVE: MANUAL/
Work:	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
	VIN: WBSDC9308J2791711	MILES IN/MILES 81273/81295
	ENGINE: 3.5 S38	

In: 11/6/2020 Out: 11/6/2020 Email:

<b>VEHICLE ISSUE #1: VEHICLE TOWED IN: VEHICLE HAS BEEN SITTING FOR YEARS. GET VEHICLE RUNNING AND SAFETY</b>				
PART: 61 21 6 946 334	BATTERY 90AH	1 @ \$235.95	\$235.95	NEW
LABOR:	CHECKED AND FOUND VEHICLE BATTERY IS COMPLETELY DEAD. REPLACED BATTERY WITH NEW BATTERY AND ADDED 2 GALLONS OF FRESH FUEL TO TANK. FUEL SMELLS LIKE VARNISH. FOUND VEHICLE WOULD NOT START. WITH ASSISTANCE SPRAYED INTAKE WITH STARTING FLUID AND FOUND ENGINE STARTED. FOUND ENGINE IS RUNNING VERY ROUGH. CHECKED AND FOUND FUEL INJECTOR #4 AND #6 STICKING. PUT INJECTOR CLEANER IN FUEL AND TAPPED ON FUEL INJECTORS. FOUND ENGINE SMOOTHED OUT. FOUND FUEL IS LEAKING FROM FUEL FEED LINE AT BODY TO FUEL RAIL. REPLACED LEAKING RUBBER HOSE AND RECHECKED FOUND NO FUEL LEAKS PRESENT AND ENGINE IS RUNNING SMOOTHER. CHECKED ALL FLUIDS AND FOUND OK. ALLOWED VEHICLE TO RUN FOR A WHILE AND RECHECKED EVERYTHING. FOUND NORMAL OPERATION. RECOMMEND ADD FRESH FUEL, PERFORMING OIL CHANGE, BRAKE FLUID FLUSH AND RECHECKING.		\$684.00	LABOR
Total for "VEHICLE TOWED IN: VEHICLE HAS BEEN SITTING FOR YEARS. GET VEHICLE RUNNING AND SAFETY			\$919.95	
<b>VEHICLE ISSUE #2:</b>				
LABOR:	CHECKED & INFLATE TIRES TO THE RECOMMENDED TIRE PRESSURES & CHECKED TIRE TREAD DEPTHS PER CALIFORNIA AIR RESOURCES BOARD TIRE PRESSURE REGULATION & MANUFACTURES RECOMMENDATIONS. FRONT TIRES: 32 PSI, REAR TIRES: 32 PSI		\$0.00	LABOR
Total for "":			\$0.00	
<b>VEHICLE ISSUE #3:</b>				
Total for "":			\$0.00	
<b>VEHICLE ISSUE #4:</b>				
LABOR:	IT IS WITH EVERY EFFORT THAT WE WANT YOU TO KNOW HOW MUCH WE APPRECIATE YOUR PATRONAGE. AS OUR VALUED CUSTOMER WE WANT TO BE SURE TO GO ABOVE AND BEYOND TO MAKE SURE THINGS ARE DONE RIGHT THE FIRST TIME AND THAT WE FOLLOW THROUGH ON ALL OUR PROMISES, AS WE STRIVE FOR "EXCEPTIONAL" SERVICE. THANK YOU FOR THE OPPORTUNITY TO SERVICE YOUR VEHICLE! ***WE VALUE YOUR BUSINESS***		\$0.00	LABOR

Recommended Repairs:  Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Labor/Jobs	\$2,819.52
	Parts	\$3,689.24
	Sublet	\$1,185.00
	Total Fees	\$24.50
	Subtotal	\$7,419.95
	Tax @ 8.75%	\$322.81
	Total	\$7,718.26
	Payments	\$8,041.07
	Balance	-\$322.81

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022



# INVOICE

CUSTC	YEAR: 1988	TRANS/DRIVE: MANUAL/
Work:	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
	VIN: WBSDC9308J2791711	MILES IN/OUT: 81273 81295
	ENGINE: 3.5 S38	

		Total for "": \$0.00
VEHICLE ISSUE #5:		

		Total for "": \$0.00
VEHICLE ISSUE #6: EMISSION TEST DUE, CHECK AND REPORT		

SUBLET	GAS	\$90.00	SUBLET
--------	-----	---------	--------

		Total for "EMISSION TEST DUE, CHECK AND REPORT": \$90.00
VEHICLE ISSUE #7: ALL RUBBER FUEL HOSES FRONT AND BACK, FUEL FILTER, FRESH FUEL		

PART: 13 32 1 270 038	FUEL FILTER KL 9	1 @ \$64.95	\$64.95	NEW
PART: 13 53 1 469 783	8MM UPDATED FUEL HOSE	6 @ \$17.67	\$106.02	NEW
PART: 13 53 1 726 960	BENT FUEL HOSE	1 @ \$12.46	\$12.46	NEW
PART: 07 12 9 952 102	HOSE CLAMP	10 @ \$3.49	\$34.90	NEW
PART: 13 31 1 272 750	6MM FUEL HOSE/FT	6 @ \$7.28	\$43.68	NEW
PART: 07 12 9 952 102	HOSE CLAMP	6 @ \$3.49	\$20.94	NEW
LABOR:	REPLACE ALL RUBBER FUEL HOSES AND CLAMPS IN ENGINE COMPARTMENT AND AT FUEL TANK, AND ALL FUEL EVAP SYSTEM HOSES, REPLACE FUEL FILTER, DRAIN FUEL TANK AND FILL WITH NEW FUEL, LEAK CHECK SYSTEM, OK.		\$684.00	LABOR
SUBLET	GAS		\$50.00	SUBLET

		Total for "ALL RUBBER FUEL HOSES FRONT AND BACK, FUEL FILTER, FRESH FUEL": \$1,016.95
VEHICLE ISSUE #8: ENGINE OIL AND FILTER		

PART: 11 42 9 063 138	OIL FILTER OX 41D	1 @ \$17.95	\$17.95	NEW
PART: MOTUL	MOTUL 5W-40 8100 X-CESS ENGINE OIL	6 @ \$10.97	\$65.82	NEW
PART: 796.1001.55	MULTI-PURPOSE SOLVENT	0.5 @ \$10.75	\$5.38	NEW
PART: 13 72 1 307 259	AIR FILTER M5 M6	1 @ \$99.44	\$99.44	NEW

Recommended Repairs:	Labor/Jobs	\$2,819.52
	Parts	\$3,689.24
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$1,185.00
	Total Fees	\$24.50
	Subtotal	\$7,419.95
	Tax @ 8.75%	\$322.81
	Total	\$7,718.26
	Payments	\$8,041.07
	Balance	-\$322.81

Replaced parts may be requested by customer, I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022



# INVOICE

CUSTC	YEAR: 1988	TRANS/DRIVE: MANUAL/
Work:	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
	VIN: WBSDC9308J2791711	MILES IN/OUT: 81273 81295
	ENGINE: 3.5 S38	

PART: 11 61 1 306 724	INTAKE AIR BOOT M5 M6	1 @ \$79.95	\$79.95	NEW
LABOR:	PERFORM 81K SERVICE, ROAD TEST VEHICLE TO WARM OIL AND CHECK FOR ANY DRIVABILITY ISSUES OR NOISES. RACK VEHICLE AND DRAINED ENGINE OIL. INSTALLED NEW SEAL RING ON DRAIN PLUG, INSTALLED THE OIL FILTER, FILL WITH OIL TO PROPER LEVEL. CHECK ALL FLUID LEVELS. INSPECT ACCESSORY FAN BELTS, COOLING SYSTEM HOSES AND CONDITION OF COOLANT. CHECK CONDITION OF BRAKES, SUSPENSION, TIRES AND SET TIRE PRESSURES. CHECK OPERATION OF ALL EXTERIOR LIGHTS. ADVISE OF ANY NEEDED OR RECOMMENDED REPAIRS. SEE ATTACHED SERVICE CHECK SHEET.		\$85.00	LABOR

Total for "ENGINE OIL AND FILTER": \$353.54

VEHICLE ISSUE #9: FRONT BRAKE SERVICE				
PART: 34 35 1 179 820	BRAKE SENSOR	1 @ \$19.07	\$19.07	NEW
PART: 796.1001.55	MULTI-PURPOSE SOLVENT	1 @ \$10.75	\$10.75	NEW
PART: 34 11 2 225 007	FRONT BRAKE ROTOR	2 @ \$205.99	\$411.98	NEW
PART: 34 11 2 226 009	FRONT BRAKE PAD SET	1 @ \$123.95	\$123.95	NEW
LABOR:	RAISE VEHICLE AND REMOVE FRONT WHEELS. REMOVE CALIPERS FROM SPINDLE ASSEMBLIES AND REMOVE OLD BRAKE PADS. REMOVE BRAKE ROTORS FROM HUB ASSEMBLIES. REPLACE ROTORS, REINSTALL ONTO HUB ASSEMBLIES, CLEAN AND LUBRICATE CALIPER PIVOT AND MOUNTING POINTS, AND INSTALL NEW BRAKE PADS AND SENSORS INTO CALIPERS. INSTALL CALIPERS ON SPINDLES AND TORQUE CALIPER BOLTS TO MANUFACTURES SPECIFICATIONS. INSTALL WHEEL ASSEMBLIES AND TORQUE LUG NUTS TO MANUFACTURES SPECIFICATIONS. ROAD TEST TO VERIFY BRAKE PERFORMANCE AND TO SEAT IN NEW BRAKE PADS.		\$342.00	LABOR

Total for "FRONT BRAKE SERVICE": \$907.75

VEHICLE ISSUE #10: REAR BRAKE SERVICE				
PART: 34 21 2 226 013	REAR BRAKE PAD SET	1 @ \$94.75	\$94.75	NEW
PART: 34 21 1 162 968	REAR BRAKE ROTOR	2 @ \$92.95	\$185.90	NEW

Recommended Repairs:	Labor/Jobs	\$2,819.52
	Parts	\$3,689.24
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$1,185.00
	Total Fees	\$24.50
	Subtotal	\$7,419.95
	Tax @ 8.75%	\$322.81
	Total	\$7,718.26
	Payments	\$8,041.07
	Balance	-\$322.81

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022



# INVOICE

CUSTC	YEAR: 1988	TRANS/DRIVE: MANUAL/	LICENSE/STATE: 6YQJ341/
Work:	MAKE/MODEL: BMW M5 BASE	MILES IN/OUT: 81273 81295	
	VIN: WBSDC9308J2791711		
	ENGINE: 3.5 S38		

PART: 34 35 1 179 821	BRAKE SENSOR	1 @ \$10.85	\$10.85	NEW
PART: 796.1001.55	MULTI-PURPOSE SOLVENT	1 @ \$10.75	\$10.75	NEW
PART: 34 21 1 153 199	ANTI RATTLE CLIP	2 @ \$15.95	\$31.90	NEW
LABOR:	RAISE VEHICLE AND REMOVE REAR WHEELS. REMOVE CALIPERS FROM CALIPER MOUNTS AND REMOVE OLD BRAKE PADS AND ROTORS. CLEAN AND LUBRICATE CALIPER PIVOT AND MOUNTING POINTS AND INSTALL NEW BRAKE ROTORS AND PADS IN CALIPERS. INSTALL CALIPERS ON CALIPER MOUNTS AND TORQUE CALIPER BOLTS TO MANUFACTURES SPECIFICATIONS. ADJUST E BRAKE IF POSSIBLE. INSTALL WHEEL ASSEMBLIES AND TORQUE LUG NUTS		\$342.00	LABOR

Total for "REAR BRAKE SERVICE": \$676.15

VEHICLE ISSUE #11: BIENNIAL BRAKE FLUID FLUSH				
PART: BRAKE FLUID	BRAKE FLUID DOT4 SL6	4 @ \$11.95	\$47.80	NEW
PART: 796.1001.55	MULTI-PURPOSE SOLVENT	1 @ \$10.75	\$10.75	NEW
LABOR:	PERFORMED BRAKE FLUID EXCHANGE, ACTIVATED ABS PUMP, ROAD TESTED, RECHECKED, OK. RESET SERVICE INDICATOR		\$171.00	LABOR

Total for "BIENNIAL BRAKE FLUID FLUSH": \$229.55

VEHICLE ISSUE #12: DRIVESHAFT ASSEMBLY, EXHAUST GASKETS AND HARDWARE				
PART: 26 11 2 225 125	DRIVESHAFT	1 @ \$1,353.75	\$1,353.75	NEW
PART: 11 76 1 308 686	EXHAUST GASKET M3 M5	2 @ \$23.95	\$47.90	NEW
PART: 11 62 1 259 559	10MM COPPER LOCK	4 @ \$2.29	\$9.16	NEW
PART: 18 21 1 105 635	MUFFLER HANGER	2 @ \$12.95	\$25.90	NEW
LABOR:	REMOVE EXHAUST SYSTEM AND HEAT SHIELDS, REMOVE WORN DRIVE-SHAFT. INSTALL NEW DRIVE SHAFT ASSEMBLY, INSTALL HEAT SHIELDS, INSTALL EXHAUST WITH NEW GASKETS AND RUBBER EXHAUST HANGERS, ROAD TEST VEHICLE, NO MORE VIBRATION, NORMAL OPERATION RESTORED.		\$513.00	LABOR

Total for "DRIVESHAFT ASSEMBLY, EXHAUST GASKETS AND HARDWARE": \$1,949.71

VEHICLE ISSUE #13: FOUR NEW TIRES AND FOUR NEW WHEEL CENTER CAPS & ALIGNMENT				
--	--	--	--	--

<p>Recommended Repairs:</p>	Labor/Jobs	\$2,819.52
	Parts	\$3,689.24
	Sublet	\$1,185.00
	Total Fees	\$24.50
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Subtotal	\$7,419.95
	Tax @ 8.75%	\$322.81
	Total	\$7,718.26
	Payments	\$8,041.07
	Balance	-\$322.81

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022

# INVOICE

CUSTC	YEAR: 1988	1988	TRANS/DRIVE: MANUAL/
	MAKE/MODEL: BMW M5 BASE		LICENSE/STATE: 6YQJ341/
Work:	VIN: WBSDC9308J2791711		MILES IN/OUT: 81273 81295
	ENGINE: 3.5 S38		

PART: 36 13 2 225 376	HUBCAP 171MM	4 @ \$126.66	\$506.64	NEW
SUBLET	NEW TIRES: FOUR NEW TIRES "AMERICAS TIRE" CONTI-EXTEREME CONTACT DWS06 PLUS 225/50/16		\$850.00	SUBLET
SUBLET	4 WHEEL ALIGNMENT		\$195.00	SUBLET

Total for "FOUR NEW TIRES AND FOUR NEW WHEEL CENTER CAPS & ALIGNMENT": \$1,551.64

Payment Rec'd	Credit Card Visa	Date: 8/13/2021	\$8,041.07
7/13/2021 11:17:00 AM - dantep	PHONE, , 6000		
4/28/2022 9:46:03 AM - BRANDON BAUGHMAN	AN EMAIL UPDATE WAS SENT TO		

Recommended Repairs:	Labor/Jobs	\$2,819.52
	Parts	\$3,689.24
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$1,185.00
	Total Fees	\$24.50
	Subtotal	\$7,419.95
	Tax @ 8.75%	\$322.81
	Total	\$7,718.26
	Payments	\$8,041.07
	Balance	-\$322.81

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_

Date 4/28/2022





**Customer:**

**Vehicle:**

1988 Bmw M5 RWD  
 Eng: 3.5 S38 Tran: Manual  
 VIN: WBSDC9308J2791711  
 Mileage In: 81235 Out: 81262  
 P Date: Clr: BLACK  
 Lic: 6YQJ341 St: MA

**Repair Order:**

Service Writer: J Clausen  
 PO Number:  
 Date In: 06/01/2018  
 Date Out: 06/29/2018

**Maintenance: BMW**

**Customer Concern:** VEHICLE HAS BEEN SITTING FOR 2 YEARS,  
 CHANGE ENGINE OIL AND FILTER, PERFORM VEHICLE INSPECTION.

Labor:	Description	Techs	Extended
	ROAD TEST VEHICLE TO WARM OIL AND CHECK FOR ANY DRIVABILITY ISSUES OR NOISES.	MM	300.00
	RACK VEHICLE AND REMOVE ENGINE OIL DRAIN PLUG. REMOVE AND REPLACE W/NEW, ENGINE OIL FILTER AND LUBRICATE CHASSIS AS NEEDED. CHECK ALL FLUID LEVELS. INSPECT AIR FILTER, ACCESSORY FAN BELTS, COOLING SYSTEM HOSES AND CONDITION OF COOLANT. CHECK CONDITION OF TIRES AND SET TIRE PRESSURES. CHECK OPERATION OF ALL EXTERIOR LIGHTS. ADVISE OF ANY NEEDED OR RECOMMENDED REPAIRS.		

**Labor Sub Total:** 300.00

Parts:	Part Num	Cond	Description	Price Ea.	Qty	Extended
	11 42 9 063 138	N	OIL FILTER OX 41D	17.95	1.00	17.95
	TOTAL	N	5W-30 LOW SAPS SYNTHETIC OIL	10.97	6.00	65.82
	796.1001.85	N	MULTI-PURPOSE SOLVENT	10.75	0.50	5.38

**Parts Sub Total:** 89.15

Sublets:	Description	Extended
	STEAM CLEAN ENGINE & TRANSMISSION	350.00

**Sublets Sub Total:** 350.00

Misc:	Description	Sold Price	Qty	Extended
	FILTER DISPOSAL	2.80	1.00	2.80
	OIL DISPOSAL	1.50	6.00	9.00

**Misc Sub Total:** 11.80

**Job Sub Total:** 750.95

**Electrical**

By signing this final invoice, I have authorized the repair work listed hereon, including any sublet work, to be done along with necessary materials. I have also authorized any increase in price and repairs over the original estimate that may be noted elsewhere on this invoice. Fees may have been charged for hazardous waste disposal. Mservice has explained that the standard warranty for parts and labor is 24 months or 24,000 miles, whichever comes first from the date of this invoice. Specific part(s) may have longer warranty period and may be noted elsewhere on this invoice. In the event a warranty issue occurs, the vehicle must be returned to Mservice for repairs. Mservice cannot be held liable for any additional costs outside of the original repairs. In the event it is necessary to retain an attorney to collect for the services and goods shown on this invoice, the repair facility will be entitled to a reasonable attorney fee in addition to its court cost. I acknowledge receipt of the vehicle in good condition and a copy of this Repair Order.

**Parts:** 1493.52  
**Labor:** 1815.00  
**Sublets:** 686.00  
**Misc:** 23.80  
**Subtotal:** 4018.32  
**Sales Tax:** 123.21

NOTICE TO CUSTOMER--PLEASE READ IMPORTANT INFORMATION ON BACK!

Customer Signature

Date

**TOTAL:** 4141.53  
**Balance:** 4141.53



**Customer:**

**Vehicle:**

1988 Bmw M5 RWD  
 Eng: 3.5 S38 Tran: Manual  
 VIN: WBSDC9308J2791711  
 Mileage In: 81235 Out: 81262  
 P Date: Clr: BLACK  
 Lic: 6YQJ341 St: MA

**Repair Order:**

Service Writer: J Clausen  
 PO Number:  
 Date In: 06/01/2018  
 Date Out: 06/29/2018

**Customer Concern:** REMOVE CLUSTER & SEND OUT FOR ODOMETER REPAIR

Labor:	Description	Techs	Extended
	REMOVED THE INSTRUMENT CLUSTER, SEND OUT FOR REPAIR OF ODOMETER GEARS. REINSTALLED, ROAD TESTED, RECHECKED, OK	DP	315.00
<b>Labor Sub Total:</b>			315.00
Sublets:	Description	Extended	
	REPAIR ODOMETER GEARS		336.00
<b>Sublets Sub Total:</b>			336.00
<b>Job Sub Total:</b>			651.00

**Windshield/Wipers**

**Customer Concern:** REPLACE WIPER BLADES

Labor:	Description	Techs	Extended			
	INSTALLED THE NEW WIPER BLADES	DP	0.00			
<b>Labor Sub Total:</b>			0.00			
Parts:	Part Num	Cond	Description	Price Ea.	Qty	Extended
	WS 18	N	WIPER BLADE	19.93	2.00	39.86
<b>Parts Sub Total:</b>						39.86
<b>Job Sub Total:</b>						39.86

**Brakes**

**Customer Concern:** REPLACE FRONT BRAKES COMPLETE

Labor:	Description	Techs	Extended			
	RAISE VEHICLE AND REMOVE FRONT WHEELS. REMOVE CALIPERS FROM SPINDLE ASSEMBLIES AND REMOVE OLD BRAKE PADS. REMOVE BRAKE ROTORS FROM HUB ASSEMBLIES. REPLACE ROTORS, REINSTALL ONTO HUB ASSEMBLIES, CLEAN AND LUBRICATE CALIPER PIVOT AND MOUNTING POINTS, AND INSTALL NEW BRAKE PADS AND SENSORS INTO CALIPERS. INSTALL CALIPERS ON SPINDLES AND TORQUE CALIPER BOLTS TO MANUFACTURES SPECIFICATIONS. INSTALL WHEEL ASSEMBLIES AND TORQUE LUG NUTS TO MANUFACTURES SPECIFICATIONS. ROAD TEST TO VERIFY BRAKE PERFORMANCE AND TO SEAT IN NEW BRAKE PADS.	BJ	300.00			
	AFTER THE FRONT BRAKES WERE REPLACED THE SHAKING UNDER BRAKING IS MUCH BETTER. THE REMAINING PULSATION IS FROM THE REAR BRAKES, THE CUSTOMER HAS BEEN ADVISED OF THIS	BJ	0.00			
<b>Labor Sub Total:</b>			300.00			
Parts:	Part Num	Cond	Description	Price Ea.	Qty	Extended
	34 11 2 225 007	N	FRONT BRAKE ROTOR	156.18	2.00	312.36
	34 11 2 226 009	N	FRONT BRAKE PAD SET	112.95	1.00	112.95





**Customer:**

**Vehicle:**

1988 Bmw M5 RWD  
 Eng: 3.5 S38 Tran: Manual  
 VIN: WBSDC9308J2791711  
 Mileage In: 81235 Out: 81262  
 P Date: Clr: BLACK  
 Lic: 6YQJ341 St: MA

**Repair Order:**

Service Writer: J Clausen  
 PO Number:  
 Date In: 06/01/2018  
 Date Out: 06/29/2018

34 35 1 179 820	N	BRAKE SENSOR	19.07	1.00	19.07
796.1001.55	N	MULTI-PURPOSE SOLVENT	10.75	1.00	10.75
<b>Parts Sub Total:</b>					<b>455.13</b>
<b>Job Sub Total:</b>					<b>755.13</b>

**Body**

**Customer Concern:** REPLACE HOOD BADGE

Labor:	Description	Techs	Extended
	INSTALLED NEW HOOD EMBLEM	BJ	0.00
<b>Labor Sub Total:</b>			<b>0.00</b>

Parts:	Part Num	Cond	Description	Price Ea.	Qty	Extended
	51 14 8 132 375	N	ROUNDEL EMBLEM	46.95	1.00	46.95
<b>Parts Sub Total:</b>						<b>46.95</b>
<b>Job Sub Total:</b>						<b>46.95</b>

**Brakes: BMW**

**Customer Concern:** PERFORM BRAKE FLUSH

Labor:	Description	Techs	Extended
	PERFORMED BRAKE FLUID EXCHANGE, ACTIVATED ABS PUMP, ROAD TESTED, RECHECKED, OK	BJ	150.00
<b>Labor Sub Total:</b>			<b>150.00</b>

Parts:	Part Num	Cond	Description	Price Ea.	Qty	Extended
	BRAKE FLUID	N	BRAKE FLUID DOT4 SL6	10.95	4.00	43.80
	796.1001.55	N	MULTI-PURPOSE SOLVENT	10.75	1.00	10.75
<b>Parts Sub Total:</b>						<b>54.55</b>

Misc:	Description	Sold Price	Qty	Extended
	BRAKE FLUID DISPOSAL	2.00	4.00	8.00
<b>Misc Sub Total:</b>				<b>8.00</b>
<b>Job Sub Total:</b>				<b>212.55</b>

**Cooling System: BMW**

**Customer Concern:** REPLACE ALL COOLANT HOSES

Labor:	Description	Techs	Extended
	REPLACED ALL COOLANT HOSES, FLUSHED COOLANT SYSTEM, ROAD TESTED, RECHECKED, OK	BJ	750.00







RO#: 1030964  
 Invoiced: 06/29/2018

Page: 4

**Customer:**

**Vehicle:**

1988 Bmw M5 RWD  
 Eng: 3.5 S38 Tran: Manual  
 VIN: WBSDC9308J2791711  
 Mileage In: 81235 Out: 81262  
 P Date: Clr: BLACK  
 Lic: 6YQJ341 St: MA

**Repair Order:**

Service Writer: J Clausen  
 PO Number:  
 Date In: 06/01/2018  
 Date Out: 06/29/2018

Parts:	Part Num	Cond	Description	Price Ea.	Qty	Extended
	11 53 1 306 832	N	TOP HOSE E28 M5	62.22	1.00	62.22
	17 12 1 712 736	N	COOLANT HOSE 8X13MM	9.59	3.00	28.77
	11 53 1 307 324	N	PLASTIC 2X T E28 M5	20.95	1.00	20.95
	11 53 1 306 851	N	EXPAN/HOSE E28 M5	60.95	1.00	60.95
	64 21 1 374 635	N	HEATER HOSE E28 M5	37.95	1.00	37.95
	11 53 1 272 866	N	WATER HOSE TEE	15.95	1.00	15.95
	11 53 1 306 850	N	HOUS/HOSE E28 M5 M6	58.95	1.00	58.95
	11 53 1 306 829	N	PIPE HOSE E28 M5	42.95	1.00	42.95
	11 53 1 310 625	N	LOWER HOSE E28 M5	64.95	1.00	64.95
	11 53 1 306 827	N	W/RAIL HOSE E28 M5	42.95	1.00	42.95
	64 21 1 374 636	N	HEATER HOSE INLET 1	52.95	1.00	52.95
	64 21 1 374 637	N	HEATER HOSE INLET 2	32.95	1.00	32.95
	11 53 1 306 828	N	WATER PUMP HOSE E28 M5	23.95	1.00	23.95
	HC 8 12	N	HOSE CLAMP	2.95	8.00	23.60
	HC 20 32	N	HOSE CLAMP	2.19	3.00	6.57
	HC 32 50	N	HOSE CLAMP	2.95	5.00	14.75
	HC 12 20	N	HOSE CLAMP	2.10	6.00	12.60
	82 14 1 467 704	N	1/2G BMW ANTIFREEZE	21.95	2.00	43.90
	796.1001.55	N	MULTI-PURPOSE SOLVENT	10.75	2.00	21.50
	17 11 1 468 071	N	RADIATOR CAP 1.4	19.95	1.00	19.95
	13 41 1 310 699	N	3WAY IDLE HOSE	80.95	1.00	80.95
	11 61 1 305 124	N	INTAKE O RING	6.27	6.00	37.62
			<b>Parts Sub Total:</b>			<b>607.88</b>
Misc:	Description			Sold Price	Qty	Extended
	COOLANT DISPOSAL			2.00	2.00	4.00
						<b>Misc Sub Total: 4.00</b>
						<b>Job Sub Total: 1561.88</b>

**Tire Inflation Service**

Labor:	Description	Techs	Extended
	CHECKED & INFLATE TIRES TO THE RECOMMENDED TIRE PRESSURES & CHECKED TIRE TREAD DEPTHS PER CALIFORNIA AIR RESOURCES BOARD TIRE PRESSURE REGULATION & MANUFACTURES RECOMMENDATIONS. FRONT TIRES: 36 PSI, REAR TIRES:36 PSI	BJ	0.00
			<b>Labor Sub Total: 0.00</b>
			<b>Job Sub Total: 0.00</b>

**Recommended Service**

**Recommendation:** FRONT BRAKE PADS 11MM THICK. REAR BRAKE PADS 7MM THICK. SLIGHT VIBRATION FELT WHILE BRAKING, FRONT BRAKES ARE NEW. BRAKE FLUID FLUSHED 06/2018. OIL LEAKING FROM V/C GASKET & CAM PLATE AT REAR OF HEAD & DISTRUBUTER SEAL. CLUTCH PEDAL STIFF, GEAR BOX IS NOISY. REAR TRANSMISSION SEALS LEAKING. FLEX DISC VERY CRACKED, VIBRATION FELT ON ACCELERATION, DRIVESHAFT U JOINTS MIGHT BE LOCKED UP. REAR SUB FRAME BUSHINGS WORN & CRACKED. ODOMETER





RO#: 1030964  
 Invoiced: 06/29/2018

Page: 5

**Customer:**

**Vehicle:**

**Repair Order:**

1988 Bmw M5 RWD  
 Eng: 3.5 S38 Tran: Manual  
 VIN: WBSDC9308J2791711  
 Mileage In: 81235 Out: 81262  
 P Date: Clr: BLACK  
 Lic: 6YQJ341 St: MA

Service Writer: J Clausen  
 PO Number:  
 Date In: 06/01/2018  
 Date Out: 06/29/2018

INOP. TIRES DATED 2005. A/C SYSTEM IS R12, INOP. MINOR CRACKS ON ALTERNATOR BELT.

**Job Sub Total:** 0.00

**THANK YOU**

Labor:	Description	Techs	Extended
	IT IS WITH EVERY EFFORT THAT WE WANT YOU TO KNOW HOW MUCH WE APPRECIATE YOUR PATRONAGE. AS OUR VALUED CUSTOMER WE WANT TO BE SURE TO GO ABOVE AND BEYOND TO MAKE SURE THINGS ARE DONE RIGHT THE FIRST TIME AND THAT WE FOLLOW THROUGH ON ALL OUR PROMISES, AS WE STRIVE FOR "EXCEPTIONAL" SERVICE. THANK YOU FOR THE OPPORTUNITY TO SERVICE YOUR VEHICLE!. ***WE VALUE YOUR BUSINESS***	MM	0.00

**Labor Sub Total:** 0.00

**Job Sub Total:** 0.00

**Contact Log**

As of 06/29/2018 at 3:36 pm

Date:	Time:	By:	Method:	# / Addr:	Auth By:	Additional Amt:	Revised Estimate:
06/01/2018	7:57 am	J Clausen	Phone			1000.00	1000.00





**INVOICE #1030945**

dante@mserviceinc.com

CUSTC	YEAR: 1988	TRANS/DRIVE: MANUAL/
Home:	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
	VIN: WBSDC9308J2791711	MILES IN/MILES /
	ENGINE: 3.5 S38	

In: 5/29/2018 Out: 5/29/2018 Email:

<b>VEHICLE ISSUE #1:</b>			
PART: 61 21 6 946 BATTERY 90AH 334	1 @ \$231.95	\$231.95	NEW
			Total for "": \$231.95
Payment Rec'd	Credit Card Visa	Date: 5/31/2018	\$253.09
4/28/2022 9:46:36 AM - BRANDON BAUGHMAN	AN EMAIL UPDATE WAS SENT TO		

Recommended Repairs:	Labor/Jobs	\$0.00
	Parts	\$231.95
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$0.00
	Total Fees	\$2.00
	Subtotal	\$216.81
	Tax @ 8.75%	\$19.14
	Total	\$233.95
	Payments	\$253.09
	Balance	-\$19.14

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_

Date 4/28/2022



CUST(	YEAR: 1988	TRANS/DRIVE: MANUAL/
Home:	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
	VIN: WBSDC9308J2791711	MILES IN/MILES 81235/81238
	ENGINE: 3.5 S38	

In: 12/21/2015 Out: 12/21/2015 Email:

VEHICLE ISSUE #1: PERFORM OIL & FILTER CHANGE				
PART: 11 42 9 063 138	OIL FILTER OX 41D	1 @ \$17.95	\$17.95	NEW
PART: TOTAL	5W-30 LOW SAPS SYNTHETIC OIL	6 @ \$10.97	\$65.82	NEW
LABOR:	ROAD TEST VEHICLE TO WARM OIL AND CHECK FOR ANY DRIVABILITY ISSUES OR NOISES. RACK VEHICLE AND REMOVE ENGINE OIL DRAIN PLUG. REMOVE AND REPLACE W/NEW, ENGINE OIL FILTER AND LUBRICATE CHASSIS AS NEEDED. CHECK ALL FLUID LEVELS. INSPECT AIR FILTER, ACCESSORY FAN BELTS, COOLING SYSTEM HOSES AND CONDITION OF COOLANT. CHECK CONDITION OF TIRES AND SET TIRE PRESSURES. CHECK OPERATION OF ALL EXTERIOR LIGHTS. ADVISE OF ANY NEEDED OR RECOMMENDED REPAIRS.		\$42.00	LABOR
			Total for "PERFORM OIL & FILTER CHANGE": \$125.77	

VEHICLE ISSUE #2:				
LABOR:	CHECKED & INFLATE TIRES TO THE RECOMMENDED TIRE PRESSURES & CHECKED TIRE TREAD DEPTHS PER CALIFORNIA AIR RESOURCES BOARD TIRE PRESSURE REGULATION & MANUFACTURES RECOMMENDATIONS. FRONT TIRES: 33 PSI, REAR TIRES: 33 PSI		\$0.00	LABOR
			Total for "": \$0.00	

VEHICLE ISSUE #3:				
			Total for "": \$0.00	

VEHICLE ISSUE #4: ORDER NEW KEY				
PART: 51 21 1 900 875	KEY NON LIGHTED - WITH KEY CODE	2 @ \$50.95	\$101.90	NEW
LABOR:	(2) NEW KEYS ORDERED		\$0.00	LABOR
			Total for "ORDER NEW KEY": \$101.90	

VEHICLE ISSUE #5:				
LABOR:	IT IS WITH EVERY EFFORT THAT WE WANT YOU TO KNOW HOW MUCH WE APPRECIATE YOUR PATRONAGE. AS OUR VALUED CUSTOMER WE WANT TO BE SURE TO GO ABOVE AND BEYOND TO MAKE SURE THINGS ARE DONE RIGHT THE FIRST TIME AND THAT WE FOLLOW THROUGH ON ALL OUR PROMISES, AS WE STRIVE FOR "EXCEPTIONAL" SERVICE. THANK YOU FOR THE OPPORTUNITY TO SERVICE YOUR VEHICLE! ***WE VALUE YOUR BUSINESS***		\$0.00	LABOR

Recommended Repairs:	Labor/Jobs	\$42.00
	Parts	\$185.67
	Sublet	\$0.00
	Total Fees	\$6.49
	Subtotal	\$224.87
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Tax @ 8.75%	\$15.78
	Total	\$234.16
	Payments	\$249.94
	Balance	-\$15.78

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022



# INVOICE

CUSTC	YEAR: 1988	1988	TRANS/DRIVE: MANUAL/
	MAKE/MODEL: BMW M5 BASE		LICENSE/STATE: 6YQJ341/
Home:	VIN: WBSDC9308J2791711		MILES IN/OUT: 81235 81238
	ENGINE: 3.5 S38		

			Total for "": \$0.00
Payment Rec'd	Credit Card Amex	Date: 12/23/2015	\$249.94
12/21/2015 8:36:00 AM - jim2	PHONE, , 150		
4/28/2022 9:46:51 AM - BRANDON BAUGHMAN	AN EMAIL UPDATE WAS SENT TO		

Recommended Repairs:	Labor/Jobs	\$42.00
	Parts	\$185.67
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$0.00
	Total Fees	\$6.49
	Subtotal	\$224.87
	Tax @ 8.75%	\$15.78
	Total	\$234.16
	Payments	\$249.94
	Balance	-\$15.78

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_

Date 4/28/2022



CUS1	YEAR: 1988	TRANS/DRIVE: MANUAL/
Home	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
	VIN: WBSDC9308J2791711	MILES IN/MILES 81231/81235
	ENGINE: 3.5 S38	

In: 12/2/2014 Out: 12/2/2014 Email:

VEHICLE ISSUE #1: WIPERS & TURN SIGNALS DONT WORK, CHECK & REPORT				
PART: 32 33 1 350 750	HORN CARBON CONTACT	1 @ \$15.70	\$15.70	NEW
LABOR:	VERIFIED THE WIPERS & TURN SIGNALS DO NOT WORK. CHECKED FUSE & IT WAS BLOWN. INSTALL THE NEW FUSE & IT BLEW RIGHT AWAY. REMOVED THE STEERING WHEEL, FOUND THE HORN CONTACT PIN SHORTED TO GROUND. INSTALLED THE NEW HORN CONTACT. REINSTALLED THE STEERING WHEEL, CHECKED OPERATION OF WIPERS & TURN SIGNALS & BOTH ARE WORKING CORRECTLY		\$420.00	LABOR
Total for "WIPERS & TURN SIGNALS DONT WORK, CHECK & REPORT": \$435.70				
VEHICLE ISSUE #2:				
LABOR:	CHECKED & INFLATE TIRES TO THE RECOMMENDED TIRE PRESSURES & CHECKED TIRE TREAD DEPTHS PER CALIFORNIA AIR RESOURCES BOARD TIRE PRESSURE REGULATION & MANUFACTURES RECOMMENDATIONS. FRONT TIRES:36 PSI, REAR TIRES: 41 PSI		\$0.00	LABOR
Total for "": \$0.00				
VEHICLE ISSUE #3:				
Total for "": \$0.00				
VEHICLE ISSUE #4: REPLACE RUBBER MUFFLER HANGERS AS NEEDED				
PART: 18 21 1 105 635	MUFFLER HANGER	2 @ \$10.95	\$21.90	NEW
LABOR:	INSTALLED (2) NEW RUBBER MUFFLER HANGERS		\$0.00	LABOR
Total for "REPLACE RUBBER MUFFLER HANGERS AS NEEDED": \$21.90				
VEHICLE ISSUE #5: PERFORM OIL & FILTER CHANGE				
PART: 11 42 9 063 138	OIL FILTER OX 41D	1 @ \$17.95	\$17.95	NEW
PART: TOTAL	5W-40 SYNTHETIC OIL	6 @ \$10.97	\$65.82	NEW
PART: 61 61 9 069 195	WIPER BLADE SET	1 @ \$39.95	\$39.95	NEW

Recommended Repairs:	Labor/Jobs	\$1,862.00
	Parts	\$310.02
Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.	Sublet	\$0.00
	Total Fees	\$14.27
	Subtotal	\$2,174.21
	Tax @ 8.75%	\$26.35
	Total	\$2,186.29
	Payments	\$2,212.64
	Balance	-\$26.35

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022



# INVOICE

CUSTC	YEAR: 1988	TRANS/DRIVE: MANUAL/
	MAKE/MODEL: BMW M5 BASE	LICENSE/STATE: 6YQJ341/
Home:	VIN: WBSDC9308J2791711	MILES IN/OUT: 81231 81235
	ENGINE: 3.5 S38	

LABOR:	ROAD TEST VEHICLE TO WARM OIL AND CHECK FOR ANY DRIVABILITY ISSUES OR NOISES. RACK VEHICLE AND REMOVE ENGINE OIL DRAIN PLUG. REMOVE AND REPLACE W/NEW, ENGINE OIL FILTER AND LUBRICATE CHASSIS AS NEEDED. CHECK ALL FLUID LEVELS. INSPECT AIR FILTER, ACCESSORY FAN BELTS, COOLING SYSTEM HOSES AND CONDITION OF COOLANT. CHECK CONDITION OF TIRES AND SET TIRE PRESSURES. CHECK OPERATION OF ALL EXTERIOR LIGHTS. ADVISE OF ANY NEEDED OR RECOMMENDED REPAIRS.	\$42.00	LABOR
LABOR:	ROTATED THE TIRES	\$0.00	LABOR
LABOR:	REPLACED WIPER BLADES	\$0.00	LABOR

Total for "PERFORM OIL & FILTER CHANGE": \$165.72

<b>VEHICLE ISSUE #6: PERFORM BRAKE FLUID FLUSH</b>				
PART: BRAKE FLUID	BRAKE FLUID DOT4 SL6	4 @ \$10.95	\$43.80	NEW
LABOR:	PERFORMED BRAKE FLUID EXCHANGE, ACTIVATED ABS PUMP, ROAD TESTED, RECHECKED, OK		\$140.00	LABOR

Total for "PERFORM BRAKE FLUID FLUSH": \$183.80

<b>VEHICLE ISSUE #7: PERFORM COOLANT FLUSH</b>				
PART: 82 14 1 467 704	1/2G BMW ANTIFREEZE	2 @ \$21.95	\$43.90	NEW
PART: 5581	COOLANT SYSTEM CLEANING SOLUTION	1 @ \$47.00	\$47.00	NEW
LABOR:	PERFORM A VISUAL INSPECTION OF THE COOLING SYSTEM, PRESSURE CHECK-COOLING SYSTEM FOR LEAKS AND PRESSURE CHECK RADIATOR CAP. HOOK UP TO COOLANT EXCHANGE MACHINE, DRAIN AND REFILL COOLING SYSTEM WITH MANUFACTURERS RECOMMENDED MIXTURE OF COOLANT / WATER, BLEED AIR FROM COOLING SYSTEM, CHECK FOR PROPER COOLING AND FAN OPERATION.		\$140.00	LABOR

Total for "PERFORM COOLANT FLUSH": \$230.90

<b>VEHICLE ISSUE #8: KNOCKING NOISE FROM THE FRONT OF THE VEHICLE WHILE DRIVING, CHECK &amp; REPORT</b>				
LABOR:	VERIFIED THE KNOCKING NOISE FROM THE FRONT OF THE VEHICLE. FOUND THE STEERING BOX MOUNT IS COMPLETELY BROKEN. RECOMMEND REMOVING THE SUBFRAME & WELDING & REENFORCE BRACKET		\$0.00	LABOR

<p>Recommended Repairs:</p>	Labor/Jobs	\$1,862.00
	Parts	\$310.02
	Sublet	\$0.00
	Total Fees	\$14.27
<p>Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.</p>	Subtotal	\$2,174.21
	Tax @ 8.75%	\$26.35
	Total	\$2,186.29
	Payments	\$2,212.64
	Balance	-\$26.35

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.

X \_\_\_\_\_ Date 4/28/2022



# INVOICE

CUSTC	YEAR: 1988	1988	TRANS/DRIVE: MANUAL/
	MAKE/MODEL: BMW M5 BASE		LICENSE/STATE: 6YQJ341/
Home:	VIN: WBSDC9308J2791711		MILES IN/OUT: 81231 81235
	ENGINE: 3.5 S38		

LABOR:	REMOVED COMPLETE FRONT SUBFRAME, WELDED STEERING BOX BRACKET & ADDED EXTRA PLATING TO MAKE IT STRONGER THEN THE ORIGINAL. REINSTALLED THE FRONT SUBFRAME. ROAD TESTED, RECHECK, OK, NOISE IS GONE.	\$1,120.00	LABOR
--------	--	------------	-------

Total for "KNOCKING NOISE FROM THE FRONT OF THE VEHICLE WHILE DRIVING, CHECK & REPORT": \$1,120.00

**VEHICLE ISSUE #9: DRIVER DOOR PANEL IS LOOSE, CHECK & REPORT**

PART: 51 41 1 973 500	DOOR PANEL CLIP	8 @ \$1.75	\$14.00	NEW
-----------------------	-----------------	------------	---------	-----

LABOR:	REMOVED THE DRIVERS DOOR PANEL & REPLACED THE DOOR PANEL CLIPS. THERE IS AN AFTERMARKET SPEAKER IN THE DOOR THAT INTERFERES WITH THE PANEL FITTING.	\$0.00	LABOR
--------	---	--------	-------

Total for "DRIVER DOOR PANEL IS LOOSE, CHECK & REPORT": \$14.00

Payment Rec'd	Credit Card Amex	Date: 12/5/2014	\$2,212.64
12/2/2014 11:38:00 AM - scott2	PHONE, , 210		
12/3/2014 2:14:00 PM - jamesc	PHONE, , 2160		
4/28/2022 9:47:08 AM - BRANDON BAUGHMAN	AN EMAIL UPDATE WAS SENT TO		

<p>Recommended Repairs:</p>  <p>Warranty: From the date of delivery for a period of months or miles, whichever comes first, this firm will repair free of charge any defects in material and workmanship to the repairs stated on the invoice. All work to be done in our shop only. This does not include towing charges or customer supplied parts. A storage fee of 0.00 per day will be charged 24 hours after notification that work is complete. Neglect/abuse of vehicle will immediately void any and all warranties.</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td>Labor/Jobs</td><td>\$1,862.00</td></tr> <tr><td>Parts</td><td>\$310.02</td></tr> <tr><td>Sublet</td><td>\$0.00</td></tr> <tr><td>Total Fees</td><td>\$14.27</td></tr> <tr><td>Subtotal</td><td>\$2,174.21</td></tr> <tr><td>Tax @ 8.75%</td><td>\$26.35</td></tr> <tr><td>Total</td><td>\$2,186.29</td></tr> <tr><td>Payments</td><td>\$2,212.64</td></tr> <tr><td>Balance</td><td>-\$26.35</td></tr> </table>	Labor/Jobs	\$1,862.00	Parts	\$310.02	Sublet	\$0.00	Total Fees	\$14.27	Subtotal	\$2,174.21	Tax @ 8.75%	\$26.35	Total	\$2,186.29	Payments	\$2,212.64	Balance	-\$26.35
Labor/Jobs	\$1,862.00																		
Parts	\$310.02																		
Sublet	\$0.00																		
Total Fees	\$14.27																		
Subtotal	\$2,174.21																		
Tax @ 8.75%	\$26.35																		
Total	\$2,186.29																		
Payments	\$2,212.64																		
Balance	-\$26.35																		

Replaced parts may be requested by customer. I hereby authorize the above repair work to be done along with all necessary materials. You and your employees may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on the above vehicle to secure the amount of repairs thereto. The shop will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs including attorney's fees and court costs. I have read the above and acknowledge receipt of an estimate.