

# Fibersteel

145 South Irwindale Ave  
 Azusa, CA 91702  
 6263340404

info@fibersteel.com

<b>Invoice</b>	29709
Date	3/26/2024

Bill To	Ship To

Part #	Description	Units	Price	Amount
Note	55 Speedster		0.00	0.00
Double Locki...	Pair of double locking drop down seat frames with welded hinges. Mounts to original factory location. Includes center tunnel cover and all hardware.	1	1,500.00	1,500.00
FG356 - Origi...	Fiberglass Original Style Speedster seat shell.	2	550.00	1,100.00
Vinyl	Vinyl Upholstery (Per Seat) Includes custom molded foam cushions, carpet backing, and edge binding.	2	1,100.00	2,200.00
	Bolsters: ___ MBL-6876 EVERGREEN ___ Piping: ___ SAN-121 CREAM ___ Inserts: ___ MBL-6876 EVERGREEN ___ Carpet: ___ 320 DRK GREEN ___ Binding: ___ YT-208 PALE GREEN ___			
Misc. Parts	Extra vinyl (yd)	5	20.00	100.00
Note	Customer visit 4900 on 6/21/24		0.00	0.00

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on vehicle to ensure the amount of repairs thereto. You will not be held responsible for loss or damaged to vehicle including articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. A storage fee of \$25 a day and \$50 inside per day will incur 30 days after completion of repairs. Unless other arrangements have been made.

Signature \_\_\_\_\_

<b>Sub Total</b>	\$4,900.00
<b>Sales Tax (1..</b>	\$0.00
<b>Payments</b>	\$0.00
<b>Balance Due</b>	\$4,900.00

# SCOTT'S INDEPENDENT, INC.

1885 South Santa Cruz Street  
Anaheim, CA 92805-0000  
(714) 634-2027

INVOICE: 024695 Page: 1  
COMPLETED: 06/17/24 16:52  
ADVISOR  
ACCOUNT #: 12123

## INVOICE FOR SERVICES

CUSTOMER:  
ADDRESS:  
CITY:  
CELL:  
WORK:

LICENSE 6M4 927-CA  
VEHICLE 1955 Porsche Speedster  
VIN #: 81085  
MILEAGE: In:84735 Out:  
TAG:  
EMAIL

### The following parts were used on this service:

Quan.	Part #	Description	Each	Total
1.00	IM HOOD	Hood Seal, IM	60.00	60.00
1.00	WAR SUMP	Sump, Willhoit 356/912	1175.00	1175.00
4.00	SWEPOIL	OIL, SWEPKO 20/50	13.25	53.00
2.00	616 104 951 00	GASKET, VALVE COVER WR	11.95	23.90
4.00	BP6HS	SPARK PLUG	6.75	27.00
1.00	999 192 006 50	BELT, GENERATOR	14.96	14.96
1.00	WF 51010	oil filter, wix 4cyl	33.00	33.00
1.00	616 101 380 00	STRAINER SCREEN	74.77	74.77
1.00	911 424 341 01	STRAP, GREY/BEIGE O.E.	6.96	6.96
2.00	999 706 005 80	Strap, Brake Cable - 220mm	24.75	49.50
1.00	616 101 380 00	STRAINER SCREEN	64.00	64.00
4.00	NLA 531 911 22	Seal, cabriolet door	34.46	137.84

### The labor performed, and the charges, are:

Install Full LED kit	320.00
Repair door handle	160.00
Make doors fit correctly	320.00
Make hand brake function correctly	160.00
COMPLETE SERVICE INCLUDES: Replace spark plugs, points, oil filter, valve cover and strainer gaskets and oil. Clean air filters or, if equipped with Zenith carburetors, replace air filters. Adjust valves, carburetors and timing. Inspect brakes, battery, lights, tire pressures and condition, transmission fluid level, wiper blades and door latches/locks. Inspect and lubricate suspension points. Add fuel treatment. Road test vehicle.	480.00
Diagnose suspension clunk	160.00
Tighten all king and link pins	
Remove studs and install deep sump	160.00
Remove and replace muffler	640.00
Slight modification to J tubes for fitment	
Remove hood and install new hood seal	800.00

# SCOTT'S INDEPENDENT, INC.

1885 South Santa Cruz Street  
 Anaheim, CA 92805-0000  
 (714) 634-2027

INVOICE: 024695 Page: 2  
 COMPLETED: 06/17/24 16:52  
 ADVISOR  
 ACCOUNT #: 12123

Reinstall hood and make hood fit	320.00
Re-route and replace fuel lines	320.00
Install door seals and fit doors	320.00

	Taxable	Non-tax			
<b>PARTS:</b>	\$ 1,719.93	\$ 0.00	<b>SUBTOTAL:</b>	\$ 5,559.93	<b>TOTAL: \$ 5,693.22</b>
<b>LABOR:</b>	\$ 0.00	\$ 3,840.00	<b>TAX:</b>	\$ 133.29	
<b>SUBLET:</b>	\$ 0.00	\$ 0.00	<b>ENVIR:</b>	\$ 0.00	
<b>SUPPLIES:</b>	\$ 0.00		<b>:</b>	\$ 0.00	<b>BALANCE: \$ 5,693.22</b>

A buyer of this product in California has the right to have this product serviced or repaired during the warranty period. All parts replaced and the labor performed are guaranteed to be free from defect for 6 months or 6,000 miles, whichever occurs first. The warranty period will be extended for the number of days that the product has been out of the buyer's hands for warranty repairs. If a defect exists within the warranty period, the warranty will not expire until the defect has been repaired. The warranty period will also be extended if the warranty repairs did not remedy the defect and the buyer notifies the manufacturer or seller of the failure of the repairs within 60 days after they were completed. If, after a reasonable number of attempts the defect has not been repaired, the buyer may return the product for a replacement or a refund subject in either case, to deduction of a reasonable charge for usage. This time extension does not affect the protections or remedies the buyer has under other laws.

----- ACCEPTED -----

BY: \_\_\_\_\_ DATE \_\_\_\_\_  
 \$ \_\_\_\_\_ CHECK# \_\_\_\_\_ AUTHOR.# \_\_\_\_\_ BY: \_\_\_\_\_  
 DATE \_\_\_\_\_

# Fibersteel

145 South Irwindale Ave  
 Azusa, CA 91702  
 6263340404

info@fibersteel.com

<b>Invoice</b>	29850
Date	7/29/2024

<b>Bill To</b>	<b>Ship To</b>

Part #	Description	Units	Price	Amount
Misc. Parts	Convertible Top Header Seal	1	135.00	135.00
K	Glasspar rear window, Molded clear Plexiglass	1	566.70	566.70
EF	Rear window upper and lower lock set (Black, white, or chrome finish)	1	73.95	73.95
Y	Glasspar head liner, pre sewn, perforated Off- white vinyl. (steel bows sold separately)	1	760.50	760.50
Misc. Parts	45mm Wheel Stud	10	12.00	120.00
Misc. Parts	50mm Wheel Stud	10	12.00	120.00
Misc. Parts	Mirror Opening Cover	1	10.00	10.00
Misc. Parts	Center Tunnel Inspection Cover	1	330.00	330.00
SC5.3 356 Pr...	ID plate, Pre A	1	75.44	75.44
SC7 Made In ...	Made In Western Germany Plate	1	19.15	19.15
	<b>Parts Subtotal.</b>			<b>2,210.74</b>
LABOR , SER...	Labor to modify, upholster, and install inspection cover	1.5	100.00	150.00
LABOR , SER...	Labor to modify soft top	8	100.00	800.00
LABOR , SER...	Labor to distress and mount mirrors	1	100.00	100.00
LABOR , SER...	Labor to install glasspar window and headliner	6	100.00	600.00
LABOR , SER...	Labor to wire brake light, fabricate mounting bracket, and install	4	100.00	400.00
LABOR , SER...	Labor to install seat belts	0.5	100.00	50.00
LABOR , SER...	Labor to install push start switch	0.25	100.00	25.00
LABOR , SER...	Labor to install windshield rubber	0.25	100.00	25.00
LABOR , SER...	Labor to install wheel studs	2	100.00	200.00
LABOR , SER...	Labor to install side moldings	0.5	100.00	50.00
LABOR , SER...	Labor to fabricate battery cover	2	100.00	200.00
LABOR , SER...	Labor to install vin plate and Made in West Germany Badge	0.25	100.00	25.00
	<b>Labor Subtotal.</b>			<b>2,625.00</b>

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on vehicle to ensure the amount of repairs thereto. You will not be held responsible for loss or damaged to vehicle including articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. A storage fee of \$25 a day and \$50 inside per day will incur 30 days after completion of repairs. Unless other arrangements have been made.

Signature \_\_\_\_\_

<b>Sub Total</b>
<b>Sales Tax (1..</b>
<b>Payments</b>
<b>Balance Due</b>

# Fibersteel

145 South Irwindale Ave  
 Azusa, CA 91702  
 6263340404

info@fibersteel.com

<b>Invoice</b>	29850
Date	7/29/2024

Bill To	Ship To

Part #	Description	Units	Price	Amount
Discount	\$700 credit applied from Invoice #29710		-700.00	-700.00
Discount	Good customer pricing		-335.74	-335.74
Note	Customer visit 8/22/24 - \$3800		0.00	0.00

I hereby authorize the repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on vehicle to ensure the amount of repairs thereto. You will not be held responsible for loss or damaged to vehicle including articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. A storage fee of \$25 a day and \$50 inside per day will incur 30 days after completion of repairs. Unless other arrangements have been made.

Signature \_\_\_\_\_

<b>Sub Total</b>	\$3,800.00
<b>Sales Tax (1..</b>	\$0.00
<b>Payments</b>	\$0.00
<b>Balance Due</b>	\$3,800.00

Date: Oct 15, 2024

Bill To:

**Balance Due: \$6,000.00**

Item	Quantity	Rate	Amount
Installation of Interior + Carpet Materiel	1	\$6,000.00	\$6,000.00

Subtotal: \$6,000.00

Tax (0%): \$0.00

Total: \$6,000.00