

S CAR GO RACING INC

533 IRWIN ST
 SAN RAFAEL, CA 94901-3914
 Tel: 415-485-6026 • Fax: 415-485-0116
 dee@scargoracing.com • www.scargoracing.com

Repair Order J057747

Service Advisor: Dee
 Technician: Patrick
 Date: 11-11-2021 08:53 AM
 Estimate: Q074986

Customer

Vehicle 2002 Porsche 911 Turbo
 3.6 GAS - Grey
 WPOAB299125685273

Miles In: 59,944
 Miles Out: 59,944
 License Plate: 4UOF999 CA

Work to be Performed**Labor**

Labor	Tech	Hrs	Price	Total
Air bag light on - we replaced the driver's side buckle and the light came back on about two weeks later	PAT	4.00	195.00	780.00

Need to modify harness for buckle on both sides

Parts	Part No	Qty	Price	Total
Harness Repair Kit	CNV000 043 206 06	2.00	75.50	151.00

	Labor	SubTotal	\$931.00
Total	Labor	780.00	
	Parts	151.00	
	Hazmat*	0.00	
	Supplies*	0.00	
	Taxes	13.97	

Repair Order Total \$944.97

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

Authorization

Original Estimate Total:

Authorization Method: email text phone fax in person

Date: _____ Contact Details: _____

Authorized By:

X _____
 Customer Signature

Save replacement parts for inspection or return? (Core may apply) Yes No

S CAR GO RACING INC

533 IRWIN ST
 SAN RAFAEL, CA 94901-3914
 Tel: 415-485-6026 • Fax: 415-485-0116
 dee@scargoracing.com • www.scargoracing.com

Repair Order J054913

Service Advisor: Dee
 Technician: Nathan
 Date: 12-02-2019 10:02 AM
 Estimate: Q072813

Customer

Vehicle 2002 Porsche 911 Turbo
 3.6 GAS - Grey
 WPOAB29912S685273

COPY

Miles In: 53,104
 Miles Out: 53,104
 License Plate: 4UOF999 CA

Work to be Performed**996 Turbo Service**

Labor	Tech	Hrs	Price	Discount	Total
Service / Replace wiper blades	NAT	8.00	180.00	0.00%	1,440.00
Brake Flush	NAT	1.00	180.00	0.00%	180.00

Parts	Part No	Qty	Price	Discount	Total
Spark Plug - List \$10.45	CNVFR 6 LDC	6.00	9.45	0.00%	56.70
Oil Filter	CNV996 107 225 53	1.00	24.70	0.00%	24.70
Air Filter	CNV996 110 131 71	1.00	51.45	0.00%	51.45
Multi Rib Belt - List \$115.10	CNV999 192 379 50	1.00	85.10	0.00%	85.10
Seal Ring	AAA900 123 106 30	1.00	1.60	0.00%	1.60
Fuel Filter - List \$93.40	CNV996 110 253 52	1.00	70.40	0.00%	70.40
Fuel Additive	CNVSG 115	1.00	29.95	0.00%	29.95
Super Blue Brake Fluid	AAASG 111	1.00	18.50	0.00%	18.50
Window Washer Fluid	FLDSG 7449	1.00	5.00	0.00%	5.00
Parts Kleen	CNVSG 112	1.00	7.35	0.00%	7.35
Swepeco 530 Engine Oil	CNV306B	9.00	11.00	0.00%	99.00
Seal Ring	CNV900 123 118 30	1.00	1.40	0.00%	1.40
Pump Seal	CNV900 123 010 20	1.00	1.75	0.00%	1.75
Seal Ring	CNV900 123 140 30	2.00	1.65	0.00%	3.30
ACC Cabin Filter - List \$73.85	CNV997 571 219 01	1.00	43.85	0.00%	43.85
Wiper Blade Set - List \$74.35	CNV3 397 001 582	1.00	34.35	0.00%	34.35

996 Turbo Service SubTotal \$2,154.40

Labor

Labor	Tech	Hrs	Price	Discount	Total
Replace battery	NAT	0.50	180.00	0.00%	90.00

Parts	Part No	Qty	Price	Discount	Total
Battery	CNVMTTP-H7	1.00	197.05	0.00%	197.05

Labor SubTotal \$287.05

Total

Labor 1,710.00
 Parts 731.45
 Hazmat* 10.00
 Supplies* 0.00
 Taxes 65.84

Repair Order Total \$2,517.29

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

Authorization

Original Estimate Total:
Authorization Method: email text phone fax in person
Date: _____ Contact Details: _____
Authorized By: _____
X _____
Customer Signature

Save replacement parts for inspection or return? (Core may apply) Yes No

Customer

Vehicle 2002 Porsche 911 Turbo
 3.6 GAS - Grey
 WP0AB29912S685273

COPY

Miles In: 53,104
 Miles Out: 53,104
 License Plate: 4UOF999 CA

Work to be Performed

Labor

Labor	Tech	Hrs	Price	Discount	Total
Replace clutch / replace rear main seal	NAT	8.00	180.00	0.00%	1,440.00

Parts	Part No	Qty	Price	Discount	Total
Clutch Kit	CNV996 116 911 01	1.00	1,051.70	0.00%	1,051.70
Flywheel Bolt	CNV999 119 017 01	9.00	4.55	0.00%	40.95
Pressure Plate Bolt	CNV999 510 015 01	9.00	4.85	0.00%	43.65
Parts Kleen	CNVSG 112	2.00	7.35	0.00%	14.70
Crankshaft Seal	CNV999 113 426 41	1.00	46.95	0.00%	46.95

	Labor	SubTotal	\$2,637.95
Total	Labor	1,440.00	
	Parts	1,197.95	
	Hazmat*	0.00	
	Supplies*	0.00	
	Taxes	107.82	

Repair Order Total \$2,745.77

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

Authorization

Original Estimate Total:
 Authorization Method: email text phone fax in person
 Date: _____ Contact Details: _____
 Authorized By: _____
 X _____
 Customer Signature

Save replacement parts for inspection or return? (Core may apply) Yes No



3800 Alhambra Ave
Martinez, CA 94553
925-370-6382

Store: 663
Invoice: 66300371460
Salesperson: Doreen R H

Work Order 66300371268

ARD 243603

Customer Information

Customer ID:

Name:

Address:

City, State,

Phone:

Vehicle Information

Vehicle: 2002 PORSCHE 911 Series

Color:

Mileage: 51316

License: 4UOF999

Les Schwab Invoice

Qty	Product Code	Product Description	Price/ea	FET	Amount
2	198286	295/30ZR-18XL PILOT SPORT PS2	\$582.80	\$0.00	\$1,165.60
2	630606	225/40ZR-18 XL PILOT SPORT PS2	\$309.99	\$0.00	\$619.98
1	122532	FREIGHT	\$50.00	\$0.00	\$50.00
4	15615	TRADE-IN PASSENGER/LIGHT TRUCK	(\$100.00)	\$0.00	(\$400.00)

Parts Subtotal: \$1,435.58
Labor Subtotal: \$0.00
Sales Tax: \$165.17
Tire Tax: \$7.00

Invoice	\$1,607.75
----------------	-------------------

Payment Method: CREDIT Approval# 05743D Card# XXXXXXXXXXXXX0476 **\$1,607.75**

DOT: Tire(s) has been electronically registered.

Remember to rotate your tires every 5,000 miles for maximum mileage - and it's free!

Les Schwab electronically registers your tire purchase with the tire manufacturer at no charge to you, in accordance with NHTSA's tire registration requirements.

Free air checks for the life of the tires.

SAEJ2492 WARNING: THE FOLLOWING APPLIES TO VEHICLES WITH MODIFIED SUSPENSION/RIDE HEIGHT

The suspension/ride height of this vehicle has been modified. As a result, this vehicle may handle differently than that of factory equipped vehicles. As with any vehicle, extreme care must be used to prevent loss of control or roll-over during sharp turns or abrupt maneuvers. Always wear seat belts and drive safely, recognizing that reduced speeds and specialized driving techniques may be required. Failure to drive this vehicle safely may result in serious injury or death. Do not drive this vehicle unless you are familiar with its unique handling characteristics and are confident of your ability to maintain control under all driving conditions. Some modifications (and combinations of modifications) are not recommended and may not be permitted in your state. Consult your owner's manual, the instructions accompanying this product and state laws before undertaking these modifications. You are responsible for the legality and safety of the vehicle you modify using these components.

Your car may have a tire pressure monitoring system that uses a warning light to alert the driver of low tire pressure or system failure. Pursuant to NHTSA, Les Schwab must install all tire and wheel combinations with functioning TPMS sensors; including tires and custom wheels or winter tires and wheels. The TPMS light may illuminate after routine service and require additional action. We offer and recommend monthly air checks.

S CAR GO RACING INC

533 IRWIN ST
 SAN RAFAEL, CA 94901-3914
 Tel: 415-485-6026 • Fax: 415-485-0116
 dee@scargoracing.com • www.scargoracing.com

Repair Order J053648

Service Advisor: Dee
 Technician: Patrick
 Date: 12-06-2018 09:47 AM

Customer**Vehicle** 2002 Porsche 911 Turbo

3.6 GAS - Grey
 WPOAB29912S685273

Miles In: 47,962
 Miles Out: 47,962
 License Plate: 4UOF999 CA

Work to be Performed**Labor**

Labor	Tech	Hrs	Price	Discount	Total
Replace clutch hydraulic pressure accumulator	PAT	1.00	160.00	15.00%	136.00

Parts	Part No	Qty	Price	Discount	Total
AS Pressure Accumulator	CNV997 314 166 00	1.00	174.35	0.00%	174.35

Labor SubTotal \$310.35

996 Turbo Oil Change

Labor	Tech	Hrs	Price	Discount	Total
Oil change & lube / checklist	PAT	1.00	160.00	15.00%	136.00

Parts	Part No	Qty	Price	Discount	Total
Oil Filter	CNV996 107 225 53	1.00	26.15	0.00%	26.15
Pump Seal	CNV900 123 010 20	1.00	0.90	0.00%	0.90
Seal Ring	CNV900 123 140 30	2.00	1.65	0.00%	3.30
Seal Ring	CNV900 123 118 30	1.00	1.25	0.00%	1.25
Window Washer Fluid	FLDSG 7449	1.00	5.00	0.00%	5.00
Parts Kleen	CNVSG 112	1.00	7.35	0.00%	7.35
Swepeco 530 Engine Oil	CNV306B	9.00	11.00	0.00%	99.00
Fuel Additive	CNV503	1.00	9.50	0.00%	9.50

996 Turbo Oil Change SubTotal \$288.45

Total

Labor 272.00
 Parts 326.80
 Hazmat* 0.00
 Supplies* 0.00
 Taxes 29.41

Repair Order Total \$628.21

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

Authorization

Original Estimate Total:

Authorization Method: email text phone fax in person

Date: _____ Contact Details: _____

Authorized By:

X _____
 Customer Signature



PORSCHE Audi

RECTOR MOTOR CAR CO.

www.rectormotors.com

1010 CADILLAC WAY

BURLINGAME, CA 94010-2504

(650) 348-0111

B.A.R. # ARD009132

EPA # CAD981416135

SERVICE DEPARTMENT HOURS:

MON. THRU FRI. - 7:30 AM - 6:00 PM

BODY SHOP HOURS:

MON. THRU FRI. - 8:00 AM - 5:00 PM

PARTS DEPARTMENT HOURS:

MON. THRU FRI. - 8:00 AM - 5:00 PM

CELL: 415-602-8895

NOTICE TO CONSUMER: PLEASE READ IMPORTANT WARRANTY AND ADDITIONAL INFORMATION ON BACK.

CUSTOMER NO. 74485	ADVISOR ROGER GRAY	TAG NO. 42136 B060	INVOICE DATE 07/28/14	INVOICE NO. POCS162102
	LICENSE NO.	MILEAGE 37,588	COLOR GRAY/BLACK	STOCK NO.
	YEAR / MAKE / MODEL 02/PORSCHE/911 CARRERA/2DR CPE		DELIVERY DATE	DELIVERY MILES
	VEHICLE I.D. NO. W P 0 A B 2 9 9 1 2 S 6 8 5 2 7 3		SELLING DEALER NO.	PRODUCTION DATE
	F. T. E. NO.	P. O. NO.	R. O. DATE 07/28/14	
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS		

MO: 37588

JOB# 1 CHARGES-----

LABOR-----

J# 1 03POZ SCHEDULED MAINT TECH(S):42223 222.00
 CLIENT REQUESTST TO HAVE THE ENGINE OIL AND FILTER CHANGED.
 COMPLETED.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT	PRICE
	1		PK996TLOF	996T LOF	****	****
	1		996-107-225-53	OIL-FILTER INSER		27.40
	1		900-123-010-20	PUMP SEAL, COPPE		0.81
	1		900-123-118-30	ALUM SEAL RING		0.81
	2		900-123-140-30	SEAL RING		1.62
	10		WTY-000-003-A	ENGINE OIL,SYNTH		84.00
TOTAL - PARTS						114.64

JOB# 1 TOTALS-----
 LABOR 222.00
 PARTS 114.64

JOB# 2 CHARGES-----

LABOR-----

J# 2 46POZ-BINSP BRAKE INSPECTION TECH(S):42223 0.00
 PERFORM FULL BRAKE INSPECTION AND NOTE PAD/ROTOR LIFE
 REMAINING.
 FRONT BRAKES HAVE APPROX 90% REMAINING. REAR PADS HAVE
 APPROX 95% REMAINING.

JOB# 2 TOTALS-----

JOB# 3 CHARGES-----

LABOR-----


J# 3 44POZ-001 TIRE/WHEEL DIAGNOSE TECH(S):42223 0.00
 PLEASE ADVISE ON THE TIRE CONDITION.
 FRONT AND REAR TIRES HAVE APPROX 40% REMAINING.

JOB# 3 TOTALS-----

JOB# 4 CHARGES-----

LABOR-----

J# 4 01POZ-LOANER RECTOR LOANER-RETAIL TECH(S):42223 0.00



A courtesy tire inflation service was completed and the measurements after the service are noted above.

The Reynolds and Reynolds Company ERMANTINE CC672146 Q (06/14)



NEW battery \$250 Feb 1, 2007
 109079 Oil change \$160 147790

CARLSEN MOTOR CARS

3636 HAVEN AVE. REDWOOD CITY, CA 94063
 PHONE: (650) 701-9200 FAX (650) 701-1448

INVOICE

PAGE 1

SERVICE ADVISOR: 264 BRIAN HASKE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
GREY	02	PORSCHE 996 TWIN TUR	WP0AB29912S685273		31025/31025	T733
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
01JAN02 IS			17:00 02FEB07		CASH	01FEB07
R.O. OPENED	READY	OPTIONS: ENG:3.6 Liter TRN:6SPD				
13:24 01FEB07	15:53 01FEB07					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A OIL AND FILTER SPECIAL							
CAUSE: MAINTENANCE SERVICE							
OFS OIL AND FILTER SPECIAL							
354 CHANG, TOU LIC#: 9							
CPM							
1	996-107-225-53	OIL-FILTER	INSERT		21.42	20.13	20.13
1	900-123-118-30	ALUM SEAL	RING		1.08	1.08	1.08
1	900-123-010-20	PUMP SEAL			1.02	1.02	1.02
LUBE MOBIL ONE 0W40							
CPL							
						46.00	46.00
PARTS:	22.23	LABOR:	80.00	OTHER:	46.00	TOTAL LINE A:	148.23

CHANGED ENGINE OIL AND FILTER

B OWNER REQUESTS TO INSTALL INTERSTATE BATTERY

CAUSE: REQUEST							
2700 ENGINE ELECTRICAL							
354 CHANG, TOU LIC#: 9							
CP							
1	MTP-91	INTERSTATE	BATTERY		165.99	165.99	165.99
PARTS:	165.99	LABOR:	75.00	OTHER:	0.00	TOTAL LINE B:	240.99

REPLACED BATTERY

EST: 409.00 01FEB07 13:24 SA: 264

CARLSEN MOTOR CARS



ORIGINAL ESTIMATE			FINAL REVISED ESTIMATE			DESCRIPTION	TOTALS
\$			\$			LABOR AMOUNT	155.00
						PARTS AMOUNT	188.22
DATE	TIME	PHONE #	AUTHORIZED	ADDITIONAL AMOUNT	REVISED TOTAL	GAS, OIL, LUBE	46.00
						SUBLET AMOUNT	0.00
						MISC. CHARGES	0.00
						TOTAL CHARGES	389.22
						ADJUSTMENTS	0.00
I ACKNOWLEDGED NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE.			I ACKNOWLEDGED RECEIPT OF VEHICLE AND I HAVE RECEIVED A COPY OF THIS INVOICE.			SALES TAX	19.32
X			X			PLEASE PAY THIS AMOUNT	408.54

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE.

DLR CODE:

BAR # AF 222073

EPA # CAR 000115923

Notice to Consumer: Please read important information on back. **CUSTOMER COPY**