

**German Motors**

2660 Lincoln Blvd. Unit B  
 Santa Monica, CA 90405  
 310.396.8440  
 James@GMEautomotive.com

**Invoice**

BILL TO

INVOICE #	DATE	TOTAL DUE	ENCLOSED
2140	07/12/2022	\$3,104.17	

**YEAR/MAKE/MODEL**

1977 Porsche 911 Turbo

SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
<b>Sales</b>	Engine Oil - Porsche Vintage Blend - 12L	1	144.00	144.00T
<b>Sales</b>	Engine Oil Filter and Seal Kit - OEM	1	20.34	20.34T
<b>Service</b>	Full Service: Engine Oil Service; Engine Oil Filter Service; Full Vehicle Inspection Notes: Okay Level all Fluids: Brake Fluid; Coolant; P.S Fluid; Washer Fluid Equalize and Correct all Pressures Engine Valve Adjustment Service: Remove Cam Covers and Adjust Valve Clearance to Specifications; Reseal Valves and Test : Okay Adjust and Tune Engine Running Condition and Mixtures	1	350.00	350.00
<b>Sales</b>	Lower Valve Cover Gasket Set - with Silicone Bead	1	38.96	38.96T
<b>Sales</b>	Brake Caliper Rebuild Kit - Front Left and Front Right	2	58.50	117.00T
<b>Sales</b>	Brake Caliper Rebuild Kit - Rear Left and Right	2	48.03	96.06T
<b>Sales</b>	Brake Pad Set - Front	1	70.58	70.58T
<b>Sales</b>	Brake Pad Set - Rear	1	120.49	120.49T
<b>Sales</b>	Brake Rotor - Front Left; Front Right	2	211.95	423.90T
<b>Sales</b>	Brake Rotor Set - Rear	2	295.80	591.60T
<b>Sales</b>	Sway Bar Link Bushings (18mm) - Rear	4	37.39	149.56T
<b>Labor</b>	Brake Calipers Binding; Brake Application stuck on; Brake Caliper pistons seized from corrosion; Remove all Brake Calipers; Extract Pistons and Replace Brake Caliper Seals and Dust Boots; Rebuild/ Reassemble; Re- mount Calipers Front and Rear; Bleed Brake System Circuit Complete; Remove and Install New Brake Pads and Rotors; Reassemble and Test Braking System: Okay; No further binding; Brake Application releases okay now; Upon Reassembly discovered rear sway bar bushings Completely deteriorated; Sway bar sitting on brackets; remove rear sway bars and replace bushings.	1	800.00	800.00T

We guarantee our labor.

Guarantee valid only if returned to our service department for adjustment.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to the vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection.

SUBTOTAL	2,922.49
TAX	181.68
TOTAL	3,104.17
BALANCE DUE	<b>\$3,104.17</b>

X \_\_\_\_\_

**INVOICE**

**German Motors**  
2660 Lincoln Blvd. Unit B  
Santa Monica, CA 90405

James@GMEautomotive.com  
+1 (310) 396-8440

**Invoice details**

Invoice no.: 908930

Terms: Net 30

Invoice date: 03/26/2025


Due date: 04/25/2025

Year/Make/Model: 1977 Porsche 911 Turbo  
Carrera

#	Date	Product or service	Description	Qty	Rate	Amount
1.		Labor	Sunroof Repair: Sunroof Went Close to full Extent; Remove Sunroof and Headliner Complete. Inspect and Found Broken Guide Rail; Remove and Replace Guide Rails; Clean and Lubricate Sunroof Tracks and Motor; Replace Sunroof Seals Rear; Repair Headliner. Note Repair on Headliner is not Permanent; New Headliner Replacement is Necessary; material Deteriorated.	1	\$450.00	\$450.00
2.		Sales	Sunroof Seal - OEM (1) Rear	1	\$62.16	\$62.16
3.		Sales	Sunroof Weather Strip - OEM (1) Rear	1	\$16.84	\$16.84
4.		Sales	Sunroof Guide Rail - OEM (1) Left (1) Right	2	\$47.75	\$95.50

Subtotal \$724.50

Sales tax \$51.23

**Ways to pay****Total \$785.73****Note to customer**

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to the vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees





Eason Auto  
BAR AG2000637  
3423 Harlan Street  
Oakland, CA 94608  
(510) 420-1262  
bill@easonauto.com  
www.easonauto.com

#4837  
p. t. lu. 25

## Invoice #1386

Created: 4/14/2025  
Invoiced: 4/15/2025  
Payment Term: On Receipt  
Service Writer: Bill Eason

Fantasy Junction \*  
Sales@fantasyjunction.com

1977 porsche 911 turbo/930  
VIN: 9307800064  
License Plate: CHOZ  
Mileage In: 158,833  
Mileage Out: 158,838

Car running poorly. Feels like fuel starvation. Test and repair					
	Description	Price	QTY	HRS	Subtotal
1	Fuel pumps sound like they're straining. Test output. Both pumps way below specs. replace			3	\$750.00
2	front fuel pump	\$280.00	1		\$280.00
3	rear fuel pump	\$320.00	1		\$320.00
4	car runs better but still feels like its starving. Test control pressure. Stuck at warm running condition. New unavailable. recommend send out to get rebuilt. Attempt to adjust=> Much better but still recommend having rebuilt to be perfect.			0.5	\$125.00
EPA (1%): \$6.00		Shop Supplies (4%): \$59.00	Tax (10.25%): \$68.16	Total: \$1,608.16	

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature \_\_\_\_\_

Parts .....	\$600.00
Labor .....	\$875.00
Subtotal .....	\$1,475.00
Shop Supplies .....	\$59.00
EPA .....	\$6.00
Tax .....	\$68.16
Grand Total .....	\$1,608.16
Paid To Date .....	(\$0.00)

**REMAINING BALANCE \$1,608.16**

### Authorizations

Text by Fantasy Junction * 4/15/2025 at 1:26 PM PDT	+ Car running poorly. Feels like fuel starvation. Test and repair	\$1,608.16
--	--	------------