



XK's Unlimited
 850 Fiero Lane
 San Luis Obispo, CA 93401
 PH: 805-544-7864
 TF: 800-444-5247
 FX: 805-544-1664

Remit To:
 850 Fiero Lane
 San Luis Obispo, CA 93401

Email: Parts@xks.com

INVOICE# 98961

S
O
L
D

T
O

Order Ref. No. 131881	Ctr.No. !WEB	Time 10:21AM	Your Salesman: WEB SITE				Page 1	Branch W1	Invoice No. 98961
Customer P.O. No. 2146497AM	SNO 0	Terms WEB CHARGE	Invoice Date 06-26-19	Shipped Via GROUND SAVER					
Line	Ord	Ship	B/O	Part Number	Description	List Price	Unit Price	Extended Price	

Placed on 2019-06-25 20:21:57

1.	1	1	CO	5482	JAGUAR KNOB, PANEL LI C5482		16.79	16.79
							5.99	

Tracking Numbers: 9400109902097379061914

Parts:	16.79
Sales Tax:	1.22
Freight Out/Handling Charges:	5.99
=====	
Invoice Total:	\$24.00

WE APPRECIATE YOUR BUSINESS EVERY DAY!

CUSTOMER COPY

CUSTOMER'S SIGNATURE:

PARTS SOLD HEREIN ARE WARRANTED ONLY TO THE EXTENT OF THE WARRANTY FURNISHED BY THE MANUFACTURER OF SUCH PARTS. ITEMS RETURNED MUST BE IN NEW CONDITION, ORIGINAL BOX, AND ACCOMPANIED BY THE PURCHASE INVOICE. THERE WILL BE NO RETURNS OR REFUNDS ALLOWED ON THE FOLLOWING: 1) PARTS RETURNED AFTER 30 DAYS, 2) ANY ELECTRICAL EQUIPMENT OR PARTS, 3) BROKEN OR PARTIAL KITS AND GASKET SETS, 4) TOOLS THAT HAVE BEEN USED, 5) SPECIAL ORDER ITEMS, OR 6) PARTS NOT IN THEIR ORIGINAL PACKAGE. 1-1/2% CHARGE ON INVOICES 30 DAYS PAST DUE (18% ANNUALLY). CORE RETURNS MUST BE IDENTICAL TO UNIT PURCHASED, ASSEMBLED AND DRAINED OF ALL LUBRICANT. CORES MUST BE RETURNED IN THE ORIGINAL BOX WITHIN 30 DAYS FROM THE DATE OF PURCHASE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL RETURNS.

*** JOIN OUR FACEBOOK GROUP AT WWW.XKS.COM ***



XKs Unlimited
 850 Fiero Lane
 San Luis Obispo, CA 93401
 PH: 805-544-7864
 TF: 800-444-5247
 FX: 805-544-1664

Remit To:
 850 Fiero Lane
 San Luis Obispo, CA 93401

Email: Parts@xks.com

INVOICE# 99305

S
O
L
D

T
O

Order Ref. No. 132420	Ctr.No. 417	Time 01:15PM	Your Salesman: Alex Mularoni			Page 1	Branch W1	Invoice No. 99305
Customer P.O. No.	SNO 532	Terms SPLIT PAYMENTS	Invoice Date 07-01-19	Shipped Via GROUND SAVER				

Line	Ord	Ship	B/O	Part Number	Description	List Price	Unit Price	Extended Price
1.	1	1	0	CO 5482	KNOB, PANEL LIGHTS SW C5482	16.79	0.00	0.00

NO CHARGE SHIPPING WRONG KNOB
 IN RIGHT BAG REF 98961

Tracking Numbers: 9400109902097379062911

=====
 Invoice Total: \$0.00

WE APPRECIATE YOUR BUSINESS EVERY DAY!

CUSTOMER COPY

CUSTOMER'S SIGNATURE:

PARTS SOLD HEREIN ARE WARRANTED ONLY TO THE EXTENT OF THE WARRANTY FURNISHED BY THE MANUFACTURER OF SUCH PARTS. ITEMS RETURNED MUST BE IN NEW CONDITION, ORIGINAL BOX, AND ACCOMPANIED BY THE PURCHASE INVOICE. THERE WILL BE NO RETURNS OR REFUNDS ALLOWED ON THE FOLLOWING: 1) PARTS RETURNED AFTER 30 DAYS, 2) ANY ELECTRICAL EQUIPMENT OR PARTS, 3) BROKEN OR PARTIAL KITS AND GASKET SETS, 4) TOOLS THAT HAVE BEEN USED, 5) SPECIAL ORDER ITEMS, OR 6) PARTS NOT IN THEIR ORIGINAL PACKAGE. 1-1/2% CHARGE ON INVOICES 30 DAYS PAST DUE (18% ANNUALLY). CORE RETURNS MUST BE IDENTICAL TO UNIT PURCHASED, ASSEMBLED AND DRAINED OF ALL LUBRICANT. CORES MUST BE RETURNED IN THE ORIGINAL BOX WITHIN 30 DAYS FROM THE DATE OF PURCHASE. A 20% RESTOCKING FEE WILL BE CHARGED ON ALL RETURNS.

*** JOIN OUR FACEBOOK GROUP AT WWW.XKS.COM ***

Four Car Garage
 839 N San Mateo Dr
 San Mateo, CA. 94401
 Phone: 650-342-3844
 Meticulous Maintenance by Passionate Professionals

INVOICE

115657

Org. Est. # 229745
 BAR# ARD00286600
 EPA# CAL000424582

INVOICE ANNUAL SERVICE

Printed Date: 11/14/2023

Work Completed: 11/14/2023

1956 Jaguar - XK140 -

Lic #: XK140DH

Unit #: body P5346

VIN #: AU19883DN- A812883DN

Odometer In: 73312

Part Description	I Number	Qty	Sale	Ext	Labor Description	Ext
WASTE- CAL EPA#000424582		1.00	3.50	3.50	Please confirm vin #	
WASTE					Specialty Service	650.25
Parts & Brake Cleaner		1.00	7.82	7.82	Perform oil & filter service. Perform brake inspection. Inspect tires & suspension, belts & hoses, air filter, battery condition, power steering system (if applicable), engine/transmission mounts, drive axles and exhaust system. Perform pressure test of cooling system. Test lighting, wipers, A/C temperature (if applicable), windows and door locks for proper operation. Check fluid levels, and top off any applicable fluids. Install reminder sticker on driver door jamb. Complete 31 Point Inspection Report. Road Test.	
St1000					Please see attached Inspection Report.	
Engine oil filter		1.00	17.63	17.63	Inbound shipping and handling	8.79
1535					Inbound shipping and handling	
Engine oil drain plug gasket		1.00	6.57	6.57	Tow from Auto-Vino to Four Car Garage	157.50
324-805					Towed as requested.	
Engine oil		5.00	8.95	44.75	Vehicle arrived extremely low on fuel and ran out while we were moving it onto the inspection rack. We added \$29.16 in fuel. We then added additional fuel (\$15.00) upon completion of repairs to test for leaks.	44.16
20W-50					Added fuel	
Brake fluid/pint		2.00	12.95	25.90	PERFORM BRAKE FLUID SERVICE.	255.00
O/P					Check brake fluid for moisture and contamination. Inspect all hydraulic line and hoses. Inspect calipers and wheel cylinders. Inspect master cylinder and cap. Serviced entire brake fluid system including master cylinder, calipers, wheel cylinders until clean. NOTE: Performing the brake fluid service on an older vehicle or on a vehicle that has not been properly serviced/maintained may cause the brake master cylinder to fail.	
WASTE- CAL EPA#000424582		1.00	3.50	3.50	European Vehicle Coolant Service	255.00
WASTE					Perform visual inspection to determine if any leaks are present, drain old coolant from vehicle. Refill coolant using manufacturer specific coolant, bleed air from the system, and test drive vehicle. Allow vehicle to cool down and recheck coolant level, top off as needed.	
Parts & Brake Cleaner		1.00	7.82	7.82	The fuel bowl on the front carburetor is leaking, the suction hoods need to be cleaned and oiled, Suggest repair of the leaking fuel bowl, and cleaning and oiling of both carburetor suction hoods and replacing necessary gaskets.	918.00
St1000					Performed as requested.	
WASTE- CAL EPA#000424582		1.00	3.50	3.50	Upon inspection of one spark plug, we found it fouled and black with soot. Suggest cleaning and re-gapping the spark plugs.	255.00
WASTE					Cleaned and gapped spark plugs as requested.	
ENGINE COOLANT		2.00	23.64	47.28	The fuel gauge is not registering on the dash. Further testing is required to determine the cause.	255.00
COOLANT					After removing and testing the dash gauge and removing and testing the fuel level sending unit, we found the fuel level sending unit has failed. Suggest replacement.	
Carb and Choke Cleaner		1.00	18.73	18.73	Install new fuel sending unit.	255.00
8700						
Carb filter including new spring		2.00	17.67	35.34		
370-270						
Float chamber gasket		2.00	2.97	5.94		
294-900						
Fuel Sending Unit		1.00	191.23	191.23		
011-312						
BATTERY- 36 MONTH (After 30 Months ProRated)		1.00	219.95	219.95		
MTP-94R/H7						
California Battery Recycling Fee		1.00	2.00	2.00		
MTP-94R/H7						

Four Car Garage
 839 N San Mateo Dr
 San Mateo, CA. 94401
 Phone: 650-342-3844
 Meticulous Maintenance by Passionate Professionals

INVOICE

115657

Org. Est. # 229745
 BAR# ARD00286600
 EPA# CAL000424582

INVOICE

Printed Date: 11/14/2023

Work Completed: 11/14/2023

1956 Jaguar - XK140 -

Lic #: XK140DH

Odometer In : 73312

Unit #: body P5346

VIN #: AU19883DN

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
					Remove old fuel sender and install new gasket, fuel sender, test operations as requested.	
					We found the brake lights and the turn signal lights are not working during our inspection. Suggest testing and determine why the lights are not working.	255.00
					Tested and found a poor contact and also a blown fuse. Replaced fuse and lights working as normal after testing.	
					The wipers are not working. This will require further diagnostic time to determine the cause.	255.00
					We performed testing and found voltage drop at fuse box. Replaced fuse and now the wipers are working.	
					The front wheel bearings were found to have excessive play. Suggest front wheel bearing adjustment.	306.00
					Performed adjustment as requested.	
					The battery has failed the load test and does not start the car. Suggest replacement.	204.00
					While the left front wheel is off for inspection, remove the old battery and install a new battery as requested.	
					TODAY'S NOTES: (11-14-23)	
					Front Brake Shoes: 6mm Material Remaining	
					Rear Brake Shoes: 4mm Material Remaining	
					Battery tested: Battery failed load test and fails to start the vehicle. A new battery was installed today.	
					The wipers were not functioning upon arrival. The brake lights and signals were also not working upon arrival. We found blown fuses and after replacement these items are working at this time.	
					We see some minor leaks that are normal for this vintage vehicle. We will monitor them at the next service and advise when repairs are required.	
					All four tires were measured at 10/32nds and appear to be wearing evenly at this time. We found the right rear wheel knock off was slightly loose, the other three wheels were tight upon arrival.	
					Vehicles equipped with knock-off style wheels should have the wheels checked for tightness every 50-100 miles. We checked and confirmed the wheels are tight at this time.	
					We have checked and adjusted your tire pressures to specification.	
					In/Out In/Out	
					FL: 23/30 FR: 23/30	
					RL: 23/30 RR: 23/30 SPARE: 27/30	
					THANK YOU FOR CHOOSING THE FOUR CAR GARAGE!	
					Tow from Four Car Garage to Auto-Vino	157.50
					Towed as requested.	
					[Recommendations]	
					NEXT MAINTENANCE IS SUGGESTED AT 76,312 MILES.	

Four Car Garage
 839 N San Mateo Dr
 San Mateo, CA. 94401
 Phone: 650-342-3844
 Meticulous Maintenance by Passionate Professionals

INVOICE

115657

Org. Est. # 229745
 BAR# ARD00286600
 EPA# CAL000424582

INVOICE

Printed Date: 11/14/2023

Work Completed: 11/14/2023

1956 Jaguar - XK140 -
 Lic # : XK140DH Odometer in : 73312
 Unit # : body P5346
 VIN # : AU19883DN

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
------------------	--------	-----	------	-----	-------------------	-----

Org. Estimate 933.36 Revisions 3,827.35 Current Estimate 4,760.71

Revision # 1, Previous Estimate Amount: 933.36, Additional Cost: 3362.71, Revised Estimate: 4296.07, Parts: \$369.96 Labor: \$2958.00 Sublet: \$0.00
 Taxes & Fees: \$34.75 Authorized by - Couch, John, Date - 11/1/2023, Time - 10:04 AM, Initiated By - Shop, Written By - Johnson, Albert, Reason -
 appr/bff/cool/crbwrk/placln/bat/bma/d. Phone Number - Received E-mail

Revision # 2, Previous Estimate Amount: 4296.06, Additional Cost: 464.64, Revised Estimate: 4760.70, Parts: \$191.23 Labor: \$255.00 Sublet: \$0.00
 Taxes & Fees: \$18.41 Authorized by - Couch, John, Date - 11/7/2023, Time - 9:52 AM, Initiated By - Shop, Written By - Johnson, Albert, Reason -
 appr/fuel sending unit replacement, Phone Number - Received E-mail

Labor:	3,863.25
Parts:	641.46
Sublet:	367.95
SubTotal:	4,872.66
Tax:	60.54
Total:	4,933.20
Bal Due:	\$4,933.20

[Payments -]

INTENSIVE CARE FOR YOUR AUTOMOBILE

Vehicle Received: 11/14/2023

Customer Number : 19957

Thank you for trusting us to take care of your vehicle. Buyer of this product/service has the right to have this product serviced or repaired during the warranty period. Unless otherwise noted above, warranty on parts and labor for maintenance items is 12 Months or 12,000 miles, whichever comes first. Warranty on parts and labor for repair items is 12 Months or 12,000 miles, whichever comes first (unless noted otherwise). Warranty work must be performed in our shop (without prior authorization) & cannot exceed the original cost of repair. Additional costs incurred (towing, rental, hotels, etc.) will not be covered.

Signature _____ Date _____

Visit us on the web: www.fourcargarage.com

Service Advisor : Johnson, Albert, Tech : KALDOR, DAVID