

Fourintune

Garage Incorporated

November 13, 2000

Re: Austin Healey 100 S quotation

Dear

Enclosed is the quotation for the 100 S that we have been working on. At the very beginning is a *Options list which totals \$4670. A large item on that list is the windshield restoration which we will need to inspect and discuss when you come out in December.

After the options list are two pages which have items we know are being sent (Wood) or that you are doing (steering wheel and wings etc.) and other items that are still undecided.

The basic quotation totals \$62,547 plus any options you choose from the list. This written quotation is the starting point and a very complete inspection has been done since the car was disassembled, the panels all have been stripped and the car was running which helped when figuring mechanicals.

You have already sent your proof of insurance from Haggerty and the car will not be at the 5370 Hwy M, West Bend, WI storage facility until late spring when we are finished with the car.

Terms for the restoration are as follows:

25% downpayment - 15636

25% chassis repairs done enough to install body, repairs on outer body 31 273.50
panels completed (new alloy nose, etc.)

25% when chassis painted and engine installed - 46909


15% exterior painted white 54727

10% upon completion (7820) = 62547

97,470.14 - Jan 2000

Please make notes on your copy so that we will be able to go through the quote when you come on December 10th. We will be able to look at what needs to be decided and I will record changes and decisions so we all have the same "game plan." Please remind me of your flight times after Thanksgiving.

Sincerely,


Kaye E. Kovacs
FOURINTUNE GARAGE INC.
Vice President

W63 N147 Washington Avenue • PO BOX 4 • Cedarburg, WI 53012

FAX: 262-675-2874

www.fourintune.com

PHONE: 262-375-0876

Fourintune

Garage Incorporated

2001

April 25, 2001

Re: AH 100 S #3802

Enclosed is an update on what is completed on the car to date of April 16th. I have shown payments, credits (mostly stuff you brought in from UK) and the authorized extras that we have done so far.

The second page lists each quotation page total, options complete and work completed for each page. Work completed including some options, and extras to date is \$50,534.00. Notes detail options and list some unknown items we are still waiting on from chrome shop.

Total you have paid to date is \$47,314.00 which is itemized on first page. This brings you to date on our "regular" terms - 75% paid when body is final hung. We will need a check for \$10,000 soon. Please call if you have any questions.

Thanks,

Kaye E. Kovacs
FOURINTUNE GARAGE INC.

47314
~~10000~~
57314
+11

6850

47314
pd - 11000

58314

Quote
63000

W63 N147 Washington Avenue • PO BOX 4 • Cedarburg, WI 53012

FAX: 262-675-2874

www.fourintune.com

PHONE: 262-375-0876

100 S payments

Jan-00 check for paint	300.00	
5/10/2000 Kilmartin parts shipped with car	1,314.00	
11/17/2000 check #3587	5,000.00	
12/10/2000 cashiers checks	16,000.00	
12/10/2000 cash	21,000.00	
12/10/2000 discount	3,700.00	
TOTAL PAID		\$47,314.00

	CREDITS	
page 14	new adj. Steering assy tubes and detail	140.00
page 17	customer supply front side lights	150.00
	use Woods spare wheel bracket	150.00
page 33	customer supply wood seat bottoms	176.00
	customer supply foam cushions	80.00
	customer supply foam seat backs	50.00
	TOTAL CREDITS (to date of 4-16-01)	\$746.00

EXTRAS		
	Kilmartin (ordered later) skirt brace	30.00
	center support	20.00
	tank neck, bolt holes, sender & pick-up	320.00
	W/S frame weld holes & refinish Woods frame	240.00
	move transmission mounts	250.00
	right angle drive supply used	30.00
	make brake nuts, brass adjusters (1 steel 1 was stripped)	80.00
	make float bowl brackets	40.00
	make brake steady and fix rod and end	120.00
	vaccum line and fix front carb	80.00
	supply oil filter - found metal in oil cooler	30.00
	correct stop light switch	30.00
	make proper shock link	50.00
	rear shocks- check and bolts page 21	40.00
	100 M sway bar page24	65.00
	grooved rubber material for floors page 34	175.00
	fit trunk to rear shroud page 3	330.00
	TOTAL EXTRAS (to date of 4-16-01)	\$1,930.00

page # basic quote options*taken notes

work completed 4/16/01

1	\$3,770.00		\$3,770.00 ✓
2	\$10,005.00	\$500.00 insulation option <i>OK</i>	\$10,505.00 ✓
3	\$3,890.00	see extras for additional trunk labor + 330	\$3,890.00 ✓
4	\$18,150.00		(7,350) — \$10,800.00
5	\$347.00		(142) — \$205.00
6	\$5,240.00		(2577) — \$2,663.00
7 (new)	\$544.00	rechrome fndr spears & trunk handle price ??	\$544.00 ✓
8 (new)	\$1,040.00	\$145.00 rechrome handbrake & shifter/grill & beads??	\$1,040.00
9 (new)	\$611.00	hood strap ends rechrome price unknown	\$611.00
10 (new)	\$970.00	guages in UK labor to paint exhaust???	\$970.00
11	\$415.00	add \$75 for water pump gasket John Bull	\$390.00
12	\$980.00	\$570.00 fuel line option @120 & OH carbs etc @450	\$1,470.00
14	\$1,380.00	\$500.00 sub harness option @350 zinc clips @150	\$1,740.00
15	\$1,185.00		\$1,185.00
17	\$1,742.00	see credit list lights and spare tire bracket	\$72.00
18	\$250.00		\$250.00
19	\$371.00		\$371.00
20	\$487.00		\$487.00
21	\$220.00		\$220.00
22	\$136.00		\$136.00
23	\$0.00	\$550.00 options taken: wishbone detail & front shocks	\$550.00
24	\$150.00		\$150.00
25	\$750.00		\$750.00
26	\$750.00		\$750.00
27	\$490.00		\$490.00
28	\$120.00		\$120.00
30	\$1,000.00		\$1,000.00
31	\$0.00		\$0.00
32	\$1,180.00		\$415.00
33	\$2,251.00	see credit customer supply seat wood & foam	\$795.00
34	\$3,050.00	grooved rubber on extras list	none to date
	\$61,474.00	\$2,265.00 TOTALS	\$46,339.00
		Total work completed plus options	\$48,604.00
		Extras completed (see list other page)	\$1,930.00
		Work completed to date 4/16/01	\$50,534.00

Fourintune
 W63 N147 Washington Ave.
 Cedarburg, WI 53012

262-375-0876 shop phone
 262-675-2874 fax
 e-mail: fntune@execpc.com
 www.fourintune.com

NAME	
ADDRESS	
YEAR	
MAKE	AT
MODEL	1005
COLOR	
LICENSE	
SPEEDOMETER	
DATE	6-10-02
HOME PHONE	
WORK	
FAX	

Quan.	PART NO.	DESCRIPTION	PRICE		
		TURN ROTORS	400	-	CHECK OIL PRESSURE 450 -
		CHROME ROTORS (4)	1000	-	
		3 PIECE CLUTCH	290	-	R&R TRANS 400 -
		UPS SPECIAL BULBS	85	-	TOUCH UP CHIPS, FENDER CRACKS 200 -
		GAS	10	-	BURNT WHEEL WELLS
		UPS CLOTHES TO CA	35	-	ASSEMBLE TUNNEL & TUNG 250 -
10	QT 20W50		25	-	OH DISTRIBUTOR (SPRINGS)
		DISMOUNT 5 TIRES			TORQUE HEAD
		MOUNT & BALANCE 4	200	-	ADJUST VALVES (1015 NOT 008)
4	60 SPOKE PAINTED SILVER				CHECK OIL PAN (EPOXY) 750 -
	RAYON WHEELS		800	-	SET UP (CHAS DASHPTS EMPTY)
	WHEELS: FREIGHT		150	-	FIX ROCKER 5 (DND PLUGS MISSING)
					MAKE VALVE COVER GSKT
					GLUED DOWN
					* NOTE: FRONT & REAR WHEELS
					ARE DIFFERENT OFFSET
					NOT INTERCHANGEABLE
					SCUFF & PAINT 2 WHEELS
					CLEAN ROUSH WINDSHIELD
					START WGT SAND TOUCH UPS 500 -
					+ BUFF
			3031	-	SCUFF & PAINT 2 WHEELS
					& WHEEL WEIGHTS 320 -
					TOUCH UP - BUFF + DETAIL 500 -
					FIX THROTTLE LINKAGE (LOOSE)
					FIX CLUTCH LINKAGE (BACKWARD)
					ADJUST HAND BRAKE 700
					FLACK HYPOID OIL
					SHIM FRONT CRAPERS (MAKE SHIM)
					MAKE LF BRAKE LING 300
					REMOVING EXHAUST - MAKE MANIFOLD
					GASKET & INSTALL 200
					SAFETY WIRE FRONT BRAKES 150
					4120 -
					TOTAL \$7151-
					SHIP VIA PASSEPORT TRANSPORT

Denis Welch Motorsport

Sudbury Road

Yoxall

Burton on Trent

Staffordshire

DE13 8NA

Tel. 01543 472214 Web. <http://www.bighealey.co.uk>

Fax. 01543 472339 E-Mail sales@bighealey.co.uk

011-44-1543--

Invoice

Page 1

PARTS HOTLINE (0044) 01543 472

Processed By : Jonathan

37863

12/04/2002

GRI001

Customer V.A.T. No.

Payment Method

c/c

Quantity	Part Number	Product Description	Unit Price	Total
1.00	SCENG495AF	Head - Fully GasFlowed - 100/S A01	2300.00	2,300.00

2450.
1275

1175

DELIVERED VIA UPS Express

Goods Total	2,300.00
Carriage & Packing	149.50
Sub Total	2449.50
VAT 0.00 %	0.00
Invoice Total	2,449.50

V.A.T. No. GB 295 3285 28



British Car Repair



www.britishcarrepair.com

ESTIMATE

Page 1
Est Date: 08/14/02 02:06 pm

BAR #: A1 157297
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

Quotes

1 08/30/02 01:54pm 821.42
by phone 415-453-0820

56 AUSTIN HEALE 100S WHITE
2038 Mi.
Lic: 8N65112/CA 4Cyl Eng
Vin:
Equipment:
Profile:

OVERDRIVE

Labor: \$255.00

REFIT WIRES AT FUSE BOX TO REPAIR OVERDRIVE.
REPLACE OVERDRIVE SOLENOID - PART SUPPLIED BY OWNER.

IGNITION

Labor: \$225.00

REPLACE IGNITION POINTS AND CONDENSOR, SECURE LOOSE LOW TENSION CONNECTION AT DISTRIBUTOR.
REPLACE IGNITION COIL AND ROTOR ARM.
PARTS SUPPLIED BY OWNER.

HOSE

Labor: \$85.00

REPLACE UPPER RADIATOR HOSE.

DAY DAY76975	HOSE REDUCER-S	1.0 @	10.50 =\$	10.50	
DAY 81141	HOSE UPPER-S	1.0 @	13.80 =\$	13.80	24.30

EXHAUST

Labor: \$225.00

REMOVE EXHAUST DOWNPIPE AND MUFFLER TO RESEAL DOWNPIPE FLANGE.
REASSEMBLE AND ROAD TEST.

GASKET	GASKET MATERIAL-S	1.0 @	5.00 =\$	5.00	5.00
--------	-------------------	-------	----------	------	------

WHEEL BEARING

Labor: \$510.00

REPLACE LEFT REAR WHEEL BEARING AND SEAL.
NOTE: PARTS WERE SUPPLIED BY OWNER.

SLS 710162	SEAL-S	1.0 @	15.00 =\$	15.00	
------------	--------	-------	-----------	-------	--

----->----->----->-----Continued on the next page----->----->----->-----

ESTIMATE

Est Date: 08/14/02 02:06 pm

BAR #: A1 157297
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

www.britishcarrepair.com

	56 AUSTIN HEALE 1001M WHITE 2038 Mi. Lic: 8N65112/CA 4Cyl Eng Vin: Equipment: Profile:
--	---

OVERDRIVE	Labor: \$255.00
------------------	-----------------

REFIT WIRES AT FUSE BOX TO REPAIR OVERDRIVE.
REPLACE OVERDRIVE SOLENOID - PART SUPPLIED BY OWNER.

IGNITION	Labor: \$225.00
-----------------	-----------------

REPLACE IGNITION POINTS AND CONDENSOR, SECURE LOOSE LOW TENSION CONNECTION AT DISTRIBUTOR.
REPLACE IGNITION COIL AND ROTOR ARM.
PARTS SUPPLIED BY OWNER.

HOSE	Labor: \$85.00
-------------	----------------

REPLACE UPPER RADIATOR HOSE.

DAY DAY76975	HOSE REDUCER-S	1.0 @	10.50 =\$	10.50	
DAY 81141	HOSE UPPER-S	1.0 @	13.80 =\$	13.80	24.3

EXHAUST	Labor: \$225.00
----------------	-----------------

REMOVE EXHAUST DOWNPIPE AND MUFFLER TO RESEAL DOWNPIPE FLANGE.
REASSEMBLE AND ROAD TEST.

GASKET	GASKET MATERIAL-S	1.0 @	5.00 =\$	5.00	5.00
--------	-------------------	-------	----------	------	------

Recommendations: LEFT REAR AXLE SEAL LEAKS. RECOMMEND REPLACEMENT.
EXHAUST MANIFOLD FLANGE HAS ONE BROKEN STUD.
RECOMMEND NEW EXHAUST DOWNPIPE.

Tax: \$2.00
Estimate Total: \$821.00

Thank you for choosing Ed Wright's British Car Repair

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. I further understand and agree that I may be charged for incidental shop supplies. All parts will be discarded unless instructed otherwise. Parts and labor are warrantied for a period of six months or six thousand miles, whichever comes first. All warranty repairs must be performed by this garage.

(Signature) _____



British Car Repair



www.britishcarrepair.com

ESTIMATE

BAR #: A1 157297
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

2002

	56 AUSTIN HEALE 100S WHITE 2038 Mi. Lic: 8N65112/CA 4Cyl Eng Vin: Equipment: Profile:
--	--

Quotes	
1 12/16/02 04:37pm	1700.01
in person.	

SERVE	Labor: \$150.00
--------------	------------------------

CHANGE ENGINE OIL. CHECK\TOP-UP FLUID LEVELS.
INSPECT LIGHTS, BRAKE PADS, WHEEL BEARINGS, FAN BELT
TENSION, TIRE PRESSURE AND SPARE. ROTATE TIRES WHERE
NECESSARY. LUBRICATE CHASSIS AND GREASE FITTINGS.
SECURE SHOCK ABSORBER BOLTS.

OIL 20\50	OIL-N	12.0 @	2.55 =\$	30.60	30.60
-----------	-------	--------	----------	-------	-------

EXHAUST	Labor: \$255.00
----------------	------------------------

REMOVE EXHAUST DOWNPIPE AND MUFFLER TO DRILL OUT BROKEN EXHAUST MANIFOLD STUDS.
HELICOIL MANIFOLD TO ACCEPT NEW STUDS.

DOR 680-002	BRASS NUT-S	5.0 @	0.65 =\$	3.25	
STUD	MANIFOLD STUD-S	5.0 @	1.00 =\$	5.00	8.25

LEAF SPRING	Labor: \$170.00
--------------------	------------------------

REPAIR AND SECURE LEAF SPRING RETAINER CLAMPS.

EXHAUST	Sublet: \$400.00
----------------	-------------------------

CUSTOM BUILT EXHAUST FLANGE AND PIPE TO MUFFLER.

MANIFOLD	Labor: \$680.00
-----------------	------------------------

REMOVE EXHAUST MANIFOLD FOR WELDING REPAIRS AFTER FLANGE BROKE.
REASSEMBLE AND ROAD TEST.

Haz Waste:	\$3.34
Tax:	\$2.82
Estimate Total:	\$1,700.01

PAID *Chad*

I hereby authorize the above signatory to be driving the above vehicle and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. I further understand and agree that I may be charged for incidental shop supplies. All parts will be discarded unless instructed otherwise. Parts and labor are warranted for a period of six months or six thousand miles, whichever comes first. All warranty repairs must be performed by this garage.

(Signature) _____




British Car Repair



www.britishcarrepair.com

ESTIMATE

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707



56 AUSTIN HEALE 100S WHITE
6393 Mi.Last in 12/16/02
Lic: 8N65112/CA 4Cyl Eng
Vin:
Equipment:
Profile:

Quotes
1 06/03/04 05:28pm 626.49
in person.

SHOCK LINK ASSY

Labor: \$100.00

CHANGE RIGHT REAR SHOCK LINK ASSEMBLY.

031-398	SHOCK LINK ASSY-S	1.0 @	50.00 =\$	50.00	
031-390	TOP TRUNNION KIT-S	2.0 @	15.00 =\$	30.00	80.00

SERVE

Labor: \$400.00

CHANGE ENGINE OIL AND FILTER. CHECK\TOP-UP FLUID LEVELS.
INSPECT LIGHTS, BRAKE PADS, WHEEL BEARINGS, FAN BELT
TENSION, TIRE PRESSURE AND SPARE. ROTATE TIRES WHERE
NECESSARY. LUBRICATE CHASSIS AND GREASE FITTINGS.

OIL 10\30	OIL 10\30-N	8.0 @	2.55 =\$	20.40	20.40
-----------	-------------	-------	----------	-------	-------

BUSHINGS

Labor: \$150.00

REPLACE FRONT SHOCK ABSORBER LINK BUSHINGS AND BOLT\NUT.

EXHAUST

Labor: \$100.00

INSPECT EXHAUST AND FACILITATE REPAIR OF LEAK.

EXHAUST

Sublet: \$225.00

REPAIR CRACKS IN EXHAUST PIPE.
RESIZE PIPES AND MUFFER INLET TO FIT.
WELD PIPES TO MUFFLER.
REPOSITION MUFFLER.
REPLACE EXHAUST FLANGE GASKET (CUSTOMER SUPPLIED).

Recommendations: OBTAIN MORE EXHAUST FLANGE GASKETS FOR SPARES.

----->----->----->-----Continued on the next page----->----->----->-----



British Car Repair

www.britishcarrepair.com

ESTIMATE

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

2008



56 AUSTIN HEALE 100S WHITE
14170 Mi. Last in 12/16/2002
Lic: 8N65112/CA 4Cyl Eng
Vin:
Eq:
Profile:

Quotes
1 02/20/09 10:44am 1127.09
in person.

WATER PUMP
DRAFT TUBE TO SIDE COVER
FRONT ENGINE PLATE
FRONT MAIN SEAL

FUEL TANK Labor: \$350.00

REMOVE FUEL TANK TO HAVE RESEALED.
HAVE TANK PAINTED.
REFIT TANK TO VEHICLE, FIT WITH FUEL AND ROAD TEST.

GAS GASOLINE-N 20.0 @ 1.00 =\$ 20.00 20.00

TANK REPAIR Sublet: \$150.00

FUEL TANK REPAIRS - FIX LEAKS.

TANK PAINTING Sublet: \$400.00

PREP (BONDO, SANDING, PAINT REPAIRS) AND PAINT FUEL TANK.

SERVE Labor: \$165.00

CHANGE ENGINE OIL AND FILTER. CHECK\TOP-UP FLUID LEVELS.
INSPECT LIGHTS, BRAKE PADS, WHEEL BEARINGS, FAN BELT
TENSION, TIRE PRESSURE AND SPARE. ROTATE TIRES WHERE
NECESSARY. LUBRICATE CHASSIS AND GREASE FITTINGS.
NOTE: OIL FILTER SUPPLIED BY OWNER.

OIL 20\50 OIL-N 10.0 @ 3.75 =\$ 37.50 37.50

Recommendations:

----->----->----->---Continued on the next page--->----->----->----->

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. Storage charges of \$50 per day will start two days after repairs are completed. Payment must be in cash if vehicle is left for more that two days after repairs have been completed. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a six month warranty on parts and labor. All warranty repairs must be performed by this shop.

(Signature) _____



British Car Repair



www.britishcarrepair.com

ESTIMATE

Page 2
Est Date: 12/23/08 04:14 pm

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

Payments to Ed Wright's British Car Repair

Cost Summary

Status: Estimate

Payments:

Labor	515.00
Parts	37.50
Non Taxable	20.00
Sublet	550.00
Haz Waste	1.50
Subtotal	1,124.00
Tax	3.09
Total	\$1,127.09
Payments	0.00
Bal Due	1,127.09

Thank you for choosing Ed Wright's British Car Repair

Suddury Road
Yoxall
Burton on Trent
Staffordshire
DE13 8NA

Tel. +44 (0) 1543 472214 Web www.bighealey.co.uk
Fax. +44 (0) 1543 472339 E-Mail sales@bighealey.co.uk
PARTS HOTLINE +44 (0) 1543 472244

Stores Invoice

Page 1



Invoice Number	58447
Processed By :	Jonathan
Invoice/Tax Date	10/02/2009
Cust. Order No.	
Account Number	GRI005
Payment Reference	

Intra-community supply, subject to VAT in the country of acquisition
Customer VAT No. US

Quantity	Part Number	Product Description	Unit Price	Discount %	Net Amount
1.00	CENG580	100/4 Inspection front cover with lip sea	128.75		128.75
1.00	SURCHARGE1	Surcharge for Exchange CENG580	200.00		200.00
2.00	SENG688K	100S Oil Filter Element Kit	48.75		97.50
1.00	SCHT110	100/s top hose	16.97		16.97
1.00	CENG305	Gasket - side cover	1.42		1.42
1.00	CENG301	Gasket - timing cover	3.06		3.06
2.00	CATAH	BIG HEALEY 2007/8 Catalogue	0.00		0.00

~~Barcode~~

SR
acct

815.72
48.76
864.48

864.48
512.69
* 351.79

RETURN MERCHANDISE POLICY:

No merchandise may be returned for any reason unless prior written permission has been obtained from Denis Welch Motors. All parts approved for return must be shipped prepaid and insured, and must be accompanied by the original invoice or date of invoice. A 15% service charge will be deducted on all returned merchandise, except in the case of factory error.

DENIS WELCH MOTORS LIMITED

Delivery Address: Delivered Via UPS expedite

Unless otherwise stated all goods are of uk origin

Goods Total	447.70
Carriage & Packing	64.99
Sub Total	512.69
VAT %	0.00
Invoice Total	512.69

All amounts are in GBP



ALL PAID TO DATE WITH THIS INVOICE

7/13/07/-pd to date > \$1,262.00

ESTIMATE

Est Date: 03/27/09 04:27 pm


British Car Repair

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

3/21/08 - \$209.56
12/10/08 - \$395.51
12/23/08 - \$1127.09
3/27/09 \$1700.00

www.britishcarrepair.com

\$3632.16
120
\$3753.44^a



56 AUSTIN HEALE 100S WHITE
14397 Mi. Last in 12/16/2002
Lic: 8N65112/CA 4Cyl Eng
Vin:
Eq:
Profile:

WATER PUMP, T\COVER Labor: \$1,100.00

REPLACE WATER PUMP AND TIMING COVER WITH UPGRADED FRONT SEAL.
RESEAL SIDE COVER TO BLOCK, DRAFT TUBE AND DISTRIBUTOR.
FIT NEW WASHERS TO OIL FEED PIPE.
ROAD TEST VEHICLE.
PARTS SUPPLIED BY OWNER.
SEE RECOMMENDATIONS.

Kids Total \$9990^{or} 4/10/09

LEAK DOWN TEST Labor: \$100.00

PERFORM COMPRESSION AND LEAK DOWN TEST.
1) 155 2) 160 3) 155 4) 145 PSI
1) 80% 2) 7% 3) 19% 4) 85% LEAKAGE
CLEAN SPARK PLUGS. CYLS #1 & #4 ARE LEAKING EXCESSIVELY.

ENGINE REMOVAL Labor: \$500.00

REMOVE ENGINE FROM VEHICLE.

Recommendations: HEAD GASKET LEAKS.
EXCESSIVE CYLINDER LEAK DOWN CYLS #1 & #4.
OIL PAN LEAKS AT FRONT RIGHT CORNER.
STEERING BOX LEAKS.
TACHOMETER INNER CABLE NEEDS REPLACEMENT.

\$pd hand
\$2025.49
Core
Mon. 13 April

Payments to Ed Wright's British Car Repair Cost Summary

Labor	1,700.00
Parts	0.00
Subtotal	1,700.00

----->----->----->-----Continued on the next page----->----->----->-----

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. Storage charges of \$50 per day will start two days after repairs are completed. Payment must be in cash if vehicle is left for more than two days after repairs have been completed. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a six month warranty on parts and labor. All warranty repairs must be performed by this shop.

(Signature) _____


Denis Welch Motorsport

Sudbury Road
Yoxall
Burton on Trent
Staffordshire
DE13 8NA

Tel. +44 (0) 1543 472214 Web www.bighealey.co.uk

Fax. +44 (0) 1543 472339 E-Mail sales@bighealey.co.uk

PARTS HOTLINE +44 (0) 1543 472244



Intra-community supply, subject to VAT in the country of acquisition
Customer VAT No. US



Stores Invoice

Page 1

Invoice Number	59301
Processed By :	Jonathan
Invoice/Tax Date	29/04/2009
Cust. Order No.	
Account Number	GRI005
Payment Reference	6667

Quantity	Part Number	Product Description	Unit Price	Discount %	Net Amount
1.00	CENG409	88mm Pistons - dished M spec	303.85		303.85
1.00	CENG432K	Steel Crankshaft 4 Cyl	1,950.00		1,950.00
1.00	CENG432R	Steel Rod Set-for Steel Crank	1,075.00		1,075.00
1.00	ENG423	Mains Set - Standard	29.50		29.50
2.00	CENG419	Big End Set (Std) Steel Crank	28.46		56.92
1.00	ENG428	Thrust Washer - STD	5.95		5.95
1.00	CENG635SO	Steel Flywheel 8 ORG. Holes	272.95		272.95
1.00	ENG635	Starter Ring Gear (0.625")	32.78		32.78
8.00	ENG637	ARP Flywheel Bolt	4.28		34.24
1.00	CENG649V	Vernier Cam Sprocket	89.95		89.95
1.00	CENG648	Timing Chain - competition	24.00		24.00
1.00	CENG640	Crank Sprocket - lightened	38.24		38.24
1.00	CENG590	Rear Crank Seal Kit	49.50		49.50
1.00	CENG402	Aluminum back plate BN1 to BN2	95.00		95.00
1.00	CENG467S	Aluminium Sump - 100/4	160.00		160.00
1.00	CENG465	Flexible Oil Hose	32.78		32.78
1.00	ENG466	Oil Pump (less shaft)	199.00		199.00
1.00	SENG465	100S Oil pump Drive Shaft	175.00		175.00
1.00	ENG402	Bottom Gasket Set	20.55		20.55
1.00	SENG546	100s Manifold to Head Gasket	9.75		9.75
1.00	SENG539	100s Rocker Cover Gasket	7.88		7.88
8.00	CENG460	Cam Followers - modified	10.82		86.56
1.00	ENG459	Cam Shell Set	30.28		30.28
1.00	SENG561	100/S Head Studs & Nuts	95.00		95.00

RETURN MERCHANDISE POLICY:

No merchandise may be returned for any reason unless prior written permission has been obtained from Denis Welch Motors. All parts approved for return must be shipped prepaid and insured, and must be accompanied by the original invoice or date of invoice. A 15% service charge will be deducted on all returned merchandise, except in the case of factory error.

Denis Welch Motorsport

Sudbury Road
Yoxall
Burton on Trent
Staffordshire
DE13 8NA

Tel. +44 (0) 1543 472214 Web www.bighealey.co.uk

Fax. +44 (0) 1543 472339 E-Mail sales@bighealey.co.uk

PARTS HOTLINE +44 (0) 1543 472244



Stores Invoice

Page 2

Invoice Number	59301
Processed By :	Jonathan
Invoice/Tax Date	29/04/2009
Cust. Order No.	
Account Number	GR1005
Payment Reference	6667

Intra-community supply, subject to VAT in the country of acquisition
Customer VAT No. US

Quantity	Part Number	Product Description	Unit Price	Discount %	Net Amount
11.00	SENG561W	1/2" 100/S Head Washers	1.10		12.10
4.00	CENG417A	Cylinder Liner	36.00		144.00
1.00	CLU101	9" Cover BN1 - BN6	94.99		94.99
1.00	CLU106	9" Std Clutch Plate BN2	56.65		56.65
1.00	CLU110	Clutch Release Thrust	32.50		32.50
1.00	CCLU123	Clutch Linkage - Uprated 100/4	81.37		81.37
1.00	S1	Balance crank line	90.00		90.00
8.00	CENG633C	Crank Insert - flywheel	3.95		31.60
6.00	516075NF	5/16 x 3/4 UNF Bolt z/p	0.24		1.44
6.00	516SW	5/16 Spring Washer Rect z/p	0.03		0.18

RETURN MERCHANDISE POLICY:

No merchandise may be returned for any reason unless prior written permission has been obtained from Denis Welch Motors. All parts approved for return must be shipped prepaid and insured, and must be accompanied by the original invoice or date of invoice. A 15% service charge will be deducted on all returned merchandise, except in the case of factory error.

DENIS WELCH MOTORS LIMITED

Delivery Address/Delivered Via UPS expedited

A Division of Denis Welch Motors Ltd

Unless otherwise stated all goods are of uk origin

Goods Total	5,419.51
Carriage & Packing	219.60
Sub Total	5639.11
VAT %	0.00



ESTIMATE

Est Date: 05/20/09 10:04 am

British Car Repair

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

Mcork - 76.00
Freight

Mcork - 225.00
Freight

www.britishcarrepair.com

56 AUSTIN HEALE 100S WHITE
14397 Mi. Last in 12/16/2002
Lic: 8N65112/CA 4Cyl Eng
Vin:
Eq:
Profile:

paid \$1000 5-26-09
PD \$2000 7/22/09

PAID # 5752 Clint 9-8-09

ENGINE REPAIR Labor: \$650.00

DISASSEMBLE ENGINE AND DELIVER TO MACHINE SHOP.
CONSULT WITH PARTS SUPPLIER AND MACHINIST RE NEEDED REPAIRS.

Table with 5 columns: Part Name, Description, Quantity, Unit Price, Total Price. Includes items like SLEEVE, SEAL, GAS, and RADIATOR HOSE-S.

MACHINE WORK Sublet: \$2,000.00

GRIND REAR MAIN SEAL SURFACE.
REMOVE FLYWHEEL LUGS.
R&R SLEEVES IN BLOCK.
BORE CYLINDERS TO 88MM PER INSTRUCTED BY CUSTOMER. THIS GIVES .004" TO .0045" CLEARANCE.
INSTALL PISTONS TO RODS.
SURFACE 4 CYL BLOCK - MACHINED .002"

----->----->----->-----Continued on the next page----->----->----->



British Car Repair



www.britishcarrepair.com

ESTIMATE

Page 2
Est Date: 05/20/09 10:04 am

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

MACHINE WORK

- R&R CAM BEARINGS.
- DEGREASE BLOCK.
- REMOVE BROKEN PAN BOLT.
- PRESSURE TEST CYLINDER HEAD.
- SURFACE CYLINDER HEAD.
- PERFORM VALVE JOB.
- WASTE DISPOSAL CHARGE.

SPACERS

MACHINE SPACERS FOR ROCKER ASSEMBLY.

Sublet: \$60.00

RADIATOR

CLEAN AND SERVICE RADIATOR.

Sublet: \$140.00

PILOT BUSHING

MACHINE PILOT BUSHING

Sublet: \$55.00

③ \$255.00 *[Handwritten initials]*

ENGINE ASSEMBLY

REASSEMBLE ENGINE AND INSTALL IN VEHICLE.
ROAD TEST AND MAKE ADJUSTMENTS\SETTINGS.

① Labor: \$5,000.00

Recommendations: OIL PAN LEAKS AT FRONT RIGHT CORNER.
STEERING BOX LEAKS.
TACHOMETER INNER CABLE NEEDS REPLACEMENT.

----->----->----->-----Continued on the next page----->----->----->-----

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. Storage charges of \$50 per day will start two days after repairs are completed. Payment must be in cash if vehicle is left for more that two days after repairs have been completed. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a six month warranty on parts and labor. All warranty repairs must be performed by this shop.

(Signature) _____



ESTIMATE

Est Date: 05/20/09 10:04 am

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

British Car Repair


www.britishcarrepair.com

	56 AUSTIN HEALE 100S WHITE 14397 Mi. Last in 12/16/2002 Lic: 8N65112/CA 4Cyl Eng Vin: Eq: Profile:
--	---

paid \$1000 5-26-09 *[Signature]*

ENGINE REPAIR

Labor: \$700.00

DISASSEMBLE ENGINE AND DELIVER TO MACHINE SHOP.
CONSULT WITH PARTS SUPPLIER AND MACHINIST RE NEEDED REPAIRS.

Recommendations: HEAD GASKET LEAKS.
EXCESSIVE CYLINDER LEAK DOWN CYLS #1 & #4.
OIL PAN LEAKS AT FRONT RIGHT CORNER.
STEERING BOX LEAKS.
TACHOMETER INNER CABLE NEEDS REPLACEMENT.

Payments to Ed Wright's British Car Repair	Cost Summary	
Status: Estimate	Labor	700.00
	Parts	0.00
Payments:	FREIGHT	225.00
	Subtotal	925.00
	Total	\$925.00
	Payments	0.00
	Bal Due	925.00

paid separate cash

Thank you for choosing Ed Wright's British Car Repair

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. Storage charges of \$50 per day will start two days after repairs are completed. Payment must be in cash if vehicle is left for more than two days after repairs have been completed. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a six month warranty on parts and labor. All warranty repairs must be performed by this shop.

(Signature) _____

3/2

Denis Welch Motorsport

Sudbury Road
Yoxall
Burton on Trent
Staffordshire
DE13 8NA



Tel. +44 (0) 1543 472214 Web www.bighealey.co.uk
Fax. +44 (0) 1543 472339 E-Mail sales@bighealey.co.uk
PARTS HOTLINE +44 (0) 1543 472244

Stores Invoice

Page 1

Invoice Number	65025
Processed By :	Jonathan
Invoice/Tax Date	05/11/2010
Cust. Order No.	
Account Number	FOU002
Payment Reference	0084

Intra-community supply, subject to VAT in the country of acquisition
Customer VAT No. US

Quantity	Part Number	Product Description	Unit Price	Discount %	Net Amount
4.00	CENG413	88mm Ring Set (omega) / piston			
1.00	CENG419	Big End Set (Std) Steel Crank	29.50		118.00
1.00	SENG546	100s Manifold to Head Gasket	35.32		35.32
1.00	SENG401	Head Gasket - 100/S	9.75		9.75
			123.60		123.60

~~Invoice to be kept on Kent~~

RETURN MERCHANDISE POLICY:

No merchandise may be returned for any reason unless prior written permission has been obtained from Denis Welch Motors. All parts approved for return must be shipped prepaid and insured, and must be accompanied by the original invoice or date of invoice. A 15% service charge will be deducted on all returned merchandise, except in the case of factory error.

DENIS WELCH MOTORS LIMITED

Delivery Address/Delivered Via UPS expedited

Unless otherwise stated all goods are of uk origin

Goods Total	286.67
Carriage & Packing	57.80
Sub Total	344.47
VAT %	0.00



...bury Road
...oxall
Burton on Trent
Staffordshire
DE13 8NA

Tel. +44 (0) 1543 472214 Web www.bighealey.co.uk
Fax. +44 (0) 1543 472339 E-Mail sales@bighealey.co.uk
PARTS HOTLINE +44 (0) 1543 472244

Stores Invoice

Page 1

Invoice Number	65432
Processed By :	Martin
Invoice/Tax Date	23/12/2010
Cust. Order No.	
Account Number	FOU002
Payment Reference	0315

Intra-community supply, subject to VAT in the country of acquisition
Customer VAT No. U.S.

Quantity	Part Number	Product Description	Unit Price	Discount %	Net Amount
1.00	CENG410	88.5mm Pistons - Dished M Spec	345.00	100-S	345.00
1.00	ENG450/1	Camshaft KIT DWRT - New	395.00		395.00
2.00	CENG850S	Seal & Grease for Crank Conv	9.95		19.90

Handwritten: CORREP

RETURN MERCHANDISE POLICY:

No merchandise may be returned for any reason unless prior written permission has been obtained from Denis Welch Motors. All parts approved for return must be shipped prepaid and insured, and must be accompanied by the original invoice or date of invoice. A 15% service charge will be deducted on all returned merchandise, except in the case of factory error.

DENIS WELCH MOTORS LIMITED

Delivery Address/Delivered Via *TIPS* *un*ted

Unless otherwise stated all goods are of uk origin

Goods Total	759.90
Carriage & Packing	74.79
Sub Total	834.69
VAT %	0.00
Invoice Total	834.69

All amounts are in GBP



IMPORTS

(269) 353-5250 · FAX (269) 375-1026
TOLL FREE 800-253-4080
www.engelimports.com



Terry's Jaguar Parts

(269) 353-5273 · FAX (269) 375-1026
TOLL FREE 800-851-9438
www.terrysag.com

5850 STADIUM DRIVE
KALAMAZOO, MI 49009



NO REFUND AFTER 45 DAYS. INVOICE OR COPY MUST ACCOMPANY ALL RETURNS.
20% RESTOCKING FEE MAY BE CHARGED ON ALL RETURNS.
ELECTRICAL AND SPECIAL ORDER PARTS ARE NOT RETURNABLE.
ALL ACCEPTED RETURNS MUST BE IN ORIGINAL PACKAGING AND IN CLEAN RESALABLE CONDITION.

DATE ENTERED 05 JAN 11	YOUR ORDER NO.	DATE SHIPPED 05 JAN 11	INVOICE DATE 05 JAN 11	INVOICE NUMBER 1076541
---------------------------	----------------	---------------------------	---------------------------	---------------------------

S
O
L
D

T
O

SHIP VIA UPS-1	EMP. 25	SLSM. 25	TERMS CREDIT CARD	F.O.B. POINT KALAMAZOO, MI	
QTY.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1	CBM3241STD	MAIN BEARING SET Part number CBM3241STD	91.61	49.53	49.53
			replaces M3241		
<i>pd TK VISA 2-8-11 #20391</i>					
				PARTS	49.53
				SUBLET	
				FREIGHT	5.67
				SALES TAX	0.00
				TOTAL	\$55.20
CUSTOMER'S SIGNATURE X					

DISCLAIMERS OF WARRANTIES
Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

1101.100.1

CUSTOMER COPY

Enterprises, LLC

Invoice

3760 Highland Lane
 Port Washington, WI 53074-9787
 Phone: 262-268-0040 Fax: 262-268-0041
 www.speedperformanceresearch.com

Date	Invoice #
1/21/2011	7524

Bill To

Ship To

S.O. No.	P.O. No.	Terms	Project
30	100-S	Due on receipt	

Item	Description	Ordered	Prev. Invoi...	Invoiced	Rate	Amount
C102	Jet wash engine block	1	0	1	38.00	38.00
C111	Jet wash connecting rod	4	0	4	3.25	13.00
C112	Jet wash crankshaft	1	0	1	22.00	22.00
C110	Jet wash flywheel	1	0	1	9.00	9.00
BW108	Bore & hone 4 cylinder (88.5mm)	1	0	1	135.75	135.75
BW126	Deck inline 4 cyl. - 6 cyl.	1	0	1	99.75	99.75
BW133	Align hone block	1	0	1	158.00	158.00
F107	R & R dowel pins	1	0	1	5.75	5.75
F101	Surface flywheel/single plane - auto	1	0	1	36.75	36.75
RW141	Magnaflux connecting rod	4	0	4	9.00	36.00
RW103	Check rod for size (2-5)	4	0	4	12.00	48.00
RW117	Measure piston pin bore for pin clearance	4	0	4	4.50	18.00
RW147	Check small end connecting rod pin clearance	4	0	4	3.50	14.00
CW107	Magnaflux crankshaft	1	0	1	52.50	52.50
CW108	Check crankshaft straightness	1	0	1	22.00	22.00
CW109	Check crankshaft for size	1	0	1	26.50	26.50
CW105	Polish crankshaft	1	0	1	47.50	47.50
HW142	R & R valve guide (4 or more)	8	0	8	6.00	48.00
HW149	Size valve guide	8	0	8	4.75	38.00
HW192	Machine valve guide for PC seal	8	0	8	6.25	50.00
HW109	Reg. valve job (4 cylinder)	1	0	1	89.50	89.50
HW105	Surface 3 & 4 cylinder head	1	0	1	42.00	42.00
AW137	Check & set bearing clearance (per bearing)	7	0	7	11.00	77.00
BA103	Balance in-line 4 or 6 cylinder	1	0	1	185.00	185.00
BA109	Balance flywheel pressure plate together	1	0	1	115.75	115.75

Subtotal

Sales Tax ()

Total

Payments/Credits

Balance Due

7/9

SPR Enterprises, LLC

3760 Highland Lane

Port Washington, WI 53074-9787

Phone: 262-268-0040 Fax: 262-268-0041

www.speedperformanceresearch.com

Invoice

Date	Invoice #
1/21/2011	7524

Bill To

Ship To

S.O. No.	P.O. No.	Terms	Project
30	100-S	Due on receipt	

Item	Description	Ordered	Prev. Invoi...	Invoiced	Rate	Amount
UVBG-341	Bronze valve guide	8	0	8	12.25	98.00
Labor	Extra time to make valve guides	1.5	0	1.5	75.00	112.50
343500	11/32" x .500" Metal clad poly valve stem seal	8	0	8	1.25	10.00
S-15-200	.015" Valve spring shim	5	0	5	0.45	2.25
S-03-200	.030" Valve spring shim	6	0	6	0.45	2.70
S-06-200	.060" Valve spring shim	8	0	8	0.45	3.60
F5060	Ferrea/SBC stainless intake valve			4	15.65	62.60
F5004	Ferrea/SBC 1.50 stainless exhaust valve			4	13.92	55.68
Shipping	Shipping (valve guides)			1	21.14	21.14
ARP206-2802	ARP 3/8-24 flywheel bolt set (6)			2	27.10	54.20
CB603P	Clevite/Ford 1.6L rod bearing			4	15.97	63.88
Shipping	Shipping (special order flywheel bolts & rod bearings & valves)			1	47.20	47.20

Subtotal	\$1,961.50
Sales Tax ()	\$0.00
Total	\$1,961.50
Payments/Credits	\$0.00
Balance Due	\$1,961.50

2/9

AH 100 S
sand damage

Nov. 16th fax

Denis Welch Invoice #65025

Denis Welch Invoice #65025
Denis Welch Invoice #65025
Denis Welch Invoice #64668
both Welch Invoices
UPS customs service

PARTS

10 qts oil 20W50
pan gasket
ring set
antifreeze
gasket manifold to head
head gasket
rocker shaft
shipping from UK & insurance
customs charges on Welch shipments
PARTS TOTAL TO NOV 16th

NOVEMBER 16TH TOTAL (\$862 +\$1870)

14-Feb-11

Denis Welch Invoice #65432
Denis Welch Invoice #65432
Engel Imports Invoice #1076541
SPR Enterprises, LLC Invoice #7524

US Bank VISA

Robertson/Ryan invoice dated 1/31/11

(4) pistons .020 over
50% of shipping for Welch shipment
main bearings
machine work
10% mark-up on machine work
parts supplied & modification
20% mark-up on parts
two trips to machine shop - 3 hours @\$40/hour
foreign transfer fee (uk pounds/usa \$)
replace carb throttle shafts

added value to inventory - shop insurance
MACHINE SHOP & PARTS TOTAL

FEBRUARY 14TH TOTAL (4622.86+\$525)

GRAND TOTAL ESTIMATE(2732 +10147.86)

PRICE

\$30.00
\$15.00
\$215.00
\$15.00
\$20.00
\$225.00
\$200.00
\$110.00
\$32.00
\$862.00

\$2,732.00

\$600.00
\$65.00
\$91.61
\$1,427.75
\$142.75
\$533.75
\$106.00
\$120.00
\$36.00
\$500.00 ALLOWANCE ONLY

\$1,000.00
\$4,622.86

\$10,147.86

\$12,879.86

LABOR

R&R coolant, top hose, water rail \$340.00 4 hours
R&R oil, oil pan \$425.00 5 hours
R&R air box & carbs \$510.00 6 hours
R&R exhaust manifold \$170.00 2 hours
R&R valve cover rocker assy \$425.00 5 hours
R&R cylinder head & re torque NOT DONE 6 hours
R&R pistons & rods, clean pistons NOT DONE 6 hours
hone cylinder walls, gap rings, & instil NOT DONE 8 hours

LABOR TOTAL TO NOV. 16TH

\$1,870.00

pull engine, interior,
transmission from car

strip engine complete

assemble engine

install engine, trans
interior

get running & set up

LABOR TOTAL - 65 HOURS

\$5,525.00

Fourintune

W63 N147 Washington Avenue
PO BOX 4
Cedarburg, WI 53012
262-375-0876
Fax 262-675-2874
www.fourintune.com
fourintune@charter.net

REPAIR ORDER

Fourintune Garage Inc.
 W63 N147 Washington Avenue
 P.O. Box 4
 Cedarburg, WI 53012

(1)

MATERIAL USED				
QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY YES/NO
2	USED	100-Y OEL PANS	500	
		MATR REALS	105	
		BRK PADS	103	20
8		STAINLESS BRAD SCREWS	144	
		GLMZ PADS ON 8	160	
		FRONT CALIPRE KIT	35	
		REAR CALIPRE KIT	35	
		CARB OVERHAUL KETS	110	
2		VALVE COVER BUSH	3	
		STREP REY + REPAINT		
		VALVE COVER	350	
			1545	20

NAME		DATE	
ADDRESS		3-1-11	
MAKE	TYPE OR MODEL	YEAR	RECEIVED
SERIAL NO.	ENGINE NO.		A.M. P.M.
ODOMETER	LICENSE NO.	TERMS	PROMISED
	ORDER WRITTEN BY		A.M. P.M.
		PHONE WHEN READY	
		<input type="checkbox"/> YES <input type="checkbox"/> NO	
		PHONE	

DSS	ISJ	LABOR CHARGE
Lubrication	<input type="checkbox"/>	
Change Oil	<input type="checkbox"/>	
Change Oil Filter Cart.	<input type="checkbox"/>	
Change Trans.	<input type="checkbox"/>	
Change Diff.	<input type="checkbox"/>	
Pack Front Wheel Brgs.	<input type="checkbox"/>	
Adjust Brakes	<input type="checkbox"/>	
Rotate Tires	<input type="checkbox"/>	
Wash Polish	<input type="checkbox"/>	
State Inspection	<input type="checkbox"/>	

OPER NO.	INSTRUCTIONS	
	MACHINE BRK PADS TO FIT BACK PLATES	120
	STREP + STRAIGHTEN 2 PANS	
	CUT HOLES CUT PAN SECTION	
	BURRD 100-3 PAN	
	TRANSFER OIL TEMP SENSOR	
	BODY OUT + PAINT JB WOLD	520
	TAKE BRKS OFF CAR DETAIL ENG ROOM + FRAME	640
	BLAST + PAINT CYL (8) PLATE ALL BRK PARTS	960
	DESSASSEMBLE FRONT SUSPENSION FORMAG	360
	OH LR CALIPRE FIT PADS DRBS PISTON	420

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Tear-down estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$_____
 3. I do not want an estimate. _____

BROUGHT FORWARD				
TOTAL PARTS				
QTY.	ACCESSORY NO.	ACCESSORIES	PRICE	WARRANTY YES/NO
		CHLIPRS ARIZ		
		STAINLESS LINED		
		134 OTHERS		
TOTAL ACCESSORIES				

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and / or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.

GAS, OIL, & GREASE	PRICE
GALS. GAS @	
QTS. OIL @	
LBS. GREASE @	
TOTAL GAS, OIL & GREASE	

METHOD OF PAYMENT:	TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL & GREASE	OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
<input type="checkbox"/> CASH	3020	1545					
<input type="checkbox"/> CHECK		20					
<input type="checkbox"/> CHARGE							
<input type="checkbox"/> FLAT RATE					4565		20
<input type="checkbox"/> HOURLY							
<input type="checkbox"/> BOTH							

REPAIR ORDER

Fourintune Garage Inc.
 W63 N147 Washington Avenue
 P.O. Box 4
 Cedarburg, WI 53012

(2)

MATERIAL USED				
QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY YES/NO
4		WIRTHANE UPPER TRIMMING	12	-
		DRILLS	15	-
2		TIMKEN FRONT WHEEL BEARINGS	200	00
		MAG FRONT SPINDLES	60	00
2		FRONT WHEEL SPACERS	30	-
		TELTON MASTER CYL	95	-
		SELICOME BRK FLD	36	-
		MEBDEL ROLLERS	20	-
		OUT PUT SHAFT	250	-
3		SYNCRIS	285	-
		G-SKT SET	20	-
		IN PUT BOARDING	38	-
2		THRUST WASHERS	40	-
		WMT DEECT CHART	75	-
		ANULUS	50	-
1		OUTSIDE REPAIRS	30	-
		REAR SPAL	10	-
		SPRDO SPAL	5	50
		SHW WHEEL	30	-
		PLANETARY	30	-
		FRONT SEAL	8	50
		SHIFT BOOT	18	-
QTY.	ACCESSORY NO.	ACCESSORIES	PRICE	WARRANTY YES/NO
		ANULUS THRUST WASHER		
		PLANATARY SHY SHAF	70	-
		CD SPAL SPALS	3	-
		ACCU M PESTON RINGS	85	-
		11 PESTON	60	-
		HARDWARE	50	-

NAME		DATE	
		3-1-11	
ADDRESS			
MAKE	TYPE OR MODEL	YEAR	RECEIVED
			A.M. P.M.
SERIAL NO.	ENGINE NO.	PROMISED	
		A.M. P.M.	
ODOMETER	LICENSE NO.	TERMS	PHONE WHEN READY
			<input type="checkbox"/> YES <input type="checkbox"/> NO
ORDER WRITTEN BY		PHONE	

DSS	ISJ	LABOR CHARGE
	Lubrication	<input type="checkbox"/>
	Change Oil	<input type="checkbox"/>
	Change Oil Filter Car.	<input type="checkbox"/>
	Change Trans.	<input type="checkbox"/>
	Change Diff.	<input type="checkbox"/>
	Pack Front Wheel Brgs.	<input type="checkbox"/>
	Adjust Brakes	<input type="checkbox"/>
	Rotate Tires	<input type="checkbox"/>
	Wash Polish	<input type="checkbox"/>
	State Inspection	<input type="checkbox"/>

OPER NO.	INSTRUCTIONS	
	REBUILD LEFT REAR CALIPRE	
	FT PARTS DRESS PISTON DELT LOCK WARE	420
	REBUILD FRONT CALIPERS PREL + " "	840
	ASSY FRONT AND REPACK BERGS	
	INSTALL FRONT CALIPERS	480
	MAKE MASTER CYL MOUNT.	350
	INSTALL MASTIC + BLEED SYSTEM	510
	WELD FRAME CRACKS TOUCHUP PAINT	
	DESSASSEMBL REAR BOX + OD	760
	OH E-BOX + OD	640

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Tear-down estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs. _____
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$_____
 3. I do not want an estimate. _____

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and / or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL	GAS, OIL, & GREASE	PRICE
	GALS. GAS @	
	QTS OIL @	
	LBS. GREASE @	
	TOTAL GAS, OIL, & GREASE	

METHOD OF PAYMENT:	TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL & GREASE	OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
<input type="checkbox"/> CASH	4000	1671					
<input type="checkbox"/> CHECK							
<input type="checkbox"/> CHARGE							
<input type="checkbox"/> FLAT RATE					5671		
<input type="checkbox"/> HOURLY							
<input type="checkbox"/> BOTH							

REPAIR ORDER

Fourintune Garage Inc.
 W63 N147 Washington Avenue
 P.O. Box 4
 Cedarburg, WI 53012

(3)

MATERIAL USED				
QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY YES NO
		SPECIAL WATER		
		PUMP NUT + HARDWARE	50	
		FRONT PLATE GEN	50	
		1" FOR BORG	30	
		ROTOR (USED)	15	
		FAN BELT	18	
		TRIPS OIL 4QT	20	
		CORROD PLUG WIRE	150	
		FLIGHT BOW-TON	50	
		GUARD BEZEL		
		LT SOCKET	150	
		+ RECHKIME + INSTAL	483	
		OUTSIDE REPAIRS		
		BROUGHT FORWARD		
		DISCUSS TOTAL PARTS		
QTY.	ACCESSORY NO.	ACCESSORIES	PRICE	WARRANTY YES NO
		DEFF LEAK		
		DEST OH PART MISSING		
		NO MUCH ADVANCE		
		PEDAL PADS		
		TOTAL ACCESSORIES		

NAME		DATE	
		3-1-11	
ADDRESS			
MAKE	TYPE OR MODEL	YEAR	RECEIVED
			A.M. P.M.
SERIAL NO.	ENGINE NO.	PROMISED	
		A.M. P.M.	
ODOMETER	LICENSE NO.	TERMS	PHONE WHEN READY
			<input type="checkbox"/> YES <input type="checkbox"/> NO
ORDER WRITTEN BY		PHONE	

DSS	SJ	LABOR CHARGE
		Lubrication <input type="checkbox"/>
		Change Oil <input type="checkbox"/>
		Change Oil Filter Cart <input type="checkbox"/>
		Change Trans. <input type="checkbox"/>
		Change Diff. <input type="checkbox"/>
		Pack Front Wheel Brgs. <input type="checkbox"/>
		Adjust Brakes <input type="checkbox"/>
		Rotate Tires <input type="checkbox"/>
		Wash Polish <input type="checkbox"/>
		State Inspection <input type="checkbox"/>

OPER NO.	INSTRUCTIONS	
	CLEAN + PAINT ENG RM ASBESTOS	160 00
	SERVICE GENERATOR RE FRONT PLATE	
	FRONT BOARDING - WELDED + STRIPPED	
	SERVICE STARTOR MAKE MESSAGE	
	ALIGNMENT PIN	
	FIX STUDS FOR DYHS MUFFLER	240
	GREASE CK ALL FLEETS	50
	FIX FIBRO WARE	30
	MAKE DR BRK + INSTAL	60

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Teardown estimate - I understand that my car will be reassembled within _____ days of the date shown if I choose not to authorize the services recommended.

1. I request an estimate in writing before you begin repairs.
 2. Please proceed with repairs, but call me before continuing if the price will exceed \$_____
 3. I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and / or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and / or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

X

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.	GAS, OIL, & GREASE	PRICE
	GALS. GAS @	
	QTS. OIL @	
	LBS. GREASE @	
	TOTAL GAS, OIL & GREASE	

METHOD OF PAYMENT:	TOTAL LABOR	TOTAL PARTS	ACCESSORIES	GAS, OIL & GREASE	OUTSIDE REPAIRS	TAX	TOTAL AMOUNT
<input type="checkbox"/> CASH	540	483					
<input type="checkbox"/> CHECK							
<input type="checkbox"/> CHARGE							
LABOR:					1023		
<input type="checkbox"/> FLAT RATE							
<input type="checkbox"/> HOURLY							
<input type="checkbox"/> BOTH							

Fourintune

Garage Incorporated

AUSTIN HEALEY 100 S

DATE	REF.	DESCRIPTION	CHARGES	✓	CREDITS	BALANCE
PREVIOUS BALANCE						
3-1-11		#1 Brakes	4565	20		
		#2 Brakes & Tires	5671	-		
		#3 Clean & Misc	1023	-		
						11,259.20
		(CREDIT WAS CHARGES & WINE PRESS)				
					1000	-
		Balance Due				10259.20

W63 N147 Washington Avenue • PO BOX 4 • Cedarburg, WI 53012

FAX: 262-675-2874

www.fourintune.com

PHONE: 262-375-0876

Fourintune

W63 N147 Washington Avenue

PO BOX 4

Cedarburg, WI 53012

262-375-0876

Fax 262-675-2874

www.fourintune.com

fmtune@charter.net

October 4, 2011

56088001

1955 Austin Healey 100 S

ID #: AHS3802

Dear Rachel,

Attached is the estimate for Robert Griffin's Austin Healey. I am still waiting to get a firm price on the part we are searching for in the UK (the steering box arm). Rather than hold up the entire estimate, I have plugged in an allowance (\$250) which should cover the cost plus shipping and customs.

The second batch of photos I sent taken by Tom were more detailed – do you need hard copy of those?

Please let me know that you have received the estimate and what the next step will be.

Thanks!

Sincerely,

Kaye E. Kovacs
FOURINTUNE GARAGE INC.
Vice President

1241P
1955 Austin Healey 100 S
chassis # AHS 3802
OD reading: 1255

PARTS

CB headlight	\$75.00
parking light assembly	\$70.00
2 front fender beads	\$84.00
steering box arm -ALLOWANCE ONLY	\$250.00
align front end	\$125.00
body shop materials	\$1,100.00

TOTAL PARTS \$1,704.00

LABOR

clean up car	\$130.00
R & R headlights & directionals	\$325.00
R&R grill, wing emblem & hood	\$405.00
R&R belt, hood hooks & windshield	\$565.00
R&R fender beads & vents	\$490.00
R&R inner shields, steering wheel & column	\$800.00
R&R bent steering arm	\$80.00

remover paint from front shroud	\$1,215.00
remove paint from right front fender	\$645.00
straighten front shroud	\$650.00
straighten right front fender	\$630.00
weld front shroud	\$245.00

mask off car	\$975.00
prep & prime damaged areas	\$730.00
mask/ blend silver paint inside	\$485.00
unmask & remask car	\$1,190.00
paint front shroud & right front fender	\$485.00
mask off & paint two tone on fender	\$405.00
wet sand front shroud & right front fender	\$975.00
buff front shroud & right front fender	\$490.00
clean & wax for delivery	\$270.00

TOTAL LABOR \$12,185.00

TOTAL ESTIMATE -- \$13,889.00

note: interstate commerce, car will be returned
to CA by professional carrier

Fourintune

W63 N147 Washington Avenue
PO BOX 4
Cedarburg, WI 53012
262-375-0876
Fax 262-675-2874
www.fourintune.com
fourintune@charter.net

A-GT3810-3811 / T-3869

REPAIR ORDER

6321 2241

2014

Fourintune Garage Inc.
 W63 N147 Washington Avenue
 P.O. Box 4
 Cedarburg, WI 53012

MATERIAL USED				
QTY.	PART NO.	DESCRIPTION	PRICE	WARRANTY VFS NO.
		CUSTOM HOOD STRAP	250 -	
		PEDAL PADS	6 -	
10	QT	20 W 50	80 -	
8		SWAY BAR BUSHES	24 -	
4		SPARK PLUGS	20 -	
		DIST. CARBON	12 -	
		FAN BELT	44 -	
		R&R #OH SPEEDO		
		CHANGE GEARS	450 -	
		UPS - FISHING ROD	35 -	

NAME _____ DATE 8-12-14

ADDRESS _____

MAKE _____ TYPE OR MODEL _____ YEAR _____

SERIAL NO. _____ ENGINE NO. _____ PROMISED _____

ODOMETER _____ LICENSE NO. _____ TERMS _____ PHONE WHEN READY _____
 YES NO

ORDER WRITTEN BY _____ PHONE _____

DSS	LABOR CHARGE
Lubrication <input type="checkbox"/>	
Change Oil <input type="checkbox"/>	
Change Oil Filter Cart. <input type="checkbox"/>	
Change Trans. <input type="checkbox"/>	
Change Diff. <input type="checkbox"/>	
Pack Front Wheel Brge. <input type="checkbox"/>	
Adjust Brakes <input type="checkbox"/>	
Rotate Tires <input type="checkbox"/>	
Wash Polish <input type="checkbox"/>	
State Inspection <input type="checkbox"/>	

SCRAPE OFF BUGS
 TOUCH UP CHIPS
 INSTALL BELT
 ADJ. STEERING BOY 600 -
OUTSIDE REPAIRS

R&R SPRING BOLTS
 CLEAN WHEELS 600 -

ADJ. CLUTCH & BRAKE
 GREASE ALL - CK OVER 400 -

OPER NO.	INSTRUCTIONS	
	CHECK ALL FLUIDS	
	CK BEARINGS WITHOUT TAKING APART - OK	
	CK OIL LEAK (BREATHER) CHANGE OIL	120 -
	LUBE, CLEAN CARBS, SET POINTS, FIX RIGHT DIRECTIONAL	600 -
	FIX DOOR SCREWS & FIX THROTTLE	700 -
	CLEAN & DETAIL	300 -

You are entitled to a price estimate for the repairs you have authorized. The repair price may be less than the estimate, but will not exceed the estimate without your permission. Your signature will indicate your estimate selection.
 Teardown estimate - I understand that my car will be reassembled _____ days of the date shown if I choose not to authorize the services recommended.

- I request an estimate in writing before you begin repairs.
- Please proceed with repairs, but call me before continuing if the price will exceed \$ _____
- I do not want an estimate.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

METHOD OF PAYMENT:

CASH

CHECK

CHARGE

LABOR:

FLAT

HOURLY

BOTH

QTY.	ACCESSORIES	PRICE	WARRANTY VFS NO.
BROUGHT FORWARD		2521	
TOTAL PARTS		2521	
TOTAL ACCESSORIES			

GAS, OIL, & GREASE		PRICE
GAL. GAS	@	
QTS. OIL	@	
LBS. GREASE	@	
TOTAL GAS, OIL, & GREASE		

carbonless unit set

AUTO REPAIR ORDER

SHIP VIA PASSPORT ORDER # 46260 TO VAIL CO.

1720 -

2521 -

1720 -

EXMPX

TOTAL AMOUNT 4241 -



British Car Repair

www.britishcarrepair.com

Invoice No.
000034903

Page: 1
Order Date 03/29/19 01:52 pm
Paid: 03/29/19 01:53 pm

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

*March
2019*

\$ 1500⁰⁰

GRIFFIN, ROBERT
912 GRAND AVE.
280 BAYVIEW, BEL
SAN RAFAEL CA 94901
Home Phone: 415-435-4665
Work Phone: 415-453-0820

56 AUSTIN HEALE 100S WHITE
13289 Mi. Last in 11/7/2018
Lic: 100S/CO 4Cyl Eng
Vin:
Eq:

NO START

Labor: \$225.00

VEHICLE TOWED INTO SHOP - NO START.
IGNITION DISTRIBUTOR HAS MOVED.
REMOVE DISTRIBUTOR TO REPAIR DISTRIBUTOR CLAMP.
REFIT DISTRIBUTOR AND SET TIMING.

Job Subtotal: \$225.00

HANDBRAKE

Labor: \$400.00

INSPECT REAR BRAKE PADS AND HANDBRAKE SYSTEM.
BRAKE PADS ARE OK.
HANDBRAKE ADJUSTMENT THREADED ROD AND NUT HAVE STRIPED AT RIGHT SIDE.
CLEAN THREADS ON HANBRAKE ADJUSTMENT STUD AND DOUBLE NUT STANDARD NUTS TO ADJUSTER.
REASSEMBLE, BLEED BRAKES.

Job Subtotal: \$419.00

SERVE

Labor: \$125.00

CHANGE ENGINE OIL AND FILTER. CHECK\TOP-UP FLUID LEVELS.
INSPECT LIGHTS, BRAKE PADS, WHEEL BEARINGS, FAN BELT
TENSION, TIRE PRESSURE AND SPARE. ROTATE TIRES WHERE
NECESSARY. LUBRICATE CHASSIS AND GREASE FITTINGS.

Job Subtotal: \$200.00

OIL FILTER

Labor: \$225.00

REPLACE OIL FILTER ELEMENT WITH PART SUPPLIED BY OWNER.

Job Subtotal: \$225.00

TUNE UP

Labor: \$400.00

ADJUST VALVE CLEARANCES.

----->----->----->-----Continued on the next page----->----->----->-----

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a twelve month warranty on parts (Note: Not parts supplied by owner or other outside source) and labor. All warranty repairs must be performed by this shop and cannot exceed the original cost of repair. Storage fee of \$100 per day will commence one week after repairs have been completed and vehicle has not been picked up.

(Signature) _____



British Car Repair


www.britishcarrepair.com

Invoice No.
000034903

Page 2
Order Date 03/29/19 01:52 pm
Paid: 03/29/19 01:53 pm

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

TUNE UP

CHECK CYLINDER COMPRESSIONS - ALL APPROX 145 PSI.
REPLACE SPARK PLUGS.
CLEAN AND ADJUST IGNITION POINTS.
CHECK/ADJUST CARBURETOR FUEL MIXTURE.
ROAD TEST VEHICLE.

Job Subtotal: \$420.00

Recommendations: TACHOMETER CABLE NEEDS TO BE REPLACED.
HANDBRAKE CABLE HAS STRETCHED.
HANDBRAKE CALIPER THREADED ADJUSTER BOLT AND NUT ARE STRIPPED.
INSPECT RIGHT REAR HUB FOR AXLE GREASE.

The tire pressures on this vehicle were inspected and set to manufacturer's recommended pressure.

Haz Waste: \$0.74
Tax: \$10.20
Estimate Total: \$1,500.00

Thank you for choosing Ed Wright's British Car Repair

Hand
✓ 7597
DR

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a twelve month warranty on parts (Note: Not parts supplied by owner or other outside source) and labor. All warranty repairs must be performed by this shop and cannot exceed the original cost of repair. Storage fee of \$100 per day will commence one week after repairs have been completed and vehicle has not been picked up.

(Signature) _____



British Car Repair

www.britishcarrepair.com

Invoice No.
000035067

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

Page 1
Order Date 06/11/19 02:03 pm
Paid: 06/11/19 02:05 pm

June 2019

Quotes \$385.00

56 AUSTIN HEALE 100S WHITE 13409 Mi. Last in 3/29/2019 Lic: 100S/CO 4Cyl Eng Vin: Eq:

1 06/11/19 02:03pm 385.00
in person.

FUEL PUMPS Labor: \$375.00

REPLACE BOTH FUEL PUMPS WITH PARTS SUPPLIED BY OWNER.
INSPECT CARBURETION, CHOKE AND IDLE SPEED.
ROAD TEST VEHICLE.

GAS	GASOLINE-N	10.0 @	1.00 =\$	10.00	10.00
-----	------------	--------	----------	-------	-------

Recommendations: TACHOMETER CABLE NEEDS TO BE REPLACED.
HANDBRAKE CABLE HAS STRETCHED.
HANDBRAKE CALIPER THREADED ADJUSTER BOLT AND NUT ARE STRIPPED.
INSPECT RIGHT REAR HUB FOR AXLE GREASE.

The tire pressures on this vehicle were inspected and set to manufacturer's recommended pressure.

Payments to Ed Wright's British Car Repair	Cost Summary
Status: Paid Work Order	Labor 375.00
	Parts 0.00
	Non Taxable 10.00
Payments: \$385.00	Subtotal 385.00
I 06/11/19 385.00 Visa	Total \$385.00
	Payments 385.00
	Bal Due 0.00

Thank you for choosing Ed Wright's British Car Repair

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a twelve month warranty on parts (Note: Not parts supplied by owner or other outside source) and labor. All warranty repairs must be performed by this shop and cannot exceed the original cost of repair. Storage fee of \$100 per day will commence one week after repairs have been completed and vehicle has not been picked up. Credit and debit card processing fees will be an additional surcharge at 4% of the total cost of repairs.

(Signature) _____



British Car Repair

www.britishcarrepair.com

000035271

BAR #: AB 220451
EPA # CAL 000018244
142 Mill Street
San Rafael, CA 94901
Phone: 415-457-1707

Page
Order Date 09/24/19 05:01 pm
Paid: 09/24/19 05:01 pm



56 AUSTIN HEALE 100S WHITE
14486 Mi. Last in 6/11/2019
Lic: 100S/CO 4Cyl Eng
Vin:
Eq:

Quotes
1 09/24/19 05:02pm 613.00
in person.

STARTER MOTOR

Labor: \$600.00

REPLACE STARTER MOTOR WITH CUSTOMER SUPPLIED PART.

Recommendations: *Lube, Oil and Filter* TACHOMETER CABLE NEEDS TO BE REPLACED.
HANDBRAKE CABLE HAS STRETCHED.
HANDBRAKE CALIPER THREADED ADJUSTER BOLT AND NUT ARE STRIPPED.
INSPECT RIGHT REAR HUB FOR AXLE GREASE.

The tire pressures on this vehicle were inspected and set to manufacturer's recommended pressure.

Payments to Ed Wright's British Car Repair Cost Summary

Status: Paid Work Order

Labor	600.00
Parts	0.00
FREIGHT	13.00
Subtotal	613.00
Total	\$613.00
Payments	613.00
Bal Due	0.00

Payments: \$613.00
1 09/24/19 613.00 Visa

Thank you for choosing Ed Wright's British Car Repair

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. Repairs have a twelve month warranty on parts (Note: Not parts supplied by owner or other outside source) and labor. All warranty repairs must be performed by this shop and cannot exceed the original cost of repair. Storage fee of \$100 per day will commence one week after repairs have been completed and vehicle has not been picked up.

(Signature) _____