


Francis G. Mandarano, Publisher and Founder

Correspondence: P.O. Box 1015, Mercer Island, Washington, 98040 USA  
Shipping Address: 1950 116th Avenue N.E., #200, Bellevue, Washington 98004 USA  
Direct Parts Line 206/455-4707 Fax 206/646-5458 Telephone 206/455-4449

INVOICE		
NUMBER	DATE	PAGE
00109133	05/24/96	3

SOLD TO

SHIP TO

ORDER NO.		ORDER DATE	CUST. NO.	CUSTOMER P.O. NO.	SHIP VIA	SALES	TERMS	
00109133			958469		U14 94070	NY	1C1 Credit Card	
QUANTITY		PART NO. - INVENTORY NO.		DESCRIPTION		LIST PRICE	YOUR PRICE	AMOUNT
ORDERED	SHIPPED	BACK ORD.						
1	1		0000068227	WOOD 3-SPOKE 109-115		980.00	599.00	599.00
<p><b>PLEASE RETURN ALL CORES WITHIN 30 DAYS OF INVOICE DATE</b></p> <p>COMMENTS</p>								
						CR. MEMO		
						WASST		.00
						SHIPPING		6.44
						HANDLING		.00
								



CR. MEMO

WASST

SHIPPING

HANDLING

**TOTAL**

**605.44**

SOME PARTS MAY BE LEGAL IN CALIFORNIA ONLY FOR VEHICLES WHICH MAY NEVER BE USED UPON A HIGHWAY.

A written request to return merchandise must be accompanied by a copy of the invoice within 30 days after receipt of goods. There will be a 20% restocking charge on all returned parts. No returns on electrical parts. Cores must be returned within 30 days of invoice.

Please read carefully the Terms and Conditions on the back of this invoice





Francis G. Mandarano, Publisher and Founder

Correspondence: P.O. Box 1015, Mercer Island, Washington, 98040 USA


Shipping Address: 1950 116th Avenue N.E., #200, Bellevue, Washington 98004 USA

Telephone: 425-455-4449 FAX: 425-646-5458 Email: mie@maseratinet.com

INVOICE		
NUMBER	DATE	PAGE
00155049	07/06/99	3

SOLD TO

SHIP TO

ORDER NO.		ORDER DATE	CUST. NO.	CUSTOMER P.O. NO.	SHIP VIA	SALES	TERMS
00155049		958469			U15 94070 NY	2C1	Credit Card
QUANTITY			INVENTORY NO.	DESCRIPTION	LIST PRICE	YOUR PRICE	AMOUNT
ORDERED	SHIPPED	BACK ORD.					
1	1	0	MIE000425-40DCOE	40DCOE COMPLETE WEBER KI2	2291.16	2062.04	2062.04
1	1	0	000047506-0A/000	101/1/6 RT CAM COVER (B)	631.25	450.00	450.00
1	1	0	000046962-0B/000	101/1/8&9 CAM COVER GASK	28.38	.00	.00
2	2	0	000043814-BB/019	101/1/11 O-RING	3.16	.00	.00
12	12	0	310620364	331/1/7 SEALING WASHER (	2.08	.00	.00
<div><div></div><div><div>CR.MEMO</div><div>WA/SST</div><div>SHIPPING</div><div>HANDLING</div></div><div><div>0.00</div><div>33.92</div><div>0.00</div><div>0.00</div></div></div>							
COMMENTS							



# Epifani Restorations



1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX  
epiresto@pacbell.net

## Invoice

DATE	INVOICE #
1/3/00	423

BILL TO

PROJECT
---------

MASERATI MISTRAL
------------------

QUAN	DESCRIPTION	RATE	AMOUNT
14	LABOR-(November 17) Pick up car from customer's shop. (November 20) Unload from transporter. (November 22) Instruct/assist Curtis with trim fabrication. Trim trident to fit front bumper. Fabricate bracket to attach trident to bumper. (November 23) Install trident, assist Curtis with trim. (November 24) Check over conversion components, found mismatched ports on manifold, misaligned mounting holes on valve cover, front valve cover studs too short. Replace studs with ones of correct lengths. Remove valve cover dowels. Remachine missaligned holes on valve cover and deburr. Dress/file ugly welds on manifold body. Take manifold to machinist to have ports welded, give to Dan to remill mounting surface. Start porting manifold. (Paolo)	65.00	910.00
11.75	LABOR-(November 22) Start making passenger side door top trim. Figure out why it rubs. (November 23) Finish fitting door trim, file. Go over other pieces with Paolo. Pull driver side door panel off. Fit driver side door top trim. (Curtis)	65.00	763.75
11.5	LABOR-(November 29) Finish porting manifold. Make fixtures to pressure test. Pressure test manifold, found three leaks (porous welds). Repair leaks (Dennis), dress welds, bead blast and repressure test. Test ok. Install new linkages on carbs. Fit water and vacuum fittings and studs to manifold. File carbs to fit studs and ports. File gaskets to fit ports. Fit throttle shaft. Found shaft mounts drilled to taper, need repair. Adjust throttle rods to equal lengths. (November 30) Test carbs for full throttle. Two new linkages do not allow full throttle. Fit linkages until proper throttle position is acheived. Adjust throttle rods to compensate for taper on throttle shaft. Adjust ball cranks to proper position. Machine spacer to allow correct free play on throttle shaft. Instruct Geoff on service repairs. (Paolo)	65.00	747.50
		<b>Total</b>	



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX  
epiresto@pacbell.net

1216 Fifth Street  
Berkeley, CA 94710 USA

## Invoice

DATE	INVOICE #
1/3/00	423

BILL TO

PROJECT
---------

MASERATI MISTRAL
------------------

QUAN	DESCRIPTION	RATE	AMOUNT
1.5	LABOR-(December 1) Supervise Curtis and Geoff. Disconnect fuel injection wiring system. Wire new fuel pump. (Paolo)	65.00	97.50
11	LABOR-(December 1) Weld up crack in driver door. Fabricate new molding for driver side front pillar-make template, make piece, fit, file. (December 2) Start making fuel door moldings. (Curtis)	65.00	715.00
0.5	LABOR-(December 2) Pick up parts. (Rick)	65.00	32.50
0.75	LABOR-(December 3) Work on timing chain adjuster. (December 7) Assist Paolo. (Rick)	65.00	48.75
5.5	LABOR-(December 6) Wrinkle finish valve cover. Remove siezed pin from timing chain tentioner. Fabricate wrench for timing chain adjuster. Adjust timing chain. Install valve cover and accessories. (Paolo)	65.00	357.50
11.5	LABOR-(December 7) Attempt to start engine, no spark. Clean points. Pick up new spark plugs (Berkeley Yamaha), gap and install. Run engine, too lean at idle. Install correct idle jets, tune carbs (Nino). Pick up and install new battery (Select Electric). Attempt test drive, no clutch-clutch master dry and in poor condition. Top up fluid, bleed clutch, check for leaks. Clean oil off engine block. Test drive car. Re torque valve cover. (December 8) Check fuel gauge. Remove trunk inner panels, remove fuel gauge sender, seach for new float (Normo) make new float arm, reinstall sender. Fabricate shim for deck lid spring. (Paolo)	65.00	747.50
6.75	LABOR-(Decemmber 7) Make key latch for gas door. Weld on. (December 8) Finish and fit gas door trim. (December 9) Fill and finish pin hole in gas door trim. (Curtis)	65.00	438.75
11.5	LABOR-(December 9) Driver door. (December 10) Exhaust. (Paolo)	65.00	747.50
Total			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX  
epiresto@pacbell.net

1216 Fifth Street  
Berkeley, CA 94710 USA

## Invoice

DATE	INVOICE #
1/3/00	423

BILL TO

PROJECT
---------

MASERATI MISTRAL
------------------

QUAN	DESCRIPTION	RATE	AMOUNT
2.5	LABOR-(December 10) Make pillar trim fit tighter. Fit front engine compartment panel. Drill and paint. (Curtis)	65.00	162.50
1.5	LABOR-(December 13) Take to gas station, check operation of new float. Drop off car at glass shop. (Paolo)	65.00	97.50
0.5	LABOR-(December 29) Pick up chrome plating. (Rick)	65.00	32.50
	SUBLET-Welding on intake manifold, ports and water leaks.	196.00	196.00
	SUBLET-Chrome gas door trim and windshield side trim.	105.00	105.00
	SUBLET-Remove and reinstall backglass.	299.60	299.60
1	PARTS-Fuel pressure regulator	35.34	35.34
	PARTS-Exterior trim material	69.12	69.12
12	PARTS-Spark plugs	2.80	33.60
	PARTS-U Bend	126.00	126.00
1	PARTS-MT-34 battery	100.73	100.73
1	PARTS- Tank float	14.00	14.00
1	PARTS-Throttle linkage grommet	4.48	4.48
1	PARTS-Throttle linkage bushing	5.15	5.15
1	PARTS-Heater hose	19.95	19.95
1	PARTS-Heater hose 1600	28.00	28.00
1	PARTS- Tie rod end left thread	35.73	35.73
	GAS-for test drive	17.21	17.21
		<b>Total</b>	<b>\$6,988.66</b>



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX  
epiresto@pacbell.net

1216 Fifth Street  
Berkeley, CA 94710 USA

## Invoice

DATE	INVOICE #
4/21/00	468

BILL TO

PROJECT
---------

MASERATI MISTRAL
------------------

QUAN	DESCRIPTION	RATE	AMOUNT
1	LABOR-(December 30) Pick up from glass shop. (Paolo)	65.00	65.00
10	LABOR-(January 4) Install new windshield trim. Reinstall driver door panel and trunks panels. Remove side-view mirror. Cut off damaged mirror adjuster screw. Slot mirror base plate to improve mirror angle. Search for new mirror adjuster screw. Fill incorrect hole on driver door trim finish fitting to car. (January 5) Install driver door trim. Machine air cleaner bases to fit carburetors. Bead blast and wash air cleaner components. Install air cleaners. (January 7) Load car, deliver to San Carlos. (Paolo)	65.00	650.00
7	LABOR-(April 14) Start trouble shooting electrical problems. (April 17) Continue trouble shooting electrical problems. Check charging system, found voltage regulator incorrectly hooked up and rusted. Pick up new regulator and install. Take car from electrician to load test battery and double check charging system. Install striker rubbers on door light switches to allow enough travel to allow switches to turn off when door are closed. Trace "no brake lights" to the fact that brake light switch was unsafely bypassed. Remove inner fender cover to access brake lines. Start removing unsafe brake plumbing. (Paolo)	65.00	455.00
Total			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

epiresto@pacbell.net

## Invoice

DATE	INVOICE #
4/21/00	468

BILL TO

PROJECT
---------

MASERATI MISTRAL
------------------

QUAN	DESCRIPTION	RATE	AMOUNT
8	LABOR-(April 18) Remove brake boosters to allow access to brake light switch "tee". Secure brake light "tee" to chassis, re-route front brake feed line to go through brake "tee", flaring lines to appropriate configuration. Bleed left front brake, check for leaks. Reinstall fender panel and wheel. Disassemble headlight toggle (melted inside). Search fo new switch. Check lights, found dash lights, left rear parking, front parking and turn and right front fender light not functioning. Remove front parking lights and inspect. Replace blown bulbs, resolder loose terminal. Found parking lights cannot be reinstalled without removing bumper to avoid removing. Pick up new screws for parking lights. (Paolo)	65.00	520.00
8	LABOR-(April 19) Drill front parking lights to fit 5mm screws. Machine screws to fit parking lights. Reinstall parking lights. Trace problem with dash lights to burned switch. Move wires to functioning side of 4-way toggle. Replace burned bulb in speedometer. Exchange headlight switch with dome light switch. Reinstall switch assembly. Found steering wheel loose. Remove lump oof weld from mating surface of steering nut, reinstall nut. Remove right front inner fender, remove air cleaner. Clean ground on fender light reinstall panel. Go to gas station, take car on test drive to listen to gearbox. (Paolo)	65.00	520.00
5.75	LABOR-(April 20) Up on jackstands. Search for oil input hole for transmission. Begin removing seats. Remove seats and transmission tunnel. Remove slave cylinder from its mounting. Remove both drain plugs and drain oil. Measure oil out (1700cc). Reinsert drain plugs. Fill with 80-140 Red Line. Reinstall transmission tunnel and seats. Vacuum interior. Back on floor. (Frederick)	65.00	373.75
	SUBLET-Chrome plate 1 gas door trim, strip trim (2 pieces).	56.00	56.00
		<b>Total</b>	



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

epiresto@pacbell.net

## Invoice

DATE	INVOICE #
4/21/00	468

BILL TO

PROJECT
---------

MASERATI MISTRAL
------------------

QUAN	DESCRIPTION	RATE	AMOUNT
4	PARTS-5mm rivnuts	2.25	9.00
4	PARTS-5mm x 50 screws	0.30	1.20
1	PARTS-Pt. brake fluid	8.60	8.60
3	PARTS-Light bulbs	2.40	7.20
2	PARTS-Qts. Red Line	8.75	17.50
1	PARTS-Side view mirror and adjuster nut	0.00	0.00
1	PARTS-Voltage regulator	77.00	77.00
	GAS-For test drive	20.80	20.80
		<b>Total</b>	<b>\$2,781.05</b>



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

DATE	INVOICE #
2/8/2010	11173

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
11.5	LABOR-(January 19) Put car on stands. Remove wheels, begin disassembly of brake system. (January 20) Continue disassembly and cleaning brake parts (every part in this brake system is rusted together, taking a lot of time to come apart without damage). (Rick P.)	95.00	1,092.50
8	LABOR-(January 21) Finish disassembly of brakes, clean parts, disassemble clutch system, master and slave, start ordering parts. (Rick P.)	95.00	760.00
8.5	LABOR-(January 22) Pull off front brake rotors, clean hubs and bearings, reassemble rear caliper emergency brake assembly, clean parts, continue trying to locate parts. (January 25) Locate and order new brake pads, pull off rear brake rotors and send out to turn, try to pull off rear hubs (will not come off) rear wheel bearings bad, had to pull rear axles out with hubs attached, very hard to pull out. (Rick P.)	95.00	807.50
8.75	LABOR-(January 26) Press axle hubs and bearings off of axles (note: rusted on took a lot of time to get apart). Clean parts, blast and paint parts. (Rick P.)	95.00	831.25
1	LABOR-(January 26) Weld rear brake back plates and straighten to original shape. (Andrew)	95.00	95.00
7.25	LABOR-(January 27) Assemble front and rear brake calipers. Work on rear axles, drain transmission and diff., make tool to pull out axle. (Rick P.)	95.00	688.75
7.75	LABOR-(January 28) Work on setting up rear axles, install left axle for final time and brake brackets hub and rotor, make gaskets. (January 29) Finish up brake assembly right rear, clean, straighten, blast and paint diff. cover, make diff. cover gasket, modify front rubber brake lines, install front brake pads. (Rick P.)	95.00	736.25
<b>Total</b>			



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
2/8/2010	11173

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
7.75	LABOR-(February 1) Pull right axle out, chase threads on end with die, install seals, grease bearings, install axle assemble brake, shim caliper to center, install pads, order parts for emergency brake, modify new rear rubber brake line, pull out old line and replace. Remove emergency brake cables, drop exhaust down to access brake hose and clutch hoses, remove hoses, order new ones, install slave cylinder and clutch master. (Rick P.)	95.00	736.25
8.5	LABOR-(February 3) Bleed and adjust clutch, pull all panels in trunk out to inspect fuel tanks and lines, fill diff. and tran. with gear oil, fix leaks in tran., pull out both fuel tanks and lines that run between, 1 choke cable sp). (Rick P.)	95.00	807.50
	SUBLET-Machine 2 rotors.	45.00	45.00
	SUBLET-Machine 2 rotors.	45.00	45.00
	SUBLET-Clean fuel tanks.	160.00	160.00
1	PARTS-External voltage regulator	77.00	77.00T
	PARTS-Front brake pads	146.95	146.95T
	PARTS-Rear brake pads	83.95	83.95T
2	PARTS-Brake hose, JH front	47.39	94.78T
	PARTS-S/C, turbo & V8 clutch slave	208.34	208.34T
	PARTS-M/C, girl, sml res, clutch master	122.64	122.64T
6	PARTS-Retainer clips	0.88	5.28T
2	PARTS-1.89" cal pist, rear calipers	41.96	83.92T
2	PARTS-Pist seal, rear calipers	5.58	11.16T
4	PARTS-Caliper pist, rear calipers	44.09	176.36T
	PARTS-Caliper kit, rear kit	56.83	56.83T
	PARTS-R/cal kit, front kit	103.45	103.45T
2	PARTS-Piston, front caliper	45.90	91.80T
Total			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
2/8/2010	11173

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
4	PARTS-Cal piston, front caliper	55.12	220.48T
	PARTS-Brake hose, jh front	47.39	47.39T
2	PARTS-Axle race (25820 tapered roller bearing)	13.16	26.32T
2	PARTS-Axle bearings (25877 roller bearing)	21.61	43.22T
2	PARTS-Axle seals (35x58x10TC) metric shaft seal	13.09	26.18T
2	PARTS-Axle seals (19993 CR small bore seals)	9.94	19.88T
12	PARTS-Hose clamp	0.83	9.96T
20	PARTS-Heater hose	0.66	13.20T
14	PARTS-Hose clamp	0.83	11.62T
	PARTS-Util cable	10.35	10.35T
	PARTS-Antenna	115.56	115.56T
	PARTS-Fuel filter	8.04	8.04T
	PARTS-Fuel hose (between tanks)	43.57	43.57T
12	PARTS-Hose clamps	0.62	7.44T
4	PARTS-Hose clamps	0.83	3.32T
2	PARTS-Fittings	6.67	13.34T
8	PARTS-F/line hose	2.66	21.28T
8	PARTS-F/inj hose	6.93	55.44T
	PARTS-Fitting	14.72	14.72T
	PARTS-Brake hose 14" long	47.39	47.39T
	PARTS-Brake hose 7.5" long	41.98	41.98T
	PARTS-Emergency brake parts	435.17	435.17T
10	PARTS-3/8 nylock nuts	0.85	8.50T
10	PARTS-3/8 flat washers	0.06	0.60T
	PARTS-10"x4" piece gasket paper	8.00	8.00T
Total			



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
2/8/2010	11173

BILL TO

PROJECT
---------

MASERATI MISTRAL #056
-----------------------

QTY	DESCRIPTION	RATE	AMOUNT
2	PARTS-3/8" copper washers	0.85	1.70T
	PARTS-12" x 12" piece of gasket material	12.00	12.00T
3	PARTS-Rubber grommets 13 x 22 x 28	1.50	4.50T
10	PARTS-5/16" lock washers	0.30	3.00T
4	PARTS-8mm nylock nuts	0.65	2.60T
4	PARTS-8mm wave washers	0.18	0.72T
1	PARTS-Pt. brake fluid	9.75	9.75T
1	PARTS-Gal. gear oil	20.80	20.80T
	MISCELLANEOUS-Brake fluid disposal fee	3.00	3.00
	FREIGHT-UPS charges to White Post.	12.14	12.14
	FREIGHT-Shipping charges for brake pads.	13.52	13.52
	FREIGHT-Shipping charges for clutch slave, master, etc.	7.31	7.31
	FREIGHT-Shipping charges for calipers, etc.	7.97	7.97
	FREIGHT-Shipping charges for brake hose	7.23	7.23
	Sales Tax	9.75%	250.62
Total			\$9,677.27



1216 Fifth Street  
Berkeley, CA 94710 USA



(510)525-3445  
(510)525-4091 FAX  
epiresto@pacbell.net

## Credit Memo

DATE	CREDIT NO.
2/15/2010	11176

CUSTOMER

PROJECT

MASERATI MISTRAL #056

[illegible]



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
4/26/2010	11190

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
8.25	LABOR-(February 2) Replace all radiator and heater hoses, pressure test heater core, install clutch rubber line, install rubber brake line under transmission. (Rick P.)	95.00	783.75
8.25	LABOR-(February 4) Pull all fuel lines, fuel pump and regulator out of car, begin installing radio antenna, continue cleaning dirt and rust out of rear inner quarter panels, drop off gas tanks to get cleaned, test radio to see if it works, try to locate hose for gas tanks, stop by supplier to get hose, make new bracket for fuel pump and regulator. (Rick P.)	95.00	783.75
9	LABOR-(February 5) Work on power antenna finish install wire up, work on fuel system. (February 8) Pick up fuel tanks at radiator shop, find diagram of tank straps, start fitting left side tank, cut metal to make tank straps. (Rick P.)	95.00	855.00
8.25	LABOR-(February 9) Make support pieces and fit left fuel tank, make a new retaining strap for the tank, fit right fuel tank, begin making strap for tank, bead blast and paint left tank strap, give right strap to welder to tack. (Rick P.)	95.00	783.75
7.75	LABOR-(February 10) Finish fitting right fuel tank, paint tank, paint strap, set both tanks in car and put in hose that connects tanks, do final install off tanks and straps, pick up hose at supplier. (Rick P.)	95.00	736.25
1	LABOR-(February 10) Assist Rick P. with misc work and assembly. (Rick)	95.00	95.00
12.75	LABOR-(February 11) Complete fuel system, run vent lines, modify vent to fit hose, finish fuel line on fuel pump and regulator, install fuel filter, install emergency brake cable and bracket, adjust emergency, install master cylinder and lines, pull battery out of car and put on charger, install right inner fender panel. (February 12) Bleed brake system, check for leaks (ok), re-install exhaust piep and hangers, install left inner fender panel, finish charging battery and test (bad), order battery. (Rick P.)	95.00	1,211.25
Total			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

DATE	INVOICE #
4/26/2010	11190

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
8.75	LABOR-(February 15) Work on dash electrical switches and wiring, replace bulbs, repair sockets, repair swtiches for interior light and power antenna, try to get wiper to work, will not move. (Rick P.)	95.00	831.25
7.75	LABOR-(February 16) Pull wiper motor out of car, disassemble and inspect (bad drive gear), re-solder armature and test (ok), reassemble motor and test (ok), pull off driver side door panel, order new window mechanism, make puller to remove steering wheel, take turn signal switch out of coloumn, install trunk panels and wire light. (February 17) Order parts for car. (Rick P.)	95.00	736.25
0.5	LABOR-(February 18) Order parts. (Rick P.)	95.00	47.50
10.25	LABOR-(February 26) Reassemble and install wiper motor, start working on turn signal switch. (March 1) Install turn signal switch and reassemble steering column, pull apart left front door window motor and cable assembly and window tracks (note: all bolts rusted had to cut some). Straighten and repair tracks, clean tracks, reassemble and shim to get window to side correct. (Rick P.)	95.00	973.75
4.25	LABOR-(March 2) Pull apart left side window motor and gear box, make up new lift cables, begin rewiring door. (Rick P.)	95.00	403.75
7.75	LABOR-(March 3) Finish rewiring driver door, install motor for window, run cables for window mechanism, set cable tension, reassemble door braces, test window (ok), pull off passenger door panel, disconnect cables and remove motor assembly, begin disassembly of motor. (Rick P.)	95.00	736.25
6	LABOR-(March 4) Disassemble, clean and test components from right window motor, pull track out of right door, clean and reinstall, assemble motor, make up new cables for right window.	95.00	570.00
Total			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

DATE	INVOICE #
4/26/2010	11190

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
2.75	LABOR-(March 9) Finish installing motor and cable in right door window, pull old radio out of car, unbox new radio and speaker and inspect. (Rick P.)	95.00	261.25
2.25	LABOR-(March 17) Unbox used heater, pull apart heater, disassemble motor, clean, blast, paint parts, order parts. (Rick P.)	95.00	213.75
3.25	LABOR-(March 18) Assemble heater fan motor and test (ok), assemble heater box cover. Install fan in cover, rewire passenger side power window motor and relays. (Rick P.)	95.00	308.75
	SUBLET-Weld Maserati Mistral tank brackets and breather tube.	70.00	70.00
	PARTS-Wiper motor gear	134.40	134.40T
	PARTS-Turn signal column switch	208.46	208.46T
	PARTS-Master cylinder complete	315.00	315.00T
	PARTS-22 Aer FBU0600 startlite hose	178.11	178.11T
	PARTS-8 F/line hose	7.28	7.28T
	PARTS-Battery	76.93	76.93T
	PARTS-Tube	23.10	23.10T
	PARTS-Coolant bottle cap	25.40	25.40T
2	PARTS-Gal. antifreeze	19.65	39.30
2	PARTS-Ft. 1 1/4 radiator hose	9.00	18.00
1	PARTS-Ft. 1 3/8 radiator hose	9.00	9.00
1	PARTS-P205/70R15 MI Harmony tire	97.90	97.90T
	PARTS-Gas tank neck grommet	7.63	7.63T
3	PARTS-Bullet conn male	0.18	0.54T
1	PARTS-5mm screw	0.31	0.31T
1	PARTS-5mm nylock nut	0.45	0.45T
2	PARTS-Qts brake fluid	26.50	53.00T
Total			



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
4/26/2010	11190

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
1	PARTS-#1185 bulb	2.80	2.80T
1	PARTS-12"x12" piece steel plate	6.00	6.00T
8	PARTS-8mmx25mm flat head allen bolts	2.20	17.60T
2	PARTS-8mm flat washers	0.11	0.22T
2	PARTS-8mm nylock nuts	0.65	1.30T
3	PARTS-6mmx15mm bolts	1.05	3.15T
3	PARTS-6mm nylock nuts	0.45	1.35T
1	PARTS-Holley fuel pressure regulator	37.25	37.25T
1	PARTS-3/8 pipe plug	2.20	2.20T
1	PARTS-3/8x3/8 brass 90 degree fitting	2.75	2.75T
2	PARTS-Lg. hose clamps	2.45	4.90T
6	PARTS-4mm screws	0.31	1.86T
6	PARTS-4mm flat washers	0.08	0.48T
6	PARTS-4mm lock washers	0.05	0.30T
1	PARTS-Can trim black paint	15.35	15.35T
12	PARTS-Ft. wire 16ga	0.90	10.80T
2	PARTS-5mm lock washers	0.05	0.10T
2	PARTS-15mm flat washers	0.16	0.32T
2	PARTS-Male bullet conn.	0.18	0.36T
3	PARTS-Ft. wire jacket	0.35	1.05T
3	PARTS-6mm lock washer	0.08	0.24T
4	PARTS-6mm x 16mm bolts	1.05	4.20T
4	PARTS-6mm lock washers	0.08	0.32T
2	PARTS-6mm nuts	0.35	0.70T
5	PARTS-Male bullet connectors	0.18	0.90T
<b>Total</b>			



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
4/26/2010	11190

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
16	PARTS-Female spade connectors	0.21	3.36T
4	PARTS-Wire eyes	0.21	0.84T
24	PARTS-In. heat shrink tube	3.20	76.80T
22	PARTS-Ft. 16 ga. wire	0.90	19.80T
4	PARTS-6mm x 15mm bolts	1.05	4.20T
2	PARTS-6mm nuts	0.35	0.70T
4	PARTS-6mm lock washers	0.08	0.32T
2	PARTS-5mm x 20mm bolts	1.05	2.10T
9	PARTS-5mm nuts	0.32	2.88T
8	PARTS-5mm flat washers	0.08	0.64T
13	PARTS-5mm lock washers	0.05	0.65T
4	PARTS-4mm x 15mm bolts	1.05	4.20T
4	PARTS-4mm nuts	0.32	1.28T
	PARTS-Misc. sundries and hardware	80.00	80.00T
2	PARTS-Forward	5.92	11.84T
	PARTS-Access Relay	11.80	11.80T
	PARTS-Maserati Mistral used air box assembly	1,800.00	1,800.00T
2	PARTS-Defroster "Y"	18.66	37.32T
2	PARTS-Defroster elbow	16.41	32.82T
8	PARTS-Defrost duct	5.52	44.16T
	PARTS-Stainless steel wire rope	13.65	13.65T
	PARTS-Used relay	49.00	49.00T
2	MISCELLANEOUS-Brake fluid disposal fee	3.00	6.00
2	MISCELLANEOUS-Antifreeze disposal fee	3.00	6.00
1	MISCELLANEOUS-Tire disposal fee	4.50	4.50
Total			



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
4/26/2010	11190

BILL TO

PROJECT
---------

MASERATI MISTRAL #056
-----------------------

QTY	DESCRIPTION	RATE	AMOUNT
1	CALIFORNIA TIRE RECYCLING FEE-	1.75	1.75
	FREIGHT-Shipping for grommet	6.00	6.00
	FREIGHT-Shipping charges for wiper motor and turn signal	10.35	10.35
	FREIGHT-Shipping charges for master cylinder.	20.00	20.00
	FREIGHT-Shipping & handling for tube	7.36	7.36
	FREIGHT-Shipping charges for tire.	15.60	15.60
	FREIGHT-Shipping charges for air box assembly.	25.00	25.00
	FREIGHT-Shipping charges for defroster parts.	10.61	10.61
	FREIGHT-UPS charges to Electric Life.	13.57	13.57
	Sales Tax	9.75%	335.73
<b>Total</b>			<b>\$14,373.39</b>



## Statement

4/26/2010

6,199.05

CURRENT	1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due
0.00	0.00	6,199.05	0.00	0.00	\$6,199.05



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
8/19/2010	11239

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
1.5	LABOR-(June 15) Remove window track driver's door. (Rick P.)	95.00	142.50
7	LABOR-(June 23) Install radio and speaker, wire in radio, make adapter pieces for heater defroster vents for heater box, install front cover for heater, cut hose to make lines to defroster vents, install passenger side door panel, drain oil, remove oil filter housing, clean and install new filter. (Rick P.)	95.00	665.00
5.25	LABOR-(June 24) Finish oil change, pull out distributor, wires, plugs, coils, clean distributor cap and test (bad), clean rotor and test (bad), pull apart distributor, clean points and reinstall, test wires (ok), try to order cap and rotor. (Rick P.)	95.00	498.75
8	LABOR-(June 29) Make new wires for coils to resistors, get coils from supplier, finish assembly of distributor, blast blue paint off of coils. (June 29) Paint coils, bead blast resistors, paint coil brackets, start making plug and coil wires, install distributor cap and rotor, put plugs in car, put plug wires on car and start installing ends. (Rick P.)	95.00	760.00
0.5	LABOR-(June 28) Run distributor and set dwell, synch points and check advance curve. Test coils and condensers. Test cap and rotor. (Rick)	95.00	47.50
4.5	LABOR-(June 30) Finish making and installing spark plug and coil wires. Figure out switches and lights on dash board, get car running, take for test drive, synch carbs, work on windows. (Rick P.)	95.00	427.50
2	PARTS-Distributor coils	51.10	102.20T
5	PARTS-Female spade conn	0.18	0.90T
2	PARTS-Male bullet conn.	0.21	0.42T
1	PARTS-Baldwin oil filter	36.00	36.00T
2	PARTS-Female bullet conn	0.18	0.36T
8	PARTS-In. heat shrink tube	0.26	2.08T
Total			



# Epifani Restorations



1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
8/19/2010	11239

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
10	PARTS-Qts 20w-50 standard oil	3.34	33.40T
4	PARTS-5mmx10mm screws	0.05	0.20T
12	PARTS-5mm flat washers	0.08	0.96T
12	PARTS-5mm lock washers	0.05	0.60T
8	PARTS-5mm nuts	0.32	2.56T
10	PARTS-Wire eyes	0.21	2.10T
12	PARTS-NGK plugs	2.33	27.96T
50	PARTS-Ft. 5mm green spark plug wire from Italy	1.00	50.00T
16	PARTS-5mm wire ends from Italy	1.50	24.00T
8	PARTS-Ft. black ignition wire	0.50	4.00T
3	PARTS-Wire sets for resistor ends	26.02	78.06T
1	PARTS-Rotor	460.60	460.60T
1	PARTS-Distributor cap	10.00	10.00T
	MISCELLANEOUS-Oil disposal fee	5.00	5.00
	Sales Tax	9.75%	81.55
<b>Total</b>			<b>\$3,464.20</b>



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
12/27/2010	11290

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
1	LABOR-(November 11) Repair and rework left door window. (Rick)	95.00	95.00
1.75	LABOR-(November 18) Install windshield squirter and run hoses reassemble firewall components moved to get access, try to find long bolts for seat belts (eye bolts have to be 3" long, can't locate). (November 22) Tape off and paint rear hatch hinges. (Rick P.)	95.00	166.25
2.25	LABOR-(November 30) Drill holes in chassis for seat belts, get bolts from supplier to make seat belt eyes, modify bolts and give to welder to weld, install rear deck hinge cover panel. (Rick P.)	95.00	213.75
2.5	LABOR-(December 2) Install seat belts, reinstall seats, put edging on exhaust heat shield. (Rick P.)	95.00	237.50
8	LABOR-(December 6) Pull out choke and heater lever panel, repair choke lever (had a bad old repair). Reinstall hook up choke cable, remove center rocker switch panel, disassemble and repair switches, repair wiring under dash, install new cigarette lighter socket. (Rick P.)	95.00	760.00
4	LABOR-(December 7) Pull out driver's seat. Pull down wiring under dash, inspect wiring burned bad connections, wipe downs car. Begin pulling out dash, radio, gauges. (Rick P.)	95.00	380.00
8.75	LABOR-(December 8) Pull out steering column. Work on repairing wiring for dash. (Rick P.)	95.00	831.25
0.5	LABOR-(December 8) Assist Rick P. with steering column removal. (Rick)	95.00	47.50
7	LABOR-(December 9) Work on wiring, begin reinstalling dash. (Rick P.)	95.00	665.00
3.25	LABOR-(December 9) Disassemble pedal assembly. Clean pedals and bushings. Polis pivot rod. Re-grease and reassemble. Clean steering column. (Nick)	95.00	308.75
Total			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
12/27/2010	11290

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
7.5	LABOR-(December 13) Finish up wiring, install gauges, pull apart steering column (not easy, stuck together). Clean parts. (Rick P.)	95.00	712.50
3.25	LABOR-(December 13) Bead blast pedal assembly. CLean with water and bottle brushes to remove ecess sand from column and pedal assembly. Mask off and paint. (Nick)	95.00	308.75
4.5	LABOR-(December 14) Clean, paint steering column parts, begin reassembly. Assemble lower portion of steering column and install in car. (Rick P.)	95.00	427.50
7	LABOR-(December 15) Finish assembly of steering column, brake and clutch pedals, wire up horn, install heater fan and cover, install defroster vents, heat shield for exhaust, steering wheel, charge battery, test components (ok). Try to locate wiper adapters. (Rick P.)	95.00	665.00
4	LABOR-(December 17) Change all dash lights, install driver seat check all systems (dome light stays on with doors closed). Try finding dome light problem (no luck). Make up new dash layout diagram. (Rick P.)	95.00	380.00
1	PARTS-Cigarette lighter socket	7.98	7.98T
1	PARTS-Shift boot outer	30.77	30.77T
1	PARTS-Wiper blade	34.30	34.30T
1	PARTS-Steering shaft coupler	54.82	54.82T
1	PARTS-Shifter boot	21.58	21.58T
10	PARTS-Dash light bulbs	1.68	16.80T
1	PARTS-Can wrinkle finish black paint for steering block	4.24	4.24T
4	PARTS-7/16 x 3" allen bolts	0.65	2.60T
4	PARTS-7/16 nylock nuts	0.40	1.60T
4	PARTS-7/16 flat washers	0.06	0.24T
9	PARTS-Male bullet connectors	0.18	1.62T
<b>Total</b>			



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
12/27/2010	11290

BILL TO

PROJECT
---------

MASERATI MISTRAL #056
-----------------------

QTY	DESCRIPTION	RATE	AMOUNT
24	PARTS-Female spade connectors	0.18	4.32T
2	PARTS-Female bullet connectors	0.21	0.42T
1	PARTS-Turn signal flasher	12.00	12.00T
3	PARTS-Ft. heat shrink tubing	3.20	9.60T
26	PARTS-Ft. wire plastic coated	0.70	18.20T
1	PARTS-Wire eye	0.21	0.21T
12	PARTS-Tie wraps	0.30	3.60T
	FREIGHT-Shipping charges for coupler	6.65	6.65
	FREIGHT-Shipping charges for light bulbs	3.64	3.64
	Sales Tax	9.75%	21.93
Total			\$6,455.87

# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
2/3/2011	11307

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
4	LABOR-(January 18) Make hardware for wiper arms, fit left arm and adjust test ok, get car out, try to start acc. pumps in carbs plugged, pull out, clean out, warm car up, take to gas station and get fuel, take for long test drive. Jack up front, put on stands. (Rick P.)	95.00	380.00
4.25	LABOR-(January 19) Repair wiper linkage arm (note: someone had drilled and screwed adjuster because studs are stripped, had to remove studs and install bolts). Remove transmission tunnel cover and make boot have clearance so shifter will go far enough forward, take for drive test brakes (takes a lot of brake pressure) research brake servo rebuilds. (Rick P.)	95.00	403.75
0.75	LABOR-(January 19) Assist Rick P. wipes and transmission boot. (Rick)	95.00	71.25
4.5	LABOR-(January 24) Pull out wiper motor and drive assembly, pull apart (barely moved, loaded up with rust and grit). Clean parts, repair studs on arm spindles, lobe and reassemble unit reinstall in car, test wiper motor works, but only in high speed, try to find correct wiring diagram. (Rick P.)	95.00	427.50
	PARTS-Material for wiper arm hardware	18.35	18.35T
	GAS, OIL & GREASE-3.599 gal gas	32.97	32.97
	Sales Tax	9.75%	1.79
<b>Total</b>			<b>\$1,335.61</b>



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
3/7/2011	11325

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
5.5	LABOR-(February 23) Jack up car, put on stand, pull out left inner fender. Remove brake reservoirs, disconnect brake lines, begin installing brake boosters, make up new brake lines to front brake booster. (Rick P.)	95.00	522.50
6.25	LABOR-(February 24) Work on install servos, install vacuum line from manifold to driver side, bleed system for first bleed (will need one more), remove windshield wiper switch and test (bad). (Rick P.)	95.00	593.75
6.75	LABOR-(February 28) Work on brake booster, install atom, bleed brakes a second time, finish hooking up vacuum lines, install inner fender, install wheels, take car out, warm up, try brake, boosters not working, test car vacuum at manifold, low vacuum, not enough to operate system, locate electric vacuum pump and order, pull apart wiper switch and fix, start adjusting wiper arms. (Rick P.)	95.00	641.25
3	LABOR-(March 1) Finish putting wipers together. Work on brake vacuum system, pick up parts in Hayward. (March 2) Temporarily rig up vacuum pump for test drive. (Rick P.)	95.00	285.00
1	PARTS-Vac filter	17.35	17.35T
10	PARTS-Hose clamps	0.94	9.40T
12	PARTS-Vac hose	1.64	19.68T
2	PARTS-Brake vacuum servo	670.60	1,341.20T
2	PARTS-Master cylinder caps	8.75	17.50T
2	PARTS-Sml res gaskets	1.70	3.40T
2	PARTS-Master cylinder reservoirs	36.26	72.52T
	PARTS-Vacuum pump	349.27	349.27T
	PARTS-Connector	3.30	3.30T
	PARTS-FDA compliant nylon check valves	12.25	12.25T
<b>Total</b>			



# Epifani Restorations



## Invoice

1216 Fifth Street  
Berkeley, CA 94710 USA

(510)525-3445  
(510)525-4091 FAX

info@epifanirestorations.com

DATE	INVOICE #
3/7/2011	11325

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
5	PARTS-Ft. brake line steel	1.60	8.00T
6	PARTS-10mm flat washers	0.08	0.48T
6	PARTS-10mm lock washers	0.15	0.90T
	FREIGHT-UPS charges to MIE with \$1,000 insurance.	12.39	12.39
	FREIGHT-Shipping charges for brake vacuums.	12.46	12.46
	FREIGHT-Shipping charges for master cylinder caps, res and gaskets.	7.63	7.63
	Sales Tax	9.75%	180.89
		<b>Total</b>	<b>\$4,111.12</b>



# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
5/23/2011	11350

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
2	LABOR-(March 4) Test drive car to test vacuum pump work, jack up car, remove front wheels and inner fender panels, begin installing vacuum pump. (Rick P.)	95.00	190.00
6.5	LABOR-(March 4) Work on vacuum pump install, get insulation from supplier. Work on hook up between vacuum pump and brake boosters. (March 8) Finish up vacuum pump install, put in right side inner fender, put on wheel, take for test drive. (Rick P.)	95.00	617.50
1.5	LABOR-(March 11) Finish up car, vacuum interior, clean glass, polish paint, grease choke cable. (Rick P.)	95.00	142.50
4.75	LABOR-(May 2) Rewire interior light door switches, replace dome light. (Rick P.)	95.00	451.25
5	LABOR-(May 5) Rewire and install new door switch passenger side door. Finish up interior lights, replace oil pressure line to gauge, replace license plate lights, test drive car, begin final check over. (Rick P.)	95.00	475.00
0.5	LABOR-(May 5) Make new oil line. (Rick)	95.00	47.50
6.25	LABOR-(May 6) Pull down center control panel, change wiring for antenna radio controlled to switch controlled finish under dash wiring. (May 9) Clean up car interior and exterior, set tire pressures, finish final check, test drive car. (Rick P.)	95.00	593.75
2	PARTS-Insulation bats	6.29	12.58T
	PARTS-Push to connect exhaust muffler, PBT, 10mm stem OD	18.38	18.38T
	PARTS-Door jamb	11.17	11.17T
4	PARTS-Female spade connectors	0.18	0.72T
1	PARTS-Wire eye	0.21	0.21T
3	PARTS-Female bullet connector	0.21	0.63T
<b>Total</b>			

# Epifani Restorations



(510)525-3445  
(510)525-4091 FAX

1216 Fifth Street  
Berkeley, CA 94710 USA

info@epifanirestorations.com

## Invoice

DATE	INVOICE #
5/23/2011	11350

BILL TO

PROJECT

MASERATI MISTRAL #056

QTY	DESCRIPTION	RATE	AMOUNT
22	PARTS-Ft. 16 ga wire	0.90	19.80T
12	PARTS-In. heat shrink tube	0.27	3.24T
1	PARTS-Dome light from Italy	220.00	220.00T
2	PARTS-Male bullet connector	0.18	0.36T
1	PARTS-Door switch	140.00	140.00T
35	PARTS-In. brown Regorsalva hose	7.20	252.00T
2	PARTS-Ferrules	1.80	3.60T
1	PARTS-Lucas toggle switch	42.00	42.00T
2	PARTS-Ft. blue 14 ga wire	2.00	4.00T
	Sales Tax	9.75%	71.05
<b>Total</b>			<b>\$3,317.24</b>