

1900 January invoice

9 messages

Watry and Baumgartner <watry@prodigy.net>

Fri, Jan 16, 2026 at 4:14 PM

Reply-To: Watry and Baumgartner <watry@prodigy.net>

To: [REDACTED]

VIN AR1900 *01474*

Engine AR1308 *01289*

Labor

* Get engine to idle and accel cleanly. Adjust carb idle and mixture screws. Check main jets and accel pumps. Check plugs. 145 main jets. Much better.

* Checking timing and dist. Adjust points slightly, check timing but no marks appeared. Leave as is for now.

* Check exhaust cam cover leak, stripped center cam nut and/or stud.

* Check tach drive, cable broken at engine.

* Check wipers, tighten spindle spline pieces

4 hrs @ \$75 = \$300

* Look further at carbs; front carb pulls more air than rear.

* Sort out ignition timing marks.

* Install mirror and water temp gauge.

Watry and Baumgartner <watry@prodigy.net>

Fri, Jan 16, 2026 at 4:34 PM

Reply-To: Watry and Baumgartner <watry@prodigy.net>

To: [REDACTED]

Here's a tool kit if you don't have one, and care. This is listed by Dave Mericle who used to run the Giulia Sedan Register before I did. He knows what he's about.

Andrew

No Reserve: Alfa Romeo 1900 Tool Kit

No Reserve: Alfa Romeo 1900 Tool Kit

Bid for the chance to own a No Reserve: Alfa Romeo 1900 Tool Kit at auction with Bring a Trailer, the home of th...

[Quoted text hidden]

Watry and Baumgartner <watry@prodigy.net>

Sat, Jan 17, 2026 at 3:57 PM

Reply-To: Watry and Baumgartner <watry@prodigy.net>

ALFA ROMEO

[REDACTED]

Dan found a mirror but no gauge. Neither he nor I is in favor of cutting into the dash, but it's your car.
Andrew

[Quoted text hidden]

Sun, Jan 18, 2026 at 11:38 AM

To: Watry and Baumgartner <watry@prodigy.net>

thanks for the heads up on the tool kit, I did see it and will be bidding on it towards the end. that is great that he found the mirror, i think it may need a jack also. maybe he can check on that too. let me know when i can pick up the mirror. thanks [REDACTED]

[Quoted text hidden]

Watry and Baumgartner <watry@prodigy.net>
Reply-To: Watry and Baumgartner <watry@prodigy.net>
[REDACTED]

Sun, Jan 18, 2026 at 11:58 AM

I'll get a price on the mirror too. Dan is in LA, so either one of us will bring it up or mail it.
Andrew

[Quoted text hidden]

Tue, Jan 27, 2026 at 12:40 PM

To: Watry and Baumgartner <watry@prodigy.net>

any word on the rear view mirror, could he send a picture? thanks [REDACTED]

[Quoted text hidden]

Watry and Baumgartner <watry@prodigy.net>
Reply-To: Watry and Baumgartner <watry@prodigy.net>
[REDACTED]

Tue, Jan 27, 2026 at 12:51 PM

I sent you a text, I got the mirror. \$150. Will send a pic.
Andrew

[Quoted text hidden]

Wed, Jan 28, 2026 at 12:25 PM

To: Watry and Baumgartner <watry@prodigy.net>

Ok, thanks.

[Quoted text hidden]

Watry and Baumgartner <watry@prodigy.net>
Reply-To: Watry and Baumgartner <watry@prodigy.net>
[REDACTED]

Wed, Jan 28, 2026 at 1:04 PM

I has an 8mm stud (roughly 5/16") so needs drilling to install. You're good with tools, right? We can look underneath to see if any evidence of the original hole, drill a new one same place.
Andrew

[Quoted text hidden]

CUSTOM CAR COVER

Order summary ▾

\$508.94



Order #10114613569

Thank you, [REDACTED]



Your order is confirmed

You'll receive an email when your order is ready.

[Download Shop to track package](#)

Order details

Contact information

[REDACTED]

Payment method

ending with 4599 - \$508.94

Shipping address

[REDACTED]

Billing address

Shipping method

Fedex Ground Shipping

Epifani
Restorations



(510)525-3445
(510)525-4091 FAX

1216 Fifth Street
Berkeley, CA 94710 USA

info@epifanirestorations.com

pd 8/5
✓ 2158.7 **Invoice**

DATE	INVOICE #
7/30/2026	13174

BILL TO

PROJECT

ALFA ROMEO 1900

QTY	DESCRIPTION	RATE	AMOUNT
0.5	LABOR-(July 6) Test drive car. Check over. (Paolo)	150.00	75.00
2.5	LABOR-(July 7) Check valve adjustment. Remove broken oil hard line. Clean and give to welder. Install cam oil tube torque cam nuts. (Ed)	150.00	375.00
3	LABOR-(July 8) Clean valve covers. Clean head, check problem with fit on exhaust side. Touch up paint valve cover. Tap valve cover allen thumb screws. Clean intake side gasket surface. Clean both valve covers again. Remove carbs from manifold. Install valve cover thumb screws. (Ed)	150.00	450.00
3	LABOR-(July 8) Assist Ed address issues with fit of driver side valve cover. Cover is probably not original to engine. Pins do not align with cover and mounting studs are damaged. Banjo bolt for added cam tube oiler is hitting valve cover. Machine bolt to increase clearance to cover. Remove material from valve cover for additional clearance. Holes for valve cover hold down nuts are out of alignment with cover. File valve cover for clearance. Install new studs. Trim gasket and install valve cover. (Paolo)	150.00	450.00
3.5	LABOR-(July 11) Remove three worn intake cam cover mounting studs (3). Clearance trim inside center of intake cam cover to clear added camshaft oiling banjo bolt. (was previously interfering with fit of intake cam cover). Clean and prepare mating surfaces of cylinder head, intake cam cover and cylinder head/cam cover end cap. Refit intake camshaft cover and its rear end cap. (John B.)	150.00	525.00
1	LABOR-(July 11) Banjo bolt on passenger side valve cover is making contact with valve cover. Machine banjo bolt for clearance and reinstall. Assist John B. with misc. (Paolo)	150.00	150.00
0.5	LABOR-(July 13) Make new fuel line. (Rick)	150.00	75.00
Total			

Epifani Restorations



(510) 525-3445
(510) 525-4091 FAX

1216 Fifth Street
Berkeley, CA 94710 USA

info@epifanrestorations.com

Invoice

DATE	INVOICE #
7/30/2026	13174

BILL TO



PROJECT

ALFA ROMEO 1900

QTY	DESCRIPTION	RATE	AMOUNT
4	LABOR-(July 13) Install carbs. Drill hole in new choke cable bolt. Install choke cable. Remove springs and check throttle shaft movement, loosen front carb. Remove leaking fuel hose and reinstall after repair. Replace fuel hose sealing washers. Wipe down leaks off engine, wipe engine area, wipe and clean floor. (Ed)	150.00	600.00
0.5	LABOR-(July 13) Misc tidy up. Run engine. Check for leaks. (Paolo)	150.00	75.00
3	LABOR-(July 14) Tighten wiper mounts, position wiper arms, test, bend wiper arm to fit. Check wiper park position. Left wiper arm parks in wrong position according to Alfa Romeo books, pictures. Run engine to full operating temperature, check for leaks. Top radiator hose is incorrect and should be replaced. Nut and bolt front steering. Tighten steering box to chassis. Tighten both lower a-arm plates. Tighten steering arms. Check front play in suspension. Left king pin has excessive play. Right king pin is worn. There is no wire leading to temp sender. (Ed)	150.00	450.00
	PARTS-Valve cover washers	2.10	2.10T
	PARTS-Misc sundries & hardware.	20.85	20.85T
17	PARTS-In. yellow fuel line	22.50	382.50T
2	PARTS-Ferrules	20.00	40.00T
2	PARTS-Valve cover gaskets	34.72	69.44T
	FREIGHT-Shipping charges for valve cover gasket.s	30.82	30.82
	FREIGHT-Duty & tax for valve cover gaskets.	26.34	26.34
	Sales Tax	10.25%	52.78
Total			\$3,849.83